

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b899"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94230f71",
    "firstName": "Ajay Kumar Sinha",
    "email": "0_default_sbi04498@sbi.co.in",
    "mobileNo": "0_DEFAULT_022-25372748",
    "workMobileNo": "0_DEFAULT_91-9953680140"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "6418456a96b58848585f8cb2",

```

```
"name": "Thane",
"email": "thane@vastukala.com",
"phone": "1234567890",
"address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
"city": "Thane",
"shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b899",
  "branchCode": "000127",
  "type": "BRANCH",
  "name": "RACPC Thane ",
  "email": "rasecc.thane@sbi.co.in",
  "mobileNo": "02220812026",
  "alternateMobileNo": "02220812027",
  "address": "Retail Assets Centralized, Processing Centre,Dosti Pinnacle , Plot no
E7,Near New Passport Office,Gate No-3,Road No 22,Panchpakhadi Village Wagle Indl
Estate,Thane- 400604\r\n",
  "ledgerName": "STATE BANK OF INDIA - THANE RACPC",
  "fax": "2538 2750 ",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "64abdb2806d6ec174986d16b",
  "role": "PICKUPPERSON",
  "firstName": "Sahadu",
  "email": "thoratsahadu8679@gmail.com",
  "lastName": "Thorat",
  "mobileNo": "9422389642",
  "shortName": "ST",
  "workWithDocumentMaker": ""
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62ea09ea4e679b264caf07d7",
  "role": "SITEENGINEER",
  "firstName": "Suraj",
  "email": "suraj@vastukala.org",
  "lastName": "Zore",
  "mobileNo": "8652448654",
  "designation": "",
  "shortName": "SZ",
  "workWithDocumentMaker": "60092304a16fab0f2af9b0c2",
  "profilePhoto": "users/62ea09ea4e679b264caf07d7/
profilePhoto_1685629394240_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "627221f4afd7d55eddeddcb4",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Prajakta",
  "email": "prajakta@vastukala.org",
  "lastName": "Patil",
  "mobileNo": "9769797568",
  "designation": "",
  "shortName": "P",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "MAKER",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
  "mobileNo": "9821518537",
```

```
"designation": "",
"shortName": "PS",
"workWithDocumentMaker": "",
"profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": "",
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
"value": "FIIV",
"label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
"title": {
"value": "Chartered_Engineer",
"label": "Chartered Engineer"
},
"_id": "60af80072ffdf65bcd658653",
"number": "AM161706-3"
}
```

```
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.22416660739812",
  "longitude": "72.98520647116372"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-09-26",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-09-26",
```

```
    "remark": ""
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Dhokali",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "20",
    "label": false
  },
  "buildingNo": {
```

```
"status": false,
"name": "Building No",
"key": "buildingNo",
"value": "",
"label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Thane (West)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Park - 2, The Icon Phase 4 Project",
```

```
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Highland Gardens Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Opp. Highland Garden",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "C - 1",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
```



```
"name": "Old Survey No.",
"key": "oldSurveyNumber",
"value": "",
"label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "60/19, 60/21, 60/22, 63/5C, 63/9",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "2001",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
}
```

```
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 400 607",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
```

```
"key": "suburb",
"value": "",
"label": false
},
"flatSpecifications": {
  "roof": {
    "value": "Proposed_RCC_SLab",
    "label": "Proposed RCC SLab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Proposed_Teak_wood_door_frame_with_flush_doors",
    "label": "Proposed Teak wood door frame with flush doors"
  },
  "windows": {
    "value": "Proposed_Powder_coated_aluminium_sliding_windows",
    "label": "Proposed Powder coated aluminium sliding windows"
  },
  "fittings": {
    "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Concealed_wiring",
    "label": "Proposed Concealed plumbing with C.P. fittings. Concealed wiring"
  },
  "finishing": {
    "value": "Proposed_Cement_Plastering",
    "label": "Proposed Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "sole_ownership",
    "label": "sole ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Thane_Municipal_Corporation",
```

```
"label": "Thane Municipal Corporation"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Wing M-2 ",
  "west": "Internal Road",
  "south": "Wing P-1",
  "east": "Narayana e-Techno School"
},
"asPerDocumentAgreement": {
  "north": "Details not available",
  "west": "Details not available",
  "south": "Details not available",
  "east": "Details not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "asPerDocument": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of Approved Building Plan No. S05 / 0075 / 14 /
TMC / TD-DP / TPS / 3857 / 14 dated 07.01.2022 issued by Thane Municipal
Corporation. (Download from RERA).",
"approvePlanVerified": "",
"empanelledOfApprovePlan": ""
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
```

```
"depreciatedCostOfConstruction": "",
"depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Dhokali",
  "rate": "116300",
  "landRate": "37500",
  "igrImage": "cases/651264d00c1bfd1d9fe2002e/igr_1695804108891_Image.png",
  "squareMeterGuideLineRate": "127930.00",
  "squareFeetGuideLineRate": "11885.00"
},
"igrFinalRate": {
  "depreciationPercentage": "0",
  "rate": "116300",
  "squareMeterGuideLineRate": "127930.00",
  "squareFeetGuideLineRate": "11885.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Middle_Class",
    "label": "Middle Class"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  },
  "monthlyRent": "21000.00",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per TMC norms",
  "tenantName": "",
  "maintenanceOfFlat": "Building is under construction"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  }
},
```

```
"anyFavouringForExtraPotentialValue": "Located in developed area",
"negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "partitions": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  },
  "waterTank": {
    "value": "Proposed_Municipal_Water_Supply",
    "label": "Proposed Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Proposed,_Yes",
    "label": "Proposed, Yes"
  },
  "carParking": "Along with one Open Car Parking",
  "constructionWorkStatus": {
    "value": "InProgress",
    "label": "Under Construction"
  },
  "asthetikLook": {
    "value": "Information_Not_Available",
    "label": "Information Not Available"
  },
  "dateOfConstruction": {
    "date": "",
    "month": "1",
    "year": "2026",
    "fullDate": "1/1/2026"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  },
  "typeOfStructure": {
    "value": "Proposed_R.C.C._Framed_Structure",
    "label": "Proposed R.C.C Framed Structure"
  },
  "typeOfFoundation": {
    "value": "rcc",
    "label": "R.C.C. Foundation"
  }
}
```

```
},
"qualityOfConstruction": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"materialUsedList": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"buildingSpecification": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"structuralSafety": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "Proposed_Connected_to_Municipal_Sewerage_System_",
  "label": "Proposed Connected to Municipal Sewerage System "
},
"walls": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"appearanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenanceOfTheBuilding": {
  "value": "Building_is_under_construction_",
  "label": "Building is under construction "
},
"maintenanceIssues": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"visibleDamageInBuilding": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"systemOfAirConditioning": {
```

```
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  },
  "provisionOfFirefighting": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  },
  "groundStilt": {
    "value": "ground",
    "label": "Ground"
  },
  "yearOfConstructionAsPer": {
    "value": "Approx.",
    "label": "Approx."
  },
  "isSiteVisitAllowed": true,
  "totalLifeBuilding": "",
  "estimatedAge": "0",
  "ageOfBuilding": "0",
  "noOfBasement": "",
  "noOfPodium": "",
  "noOfAmenityFloors": "",
  "noOfFloors": "29",
  "flatFloorNo": "",
  "noOfLifts": "3",
  "noOfDwellingUnitsInBuilding": "8"
},
"finalPlinthArea": {
  "area": "474.10",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  },
  "routeMapImg": "cases/651264d00c1bfd1d9fe2002e/
routeMap_1695982848776_Image.png",
  "routeLat": "19.222823",
  "routeLng": "72.985773",
  "stationName": "Thane",
  "routeDistance": "4.9 Km"
},
"finalLatLng": {
```



```
"coordinates": [
  null,
  null
],
"type": "Point"
},
"showLocation": {
  "latlng": true,
  "finallatlng": true
},
"locationMapImg": [
  {
    "id": "5jgj47",
    "name": "5jgj47",
    "image": "cases/651264d00c1bfd1d9fe2002e/
routeMap_1695982776710_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
```

```
"totalOthersRate": "0",
"finalTotal": "8404500.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "8404500.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "3",
    "percentage": "3.870967741935484",
    "isHideFloor": false,
    "status": true
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "13.87",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "5634679.00",
  "selectedBuildUpValue": "474.10",
```

```
"selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "6512d9aa0c1bfd1d9fe4398a",
      "name": "externallmg_r_1695734162409_1695734061311_image_2.jpg",
      "path": "cases/651264d00c1bfd1d9fe2002e/
externallmg_r_1695734162409_1695734061311_image_2.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "6512d9aa0c1bfd1d9fe4398d",
      "name": "externallmg_r_1695734169472_1695734061311_image_4.jpg",
      "path": "cases/651264d00c1bfd1d9fe2002e/
externallmg_r_1695734169472_1695734061311_image_4.jpg",
      "orientation": "landscape"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "6512d9aa0c1bfd1d9fe4398c",
      "name": "externallmg_r_1695734153507_1695734061311_image_0.jpg",
      "path": "cases/651264d00c1bfd1d9fe2002e/
externallmg_r_1695734153507_1695734061311_image_0.jpg",
      "orientation": "portrait"
    }
  ],
  "parkingImages": [],
  "societyNameBoardImage": [
    {
      "status": false,
      "_id": "6512d9aa0c1bfd1d9fe4398a",
      "name": "externallmg_r_1695734162409_1695734061311_image_2.jpg",
      "path": "cases/651264d00c1bfd1d9fe2002e/
externallmg_r_1695734162409_1695734061311_image_2.jpg",
      "orientation": "portrait"
    }
  ],
  "compositionImages": [
    {
```

```
    "status": false,
    "_id": "6512d9aa0c1bfd1d9fe43989",
    "name": "Bedroom",
    "path": "cases/651264d00c1bfd1d9fe2002e/
externallmg_r_1695734165531_1695734061311_image_3.jpg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": null,
    "max": null
  },
  "builtUpRateRange": {
    "min": null,
    "max": null
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
}
```

```
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "431.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentId": [],
```



```
"_id": "651264d00c1bfd1d9fe2002e",
"ownerName": "Mr. Aiyaz Sagir Ahmed",
"ownerPhoneNo": "8657102013",
"fullAddress": "Residential Flat No. 2001, 20th Floor, Wing - C - 1, Park - 2, The Icon
Phase 4 Project, Opp. Highland Garden, Highland Gardens Road, Village - Dhokali,
Taluka - Thane, District - Thane, Thane (West), PIN Code - 400 607, State -
Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "18/09/2023",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "Leading Frontier Private Limited and Other",
      "to": {
        "value": "purchaser",
        "label": "purchaser"
      },
      "purchaser": "Mr. Aiyaz Sagir Ahmed"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "219474",
    "path": "cases/651264d00c1bfd1d9fe2002e/
document_1695704227089_Adobe_Scan_25Sep2023.pdf",
    "fileName": "document_1695704227089_Adobe_Scan_25Sep2023.pdf"
  },
  {
    "documentType": {
      "value": "60ae129faa6d152c1801b47d",
      "label": "RERA Certificate"
    },
    "inputs": {
      "documentDate": "23/04/2021",
      "nameOfApprovingAuthority": {
        "value": "Maharashtra_Real_Estate_Regulatory_Authority",
        "label": "Maharashtra Real Estate Regulatory Authority"
      },
      "number": {
```

```
    "value": "No",
    "label": "No"
  },
  "No": "P51700029062"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1695981544056_P51700018370_3.pdf",
"path": "cases/651264d00c1bfd1d9fe2002e/
document_1695981544056_P51700018370_3.pdf",
"id": "852940",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Fri Sep 29 2023 15:29:04 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1279aa6d152c1801b3d4",
    "label": "Amended Commencement Certificate"
  },
  "inputs": {
    "documentDate": "07/01/2022",
    "nameOfApprovingAuthority": {
      "value": "Thane_Municipal_Corporation",
      "label": "Thane Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "S05 / 0075 / 14 / TMC / TDD / 3857 / 22"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1695981748970_2_Commencement_Certificates___NA_Order_for_plotted_development_62.pdf",
"path": "cases/651264d00c1bfd1d9fe2002e/document_1695981748970_2_Commencement_Certificates___NA_Order_for_plotted_development_62.pdf",
"id": "450488",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Fri Sep 29 2023 15:32:29 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
}
```

```
"inputs": {
  "documentDate": "07/01/2022",
  "nameOfApprovingAuthority": {
    "value": "Thane_Municipal_Corporation",
    "label": "Thane Municipal Corporation"
  },
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "S05 / 0075 / 14 / TMC / TD-DP / TPS / 3857 / 14"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1695981976062_4_Building_Plan_Approval___NA_Order_f
or_plotted_development_11.pdf",
"path": "cases/651264d00c1bfd1d9fe2002e/document_1695981976062_4_Building
_Plan_Approval___NA_Order_for_plotted_development_11.pdf",
"id": "653171",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Fri Sep 29 2023 15:36:16 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "004029",
"createdBy": "6430f74691d7c62df11f3f15",
"caseHistory": [
  {
    "id": "411197",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Sep 26 2023 10:27:52 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Aiyaz Sagir Ahmed",
    "phone": "8657102013",
    "ownershipShare": "100",
    "email": "",
    "id": "902126"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
```

```
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "1",
"name": "Living Room",
"length": "0.00",
"length1": "0",
"length2": "0",
"width": "0.00",
"width1": "0",
"width2": "0",
"totalArea": "0.00",
"images": [],
"finalArea": "0.00",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Bedroom",
  "length": "0.00",
  "length1": "0",
  "length2": "00",
  "width": "0.00",
  "width1": "0",
  "width2": "00",
  "totalArea": "0.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "0.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Kitchen",
  "length": "0.00",
  "length1": "0",
  "length2": "00",
  "width": "0.00",
```

```
"width1": "0",
"width2": "00",
"totalArea": "0.00",
"images": [],
"extraAreas": [],
"finalArea": "0.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Passage",
  "length": "0.00",
  "length1": "0",
  "length2": "00",
  "width": "0.00",
  "width1": "0",
  "width2": "00",
  "totalArea": "0.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "0.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "0.00",
  "length1": "0",
  "length2": "00",
  "width": "0.00",
  "width1": "0",
  "width2": "00",
  "totalArea": "0.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "0.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
```

```
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Toilet",
  "length": "0.00",
  "length1": "0",
  "length2": "00",
  "width": "0.00",
  "width1": "0",
  "width2": "00",
  "totalArea": "0.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "0.00"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "40.04",
    "totalAreaDocument": "431",
    "docBuiltupPercentage": "10",
    "docFinalBuiltUp": "474.10",
    "docFinalBuiltUpSquareMeter": "44.05",
    "docSaleablePercentage": "",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "791143"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": false,
    "_id": "6513eadb0c1bfd1d9fe57bc2",
    "property": "The Icon, Dhokali, Thane",
  }
]
```

```
"area": "756",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"source": "https://www.99acres.com/",
"expectedPrice": "14800000",
"expectedRate": "19576.72",
"builtUpExpectedRate": "17797.02",
"image": "cases/651264d00c1bfd1d9fe2002e/
indicator_1695803975433_Image.png",
"squareMeter": "70.23",
"id": "435627"
},
{
  "printlnReport": false,
  "_id": "6513eadb0c1bfd1d9fe57bc3",
  "property": "Risland The Icon",
  "area": "429",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "Housing.Com",
  "expectedPrice": "8200000",
  "expectedRate": "19114.22",
  "builtUpExpectedRate": "17376.56",
  "image": "cases/651264d00c1bfd1d9fe2002e/
indicator_1695804008574_Image.png",
  "squareMeter": "39.86",
  "id": "500597"
},
{
  "printlnReport": false,
  "_id": "6513eadb0c1bfd1d9fe57bc4",
  "property": "The Icon, Dhokali, Thane",
  "area": "449",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "magic_bricks",
  "expectedPrice": "8250000",
  "expectedRate": "18374.16",
  "builtUpExpectedRate": "16703.79",
  "image": "cases/651264d00c1bfd1d9fe2002e/
indicator_1695804041793_Image.png",
```

```
"squareMeter": "41.71",
"id": "965490"
},
{
  "printlnReport": false,
  "_id": "6513eadb0c1bfd1d9fe57bc5",
  "property": "The Icon, Dhokali, Thane",
  "area": "750",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "magic_bricks",
  "expectedPrice": "15000000",
  "expectedRate": "20000.00",
  "builtUpExpectedRate": "18181.82",
  "image": "cases/651264d00c1bfd1d9fe2002e/
indicator_1695804072094_Image.png",
  "squareMeter": "69.68",
  "id": "878525"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6512d9aa0c1bfd1d9fe43989",
    "name": "externalImg_r_1695734165531_1695734061311_image_3.jpg",
    "path": "cases/651264d00c1bfd1d9fe2002e/
externalImg_r_1695734165531_1695734061311_image_3.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6512d9aa0c1bfd1d9fe4398a",
    "name": "externalImg_r_1695734162409_1695734061311_image_2.jpg",
    "path": "cases/651264d00c1bfd1d9fe2002e/
externalImg_r_1695734162409_1695734061311_image_2.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6512d9aa0c1bfd1d9fe4398b",
    "name": "externalImg_r_1695734158644_1695734061311_image_1.jpg",
```



```
    "path": "cases/651264d00c1bfd1d9fe2002e/
externallmg_r_1695734158644_1695734061311_image_1.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6512d9aa0c1bfd1d9fe4398c",
    "name": "externallmg_r_1695734153507_1695734061311_image_0.jpg",
    "path": "cases/651264d00c1bfd1d9fe2002e/
externallmg_r_1695734153507_1695734061311_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6512d9aa0c1bfd1d9fe4398d",
    "name": "externallmg_r_1695734169472_1695734061311_image_4.jpg",
    "path": "cases/651264d00c1bfd1d9fe2002e/
externallmg_r_1695734169472_1695734061311_image_4.jpg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6512d9aa0c1bfd1d9fe4398e",
    "name": "externallmg_r_1695734137112_1695734046132_image_0.png",
    "path": "cases/651264d00c1bfd1d9fe2002e/
externallmg_r_1695734137112_1695734046132_image_0.png",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6512d9aa0c1bfd1d9fe4398f",
    "name": "externallmg_r_1695734137428_1695734046132_image_1.jpg",
    "path": "cases/651264d00c1bfd1d9fe2002e/
externallmg_r_1695734137428_1695734046132_image_1.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-09-26T04:57:52.527Z",
"updatedAt": "2023-09-29T11:00:04.114Z",
```

```
"__v": 0,
"invoiceId": "651264d00c1bfd1d9fe20045",
"updatedBy": "627222afafd7d55eddedd82",
"addressForMap": "",
"caseReferredBy": "64abdb2806d6ec174986d16b",
"contactPersonName": "Mr. Amit",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "100",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "CRM",
"siteVisitContactNo": "9967550806",
"siteVisitDate": "2023-09-26",
"buildingServicesRate": "2800",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 431.00",
"flatRate": "19500",
"landOtherRate": "16700",
"finalSaleablePercentage": "",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
  "leaseFrom": "",
  "leaseTo": "",
  "remainingLeasePeriod": 0,
  "leaseDate": ""
}
},
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Passage + 2 Toilet",
"carpetTotal": "0.00",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"extendOfSiteRemark": "",
```

"finalBuiltupArea": "0.00",
"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": ""

}

Name	Length	Width	Total
Composition :			
Living Room	0'0"	0'0"	0.00
Bedroom	0'00"	0'00"	0.00
Kitchen	0'00"	0'00"	0.00
Passage	0'00"	0'00"	0.00
Toilet	0'00"	0'00"	0.00
Toilet	0'00"	0'00"	0.00
Other Composition :			