## Deepak jain

## Inspection report of Residential/ Commercial/ Industrial properties

Name of Bank: sbi Date of inspection:26-9-2023

Name of Bank: SD1 Date of inspection:26-9-2023		
	Name of the Applicant	Shilpa perulkar
1.	Type of property:	Residental flat
2.	Address of the property	Flat No 2105,21st Floor D Wing Building No
3.	Magnet Pailway station	2 Pahadi Village Goregaon West
3.	Nearest Railway station	1.2 km away from goregaon station
4.	Name of the road access to	Off s.v road
5.	the property	Dether callege
5.	Landmark/vicinity:	Patkar college
6.	Boundaries of the building	North: bldg no 3ABCD/416 mahada society
		south : road
		east: under constrution property
		west: wing 2 ABC
7.	Locality	Type : Residential / Commercial / Industrial /
		Mix
		Class of people: Lower class/Middle class/
		Upper Middle class/ Higher class
		Opper whome classy i figher class
		Site is: Normal/ above road/ below road
8.	Permitted Land Use	Residential/Commercial/Industrial/Mix
9.	Actual Land Use	Residential/Commercial/Industrial/Mix
10.	Availability of other	School
	amenities in the	Market
	surrounding	College
		Temple
11.	Surrounding development	Developed/Well Developed
12.	Occupant	vacant
13.	Building details	Type of Structure: : (RCC/Load Beaing)
		No. of Floors: stilt+23 <sup>rd</sup> floor
		No of wings:4
		No. of flats/units on each :8 flat
14.	No. of lifts with capacity &	2 no with 8 person capacity
	Status	
15.	Underground & Overhead	1 no. Overhead Tank &
	tanks	1 no. Under ground Tank
16.	Year of Construction	Recently completed
17.	Age of the building	00years
18.	Estimated future life of the	60 years
10	building	Cool
19.	Building elevation	Good
20.	Condition of the building:	Good
21.	Finishing	Luster paint / cement
22.	Amenities	Parking ,

23.	Flooring in open spaces and staircase	Open Space Garden tiles & Kotastone staircase
24.	Doors & Windows	Wooden door/safty door
25.	Compound wall & no. of gates	6 ft height of compound wall & nos. of MS Gates & security
26.	Č	1 bhk
27.	View from the different rooms of the property	building
28.	Internal finishing	Flooring in different rooms: internal visit not allowed Kitchen Platform: Electrical: OPEN / CONCEALED Plumbing: OPEN / CONCEALED
29.	Balcony	_
31	Carpet area as per Measurement :	322sq feet as per rera carpet
32	Nearest Bus stop	Patkar college
33	Nearest Hospital	Shree sai clinic
34	Condition of Road	30 feet good wide road
35	Rate per sq ft.	
36	Person Met at Site	Mahada supervisor
37	Coordinate	19.169200,72.842823
38	Name on society board	Na
39	Name on door	Na

## REMARKS:

1:the said property internal visit noyt allowed .