

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9f4"
    },
    "type": "CREDITOFFICER",
    "_id": "650581d3a8e9b70221e855e5",
    "firstName": "Bhakti",
    "lastName": "Podkar",
    "mobileNo": "",
    "workMobileNo": "8425827511",
    "email": "Bhakti.racpc.sion@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5000000",
    "discussWithPerson": "Bhakti",
    "expectedFees": 2500,
    "quotedAmount": "2500"
  },
  "organization": {
```

```
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9f4",
  "branchCode": "000215",
  "type": "BRANCH",
  "name": "RACPC Sion ",
  "email": "racpc.sion@sbi.co.in",
  "mobileNo": "02225046265",
  "alternateMobileNo": "",
  "address": "B-603 & 604, Kohinoor City, Commercial-1, 6th Floor, Kirol Road, Off
L.B.S. Marg, Kurla (West), Mumbai, Pin Code - 400 070, State - Maharashtra, Country -
India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62ea09ea4e679b264caf07d7",
  "role": "SITEENGINEER",
  "firstName": "Suraj",
  "email": "suraj@vastukala.org",
  "lastName": "Zore",
  "mobileNo": "8652448654",
  "designation": "",
  "shortName": "SZ",
  "workWithDocumentMaker": "60092304a16fab0f2af9b0c2",
  "profilePhoto": "users/62ea09ea4e679b264caf07d7/
profilePhoto_1685629394240_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shyam_Photo.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60eebe33f3dd69653a5837ae",
  "role": "MAKER",
  "firstName": "Shamal",
  "email": "shamal@vastukala.org",
```

```
"lastName": "Bodke",
"mobileNo": "9821740317",
"designation": "",
"shortName": "SB",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eebe33f3dd69653a5837ae\
\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
},
"checker": "",
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        },
        "_id": "60af80072ffdf65bcd658652",
        "number": "CAT-I-F-1763"
      },
      {
        "title": {
          "value": "Chartered_Engineer",
          "label": "Chartered Engineer"
        }
      },
    ]
  }
]
```

```
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.285354852968236",
  "longitude": "73.08209466996288"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.08209466996288,
    19.285354852968236
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-09-27",
      "remark": ""
    }
  ]
}
]
```

```
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Temghar",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "1",
    "label": false
  },
  "buildingNo": {
    "status": true,
    "name": "Building No",
    "key": "buildingNo",
```

```
"value": "4",
"label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Bhiwandi",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Bhiwandi",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Shivaalik Park",
  "label": false
},
"selectArea": {
```

```
"status": false,
"name": "Sector",
"key": "selectArea",
"value": "",
"label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Kalyan Bhiwandi Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "C",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
```



```
"label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "80/16/A/1, 80/16A/6, 73/2, 74/1/77/1/80/16/U/80/16",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "110",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
```

```
"name": "Khata No",
"key": "khataNo",
"value": "",
"label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 421 302",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
```

```

    }
  },
  "flatSpecifications": {
    "roof": {
      "value": "rcc_Slab",
      "label": "R. C. C. Slab"
    },
    "flooring": {
      "value": "Proposed_Vitrified_tiles_flooring",
      "label": "Proposed Vitrified tiles flooring"
    },
    "doors": {
      "value": "Proposed_Teak_wood_door_frame_with_flush_doors",
      "label": "Proposed Teak wood door frame with flush doors"
    },
    "windows": {
      "value": "Proposed_Powder_coated_aluminium_sliding_windows",
      "label": "Proposed Powder coated aluminium sliding windows"
    },
    "fittings": {
      "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
      "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
    },
    "finishing": {
      "value": "Building_Under_Construction",
      "label": "Building Under Construction"
    }
  },
  "general": {
    "ownership": {
      "value": "Joint_Ownership",
      "label": "Joint Ownership"
    },
    "populationClassList": {
      "value": "MiddleClass",
      "label": "Middle Class"
    },
    "populationGroupList": {
      "value": "Urban",
      "label": "Urban"
    },
    "townplanApprovedByList": {
      "value": "Bhiwandi_Nizampur_Municipal_Council",
      "label": "Bhiwandi Nizampur Municipal Council"
    }
  },

```

```
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Building No. 3",
  "west": "Sales Office",
  "south": "Building No. 5",
  "east": "Internal Road"
},
"asPerDocumentAgreement": {
  "north": "Details not available",
  "west": "Details not available",
  "south": "Details not available",
  "east": "Details not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "As per approved plan & Agreement sale plan, the
composition of flat is 2 Bedrooms + Living Room + Kitchen + WC & Bath + Balcony
(i.e., 2 BHK + W.C. + Bath). ",
"dateOfIssusApprovePlan": "",
"approvePlanVerified": "",
"empanelledOfApprovePlan": ""
},
"compositeRate": {
  "remark": "Internal visit not allowed at site. The details about the work progress
status has been provided by Sales Person Mayuri (Contact No. 8888048222)",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": ""
```

```
"depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "45500",
  "landRate": "10200",
  "igrImage": "cases/6512bc530c1bfd1d9fe3caf8/igr_1696076700953_Image.png",
  "squareMeterGuideLineRate": "47775.00",
  "squareFeetGuideLineRate": "4438.00"
},
"igrFinalRate": {
  "depreciationPercentage": "0",
  "rate": "45500",
  "squareMeterGuideLineRate": "47775.00",
  "squareFeetGuideLineRate": "4438.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  },
  "monthlyRent": "5,000",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per local norms",
  "tenantName": "",
  "maintenanceOfFlat": "Building Under Construction"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
```

```
"negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "Proposed_RCC_SLab",
    "label": "Proposed RCC SLab"
  },
  "partitions": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  },
  "waterTank": {
    "value": "Proposed_Municipal_Water_Supply",
    "label": "Proposed Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  },
  "carParking": "Proposed Open Car Parking",
  "constructionWorkStatus": {
    "value": "InProgress",
    "label": "Under Construction"
  },
  "asthetikLook": {
    "value": "Information_Not_Available",
    "label": "Information Not Available"
  },
  "dateOfConstruction": {
    "date": "",
    "month": "1",
    "year": "2023",
    "fullDate": "1/1/2023"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  },
  "typeOfStructure": {
    "value": "Proposed_R.C.C_Framed_Structure",
    "label": "Proposed R.C.C Framed Structure"
  },
  "typeOfFoundation": {
    "value": "rcc",
    "label": "R.C.C. Foundation"
  },
}
```

```
"qualityOfConstruction": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"materialUsedList": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"buildingSpecification": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"structuralSafety": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "Proposed_Connected_to_Municipal_Sewerage_System_",
  "label": "Proposed Connected to Municipal Sewerage System "
},
"walls": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"appearanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenancelssues": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"visibleDamageInBuilding": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"systemOfAirConditioning": {
  "value": "Building_Under_Construction",
```

```
"label": "Building Under Construction"
},
"provisionOfFirefighting": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "Approx.",
  "label": "Approx."
},
"isSiteVisitAllowed": false,
"totalLifeBuilding": "",
"estimatedAge": "0",
"ageOfBuilding": "0",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "4",
"flatFloorNo": "",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "401.50",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/6512bc530c1bfd1d9fe3caf8/
routeMap_1696311790015_Image.png",
    "routeLat": "19.284944",
    "routeLng": "73.082722",
    "stationName": "Bhiwandi Road",
    "routeDistance": "4.8 Km."
  },
  "finalLatLng": {
    "coordinates": [
```



```
    null,
    null
  ],
  "type": "Point"
},
"showLocation": {
  "latlng": true,
  "finallatlng": true
},
"locationMapImg": [
  {
    "id": "d92zml",
    "name": "d92zml",
    "image": "cases/6512bc530c1bfd1d9fe3caf8/
routeMap_1696311712225_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
```

```
"finaltotal": "2482000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "2482000.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "6",
    "percentage": "40",
    "isHideFloor": false,
    "status": true
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "6",
    "percentage": "7.00",
    "isHideFloor": false,
    "status": true
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "6",
    "percentage": "7.00",
```

```
"isHideFloor": false,
"status": true
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "4",
  "percentage": "2.33",
  "isHideFloor": false,
  "status": true
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "6",
  "percentage": "3.50",
  "isHideFloor": false,
  "status": true
},
"door": {
  "label": "Door",
  "floorsCompleted": "3",
  "percentage": "1.25",
  "isHideFloor": false,
  "status": true
},
"window": {
  "label": "Window",
  "floorsCompleted": "3",
  "percentage": "1.25",
  "isHideFloor": false,
  "status": true
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "3",
  "percentage": "5.00",
  "isHideFloor": false,
  "status": true
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "3",
  "percentage": "0.75",
  "isHideFloor": false,
  "status": true
},
"externalPainting": {
```

```
"label": "External Painting",
"floorsCompleted": "3",
"percentage": "0.75",
"isHideFloor": false,
"status": true
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "3",
"percentage": "2.50",
"isHideFloor": false,
"status": true
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "81.33",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "1781857.00",
"selectedBuildUpValue": "401.50",
"selectedBuildUpMeasurementType": "Sq. Ft."
}
```

```
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "65140c720c1bfd1d9fe63170",
      "name": "externallmg_r_1695812679589_1695812582094_image_0.jpg",
      "path": "cases/6512bc530c1bfd1d9fe3caf8/
externallmg_r_1695812679589_1695812582094_image_0.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "65140c720c1bfd1d9fe6316e",
      "name": "externallmg_r_1695812689929_1695812582094_image_2.jpg",
      "path": "cases/6512bc530c1bfd1d9fe3caf8/
externallmg_r_1695812689929_1695812582094_image_2.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "65140c720c1bfd1d9fe6316f",
      "name": "externallmg_r_1695812685328_1695812582094_image_1.jpg",
      "path": "cases/6512bc530c1bfd1d9fe3caf8/
externallmg_r_1695812685328_1695812582094_image_1.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "65140c720c1bfd1d9fe63172",
      "name": "externallmg_r_1695812700117_1695812582094_image_4.jpg",
      "path": "cases/6512bc530c1bfd1d9fe3caf8/
externallmg_r_1695812700117_1695812582094_image_4.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "65140c720c1bfd1d9fe63170",
      "name": "externallmg_r_1695812679589_1695812582094_image_0.jpg",
      "path": "cases/6512bc530c1bfd1d9fe3caf8/
externallmg_r_1695812679589_1695812582094_image_0.jpg",
      "orientation": "portrait"
    }
  ]
}
```

```
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "6456",
    "max": "8043"
  },
  "builtUpRateRange": {
    "min": "5870",
    "max": "7312"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
```

```
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "365.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentId": [],
"_id": "6512bc530c1bfd1d9fe3caf8",
"ownerName": "Atish Mallikarjun Vhatkar & Ashwini Mallikarjun Vhatkar",
"ownerPhoneNo": "8655370922",
"appAddress": "Flat no. 110, 1st Floor, Building no. 4, Wing - C, Shivaalik Park,
```



```
Temghar, Bhiwandi ",
"remark": "",
"documents": [
{
"documentType": {
"label": "Agreement For Sale",
"value": "60ae1254aa6d152c1801b326"
},
"inputs": {
"documentDate": "12/05/2022",
"from": {
"value": "Developers",
"label": "Developers"
},
"Developers": "M/s. Sun Realtors",
"to": {
"value": "Purchasers",
"label": "Purchasers"
},
"Purchasers": "Atish Mallikarjun Vhatkar & Ashwini Mallikarjun Vhatkar"
},
"isHardCopy": false,
"displayStatus": true,
"id": "814672",
"path": "cases/6512bc530c1bfd1d9fe3caf8/
document_1695726616691_Racpc_Sion_Atish_Vhatkar.pdf",
"fileName": "document_1695726616691_Racpc_Sion_Atish_Vhatkar.pdf"
},
{
"documentType": {
"value": "60ae1247aa6d152c1801b2ea",
"label": "Commencement Certificate"
},
"inputs": {
"documentDate": "03/01/2020",
"nameOfApprovingAuthority": {
"value": "Bhiwandi_Nizampur_City_Municipal_Corporation",
"label": "Bhiwandi Nizampur City Municipal Corporation"
},
"number": {
"value": "No",
"label": "No"
},
"No": "B.P.No. 65 / 2019-2020 / J. K. N. R. V. / 122"
},
"isHardCopy": false,
```

```
"displayStatus": false,
"fileName": "document_1696310875736_1_Commencement_Certificates___NA_Order_for_plotted_development.pdf",
"path": "cases/6512bc530c1bfd1d9fe3caf8/document_1696310875736_1_Commencement_Certificates___NA_Order_for_plotted_development.pdf",
"id": "268063",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Tue Oct 03 2023 10:57:55 GMT+0530 (India Standard Time)"
},
{
"documentType": {
"value": "60ae1277aa6d152c1801b3cc",
"label": "Approved Building Plan"
},
"inputs": {
"documentDate": "03/01/2020",
"nameOfApprovingAuthority": {
"value": "Bhiwandi_Nizampur_City_Municipal_Corporation",
"label": "Bhiwandi Nizampur City Municipal Corporation"
},
"number": {
"value": "No",
"label": "No"
},
},
"No": "B.P.No. 65 / 2019-2020 / J. K. N. R. V. / 122"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1696310940998_1_Building_Plan_Approval___NA_Order_for_plotted_development.pdf",
"path": "cases/6512bc530c1bfd1d9fe3caf8/document_1696310940998_1_Building_Plan_Approval___NA_Order_for_plotted_development.pdf",
"id": "707972",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Tue Oct 03 2023 10:59:01 GMT+0530 (India Standard Time)"
},
{
"documentType": {
"value": "60ae129faa6d152c1801b47d",
"label": "RERA Certificate"
},
"inputs": {
"documentDate": "08/09/2021",
"nameOfApprovingAuthority": {
"value": "Maharashtra_Real_Estate_Regulatory_Authority",
"label": "Maharashtra Real Estate Regulatory Authority"
}
```

```
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "P51700023966"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1696310990559_P51700023966.pdf",
  "path": "cases/6512bc530c1bfd1d9fe3caf8/
document_1696310990559_P51700023966.pdf",
  "id": "349022",
  "uploadedBy": "60eebe33f3dd69653a5837ae",
  "createdAt": "Tue Oct 03 2023 10:59:50 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "004049",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "741987",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Sep 26 2023 16:41:15 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Atish Mallikarjun Vhatkar & Ashwini Mallikarjun Vhatkar",
    "phone": "8655370922",
    "ownershipShare": "",
    "email": "",
    "id": "891071"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    }
  }
]
```

```
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "33.91",
    "totalAreaDocument": "365",
    "docBultupPercentage": "10",
    "docFinalBultUp": "401.50",
    "docFinalBultUpSquareMeter": "37.30",
    "docSaleablePercentage": "",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "216429"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "651813a52c6c0778ddf14a4b",
    "property": "Residential Flat",
    "area": "375",
    "bultUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "sale_Instance",
    "areaType": "Carpet",
    "source": "Index_no.2",
    "expectedPrice": "2470000",
    "expectedRate": "6586.67",
    "bultUpExpectedRate": "5987.88",
    "image": "cases/6512bc530c1bfd1d9fe3caf8/
indicator_1696076495541_Image.jpeg",
    "squareMeter": "34.84",
    "id": "955988"
  },
  {
    "printlnReport": true,
    "_id": "651813a52c6c0778ddf14a4c",
    "property": "Residential Flat",
    "area": "365",
    "bultUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "sale_Instance",
    "areaType": "Carpet",
```

```
"source": "Index_no.2",
"expectedPrice": "2465000",
"expectedRate": "6753.42",
"builtUpExpectedRate": "6139.48",
"image": "cases/6512bc530c1bfd1d9fe3caf8/
indicator_1696076531031_Image.jpeg",
"squareMeter": "33.91",
"id": "495955"
},
{
"printlnReport": true,
"_id": "651813a52c6c0778ddf14a4d",
"property": "Residential Flat",
"area": "365",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"source": "Index_no.2",
"expectedPrice": "2400000",
"expectedRate": "6575.34",
"builtUpExpectedRate": "5977.58",
"image": "cases/6512bc530c1bfd1d9fe3caf8/
indicator_1696076559298_Image.jpeg",
"squareMeter": "33.91",
"id": "609642"
},
{
"printlnReport": true,
"_id": "651813a52c6c0778ddf14a4e",
"property": "Residential Flat",
"area": "375",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "1",
"source": "Index_no.2",
"expectedPrice": "2421111",
"expectedRate": "6456.30",
"builtUpExpectedRate": "5869.36",
"image": "cases/6512bc530c1bfd1d9fe3caf8/
indicator_1696076600407_Image.jpeg",
"squareMeter": "34.84",
"id": "161893"
},
```

```

{
  "printlnReport": true,
  "_id": "651813a52c6c0778ddf14a4f",
  "property": "Residential Flat",
  "area": "373",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "https://www.proptiger.com/",
  "expectedPrice": "3000000",
  "expectedRate": "8042.90",
  "builtUpExpectedRate": "7311.72",
  "image": "cases/6512bc530c1bfd1d9fe3caf8/indicator_1696076626659_Image.png",
  "squareMeter": "34.65",
  "id": "383681"
},
{
  "printlnReport": true,
  "_id": "651813a52c6c0778ddf14a50",
  "property": "Residential Flat",
  "area": "373",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "Housing.Com",
  "expectedPrice": "3000000",
  "expectedRate": "8042.90",
  "builtUpExpectedRate": "7311.72",
  "image": "cases/6512bc530c1bfd1d9fe3caf8/indicator_1696076650016_Image.png",
  "squareMeter": "34.65",
  "id": "135811"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65140c720c1bfd1d9fe6316e",
    "name": "externalImg_r_1695812689929_1695812582094_image_2.jpg",
    "path": "cases/6512bc530c1bfd1d9fe3caf8/
externalImg_r_1695812689929_1695812582094_image_2.jpg",
    "orientation": "portrait"
  },
  {

```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65140c720c1bfd1d9fe6316f",
    "name": "externallmg_r_1695812685328_1695812582094_image_1.jpg",
    "path": "cases/6512bc530c1bfd1d9fe3caf8/
externallmg_r_1695812685328_1695812582094_image_1.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65140c720c1bfd1d9fe63170",
    "name": "externallmg_r_1695812679589_1695812582094_image_0.jpg",
    "path": "cases/6512bc530c1bfd1d9fe3caf8/
externallmg_r_1695812679589_1695812582094_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65140c720c1bfd1d9fe63171",
    "name": "externallmg_r_1695812694359_1695812582094_image_3.jpg",
    "path": "cases/6512bc530c1bfd1d9fe3caf8/
externallmg_r_1695812694359_1695812582094_image_3.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65140c720c1bfd1d9fe63172",
    "name": "externallmg_r_1695812700117_1695812582094_image_4.jpg",
    "path": "cases/6512bc530c1bfd1d9fe3caf8/
externallmg_r_1695812700117_1695812582094_image_4.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65140c720c1bfd1d9fe63173",
    "name": "externallmg_r_1695812710385_1695812582094_image_6.jpg",
    "path": "cases/6512bc530c1bfd1d9fe3caf8/
externallmg_r_1695812710385_1695812582094_image_6.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "65140c720c1bfd1d9fe63174",
  "name": "externallmg_r_1695812705464_1695812582094_image_5.jpg",
  "path": "cases/6512bc530c1bfd1d9fe3caf8/
externallmg_r_1695812705464_1695812582094_image_5.jpg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65140c720c1bfd1d9fe63175",
  "name": "externallmg_r_1695812660838_1695812563624_image_1.png",
  "path": "cases/6512bc530c1bfd1d9fe3caf8/
externallmg_r_1695812660838_1695812563624_image_1.png",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65140c720c1bfd1d9fe63176",
  "name": "externallmg_r_1695812653714_1695812563624_image_0.jpg",
  "path": "cases/6512bc530c1bfd1d9fe3caf8/
externallmg_r_1695812653714_1695812563624_image_0.jpg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "AGR.pdf",
    "filename": "1696076730058_AGR.pdf",
    "path": "cases/6512bc530c1bfd1d9fe3caf8/
processingDocuments/1696076730058_AGR.pdf",
    "size": "19059098",
    "createdAt": "Sat Sep 30 2023 17:55:31 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "externallmg_r_1695812653714_1695812563624_image_0.jpg",
    "filename":
"1696076730945_externallmg_r_1695812653714_1695812563624_image_0.jpg",
    "path": "cases/6512bc530c1bfd1d9fe3caf8/processingDocuments/1696076730945_
externallmg_r_1695812653714_1695812563624_image_0.jpg",
    "size": "2249528",
    "createdAt": "Sat Sep 30 2023 17:55:31 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  }
]
```



```
    },
    {
      "originalname": "externallmg_r_1695812660838_1695812563624_image_1.png",
      "filename":
"1696076731008_externallmg_r_1695812660838_1695812563624_image_1.png",
      "path": "cases/6512bc530c1bfd1d9fe3caf8/processingDocuments/1696076731008_
externallmg_r_1695812660838_1695812563624_image_1.png",
      "size": "980865",
      "createdAt": "Sat Sep 30 2023 17:55:31 GMT+0530 (India Standard Time)",
      "uploadedBy": "60eeaeddf3dd69653a581316"
    },
    {
      "originalname": "IGR-01.pdf",
      "filename": "1696076731072_IGR01.pdf",
      "path": "cases/6512bc530c1bfd1d9fe3caf8/
processingDocuments/1696076731072_IGR01.pdf",
      "size": "147329",
      "createdAt": "Sat Sep 30 2023 17:55:31 GMT+0530 (India Standard Time)",
      "uploadedBy": "60eeaeddf3dd69653a581316"
    },
    {
      "originalname": "IGR-02.pdf",
      "filename": "1696076731087_IGR02.pdf",
      "path": "cases/6512bc530c1bfd1d9fe3caf8/
processingDocuments/1696076731087_IGR02.pdf",
      "size": "159077",
      "createdAt": "Sat Sep 30 2023 17:55:31 GMT+0530 (India Standard Time)",
      "uploadedBy": "60eeaeddf3dd69653a581316"
    },
    {
      "originalname": "IGR-03.pdf",
      "filename": "1696076731093_IGR03.pdf",
      "path": "cases/6512bc530c1bfd1d9fe3caf8/
processingDocuments/1696076731093_IGR03.pdf",
      "size": "142547",
      "createdAt": "Sat Sep 30 2023 17:55:31 GMT+0530 (India Standard Time)",
      "uploadedBy": "60eeaeddf3dd69653a581316"
    },
    {
      "originalname": "IGR-04.pdf",
      "filename": "1696076731095_IGR04.pdf",
      "path": "cases/6512bc530c1bfd1d9fe3caf8/
processingDocuments/1696076731095_IGR04.pdf",
      "size": "150983",
      "createdAt": "Sat Sep 30 2023 17:55:31 GMT+0530 (India Standard Time)",
      "uploadedBy": "60eeaeddf3dd69653a581316"
    }
  ]
}
```

```
    },
    {
      "originalName": "IGR-05.pdf",
      "fileName": "1696076731099_IGR05.pdf",
      "path": "cases/6512bc530c1bfd1d9fe3caf8/
processingDocuments/1696076731099_IGR05.pdf",
      "size": "149492",
      "createdAt": "Sat Sep 30 2023 17:55:31 GMT+0530 (India Standard Time)",
      "uploadedBy": "60eeaeddf3dd69653a581316"
    },
    {
      "originalName": "Summary New=ATISH.xlsx",
      "fileName": "1696076731101_Summary_NewATISH.xlsx",
      "path": "cases/6512bc530c1bfd1d9fe3caf8/
processingDocuments/1696076731101_Summary_NewATISH.xlsx",
      "size": "2358165",
      "createdAt": "Sat Sep 30 2023 17:55:31 GMT+0530 (India Standard Time)",
      "uploadedBy": "60eeaeddf3dd69653a581316"
    }
  ],
  "remarks": [],
  "createdAt": "2023-09-26T11:11:15.950Z",
  "updatedAt": "2023-10-03T05:49:01.456Z",
  "__v": 0,
  "invoiceId": "6512bc550c1bfd1d9fe3cb10",
  "fullAddress": "Residential Flat No. 110, 1st Floor, Building No 4, Wing - C, Shivaalik
Park, Kalyan Bhiwandi Road, Village - Temghar, Taluka - Bhiwandi, District - Thane,
Bhiwandi, PIN - 421 302, State - Maharashtra, India",
  "updatedBy": "60eebe33f3dd69653a5837ae",
  "addressForMap": "",
  "caseReferredBy": "60b7177d2ffdf65bcd65882a",
  "contactPersonName": "Mayuri (Sales Person)",
  "email": "",
  "isExternal": "false",
  "isUrgent": "false",
  "ownershipShare": "",
  "purchaseValueAsPerDocument": "",
  "relationWithOwner": "self",
  "siteVisitContactNo": "8888048222",
  "buildingServicesRate": "2500",
  "finalAreaType": "Carpet Area",
  "finalAsPerArea": "Agreement For Sale",
  "finalBuiltUpPercentage": "10",
  "finalCarpetConvertToBuiltUpPer": "10",
  "finalMeasurementType": "Sq. Ft.",
  "finalValuationAreaString": "Carpet Area in Sq. Ft. = 365.00",
```

"flatRate": "6800",
"landOtherRate": "4300",
"siteVisitDate": "2023-09-27",
"builtupPercentage": "10",
"carpetTotal": "0",
"extendOfSiteRemark": "",
"finalBuiltupArea": "0.00",
"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"otherCarpetTotal": "0",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"finalSaleablePercentage": ""

}

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			