

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002",
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002"
  },
  "masterTypeOfPurpose": {
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002",
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9f4"
    },
    "type": "CREDITOFFICER",
    "_id": "648aa63dda662768e994f772",
    "firstName": "Saumita Chakraborty",
    "lastName": "Chakraborty",
    "mobileNo": "",
    "workMobileNo": "9167177426",
    "email": "Saumita.racpc.sion@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5000000",
    "discussWithPerson": "Saumita Chakraborty",
  }
}
```

```
"expectedFees": 2500,
"quotedAmount": "2500"
},
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9f4",
  "branchCode": "000215",
  "type": "BRANCH",
  "name": "RACPC Sion ",
  "email": "racpc.sion@sbi.co.in",
  "mobileNo": "02225046265",
  "alternateMobileNo": "",
  "address": "B-603 & 604, Kohinoor City, Commercial-1, 6th Floor, Kiroi Road, Off
L.B.S. Marg, Kurla (West), Mumbai, Pin Code - 400 070, State - Maharashtra, Country -
India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land & Building / Immovable Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
```

```
"zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60b7177d2ffdf65bcd65882a",
    "role": "PICKUPPERSON",
    "firstName": "Saurabh",
    "email": "saurabhvelonde143@gmail.com",
    "lastName": "Velonde",
    "mobileNo": "8691048846",
    "shortName": "SSV",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "6401b61f0e28255fb44e636a",
    "role": "SITEENGINEER",
    "firstName": "Sanket",
    "email": "ksanket7414@yahoo.com",
    "lastName": "Karalkar",
    "mobileNo": "8080582858",
    "designation": "",
    "shortName": "SAK",
    "workWithDocumentMaker": ""
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "64cde526dc9f3034f3fefa49",
    "role": "FRONTDESK",
    "firstName": "Rashmi",
    "email": "rashmijadhav14feb@gmail.com",
    "lastName": "Jadhav",
    "mobileNo": "7738144625",
    "designation": "Back Office Coordinatiion",
    "shortName": "Rashmi",
    "workWithDocumentMaker": "60eeaeddf3dd69653a581316"
  },
  "maker": "",
  "checker": "",
  "valuers": []
},
"clientType": {
  "label": "BANK",
```

```
"value": "BANK"
},
"location": {
  "latitude": "19.339285783292418",
  "longitude": "72.80747811102638"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.80747811102638,
    19.339285783292418
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "2023-09-27T03:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-09-27T03:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-09-27T03:30:00.000Z",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  }
}
```

```
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Achole",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "1",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Vasai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
```

```
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Orchid",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Anchor Park",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Near Chheda Park",
  "label": false
},
```

```
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "C",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
```

```
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "103",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
```



```
"status": false,
"name": "Police Station(P.S)",
"key": "policeStation",
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Vasai East",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  }
},
```

```
"locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
```

```
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
```

```
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
```

```
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentId": [],
"_id": "6512e0bd0c1bfd1d9fe43df7",
"ownerName": "Santosh Vivek Surte",
"ownerPhoneNo": "9920631233",
"appAddress": "Flat no. C/103, 1st Floor, Orchid, Anchor Park, Vasai East ",
"remark": "NPA Account ",
"documents": [
```

```
{
  "documentType": {
    "label": "Agreement For Sale",
    "value": "60ae1254aa6d152c1801b326"
  },
  "isHardCopy": false,
  "path": "cases/6512e0bd0c1bfd1d9fe43df7/
document_1695735932730_Racpc_Sion_Santosh_Surte103_NPA.pdf",
  "fileName": "document_1695735932730_Racpc_Sion_Santosh_Surte103_NPA.pdf",
  "displayStatus": false,
  "id": "581942",
  "uploadedBy": "60b7177d2ffdf65bcd65882a",
  "createdAt": "Tue Sep 26 2023 19:15:59 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "004060",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "964722",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Sep 26 2023 19:16:37 GMT+0530 (India Standard Time)"
  }
]
],
"owners": [
  {
    "name": "Santosh Vivek Surte",
    "phone": "9920631233",
    "ownershipShare": "",
    "email": "",
    "id": "550611"
  }
]
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
  }
]
```



```
    "_id": "651794192c6c0778ddef5738",
    "name":
"externallmg_1696044057526_WhatsApp_Image_20230929_at_111304_PM.jpeg",
    "path": "cases/6512e0bd0c1bfd1d9fe43df7/
externallmg_1696044057526_WhatsApp_Image_20230929_at_111304_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651794192c6c0778ddef5739",
    "name":
"externallmg_1696044057532_WhatsApp_Image_20230929_at_111305_PM.jpeg",
    "path": "cases/6512e0bd0c1bfd1d9fe43df7/
externallmg_1696044057532_WhatsApp_Image_20230929_at_111305_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651794192c6c0778ddef573a",
    "name":
"externallmg_1696044057540_WhatsApp_Image_20230929_at_111308_PM.jpeg",
    "path": "cases/6512e0bd0c1bfd1d9fe43df7/
externallmg_1696044057540_WhatsApp_Image_20230929_at_111308_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651794192c6c0778ddef573b",
    "name":
"externallmg_1696044057545_WhatsApp_Image_20230929_at_111309_PM.jpeg",
    "path": "cases/6512e0bd0c1bfd1d9fe43df7/
externallmg_1696044057545_WhatsApp_Image_20230929_at_111309_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651794192c6c0778ddef573c",
    "name":
"externallmg_1696044057549_WhatsApp_Image_20230929_at_111310_PM_1.jpeg",
    "path": "cases/6512e0bd0c1bfd1d9fe43df7/
externallmg_1696044057549_WhatsApp_Image_20230929_at_111310_PM_1.jpeg",
    "orientation": "portrait"
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651794192c6c0778ddef573d",
  "name":
"externallmg_1696044057551_WhatsApp_Image_20230929_at_111310_PM_2.jpeg",
  "path": "cases/6512e0bd0c1bfd1d9fe43df7/
externallmg_1696044057551_WhatsApp_Image_20230929_at_111310_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651794192c6c0778ddef573e",
  "name":
"externallmg_1696044057554_WhatsApp_Image_20230929_at_111310_PM.jpeg",
  "path": "cases/6512e0bd0c1bfd1d9fe43df7/
externallmg_1696044057554_WhatsApp_Image_20230929_at_111310_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651794192c6c0778ddef573f",
  "name":
"externallmg_1696044057557_WhatsApp_Image_20230929_at_111311_PM_1.jpeg",
  "path": "cases/6512e0bd0c1bfd1d9fe43df7/
externallmg_1696044057557_WhatsApp_Image_20230929_at_111311_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651794192c6c0778ddef5740",
  "name":
"externallmg_1696044057560_WhatsApp_Image_20230929_at_111311_PM.jpeg",
  "path": "cases/6512e0bd0c1bfd1d9fe43df7/
externallmg_1696044057560_WhatsApp_Image_20230929_at_111311_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651794192c6c0778ddef5741",
  "name":
"externallmg_1696044057563_WhatsApp_Image_20230929_at_111312_PM.jpeg",
```

```
    "path": "cases/6512e0bd0c1bfd1d9fe43df7/
externallmg_1696044057563_WhatsApp_Image_20230929_at_111312_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651794192c6c0778ddef5742",
    "name":
"externallmg_1696044057566_WhatsApp_Image_20230929_at_111313_PM_1.jpeg",
    "path": "cases/6512e0bd0c1bfd1d9fe43df7/
externallmg_1696044057566_WhatsApp_Image_20230929_at_111313_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651794192c6c0778ddef5743",
    "name":
"externallmg_1696044057567_WhatsApp_Image_20230929_at_111313_PM_2.jpeg",
    "path": "cases/6512e0bd0c1bfd1d9fe43df7/
externallmg_1696044057567_WhatsApp_Image_20230929_at_111313_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651794192c6c0778ddef5744",
    "name":
"externallmg_1696044057570_WhatsApp_Image_20230929_at_111313_PM.jpeg",
    "path": "cases/6512e0bd0c1bfd1d9fe43df7/
externallmg_1696044057570_WhatsApp_Image_20230929_at_111313_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651794192c6c0778ddef5745",
    "name":
"externallmg_1696044057573_WhatsApp_Image_20230929_at_111314_PM_1.jpeg",
    "path": "cases/6512e0bd0c1bfd1d9fe43df7/
externallmg_1696044057573_WhatsApp_Image_20230929_at_111314_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "651794192c6c0778ddef5746",
    "name":
"externallmg_1696044057575_WhatsApp_Image_20230929_at_111314_PM.jpeg",
    "path": "cases/6512e0bd0c1bfd1d9fe43df7/
externallmg_1696044057575_WhatsApp_Image_20230929_at_111314_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651794192c6c0778ddef5747",
    "name":
"externallmg_1696044057576_WhatsApp_Image_20230929_at_111315_PM_1.jpeg",
    "path": "cases/6512e0bd0c1bfd1d9fe43df7/
externallmg_1696044057576_WhatsApp_Image_20230929_at_111315_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651794192c6c0778ddef5748",
    "name":
"externallmg_1696044057578_WhatsApp_Image_20230929_at_111315_PM.jpeg",
    "path": "cases/6512e0bd0c1bfd1d9fe43df7/
externallmg_1696044057578_WhatsApp_Image_20230929_at_111315_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651794192c6c0778ddef5749",
    "name":
"externallmg_1696044057580_WhatsApp_Image_20230929_at_111319_PM.jpeg",
    "path": "cases/6512e0bd0c1bfd1d9fe43df7/
externallmg_1696044057580_WhatsApp_Image_20230929_at_111319_PM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [
  {
    "createdBy": {
      "_id": "64cde526dc9f3034f3fefa49",
      "role": "FRONTDESK",
```

```

    "firstName": "Rashmi",
    "lastName": "Jadhav"
  },
  "workType": "RATE_VERIFY",
  "display": true,
  "status": true,
  "_id": "65165b6ce393a05c2411d16f",
  "note": "NPA case - Pending for mail confirmation",
  "taskId": "6513a6fe0c1bfd1d9fe44e20",
  "createdAt": "2023-09-29T05:06:52.113Z"
}
],
"createdAt": "2023-09-26T13:46:37.310Z",
"updatedAt": "2023-09-30T03:20:57.669Z",
"__v": 0,
"invoiceId": "6512e0bd0c1bfd1d9fe43dff",
"fullAddress": "Residential Flat No. 103, 1st Floor, Wing - C, Orchid, Anchor Park, Near
Chheda Park, Village - Achole, Vasai East, Vasai, State - Maharashtra, India",
"updatedBy": "62691c48afd7d55eddecfda3",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Santosh Vivek Surte",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9920631233"
}

```

| Name | Length | Width | Total |
|---------------|--------|-------|-------|
| Composition : | | | |
| Other | | | |
| Composition : | | | |