

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": true,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856bb45"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94231313",
    "firstName": "Satish Chandra",
    "email": "0_default_",
    "mobileNo": "0_DEFAULT_-",
    "workMobileNo": "0_DEFAULT_91-8422925179"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "8200000",
    "discussWithPerson": "Satish Chandra",
    "expectedFees": 4100,
    "quotedAmount": "No Bill"
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",

```

```
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856bb45",
  "branchCode": "000343",
  "type": "BRANCH",
  "name": "Nariman Point Branch",
  "email": "sbi.06945@sbi.co.in",
  "mobileNo": "022-22852674",
  "alternateMobileNo": "",
  "address": "Atlanta Building 1st Floor, Jamnalal Bajaj Road, Off, Vinay K Shah Marg,
Nariman Point, Mumbai, Maharashtra 400021",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "62727444afd7d55eddee092c",
```

```
"role": "PICKUPPERSON",
"firstName": "Shantilal",
"email": "shantilal@vastukala.org",
"lastName": "Patel",
"mobileNo": "9969039853",
"shortName": "SHP",
"workWithDocumentMaker": "",
"profilePhoto": "users/62727444afd7d55eddee092c/
profilePhoto_1668057663775_WhatsApp_Image_20221110_at_104853_AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "60f9462345132d6a6bddb9d5",
"role": "SITEENGINEER",
"firstName": "Dashrath ",
"email": "dasrat.jaiswar1234@gmail.com",
"lastName": "Jaiswar",
"mobileNo": "9987305468",
"designation": "",
"shortName": "DFJ",
"workWithDocumentMaker": ""
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"email": "v.sarmalkar@vastukala.org",
"lastName": "Sarmalkar",
"mobileNo": "9004437379",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"maker": {
"type": "EMPLOYEE",
"_id": "60eebe33f3dd69653a5837ae",
"role": "MAKER",
"firstName": "Shamal",
"email": "shamal@vastukala.org",
"lastName": "Bodke",
"mobileNo": "9821740317",
"designation": "",
"shortName": "SB",
```

```
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eebe33f3dd69653a5837ae\
\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      }
    }
  }
]
```

```
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.00577339956799",
  "longitude": "72.82927277181129"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.82927277181129,
    19.00577339956799
  ]
},
"siteVisit": {
```

```
"siteVisitStatus": true,
"schedule": [
  {
    "dateTime": "2023-09-27T03:30:00.000Z",
    "remark": ""
  },
  {
    "dateTime": "2023-09-27T03:30:00.000Z",
    "remark": ""
  },
  {
    "dateTime": "2023-09-27T03:30:00.000Z",
    "remark": ""
  },
  {
    "dateTime": "2023-09-27T03:30:00.000Z",
    "remark": ""
  },
  {
    "dateTime": "2023-09-27T03:30:00.000Z",
    "remark": ""
  }
],
"visitedDate": [
  {
    "status": "COMPLETED",
    "dateTime": "2023-09-27",
    "remark": "MANUAL_IN_TASK"
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "4BHK",
  "label": "4 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
```

```
"name": "State",
"key": "state",
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": false,
  "name": "Village",
  "key": "village",
  "value": "",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "27",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Lower Parel",
  "label": false
}
```

```
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Lodha Marquise - B",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Senapati Bapat Marg",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
```



```
"key": "street2",
"value": "",
"label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
}
```

```
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "464",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "2701",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
```

```
"value": "",
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 013",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door_with_M.S_Safety_door",
    "label": "Teak Wood Door frame with Solid flush door with M.S Safety door"
  },
  "windows": {
```

```
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MCGM",
    "label": "Municipal Corporation of Greater Mumbai (MCGM)"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Lodha Trump Tower",
    "west": "Kamala Mill",
    "south": "Internal Road & Times Tower",
    "east": "Senapati Bapat Marg"
  },
  "asPerDocumentAgreement": {
    "north": "Details not available",
    "west": "Details not available",
    "south": "Details not available",
    "east": "Details not available"
  },
}
```

```
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "",
"approvePlanVerified": "",
"empanelledOfApprovePlan": ""
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "323420",
  "landRate": "126110",
  "igrImage": "cases/6513a2b10c1bfd1d9fe44467/igr_1696075203453_Image.png",
  "squareMeterGuideLineRate": "371933.00",
  "squareFeetGuideLineRate": "34554.00"
},
"igrFinalRate": {
  "depreciationPercentage": "95",
  "rate": "33412.00",
  "squareFeetGuideLineRate": "33412.00",
  "squareMeterGuideLineRate": "359642.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
```

```
"label": "Medium"
},
"propertyTypeOfUseList": {
  "value": "Residential_Purpose",
  "label": "Residential Purpose"
},
"propertyOccupiedByList": {
  "value": "Vacant",
  "label": "Vacant"
},
"monthlyRent": "1,93,000",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per MCGM norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  }
},
```

```
"carParking": "Along with Three Car Parking Space",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2019",
  "fullDate": "1/1/2019"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
}
```

```
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenancelssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "As_Per_Part_Occupancy_Certificate",
  "label": "As Per Part Occupancy Certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "56",
"ageOfBuilding": "4",
"noOfBasement": "",
```



```
"noOfPodium": "7",
"noOfAmenityFloors": "",
"noOfFloors": "69",
"flatFloorNo": "",
"noOfLifts": "7",
"noOfDwellingUnitsInBuilding": "3"
},
"finalPlinthArea": {
  "area": "1689.60",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/6513a2b10c1bfd1d9fe44467/
routeMap_1696073619004_Image.png",
    "routeLat": "19.004639",
    "routeLng": "72.828694",
    "stationName": "Prabhadevi",
    "routeDistance": "1.3 Km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "nknjmk",
      "name": "nknjmk",
      "image": "cases/6513a2b10c1bfd1d9fe44467/
routeMap_1696073528745_Image.png"
    }
  ]
},
"valuation": {
```

```
"wardrobesRate": "0",
"totalwardrobesRate": "0",
"wardrobesQty": "0",
"showcasesQty": "0",
"showcasesRate": "0",
"totalshowcasesRate": "0",
"kitchenArrangementsQty": "0",
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "77440000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "77440000.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": true
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "56452915.00",
  "selectedBuildUpValue": "1689.60",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "651698d1e393a05c241306a4",
      "name":
"externallmg_1695979729851_WhatsApp_Image_20230929_at_121323_PM.jpeg",
      "path": "cases/6513a2b10c1bfd1d9fe44467/
externallmg_1695979729851_WhatsApp_Image_20230929_at_121323_PM.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "651698bae393a05c24130630",
      "name":
"externallmg_1695979706035_WhatsApp_Image_20230929_at_121334_PM_1.jpeg",
```

```
    "path": "cases/6513a2b10c1bfd1d9fe44467/
externallmg_1695979706035_WhatsApp_Image_20230929_at_121334_PM_1.jpeg",
    "orientation": "portrait"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "651698bae393a05c24130632",
    "name":
"externallmg_1695979706040_WhatsApp_Image_20230929_at_121335_PM.jpeg",
    "path": "cases/6513a2b10c1bfd1d9fe44467/
externallmg_1695979706040_WhatsApp_Image_20230929_at_121335_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "651698d1e393a05c241306a4",
    "name":
"externallmg_1695979729851_WhatsApp_Image_20230929_at_121323_PM.jpeg",
    "path": "cases/6513a2b10c1bfd1d9fe44467/
externallmg_1695979729851_WhatsApp_Image_20230929_at_121323_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "651698d1e393a05c241306a2",
    "name":
"externallmg_1695979729844_WhatsApp_Image_20230929_at_121323_PM_1.jpeg",
    "path": "cases/6513a2b10c1bfd1d9fe44467/
externallmg_1695979729844_WhatsApp_Image_20230929_at_121323_PM_1.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "651698bae393a05c2413062b",
    "name": "Bedroom",
    "path": "cases/6513a2b10c1bfd1d9fe44467/
externallmg_1695979706022_WhatsApp_Image_20230929_at_121331_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
```

```
    "status": false,
    "_id": "651698bae393a05c2413062e",
    "name": "Bedroom",
    "path": "cases/6513a2b10c1bfd1d9fe44467/
externallmg_1695979706031_WhatsApp_Image_20230929_at_121333_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "651698bae393a05c2413062f",
    "name": "Bedroom",
    "path": "cases/6513a2b10c1bfd1d9fe44467/
externallmg_1695979706034_WhatsApp_Image_20230929_at_121333_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "651698bae393a05c24130631",
    "name": "Bedroom",
    "path": "cases/6513a2b10c1bfd1d9fe44467/
externallmg_1695979706038_WhatsApp_Image_20230929_at_121334_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "651698d1e393a05c241306a7",
    "name": "Bedroom",
    "path": "cases/6513a2b10c1bfd1d9fe44467/
externallmg_1695979729858_WhatsApp_Image_20230929_at_121325_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "651698d1e393a05c241306aa",
    "name": "Bedroom",
    "path": "cases/6513a2b10c1bfd1d9fe44467/
externallmg_1695979729863_WhatsApp_Image_20230929_at_121327_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "651698d1e393a05c241306ac",
    "name": "Bedroom",
    "path": "cases/6513a2b10c1bfd1d9fe44467/
externallmg_1695979729864_WhatsApp_Image_20230929_at_121327_PM.jpeg",
    "orientation": "portrait"
  }
```

```
    },
    {
      "status": false,
      "_id": "651698d1e393a05c241306ae",
      "name": "Bedroom",
      "path": "cases/6513a2b10c1bfd1d9fe44467/
externallmg_1695979729868_WhatsApp_Image_20230929_at_121328_PM.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "651698d1e393a05c241306af",
      "name": "Bedroom",
      "path": "cases/6513a2b10c1bfd1d9fe44467/
externallmg_1695979729869_WhatsApp_Image_20230929_at_121329_PM.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "651698dde393a05c24130717",
      "name": "Bedroom",
      "path": "cases/6513a2b10c1bfd1d9fe44467/
externallmg_1695979741232_WhatsApp_Image_20230929_at_121331_PM.jpeg",
      "orientation": "portrait"
    }
  ]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  }
},
```



```
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```

```
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
```

```
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "1408.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentId": [],
"_id": "6513a2b10c1bfd1d9fe44467",
"ownerName": "Mr. Rajesh Khursija",
"ownerPhoneNo": "9810009269",
"appAddress": "Lodh marquis B\nB 2701 27 floor \nwarli Mumbai 25",
"remark": "Rupesh sir ",
"documents": [
  {
    "documentType": {
      "value": "60ae1245aa6d152c1801b2e1",
      "label": "Agreement To Sale"
    },
    "inputs": {
      "documentDate": "16/05/2013",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "Jawala Real Estate Private Limited",
      "to": {
        "value": "Purchaser",
        "label": "Purchaser"
      },
      "Purchaser": "Mr. Rajesh Khursija"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1695991506326_Agreement.pdf",
    "path": "cases/6513a2b10c1bfd1d9fe44467/
document_1695991506326_Agreement.pdf",
```

```
"id": "142531",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Fri Sep 29 2023 18:15:07 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "11/12/2018",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_of_Greater_Mumbai",
      "label": "Municipal Corporation of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "EB / 1342 / GS / A"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1695991564442_2210208_FurtherCC_signed.pdf",
"path": "cases/6513a2b10c1bfd1d9fe44467/
document_1695991564442_2210208_FurtherCC_signed.pdf",
"id": "737358",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Fri Sep 29 2023 18:16:04 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1250aa6d152c1801b316",
    "label": "Part Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "20/05/2019",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_of_Greater_Mumbai",
      "label": "Municipal Corporation of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "EB / 1342 / GS / A / OCC / 1 / New "
```

```
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1695992064904_2218559_OC_signed.pdf",
    "path": "cases/6513a2b10c1bfd1d9fe44467/
document_1695992064904_2218559_OC_signed.pdf",
    "id": "714086",
    "uploadedBy": "60eebe33f3dd69653a5837ae",
    "createdAt": "Fri Sep 29 2023 18:24:25 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae1249aa6d152c1801b2f1",
      "label": "Society Maintenance Bill"
    },
    "inputs": {
      "documentDate": "01/04/2023",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "23-24/ Q1 / 0251"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1696075491184_Maintinance_Bill.pdf",
    "path": "cases/6513a2b10c1bfd1d9fe44467/
document_1696075491184_Maintinance_Bill.pdf",
    "id": "513941",
    "uploadedBy": "60eebe33f3dd69653a5837ae",
    "createdAt": "Sat Sep 30 2023 17:34:51 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f9",
      "label": "Memorandum of Understanding"
    },
    "inputs": {
      "documentDate": "22/09/2023",
      "from": {
        "value": "Seller",
        "label": "Seller"
      },
      "Seller": "Mr. Rajesh Khursija",
      "to": {
        "value": "Purchaser",
```

```
    "label": "Purchaser"
  },
  "Purchaser": "Mrs. Usha Gautam & Mr. Ashok Kumar Gautam "
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1696076227613_MOU_Usha.pdf",
"path": "cases/6513a2b10c1bfd1d9fe44467/
document_1696076227613_MOU_Usha.pdf",
"id": "712587",
"uploadedBy": "5fc78e26625ecd20ec1f88e9",
"createdAt": "Sat Sep 30 2023 17:47:10 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "004063",
"createdBy": "62727444afd7d55eddee092c",
"caseHistory": [
  {
    "id": "359518",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Sep 27 2023 09:04:09 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Rajesh Khursija",
    "phone": "9810009269",
    "ownershipShare": "",
    "email": "",
    "id": "955903"
  }
],
"proposePurchasers": [
  {
    "name": "Mrs. Usha Gautam & Mr. Ashok Kumar Gautam",
    "phone": "",
    "ownershipShare": "",
    "email": ""
  }
],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
```

```
    "label": "Square Feet"
  },
  "id": "750912",
  "name": "Bedroom",
  "length": "10.08",
  "length1": "10",
  "length2": "1",
  "width": "11.33",
  "width1": "11",
  "width2": "4",
  "totalArea": "114.28",
  "images": [],
  "extraAreas": [
    {
      "measurementType": {
        "value": "Square_Feet",
        "label": "Square Feet"
      },
      "_id": "6516bf192c6c0778ddef27ac",
      "name": "Extra",
      "extraAreaType": "Add",
      "length": "4.92",
      "length1": "4",
      "length2": "11",
      "width": "3.92",
      "width1": "3",
      "width2": "11",
      "totalArea": "19.26"
    }
  ],
  "finalArea": "133.54"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Toilet",
  "length": "5.33",
  "length1": "5",
  "length2": "4",
  "width": "5.33",
  "width1": "5",
  "width2": "4",
  "totalArea": "28.44",
```

```
"images": [],
"extraAreas": [],
"finalArea": "28.44"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Living Room",
  "length": "11.83",
  "length1": "11",
  "length2": "10",
  "width": "27.83",
  "width1": "27",
  "width2": "10",
  "totalArea": "329.36",
  "images": [],
  "extraAreas": [
    {
      "measurementType": {
        "value": "Square_Feet",
        "label": "Square Feet"
      },
      "_id": "6516c0ae2c6c0778ddef2cc1",
      "name": "Extra",
      "extraAreaType": "Add",
      "length": "2.00",
      "length1": "2",
      "length2": "00",
      "width": "3.00",
      "width1": "3",
      "width2": "00",
      "totalArea": "6.00"
    }
  ],
  "finalArea": "335.36"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Passage",
```



```
"length": "3.33",
"length1": "3",
"length2": "4",
"width": "27.25",
"width1": "27",
"width2": "3",
"totalArea": "90.83",
"images": [],
"extraAreas": [],
"finalArea": "90.83"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Kitchen",
  "length": "11.17",
  "length1": "11",
  "length2": "2",
  "width": "7.50",
  "width1": "7",
  "width2": "6",
  "totalArea": "83.75",
  "images": [],
  "extraAreas": [],
  "finalArea": "83.75"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bedroom",
  "length": "12.17",
  "length1": "12",
  "length2": "2",
  "width": "9.83",
  "width1": "9",
  "width2": "10",
  "totalArea": "119.64",
  "images": [],
  "extraAreas": [],
  "finalArea": "119.64"
```

```
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Toilet",
  "length": "4.33",
  "length1": "4",
  "length2": "4",
  "width": "7.25",
  "width1": "7",
  "width2": "3",
  "totalArea": "31.42",
  "images": [],
  "extraAreas": [],
  "finalArea": "31.42"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Toilet",
  "length": "4.58",
  "length1": "4",
  "length2": "7",
  "width": "3.50",
  "width1": "3",
  "width2": "6",
  "totalArea": "16.04",
  "images": [],
  "extraAreas": [],
  "finalArea": "16.04"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Bedroom",
  "length": "10.08",
  "length1": "10",
```

```
"length2": "1",
"width": "12.17",
"width1": "12",
"width2": "2",
"totalArea": "122.68",
"images": [],
"extraAreas": [],
"finalArea": "122.68"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "9",
  "name": "Toilet",
  "length": "4.42",
  "length1": "4",
  "length2": "5",
  "width": "7.42",
  "width1": "7",
  "width2": "5",
  "totalArea": "32.76",
  "images": [],
  "extraAreas": [],
  "finalArea": "32.76"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "10",
  "name": "Bedroom",
  "length": "10.83",
  "length1": "10",
  "length2": "10",
  "width": "15.92",
  "width1": "15",
  "width2": "11",
  "totalArea": "172.43",
  "images": [],
  "extraAreas": [
    {
      "measurementType": {
        "value": "Square_Feet",
```

```
    "label": "Square Feet"
  },
  "_id": "6516c2ae2c6c0778ddef3246",
  "name": "Extra",
  "extraAreaType": "Add",
  "length": "3.42",
  "length1": "3",
  "length2": "5",
  "width": "5.58",
  "width1": "5",
  "width2": "7",
  "totalArea": "19.08"
}
],
"finalArea": "191.51"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "11",
  "name": "Toilet",
  "length": "4.67",
  "length1": "4",
  "length2": "8",
  "width": "10.83",
  "width1": "10",
  "width2": "10",
  "totalArea": "50.56",
  "images": [],
  "extraAreas": [
    {
      "measurementType": {
        "value": "Square_Feet",
        "label": "Square Feet"
      },
      "_id": "6516c3652c6c0778ddef340a",
      "name": "Extra",
      "extraAreaType": "Add",
      "length": "2.58",
      "length1": "2",
      "length2": "7",
      "width": "6.42",
      "width1": "6",
      "width2": "5",
```

```
    "totalArea": "16.58"
  }
],
"finalArea": "67.14"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "12",
  "name": "Servent Room",
  "length": "6.25",
  "length1": "6",
  "length2": "3",
  "width": "6.75",
  "width1": "6",
  "width2": "9",
  "totalArea": "42.19",
  "images": [],
  "extraAreas": [
    {
      "measurementType": {
        "value": "Square_Feet",
        "label": "Square Feet"
      },
      "_id": "6516c57d2c6c0778ddef3ea8",
      "name": "Extra",
      "extraAreaType": "Add",
      "length": "4.42",
      "length1": "4",
      "length2": "5",
      "width": "2.42",
      "width1": "2",
      "width2": "5",
      "totalArea": "10.67"
    }
  ],
  "finalArea": "52.86"
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    }
  }
]
```

```
},
"name": {
  "label": "Store Room",
  "value": "Store_Room"
},
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "0",
"length1": "2",
"length2": "10",
"length": "2.83",
"width1": "4",
"width2": "9",
"width": "4.75",
"totalArea": "13.46",
"percentageBeforeTotal": "13.46",
"images": [],
"extraAreas": [],
"percentage": "100",
"finalArea": "13.46"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Temple",
    "value": "Temple"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "length1": "3",
  "length2": "7",
  "length": "3.58",
  "width1": "5",
  "width2": "3",
  "width": "5.25",
  "totalArea": "18.81",
  "percentageBeforeTotal": "18.81",
  "images": [],
```

```
"extraAreas": [],
"percentage": "100",
"finalArea": "18.81"
}
],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "value": "60ae1245aa6d152c1801b2e1",
    "label": "Agreement To Sale"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "434353",
  "selectAreaTypeDocument": "Carpet",
  "totalAreaDocument": "1408",
  "squareMeterArea": "130.81",
  "docFinalBuiltUp": "1689.6",
  "docFinalBuiltUpSquareMeter": "156.972",
  "docBultupPercentage": "20",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "65180c212c6c0778ddf12346",
  "id": "1",
  "property": "Flat",
  "area": "1600",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "magic_bricks",
  "expectedPrice": "87000000",
  "expectedRate": "54375.00",
  "builtUpExpectedRate": "49431.82",
  "image": "cases/6513a2b10c1bfd1d9fe44467/
indicator_1696074785690_Image.png"
```

```
    },
    {
      "printlnReport": true,
      "_id": "65180c442c6c0778ddf124a7",
      "id": "2",
      "property": "Flat",
      "area": "1526",
      "builtUpPercentage": "10",
      "saleablePercentage": "0",
      "rateType": "price_Indicator",
      "areaType": "Carpet",
      "floor": "",
      "source": "https://www.99acres.com/",
      "expectedPrice": "85000000",
      "expectedRate": "55701.18",
      "builtUpExpectedRate": "50637.44",
      "image": "cases/6513a2b10c1bfd1d9fe44467/
indicator_1696074820907_Image.png"
    },
    {
      "printlnReport": true,
      "_id": "65180caf2c6c0778ddf12617",
      "id": "3",
      "property": "Flat",
      "area": "1475",
      "builtUpPercentage": "10",
      "saleablePercentage": "0",
      "rateType": "price_Indicator",
      "areaType": "Carpet",
      "floor": "",
      "source": "magic_bricks",
      "expectedPrice": "86000000",
      "expectedRate": "58305.08",
      "builtUpExpectedRate": "53004.62",
      "image": "cases/6513a2b10c1bfd1d9fe44467/
indicator_1696074927201_Image.png"
    }
  ],
  "externalImages": [
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "651698bae393a05c2413062b",
      "name":
"externalImg_1695979706022_WhatsApp_Image_20230929_at_121331_PM_2.jpeg",
      "path": "cases/6513a2b10c1bfd1d9fe44467/
externalImg_1695979706022_WhatsApp_Image_20230929_at_121331_PM_2.jpeg",
```



```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651698bae393a05c2413062c",
    "name":
"externallmg_1695979706025_WhatsApp_Image_20230929_at_121332_PM_1.jpeg",
    "path": "cases/6513a2b10c1bfd1d9fe44467/
externallmg_1695979706025_WhatsApp_Image_20230929_at_121332_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651698bae393a05c2413062d",
    "name":
"externallmg_1695979706030_WhatsApp_Image_20230929_at_121332_PM.jpeg",
    "path": "cases/6513a2b10c1bfd1d9fe44467/
externallmg_1695979706030_WhatsApp_Image_20230929_at_121332_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651698bae393a05c2413062e",
    "name":
"externallmg_1695979706031_WhatsApp_Image_20230929_at_121333_PM_1.jpeg",
    "path": "cases/6513a2b10c1bfd1d9fe44467/
externallmg_1695979706031_WhatsApp_Image_20230929_at_121333_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651698bae393a05c2413062f",
    "name":
"externallmg_1695979706034_WhatsApp_Image_20230929_at_121333_PM.jpeg",
    "path": "cases/6513a2b10c1bfd1d9fe44467/
externallmg_1695979706034_WhatsApp_Image_20230929_at_121333_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651698bae393a05c24130630",
```

```
    "name":
"externallmg_1695979706035_WhatsApp_Image_20230929_at_121334_PM_1.jpeg",
  "path": "cases/6513a2b10c1bfd1d9fe44467/
externallmg_1695979706035_WhatsApp_Image_20230929_at_121334_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651698bae393a05c24130631",
  "name":
"externallmg_1695979706038_WhatsApp_Image_20230929_at_121334_PM.jpeg",
  "path": "cases/6513a2b10c1bfd1d9fe44467/
externallmg_1695979706038_WhatsApp_Image_20230929_at_121334_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651698bae393a05c24130632",
  "name":
"externallmg_1695979706040_WhatsApp_Image_20230929_at_121335_PM.jpeg",
  "path": "cases/6513a2b10c1bfd1d9fe44467/
externallmg_1695979706040_WhatsApp_Image_20230929_at_121335_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651698bae393a05c24130633",
  "name":
"externallmg_1695979706041_WhatsApp_Image_20230929_at_121317_PM_1.jpeg",
  "path": "cases/6513a2b10c1bfd1d9fe44467/
externallmg_1695979706041_WhatsApp_Image_20230929_at_121317_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651698bae393a05c24130634",
  "name":
"externallmg_1695979706044_WhatsApp_Image_20230929_at_121317_PM.jpeg",
  "path": "cases/6513a2b10c1bfd1d9fe44467/
externallmg_1695979706044_WhatsApp_Image_20230929_at_121317_PM.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651698bae393a05c24130635",
  "name":
"externallmg_1695979706046_WhatsApp_Image_20230929_at_121318_PM_1.jpeg",
  "path": "cases/6513a2b10c1bfd1d9fe44467/
externallmg_1695979706046_WhatsApp_Image_20230929_at_121318_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651698d1e393a05c241306a0",
  "name":
"externallmg_1695979729838_WhatsApp_Image_20230929_at_121318_PM.jpeg",
  "path": "cases/6513a2b10c1bfd1d9fe44467/
externallmg_1695979729838_WhatsApp_Image_20230929_at_121318_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651698d1e393a05c241306a1",
  "name":
"externallmg_1695979729840_WhatsApp_Image_20230929_at_121322_PM.jpeg",
  "path": "cases/6513a2b10c1bfd1d9fe44467/
externallmg_1695979729840_WhatsApp_Image_20230929_at_121322_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651698d1e393a05c241306a2",
  "name":
"externallmg_1695979729844_WhatsApp_Image_20230929_at_121323_PM_1.jpeg",
  "path": "cases/6513a2b10c1bfd1d9fe44467/
externallmg_1695979729844_WhatsApp_Image_20230929_at_121323_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651698d1e393a05c241306a3",
  "name":
"externallmg_1695979729848_WhatsApp_Image_20230929_at_121323_PM_2.jpeg",
```

```
    "path": "cases/6513a2b10c1bfd1d9fe44467/
externallmg_1695979729848_WhatsApp_Image_20230929_at_121323_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651698d1e393a05c241306a4",
    "name":
"externallmg_1695979729851_WhatsApp_Image_20230929_at_121323_PM.jpeg",
    "path": "cases/6513a2b10c1bfd1d9fe44467/
externallmg_1695979729851_WhatsApp_Image_20230929_at_121323_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651698d1e393a05c241306a5",
    "name":
"externallmg_1695979729854_WhatsApp_Image_20230929_at_121324_PM_1.jpeg",
    "path": "cases/6513a2b10c1bfd1d9fe44467/
externallmg_1695979729854_WhatsApp_Image_20230929_at_121324_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651698d1e393a05c241306a6",
    "name":
"externallmg_1695979729856_WhatsApp_Image_20230929_at_121324_PM.jpeg",
    "path": "cases/6513a2b10c1bfd1d9fe44467/
externallmg_1695979729856_WhatsApp_Image_20230929_at_121324_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651698d1e393a05c241306a7",
    "name":
"externallmg_1695979729858_WhatsApp_Image_20230929_at_121325_PM_1.jpeg",
    "path": "cases/6513a2b10c1bfd1d9fe44467/
externallmg_1695979729858_WhatsApp_Image_20230929_at_121325_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "651698d1e393a05c241306a8",
  "name":
"externallmg_1695979729859_WhatsApp_Image_20230929_at_121325_PM.jpeg",
  "path": "cases/6513a2b10c1bfd1d9fe44467/
externallmg_1695979729859_WhatsApp_Image_20230929_at_121325_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651698d1e393a05c241306a9",
  "name":
"externallmg_1695979729861_WhatsApp_Image_20230929_at_121326_PM.jpeg",
  "path": "cases/6513a2b10c1bfd1d9fe44467/
externallmg_1695979729861_WhatsApp_Image_20230929_at_121326_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651698d1e393a05c241306aa",
  "name":
"externallmg_1695979729863_WhatsApp_Image_20230929_at_121327_PM_1.jpeg",
  "path": "cases/6513a2b10c1bfd1d9fe44467/
externallmg_1695979729863_WhatsApp_Image_20230929_at_121327_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651698d1e393a05c241306ab",
  "name":
"externallmg_1695979729863_WhatsApp_Image_20230929_at_121327_PM_2.jpeg",
  "path": "cases/6513a2b10c1bfd1d9fe44467/
externallmg_1695979729863_WhatsApp_Image_20230929_at_121327_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651698d1e393a05c241306ac",
  "name":
"externallmg_1695979729864_WhatsApp_Image_20230929_at_121327_PM.jpeg",
  "path": "cases/6513a2b10c1bfd1d9fe44467/
externallmg_1695979729864_WhatsApp_Image_20230929_at_121327_PM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651698d1e393a05c241306ad",
    "name":
"externallmg_1695979729866_WhatsApp_Image_20230929_at_121328_PM_1.jpeg",
    "path": "cases/6513a2b10c1bfd1d9fe44467/
externallmg_1695979729866_WhatsApp_Image_20230929_at_121328_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651698d1e393a05c241306ae",
    "name":
"externallmg_1695979729868_WhatsApp_Image_20230929_at_121328_PM.jpeg",
    "path": "cases/6513a2b10c1bfd1d9fe44467/
externallmg_1695979729868_WhatsApp_Image_20230929_at_121328_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651698d1e393a05c241306af",
    "name":
"externallmg_1695979729869_WhatsApp_Image_20230929_at_121329_PM.jpeg",
    "path": "cases/6513a2b10c1bfd1d9fe44467/
externallmg_1695979729869_WhatsApp_Image_20230929_at_121329_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651698d1e393a05c241306b0",
    "name":
"externallmg_1695979729871_WhatsApp_Image_20230929_at_121330_PM_1.jpeg",
    "path": "cases/6513a2b10c1bfd1d9fe44467/
externallmg_1695979729871_WhatsApp_Image_20230929_at_121330_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651698d1e393a05c241306b1",
```

```
    "name":
"externallmg_1695979729873_WhatsApp_Image_20230929_at_121330_PM.jpeg",
  "path": "cases/6513a2b10c1bfd1d9fe44467/
externallmg_1695979729873_WhatsApp_Image_20230929_at_121330_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651698d1e393a05c241306b2",
  "name":
"externallmg_1695979729874_WhatsApp_Image_20230929_at_121331_PM_1.jpeg",
  "path": "cases/6513a2b10c1bfd1d9fe44467/
externallmg_1695979729874_WhatsApp_Image_20230929_at_121331_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651698dde393a05c24130717",
  "name":
"externallmg_1695979741232_WhatsApp_Image_20230929_at_121331_PM.jpeg",
  "path": "cases/6513a2b10c1bfd1d9fe44467/
externallmg_1695979741232_WhatsApp_Image_20230929_at_121331_PM.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
{
  "originalname": "2210208_FurtherCC_signed.pdf",
  "filename": "1696075566804_2210208_FurtherCC_signed.pdf",
  "path": "cases/6513a2b10c1bfd1d9fe44467/
processingDocuments/1696075566804_2210208_FurtherCC_signed.pdf",
  "size": "180312",
  "createdAt": "Sat Sep 30 2023 17:36:07 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eebe33f3dd69653a5837ae"
},
{
  "originalname": "2218559_OC_signed.pdf",
  "filename": "1696075566808_2218559_OC_signed.pdf",
  "path": "cases/6513a2b10c1bfd1d9fe44467/
processingDocuments/1696075566808_2218559_OC_signed.pdf",
  "size": "202674",
  "createdAt": "Sat Sep 30 2023 17:36:07 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eebe33f3dd69653a5837ae"
```

```
},
{
  "originalname": "Agreement.pdf",
  "filename": "1696075566812_Agreement.pdf",
  "path": "cases/6513a2b10c1bfd1d9fe44467/
processingDocuments/1696075566812_Agreement.pdf",
  "size": "37256141",
  "createdAt": "Sat Sep 30 2023 17:36:07 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eebe33f3dd69653a5837ae"
},
{
  "originalname": "Annexure II.pdf",
  "filename": "1696075567312_Annexure_II.pdf",
  "path": "cases/6513a2b10c1bfd1d9fe44467/
processingDocuments/1696075567312_Annexure_II.pdf",
  "size": "1849099",
  "createdAt": "Sat Sep 30 2023 17:36:07 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eebe33f3dd69653a5837ae"
},
{
  "originalname": "Bank_Loan_Statement.pdf",
  "filename": "1696075578875_Bank_Loan_Statement.pdf",
  "path": "cases/6513a2b10c1bfd1d9fe44467/
processingDocuments/1696075578875_Bank_Loan_Statement.pdf",
  "size": "5349099",
  "createdAt": "Sat Sep 30 2023 17:36:19 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eebe33f3dd69653a5837ae"
},
{
  "originalname": "Calculation (2)- rajesh.xlsx",
  "filename": "1696075578944_Calculation_2_rajesh.xlsx",
  "path": "cases/6513a2b10c1bfd1d9fe44467/
processingDocuments/1696075578944_Calculation_2_rajesh.xlsx",
  "size": "16576",
  "createdAt": "Sat Sep 30 2023 17:36:19 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eebe33f3dd69653a5837ae"
},
{
  "originalname": "igr1.pdf",
  "filename": "1696075578945_igr1.pdf",
  "path": "cases/6513a2b10c1bfd1d9fe44467/
processingDocuments/1696075578945_igr1.pdf",
  "size": "100752",
  "createdAt": "Sat Sep 30 2023 17:36:19 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eebe33f3dd69653a5837ae"
},
}
```



```
{
  "originalname": "igr2.pdf",
  "filename": "1696075578947_igr2.pdf",
  "path": "cases/6513a2b10c1bfd1d9fe44467/
processingDocuments/1696075578947_igr2.pdf",
  "size": "101001",
  "createdAt": "Sat Sep 30 2023 17:36:19 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eebe33f3dd69653a5837ae"
},
{
  "originalname": "igr3.pdf",
  "filename": "1696075578949_igr3.pdf",
  "path": "cases/6513a2b10c1bfd1d9fe44467/
processingDocuments/1696075578949_igr3.pdf",
  "size": "103211",
  "createdAt": "Sat Sep 30 2023 17:36:19 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eebe33f3dd69653a5837ae"
},
{
  "originalname": "Maintinance_Bill.pdf",
  "filename": "1696075578951_Maintinance_Bill.pdf",
  "path": "cases/6513a2b10c1bfd1d9fe44467/
processingDocuments/1696075578951_Maintinance_Bill.pdf",
  "size": "965226",
  "createdAt": "Sat Sep 30 2023 17:36:19 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eebe33f3dd69653a5837ae"
},
{
  "originalname": "REference report.pdf",
  "filename": "1696075578964_REference_report.pdf",
  "path": "cases/6513a2b10c1bfd1d9fe44467/
processingDocuments/1696075578964_REference_report.pdf",
  "size": "6691166",
  "createdAt": "Sat Sep 30 2023 17:36:19 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eebe33f3dd69653a5837ae"
},
{
  "originalname": "REference report1.doc",
  "filename": "1696075579060_REference_report1.doc",
  "path": "cases/6513a2b10c1bfd1d9fe44467/
processingDocuments/1696075579060_REference_report1.doc",
  "size": "5862912",
  "createdAt": "Sat Sep 30 2023 17:36:19 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eebe33f3dd69653a5837ae"
},
{
```

```
"originalname": "Summary - rajesh.xlsx",
"filename": "1696075579166_Summary__rajesh.xlsx",
"path": "cases/6513a2b10c1bfd1d9fe44467/
processingDocuments/1696075579166_Summary__rajesh.xlsx",
"size": "5237005",
"createdAt": "Sat Sep 30 2023 17:36:19 GMT+0530 (India Standard Time)",
"uploadedBy": "60eebe33f3dd69653a5837ae"
}
],
"remarks": [],
"createdAt": "2023-09-27T03:34:09.582Z",
"updatedAt": "2023-09-30T12:22:14.898Z",
"__v": 0,
"invoiceId": "6513a2b10c1bfd1d9fe44473",
"fullAddress": "Residential Flat No. 2701, 27th Floor, Lodha Marquise - B, Senapati
Bapat Marg, District - Mumbai, Lower Parel, PIN - 400 013, State - Maharashtra, India",
"updatedAt": "5fc78e26625ecd20ec1f88e9",
"addressForMap": "",
"caseReferredBy": "62727444afd7d55eddee092c",
"contactPersonName": "Mr. Rajesh Khursija",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Self",
"siteVisitContactNo": "9810009269",
"briefDescOfProperty": "4 Bedroom + Living Room + Kitchen + 5 Toilet + Passage +
Servent Room",
"carpetTotal": "1305.97",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "1472.06",
"finalCarpetArea": "1338.24",
"finalSalableArea": "1619.27",
"salablePercentage": "10",
"toBeAdded": "",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "32.27",
"otherCompositionSaleableTotal": "0.00",
"extendOfSiteRemark": "All the above areas are within +/- 10% of the Agreement for
Sale Area. The above calculations and detail measurements taken by us prove that the
Agreement for Sale are is not exorbitantly inflated. Hence, valuation is based on the
Agreement for Sale area",
"siteMeasurementRemark": "",
```

"finalAreaType": "Carpet Area",
 "finalAsPerArea": "Agreement To Sale",
 "finalBuiltUpPercentage": "20",
 "finalCarpetConvertToBuiltUpPer": "20",
 "finalSaleablePercentage": "0",
 "finalValuationAreaString": "Carpet Area in Sq. Ft. = 1408.00",
 "buildingServicesRate": "3500",
 "flatRate": "55000",
 "landOtherRate": "51500",
 "reportGeneratedDate": "Sat Sep 30 2023 17:35:53 GMT+0530 (India Standard Time)",
 "siteVisitDate": "2023-09-27"
 }

Name	Length	Width	Total
Composition :			
Bedroom	10'1"	11'4"	114.28
Toilet	5'4"	5'4"	28.44
Living Room	11'10"	27'10"	329.36
Passage	3'4"	27'3"	90.83
Kitchen	11'2"	7'6"	83.75
Bedroom	12'2"	9'10"	119.64
Toilet	4'4"	7'3"	31.42
Toilet	4'7"	3'6"	16.04
Bedroom	10'1"	12'2"	122.68
Toilet	4'5"	7'5"	32.76
Bedroom	10'10"	15'11"	172.43
Toilet	4'8"	10'10"	50.56
Servent Room	6'3"	6'9"	42.19
Other Composition :			
Store Room	2'10"	4'9"	13.46
Temple	3'7"	5'3"	18.81