Deepak jain

Inspection report of Residential/ Commercial/ Industrial properties

Name of Bank: sbi Date of inspection: 30-9-2023

Name of bank: SUI Date of inspection:30-9-2025		
	Name of the Applicant	Sneha Samir korgaonkar
1.	Type of property:	Residental flat
2.	Address of the property	Flat no 202,2 nd floor,a wing,navnath jayas ,jay prakash
		nagar, road no 5,goregaon east
3.	Nearest Railway station	850 m away from station
4.	Name of the road access to the property	j.p road no 2
5.	Landmark / vicinity:	Pahadi school
6.	Boundaries of the building	North: road no 2 south: b wing under constrution east: under constrution west: road
7.	Locality	Type : Residential / Commercial / Industrial / Mix Class of people : Lower class / Middle class / Upper Middle class / Higher class Site is: Normal / above road / below road
8.	Permitted Land Use	Residential/Commercial/Industrial/Mix
9.	Actual Land Use	Residential/Commercial/Industrial/Mix
10.	Availability of other amenities in the surrounding	School Market College Temple
11.	Surrounding development	Developed/Well Developed
12.	Occupant	Vacant
13.	Building details	Type of Structure: : (<u>RCC</u> /Load Beaing) No. of Floors: stilt+17 th floor No of wings:2 No. of flats/units on each :4 flat
14.	No. of lifts with capacity & Status	3 no with 6person capacity
15.	Underground & Overhead tanks	1 no. Overhead Tank & 1 no. Under ground Tank
16.	Year of Construction	Under constrution
17.	Age of the building	Under constrution
18.	Estimated future life of the building	Under constrution
19.	Building elevation	Under constrution
20.	Condition of the building :	Under constrution
21.	Finishing	Under constrution
22.	Amenities	Under constrution

23.	Flooring in open spaces and	Under constrution
	staircase	
24.	Doors & Windows	Under constrution
25.	Compound wall & no. of	Under constrution
	gates	
26.	No. of rooms	1 bhk
27.	View from the different	Buildin1 g
	rooms of the property	
28.	Internal finishing	Flooring in different rooms: Under constrution
		Kitchen Platform: Under constrution
		Electrical : OPEN / <u>CONCEALED</u>
		Plumbing: OPEN / <u>CONCEALED</u>
29.	Balcony	
31	Carpet area as per	404sq feet as per rera carpet
	Measurement:	
32	Nearest Bus stop	Peru baug
33	Nearest Hospital	Yashada hospital
34	Condition of Road	30 feet good wide road
35	Rate per sq ft.	
36	Person Met at Site	Prathmesh pawar/7038074232(site superwiser)
37	Coordinate	19.164147,72.855275
38	Name on society board	Na
39	Name on door	Na

REMARKS:

1 the said property is under constrution and plinth level work completed . 2:the said proiperty possession date december 2025.