

```
{
  "typeOfReport": {
    "value": "APF",
    "label": "APF"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63b26652191f7b344b008cac"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f66be948726cc141b93",
    "email": "sbi.04380@sbi.co.in",
    "firstName": "BHAUSAHEB ",
    "mobileNo": "",
    "workMobileNo": "9167778443",
    "lastName": "PATIL"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "0"
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63b26652191f7b344b008cac",
  "name": "HLST BKC",
  "branchCode": "",
  "mobileNo": "022-26445021",
  "alternateMobileNo": "",
  "email": "sbi.04380@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "HLST Synergy Building, 1st floor, C – 6, G Block\nBandra Kurla
Complex, Bandra (East),\nMumbai – 400 051."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential_cum_commercial",
  "label": "Residential cum Commercial"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "63fda584ce84bf289baadaf6",
```

```
"role": "PICKUPPERSON",
"firstName": "Mahendra",
"email": "mahindra.bijlaney@gmail.com",
"lastName": "Bijlaney",
"mobileNo": "9833016592",
"shortName": "MB",
"workWithDocumentMaker": "",
"profilePhoto": "users/63fda584ce84bf289baadaf6/
profilePhoto_1677567364613_WhatsApp_Image_20230228_at_121901_PM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "60f9343b45132d6a6bdd96e8",
"role": "SITEENGINEER",
"firstName": "Rajesh",
"email": "rajeshb.ghadi@gmail.com",
"lastName": "Ghadi",
"mobileNo": "8652092666",
"designation": "",
"shortName": "RHG",
"workWithDocumentMaker": ""
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60f9147bf3dd69653a591e8c",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Vinita",
"email": "vinita.surve@vastukala.org",
"lastName": "Surve",
"mobileNo": "9820652818",
"designation": "",
"shortName": "V",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "60f9147bf3dd69653a591e8c",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Vinita",
"email": "vinita.surve@vastukala.org",
"lastName": "Surve",
"mobileNo": "9820652818",
"designation": "",
"shortName": "V",
```

```
"workWithDocumentMaker": "",
"profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f9147bf3dd69653a591e8c",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Vinita",
  "email": "vinita.surve@vastukala.org",
  "lastName": "Surve",
  "mobileNo": "9820652818",
  "designation": "",
  "shortName": "V",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        }
      },
      {
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ]
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    }
  }
]
```

```
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "18.97955220719612",
  "longitude": "73.07478244984169"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.07478244984169,
    18.97955220719612
  ]
},
"siteVisit": {
```

```
"siteVisitStatus": true,
"visitedDate": [
  {
    "status": "COMPLETED",
    "dateTime": "2023-10-04",
    "remark": ""
  },
  {
    "status": "COMPLETED",
    "dateTime": "2023-10-04",
    "remark": ""
  }
],
"schedule": [],
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Dhapoli",
    "label": true
  },
  "floorNo": {
```

```
"status": true,
"name": "Floor No",
"key": "floorNo",
"value": "36",
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Raigadh",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Navi Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Panvel",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": " 28",
```

```
"label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "5",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": true,
```



```
"name": "Project Name",
"key": "projectName",
"value": "Shreeji Neelkanth",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
}
```

```
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
```

```
"key": "postalCode",
"value": "410206",
"label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  },
  "flooring": {
    "label": "Proposed Vitrified tiles flooring",
    "value": "Proposed_Vitrified_tiles_flooring"
  },
  "doors": {
    "label": "Proposed Teak wood door frame with flush doors",
    "value": "Proposed_Teak_wood_door_frame_with_flush_doors"
  },
  "windows": {
    "label": "Powder coated Aluminum sliding windows with M. S. Grills",
    "value": "Powder_coated_Aluminum_sliding_windows_with_M._S._Grills"
  },
  "fittings": {
    "label": "Proposed Concealed plumbing with C.P. fittings. Concealed wiring",
    "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Concealed_wiring"
  },
  "finishing": {
    "label": "Building Under Construction",
    "value": "Building_Under_Construction"
  }
}
},
"general": {
  "populationClassList": {
    "label": "Higher Middle Class",
    "value": "HigherMiddleClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  }
}
```

```
},
"townplanApprovedByList": {
  "label": "CIDCO",
  "value": "CIDCO"
},
"unitBoundaries": {
  "isDisplay": false
}
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Middle Class",
    "value": "Middle_Class"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  },
  "propertyOccupiedByList": {
    "label": "Building is under construction ",
    "value": "Building_is_under_construction_"
  },
  "monthlyRent": ""
},
"siteMeasurement": {
  "partitions": {
    "label": "Building Under Construction",
    "value": "Building_Under_Construction"
  },
  "waterTank": {
    "label": "CIDCO",
    "value": "CIDCO"
  },
  "pavementLaid": {
    "label": "Building Under Construction",
    "value": "Building_Under_Construction"
  },
  "carParking": {
    "label": "Podium Parking",
    "value": "Podium_Parking"
  },
  "constructionWorkStatus": {
    "label": "Under Construction",
    "value": "InProgress"
  },
  "dateOfConstruction": {
```

```
"date": "",
"month": "1",
"year": "2025",
"fullDate": "1/1/2025"
},
"propertyTypeList": {
  "value": "Residential_cum_commercial",
  "label": "Residential cum Commercial"
},
"planningArea": {
  "value": "Residential_cum_commercial",
  "label": "Residential cum Commercial"
},
"typeOfStructure": {
  "label": "R.C.C. Framed Structure",
  "value": "R.C.C._Framed_Structure"
},
"qualityOfConstruction": {
  "label": "Building is under construction ",
  "value": "Building_is_under_construction_"
},
"walls": {
  "label": "Building Under Construction",
  "value": "Building_Under_Construction"
},
"appearanceOfTheBuilding": {
  "label": "Building is under construction ",
  "value": "Building_is_under_construction_"
},
"maintenanceOfTheBuilding": {
  "label": "Building is under construction ",
  "value": "Building_is_under_construction_"
},
"visibleDamageInBuilding": {
  "label": "Building Under Construction",
  "value": "Building_Under_Construction"
},
"groundStilt": {
  "label": "Part Ground + Part Stilt",
  "value": "Part_Ground_and_Part_Stilt"
},
"isSiteVisitAllowed": true,
"noOfBasement": "0",
"flatFloorNo": "",
"noOfLiftsInEachWings": "0",
"totalLifeBuilding": ""
```

```
"ageOfBuilding": "",
"estimatedAge": "",
"noOfAmenityFloors": "03",
"noOfPodium": "1",
"noOfFloors": "013",
"noOfDwellingUnitsInBuilding": "015",
"noOfLifts": "04"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "InProgress",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
}
```

```
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
```



```
    "label": "Work Completed (%)",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": true,
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
}
```

```
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
```

```
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": false,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"paymentId": [],
"_id": "65180a572c6c0778ddf117b7",
"ownerName": "Shreeji Neelkanth",
"ownerPhoneNo": "9892766957",
"fullAddress": " APF No. 36th Floor, Shreeji Neelkanth, Plot No. 28, Sector 5, Village -
Dhapoli, Taluka - Panvel, District - Raigadh, Navi Mumbai, 410206",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "30/09/2023",
      "nameOfApprovingAuthority": {
        "value": "Mumbai_Metropolitan_Region_Development_Authority",
        "label": "Mumbai Metropolitan Region Development Authority"
      },
      "from": {
        "value": "Developers",
        "label": "Developers"
      },
      "Developers": "Shyam Builders & Developers",
      "to": {
        "value": "Joint_Purchaser",
        "label": "Joint Purchaser"
      },
      "Joint_Purchaser": "Vijay Jadhav"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1696073721291_Document_Shreeji.pdf",
    "path": "cases/65180a572c6c0778ddf117b7/
document_1696073721291_Document_Shreeji.pdf",
    "id": "268647",
    "uploadedBy": "63fda584ce84bf289baadaf6",
    "createdAt": "Sat Sep 30 2023 17:14:46 GMT+0530 (India Standard Time)"
  }
]
```

```
}
],
"caseNumber": "004129",
"createdBy": "63fda584ce84bf289baadaf6",
"caseHistory": [
  {
    "id": "711170",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Sep 30 2023 17:15:27 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Shreeji Neelkanth",
    "phone": "9892766957",
    "ownershipShare": "",
    "email": "",
    "id": "592269"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651cded12c6c0778ddf383b3",
    "name": "externalImg_1696390843503_1696390756468_image_0.jpeg",
    "path": "cases/65180a572c6c0778ddf117b7/externalImg_1696390843503_1696390756468_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651cded12c6c0778ddf383b4",
    "name": "externalImg_1696390843755_1696390756468_image_1.jpeg",
    "path": "cases/65180a572c6c0778ddf117b7/externalImg_1696390843755_1696390756468_image_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651cded12c6c0778ddf383b5",
    "name": "externallmg_1696390844925_1696390756468_image_2.jpeg",
    "path": "cases/65180a572c6c0778ddf117b7/
externallmg_1696390844925_1696390756468_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651cded12c6c0778ddf383b6",
    "name": "externallmg_1696390845883_1696390756468_image_3.jpeg",
    "path": "cases/65180a572c6c0778ddf117b7/
externallmg_1696390845883_1696390756468_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651cded12c6c0778ddf383b7",
    "name": "externallmg_1696390847025_1696390756468_image_4.jpeg",
    "path": "cases/65180a572c6c0778ddf117b7/
externallmg_1696390847025_1696390756468_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651cded12c6c0778ddf383b8",
    "name": "externallmg_1696390847364_1696390756468_image_5.jpeg",
    "path": "cases/65180a572c6c0778ddf117b7/
externallmg_1696390847364_1696390756468_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651cded12c6c0778ddf383b9",
    "name": "externallmg_1696390848435_1696390756468_image_6.jpeg",
    "path": "cases/65180a572c6c0778ddf117b7/
externallmg_1696390848435_1696390756468_image_6.jpeg",
    "orientation": "landscape"
  }
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651cded12c6c0778ddf383ba",
  "name": "externallmg_1696390850010_1696390756468_image_7.jpeg",
  "path": "cases/65180a572c6c0778ddf117b7/
externallmg_1696390850010_1696390756468_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651cded12c6c0778ddf383bb",
  "name": "externallmg_1696390850017_1696390756468_image_8.jpeg",
  "path": "cases/65180a572c6c0778ddf117b7/
externallmg_1696390850017_1696390756468_image_8.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651cded12c6c0778ddf383bc",
  "name": "externallmg_1696390851707_1696390756468_image_9.jpeg",
  "path": "cases/65180a572c6c0778ddf117b7/
externallmg_1696390851707_1696390756468_image_9.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651cded12c6c0778ddf383bd",
  "name": "externallmg_1696390853419_1696390756468_image_10.jpeg",
  "path": "cases/65180a572c6c0778ddf117b7/
externallmg_1696390853419_1696390756468_image_10.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651cded12c6c0778ddf383be",
  "name": "externallmg_1696390855127_1696390756468_image_11.jpeg",
  "path": "cases/65180a572c6c0778ddf117b7/
externallmg_1696390855127_1696390756468_image_11.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651cded12c6c0778ddf383bf",
  "name": "externallmg_1696390856645_1696390756468_image_12.jpeg",
  "path": "cases/65180a572c6c0778ddf117b7/
externallmg_1696390856645_1696390756468_image_12.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651cded12c6c0778ddf383c0",
  "name": "externallmg_1696390857866_1696390756468_image_13.jpeg",
  "path": "cases/65180a572c6c0778ddf117b7/
externallmg_1696390857866_1696390756468_image_13.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651cded12c6c0778ddf383c1",
  "name": "externallmg_1696390859489_1696390756468_image_14.jpeg",
  "path": "cases/65180a572c6c0778ddf117b7/
externallmg_1696390859489_1696390756468_image_14.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651cded12c6c0778ddf383c2",
  "name": "externallmg_1696390859490_1696390756468_image_15.jpeg",
  "path": "cases/65180a572c6c0778ddf117b7/
externallmg_1696390859490_1696390756468_image_15.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651cded12c6c0778ddf383c3",
  "name": "externallmg_1696390861348_1696390756468_image_16.jpeg",
  "path": "cases/65180a572c6c0778ddf117b7/
externallmg_1696390861348_1696390756468_image_16.jpeg",
  "orientation": "landscape"
},
{
```



```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651cded12c6c0778ddf383c4",
    "name": "externallmg_1696390862436_1696390756468_image_17.jpeg",
    "path": "cases/65180a572c6c0778ddf117b7/
externallmg_1696390862436_1696390756468_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "651cded12c6c0778ddf383c5",
    "name": "externallmg_1696390781371_1696390691769_image_0.jpeg",
    "path": "cases/65180a572c6c0778ddf117b7/
externallmg_1696390781371_1696390691769_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "651cded12c6c0778ddf383c6",
    "name": "externallmg_1696390781707_1696390691769_image_1.jpeg",
    "path": "cases/65180a572c6c0778ddf117b7/
externallmg_1696390781707_1696390691769_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "651cded12c6c0778ddf383c7",
    "name": "externallmg_1696390782875_1696390691769_image_2.jpeg",
    "path": "cases/65180a572c6c0778ddf117b7/
externallmg_1696390782875_1696390691769_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "651cded12c6c0778ddf383c8",
    "name": "externallmg_1696390783603_1696390691769_image_3.jpeg",
    "path": "cases/65180a572c6c0778ddf117b7/
externallmg_1696390783603_1696390691769_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
```

```
    "status": false,
    "_id": "651cded12c6c0778ddf383c9",
    "name": "externallmg_1696390784739_1696390691769_image_4.jpeg",
    "path": "cases/65180a572c6c0778ddf117b7/
externallmg_1696390784739_1696390691769_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "651cded12c6c0778ddf383ca",
    "name": "externallmg_1696390785017_1696390691769_image_5.jpeg",
    "path": "cases/65180a572c6c0778ddf117b7/
externallmg_1696390785017_1696390691769_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "651cded12c6c0778ddf383cb",
    "name": "externallmg_1696390786045_1696390691769_image_6.jpeg",
    "path": "cases/65180a572c6c0778ddf117b7/
externallmg_1696390786045_1696390691769_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "651cded12c6c0778ddf383cc",
    "name": "externallmg_1696390787336_1696390691769_image_7.jpeg",
    "path": "cases/65180a572c6c0778ddf117b7/
externallmg_1696390787336_1696390691769_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "651cded12c6c0778ddf383cd",
    "name": "externallmg_1696390787357_1696390691769_image_8.jpeg",
    "path": "cases/65180a572c6c0778ddf117b7/
externallmg_1696390787357_1696390691769_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
```

```
    "_id": "651cded12c6c0778ddf383ce",
    "name": "externallmg_1696390788441_1696390691769_image_9.jpeg",
    "path": "cases/65180a572c6c0778ddf117b7/
externallmg_1696390788441_1696390691769_image_9.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "651cded12c6c0778ddf383cf",
    "name": "externallmg_1696390789749_1696390691769_image_10.jpeg",
    "path": "cases/65180a572c6c0778ddf117b7/
externallmg_1696390789749_1696390691769_image_10.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "651cded12c6c0778ddf383d0",
    "name": "externallmg_1696390790587_1696390691769_image_11.jpeg",
    "path": "cases/65180a572c6c0778ddf117b7/
externallmg_1696390790587_1696390691769_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "651cded12c6c0778ddf383d1",
    "name": "externallmg_1696390791536_1696390691769_image_12.jpeg",
    "path": "cases/65180a572c6c0778ddf117b7/
externallmg_1696390791536_1696390691769_image_12.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "651cded12c6c0778ddf383d2",
    "name": "externallmg_1696390792420_1696390691769_image_13.jpeg",
    "path": "cases/65180a572c6c0778ddf117b7/
externallmg_1696390792420_1696390691769_image_13.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "651cded12c6c0778ddf383d3",
```

```
    "name": "externalImg_1696390793586_1696390691769_image_14.jpeg",
    "path": "cases/65180a572c6c0778ddf117b7/
externalImg_1696390793586_1696390691769_image_14.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "651cde12c6c0778ddf383d4",
    "name": "externalImg_1696390794598_1696390691769_image_15.jpeg",
    "path": "cases/65180a572c6c0778ddf117b7/
externalImg_1696390794598_1696390691769_image_15.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "651cde12c6c0778ddf383d5",
    "name": "externalImg_1696390794626_1696390691769_image_16.jpeg",
    "path": "cases/65180a572c6c0778ddf117b7/
externalImg_1696390794626_1696390691769_image_16.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "651cde12c6c0778ddf383d6",
    "name": "externalImg_1696390795901_1696390691769_image_17.jpeg",
    "path": "cases/65180a572c6c0778ddf117b7/
externalImg_1696390795901_1696390691769_image_17.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "651cde12c6c0778ddf383d7",
    "name": "externalImg_1696390796639_1696390691769_image_18.jpeg",
    "path": "cases/65180a572c6c0778ddf117b7/
externalImg_1696390796639_1696390691769_image_18.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-09-30T11:45:28.051Z",
```

"updatedAt": "2023-10-04T03:44:36.473Z",
"__v": 0,
"invoiceId": "65180a582c6c0778ddf117e7",
"updatedBy": "60f9343b45132d6a6bdd96e8",
"addressForMap": "",
"caseReferredBy": "",
"contactPersonName": "Shreeji Neelkanth",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9892766957",
"briefDescOfProperty": "",
"carpetTotal": "0",
"finalMeasurementType": "",
"otherCarpetTotal": "0"

}

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			