

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And
Enforcement Of Security Interest Act, 2002",
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_
Enforcement_Of_Security_Interest_Act,_2002"
  },
  "masterTypeOfPurpose": {
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And
Enforcement Of Security Interest Act, 2002",
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_
Enforcement_Of_Security_Interest_Act,_2002"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9f4"
    },
    "type": "CREDITOFFICER",
    "_id": "648aa63dda662768e994f772",
    "firstName": "Saumita Chakraborty",
    "lastName": "Chakraborty",
    "mobileNo": "",
    "workMobileNo": "9167177426",
    "email": "Saumita.racpc.sion@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5000000",
    "discussWithPerson": "Saumita Chakraborty",
```

```
"expectedFees": 2500,
"quotedAmount": "2500"
},
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9f4",
  "branchCode": "000215",
  "type": "BRANCH",
  "name": "RACPC Sion ",
  "email": "racpc.sion@sbi.co.in",
  "mobileNo": "02225046265",
  "alternateMobileNo": "",
  "address": "B-603 & 604, Kohinoor City, Commercial-1, 6th Floor, Kirol Road, Off
L.B.S. Marg, Kurla (West), Mumbai, Pin Code - 400 070, State - Maharashtra, Country -
India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land & _Building / _Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
```

```
    "zoneName": "Mumbai (Metro) & Maharashtra"
  },
  "staff": {
    "pickupPerson": {
      "type": "EMPLOYEE",
      "_id": "60b7177d2ffdf65bcd65882a",
      "role": "PICKUPPERSON",
      "firstName": "Saurabh",
      "email": "saurabhvelonde143@gmail.com",
      "lastName": "Velonde",
      "mobileNo": "8691048846",
      "shortName": "SSV",
      "workWithDocumentMaker": "",
      "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
    },
    "siteEngineer": {
      "type": "EMPLOYEE",
      "_id": "60f9343b45132d6a6bdd96e8",
      "role": "SITEENGINEER",
      "firstName": "Rajesh",
      "email": "rajeshb.ghadi@gmail.com",
      "lastName": "Ghadi",
      "mobileNo": "8652092666",
      "designation": "",
      "shortName": "RHG",
      "workWithDocumentMaker": ""
    },
    "rateVerifier": {
      "type": "EMPLOYEE",
      "_id": "5fc78e26625ecd20ec1f88e9",
      "role": "MAKER+CHECKER",
      "firstName": "Vaishali",
      "email": "v.sarmalkar@vastukala.org",
      "lastName": "Sarmalkar",
      "mobileNo": "9004437379",
      "shortName": "VS",
      "workWithDocumentMaker": "1",
      "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
      "designation": ""
    },
    "maker": "",
    "checker": "",
    "valuers": [
      {
```

```
"valuersRegistrationNumber": [
  {
    "value": "[N]C.C.I.T/I -14/52/2008-09",
    "label": "Wealth Tax"
  }
],
"type": "EMPLOYEE",
"_id": "6084131a13f01f158c6ea1f3",
"PANNo": "AEAPC7114Q",
"role": "VALUER",
"firstName": "Sharadkumar",
"fatherName": "Baburao",
"email": "cmd@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9422171100",
"designation": "CMD",
"registrationNo": [
  {
    "title": {
      "value": "Wealth_Tax",
      "label": "Wealth Tax"
    },
    "_id": "6084131a13f01f158c6ea1f4",
    "number": "[N]C.C.I.T/I -14/52/2008-09"
  }
],
"shortName": "SBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.023706141396698",
  "longitude": "73.0937938387259"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.0937938387259,
    19.023706141396698
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-04",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-04",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-04",
      "remark": ""
    }
  ],
  "schedule": [],
},
"marketAnalysisAndRemark": {
  "audioNotes": [],
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
},
```

```
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Kamothe",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Ground",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahsilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahsilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
```

```
    "value": "",
    "label": true
  },
  "plotNo": {
    "status": true,
    "name": "Plot No.",
    "key": "plotNo",
    "value": "15-16",
    "label": true
  },
  "buildingName": {
    "status": true,
    "name": "Building Name",
    "key": "buildingName",
    "value": "Shreeji Apartment",
    "label": false
  },
  "selectArea": {
    "status": true,
    "name": "Sector",
    "key": "selectArea",
    "value": "6",
    "label": true
  },
  "street1": {
    "status": false,
    "name": "Street 1",
    "key": "street1",
    "value": "",
    "label": false
  },
  "street2": {
    "status": false,
    "name": "Street 2",
    "key": "street2",
    "value": "",
    "label": false
  },
  "landmark": {
    "status": false,
    "name": "Landmark",
    "key": "landmark",
    "value": "",
    "label": false
  },
  "wing": {
```

```

    "status": true,
    "name": "Wing",
    "key": "wing",
    "value": "D",
    "label": true
  },
  "projectName": {
    "status": false,
    "name": "Project Name",
    "key": "projectName",
    "value": "",
    "label": false
  },
  "oldSurveyNumber": {
    "status": false,
    "name": "Old Survey No.",
    "key": "oldSurveyNumber",
    "value": "",
    "label": true
  },
  "newSurveyNumber": {
    "status": false,
    "name": "New/Current Survey No.",
    "key": "newSurveyNumber",
    "value": "",
    "label": true
  },
  "hissaNo": {
    "status": false,
    "name": "Hissa No.",
    "key": "hissaNo",
    "value": "",
    "label": true
  },
  "CTSNo": {
    "status": false,
    "name": "CTS No.",
    "key": "CTSNo",
    "value": "",
    "label": true
  },
  "blockNo": {
    "status": false,
    "name": "Block No",
    "key": "blockNo",
    "value": "",
  }

```



```
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "001",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
```

```
"name": "Gut No.",
"key": "GUTNo",
"value": "",
"label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Kamothe",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  },
  "flooring": {
    "label": "Internal Visit not allowed",
    "value": "Internal_Visit_not_allowed"
  },
  "doors": {
    "label": "Teak Wood Door frame with Solid flush door with M.S Safety door",
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door_with_M.S_Safety_door"
  },
  "windows": {
    "label": "Internal Visit not allowed",
    "value": "Internal_Visit_not_allowed"
  },
  "fittings": {
    "label": "Internal Visit not allowed",
    "value": "Internal_Visit_not_allowed"
  },
  "finishing": {
    "label": "Cement Plastering + POP Finish",
    "value": "Cement_Plastering_+_POP_Finish"
  }
}
},
```

```
"general": {
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  },
  "townplanApprovedByList": {
    "label": "Panvel Municipal Corporation",
    "value": "Panvel_Municipal_Corporation"
  },
  "unitBoundaries": {
    "isDisplay": false
  }
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Middle Class",
    "value": "Middle_Class"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  },
  "propertyOccupiedByList": {
    "label": "External Site Visit Only",
    "value": "External_Site_Visit_Only"
  },
  "monthlyRent": ""
},
"siteMeasurement": {
  "partitions": {
    "label": "6\" Thk. Brick Masonery",
    "value": "6\"_Thk._Brick_Masonery"
  },
  "waterTank": {
    "label": "Municipal Water Supply",
    "value": "MunicipalWaterSupply"
  },
  "pavementLaid": {
    "label": "Yes",
    "value": "Yes"
  },
  "carParking": {
```

```
"label": "Open Car Parking",
"value": "Open_Car_Parking"
},
"constructionWorkStatus": {
  "label": "Completed",
  "value": "Completed"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2008",
  "fullDate": "1/1/2008"
},
"propertyTypeList": {
  "value": "Residential",
  "label": "Residential"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "label": "R.C.C. Framed Structure",
  "value": "R.C.C._Framed_Structure"
},
"qualityOfConstruction": {
  "label": "Good",
  "value": "Good"
},
"walls": {
  "label": "Yes",
  "value": "1"
},
"appearanceOfTheBuilding": {
  "label": "Good",
  "value": "Good"
},
"maintenanceOfTheBuilding": {
  "label": "Good",
  "value": "Good"
},
"visibleDamageInBuilding": {
  "label": "No",
  "value": "0"
},
"groundStilt": {
```

```
"label": "Ground",
"value": "ground"
},
"isSiteVisitAllowed": false,
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"flatFloorNo": "",
"noOfLiftsInEachWings": "0",
"totalLifeBuilding": "60",
"ageOfBuilding": "15",
"estimatedAge": "45",
"noOfFloors": "4",
"noOfDwellingUnitsInBuilding": "02",
"noOfLifts": ""
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
}
```

```
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  }
}
```



```
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
```

```
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"paymentId": [],
"_id": "65181a792c6c0778ddf17412",
"ownerName": "P. Shivdasan ",
"ownerPhoneNo": "0000000000",
"appAddress": "Flat no. 001, Ground floor, D Wing, Shreeji Apartment, Plot no. 15 &
16, Sector - 06, Kamothe Navi Mumbai ",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "path": "cases/65181a792c6c0778ddf17412/
document_1696078384516_Racpc_Sion_P_Shivdasan_NPA.pdf",
    "fileName": "document_1696078384516_Racpc_Sion_P_Shivdasan_NPA.pdf",
    "displayStatus": false,
    "id": "816869",
    "uploadedBy": "60b7177d2ffdf65bcd65882a",
    "createdAt": "Sat Sep 30 2023 18:23:39 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "004131",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "944963",
    "title": "Create Lead",
    "description": "Create Lead",
```

```
"datetime": "Sat Sep 30 2023 18:24:17 GMT+0530 (India Standard Time)"
}
],
"owners": [
{
"name": "P. Shivdasan ",
"phone": "0000000000",
"ownershipShare": "",
"email": "",
"id": "719939"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "651ce02c2c6c0778ddf386d7",
"name": "externalImg_1696391199148_1696391111306_image_0.jpeg",
"path": "cases/65181a792c6c0778ddf17412/
externalImg_1696391199148_1696391111306_image_0.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "651ce02c2c6c0778ddf386d8",
"name": "externalImg_1696391199235_1696391111307_image_1.jpeg",
"path": "cases/65181a792c6c0778ddf17412/
externalImg_1696391199235_1696391111307_image_1.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "651ce02c2c6c0778ddf386d9",
"name": "externalImg_1696391199288_1696391111307_image_2.jpeg",
"path": "cases/65181a792c6c0778ddf17412/
externalImg_1696391199288_1696391111307_image_2.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651ce02c2c6c0778ddf386da",
  "name": "externallmg_1696391200496_1696391111307_image_3.jpeg",
  "path": "cases/65181a792c6c0778ddf17412/
externallmg_1696391200496_1696391111307_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651ce02c2c6c0778ddf386db",
  "name": "externallmg_1696391200509_1696391111307_image_4.jpeg",
  "path": "cases/65181a792c6c0778ddf17412/
externallmg_1696391200509_1696391111307_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651ce02c2c6c0778ddf386dc",
  "name": "externallmg_1696391200550_1696391111307_image_5.jpeg",
  "path": "cases/65181a792c6c0778ddf17412/
externallmg_1696391200550_1696391111307_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651ce02c2c6c0778ddf386dd",
  "name": "externallmg_1696391200577_1696391111307_image_6.jpeg",
  "path": "cases/65181a792c6c0778ddf17412/
externallmg_1696391200577_1696391111307_image_6.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651ce02c2c6c0778ddf386de",
  "name": "externallmg_1696391200604_1696391111307_image_7.jpeg",
  "path": "cases/65181a792c6c0778ddf17412/
externallmg_1696391200604_1696391111307_image_7.jpeg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "651ce02c2c6c0778ddf386df",
      "name": "externallmg_1696391200641_1696391111307_image_8.jpeg",
      "path": "cases/65181a792c6c0778ddf17412/
externallmg_1696391200641_1696391111307_image_8.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "651ce02c2c6c0778ddf386e0",
      "name": "externallmg_1696391201504_1696391111307_image_9.jpeg",
      "path": "cases/65181a792c6c0778ddf17412/
externallmg_1696391201504_1696391111307_image_9.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "651ce02c2c6c0778ddf386e1",
      "name": "externallmg_1696391201506_1696391111307_image_10.jpeg",
      "path": "cases/65181a792c6c0778ddf17412/
externallmg_1696391201506_1696391111307_image_10.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "651ce02c2c6c0778ddf386e2",
      "name": "externallmg_1696391201528_1696391111307_image_11.jpeg",
      "path": "cases/65181a792c6c0778ddf17412/
externallmg_1696391201528_1696391111307_image_11.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "651ce02c2c6c0778ddf386e3",
      "name": "externallmg_1696391201551_1696391111307_image_12.jpeg",
      "path": "cases/65181a792c6c0778ddf17412/
externallmg_1696391201551_1696391111307_image_12.jpeg",
      "orientation": "landscape"
    },
  },
```

```
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "651ce02c2c6c0778ddf386e4",
  "name": "externallmg_1696391160542_1696391042074_image_0.jpeg",
  "path": "cases/65181a792c6c0778ddf17412/
externallmg_1696391160542_1696391042074_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "651ce02c2c6c0778ddf386e5",
  "name": "externallmg_1696391160757_1696391068144_image_0.jpeg",
  "path": "cases/65181a792c6c0778ddf17412/
externallmg_1696391160757_1696391068144_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "651ce02c2c6c0778ddf386e6",
  "name": "externallmg_1696391160778_1696391068144_image_1.jpeg",
  "path": "cases/65181a792c6c0778ddf17412/
externallmg_1696391160778_1696391068144_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "651ce02c2c6c0778ddf386e7",
  "name": "externallmg_1696391160808_1696391068144_image_2.jpeg",
  "path": "cases/65181a792c6c0778ddf17412/
externallmg_1696391160808_1696391068144_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "651ce02c2c6c0778ddf386e8",
  "name": "externallmg_1696391162022_1696391068144_image_3.jpeg",
  "path": "cases/65181a792c6c0778ddf17412/
externallmg_1696391162022_1696391068144_image_3.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "651ce02c2c6c0778ddf386e9",
    "name": "externallmg_1696391162042_1696391068144_image_4.jpeg",
    "path": "cases/65181a792c6c0778ddf17412/
externallmg_1696391162042_1696391068144_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "651ce02c2c6c0778ddf386ea",
    "name": "externallmg_1696391162064_1696391068144_image_5.jpeg",
    "path": "cases/65181a792c6c0778ddf17412/
externallmg_1696391162064_1696391068144_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "651ce02c2c6c0778ddf386eb",
    "name": "externallmg_1696391162089_1696391068144_image_6.jpeg",
    "path": "cases/65181a792c6c0778ddf17412/
externallmg_1696391162089_1696391068144_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "651ce02c2c6c0778ddf386ec",
    "name": "externallmg_1696391162121_1696391068144_image_7.jpeg",
    "path": "cases/65181a792c6c0778ddf17412/
externallmg_1696391162121_1696391068144_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "651ce02c2c6c0778ddf386ed",
    "name": "externallmg_1696391162156_1696391068144_image_8.jpeg",
    "path": "cases/65181a792c6c0778ddf17412/
externallmg_1696391162156_1696391068144_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
```



```
    "status": false,
    "_id": "651ce02c2c6c0778ddf386ee",
    "name": "externalimg_1696391162945_1696391068144_image_9.jpeg",
    "path": "cases/65181a792c6c0778ddf17412/
externalimg_1696391162945_1696391068144_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "651ce02c2c6c0778ddf386ef",
    "name": "externalimg_1696391162970_1696391068144_image_10.jpeg",
    "path": "cases/65181a792c6c0778ddf17412/
externalimg_1696391162970_1696391068144_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "651ce02c2c6c0778ddf386f0",
    "name": "externalimg_1696391162999_1696391068144_image_11.jpeg",
    "path": "cases/65181a792c6c0778ddf17412/
externalimg_1696391162999_1696391068144_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "651ce02c2c6c0778ddf386f1",
    "name": "externalimg_1696391163038_1696391068144_image_12.jpeg",
    "path": "cases/65181a792c6c0778ddf17412/
externalimg_1696391163038_1696391068144_image_12.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-09-30T12:54:17.711Z",
"updatedAt": "2023-10-04T03:50:12.341Z",
"__v": 0,
"invoiceId": "65181a7a2c6c0778ddf17436",
"updatedBy": "60f9343b45132d6a6bdd96e8",
"fullAddress": " Flat No. 001, Ground Floor, Wing - D, Shreeji Apartment, Plot No.
15-16, Sector 6, Village - Kamothe, Kamothe",
"addressForMap": "",
```

"caseReferredBy": "60b7177d2ffdf65bcd65882a",  
"contactPersonName": "P. Shivdasan ",  
"email": "",  
"isExternal": "false",  
"isUrgent": "false",  
"ownershipShare": "",  
"purchaseValueAsPerDocument": "",  
"relationWithOwner": "self",  
"siteVisitContactNo": "0000000000"

}

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
Composition :			
Other			
Composition :			