

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7f7"
    },
    "type": "CREDITOFFICER",
    "_id": "64d4829d87258203eab0d8d8",
    "firstName": "Shivani ",
    "lastName": "Yadav",
    "mobileNo": "",
    "workMobileNo": "8240289378",
    "email": "racpcghatkopar.sanctions@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5000000",
    "discussWithPerson": "Shivani ",
    "expectedFees": 2500,
    "quotedAmount": "2500"
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7f7",
  "branchCode": "000064",
  "type": "BRANCH",
  "name": "RACPC Ghatkopar (West)",
  "email": "racpcghatkopar.sanctions@sbi.co.in",
  "mobileNo": "022-25009143",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, 1st Floor, Ashok Silk Mills
Compound, LBS Marg, Ghatkopar (West), Mumbai - 400 086, State - Maharashtra,
Country - India.\r\n\r\n\r\n\r\n",
  "ledgerName": "STATE BANK OF INDIA - RACPC GHATKOPAR",
  "fax": "022-25009010",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62ea09ea4e679b264caf07d7",
  "role": "SITEENGINEER",
  "firstName": "Suraj",
  "email": "suraj@vastukala.org",
  "lastName": "Zore",
  "mobileNo": "8652448654",
  "designation": "",
  "shortName": "SZ",
  "workWithDocumentMaker": "60092304a16fab0f2af9b0c2",
  "profilePhoto": "users/62ea09ea4e679b264caf07d7/
profilePhoto_1685629394240_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
  "designation": "",
  "shortName": "NK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
```

```
"lastName": "Khedekar",
"mobileNo": "8369040652",
"designation": "",
"shortName": "NK",
"workWithDocumentMaker": "",
"profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "627221f4afd7d55eddeddcb4",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Prajakta",
  "email": "prajakta@vastukala.org",
  "lastName": "Patil",
  "mobileNo": "9769797568",
  "designation": "",
  "shortName": "P",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
  },

```

```
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.152070627701445",
  "longitude": " 72.94668409140482"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.94668409140482,
```

```
19.152070627701445
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-04",
      "remark": ""
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Bhandup",
```

```
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "16",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban ",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kurla",
  "label": true
},
"plotNo": {
  "status": false,
```

```
"name": "Plot No.",
"key": "plotNo",
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Shubh Aangan",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "M. D. Kini Marg",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
}
```



```
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "519, 519/1 & 2 ",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
```

```
"key": "selectNo",
"value": "1602",
"label": false
},
"municipalityWardNo": {
  "status": true,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "S Ward ",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
```

```
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 400 042",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Nahur(East), Mumbai",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Concealed_wiring",
    "label": "Proposed Concealed plumbing with C.P. fittings. Concealed wiring"
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
}
```

```
"populationClassList": {
  "value": "MiddleClass",
  "label": "Middle Class"
},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "MCGM",
  "label": "Municipal Corporation of Greater Mumbai (MCGM)"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Pankaj Apartment",
  "west": "Slum Area",
  "south": "M. D. Kini Marg",
  "east": "Shubhkamana Society"
},
"asPerDocumentAgreement": {
  "north": "Vijay CHSL",
  "west": "Advait CHSL",
  "south": "M. D. Keni Marg",
  "east": "RBI Complex "
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "",
```

```
"approvePlanVerified": "",
"empanelledOfApprovePlan": ""
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Residential ",
  "rate": "141340.00",
  "landRate": "61430",
  "igrImage": "cases/651d0e912c6c0778ddf43530/igr_1696488444337_Image.png",
  "squareMeterGuideLineRate": "155474.00",
  "squareFeetGuideLineRate": "14444.00"
},
"igrFinalRate": {
  "depreciationPercentage": "0",
  "rate": "141340",
  "squareMeterGuideLineRate": "155474.00",
  "squareFeetGuideLineRate": "14444.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Middle_Class",
    "label": "Middle Class"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "28000",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per MCGM norms",
```

```
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Covered parking space",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2022",
    "fullDate": "1/1/2022"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  }
}
```

```
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenancelssues": {
```

```
"value": "0",
"label": "No"
},
"visibleDamageInBuilding": {
"value": "0",
"label": "No"
},
"systemOfAirConditioning": {
"value": "Information_not_available",
"label": "Information not available"
},
"provisionOfFirefighting": {
"value": "Information_not_available",
"label": "Information not available"
},
"groundStilt": {
"value": "stilt",
"label": "Stilt"
},
"yearOfConstructionAsPer": {
"value": "As_Per_Part_Occupancy_Certificate",
"label": "As Per Part Occupancy Certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "1",
"totalLifeBuilding": "60",
"estimatedAge": "59",
"noOfBasement": "",
"noOfPodium": "1",
"noOfAmenityFloors": "",
"noOfFloors": "21",
"flatFloorNo": "",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
"area": "748.00",
"measurementType": "Sq. Ft.",
"areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
"routeMapDetail": {
"routeStation": {
"value": "Railway_Station",
"label": "Railway Station"
}
}
},
```



```
    "routeMapImg": "cases/651d0e912c6c0778ddf43530/
routeMap_1696489701010_Image.png",
    "routeLat": "19.151980",
    "routeLng": "72.946825",
    "stationName": "Nahur",
    "routeDistance": "400 Mts."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latlng": true,
    "finallatlng": true
  },
  "locationMapImg": [
    {
      "id": "jgk8gs",
      "name": "jgk8gs",
      "image": "cases/651d0e912c6c0778ddf43530/
routeMap_1696489734924_Image.png"
    }
  ],
  "valuation": {
    "wardrobesRate": "0",
    "totalwardrobesRate": "0",
    "wardrobesQty": "0",
    "showcasesQty": "0",
    "showcasesRate": "0",
    "totalshowcasesRate": "0",
    "kitchenArrangementsQty": "0",
    "kitchenArrangementsRate": "0",
    "totalkitchenArrangementsRate": "0",
    "superfineFinishQty": "0",
    "superfineFinishRate": "0",
    "totalsuperfineFinishRate": "0",
    "interiorDecorationsQty": "0",
    "interiorDecorationsRate": "0",
    "totalinteriorDecorationsRate": "0",
    "electricityDepositsQty": "0",
    "electricityDepositsRate": "0",
    "totalelectricityDepositsRate": "0",
```

```
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "13600000.00",
"finalValue": "13600000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Thu Oct 05 2023 13:35:22 GMT+0530 (India Standard Time)",
  "number": "2302851",
  "dayCount": "6",
  "monthCount": "48",
  "generatedBy": "627221f4afd7d55eddeddcb4"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "10804112.00",
"selectedBuildUpValue": "748.00",
"selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
"frontPageImages": [
{
"status": false,
"_id": "651da9b1b98e691677d915bf",
"name": "externallmg_r_1696442735018_1696442645610_image_0.jpg",
"path": "cases/651d0e912c6c0778ddf43530/externallmg_r_1696442735018_1696442645610_image_0.jpg",
"orientation": "portrait"
}
],
"selfieWithSiteVisitImages": [
{
"status": false,
"_id": "651da9b1b98e691677d915cf",
"name": "externallmg_r_1696442772085_1696442645610_image_18.jpg",
"path": "cases/651d0e912c6c0778ddf43530/externallmg_r_1696442772085_1696442645610_image_18.jpg",
"orientation": "portrait"
}
],
"externalPhotos": [
{
"status": false,
"_id": "651da9b1b98e691677d915c2",
"name": "externallmg_r_1696442736799_1696442645610_image_1.jpg",
"path": "cases/651d0e912c6c0778ddf43530/externallmg_r_1696442736799_1696442645610_image_1.jpg",
"orientation": "portrait"
}
]
```

```
}
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "651da9b1b98e691677d915c1",
    "name": "externallmg_r_1696442737714_1696442645610_image_2.jpg",
    "path": "cases/651d0e912c6c0778ddf43530/
externallmg_r_1696442737714_1696442645610_image_2.jpg",
    "orientation": "portrait"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "651da9b1b98e691677d915c8",
    "name": "Living Room",
    "path": "cases/651d0e912c6c0778ddf43530/
externallmg_r_1696442757548_1696442645610_image_9.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "651da9b1b98e691677d915c7",
    "name": "Living Room",
    "path": "cases/651d0e912c6c0778ddf43530/
externallmg_r_1696442756312_1696442645610_image_8.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "651da9b1b98e691677d915ca",
    "name": "Living Room",
    "path": "cases/651d0e912c6c0778ddf43530/
externallmg_r_1696442760435_1696442645610_image_11.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "651da9b1b98e691677d915cb",
    "name": "Living Room",
    "path": "cases/651d0e912c6c0778ddf43530/
externallmg_r_1696442765525_1696442645610_image_14.jpg",
    "orientation": "portrait"
  }
]
```

```
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "18879",
    "max": "21967"
  },
  "builtUpRateRange": {
    "min": "17163",
    "max": "19971"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
```

```
"title": "Superfine finish",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```



```
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "680.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvancelInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentId": [],
"_id": "651d0e912c6c0778ddf43530",
"ownerName": "Rajeshri Sukhadev Bangar",
"ownerPhoneNo": "9892379478",
"appAddress": "Flat no. 1602, 16th Floor, Wing - A, Shubh Angan, Nahur West ",
"remark": "",
"documents": [
  {
```

```
"documentType": {
  "label": "Agreement For Sale",
  "value": "60ae1254aa6d152c1801b326"
},
"inputs": {
  "documentDate": "07/05/2019",
  "from": {
    "value": "Promoter",
    "label": "Promoter"
  },
  "Promoter": "G. D. Realtors Private Limited ",
  "to": {
    "value": "The_Allottees",
    "label": "The Allottees"
  },
  "The_Allottees": "Rajeshri Sukhadev Bangar & Sukhadev Kondiba Bangar",
  "number": {
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "5383 / 2019"
},
"isHardCopy": false,
"displayStatus": true,
"id": "635193",
"path": "cases/651d0e912c6c0778ddf43530/
document_1696403013402_Racpc_GHatkopar_Rajashri_Bangar.pdf",
"fileName": "document_1696403013402_Racpc_GHatkopar_Rajashri_Bangar.pdf"
},
{
  "documentType": {
    "value": "60ae1250aa6d152c1801b316",
    "label": "Part Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "28/04/2022",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_Of_Greater_Mumbai",
      "label": "Municipal Corporation Of Greater Mumbai"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "CE / 1258 / BPES / AS / OCC / 1 / New"
  },
}
```

```
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1696489021638_138015.pdf",
    "path": "cases/651d0e912c6c0778ddf43530/
document_1696489021638_138015.pdf",
    "id": "640409",
    "uploadedBy": "60092304a16fab0f2af9b0c2",
    "createdAt": "Thu Oct 05 2023 12:27:01 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae1247aa6d152c1801b2ea",
      "label": "Commencement Certificate"
    },
    "inputs": {
      "documentDate": "04/01/2018",
      "nameOfApprovingAuthority": {
        "value": "Municipal_Corporation_Of_Greater_Mumbai",
        "label": "Municipal Corporation Of Greater Mumbai"
      },
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "CE / 1258 / BPES / AS"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1696489177778_149752.pdf",
    "path": "cases/651d0e912c6c0778ddf43530/
document_1696489177778_149752.pdf",
    "id": "369969",
    "uploadedBy": "60092304a16fab0f2af9b0c2",
    "createdAt": "Thu Oct 05 2023 12:29:38 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "004166",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "583770",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Oct 04 2023 12:34:49 GMT+0530 (India Standard Time)"
  }
],
```

```
"owners": [
  {
    "name": "Rajeshri Sukhadev Bangar",
    "phone": "9892379478",
    "ownershipShare": "",
    "email": "",
    "id": "847132"
  },
  {
    "name": "Sukhadev Kondiba Bangar",
    "phone": "",
    "email": "",
    "ownershipShare": "",
    "id": "778099"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "135592",
    "name": "Living Room",
    "length": "20.75",
    "length1": "20",
    "length2": "9",
    "width": "10.75",
    "width1": "10",
    "width2": "9",
    "totalArea": "223.06",
    "images": [],
    "extraAreas": [],
    "finalArea": "223.06"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "name": "Kitchen",
    "length": "7.17",
    "length1": "7",
```

```
"length2": "2",
"width": "10.33",
"width1": "10",
"width2": "4",
"totalArea": "74.06",
"images": [],
"extraAreas": [],
"finalArea": "74.06"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Toilet",
  "length": "6.33",
  "length1": "6",
  "length2": "4",
  "width": "3.75",
  "width1": "3",
  "width2": "9",
  "totalArea": "23.75",
  "images": [],
  "extraAreas": [],
  "finalArea": "23.75"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Toilet",
  "length": "3.75",
  "length1": "3",
  "length2": "9",
  "width": "7.75",
  "width1": "7",
  "width2": "9",
  "totalArea": "29.06",
  "images": [],
  "extraAreas": [],
  "finalArea": "29.06"
},
{
```

```
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "4",
"name": "Bedroom",
"length": "11.58",
"length1": "11",
"length2": "7",
"width": "10.08",
"width1": "10",
"width2": "1",
"totalArea": "116.80",
"images": [],
"extraAreas": [],
"finalArea": "116.80"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bedroom",
  "length": "9.33",
  "length1": "9",
  "length2": "4",
  "width": "12.75",
  "width1": "12",
  "width2": "9",
  "totalArea": "119.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "119.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Passage",
  "length": "3.17",
  "length1": "3",
  "length2": "2",
  "width": "9.08",
```

```
"width1": "9",
"width2": "1",
"totalArea": "28.76",
"images": [],
"extraAreas": [],
"finalArea": "28.76"
}
],
"otherComposition": [
{
"toBeAdded": {
"label": "Carpet",
"value": "Carpet"
},
"name": {
"label": "Dry Balcony Area",
"value": "Dry_Balcony_Area"
},
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "0",
"length1": "7",
"length2": "2",
"length": "7.17",
"width1": "2",
"width2": "2",
"width": "2.17",
"totalArea": "15.53",
"percentageBeforeTotal": "15.53",
"images": [],
"extraAreas": [],
"percentage": "100",
"finalArea": "15.53"
}
],
"externalReport": [],
"documentPerArea": [
{
"typeOfDocument": {
"label": "Agreement For Sale",
"value": "60ae1254aa6d152c1801b326"
},
"docMeasurementType": {
"value": "Square_Feet",
```

```
    "label": "Square Feet"
  },
  "selectAreaTypeDocument": "Carpet",
  "squareMeterArea": "63.17",
  "totalAreaDocument": "680.00",
  "docBuiltupPercentage": "10",
  "docFinalBuiltUp": "748.00",
  "docFinalBuiltUpSquareMeter": "69.49",
  "docSaleablePercentage": "",
  "docFinalSaleable": "0.00",
  "docFinalSaleableSquareMeter": "0.00",
  "id": "123305"
}
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "651e5c0db98e691677d9c155",
    "property": "GD Shubh Angan, Nahur (East)",
    "area": "455.00",
    "builtUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "Housing.Com",
    "expectedPrice": "9995000.00",
    "expectedRate": "21967.03",
    "builtUpExpectedRate": "19970.03",
    "image": "cases/651d0e912c6c0778ddf43530/indicator_1696488250738_Image.png",
    "squareMeter": "42.27",
    "id": "325197"
  },
  {
    "printlnReport": true,
    "_id": "651e5c0db98e691677d9c156",
    "property": "Aum Shubh Chintan, Nahur (East), Mumbai",
    "area": "478.00",
    "builtUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "Housing.Com",
    "expectedPrice": "9998000.00",
    "expectedRate": "20916.32",
```



```
    "builtUpExpectedRate": "19014.83",
    "image": "cases/651d0e912c6c0778ddf43530/
indicator_1696488305052_Image.png",
    "squareMeter": "44.41",
    "id": "303771"
  },
  {
    "printlnReport": true,
    "_id": "651e5c0db98e691677d9c157",
    "property": "Aum Shubh Chintan Bhandup East, Mumbai",
    "area": "478.00",
    "builtUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "square_yards",
    "expectedPrice": "9999000.00",
    "expectedRate": "20918.41",
    "builtUpExpectedRate": "19016.74",
    "image": "cases/651d0e912c6c0778ddf43530/
indicator_1696488359937_Image.png",
    "squareMeter": "44.41",
    "id": "748701"
  },
  {
    "printlnReport": true,
    "_id": "651e5c0db98e691677d9c158",
    "property": "AUM Shubh Chintan, Bhandup East",
    "area": "478.00",
    "builtUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "Commonfloor.com",
    "expectedPrice": "9024000.00",
    "expectedRate": "18878.66",
    "builtUpExpectedRate": "17162.42",
    "image": "cases/651d0e912c6c0778ddf43530/
indicator_1696488406187_Image.png",
    "squareMeter": "44.41",
    "id": "740032"
  }
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "651da9b1b98e691677d915bf",
  "name": "externallmg_r_1696442735018_1696442645610_image_0.jpg",
  "path": "cases/651d0e912c6c0778ddf43530/
externallmg_r_1696442735018_1696442645610_image_0.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651da9b1b98e691677d915c0",
  "name": "externallmg_r_1696442739585_1696442645610_image_3.jpg",
  "path": "cases/651d0e912c6c0778ddf43530/
externallmg_r_1696442739585_1696442645610_image_3.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651da9b1b98e691677d915c1",
  "name": "externallmg_r_1696442737714_1696442645610_image_2.jpg",
  "path": "cases/651d0e912c6c0778ddf43530/
externallmg_r_1696442737714_1696442645610_image_2.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651da9b1b98e691677d915c2",
  "name": "externallmg_r_1696442736799_1696442645610_image_1.jpg",
  "path": "cases/651d0e912c6c0778ddf43530/
externallmg_r_1696442736799_1696442645610_image_1.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651da9b1b98e691677d915c3",
  "name": "externallmg_r_1696442740827_1696442645610_image_4.jpg",
  "path": "cases/651d0e912c6c0778ddf43530/
externallmg_r_1696442740827_1696442645610_image_4.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "651da9b1b98e691677d915c4",
    "name": "externallmg_r_1696442743908_1696442645610_image_6.jpg",
    "path": "cases/651d0e912c6c0778ddf43530/
externallmg_r_1696442743908_1696442645610_image_6.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651da9b1b98e691677d915c5",
    "name": "externallmg_r_1696442742696_1696442645610_image_5.jpg",
    "path": "cases/651d0e912c6c0778ddf43530/
externallmg_r_1696442742696_1696442645610_image_5.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651da9b1b98e691677d915c6",
    "name": "externallmg_r_1696442747380_1696442645610_image_7.jpg",
    "path": "cases/651d0e912c6c0778ddf43530/
externallmg_r_1696442747380_1696442645610_image_7.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651da9b1b98e691677d915c7",
    "name": "externallmg_r_1696442756312_1696442645610_image_8.jpg",
    "path": "cases/651d0e912c6c0778ddf43530/
externallmg_r_1696442756312_1696442645610_image_8.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651da9b1b98e691677d915c8",
    "name": "externallmg_r_1696442757548_1696442645610_image_9.jpg",
    "path": "cases/651d0e912c6c0778ddf43530/
externallmg_r_1696442757548_1696442645610_image_9.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651da9b1b98e691677d915c9",
```

```
    "name": "externallmg_r_1696442758318_1696442645610_image_10.jpg",
    "path": "cases/651d0e912c6c0778ddf43530/
externallmg_r_1696442758318_1696442645610_image_10.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651da9b1b98e691677d915ca",
    "name": "externallmg_r_1696442760435_1696442645610_image_11.jpg",
    "path": "cases/651d0e912c6c0778ddf43530/
externallmg_r_1696442760435_1696442645610_image_11.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651da9b1b98e691677d915cb",
    "name": "externallmg_r_1696442765525_1696442645610_image_14.jpg",
    "path": "cases/651d0e912c6c0778ddf43530/
externallmg_r_1696442765525_1696442645610_image_14.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651da9b1b98e691677d915cc",
    "name": "externallmg_r_1696442763472_1696442645610_image_13.jpg",
    "path": "cases/651d0e912c6c0778ddf43530/
externallmg_r_1696442763472_1696442645610_image_13.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651da9b1b98e691677d915cd",
    "name": "externallmg_r_1696442761393_1696442645610_image_12.jpg",
    "path": "cases/651d0e912c6c0778ddf43530/
externallmg_r_1696442761393_1696442645610_image_12.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651da9b1b98e691677d915ce",
    "name": "externallmg_r_1696442767579_1696442645610_image_15.jpg",
```

```
    "path": "cases/651d0e912c6c0778ddf43530/
externallmg_r_1696442767579_1696442645610_image_15.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651da9b1b98e691677d915cf",
    "name": "externallmg_r_1696442772085_1696442645610_image_18.jpg",
    "path": "cases/651d0e912c6c0778ddf43530/
externallmg_r_1696442772085_1696442645610_image_18.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651da9b1b98e691677d915d0",
    "name": "externallmg_r_1696442770150_1696442645610_image_17.jpg",
    "path": "cases/651d0e912c6c0778ddf43530/
externallmg_r_1696442770150_1696442645610_image_17.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651da9b1b98e691677d915d1",
    "name": "externallmg_r_1696442768873_1696442645610_image_16.jpg",
    "path": "cases/651d0e912c6c0778ddf43530/
externallmg_r_1696442768873_1696442645610_image_16.jpg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "651da9b1b98e691677d915d2",
    "name": "externallmg_r_1696442657046_1696442557026_image_2.png",
    "path": "cases/651d0e912c6c0778ddf43530/
externallmg_r_1696442657046_1696442557026_image_2.png",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "651da9b1b98e691677d915d3",
    "name": "externallmg_r_1696442640139_1696442557026_image_0.jpg",
    "path": "cases/651d0e912c6c0778ddf43530/
externallmg_r_1696442640139_1696442557026_image_0.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "651da9b1b98e691677d915d4",
  "name": "externalimg_r_1696442649526_1696442557026_image_1.jpg",
  "path": "cases/651d0e912c6c0778ddf43530/
externalimg_r_1696442649526_1696442557026_image_1.jpg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-10-04T07:04:49.255Z",
"updatedAt": "2023-10-05T08:35:16.933Z",
"__v": 0,
"invoiceId": "651d0e912c6c0778ddf43553",
"fullAddress": "Residential Flat No. 1602, 16th Floor, Wing - A, Shubh Aangan, M. D.
Kini Marg, Village - Bhandup, Municipality Ward No. S Ward , Nahur(East), Mumbai,
Taluka - Kurla, District - Mumbai Suburban , PIN Code - 400 042, State - Maharashtra,
India",
"updatedBy": "627221f4afd7d55eddeddcb4",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Rajeshri Sukhdev Bangar",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9892379478",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + 2 Toilet + Passage",
"carpetTotal": "223.06",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "15.53",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "15.53",
"otherCompositionSaleableTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "693.02",
"finalCarpetArea": "630.02",
"finalSalableArea": "762.32",
"salablePercentage": "10",
```

```

"toBeAdded": "",
"extendOfSiteRemark": "Carpet Area in Sq. Ft. = 662.00\nBalcony Area in Sq. Ft. =
18.00\nTotal Carpet Area in Sq. Ft. = 680.00\n(Area as per Agreement for Sale)",
"siteMeasurementRemark": "",
"buildingServicesRate": "3000.00",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 680.00",
"flatRate": "20000.00",
"landOtherRate": "17000",
"finalSaleablePercentage": "",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"shopDetails": {
  "typeOfShops": {
    "label": "",
    "value": ""
  },
  "roadFacing": false,
  "mall": false
},
"siteVisitDate": "2023-10-04"
}

```

Name	Length	Width	Total
Composition :			
Living Room	20'9"	10'9"	223.06

Kitchen	7'2"	10'4"	74.06
Toilet	6'4"	3'9"	23.75
Toilet	3'9"	7'9"	29.06
Bedroom	11'7"	10'1"	116.80
Bedroom	9'4"	12'9"	119.00
Passage	3'2"	9'1"	28.76
Other Composition :			
Dry Balcony Area	7'2"	2'2"	15.53