

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7f7"
    },
    "type": "CREDITOFFICER",
    "_id": "64d4829d87258203eab0d8d8",
    "firstName": "Shivani ",
    "lastName": "Yadav",
    "mobileNo": "",
    "workMobileNo": "8240289378",
    "email": "racpcghatkopar.sanctions@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "6000000",
    "discussWithPerson": "Shivani ",
    "expectedFees": 3000,
    "quotedAmount": "2500"
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7f7",
  "branchCode": "000064",
  "type": "BRANCH",
  "name": "RACPC Ghatkopar (West)",
  "email": "racpcghatkopar.sanctions@sbi.co.in",
  "mobileNo": "022-25009143",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, 1st Floor, Ashok Silk Mills
Compound, LBS Marg, Ghatkopar (West), Mumbai - 400 086, State - Maharashtra,
Country - India.\r\n\r\n\r\n",
  "ledgerName": "STATE BANK OF INDIA - RACPC GHATKOPAR",
  "fax": "022-25009010",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62ea09ea4e679b264caf07d7",
  "role": "SITEENGINEER",
  "firstName": "Suraj",
  "email": "suraj@vastukala.org",
  "lastName": "Zore",
  "mobileNo": "8652448654",
  "designation": "",
  "shortName": "SZ",
  "workWithDocumentMaker": "60092304a16fab0f2af9b0c2",
  "profilePhoto": "users/62ea09ea4e679b264caf07d7/
profilePhoto_1685629394240_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
  "designation": "",
  "shortName": "NK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627221f4afd7d55eddeddcb4",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Prajakta",
  "email": "prajakta@vastukala.org",
```

```
"lastName": "Patil",
"mobileNo": "9769797568",
"designation": "",
"shortName": "P",
"workWithDocumentMaker": "",
"profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
  "designation": "",
  "shortName": "NK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
  },

```

```
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.180832798275812",
  "longitude": "72.97516083558223"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.97516083558223,
```

```
19.180832798275812
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-05",
      "remark": ""
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Kopri",
```

```
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "6",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "D",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane",
  "label": true
},
"plotNo": {
  "status": true,
```

```
"name": "Plot No.",
"key": "plotNo",
"value": "Gut No. 70 (P)",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Maitrey Park D Wing Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Parsiwadi Kopri",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "D",
  "label": true
}
```



```
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
```

```
"key": "selectNo",
"value": "603",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
}
```

```
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 400 603",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Thane (East)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows_with_M._S._Grills",
    "label": "Powder coated Aluminum sliding windows with M. S. Grills"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  }
}
```

```
},
"populationClassList": {
  "value": "MiddleClass",
  "label": "Middle Class"
},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "Thane_Municipal_Corporation",
  "label": "Thane Municipal Corporation"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Slum Area",
  "west": "SRA Building",
  "south": "Slum Area",
  "east": "Wing - I"
},
"asPerDocumentAgreement": {
  "north": "Details not available",
  "west": "Details not available",
  "south": "Details not available",
  "east": "Details not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
```

```
"dateOfIssusApprovePlan": "",
"approvePlanVerified": "",
"empanelledOfApprovePlan": ""
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "16.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "12538",
  "depreciatedBuildingRate": "2338"
},
"igrRate": {
  "propertyName": "Residential ",
  "rate": "109800",
  "landRate": "39500",
  "igrImage": "cases/651d18f92c6c0778ddf454f4/igr_1696481700402_Image.png",
  "squareMeterGuideLineRate": "115290.00",
  "squareFeetGuideLineRate": "10711.00"
},
"igrFinalRate": {
  "depreciationPercentage": "89",
  "rate": "9936.00",
  "squareFeetGuideLineRate": "9936.00",
  "squareMeterGuideLineRate": "106953.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Middle_Class",
    "label": "Middle Class"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Vacant",
    "label": "Vacant"
  },
  "monthlyRent": "15000",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
```

```
"floorSpaceIndex": "As per TMC norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed Area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Stilt Car parking",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2012",
    "fullDate": "1/1/2012"
  },
  "planningArea": {
    "value": "Residential",
```

```
"label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "RCC_Framed_Structure",
  "label": "RCC Framed Structure"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
}
```

```
"maintenancelssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "11",
"totalLifeBuilding": "60",
"estimatedAge": "49",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "8",
"flatFloorNo": "",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "575.00",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  }
}
```



```
    },
    "routeMapImg": "cases/651d18f92c6c0778ddf454f4/
routeMap_1696507621744_Image.png",
    "routeLat": "19.180951",
    "routeLng": "72.974507",
    "stationName": "Thane",
    "routeDistance": "850 Mt."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "ad13v",
      "name": "ad13v",
      "image": "cases/651d18f92c6c0778ddf454f4/
routeMap_1696507558649_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
```

```
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "7209350.00",
"finalValue": "7209350.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
}
```

```
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"guidelineDetails": {
  "finalGuidelineValue": "5713200.00",
  "selectedBuildUpValue": "575.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "651e83b4072fba0ce3f3e0a1",
      "name": "externallmg_r_1696498590446_1696498472203_image_16.jpg",
      "path": "cases/651d18f92c6c0778ddf454f4/externallmg_r_1696498590446_1696498472203_image_16.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "651e83b4072fba0ce3f3e09d",
      "name": "externallmg_r_1696498581416_1696498472203_image_12.jpg",
      "path": "cases/651d18f92c6c0778ddf454f4/externallmg_r_1696498581416_1696498472203_image_12.jpg",
      "orientation": "landscape"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "651e83b4072fba0ce3f3e09f",
      "name": "externallmg_r_1696498588393_1696498472203_image_15.jpg",
      "path": "cases/651d18f92c6c0778ddf454f4/externallmg_r_1696498588393_1696498472203_image_15.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "651e83b4072fba0ce3f3e0a0",
```

```
    "name": "externallmg_r_1696498585129_1696498472203_image_14.jpg",
    "path": "cases/651d18f92c6c0778ddf454f4/
externallmg_r_1696498585129_1696498472203_image_14.jpg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "651e83b4072fba0ce3f3e092",
    "name": "externallmg_r_1696498559869_1696498472203_image_1.jpg",
    "path": "cases/651d18f92c6c0778ddf454f4/
externallmg_r_1696498559869_1696498472203_image_1.jpg",
    "orientation": "portrait"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "651e83b4072fba0ce3f3e097",
    "name": "Living Room",
    "path": "cases/651d18f92c6c0778ddf454f4/
externallmg_r_1696498563126_1696498472203_image_4.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "651e83b4072fba0ce3f3e096",
    "name": "Living Room",
    "path": "cases/651d18f92c6c0778ddf454f4/
externallmg_r_1696498566617_1696498472203_image_5.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "651e83b4072fba0ce3f3e095",
    "name": "Living Room",
    "path": "cases/651d18f92c6c0778ddf454f4/
externallmg_r_1696498568194_1696498472203_image_6.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "651e83b4072fba0ce3f3e098",
    "name": "Living Room",
```

```
    "path": "cases/651d18f92c6c0778ddf454f4/
externallmg_r_1696498570328_1696498472203_image_7.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "651e83b4072fba0ce3f3e09a",
    "name": "Living Room",
    "path": "cases/651d18f92c6c0778ddf454f4/
externallmg_r_1696498574967_1696498472203_image_9.jpg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "15556",
    "max": "16042"
  },
  "builtUpRateRange": {
    "min": "12963",
    "max": "13369"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
```



```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "575.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
```

```
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentId": [],
"_id": "651d18f92c6c0778ddf454f4",
"ownerName": "Miss. Prajkta Ashok Khairnar ",
"ownerPhoneNo": "8308732417",
"appAddress": "Flat no. 603, 6th Floor, Building no. D, Wing - D, Maitreya Park,
Parshiwadi, Kopari, Thane",
"remark": "",
"documents": [
{
  "documentType": {
    "label": "Agreement For Sale",
    "value": "60ae1254aa6d152c1801b326"
  },
  "inputs": {
    "documentDate": "25/09/2023",
    "from": {
      "value": "The_Transferor",
      "label": "The Transferor"
    },
    "The_Transferor": "Mr. Prasad Nilkanth Sakpal",
    "to": {
      "value": "The_Transferee",
      "label": "The Transferee"
    },
    "The_Transferee": "Miss. Prajkta Ashok Khairnar",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "7061/2023"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "567375",
  "path": "cases/651d18f92c6c0778ddf454f4/
document_1696405664582_Racpc_GHatkopar_Prajakta_Khairnar.pdf",
  "fileName": "document_1696405664582_Racpc_GHatkopar_Prajakta_Khairnar.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  }
}
```

```
},
"inputs": {
  "documentDate": "25/11/2008",
  "nameOfApprovingAuthority": {
    "value": "Thane_Municipal_Corporation",
    "label": "Thane Municipal Corporation"
  },
},
"number": {
  "value": "Document_No",
  "label": "Document No"
},
"Document_No": "V.P. No. 98 / 066 / TMC / TDD / 545"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1696507105767_123158.pdf",
"path": "cases/651d18f92c6c0778ddf454f4/
document_1696507105767_123158.pdf",
"id": "947881",
"uploadedBy": "627221f4afd7d55eddeddcb4",
"createdAt": "Thu Oct 05 2023 17:28:25 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
},
"inputs": {
  "documentDate": "13/06/2012",
  "nameOfApprovingAuthority": {
    "value": "Thane_Municipal_Corporation",
    "label": "Thane Municipal Corporation"
  },
},
"number": {
  "value": "Document_No",
  "label": "Document No"
},
"Document_No": "V.P. No. 98 / 066 / TMC / TDD / 058 "
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1696507180330_123646.pdf",
"path": "cases/651d18f92c6c0778ddf454f4/
document_1696507180330_123646.pdf",
"id": "907333",
"uploadedBy": "627221f4afd7d55eddeddcb4",
```

```
    "createdAt": "Thu Oct 05 2023 17:29:40 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "004167",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "128334",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Oct 04 2023 13:19:13 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Miss. Prajkta Ashok Khairnar ",
    "phone": "8308732417",
    "ownershipShare": "",
    "email": "",
    "id": "139617"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "318007",
    "name": "Living Room",
    "length": "17.17",
    "length1": "17",
    "length2": "2",
    "width": "8.42",
    "width1": "8",
    "width2": "5",
    "totalArea": "144.49",
    "images": [],
    "extraAreas": [],
    "finalArea": "144.49"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
```

```
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Kitchen",
  "length": "6.75",
  "length1": "6",
  "length2": "9",
  "width": "6.50",
  "width1": "6",
  "width2": "6",
  "totalArea": "43.87",
  "images": [],
  "extraAreas": [],
  "finalArea": "43.87"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Passage",
  "length": "7.17",
  "length1": "7",
  "length2": "2",
  "width": "7.42",
  "width1": "7",
  "width2": "5",
  "totalArea": "53.15",
  "images": [],
  "extraAreas": [],
  "finalArea": "53.15"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Passage",
  "length": "3.33",
  "length1": "3",
  "length2": "4",
  "width": "3.50",
  "width1": "3",
  "width2": "6",
```

```
"totalArea": "11.67",
"images": [],
"extraAreas": [],
"finalArea": "11.67"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "WC",
  "length": "3.67",
  "length1": "3",
  "length2": "8",
  "width": "3.08",
  "width1": "3",
  "width2": "1",
  "totalArea": "11.31",
  "images": [],
  "extraAreas": [],
  "finalArea": "11.31"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bathroom",
  "length": "3.67",
  "length1": "3",
  "length2": "8",
  "width": "4.58",
  "width1": "4",
  "width2": "7",
  "totalArea": "16.81",
  "images": [],
  "extraAreas": [],
  "finalArea": "16.81"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
}
```

```
"id": "6",
"name": "Bedroom",
"length": "10.83",
"length1": "10",
"length2": "10",
"width": "8.92",
"width1": "8",
"width2": "11",
"totalArea": "96.60",
"images": [],
"extraAreas": [],
"finalArea": "96.60"
}
],
"otherComposition": [
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Cupboard",
    "value": "Cupboard"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "0",
  "length1": "2",
  "length2": "00",
  "length": "2.00",
  "width1": "2",
  "width2": "5",
  "width": "2.42",
  "totalArea": "4.83",
  "percentageBeforeTotal": "4.83",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "4.83"
}
],
"externalReport": [],
"documentPerArea": [
{
```

```
"typeOfDocument": {
  "label": "Agreement For Sale",
  "value": "60ae1254aa6d152c1801b326"
},
"docMeasurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"selectAreaTypeDocument": "Built_Up",
"squareMeterArea": "53.42",
"totalAreaDocument": "575.00",
"docBUILTUPPercentage": "",
"docFinalBUILTUP": "0.00",
"docFinalBUILTUPSquareMeter": "0.00",
"docSaleablePercentage": "",
"docFinalSaleable": "0.00",
"docFinalSaleableSquareMeter": "0.00",
"id": "798560"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "651e41ddb98e691677d947ff",
  "property": "1 BHK Flat for Sale in Maitreya Park Housing Society, Kopri, Thane",
  "area": "450.00",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "Nobroker.com",
  "expectedPrice": "7000000.00",
  "expectedRate": "15555.56",
  "builtUpExpectedRate": "12962.96",
  "image": "cases/651d18f92c6c0778ddf454f4/indicator_1696480289153_Image.png",
  "squareMeter": "41.81",
  "id": "667882"
},
{
  "printlnReport": true,
  "_id": "651e41ddb98e691677d94800",
  "property": "1BHK Flat for Sale in Maitreya Park Housing Society, Kopri, Thane",
  "area": "575.00",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
}
```



```
"rateType": "price_Indicator",
"areaType": "Built_Up",
"source": "https://www.99acres.com/",
"expectedPrice": "7500000.00",
"expectedRate": "13043.48",
"builtUpExpectedRate": "0.00",
"image": "cases/651d18f92c6c0778ddf454f4/indicator_1696480346896_Image.png",
"squareMeter": "53.42",
"id": "283985"
},
{
  "printlnReport": true,
  "_id": "651e41ddb98e691677d94801",
  "property": "1 BHK Flat In Kamini Chs For Sale In Thane (East)",
  "area": "450.00",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "source": "Nobroker.com",
  "expectedPrice": "6000000.00",
  "expectedRate": "13333.33",
  "builtUpExpectedRate": "0.00",
  "image": "cases/651d18f92c6c0778ddf454f4/indicator_1696480413927_Image.png",
  "squareMeter": "41.81",
  "id": "839347"
},
{
  "printlnReport": true,
  "_id": "651e41ddb98e691677d94802",
  "property": "1 BHK Flat In Jay Natraj Soceity For Sale In Thane East",
  "area": "480.00",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "Nobroker.com",
  "expectedPrice": "7700000.00",
  "expectedRate": "16041.67",
  "builtUpExpectedRate": "13368.06",
  "image": "cases/651d18f92c6c0778ddf454f4/indicator_1696480487650_Image.png",
  "squareMeter": "44.59",
  "id": "834062"
}
],
"externallImages": [
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651e83b4072fba0ce3f3e091",
  "name": "externallmg_r_1696498561354_1696498472203_image_2.jpg",
  "path": "cases/651d18f92c6c0778ddf454f4/
externallmg_r_1696498561354_1696498472203_image_2.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651e83b4072fba0ce3f3e092",
  "name": "externallmg_r_1696498559869_1696498472203_image_1.jpg",
  "path": "cases/651d18f92c6c0778ddf454f4/
externallmg_r_1696498559869_1696498472203_image_1.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651e83b4072fba0ce3f3e093",
  "name": "externallmg_r_1696498562155_1696498472203_image_3.jpg",
  "path": "cases/651d18f92c6c0778ddf454f4/
externallmg_r_1696498562155_1696498472203_image_3.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651e83b4072fba0ce3f3e094",
  "name": "externallmg_r_1696498558301_1696498472203_image_0.jpg",
  "path": "cases/651d18f92c6c0778ddf454f4/
externallmg_r_1696498558301_1696498472203_image_0.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651e83b4072fba0ce3f3e095",
  "name": "externallmg_r_1696498568194_1696498472203_image_6.jpg",
  "path": "cases/651d18f92c6c0778ddf454f4/
externallmg_r_1696498568194_1696498472203_image_6.jpg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651e83b4072fba0ce3f3e096",
    "name": "externallmg_r_1696498566617_1696498472203_image_5.jpg",
    "path": "cases/651d18f92c6c0778ddf454f4/
externallmg_r_1696498566617_1696498472203_image_5.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651e83b4072fba0ce3f3e097",
    "name": "externallmg_r_1696498563126_1696498472203_image_4.jpg",
    "path": "cases/651d18f92c6c0778ddf454f4/
externallmg_r_1696498563126_1696498472203_image_4.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651e83b4072fba0ce3f3e098",
    "name": "externallmg_r_1696498570328_1696498472203_image_7.jpg",
    "path": "cases/651d18f92c6c0778ddf454f4/
externallmg_r_1696498570328_1696498472203_image_7.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651e83b4072fba0ce3f3e099",
    "name": "externallmg_r_1696498577143_1696498472203_image_10.jpg",
    "path": "cases/651d18f92c6c0778ddf454f4/
externallmg_r_1696498577143_1696498472203_image_10.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651e83b4072fba0ce3f3e09a",
    "name": "externallmg_r_1696498574967_1696498472203_image_9.jpg",
    "path": "cases/651d18f92c6c0778ddf454f4/
externallmg_r_1696498574967_1696498472203_image_9.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "651e83b4072fba0ce3f3e09b",
    "name": "externallmg_r_1696498572699_1696498472203_image_8.jpg",
    "path": "cases/651d18f92c6c0778ddf454f4/
externallmg_r_1696498572699_1696498472203_image_8.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651e83b4072fba0ce3f3e09c",
    "name": "externallmg_r_1696498578796_1696498472203_image_11.jpg",
    "path": "cases/651d18f92c6c0778ddf454f4/
externallmg_r_1696498578796_1696498472203_image_11.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651e83b4072fba0ce3f3e09d",
    "name": "externallmg_r_1696498581416_1696498472203_image_12.jpg",
    "path": "cases/651d18f92c6c0778ddf454f4/
externallmg_r_1696498581416_1696498472203_image_12.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651e83b4072fba0ce3f3e09e",
    "name": "externallmg_r_1696498583587_1696498472203_image_13.jpg",
    "path": "cases/651d18f92c6c0778ddf454f4/
externallmg_r_1696498583587_1696498472203_image_13.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651e83b4072fba0ce3f3e09f",
    "name": "externallmg_r_1696498588393_1696498472203_image_15.jpg",
    "path": "cases/651d18f92c6c0778ddf454f4/
externallmg_r_1696498588393_1696498472203_image_15.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "651e83b4072fba0ce3f3e0a0",
    "name": "externalimg_r_1696498585129_1696498472203_image_14.jpg",
    "path": "cases/651d18f92c6c0778ddf454f4/
externalimg_r_1696498585129_1696498472203_image_14.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651e83b4072fba0ce3f3e0a1",
    "name": "externalimg_r_1696498590446_1696498472203_image_16.jpg",
    "path": "cases/651d18f92c6c0778ddf454f4/
externalimg_r_1696498590446_1696498472203_image_16.jpg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "651e83b4072fba0ce3f3e0a2",
    "name": "externalimg_r_1696498539874_1696498453827_image_2.png",
    "path": "cases/651d18f92c6c0778ddf454f4/
externalimg_r_1696498539874_1696498453827_image_2.png",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "651e83b4072fba0ce3f3e0a3",
    "name": "externalimg_r_1696498536879_1696498453827_image_0.jpg",
    "path": "cases/651d18f92c6c0778ddf454f4/
externalimg_r_1696498536879_1696498453827_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "651e83b4072fba0ce3f3e0a4",
    "name": "externalimg_r_1696498538460_1696498453827_image_1.jpg",
    "path": "cases/651d18f92c6c0778ddf454f4/
externalimg_r_1696498538460_1696498453827_image_1.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
```

"createdAt": "2023-10-04T07:49:13.217Z",
"updatedAt": "2023-10-06T07:16:42.269Z",
"__v": 0,
"invoiceId": "651d18f92c6c0778ddf45501",
"fullAddress": "Residential Flat No. 603, 6th Floor, Building No D, Wing - D, Maitrey
Park D Wing Co-op. Hsg. Soc. Ltd., Plot No. Gut No. 70 (P), Parsiwadi Kopri, Village -
Kopri, Thane (East), Taluka - Thane, District - Thane, PIN Code - 400 603, State -
Maharashtra, India",
"updatedBy": "60092304a16fab0f2af9b0c2",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Neelkanth Sakpal",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Seller's Father",
"siteVisitContactNo": "9594963491",
"buildingServicesRate": "2800.00",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 575.00",
"flatRate": "13000.00",
"landOtherRate": "10200",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + 2 Passage + WC +
Bathroom",
"carpetTotal": "377.90",
"otherCarpetTotal": "4.83",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "4.83",
"otherCompositionSaleableTotal": "0.00",
"builtupPercentage": "20",
"finalBuiltupArea": "459.28",
"finalCarpetArea": "382.73",
"finalSalableArea": "505.20",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalSaleablePercentage": "",
"landDetails": {
 "holdType": {

```

"label": "Free Hold",
"value": "Free_Hold"
},
"leaseDetails": {
"lessorName": "",
"lesseeName": "",
"leasePremium": "",
"leaseRent": "",
"leasePeriod": 0,
"leaseFrom": "",
"leaseTo": "",
"remainingLeasePeriod": 0,
"leaseDate": ""
}
},
"shopDetails": {
"typeOfShops": {
"label": "",
"value": ""
}
},
"roadFacing": false,
"mall": false
},
"siteVisitDate": "2023-10-05"
}

```

Name	Length	Width	Total
Composition :			
Living Room	17'2"	8'5"	144.49
Kitchen	6'9"	6'6"	43.87
Passage	7'2"	7'5"	53.15
Passage	3'4"	3'6"	11.67
WC	3'8"	3'1"	11.31
Bathroom	3'8"	4'7"	16.81
Bedroom	10'10"	8'11"	96.60
Other Composition :			
Cupboard	2'00"	2'5"	4.83