

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63ae703e191f7b344b004517"
    },
    "type": "CREDITOFFICER",
    "_id": "641bdb99ee0c792c533bc702",
    "firstName": "R. S. Chouhan",
    "lastName": "Chouhan",
    "mobileNo": "",
    "workMobileNo": "8879531811",
    "email": "agmmumu0595@centralbank.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "1800000",
    "discussWithPerson": "R. S. Chouhan",
    "expectedFees": 900,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17fa",
  "type": "BANK",
  "name": "Central Bank of India",
  "displayName": "Central Bank of India",
  "initial": "CBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63ae703e191f7b344b004517",
  "name": "Andheri (East) Branch",
  "branchCode": "",
  "mobileNo": "022 26837530",
  "alternateMobileNo": "",
  "email": "agmmumn0595@centralbank.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Vastu Darshan B wing, 1st Floor, Azad Road, Next to K/East Ward,
Municipal Office Building, Andheri (East), Mumbai - 400 069"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60f917e0f3dd69653a592221",
  "zoneName": "South Mumbai Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af6ae22ffdf65bcd65861d",
```

```
"role": "PICKUPPERSON",
"firstName": "Sunil",
"email": "misalsunil87@gmail.com",
"lastName": "Misal",
"mobileNo": "8422982721",
"shortName": "SM",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60af6ae22ffdf65bcd65861d\
\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "648fcad91b499c2d52dc86f3",
"role": "SITEENGINEER",
"firstName": "Barkat",
"email": "barkathodekar68@gmail.com",
"lastName": "Hodekar",
"mobileNo": "8879011615",
"designation": "Site Engg",
"shortName": "Barkat",
"workWithDocumentMaker": "",
"profilePhoto": "users/648fcad91b499c2d52dc86f3/
profilePhoto_1687758876977_image.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60eeaeddf3dd69653a581316",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Shyam",
"email": "shyam@vastukala.org",
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shyma_Photo.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "60eeaeddf3dd69653a581316",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Shyam",
"email": "shyam@vastukala.org",
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
```

```
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shymam_Photo.jpg"
},
"checker": "",
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
"value": "FIIV",
"label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
"title": {
"value": "Chartered_Engineer",
"label": "Chartered Engineer"
},
"_id": "60af80072ffdf65bcd658653",
"number": "AM161706-3"
}
```

```
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.115390868049918",
  "longitude": "72.88268696199904"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.88268696199904,
    19.115390868049918
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-13",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-13",
      "remark": ""
    }
  ]
}
```

```
    }
  ],
  "schedule": [],
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Kondivita",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "7",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",

```

```
"label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai Suburban",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Andheri",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "88-91",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Giri Shikhar Centre Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
```

```
"name": "Sector",
"key": "selectArea",
"value": "",
"label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "J. B. Nagar",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
}
```



```
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "329-B",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "721",
  "label": false
},
"municipalityWardNo": {
  "status": true,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "K East",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
```

```
"key": "khataNo",
"value": "",
"label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400059",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Andheri (East)",
  "label": false
}
```

```
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "34.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "buildingServicesDepreciatedRate": "931.5",
  "depreciatedCostOfConstruction": "25568.50",
  "depreciatedBuildingRate": "1768.5"
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "122290",
  "landRate": "70220",
  "igrImage": "cases/651fe767119cca234ddb654/igr_1697713604620_Image.png",
  "squareMeterGuideLineRate": "128405.00",
  "squareFeetGuideLineRate": "11929.00"
},
"igrFinalRate": {
  "rate": "10686.00",
  "squareMeterGuideLineRate": "115022.00",
  "squareFeetGuideLineRate": "10686.00",
  "depreciationPercentage": "77"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
```

```
"value": "Yes",
"label": "Yes"
},
"carParking": "Stilt + Open Car Parking",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2000",
  "fullDate": "1/1/2000"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Normal",
  "label": "Normal"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
}
```

```
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenancelssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "0",
  "label": "No"
},
"provisionOfFirefighting": {
  "value": "0",
  "label": "No"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
```

```
"estimatedAge": "37",
"ageOfBuilding": "23",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "7",
"flatFloorNo": "7",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "2"
},
"finalPlinthArea": {
  "areaType": "Built Up",
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
```

```
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
```



```
"status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "7245108.00",
  "selectedBuildUpValue": "678.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "2857",
    "max": "27163"
  },
  "builtUpRateRange": {
    "min": "2381",
    "max": "22636"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
```

```
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "565.00",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentId": [],
"_id": "651fe767119cca234ddb654",
"ownerName": "Govind.Saraf",
"ownerPhoneNo": "9169449191",
"appAddress": "Flat no 721 ,7 th floor, Bldg- Giri Shaikhar & Centre Co-op HSG Soc
Ltd,J.B.Nagar, Andheri East- 400059",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "05/04/2005",
      "from": {
        "value": "Seller",
        "label": "Seller"
      },
      "Seller": "Mr. Haresh M. Mehta & Mrs. Yashodhara H. Mehta ",
      "to": {
        "value": "purchaser",
        "label": "purchaser"
      },
      "purchaser": "Mr. Govind Saraf & Mrs. Priti Saraf",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "3357/2005"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName":
"document_1697713181910_CBI_Andheri_East_Govind_Saraf__Flat_no721.pdf",
```

```
    "path": "cases/651fe767119cca234ddbd654/
document_1697713181910_CBI_Andheri_East_Govind_Saraf__Flat_no721.pdf"
  }
],
"caseNumber": "004242",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "981985",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Oct 06 2023 16:24:31 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Govind.Saraf",
    "phone": "9169449191",
    "ownershipShare": "",
    "email": "",
    "id": "519707"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "52.49",
    "totalAreaDocument": "565",
    "docBUILTUPPercentage": "20",
    "docFinalBUILTUP": "678.00",
    "docFinalBUILTUPSquareMeter": "62.99",
    "docSaleablePercentage": "",
    "docFinalSaleable": "0.00",
```

```
    "docFinalSaleableSquareMeter": "0.00",
    "id": "603945"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "65310e05619c14402da5c273",
    "property": "Residential Flat",
    "area": "458",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "sale_Instance",
    "areaType": "Carpet",
    "source": "Index_no.2",
    "expectedPrice": "12000000",
    "expectedRate": "26200.87",
    "builtUpExpectedRate": "21834.06",
    "image": "cases/651fe767119cca234ddb654/
indicator_1697713366983_Image.jpeg",
    "squareMeter": "42.55",
    "id": "305655"
  },
  {
    "printlnReport": true,
    "_id": "65310e05619c14402da5c274",
    "property": "Residential Flat",
    "area": "494",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "sale_Instance",
    "areaType": "Carpet",
    "source": "Index_no.2",
    "expectedPrice": "12000000",
    "expectedRate": "24291.50",
    "builtUpExpectedRate": "20242.91",
    "image": "cases/651fe767119cca234ddb654/
indicator_1697713390098_Image.jpeg",
    "squareMeter": "45.89",
    "id": "657111"
  },
  {
    "printlnReport": true,
    "_id": "65310e05619c14402da5c275",
    "property": "Residential Flat",
```

```
"area": "497",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"source": "https://www.99acres.com/",
"expectedPrice": "13500000",
"expectedRate": "27162.98",
"builtUpExpectedRate": "22635.81",
"image": "cases/651fe767119cca234ddb654/
indicator_1697713465411_Image.png",
"squareMeter": "46.17",
"id": "216809"
},
{
  "printInReport": true,
  "_id": "65310e05619c14402da5c276",
  "property": "Residential Flat",
  "area": "455",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "Nobroker.com",
  "expectedPrice": "1300000",
  "expectedRate": "2857.14",
  "builtUpExpectedRate": "2380.95",
  "image": "cases/651fe767119cca234ddb654/
indicator_1697713518068_Image.jpeg",
  "squareMeter": "42.27",
  "id": "838938"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6528a1f3d040066d2c56aff",
    "name": "externalImg_1697161655839_1697161579822_image_0.jpeg",
    "path": "cases/651fe767119cca234ddb654/
externalImg_1697161655839_1697161579822_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "6528a1f3d040066d2c56b000",
    "name": "externallmg_1697161656010_1697161579822_image_1.jpeg",
    "path": "cases/651fe767119cca234ddb654/
externallmg_1697161656010_1697161579822_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6528a1f3d040066d2c56b001",
    "name": "externallmg_1697161656167_1697161579822_image_2.jpeg",
    "path": "cases/651fe767119cca234ddb654/
externallmg_1697161656167_1697161579822_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6528a1f3d040066d2c56b002",
    "name": "externallmg_1697161656672_1697161579822_image_3.jpeg",
    "path": "cases/651fe767119cca234ddb654/
externallmg_1697161656672_1697161579822_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6528a1f3d040066d2c56b003",
    "name": "externallmg_1697161656940_1697161579822_image_4.jpeg",
    "path": "cases/651fe767119cca234ddb654/
externallmg_1697161656940_1697161579822_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6528a1f3d040066d2c56b004",
    "name": "externallmg_1697161656997_1697161579822_image_5.jpeg",
    "path": "cases/651fe767119cca234ddb654/
externallmg_1697161656997_1697161579822_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6528a1f3d040066d2c56b005",
```



```
    "name": "externallmg_1697161657099_1697161579822_image_6.jpeg",
    "path": "cases/651fe767119cca234ddb654/
externallmg_1697161657099_1697161579822_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6528a1f3d040066d2c56b006",
    "name": "externallmg_1697161697283_1697161620135_image_0.jpeg",
    "path": "cases/651fe767119cca234ddb654/
externallmg_1697161697283_1697161620135_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6528a1f3d040066d2c56b007",
    "name": "externallmg_1697161697438_1697161620135_image_1.jpeg",
    "path": "cases/651fe767119cca234ddb654/
externallmg_1697161697438_1697161620135_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6528a1f3d040066d2c56b008",
    "name": "externallmg_1697161697542_1697161620135_image_2.jpeg",
    "path": "cases/651fe767119cca234ddb654/
externallmg_1697161697542_1697161620135_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6528a1f3d040066d2c56b009",
    "name": "externallmg_1697161697687_1697161620135_image_3.jpeg",
    "path": "cases/651fe767119cca234ddb654/
externallmg_1697161697687_1697161620135_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6528a1f3d040066d2c56b00a",
    "name": "externallmg_1697161697908_1697161620135_image_4.jpeg",
```

```
    "path": "cases/651fe767119cca234ddb654/
externallmg_1697161697908_1697161620135_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6528a1f3d040066d2c56b00b",
    "name": "externallmg_1697161698300_1697161620135_image_5.jpeg",
    "path": "cases/651fe767119cca234ddb654/
externallmg_1697161698300_1697161620135_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6528a1f3d040066d2c56b00c",
    "name": "externallmg_1697161698370_1697161620135_image_6.jpeg",
    "path": "cases/651fe767119cca234ddb654/
externallmg_1697161698370_1697161620135_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6528a1f3d040066d2c56b00d",
    "name": "externallmg_1697161698581_1697161620135_image_7.jpeg",
    "path": "cases/651fe767119cca234ddb654/
externallmg_1697161698581_1697161620135_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6528a1f3d040066d2c56b00e",
    "name": "externallmg_1697161698694_1697161620135_image_8.jpeg",
    "path": "cases/651fe767119cca234ddb654/
externallmg_1697161698694_1697161620135_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6528a1f3d040066d2c56b00f",
    "name": "externallmg_1697161698745_1697161620135_image_9.jpeg",
    "path": "cases/651fe767119cca234ddb654/
externallmg_1697161698745_1697161620135_image_9.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6528a1f3d040066d2c56b010",
  "name": "externallmg_1697161698833_1697161620135_image_10.jpeg",
  "path": "cases/651fe767119cca234ddb654/
externallmg_1697161698833_1697161620135_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6528a1f3d040066d2c56b011",
  "name": "externallmg_1697161699006_1697161620135_image_11.jpeg",
  "path": "cases/651fe767119cca234ddb654/
externallmg_1697161699006_1697161620135_image_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6528a1f3d040066d2c56b012",
  "name": "externallmg_1697161699125_1697161620135_image_12.jpeg",
  "path": "cases/651fe767119cca234ddb654/
externallmg_1697161699125_1697161620135_image_12.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6528a1f3d040066d2c56b013",
  "name": "externallmg_1697161699499_1697161620135_image_13.jpeg",
  "path": "cases/651fe767119cca234ddb654/
externallmg_1697161699499_1697161620135_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6528a1f3d040066d2c56b014",
  "name": "externallmg_1697161699729_1697161620135_image_14.jpeg",
  "path": "cases/651fe767119cca234ddb654/
externallmg_1697161699729_1697161620135_image_14.jpeg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6528a1f3d040066d2c56b015",
      "name": "externalImg_1697161699899_1697161620135_image_15.jpeg",
      "path": "cases/651fe767119cca234ddb654/
externalImg_1697161699899_1697161620135_image_15.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6528a1f3d040066d2c56b016",
      "name": "externalImg_1697161700288_1697161620135_image_16.jpeg",
      "path": "cases/651fe767119cca234ddb654/
externalImg_1697161700288_1697161620135_image_16.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "6528a1f3d040066d2c56b017",
      "name": "externalImg_1697161609616_1697161533555_image_0.jpeg",
      "path": "cases/651fe767119cca234ddb654/
externalImg_1697161609616_1697161533555_image_0.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "6528a1f3d040066d2c56b018",
      "name": "externalImg_1697161609931_1697161533555_image_1.jpeg",
      "path": "cases/651fe767119cca234ddb654/
externalImg_1697161609931_1697161533555_image_1.jpeg",
      "orientation": "portrait"
    }
  ],
  "externalDocuments": [],
  "processingDocuments": [
    {
      "originalname": "CBI Andheri East- Govind Saraf Flat no.721.pdf",
      "filename": "1697713648091_CBI_Andheri_East_Govind_Saraf__Flat_no721.pdf",
      "path": "cases/651fe767119cca234ddb654/processingDocuments/1697713648091
_CBI_Andheri_East_Govind_Saraf__Flat_no721.pdf",
      "size": "16932977",
```

```
"createdAt": "Thu Oct 19 2023 16:37:28 GMT+0530 (India Standard Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "externallmg_1697161609616_1697161533555_image_0.jpeg",
  "filename":
"1697713648338_externallmg_1697161609616_1697161533555_image_0.jpeg",
  "path": "cases/651fe767119cca234ddb654/processingDocuments/1697713648338
_externallmg_1697161609616_1697161533555_image_0.jpeg",
  "size": "1209154",
  "createdAt": "Thu Oct 19 2023 16:37:28 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "externallmg_1697161609931_1697161533555_image_1.jpeg",
  "filename":
"1697713648362_externallmg_1697161609931_1697161533555_image_1.jpeg",
  "path": "cases/651fe767119cca234ddb654/processingDocuments/1697713648362
_externallmg_1697161609931_1697161533555_image_1.jpeg",
  "size": "778593",
  "createdAt": "Thu Oct 19 2023 16:37:28 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-01.pdf",
  "filename": "1697713648380_IGR01.pdf",
  "path": "cases/651fe767119cca234ddb654/
processingDocuments/1697713648380_IGR01.pdf",
  "size": "146265",
  "createdAt": "Thu Oct 19 2023 16:37:28 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-02.pdf",
  "filename": "1697713648384_IGR02.pdf",
  "path": "cases/651fe767119cca234ddb654/
processingDocuments/1697713648384_IGR02.pdf",
  "size": "143421",
  "createdAt": "Thu Oct 19 2023 16:37:28 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-03.pdf",
  "filename": "1697713648387_IGR03.pdf",
  "path": "cases/651fe767119cca234ddb654/
processingDocuments/1697713648387_IGR03.pdf",
```

```
"size": "145575",
"createdAt": "Thu Oct 19 2023 16:37:28 GMT+0530 (India Standard Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
"originalname": "Summary New=GOVIND.xlsx",
"filename": "1697713648393_Summary_NewGOVIND.xlsx",
"path": "cases/651fe767119cca234ddb654/
processingDocuments/1697713648393_Summary_NewGOVIND.xlsx",
"size": "3379267",
"createdAt": "Thu Oct 19 2023 16:37:28 GMT+0530 (India Standard Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
"originalname": "Untitled.jpg",
"filename": "1697713648478_Untitled.jpg",
"path": "cases/651fe767119cca234ddb654/
processingDocuments/1697713648478_Untitled.jpg",
"size": "383750",
"createdAt": "Thu Oct 19 2023 16:37:28 GMT+0530 (India Standard Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
}
],
"remarks": [
{
"createdBy": {
"_id": "60eeaeddf3dd69653a581316",
"role": "MAKER + RATE VERIFIER + CHEAKER",
"firstName": "Shyam",
"lastName": "Kajvilkar",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shyam_Photo.jpg"
},
"workType": "RATE_VERIFY",
"display": true,
"status": true,
"_id": "6529043cd040066d2c579bdd",
"note": "Pending for value confirmation",
"taskId": "6525488a703d7c40db994484",
"createdAt": "2023-10-13T08:47:56.135Z"
}
],
"createdAt": "2023-10-06T10:54:31.844Z",
"updatedAt": "2023-10-20T06:45:23.447Z",
"__v": 0,
"updatedBy": "60eeaeddf3dd69653a581316",
```

"fullAddress": "Residential Flat No. 721, 7th Floor, Giri Shikhar Centre Co-op. Hsg. Soc. Ltd., Plot No. 88-91, J. B. Nagar, Village - Kondivita, Municipality Ward No. K East, Andheri (East), Taluka - Andheri, Mumbai Suburban, 400059, State - Maharashtra, India",

"addressForMap": "",  
"caseReferredBy": "60af6ae22ffdf65bcd65861d",  
"contactPersonName": "Govind.Saraf",  
"email": "",  
"isExternal": "false",  
"isUrgent": "false",  
"ownershipShare": "",  
"purchaseValueAsPerDocument": "",  
"relationWithOwner": "self",  
"siteVisitContactNo": "9169449191",  
"buildingServicesRate": "2700",  
"finalAreaType": "Carpet Area",  
"finalAsPerArea": "Agreement for sale",  
"finalBuiltUpPercentage": "20",  
"finalCarpetConvertToBuiltUpPer": "20",  
"finalMeasurementType": "Sq. Ft.",  
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 565.00",  
"flatRate": "26500",  
"landOtherRate": "23800"

}

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			