

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9f4"
    },
    "type": "CREDITOFFICER",
    "_id": "650581d3a8e9b70221e855e5",
    "firstName": "Bhakti",
    "lastName": "Podkar",
    "mobileNo": "",
    "workMobileNo": "8425827511",
    "email": "Bhakti.racpc.sion@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "6000000",
    "discussWithPerson": "Bhakti",
    "expectedFees": 3000,
    "quotedAmount": "2500"
  },
  "organization": {
```

```
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9f4",
  "branchCode": "000215",
  "type": "BRANCH",
  "name": "RACPC Sion ",
  "email": "racpc.sion@sbi.co.in",
  "mobileNo": "02225046265",
  "alternateMobileNo": "",
  "address": "B-603 & 604, Kohinoor City, Commercial-1, 6th Floor, Kiroi Road, Off
L.B.S. Marg, Kurla (West), Mumbai, Pin Code - 400 070, State - Maharashtra, Country -
India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "648fcad91b499c2d52dc86f3",
  "role": "SITEENGINEER",
  "firstName": "Barkat",
  "email": "barkathodekar68@gmail.com",
  "lastName": "Hodekar",
  "mobileNo": "8879011615",
  "designation": "Site Engg",
  "shortName": "Barkat",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/648fcad91b499c2d52dc86f3/
profilePhoto_1687758876977_image.jpeg"
},
"rateVerifier": "",
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
  "email": "pradnya@vastukala.org",
  "lastName": "Rasam",
  "mobileNo": "9529385821",
  "designation": "",
  "shortName": "PR",
  "workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
  "profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": "",
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
```

```
    "value": "IBBI/RV/07/2018/10366",
    "label": "Registered Valuer"
  }
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
```

```
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
    "PANNo": "AERPC9086P",
    "fatherName": "Baburao"
  }
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.060279689218422",
  "longitude": "72.89879431663888"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.89879431663888,
    19.060279689218422
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-06",
      "remark": ""
    }
  ]
},
"schedule": [],
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "3BHK",
  "label": "3 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
```

```
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "Country - India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Chembur",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "8",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
    "value": "Mumbai Suburban",
    "label": true
  },
  "city": {
    "status": true,
    "name": "City",
```

```
"key": "city",
"value": "Chembur",
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "kurla",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "434",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Sabari Shikhar Co-Op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "R.C. Marg",
  "label": false
},
}
```

```
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
```



```
"value": "",
"label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "1281 & 1281/1",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "802",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
```

```
"status": false,
"name": "SRO",
"key": "SRO",
"value": "",
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 071",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "MarbleFlooring",
    "label": "Marble Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
```

```

    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering_+_POP_Finish",
    "label": "Cement Plastering + POP Finish"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MCGM",
    "label": "Municipal Corporation of Greater Mumbai (MCGM)"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Ornate Apartment",
    "west": "Ramkrishna Chemburkar Marg",
    "south": "BMC School",
    "east": "Open Plot"
  },
  "asPerDocumentAgreement": {
    "north": "Details is not available",
    "west": "Details is not available",

```

```
"south": "Details is not available",
"east": "Details is not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Details is not available",
    "east": "Details is not available",
    "south": "Details is not available",
    "west": "Details is not available"
  },
  "asPerDocument": {
    "north": "Details is not available",
    "east": "Details is not available",
    "south": "Details is not available",
    "west": "Details is not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "",
"approvePlanVerified": "",
"empanelledOfApprovePlan": ""
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "28.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "buildingServicesDepreciatedRate": "855",
  "depreciatedCostOfConstruction": "26145.00",
  "depreciatedBuildingRate": "2145"
},
"igrRate": {
  "propertyName": "Chembur",
  "rate": "157260",
  "landRate": "69600",
  "igrImage": "cases/651fe7f8119cca234ddb8b9/igr_1696677731591_Image.png",
  "squareMeterGuideLineRate": "165123.00",
  "squareFeetGuideLineRate": "15340.00"
},
"igrFinalRate": {
  "rate": "13654.00",
  "squareMeterGuideLineRate": "146974.00",
  "squareFeetGuideLineRate": "13654.00",
  "depreciationPercentage": "81"
```

```
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "50,000",
  "assessmentNo": "Details is not available",
  "taxPaidHolderName": "Details is not available",
  "taxAmount": "Details is not available",
  "electricityServiceConnectionNo": "CA No. 150524413",
  "meterCardHolderName": "Mr. P. Bheemeshwar Reddy ",
  "undividedAreaOfLandAsPerSaleDeed": "Details is not available",
  "floorSpaceIndex": "As per MCGM norms",
  "tenantName": "",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
}
```

```
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": "Stilt Car Parking Space",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2004",
  "fullDate": "1/1/2004"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"structuralSafety": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
}
```

```
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "0",
  "label": "No"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
```

```
"ageOfBuilding": "19",
"totalLifeBuilding": "60",
"estimatedAge": "41",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "10",
"flatFloorNo": "",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "2"
},
"finalPlinthArea": {
  "area": "915.00",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/651fe7f8119cca234ddbd8b9/
routeMap_1696824168193_Image.png",
    "routeLat": "19.055876",
    "routeLng": "72.895255",
    "stationName": "Chembur",
    "routeDistance": "1.5 Km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "1e29jh",
      "name": "1e29jh",
      "image": "cases/651fe7f8119cca234ddbd8b9/
routeMap_1696824073706_Image.png"
```



```
}
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "23922675.00",
  "finalValue": "23922675.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValueDocument": null,
  "purchaseValueDocument": null,
  "bookValue": "0"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
}
```

```
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
    "label": "External Plastering",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "12493410.00",
  "selectedBuildUpValue": "915.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "6520415a119cca234ddc6b1d",
      "name": "externalImg_1696612681040_1696612596930_image_0.jpeg",
      "path": "cases/651fe7f8119cca234ddb8b9/
externalImg_1696612681040_1696612596930_image_0.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],

```

```
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "6520415a119cca234ddc6b14",
    "name": "Living Room",
    "path": "cases/651fe7f8119cca234ddb8b9/
externallmg_1696612632143_1696612549480_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6520415a119cca234ddc6b17",
    "name": "Living Room",
    "path": "cases/651fe7f8119cca234ddb8b9/
externallmg_1696612633019_1696612549480_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6520415a119cca234ddc6b15",
    "name": "Living Room",
    "path": "cases/651fe7f8119cca234ddb8b9/
externallmg_1696612632403_1696612549480_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6520415a119cca234ddc6b16",
    "name": "Living Room",
    "path": "cases/651fe7f8119cca234ddb8b9/
externallmg_1696612632660_1696612549480_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6520415a119cca234ddc6b22",
    "name": "Living Room",
    "path": "cases/651fe7f8119cca234ddb8b9/
externallmg_1696612682845_1696612596930_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
```

```
    "_id": "6520415a119cca234ddc6b20",
    "name": "Living Room",
    "path": "cases/651fe7f8119cca234ddb8b9/
externallmg_1696612682054_1696612596930_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6520415a119cca234ddc6b1e",
    "name": "Living Room",
    "path": "cases/651fe7f8119cca234ddb8b9/
externallmg_1696612681943_1696612596930_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6520415a119cca234ddc6b1d",
    "name": "Living Room",
    "path": "cases/651fe7f8119cca234ddb8b9/
externallmg_1696612681040_1696612596930_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6520415a119cca234ddc6b25",
    "name": "Living Room",
    "path": "cases/651fe7f8119cca234ddb8b9/
externallmg_1696612684232_1696612596930_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6520415a119cca234ddc6b27",
    "name": "Living Room",
    "path": "cases/651fe7f8119cca234ddb8b9/
externallmg_1696612685267_1696612596930_image_10.jpeg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": null,
    "max": null
  },
  "builtUpRateRange": {
```

```
"min": "22728",
"max": "28572"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
```

```
"title": "Interior Decorations",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
```



```
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "915.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentId": [],
"_id": "651fe7f8119cca234ddb8b9",
"ownerName": "Mr. P. Bheemeshwar Reddy & Mrs. Rekha B. Reddy",
"ownerPhoneNo": "9821056179",
"appAddress": "Flat no. 802, 8th Floor, Sabari Shikhar CHS, R.C. Marg, Chembur ",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "inputs": {
      "documentDate": "10/03/2005",
      "from": {
        "value": "Vendor",

```

```
    "label": "Vendor"
  },
  "Vendor": "Mr. Sameer Janardan Apte & Mrs. Meera Sameer Apte",
  "to": {
    "value": "Purchasers",
    "label": "Purchasers"
  },
  "Purchasers": "Mr. P. Bheemeshwar Reddy & Mrs. Rekha B. Reddy",
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "1870 / 2 / 2005"
},
"isHardCopy": false,
"displayStatus": true,
"id": "633436",
"path": "cases/651fe7f8119cca234ddb8b9/
document_1696589722129_Racpc_SionBheemeshwar_Reddy.pdf",
"fileName": "document_1696589722129_Racpc_SionBheemeshwar_Reddy.pdf"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "05/03/2004",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_Of_Greater_Mumbai",
      "label": "Municipal Corporation Of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "CE / 5384 / BPES / AM"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1696680334639_867837.pdf",
"path": "cases/651fe7f8119cca234ddb8b9/
document_1696680334639_867837.pdf",
"id": "831686",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Sat Oct 07 2023 17:35:34 GMT+0530 (India Standard Time)"
```

```
    },
    {
      "documentType": {
        "value": "60ae1264aa6d152c1801b371",
        "label": "Share Certificate "
      },
      "inputs": {
        "documentDate": "14/02/2005",
        "remark": " in the name of Mr. Sameer Janardan Apte & Mrs. Meera Sameer Apte  
issued by Sabari Shikhar Co-Op. Hsg. Soc. Ltd",
        "number": {
          "value": "No",
          "label": "No"
        },
        "No": "016"
      },
      "isHardCopy": false,
      "displayStatus": false,
      "id": "530869",
      "path": "cases/651fe7f8119cca234ddbd8b9/  
document_1696680440371_899645.pdf",
      "fileName": "document_1696680440371_899645.pdf"
    },
    {
      "documentType": {
        "value": "6077c791395bc80714864a30",
        "label": "Electricity Bill"
      },
      "inputs": {
        "documentDate": "31/08/2023",
        "nameOfApprovingAuthority": {
          "value": "MSEDCL",
          "label": "MSEDCL"
        },
        "to": {
          "value": "Purchaser",
          "label": "Purchaser"
        },
        "Purchaser": "Mr. P. Bheemeshwar Reddy",
        "number": {
          "value": "No",
          "label": "No"
        },
        "No": "150524413"
      },
      "isHardCopy": false,
```

```
"displayStatus": false,
"fileName": "document_1696680559649_480685.pdf",
"path": "cases/651fe7f8119cca234ddb8b9/
document_1696680559649_480685.pdf",
"id": "137020",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Sat Oct 07 2023 17:39:19 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae125eaa6d152c1801b353",
    "label": "Maintenance Bill"
  },
  "inputs": {
    "documentDate": "15/07/2023",
    "remark": "in the name of Mr. P. Bheemeshwar Reddy & Mrs. Rekha B. Reddy
issued by Sabari Shikhar Co-Op. Hsg. Soc. Ltd.",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "36"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1696680629679_570298.pdf",
  "path": "cases/651fe7f8119cca234ddb8b9/
document_1696680629679_570298.pdf",
  "id": "219878",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Sat Oct 07 2023 17:40:30 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "004244",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "438294",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Oct 06 2023 16:26:56 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. P. Bheemeshwar Reddy & Mrs. Rekha B. Reddy",
```

```
"phone": "9821056179",
"ownershipShare": "",
"email": "",
"id": "576461"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "746362",
"name": "Living Room",
"length": "14.00",
"length1": "14",
"length2": "00",
"width": "10.58",
"width1": "10",
"width2": "7",
"totalArea": "148.17",
"images": [],
"extraAreas": [],
"finalArea": "148.17"
},
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "1",
"name": "Dining",
"length": "9.42",
"length1": "9",
"length2": "5",
"width": "10.92",
"width1": "10",
"width2": "11",
"totalArea": "102.80",
"images": [],
"extraAreas": [],
"finalArea": "102.80"
},
{
```

```
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "2",
"name": "Toilet",
"length": "7.42",
"length1": "7",
"length2": "5",
"width": "3.83",
"width1": "3",
"width2": "10",
"totalArea": "28.43",
"images": [],
"extraAreas": [],
"finalArea": "28.43"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "11",
  "name": "Bedroom",
  "length": "11.67",
  "length1": "11",
  "length2": "8",
  "width": "10.92",
  "width1": "10",
  "width2": "11",
  "totalArea": "127.36",
  "images": [],
  "finalArea": "127.36",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Kitchen",
  "length": "11.00",
  "length1": "11",
  "length2": "00",
  "width": "7.42",
```

```
"width1": "7",
"width2": "5",
"totalArea": "81.58",
"images": [],
"extraAreas": [],
"finalArea": "81.58"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Passage",
  "length": "5.00",
  "length1": "5",
  "length2": "00",
  "width": "3.58",
  "width1": "3",
  "width2": "7",
  "totalArea": "17.92",
  "images": [],
  "extraAreas": [],
  "finalArea": "17.92"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Bedroom",
  "length": "10.25",
  "length1": "10",
  "length2": "3",
  "width": "14.17",
  "width1": "14",
  "width2": "2",
  "totalArea": "145.21",
  "images": [],
  "extraAreas": [],
  "finalArea": "145.21"
},
{
  "measurementType": {
    "value": "Square_Feet",
```

```
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Toilet",
  "length": "4.00",
  "length1": "4",
  "length2": "00",
  "width": "9.17",
  "width1": "9",
  "width2": "2",
  "totalArea": "36.67",
  "images": [],
  "extraAreas": [],
  "finalArea": "36.67"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Passage",
  "length": "3.08",
  "length1": "3",
  "length2": "1",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "12.33",
  "images": [],
  "extraAreas": [],
  "finalArea": "12.33"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "9",
  "name": "Toilet",
  "length": "4.00",
  "length1": "4",
  "length2": "00",
  "width": "8.00",
  "width1": "8",
  "width2": "00",
```



```
"totalArea": "32.00",
"images": [],
"extraAreas": [],
"finalArea": "32.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "10",
  "name": "Bedroom",
  "length": "11.50",
  "length1": "11",
  "length2": "6",
  "width": "10.17",
  "width1": "10",
  "width2": "2",
  "totalArea": "116.92",
  "images": [],
  "extraAreas": [],
  "finalArea": "116.92"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Built_Up",
    "squareMeterArea": "85.01",
    "totalAreaDocument": "915",
    "docBultupPercentage": "",
    "docFinalBuiltUp": "0.00",
    "docFinalBuiltUpSquareMeter": "0.00",
    "docSaleablePercentage": "",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "794630"
  }
]
```

```
}
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "65213f79119cca234ddd78e9",
    "property": "Sunder Apartment, Chembur",
    "area": "1150",
    "builtUpPercentage": "0",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Built_Up",
    "floor": "Middle",
    "source": "Nobroker.com",
    "expectedPrice": "30000000",
    "expectedRate": "26086.96",
    "builtUpExpectedRate": "0.00",
    "image": "cases/651fe7f8119cca234ddb8b9/
indicator_1696677362984_Image.png",
    "squareMeter": "106.84",
    "id": "496350"
  },
  {
    "printlnReport": true,
    "_id": "65213f79119cca234ddd78ea",
    "property": "RC Marg, Chembur",
    "area": "550",
    "builtUpPercentage": "0",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Built_Up",
    "floor": "Middle",
    "source": "Nobroker.com",
    "expectedPrice": "12500000",
    "expectedRate": "22727.27",
    "builtUpExpectedRate": "0.00",
    "image": "cases/651fe7f8119cca234ddb8b9/
indicator_1696677439834_Image.png",
    "squareMeter": "51.10",
    "id": "801495"
  },
  {
    "printlnReport": true,
    "_id": "65213f79119cca234ddd78eb",
    "property": "Jai Ambe Nagar, chembur",
```

```
"area": "1050",
"builtUpPercentage": "0",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"floor": "Middle",
"source": "Nobroker.com",
"expectedPrice": "30000000",
"expectedRate": "28571.43",
"builtUpExpectedRate": "0.00",
"image": "cases/651fe7f8119cca234ddbd8b9/
indicator_1696677591642_Image.png",
"squareMeter": "97.55",
"id": "517945"
}
],
"externalImages": [
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "6520415a119cca234ddc6b13",
"name": "externalImg_1696612631866_1696612549479_image_0.jpeg",
"path": "cases/651fe7f8119cca234ddbd8b9/
externalImg_1696612631866_1696612549479_image_0.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "6520415a119cca234ddc6b14",
"name": "externalImg_1696612632143_1696612549480_image_1.jpeg",
"path": "cases/651fe7f8119cca234ddbd8b9/
externalImg_1696612632143_1696612549480_image_1.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "6520415a119cca234ddc6b15",
"name": "externalImg_1696612632403_1696612549480_image_2.jpeg",
"path": "cases/651fe7f8119cca234ddbd8b9/
externalImg_1696612632403_1696612549480_image_2.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "6520415a119cca234ddc6b16",
    "name": "externallmg_1696612632660_1696612549480_image_3.jpeg",
    "path": "cases/651fe7f8119cca234ddbd8b9/
externallmg_1696612632660_1696612549480_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6520415a119cca234ddc6b17",
    "name": "externallmg_1696612633019_1696612549480_image_4.jpeg",
    "path": "cases/651fe7f8119cca234ddbd8b9/
externallmg_1696612633019_1696612549480_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6520415a119cca234ddc6b18",
    "name": "externallmg_1696612633249_1696612549480_image_5.jpeg",
    "path": "cases/651fe7f8119cca234ddbd8b9/
externallmg_1696612633249_1696612549480_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6520415a119cca234ddc6b19",
    "name": "externallmg_1696612633515_1696612549480_image_6.jpeg",
    "path": "cases/651fe7f8119cca234ddbd8b9/
externallmg_1696612633515_1696612549480_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6520415a119cca234ddc6b1a",
    "name": "externallmg_1696612633745_1696612549480_image_7.jpeg",
    "path": "cases/651fe7f8119cca234ddbd8b9/
externallmg_1696612633745_1696612549480_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "6520415a119cca234ddc6b1b",
    "name": "externallmg_1696612634060_1696612549480_image_8.jpeg",
    "path": "cases/651fe7f8119cca234ddbd8b9/
externallmg_1696612634060_1696612549480_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6520415a119cca234ddc6b1c",
    "name": "externallmg_1696612634259_1696612549480_image_9.jpeg",
    "path": "cases/651fe7f8119cca234ddbd8b9/
externallmg_1696612634259_1696612549480_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6520415a119cca234ddc6b1d",
    "name": "externallmg_1696612681040_1696612596930_image_0.jpeg",
    "path": "cases/651fe7f8119cca234ddbd8b9/
externallmg_1696612681040_1696612596930_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6520415a119cca234ddc6b1e",
    "name": "externallmg_1696612681943_1696612596930_image_1.jpeg",
    "path": "cases/651fe7f8119cca234ddbd8b9/
externallmg_1696612681943_1696612596930_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6520415a119cca234ddc6b1f",
    "name": "externallmg_1696612681963_1696612596930_image_2.jpeg",
    "path": "cases/651fe7f8119cca234ddbd8b9/
externallmg_1696612681963_1696612596930_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6520415a119cca234ddc6b20",
```

```
    "name": "externallmg_1696612682054_1696612596930_image_3.jpeg",
    "path": "cases/651fe7f8119cca234ddbd8b9/
externallmg_1696612682054_1696612596930_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6520415a119cca234ddc6b21",
    "name": "externallmg_1696612682466_1696612596930_image_4.jpeg",
    "path": "cases/651fe7f8119cca234ddbd8b9/
externallmg_1696612682466_1696612596930_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6520415a119cca234ddc6b22",
    "name": "externallmg_1696612682845_1696612596930_image_5.jpeg",
    "path": "cases/651fe7f8119cca234ddbd8b9/
externallmg_1696612682845_1696612596930_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6520415a119cca234ddc6b23",
    "name": "externallmg_1696612683159_1696612596930_image_6.jpeg",
    "path": "cases/651fe7f8119cca234ddbd8b9/
externallmg_1696612683159_1696612596930_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6520415a119cca234ddc6b24",
    "name": "externallmg_1696612683868_1696612596930_image_7.jpeg",
    "path": "cases/651fe7f8119cca234ddbd8b9/
externallmg_1696612683868_1696612596930_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6520415a119cca234ddc6b25",
    "name": "externallmg_1696612684232_1696612596930_image_8.jpeg",
```

```
    "path": "cases/651fe7f8119cca234ddbd8b9/
externallmg_1696612684232_1696612596930_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6520415a119cca234ddc6b26",
    "name": "externallmg_1696612684948_1696612596930_image_9.jpeg",
    "path": "cases/651fe7f8119cca234ddbd8b9/
externallmg_1696612684948_1696612596930_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6520415a119cca234ddc6b27",
    "name": "externallmg_1696612685267_1696612596930_image_10.jpeg",
    "path": "cases/651fe7f8119cca234ddbd8b9/
externallmg_1696612685267_1696612596930_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6520415a119cca234ddc6b28",
    "name": "externallmg_1696612686345_1696612596930_image_11.jpeg",
    "path": "cases/651fe7f8119cca234ddbd8b9/
externallmg_1696612686345_1696612596930_image_11.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6520415a119cca234ddc6b29",
    "name": "externallmg_1696612686867_1696612596930_image_12.jpeg",
    "path": "cases/651fe7f8119cca234ddbd8b9/
externallmg_1696612686867_1696612596930_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6520415a119cca234ddc6b2a",
    "name": "externallmg_1696612564757_1696612482910_image_0.jpeg",
    "path": "cases/651fe7f8119cca234ddbd8b9/
externallmg_1696612564757_1696612482910_image_0.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6520415a119cca234ddc6b2b",
  "name": "externalImg_1696612565082_1696612482910_image_1.jpeg",
  "path": "cases/651fe7f8119cca234ddb8b9/
externalImg_1696612565082_1696612482910_image_1.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalName": "1696395983884_Calculation.xlsx",
    "filename": "1696677801461_1696395983884_Calculation.xlsx",
    "path": "cases/651fe7f8119cca234ddb8b9/
processingDocuments/1696677801461_1696395983884_Calculation.xlsx",
    "size": "3207739",
    "createdAt": "Sat Oct 07 2023 16:53:21 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  }
],
"remarks": [],
"createdAt": "2023-10-06T10:56:56.444Z",
"updatedAt": "2023-10-09T04:08:49.810Z",
"__v": 0,
"invoiceId": "651fe7f8119cca234ddb8cd",
"fullAddress": "Residential Flat No. 802, 8th Floor, Sabari Shikhar Co-Op. Hsg. Soc.
Ltd., Plot No. 434, R.C. Marg, Village - Chembur, Taluka - kurla, District - Mumbai
Suburban, Chembur, PIN - 400 071, State - Maharashtra, Country - India",
"updatedBy": "62fe044a48a26047e6552796",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Mrs. Rekha Reddy",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9821056179",
"buildingServicesRate": "3000.00",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement For Sale",
```



```
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 915.00",
"flatRate": "27000",
"landOtherRate": "24000",
"briefDescOfProperty": "3 Bedroom + Living Room + Kitchen + Dining + 3 Toilet + 2
Passage",
"carpetTotal": "849.39",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "934.33",
"finalCarpetArea": "849.39",
"finalSalableArea": "1027.76",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalSaleablePercentage": "",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00",
"shopDetails": {
  "typeOfShops": {
    "label": "",
    "value": ""
  },
  "roadFacing": false,
  "mall": false
```

}
}

Name	Length	Width	Total
Composition :			
Living Room	14'00"	10'7"	148.17
Dining	9'5"	10'11"	102.80
Toilet	7'5"	3'10"	28.43
Bedroom	11'8"	10'11"	127.36
Kitchen	11'00"	7'5"	81.58
Passage	5'00"	3'7"	17.92
Bedroom	10'3"	14'2"	145.21
Toilet	4'00"	9'2"	36.67
Passage	3'1"	4'00"	12.33
Toilet	4'00"	8'00"	32.00
Bedroom	11'6"	10'2"	116.92
Other Composition :			