

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856bb63"
    },
    "type": "CREDITOFFICER",
    "_id": "64bb68afa87c525d5c04ab9d",
    "firstName": "Sayali",
    "lastName": "Bangar",
    "mobileNo": "",
    "workMobileNo": "8097275708",
    "email": "cord.racpckalyan@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "6418456a96b58848585f8cb2",
"name": "Thane",
"email": "thane@vastukala.com",
"phone": "1234567890",
"address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
"city": "Thane",
"shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856bb63",
  "branchCode": "000355",
  "type": "BRANCH",
  "name": "RACPC Kalyan",
  "email": "cord.racpckalyan@sbi.co.in",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "address": "Ground Floor, 1 st Floor, Millenium Heights, Opp. Patedar Bhawan
Marriage Hall, Shahad Mohone Road, Shahad, Kalyan (West) - 421 103 \n\n",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "6410199a140f140ffc59b58c",
  "role": "PICKUPPERSON",
  "firstName": "Prakash ",
  "email": "prakashnvetkoli@gmail.com",
  "lastName": "Vetkoli",
  "mobileNo": "9076237689",
  "shortName": "PV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/6410199a140f140ffc59b58c/
profilePhoto_1689054480133_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "64e5a649daae6a1c98101989",
  "role": "SITEENGINEER",
  "firstName": "Sameer",
  "email": "sameeryp2010@gmail.com",
  "lastName": "Parab",
  "mobileNo": "8291009567",
  "designation": "Site Engineer",
  "shortName": "Sameer",
  "workWithDocumentMaker": "62ea09ea4e679b264caf07d7"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordinatiion",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "MAKER",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
  "mobileNo": "9821518537",
```

```
"designation": "",
"shortName": "PS",
"workWithDocumentMaker": "",
"profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": "",
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
"value": "FIIV",
"label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
"title": {
"value": "Chartered_Engineer",
"label": "Chartered Engineer"
},
"_id": "60af80072ffdf65bcd658653",
"number": "AM161706-3"
}
```

```
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.29194541573889",
  "longitude": "73.20248650195283"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-07",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-07",
```

```
    "remark": ""
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Manda",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "4",
    "label": false
  },
  "buildingNo": {
```

```
"status": false,
"name": "Building No",
"key": "buildingNo",
"value": "",
"label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Titwala (East)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kalyan",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Ravindra Residency Co-Op. Hsg. Soc. Ltd.",
```

```
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Balyani Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "C",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
```



```
"name": "Old Survey No.",
"key": "oldSurveyNumber",
"value": "",
"label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "128/7 & 130/6/8/1",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "404",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
}
```

```
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 421 605",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
```

```

    "key": "suburb",
    "value": "",
    "label": false
  }
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door_with_M.S_Safety_door",
    "label": "Teak Wood Door frame with Solid flush door with M.S Safety door"
  },
  "windows": {
    "value": "Alluminum_sliding_windows_with_M._S._Grills",
    "label": "Alluminum sliding windows with M. S. Grills"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering_+_POP_Finish",
    "label": "Cement Plastering + POP Finish"
  }
},
"general": {
  "ownership": {
    "value": "sole_ownership",
    "label": "sole ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {

```

```
"value": "Kalyan_Dombivali_Municipal_Corporation",
"label": "Kalyan Dombivali Municipal Corporation"
},
"whetherCoveredUnderAnyState": {
"value": "No",
"label": "No"
},
"asPerActualAgreement": {
"north": "B - Wing",
"west": "Railway Tracks",
"south": "Ring Rut Road",
"east": "Titwala - Ambivli Road"
},
"asPerDocumentAgreement": {
"north": "Details not available",
"west": "Details not available",
"south": "Details not available",
"east": "Details not available"
},
"unitBoundaries": {
"asPerActual": {
"north": "Details not available",
"east": "Details not available",
"south": "Details not available",
"west": "Details not available"
},
"asPerDocument": {
"north": "Details not available",
"east": "Details not available",
"south": "Details not available",
"west": "Details not available"
},
"isOpen": false,
"title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "",
"approvePlanVerified": "",
"empanelledOfApprovePlan": ""
},
"compositeRate": {
"remark": "",
"depreciationPercentage": "24",
"depreciationRatioOfBuilding": "",
"salvageValue": "10",
"depreciatedCostOfConstruction": "6000",
```

```
"depreciatedBuildingRate": "1900"
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "47900",
  "landRate": "11400",
  "igrImage": "cases/6520000d119cca234ddc4af9/igr_1696680655680_Image.png",
  "squareMeterGuideLineRate": "38320.00",
  "squareFeetGuideLineRate": "3560.00"
},
"igrFinalRate": {
  "depreciationPercentage": "84",
  "rate": "3160.00",
  "squareFeetGuideLineRate": "3160.00",
  "squareMeterGuideLineRate": "34013.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Middle_Class",
    "label": "Middle Class"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Seller_Occupied",
    "label": "Seller Occupied"
  },
  "monthlyRent": "5,500.00",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Electricity Bill Consumer No. 020110145722",
  "meterCardHolderName": "Roshan Ramdas Gunjal",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per KDMC norms",
  "tenantName": "",
  "maintenanceOfFlat": "Details not available"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
```

```
"negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Covered Parking",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2007",
    "fullDate": "1/1/2007"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  },
  "typeOfStructure": {
    "value": "R.C.C.",
    "label": "R.C.C. Framed"
  },
  "typeOfFoundation": {
    "value": "rcc",
    "label": "R.C.C. Foundation"
  },
}
```

```
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenancelssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
```

```
"label": "Information not available"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
  "value": "Part_Ground_and_Part_Stilt",
  "label": "Part Ground + Part Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "44",
"ageOfBuilding": "16",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "4",
"flatFloorNo": "",
"noOfLifts": "",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "514.80",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  },
  "routeMapImg": "cases/6520000d119cca234ddc4af9/
routeMap_1696829600405_Image.png",
  "routeLat": "19.291869",
  "routeLng": "73.202423",
  "stationName": "Titwala ",
  "routeDistance": "500 M"
},
"finalLatLng": {
  "coordinates": [
```



```
    null,
    null
  ],
  "type": "Point"
},
"showLocation": {
  "latlng": true,
  "finallatlng": true
},
"locationMapImg": [
  {
    "id": "k93l8",
    "name": "k93l8",
    "image": "cases/6520000d119cca234ddc4af9/
routeMap_1696829454780_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
```

```
"finaltotal": "2574000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "2574000.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
```

```
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "1626768.00",
"selectedBuildUpValue": "514.80",
"selectedBuildUpMeasurementType": "Sq. Ft."
}
```

```
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "6520ebfb119cca234ddcb542",
      "name": "externallmg_1696656334771_1696656251648_image_2.jpeg",
      "path": "cases/6520000d119cca234ddc4af9/
externallmg_1696656334771_1696656251648_image_2.jpeg",
      "orientation": "landscape"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "6520ebfb119cca234ddcb547",
      "name": "externallmg_1696656335665_1696656251648_image_7.jpeg",
      "path": "cases/6520000d119cca234ddc4af9/
externallmg_1696656335665_1696656251648_image_7.jpeg",
      "orientation": "landscape"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "6520ebfb119cca234ddcb54d",
      "name": "externallmg_1696656336555_1696656251648_image_13.jpeg",
      "path": "cases/6520000d119cca234ddc4af9/
externallmg_1696656336555_1696656251648_image_13.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "6520ebfb119cca234ddcb543",
      "name": "externallmg_1696656334890_1696656251648_image_3.jpeg",
      "path": "cases/6520000d119cca234ddc4af9/
externallmg_1696656334890_1696656251648_image_3.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "6520ebfb119cca234ddcb545",
      "name": "externallmg_1696656335320_1696656251648_image_5.jpeg",
      "path": "cases/6520000d119cca234ddc4af9/
externallmg_1696656335320_1696656251648_image_5.jpeg",
      "orientation": "portrait"
    }
  ]
}
```

```
    },
    {
      "status": false,
      "_id": "6520ebfb119cca234ddcb544",
      "name": "externallmg_1696656335223_1696656251648_image_4.jpeg",
      "path": "cases/6520000d119cca234ddc4af9/
externallmg_1696656335223_1696656251648_image_4.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "6520ebfb119cca234ddcb542",
      "name": "externallmg_1696656334771_1696656251648_image_2.jpeg",
      "path": "cases/6520000d119cca234ddc4af9/
externallmg_1696656334771_1696656251648_image_2.jpeg",
      "orientation": "landscape"
    }
  ],
  "parkingImages": [],
  "societyNameBoardImage": [
    {
      "status": false,
      "_id": "6520ebfb119cca234ddcb54f",
      "name": "externallmg_1696656337040_1696656251648_image_15.jpeg",
      "path": "cases/6520000d119cca234ddc4af9/
externallmg_1696656337040_1696656251648_image_15.jpeg",
      "orientation": "landscape"
    }
  ],
  "compositionImages": [
    {
      "status": false,
      "_id": "6520ebfb119cca234ddcb548",
      "name": "Living Room",
      "path": "cases/6520000d119cca234ddc4af9/
externallmg_1696656335810_1696656251648_image_8.jpeg",
      "orientation": "landscape"
    },
    {
      "status": false,
      "_id": "6520ebfb119cca234ddcb549",
      "name": "Living Room",
      "path": "cases/6520000d119cca234ddc4af9/
externallmg_1696656335924_1696656251648_image_9.jpeg",
      "orientation": "landscape"
    }
  ],
```

```
{
  "status": false,
  "_id": "6520ebfb119cca234ddcb54a",
  "name": "Bedroom",
  "path": "cases/6520000d119cca234ddc4af9/
externallmg_1696656336206_1696656251648_image_10.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "6520ebfb119cca234ddcb54c",
  "name": "Kitchen",
  "path": "cases/6520000d119cca234ddc4af9/
externallmg_1696656336485_1696656251648_image_12.jpeg",
  "orientation": "portrait"
}
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "6383",
    "max": "7174"
  },
  "builtUpRateRange": {
    "min": "5320",
    "max": "5979"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
```

```
"title": "Showcases",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```



```
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "true",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
```

```
"isSiteMeasurementAllowed": true,
"finalValuationArea": "429.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentId": [],
"_id": "6520000d119cca234ddc4af9",
"ownerName": "Mr. Ishan Sanjay Dhone",
"ownerPhoneNo": "7506932086",
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "8850212288",
"contactPersonName": "Mr. Rahul Gunjal",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "Mr. Ishan Sanjay Dhone",
    "phone": "7506932086",
    "ownershipShare": "",
    "email": "",
    "id": "865992"
  }
],
"caseReferredBy": "6410199a140f140ffc59b58c",
"relationWithOwner": "Seller's Brother",
"fullAddress": "Residential Flat No. 404, 4th Floor, Wing - C, Ravindra Residency Co-
Op. Hsg. Soc. Ltd., Balyani Road, Village - Manda, Taluka - Kalyan, District - Thane,
Titwala (East), PIN Code - 421 605, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "24/08/2023",
      "from": {
        "value": "Vendor",
        "label": "Vendor"
      },
      "Vendor": "Mr. Roshan Ramdas Gunjal",
      "to": {
```

```
    "value": "Purchaser",
    "label": "Purchaser"
  },
  "Purchaser": "Mr. Ishan Sanjay Dhone",
  "number": {
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "9750/2023"
},
"isHardCopy": false,
"displayStatus": false,
"id": "162308",
"path": "cases/6520000d119cca234ddc4af9/
document_1696595935327_AGREEMENT_0001_4.pdf",
"fileName": "document_1696595935327_AGREEMENT_0001_4.pdf"
},
{
  "documentType": {
    "value": "60ae1260aa6d152c1801b35c",
    "label": "Builder Possession Letter"
  },
  "inputs": {
    "documentDate": "29/12/2007",
    "remark": "issued by Shree Siddhi Vinayak Builders & Developers"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1696827577867_108786.pdf",
  "path": "cases/6520000d119cca234ddc4af9/
document_1696827577867_108786.pdf",
  "id": "633379",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Mon Oct 09 2023 10:29:37 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "30/10/2007",
    "nameOfApprovingAuthority": {
      "value": "Kalyan_Dombivli_Municipal_Corporation",
      "label": "Kalyan Dombivli Municipal Corporation"
    }
  },
}
```

```
"number": {
  "value": "No",
  "label": "No"
},
"No": "KDMC / NRV / CC / KV / 455"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1696827801537_143845.pdf",
"path": "cases/6520000d119cca234ddc4af9/
document_1696827801537_143845.pdf",
"id": "324207",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Mon Oct 09 2023 10:33:21 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "01/03/2006",
    "nameOfApprovingAuthority": {
      "value": "Kalyan_Dombivli_Municipal_Corporation",
      "label": "Kalyan Dombivli Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "KDMC / NRV / BP / KV / 680 -246"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1696828216307_196113.pdf",
"path": "cases/6520000d119cca234ddc4af9/
document_1696828216307_196113.pdf",
"id": "756438",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Mon Oct 09 2023 10:40:16 GMT+0530 (India Standard Time)"
}
],
"isUrgent": "false",
"isExternal": "false",
"scheduleSiteVisitDate": "Invalid date",
"caseNumber": "004254",
```

```
"createdBy": "6430f74691d7c62df11f3f15",
"caseHistory": [
  {
    "id": "921913",
    "title": "Create Case",
    "description": "Create Case",
    "datetime": "Fri Oct 06 2023 18:09:41 GMT+0530 (India Standard Time)"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "6",
    "name": "Living Room",
    "length": "14.00",
    "length1": "14",
    "length2": "0",
    "width": "10.00",
    "width1": "10",
    "width2": "0",
    "totalArea": "140.00",
    "images": [],
    "finalArea": "140.00",
    "extraAreas": []
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "2",
    "name": "Kitchen",
    "length": "15.00",
    "length1": "15",
    "length2": "0",
    "width": "5.00",
    "width1": "5",
    "width2": "0",
    "totalArea": "75.00",
    "images": [],
    "finalArea": "75.00",
```

```
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Bedroom",
  "length": "13.00",
  "length1": "13",
  "length2": "00",
  "width": "9.00",
  "width1": "9",
  "width2": "00",
  "totalArea": "117.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "117.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Passage",
  "length": "4.00",
  "length1": "4",
  "length2": "00",
  "width": "10.00",
  "width1": "10",
  "width2": "00",
  "totalArea": "40.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "40.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "WC",
  "length": "4.00",
```

```
"length1": "4",
"length2": "00",
"width": "3.00",
"width1": "3",
"width2": "00",
"totalArea": "12.00",
"images": [],
"extraAreas": [],
"finalArea": "12.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bathroom",
  "length": "6.00",
  "length1": "6",
  "length2": "00",
  "width": "5.00",
  "width1": "5",
  "width2": "00",
  "totalArea": "30.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "30.00"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "39.86",
    "totalAreaDocument": "429",
    "docBuiltupPercentage": "20",
    "docFinalBuiltUp": "514.80",
```

```
"docFinalBuiltUpSquareMeter": "47.83",
"docSaleablePercentage": "",
"docFinalSaleable": "0.00",
"docFinalSaleableSquareMeter": "0.00",
"id": "499367"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "65214ae7119cca234dddb062",
  "property": "Residential Flat",
  "area": "470",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "Nobroker.com",
  "expectedPrice": "3000000",
  "expectedRate": "6382.98",
  "builtUpExpectedRate": "5319.15",
  "image": "cases/6520000d119cca234ddc4af9/
indicator_1696680419206_Image.png",
  "squareMeter": "43.66",
  "id": "251948"
},
{
  "printlnReport": true,
  "_id": "65214ae7119cca234dddb063",
  "property": "Residential Flat",
  "area": "460",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "source": "Index_no.2",
  "expectedPrice": "3300000",
  "expectedRate": "7173.91",
  "builtUpExpectedRate": "5978.26",
  "image": "cases/6520000d119cca234ddc4af9/
indicator_1696680459803_Image.png",
  "squareMeter": "42.74",
  "id": "424480"
}
],
```



```
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6520ebfb119cca234ddcb540",
    "name": "externalimg_1696656334226_1696656251648_image_0.jpeg",
    "path": "cases/6520000d119cca234ddc4af9/
externalimg_1696656334226_1696656251648_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6520ebfb119cca234ddcb541",
    "name": "externalimg_1696656334539_1696656251648_image_1.jpeg",
    "path": "cases/6520000d119cca234ddc4af9/
externalimg_1696656334539_1696656251648_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6520ebfb119cca234ddcb542",
    "name": "externalimg_1696656334771_1696656251648_image_2.jpeg",
    "path": "cases/6520000d119cca234ddc4af9/
externalimg_1696656334771_1696656251648_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6520ebfb119cca234ddcb543",
    "name": "externalimg_1696656334890_1696656251648_image_3.jpeg",
    "path": "cases/6520000d119cca234ddc4af9/
externalimg_1696656334890_1696656251648_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6520ebfb119cca234ddcb544",
    "name": "externalimg_1696656335223_1696656251648_image_4.jpeg",
    "path": "cases/6520000d119cca234ddc4af9/
externalimg_1696656335223_1696656251648_image_4.jpeg",
    "orientation": "portrait"
  },
  },
]
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6520ebfb119cca234ddcb545",
  "name": "externallmg_1696656335320_1696656251648_image_5.jpeg",
  "path": "cases/6520000d119cca234ddc4af9/
externallmg_1696656335320_1696656251648_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6520ebfb119cca234ddcb546",
  "name": "externallmg_1696656335515_1696656251648_image_6.jpeg",
  "path": "cases/6520000d119cca234ddc4af9/
externallmg_1696656335515_1696656251648_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6520ebfb119cca234ddcb547",
  "name": "externallmg_1696656335665_1696656251648_image_7.jpeg",
  "path": "cases/6520000d119cca234ddc4af9/
externallmg_1696656335665_1696656251648_image_7.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6520ebfb119cca234ddcb548",
  "name": "externallmg_1696656335810_1696656251648_image_8.jpeg",
  "path": "cases/6520000d119cca234ddc4af9/
externallmg_1696656335810_1696656251648_image_8.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6520ebfb119cca234ddcb549",
  "name": "externallmg_1696656335924_1696656251648_image_9.jpeg",
  "path": "cases/6520000d119cca234ddc4af9/
externallmg_1696656335924_1696656251648_image_9.jpeg",
  "orientation": "landscape"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6520ebfb119cca234ddcb54a",
    "name": "externallmg_1696656336206_1696656251648_image_10.jpeg",
    "path": "cases/6520000d119cca234ddc4af9/
externallmg_1696656336206_1696656251648_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6520ebfb119cca234ddcb54b",
    "name": "externallmg_1696656336294_1696656251648_image_11.jpeg",
    "path": "cases/6520000d119cca234ddc4af9/
externallmg_1696656336294_1696656251648_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6520ebfb119cca234ddcb54c",
    "name": "externallmg_1696656336485_1696656251648_image_12.jpeg",
    "path": "cases/6520000d119cca234ddc4af9/
externallmg_1696656336485_1696656251648_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6520ebfb119cca234ddcb54d",
    "name": "externallmg_1696656336555_1696656251648_image_13.jpeg",
    "path": "cases/6520000d119cca234ddc4af9/
externallmg_1696656336555_1696656251648_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6520ebfb119cca234ddcb54e",
    "name": "externallmg_1696656336709_1696656251648_image_14.jpeg",
    "path": "cases/6520000d119cca234ddc4af9/
externallmg_1696656336709_1696656251648_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "6520ebfb119cca234ddcb54f",
    "name": "externalImg_1696656337040_1696656251648_image_15.jpeg",
    "path": "cases/6520000d119cca234ddc4af9/
externalImg_1696656337040_1696656251648_image_15.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6520ebfb119cca234ddcb550",
    "name": "externalImg_1696656284734_1696656202208_image_1.jpeg",
    "path": "cases/6520000d119cca234ddc4af9/
externalImg_1696656284734_1696656202208_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6520ebfb119cca234ddcb551",
    "name": "externalImg_1696656349154_1696656263317_image_0.jpeg",
    "path": "cases/6520000d119cca234ddc4af9/
externalImg_1696656349154_1696656263317_image_0.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Calculation Sheet.xlsx",
    "filename": "1696828109359_Calculation_Sheet.xlsx",
    "path": "cases/6520000d119cca234ddc4af9/
processingDocuments/1696828109359_Calculation_Sheet.xlsx",
    "size": "16196",
    "createdAt": "Mon Oct 09 2023 10:38:29 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  },
  {
    "originalname": "Summary Sheet.xlsx",
    "filename": "1696828116066_Summary_Sheet.xlsx",
    "path": "cases/6520000d119cca234ddc4af9/
processingDocuments/1696828116066_Summary_Sheet.xlsx",
    "size": "1420630",
    "createdAt": "Mon Oct 09 2023 10:38:36 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  }
]
```

```
],
"remarks": [
  {
    "createdBy": {
      "_id": "64cde526dc9f3034f3fefa49",
      "role": "FRONTDESK",
      "firstName": "Rashmi",
      "lastName": "Jadhav",
      "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "652138f5119cca234ddd6caf",
    "note": "Value share with bank person",
    "taskId": "6520000e119cca234ddc4b5c",
    "createdAt": "2023-10-07T10:54:45.551Z"
  }
],
"createdAt": "2023-10-06T12:39:41.805Z",
"updatedAt": "2023-10-09T05:48:09.941Z",
"__v": 0,
"invoiceId": "6520000d119cca234ddc4b00",
"updatedBy": "627222afafd7d55eddedd82",
"buildingServicesRate": "2500",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 429.00",
"flatRate": "6600",
"landOtherRate": "4100",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Passage + WC +
Bathroom",
"carpetTotal": "414",
"otherCarpetTotal": "0.00",
"finalSaleablePercentage": "",
"builtupPercentage": "10",
"extendOfSiteRemark": "All the above areas are within +/- 10% of the Agreement for
Sale Area. The above calculations and detail measurements taken by us prove that the
Agreement for Sale are is not exorbitantly inflated. Hence, valuation is based on the
Agreement for Sale area.",
"finalBuiltupArea": "455.40",
"finalCarpetArea": "414.00",
```

```

"finalSalableArea": "500.94",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"addressForMap": "",
"siteVisitDate": "2023-10-07",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00",
"shopDetails": {
  "typeOfShops": {
    "label": "",
    "value": ""
  }
},
"roadFacing": false,
"mall": false
}
}

```

Name	Length	Width	Total
Composition :			
Living Room	14'0"	10'0"	140.00
Kitchen	15'0"	5'0"	75.00
Bedroom	13'00"	9'00"	117.00
Passage	4'00"	10'00"	40.00

WC	4'00"	3'00"	12.00
Bathroom	6'00"	5'00"	30.00
Other Composition :			