

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Education Loan",
    "value": "Education_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b8a4"
    },
    "type": "CREDITOFFICER",
    "_id": "64cb46df0faf29427aca399a",
    "firstName": "Rajesh ",
    "lastName": "Kumar",
    "mobileNo": "",
    "workMobileNo": "9975642826",
    "email": "cord2.racpcandheri@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "561000.00",
    "discussWithPerson": "Rajesh ",
    "expectedFees": 280.5,
    "quotedAmount": ""
  },
  "organization": {
```

```
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b8a4",
  "branchCode": "000111",
  "type": "BRANCH",
  "name": "RACPC Andheri (East)",
  "email": "cord2.racpcandheri@sbi.co.in",
  "mobileNo": "02228389765/69",
  "alternateMobileNo": "",
  "address": "1st Floor, UTI Building, Plot No. 12, MIDC, Road No. 9, Behind Tunga
Paradise Hotel, Andheri (East), Mumbai - 400 093, State - Maharashtra, Country -
India.",
  "ledgerName": "STATE BANK OF INDIA - RACPC ANDHERI",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60af6ae22ffdf65bcd65861d",
  "role": "PICKUPPERSON",
  "firstName": "Sunil",
  "email": "misalsunil87@gmail.com",
  "lastName": "Misal",
  "mobileNo": "8422982721",
  "shortName": "SM",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60af6ae22ffdf65bcd65861d\
\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "63fc575ece84bf289ba9e82d",
  "role": "SITEENGINEER",
  "firstName": "Deepak ",
  "email": "daksh7831@gmail.com",
  "lastName": "Jain ",
  "mobileNo": "9022815908",
  "designation": "",
  "shortName": "DJ",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
  "designation": "",
  "shortName": "NK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
  "email": "pradnya@vastukala.org",
  "lastName": "Rasam",
  "mobileNo": "9529385821",
```

```

    "designation": "",
    "shortName": "PR",
    "workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
    "profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
  },
  "checker": {
    "type": "EMPLOYEE",
    "_id": "60092304a16fab0f2af9b0c2",
    "role": "MAKER + RATE VERFIER + CHEAKER",
    "firstName": "Nitesh",
    "email": "nitesh.khedekar@vastukala.org",
    "lastName": "Khedekar",
    "mobileNo": "8369040652",
    "designation": "",
    "shortName": "NK",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
  },
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "IBBI/RV/07/2018/10366",
          "label": "Registered Valuer"
        }
      ],
      "type": "EMPLOYEE",
      "_id": "5ffe92d27737ca4d986b6453",
      "role": "VALUER",
      "firstName": "Manoj",
      "email": "manoj@vastukala.org",
      "lastName": "Chalikwar",
      "mobileNo": "9819597579",
      "designation": "Registered Valuer",
      "registrationNo": [
        {
          "title": {
            "label": "IBBI"
          },
          "_id": "60af80072ffdf65bcd658651",
          "number": "IBBI/RV/07/2018/10366"
        }
      ],
      {
        "title": {

```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.16144897368583",
  "longitude": "72.84068253659927"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.84068253659927,
    19.16144897368583
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-10-07T07:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-10-07T07:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-10-07T07:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-10-07T07:30:00.000Z",
      "remark": ""
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-07",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "3BHK",
  "label": "3 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
```

```
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "Country - India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Pahadi Goregaon",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "7",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
```

```
"status": false,
"name": "Tahasil",
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Borivali",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Kritarth Jeevan Co-Op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Lokmanya Tilak Nagar Road No. 1",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "M. G. Road",
```



```
"label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
```

```
"name": "CTS No.",
"key": "CTSNo",
"value": "126 & 127",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "703",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
}
```

```
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 062",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Goregaon (West), Mumbai",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Wooden_frame_openable_widow_with_M._S._Grill",
    "label": "Wooden frame openable widow with M. S. Grill"
  }
}
```

```

    },
    "fittings": {
      "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
      "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
    },
    "finishing": {
      "value": "Cement_Plastering_+_POP_Finish",
      "label": "Cement Plastering + POP Finish"
    }
  },
  "general": {
    "ownership": {
      "value": "Joint_Ownership",
      "label": "Joint Ownership"
    },
    "populationClassList": {
      "value": "MiddleClass",
      "label": "Middle Class"
    },
    "populationGroupList": {
      "value": "Urban",
      "label": "Urban"
    },
    "townplanApprovedByList": {
      "value": "MCGM",
      "label": "Municipal Corporation of Greater Mumbai (MCGM)"
    },
    "whetherCoveredUnderAnyState": {
      "value": "No",
      "label": "No"
    },
    "asPerActualAgreement": {
      "north": "Mahatma Gandhi Road",
      "west": "MICL Goregaon Apartment",
      "south": "Shree Vinayak Building",
      "east": "Internal Road"
    },
    "asPerDocumentAgreement": {
      "north": "Mahatma Gandhi Road",
      "west": "L. T. Nagar, Plot Nos. 22,23",
      "south": "L. T. Nagar Plot No. 11",
      "east": "L. T. Nagar, Road No. 1"
    },
    "unitBoundaries": {
      "asPerActual": {

```

```
    "north": "Details is not available",
    "east": "Details is not available",
    "south": "Details is not available",
    "west": "Details is not available"
  },
  "asPerDocument": {
    "north": "Details is not available",
    "east": "Details is not available",
    "south": "Details is not available",
    "west": "Details is not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of Approved Building Plan No. CHE / 8943 /
BP(WS) / AP Dated 27.11.2008 issued by Municipal Corporation Of Greater Mumbai.",
"approvePlanVerified": "Yes",
"empanelledOfApprovePlan": "No"
},
"compositeRate": {
  "remark": "As per the Agreement provided to us, the Carpet Area of the flat is 738.00
Sq. Ft., but as per site inspection the Carpet area is 752.00 Sq. Ft., Dry Balcony Area is
21.00 & Top Terrace area is 357.00 Sq. Ft. covered with brick walls. But as there is no
documentary evidence for the ownership of this Top Terrace area, hence we are
consider area as per Agreement for the purpose of valuation.",
  "depreciationPercentage": "13.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "25122",
  "depreciatedBuildingRate": "2422"
},
"igrRate": {
  "propertyName": "Residential ",
  "rate": "160470.00",
  "landRate": "76820",
  "igrImage": "cases/6520f965119cca234ddcd0d8/igr_1697114423375_Image.png",
  "squareMeterGuideLineRate": "168494.00",
  "squareFeetGuideLineRate": "15654.00"
},
"igrFinalRate": {
  "depreciationPercentage": "91",
  "rate": "14887.00",
  "squareFeetGuideLineRate": "14887.00",
  "squareMeterGuideLineRate": "160242.00"
},
```

```
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "38,500",
  "assessmentNo": "Details is not available",
  "taxPaidHolderName": "Details is not available",
  "taxAmount": "Details is not available",
  "electricityServiceConnectionNo": "C.A No. 152303914",
  "meterCardHolderName": "Shri. Anand Sharad Sarawate & Smt. Varsha Anand Sarawate",
  "undividedAreaOfLandAsPerSaleDeed": "Details is not available",
  "floorSpaceIndex": "As per MCGM norms",
  "tenantName": "",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\\_Thk._Brick_Masonry",
    "label": "6\\ Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
}
```

```
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": "Covered Car Parking",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2014",
  "fullDate": "1/1/2014"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Normal",
  "label": "Normal"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Normal",
  "label": "Normal"
}
```

```
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
```



```
"totalLifeBuilding": "60",
"estimatedAge": "51",
"ageOfBuilding": "9",
"noOfBasement": "1",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "7",
"flatFloorNo": "7",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "1"
},
"finalPlinthArea": {
  "areaType": "Built Up",
  "area": "885.60",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/6520f965119cca234ddcd0d8/
routeMap_1697178697068_Image.png",
    "routeLat": "19.163083",
    "routeLng": "72.841194",
    "stationName": "Goregaon",
    "routeDistance": "1.3 Km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "kv1ii",
      "name": "kv1ii",
      "image": "cases/6520f965119cca234ddcd0d8/
routeMap_1697178587530_Image.png"
```

```
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "18540036.00",
  "finalValue": "18540036.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValueDocument": null,
  "purchaseValueDocument": null,
  "bookValue": "0"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
}
```

```
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
    "label": "External Plastering",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "13183927.00",
  "selectedBuildUpValue": "885.60",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "65238d9b119cca234dde49c8",
      "name": "externalImg_1696828826999_IMG_20231007_163635.jpg",
      "path": "cases/6520f965119cca234ddcd0d8/
externalImg_1696828826999_IMG_20231007_163635.jpg",
      "orientation": "portrait"
    }
  ]
},
"selfieWithSiteVisitImages": [],
```

```
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "65238d9b119cca234dde49d4",
    "name": "Living Room",
    "path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828827690_IMG_20231007_162211.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65238d9b119cca234dde49d5",
    "name": "Living Room",
    "path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828827694_IMG_20231007_162219.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65238d9b119cca234dde49d1",
    "name": "Living Room",
    "path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828827677_IMG_20231007_162201.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65238d9b119cca234dde49d0",
    "name": "Living Room",
    "path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828827673_IMG_20231007_162200.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65238d9b119cca234dde49cd",
    "name": "Living Room",
    "path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828827606_IMG_20231007_162146.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
```

```
    "_id": "65238d9b119cca234dde49d7",
    "name": "Living Room",
    "path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828827708_IMG_20231007_162232.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65238db1119cca234dde4a37",
    "name": "Living Room",
    "path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828849272_IMG_20231007_162451.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65238d9b119cca234dde49d8",
    "name": "Living Room",
    "path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828827713_IMG_20231007_162234.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65238d9b119cca234dde49d6",
    "name": "Living Room",
    "path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828827703_IMG_20231007_162224.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65238db1119cca234dde4a3d",
    "name": "Living Room",
    "path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828849293_IMG_20231007_163221.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65238db1119cca234dde4a3e",
    "name": "Living Room",
    "path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828849302_IMG_20231007_163345.jpg",
    "orientation": "portrait"
  },
}
```

```
{
  "status": false,
  "_id": "65238db1119cca234dde4a3c",
  "name": "Living Room",
  "path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828849288_IMG_20231007_163207.jpg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "65238dc6119cca234dde4a9b",
  "name": "Living Room",
  "path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828870267_IMG_20231007_163631.jpg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "65238d9b119cca234dde49c8",
  "name": "Living Room",
  "path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828826999_IMG_20231007_163635.jpg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "65238d9b119cca234dde49c9",
  "name": "Living Room",
  "path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828827160_IMG_20231007_163636.jpg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "65238db1119cca234dde4a40",
  "name": "Living Room",
  "path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828849315_IMG_20231007_163414.jpg",
  "orientation": "portrait"
}
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "24784",
    "max": "27419"
```



```
},
"builtUpRateRange": {
  "min": "20654",
  "max": "22850"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
}
```

```
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
```

```
"status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "738.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentId": [],
"_id": "6520f965119cca234ddcd0d8",
"ownerName": "Shri. Anand Sharad Sarawate & Smt. Varsha Anand Sarawate",
"ownerPhoneNo": "9820782021",
"appAddress": "Flat no. B-703, 7 th floor,Kritarth Jeevan Co-op HSG Soc
Ltd,M.G.Road, L.T.Roadno.1, Goregoan West- 400062",
"remark": "Mitali madam & Case Reference\nContact person Janhvi - 8850613843",
"documents": [
  {
    "documentType": {
      "value": "60ae124faa6d152c1801b30f",
      "label": "Article of Agreement"
    }
  },
  "inputs": {
```

```
"documentDate": "14/12/2010",
"from": {
  "value": "Promoter",
  "label": "Promoter"
},
"Promoter": "M/s. Ameya Properties",
"to": {
  "value": "Purchasers",
  "label": "Purchasers"
},
"Purchasers": "Shri. Anand Sharad Sarawate & Smt. Varsha Anand Sarawate"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1697174251617_document_1696659715314_AnandSarawate_SBI_Racpc_Andheri_East_1.pdf",
"path": "cases/6520f965119cca234ddcd0d8/document_1697174251617_document_1696659715314_AnandSarawate_SBI_Racpc_Andheri_East_1.pdf",
"id": "206289",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Fri Oct 13 2023 10:47:32 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "22/10/2014",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_Of_Greater_Mumbai",
      "label": "Municipal Corporation Of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "CHE / 8943 / BP(WS) / AP"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1697174308948_257777.pdf",
  "path": "cases/6520f965119cca234ddcd0d8/document_1697174308948_257777.pdf",
  "id": "441970",
  "uploadedBy": "62fe044a48a26047e6552796",
```

```
"createdAt": "Fri Oct 13 2023 10:48:29 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "08/09/2011",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_Of_Greater_Mumbai",
      "label": "Municipal Corporation Of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "CHE / 8943 / BP(WS) / AP"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "778952",
  "path": "cases/6520f965119cca234ddcd0d8/
document_1697174370858_352187.pdf",
  "fileName": "document_1697174370858_352187.pdf"
},
{
  "documentType": {
    "value": "60ae1249aa6d152c1801b2f3",
    "label": "Electricity Bill"
  },
  "inputs": {
    "documentDate": "11/09/2023",
    "to": {
      "value": "Purchasers",
      "label": "Purchasers"
    },
    "Purchasers": "Shri. Anand Sharad Sarawate & Smt. Varsha Anand Sarawate",
    "number": {
      "value": "CA_No",
      "label": "CA No"
    },
    "CA_No": "152303914"
  },
  "isHardCopy": false,
  "displayStatus": false,

```

```
"fileName": "document_1697174438140_298067.pdf",
"path": "cases/6520f965119cca234ddcd0d8/
document_1697174438140_298067.pdf",
"id": "926990",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Fri Oct 13 2023 10:50:38 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1249aa6d152c1801b2f1",
    "label": "Society Maintenance Bill"
  },
  "inputs": {
    "documentDate": "01/09/2023",
    "remark": " in the name of Shri. Anand Sharad Sarawate & Smt. Varsha Anand Sarawate issued by Kritarth Jeevan Co-OP. Hsg. Soc. Ltd \n",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "263"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "778916",
  "path": "cases/6520f965119cca234ddcd0d8/
document_1697174491770_193354.pdf",
  "fileName": "document_1697174491770_193354.pdf"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "27/11/2008",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_Of_Greater_Mumbai",
      "label": "Municipal Corporation Of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "CHE / 8943 / BP(WS) / AP"
  },
}
```

```
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1697179188876_139085.pdf",
"path": "cases/6520f965119cca234ddcd0d8/
document_1697179188876_139085.pdf",
"id": "763064",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Fri Oct 13 2023 12:09:48 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "004264",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
{
  "id": "183293",
  "title": "Create Lead",
  "description": "Create Lead",
  "datetime": "Sat Oct 07 2023 11:53:33 GMT+0530 (India Standard Time)"
}
],
"owners": [
{
  "name": "Shri. Anand Sharad Sarawate & Smt. Varsha Anand Sarawate",
  "phone": "9820782021",
  "ownershipShare": "",
  "email": "",
  "id": "976821"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "280907",
  "name": "Living Room",
  "length": "17.08",
  "length1": "17",
  "length2": "1",
  "width": "9.17",
  "width1": "9",
  "width2": "2",
  "totalArea": "156.60",
```

```
"images": [],
"extraAreas": [],
"finalArea": "156.60"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Passage",
  "length": "14.25",
  "length1": "14",
  "length2": "3",
  "width": "3.92",
  "width1": "3",
  "width2": "11",
  "totalArea": "55.81",
  "images": [],
  "extraAreas": [],
  "finalArea": "55.81"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Bedroom",
  "length": "12.42",
  "length1": "12",
  "length2": "5",
  "width": "11.50",
  "width1": "11",
  "width2": "6",
  "totalArea": "142.79",
  "images": [],
  "extraAreas": [],
  "finalArea": "142.79"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
```



```
"name": "Passage",
"length": "3.75",
"length1": "3",
"length2": "9",
"width": "2.83",
"width1": "2",
"width2": "10",
"totalArea": "10.62",
"images": [],
"extraAreas": [],
"finalArea": "10.62"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Bedroom",
  "length": "7.50",
  "length1": "7",
  "length2": "6",
  "width": "13.92",
  "width1": "13",
  "width2": "11",
  "totalArea": "104.37",
  "images": [],
  "extraAreas": [],
  "finalArea": "104.37"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Toilet",
  "length": "4.42",
  "length1": "4",
  "length2": "5",
  "width": "6.17",
  "width1": "6",
  "width2": "2",
  "totalArea": "27.24",
  "images": [],
  "extraAreas": [],
```

```
"finalArea": "27.24"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Toilet",
  "length": "4.00",
  "length1": "4",
  "length2": "00",
  "width": "8.17",
  "width1": "8",
  "width2": "2",
  "totalArea": "32.67",
  "images": [],
  "extraAreas": [],
  "finalArea": "32.67"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Passage",
  "length": "4.50",
  "length1": "4",
  "length2": "6",
  "width": "6.92",
  "width1": "6",
  "width2": "11",
  "totalArea": "31.12",
  "images": [],
  "extraAreas": [],
  "finalArea": "31.12"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Kitchen",
  "length": "10.33",
```

```
"length1": "10",
"length2": "4",
"width": "7.83",
"width1": "7",
"width2": "10",
"totalArea": "80.94",
"images": [],
"extraAreas": [],
"finalArea": "80.94"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "9",
  "name": "Bedroom",
  "length": "9.25",
  "length1": "9",
  "length2": "3",
  "width": "11.92",
  "width1": "11",
  "width2": "11",
  "totalArea": "110.23",
  "images": [],
  "extraAreas": [],
  "finalArea": "110.23"
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "label": "Dry Balcony Area",
      "value": "Dry_Balcony_Area"
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "0",
    "length1": "2",
    "length2": "8",
```

```
"length": "2.67",
"width1": "7",
"width2": "11",
"width": "7.92",
"totalArea": "21.11",
"percentageBeforeTotal": "21.11",
"images": [],
"extraAreas": [],
"percentage": "100",
"finalArea": "21.11"
}
],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "value": "60ae124faa6d152c1801b30f",
    "label": "Article of Agreement"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "185022",
  "selectAreaTypeDocument": "Carpet",
  "totalAreaDocument": "738",
  "squareMeterArea": "68.56",
  "docFinalBuiltUp": "885.6",
  "docFinalBuiltUpSquareMeter": "82.272",
  "docBuiltupPercentage": "20",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
  "printInReport": true,
  "_id": "6527e940d040066d2c56a4e2",
  "property": "1 BHK Flat In Sunrise Tower Goregaon For Sale In Goregaon West",
  "area": "310.00",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
```

```
"source": "Nobroker.com",
"expectedPrice": "8500000.00",
"expectedRate": "27419.35",
"builtUpExpectedRate": "22849.46",
"image": "cases/6520f965119cca234ddcd0d8/
indicator_1697113695611_Image.png",
"squareMeter": "28.80",
"id": "504800"
},
{
"printlnReport": true,
"_id": "6527e940d040066d2c56a4e3",
"property": "1 BHK Flat In Vrindavan For Sale In Goregaon West",
"area": "420.00",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"source": "Nobroker.com",
"expectedPrice": "10500000.00",
"expectedRate": "25000.00",
"builtUpExpectedRate": "20833.33",
"image": "cases/6520f965119cca234ddcd0d8/
indicator_1697113781992_Image.png",
"squareMeter": "39.02",
"id": "169671"
},
{
"printlnReport": true,
"_id": "6527e940d040066d2c56a4e4",
"property": "Motilal Nagar III, Goregaon (West)",
"area": "690.00",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"source": "Nobroker.com",
"expectedPrice": "17500000.00",
"expectedRate": "25362.32",
"builtUpExpectedRate": "21135.27",
"image": "cases/6520f965119cca234ddcd0d8/
indicator_1697113871973_Image.png",
"squareMeter": "64.10",
"id": "294864"
},
{
```

```
"printlnReport": true,
"_id": "6527e940d040066d2c56a4e5",
"property": "1 BHK Flat In Samarth Srushti For Sale In Goregaon West",
"area": "464.00",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"source": "Nobroker.com",
"expectedPrice": "11500000.00",
"expectedRate": "24784.48",
"builtUpExpectedRate": "20653.74",
"image": "cases/6520f965119cca234ddcd0d8/
indicator_1697113929182_Image.png",
"squareMeter": "43.11",
"id": "509894"
}
],
"externalImages": [
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "65238d9b119cca234dde49c6",
"name": "externallmg_1696828826701_IMG_20231007_163632.jpg",
"path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828826701_IMG_20231007_163632.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "65238d9b119cca234dde49c7",
"name": "externallmg_1696828826830_IMG_20231007_163633.jpg",
"path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828826830_IMG_20231007_163633.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "65238d9b119cca234dde49c8",
"name": "externallmg_1696828826999_IMG_20231007_163635.jpg",
"path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828826999_IMG_20231007_163635.jpg",
"orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65238d9b119cca234dde49c9",
  "name": "externallmg_1696828827160_IMG_20231007_163636.jpg",
  "path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828827160_IMG_20231007_163636.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65238d9b119cca234dde49ca",
  "name": "externallmg_1696828827320_IMG_20231008_180513__01.jpg",
  "path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828827320_IMG_20231008_180513__01.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65238d9b119cca234dde49cb",
  "name": "externallmg_1696828827359_IMG_20231008_180519__01.jpg",
  "path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828827359_IMG_20231008_180519__01.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65238d9b119cca234dde49cc",
  "name": "externallmg_1696828827445_IMG_20231007_162136.jpg",
  "path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828827445_IMG_20231007_162136.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65238d9b119cca234dde49cd",
  "name": "externallmg_1696828827606_IMG_20231007_162146.jpg",
  "path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828827606_IMG_20231007_162146.jpg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65238d9b119cca234dde49ce",
    "name": "externallmg_1696828827660_IMG_20231007_162148.jpg",
    "path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828827660_IMG_20231007_162148.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65238d9b119cca234dde49cf",
    "name": "externallmg_1696828827667_IMG_20231007_162151.jpg",
    "path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828827667_IMG_20231007_162151.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65238d9b119cca234dde49d0",
    "name": "externallmg_1696828827673_IMG_20231007_162200.jpg",
    "path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828827673_IMG_20231007_162200.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65238d9b119cca234dde49d1",
    "name": "externallmg_1696828827677_IMG_20231007_162201.jpg",
    "path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828827677_IMG_20231007_162201.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65238d9b119cca234dde49d2",
    "name": "externallmg_1696828827681_IMG_20231007_162203.jpg",
    "path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828827681_IMG_20231007_162203.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```



```
    "status": false,
    "_id": "65238d9b119cca234dde49d3",
    "name": "externallmg_1696828827686_IMG_20231007_162210.jpg",
    "path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828827686_IMG_20231007_162210.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65238d9b119cca234dde49d4",
    "name": "externallmg_1696828827690_IMG_20231007_162211.jpg",
    "path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828827690_IMG_20231007_162211.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65238d9b119cca234dde49d5",
    "name": "externallmg_1696828827694_IMG_20231007_162219.jpg",
    "path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828827694_IMG_20231007_162219.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65238d9b119cca234dde49d6",
    "name": "externallmg_1696828827703_IMG_20231007_162224.jpg",
    "path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828827703_IMG_20231007_162224.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65238d9b119cca234dde49d7",
    "name": "externallmg_1696828827708_IMG_20231007_162232.jpg",
    "path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828827708_IMG_20231007_162232.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "65238d9b119cca234dde49d8",
    "name": "externallmg_1696828827713_IMG_20231007_162234.jpg",
    "path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828827713_IMG_20231007_162234.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65238d9b119cca234dde49d9",
    "name": "externallmg_1696828827720_IMG_20231007_162434.jpg",
    "path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828827720_IMG_20231007_162434.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65238db1119cca234dde4a34",
    "name": "externallmg_1696828849244_IMG_20231007_162436.jpg",
    "path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828849244_IMG_20231007_162436.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65238db1119cca234dde4a35",
    "name": "externallmg_1696828849250_IMG_20231007_162443.jpg",
    "path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828849250_IMG_20231007_162443.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65238db1119cca234dde4a36",
    "name": "externallmg_1696828849261_IMG_20231007_162444.jpg",
    "path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828849261_IMG_20231007_162444.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65238db1119cca234dde4a37",
```

```
    "name": "externallmg_1696828849272_IMG_20231007_162451.jpg",
    "path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828849272_IMG_20231007_162451.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65238db1119cca234dde4a38",
    "name": "externallmg_1696828849276_IMG_20231007_163147.jpg",
    "path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828849276_IMG_20231007_163147.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65238db1119cca234dde4a39",
    "name": "externallmg_1696828849279_IMG_20231007_163149.jpg",
    "path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828849279_IMG_20231007_163149.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65238db1119cca234dde4a3a",
    "name": "externallmg_1696828849282_IMG_20231007_163151.jpg",
    "path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828849282_IMG_20231007_163151.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65238db1119cca234dde4a3b",
    "name": "externallmg_1696828849285_IMG_20231007_163154.jpg",
    "path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828849285_IMG_20231007_163154.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65238db1119cca234dde4a3c",
    "name": "externallmg_1696828849288_IMG_20231007_163207.jpg",
```

```
    "path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828849288_IMG_20231007_163207.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65238db1119cca234dde4a3d",
    "name": "externallmg_1696828849293_IMG_20231007_163221.jpg",
    "path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828849293_IMG_20231007_163221.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65238db1119cca234dde4a3e",
    "name": "externallmg_1696828849302_IMG_20231007_163345.jpg",
    "path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828849302_IMG_20231007_163345.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65238db1119cca234dde4a3f",
    "name": "externallmg_1696828849310_IMG_20231007_163412.jpg",
    "path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828849310_IMG_20231007_163412.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65238db1119cca234dde4a40",
    "name": "externallmg_1696828849315_IMG_20231007_163414.jpg",
    "path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828849315_IMG_20231007_163414.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65238db1119cca234dde4a41",
    "name": "externallmg_1696828849321_IMG_20231007_163416.jpg",
    "path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828849321_IMG_20231007_163416.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65238db1119cca234dde4a42",
  "name": "externallmg_1696828849326_IMG_20231007_163445.jpg",
  "path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828849326_IMG_20231007_163445.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65238db1119cca234dde4a43",
  "name": "externallmg_1696828849333_IMG_20231007_163448.jpg",
  "path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828849333_IMG_20231007_163448.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65238db1119cca234dde4a44",
  "name": "externallmg_1696828849338_IMG_20231007_163449.jpg",
  "path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828849338_IMG_20231007_163449.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65238db1119cca234dde4a45",
  "name": "externallmg_1696828849353_IMG_20231007_163450.jpg",
  "path": "cases/6520f965119cca234ddcd0d8/
externallmg_1696828849353_IMG_20231007_163450.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65238db1119cca234dde4a46",
  "name": "externallmg_r_1696828849298_IMG_20231007_163340.jpg",
  "path": "cases/6520f965119cca234ddcd0d8/
externallmg_r_1696828849298_IMG_20231007_163340.jpg",
  "orientation": "landscape"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65238db1119cca234dde4a47",
      "name": "externalimg_r_1696828849306_IMG_20231007_163348.jpg",
      "path": "cases/6520f965119cca234ddcd0d8/
externalimg_r_1696828849306_IMG_20231007_163348.jpg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65238dc6119cca234dde4a9a",
      "name": "externalimg_1696828870167_IMG_20231007_163517.jpg",
      "path": "cases/6520f965119cca234ddcd0d8/
externalimg_1696828870167_IMG_20231007_163517.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65238dc6119cca234dde4a9b",
      "name": "externalimg_1696828870267_IMG_20231007_163631.jpg",
      "path": "cases/6520f965119cca234ddcd0d8/
externalimg_1696828870267_IMG_20231007_163631.jpg",
      "orientation": "portrait"
    }
  ],
  "externalDocuments": [],
  "processingDocuments": [
    {
      "originalname": "WhatsApp Image 2023-10-13 at 10.20.39 AM (1).jpeg",
      "filename":
"1697179403809_WhatsApp_Image_20231013_at_102039_AM_1.jpeg",
      "path": "cases/6520f965119cca234ddcd0d8/processingDocuments/1697179403809
_WhatsApp_Image_20231013_at_102039_AM_1.jpeg",
      "size": "139085",
      "createdAt": "Fri Oct 13 2023 12:13:24 GMT+0530 (India Standard Time)",
      "uploadedBy": "62fe044a48a26047e6552796"
    },
    {
      "originalname": "WhatsApp Image 2023-10-13 at 10.20.39 AM (2).jpeg",
      "filename":
"1697179404036_WhatsApp_Image_20231013_at_102039_AM_2.jpeg",
      "path": "cases/6520f965119cca234ddcd0d8/processingDocuments/1697179404036
```

```
_WhatsApp_Image_20231013_at_102039_AM_2.jpeg",
  "size": "109678",
  "createdAt": "Fri Oct 13 2023 12:13:24 GMT+0530 (India Standard Time)",
  "uploadedBy": "62fe044a48a26047e6552796"
},
{
  "originalname": "WhatsApp Image 2023-10-13 at 10.20.39 AM.jpeg",
  "filename": "1697179404042_WhatsApp_Image_20231013_at_102039_AM.jpeg",
  "path": "cases/6520f965119cca234ddcd0d8/processingDocuments/1697179404042
_WhatsApp_Image_20231013_at_102039_AM.jpeg",
  "size": "134371",
  "createdAt": "Fri Oct 13 2023 12:13:24 GMT+0530 (India Standard Time)",
  "uploadedBy": "62fe044a48a26047e6552796"
},
{
  "originalname": "WhatsApp Image 2023-10-13 at 10.20.40 AM.jpeg",
  "filename": "1697179404045_WhatsApp_Image_20231013_at_102040_AM.jpeg",
  "path": "cases/6520f965119cca234ddcd0d8/processingDocuments/1697179404045
_WhatsApp_Image_20231013_at_102040_AM.jpeg",
  "size": "107364",
  "createdAt": "Fri Oct 13 2023 12:13:24 GMT+0530 (India Standard Time)",
  "uploadedBy": "62fe044a48a26047e6552796"
}
],
"remarks": [
  {
    "createdBy": {
      "_id": "60092304a16fab0f2af9b0c2",
      "role": "MAKER + RATE VERIFIER + CHEAKER",
      "firstName": "Nitesh",
      "lastName": "Khedekar",
      "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "6523cbf4703d7c40db967f4e",
    "note": "VALUE AND PENDING PLAN",
    "taskId": "65210706119cca234ddcf3ef",
    "createdAt": "2023-10-09T09:46:28.119Z"
  }
],
"createdAt": "2023-10-07T06:23:33.782Z",
"updatedAt": "2023-10-13T10:34:42.708Z",
"__v": 0,
```

```
"invoiceId": "6520f966119cca234ddcd0e9",
"fullAddress": "Residential Flat No. 703, 7th Floor, Wing - B, Kritarth Jeevan Co-Op.
Hsg. Soc. Ltd., Lokmanya Tilak Nagar Road No. 1, M. G. Road, Village - Pahadi
Goregaon, Goregaon (West), Mumbai, Taluka - Borivali, District - Mumbai Suburban,
PIN - 400 062, State - Maharashtra, Country - India",
"updatedBy": "60092304a16fab0f2af9b0c2",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Smt. Varsha Anand Sarawate",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9920624057",
"buildingServicesRate": "2800.00",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Article of Agreement",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 738.00",
"flatRate": "25500.00",
"landOtherRate": "22700",
"briefDescOfProperty": "3 Bedroom + Living Room + Kitchen + 3 Passage + 2 Toilet",
"carpetTotal": "752.39",
"otherCarpetTotal": "21.11",
"builtupPercentage": "10",
"finalBuiltupArea": "850.85",
"finalCarpetArea": "773.50",
"finalSalableArea": "935.94",
"salablePercentage": "10",
"toBeAdded": "",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "21.11",
"otherCompositionSaleableTotal": "0.00",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 752.00\nDry Balcony Area in Sq.
Ft. = 21.00\nTerrace Area in Sq. Ft. = 357.00",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  }
},
```



```

"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
  "leaseFrom": "",
  "leaseTo": "",
  "remainingLeasePeriod": 0,
  "leaseDate": ""
},
"shopDetails": {
  "typeOfShops": {
    "label": "",
    "value": ""
  },
  "roadFacing": false,
  "mall": false
},
"reportGeneratedDate": "Fri Oct 13 2023 15:42:36 GMT+0530 (India Standard Time)",
"siteVisitDate": "2023-10-07"
}

```

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
Composition :			
Living Room	17'1"	9'2"	156.60
Passage	14'3"	3'11"	55.81
Bedroom	12'5"	11'6"	142.79
Passage	3'9"	2'10"	10.62
Bedroom	7'6"	13'11"	104.37
Toilet	4'5"	6'2"	27.24
Toilet	4'00"	8'2"	32.67
Passage	4'6"	6'11"	31.12
Kitchen	10'4"	7'10"	80.94
Bedroom	9'3"	11'11"	110.23

Other  
Composition :

---

Dry Balcony Area	2'8"	7'11"	21.11
------------------	------	-------	-------

---