

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": true,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b80a"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f65be948726cc1419a7",
    "email": "kaushik.datta@sbi.co.in",
    "firstName": "KAUSHUIK",
    "mobileNo": "",
    "workMobileNo": "9757023640",
    "lastName": " DATTA "
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "2000000",
    "discussWithPerson": "KAUSHUIK",
    "expectedFees": 1000,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b80a",
  "branchCode": "000088",
  "type": "BRANCH",
  "name": "RACPC - Chinchpokli ",
  "email": "sbi.17889@sbi.co.in",
  "mobileNo": "022-23707514",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, Mumbai South Voltas
House, 'A', 1st Floor, Dr. Ambedkar Road, Chinchpokli (East), Mumbai - 400 033, State
- Maharashtra, Country - India.\r\n",
  "ledgerName": "STATE BANK OF INDIA - CHINCHPOKALI",
  "fax": "022-23707512 / 13",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "62727444afd7d55eddee092c",
  "role": "PICKUPPERSON",
  "firstName": "Shantilal",
  "email": "shantilal@vastukala.org",
  "lastName": "Patel",
  "mobileNo": "9969039853",
  "shortName": "SHP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62727444afd7d55eddee092c/
profilePhoto_1668057663775_WhatsApp_Image_20221110_at_104853_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "6401b61f0e28255fb44e636a",
  "role": "SITEENGINEER",
  "firstName": "Sanket",
  "email": "ksanket7414@yahoo.com",
  "lastName": "Karalkar",
  "mobileNo": "8080582858",
  "designation": "",
  "shortName": "SAK",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
  "designation": "",
  "shortName": "NK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62691c48afd7d55eddecfda3",
  "role": "ADMIN",
  "firstName": "Bhavika",
  "email": "bhavikachavan0102@gmail.com",
  "lastName": "chavan",
  "mobileNo": "8390804382",
```

```
    "designation": "Site Engineer",
    "shortName": "BH",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
  },
  "checker": {
    "type": "EMPLOYEE",
    "_id": "60092304a16fab0f2af9b0c2",
    "role": "MAKER + RATE VERIFIER + CHEAKER",
    "firstName": "Nitesh",
    "email": "nitesh.khedekar@vastukala.org",
    "lastName": "Khedekar",
    "mobileNo": "8369040652",
    "designation": "",
    "shortName": "NK",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
  },
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "IBBI/RV/07/2018/10366",
          "label": "Registered Valuer"
        }
      ],
      "type": "EMPLOYEE",
      "_id": "5ffe92d27737ca4d986b6453",
      "role": "VALUER",
      "firstName": "Manoj",
      "email": "manoj@vastukala.org",
      "lastName": "Chalikwar",
      "mobileNo": "9819597579",
      "designation": "Registered Valuer",
      "registrationNo": [
        {
          "title": {
            "label": "IBBI"
          },
          "_id": "60af80072ffdf65bcd658651",
          "number": "IBBI/RV/07/2018/10366"
        }
      ],
      {
        "title": {
```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.39491018962582",
  "longitude": "72.82519091663889"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.82519091663889,
    19.39491018962582
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-10-07T11:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-10-07T11:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-10-07T11:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-10-07T11:30:00.000Z",
      "remark": ""
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-16",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-16",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "3BHK",
  "label": "3 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
```

```
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Diwanman",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "1",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
    "value": "Palghar",
    "label": true
  },
  "city": {
    "status": false,
    "name": "City",
```

```
"key": "city",
"value": "",
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Vasai",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Eskon Heights Co-Op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Navghar Manikpur",
  "label": false
},
}
```



```
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "45",
  "label": true
},
"hissaNo": {
  "status": true,
  "name": "Hissa No.",
  "key": "hissaNo",
```

```
"value": "B",
"label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "102",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
```

```
"status": false,
"name": "SRO",
"key": "SRO",
"value": "",
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 401 202",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Vasai Road (West)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_door_frame,_Flush_doors_shutters",
```

```
"label": "Teak Wood door frame, Flush doors shutters"
},
"windows": {
  "value": "Powder_coated_Aluminum_sliding_windows_with_M._S._Grills",
  "label": "Powder coated Aluminum sliding windows with M. S. Grills"
},
"fittings": {
  "value":
"Concealed_plumbing_with_C.P._fittings._Casting_Capping_Electrical_wiring",
  "label": "Concealed plumbing with C.P. fittings. Casting Capping Electrical wiring"
},
"finishing": {
  "value": "Cement_Plastering_+_POP_Finish",
  "label": "Cement Plastering + POP Finish"
}
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Vasai_Virar_City_Municipal_Corporation",
    "label": "Vasai Virar City Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Open Plot",
    "west": "New Shilp CHSL",
    "south": "Dhuri Complex",
    "east": "Ram Rahim Garden CHSL"
  },
  "asPerDocumentAgreement": {
    "north": "details not available ",
    "west": "details not available ",
```

```
"south": "details not available ",
"east": "details not available "
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "N.A. Copy of approved Building Plan were not provided
& not Verified.",
"approvePlanVerified": "",
"empanelledOfApprovePlan": "N.A."
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "16.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "buildingServicesDepreciatedRate": "445.5",
  "depreciatedCostOfConstruction": "8354.50",
  "depreciatedBuildingRate": "2254.5"
},
"igrRate": {
  "propertyName": "Residential ",
  "rate": "60700.00",
  "landRate": "18300",
  "igrImage": "cases/65213247119cca234ddd568b/igr_1697453076688_Image.png",
  "squareMeterGuideLineRate": "57665.00",
  "squareFeetGuideLineRate": "5357.00"
},
"igrFinalRate": {
  "depreciationPercentage": "89",
  "rate": "4955.00",
  "squareFeetGuideLineRate": "4955.00",
```

```
"squareMeterGuideLineRate": "53335.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Vacant",
    "label": "Vacant"
  },
  "monthlyRent": "18000",
  "assessmentNo": "Details not available ",
  "taxPaidHolderName": "Details not available ",
  "taxAmount": "Details not available ",
  "electricityServiceConnectionNo": "Details not available ",
  "meterCardHolderName": "Details not available ",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available ",
  "floorSpaceIndex": "as per VVMC norms",
  "tenantName": "",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located at developing area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\\_Thk._Brick_Masonry",
    "label": "6\\ Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  }
}
```

```
},
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": "Stilt Parking",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2012",
  "fullDate": "1/1/2012"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Normal",
  "label": "Normal"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Average",
  "label": "Average"
},
"structuralSafety": {
  "value": "Normal",
```

```
"label": "Normal"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
  "value": "Part_Ground_and_Part_Stilt",
  "label": "Part Ground + Part Stilt"
},
"yearOfConstructionAsPer": {
  "value": "Approx.",
  "label": "Approx."
},
}
```



```
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "49",
"ageOfBuilding": "11",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "7",
"flatFloorNo": "1",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "5"
},
"finalPlinthArea": {
  "areaType": "Built Up",
  "area": "1043.00",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/65213247119cca234ddd568b/
routeMap_1697439387625_Image.png",
    "routeLat": "19.395195",
    "routeLng": "72.825285",
    "stationName": "Vasai Road",
    "routeDistance": "2.8 Km"
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "n1qgrk",
      "name": "n1qgrk",

```

```
    "image": "cases/65213247119cca234ddd568b/  
routeMap_1697439175077_Image.png"
```

```
  }
```

```
]
```

```
},
```

```
"valuation": {
```

```
  "wardrobesRate": "0",
```

```
  "totalwardrobesRate": "0",
```

```
  "wardrobesQty": "0",
```

```
  "showcasesQty": "0",
```

```
  "showcasesRate": "0",
```

```
  "totalshowcasesRate": "0",
```

```
  "kitchenArrangementsQty": "0",
```

```
  "kitchenArrangementsRate": "0",
```

```
  "totalkitchenArrangementsRate": "0",
```

```
  "superfineFinishQty": "0",
```

```
  "superfineFinishRate": "0",
```

```
  "totalsuperfineFinishRate": "0",
```

```
  "interiorDecorationsQty": "0",
```

```
  "interiorDecorationsRate": "0",
```

```
  "totalinteriorDecorationsRate": "0",
```

```
  "electricityDepositsQty": "0",
```

```
  "electricityDepositsRate": "0",
```

```
  "totalelectricityDepositsRate": "0",
```

```
  "extraCollapsibleGatesQty": "0",
```

```
  "extraCollapsibleGatesRate": "0",
```

```
  "totalextraCollapsibleGatesRate": "0",
```

```
  "potentialValueQty": "0",
```

```
  "potentialValueRate": "0",
```

```
  "totalpotentialValueRate": "0",
```

```
  "othersQty": "0",
```

```
  "othersRate": "0",
```

```
  "totalothersRate": "0",
```

```
  "finaltotal": "8714265.00",
```

```
  "finalValue": "8714265.00",
```

```
  "distressValuePercentage": "80",
```

```
  "realizableValuePercentage": "90",
```

```
  "bookValueDocument": null,
```

```
  "purchaseValueDocument": null,
```

```
  "bookValue": "0"
```

```
},
```

```
"outward": {
```

```
  "status": false,
```

```
  "remark": "SYSTEM_GENERATED"
```

```
},
```

```
"rateVerify": {
```

```
"status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
```

```
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "5168065.00",
  "selectedBuildUpValue": "1043.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "652a8d65758ee2361b418912",
      "name":
"externalImg_1697287525131_WhatsApp_Image_20231014_at_60330_PM.jpeg",
      "path": "cases/65213247119cca234ddd568b/
externalImg_1697287525131_WhatsApp_Image_20231014_at_60330_PM.jpeg",
      "orientation": "landscape"
    }
  ]
}
```

```
}
],
"selfieWithSiteVisitImages": [
  {
    "status": false,
    "_id": "652a8d7c758ee2361b418961",
    "name":
"externallmg_1697287548349_WhatsApp_Image_20231014_at_60336_PM_3.jpeg",
    "path": "cases/65213247119cca234ddd568b/
externallmg_1697287548349_WhatsApp_Image_20231014_at_60336_PM_3.jpeg",
    "orientation": "landscape"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "652a8d65758ee2361b418919",
    "name":
"externallmg_1697287525235_WhatsApp_Image_20231014_at_60333_PM_1.jpeg",
    "path": "cases/65213247119cca234ddd568b/
externallmg_1697287525235_WhatsApp_Image_20231014_at_60333_PM_1.jpeg",
    "orientation": "landscape"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "652a8d65758ee2361b41891c",
    "name":
"externallmg_1697287525248_WhatsApp_Image_20231014_at_60334_PM_1.jpeg",
    "path": "cases/65213247119cca234ddd568b/
externallmg_1697287525248_WhatsApp_Image_20231014_at_60334_PM_1.jpeg",
    "orientation": "landscape"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "652a8d65758ee2361b418922",
    "name": "Living Room",
    "path": "cases/65213247119cca234ddd568b/
externallmg_1697287525623_WhatsApp_Image_20231014_at_60336_PM_1.jpeg",
    "orientation": "landscape"
  }
],
{
```

```
    "status": false,
    "_id": "652a8d7c758ee2361b418960",
    "name": "Living Room",
    "path": "cases/65213247119cca234ddd568b/
externallmg_1697287548337_WhatsApp_Image_20231014_at_60336_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "652a8d7c758ee2361b418965",
    "name": "Living Room",
    "path": "cases/65213247119cca234ddd568b/
externallmg_1697287548415_WhatsApp_Image_20231014_at_60337_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "652a8d7c758ee2361b41896a",
    "name": "Living Room",
    "path": "cases/65213247119cca234ddd568b/
externallmg_1697287548448_WhatsApp_Image_20231014_at_60349_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "652a8d93758ee2361b4189c0",
    "name": "Living Room",
    "path": "cases/65213247119cca234ddd568b/
externallmg_1697287571242_WhatsApp_Image_20231014_at_60352_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "652a8d93758ee2361b4189c1",
    "name": "Living Room",
    "path": "cases/65213247119cca234ddd568b/
externallmg_1697287571251_WhatsApp_Image_20231014_at_60352_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "652a8d93758ee2361b4189c7",
    "name": "Living Room",
    "path": "cases/65213247119cca234ddd568b/
externallmg_1697287571291_WhatsApp_Image_20231014_at_60354_PM_1.jpeg",
    "orientation": "portrait"
  }
```

```
    }
  ]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "9781",
    "max": "10444"
  },
  "builtUpRateRange": {
    "min": "8157",
    "max": "8892"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
}
```



```
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```

```
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "1043.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentId": [],
"_id": "65213247119cca234ddd568b",
"ownerName": "Mr. Ramasray R Yadav",
"ownerPhoneNo": "7666637625",
"appAddress": "B 301 Rashmi Heights\nvasant Nagari\nNalasopara\npin 401200",
"remark": "All documents in Mumbai id ",
"documents": [
```

```
{
  "documentType": {
    "value": "60ae1256aa6d152c1801b330",
    "label": "Draft Agreement for sale"
  },
  "inputs": {
    "from": {
      "value": "Vendor",
      "label": "Vendor"
    },
    "Vendor": "Mr. Ramasray R Yadav & Mrs. Kalavati Ramashray Yadav",
    "to": {
      "value": "Purchaser",
      "label": "Purchaser"
    },
    "Purchaser": "Ms. Preeti Yadav"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "870414",
  "path": "cases/65213247119cca234ddd568b/
document_1696674290112_267902.pdf",
  "fileName": "document_1696674290112_267902.pdf"
}
],
"caseNumber": "004272",
"createdBy": "62727444afd7d55eddee092c",
"caseHistory": [
  {
    "id": "138425",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Oct 07 2023 15:56:15 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Ramasray R Yadav",
    "phone": "7666637625",
    "ownershipShare": "",
    "email": "",
    "id": "918833"
  },
  {
    "name": "Mrs. Kalavati Ramasray Yadav",
    "phone": ""
  }
]
```

```
"email": "",
"ownershipShare": "",
"id": "389591"
}
],
"proposePurchasers": [
{
"name": "Ms. Preeti Yadav",
"phone": "",
"ownershipShare": "",
"email": ""
}
],
"siteInspection": [],
"composition": [
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "880946",
"name": "Living Room",
"length": "10.00",
"length1": "10",
"length2": "00",
"width": "21.00",
"width1": "21",
"width2": "00",
"totalArea": "210.00",
"images": [],
"extraAreas": [],
"finalArea": "210.00"
},
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "1",
"name": "Dining",
"length": "5.17",
"length1": "5",
"length2": "2",
"width": "6.58",
"width1": "6",
"width2": "7",
```

```
"totalArea": "34.01",
"images": [],
"extraAreas": [],
"finalArea": "34.01"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Bedroom",
  "length": "9.50",
  "length1": "9",
  "length2": "6",
  "width": "13.33",
  "width1": "13",
  "width2": "4",
  "totalArea": "126.67",
  "images": [],
  "extraAreas": [],
  "finalArea": "126.67"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bedroom",
  "length": "10.00",
  "length1": "10",
  "length2": "00",
  "width": "12.42",
  "width1": "12",
  "width2": "5",
  "totalArea": "124.17",
  "images": [],
  "extraAreas": [],
  "finalArea": "124.17"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Bedroom",
  "length": "10.00",
  "length1": "10",
  "length2": "00",
  "width": "12.42",
  "width1": "12",
  "width2": "5",
  "totalArea": "124.17",
  "images": [],
  "extraAreas": [],
  "finalArea": "124.17"
}
```

```
"id": "4",
"name": "Bedroom",
"length": "9.00",
"length1": "9",
"length2": "00",
"width": "10.42",
"width1": "10",
"width2": "5",
"totalArea": "93.75",
"images": [],
"extraAreas": [],
"finalArea": "93.75"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Kitchen",
  "length": "",
  "length1": "9",
  "length2": "3",
  "width": "",
  "width1": "8",
  "width2": "0",
  "totalArea": "74.00",
  "images": [],
  "finalArea": "74.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Toilet",
  "length": "7.00",
  "length1": "7",
  "length2": "00",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "28.00",
  "images": [],
```

```
"extraAreas": [],
"finalArea": "28.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Toilet",
  "length": "",
  "length1": "7",
  "length2": "0",
  "width": "",
  "width1": "5",
  "width2": "0",
  "totalArea": "35.00",
  "images": [],
  "finalArea": "35.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "9",
  "name": "Toilet",
  "length": "",
  "length1": "4",
  "length2": "0",
  "width": "",
  "width1": "6",
  "width2": "2",
  "totalArea": "24.67",
  "images": [],
  "finalArea": "24.67",
  "extraAreas": []
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    }
  },

```

```
"name": {
  "label": "Passage",
  "value": "Passage"
},
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"length1": "18",
"length2": "00",
"length": "18.00",
"width1": "3",
"width2": "8",
"width": "3.67",
"totalArea": "66.00",
"percentageBeforeTotal": "66.00",
"images": [],
"extraAreas": [],
"percentage": "100",
"finalArea": "66"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Passage",
    "value": "Passage"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "length1": "5",
  "length2": "0",
  "length": "",
  "width1": "2",
  "width2": "0",
  "width": "",
  "totalArea": "10.00",
  "percentageBeforeTotal": "10.00",
  "images": [],
  "extraAreas": [],
```



```
"percentage": "100",
"finalArea": "10"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Passage",
    "value": "Passage"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "length1": "5",
  "length2": "9",
  "length": "5.75",
  "width1": "4",
  "width2": "7",
  "width": "4.58",
  "totalArea": "26.35",
  "percentageBeforeTotal": "26.35",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "26.35"
}
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60ae1256aa6d152c1801b330",
      "label": "Draft Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "508567",
    "selectAreaTypeDocument": "Built_Up",
    "totalAreaDocument": "1043",
    "squareMeterArea": "96.9",
```

```
"docFinalBuiltUp": "0.00",
"docFinalBuiltUpSquareMeter": "0.00",
"docBuiltupPercentage": "",
"docSaleablePercentage": "0",
"docFinalSaleable": "0",
"docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "652d1421316e1359cebd2b1d",
  "property": "Resale flat for sale in Eskon Heights, Vasai Road (West)",
  "area": "776.00",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Built_Up",
  "source": "https://maharera.mahaonline.gov.in",
  "expectedPrice": "6900000.00",
  "expectedRate": "8891.75",
  "builtUpExpectedRate": "0.00",
  "image": "cases/65213247119cca234ddd568b/
indicator_1697452087686_Image.png",
  "squareMeter": "72.09",
  "id": "565482"
},
{
  "printlnReport": true,
  "_id": "652d1421316e1359cebd2b1e",
  "property": "1 BHK Flat In Parshwa Darshan CHSL, Vasai (West)",
  "area": "360.00",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "Nobroker.com",
  "expectedPrice": "3600000.00",
  "expectedRate": "10000.00",
  "builtUpExpectedRate": "8333.33",
  "image": "cases/65213247119cca234ddd568b/
indicator_1697452176564_Image.png",
  "squareMeter": "33.45",
  "id": "200744"
},
}
```

```
{
  "printlnReport": true,
  "_id": "652d1421316e1359cebd2b1f",
  "property": "1 BHK Flat For Sale In Om Nagar, Vasai (West)",
  "area": "383.00",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "Nobroker.com",
  "expectedPrice": "4000000.00",
  "expectedRate": "10443.86",
  "builtUpExpectedRate": "8703.22",
  "image": "cases/65213247119cca234ddd568b/
indicator_1697452242457_Image.png",
  "squareMeter": "35.58",
  "id": "801073"
},
{
  "printlnReport": true,
  "_id": "652d1421316e1359cebd2b20",
  "property": "1 BHK Flat In Kt Melody Chs For Sale In Vasai West",
  "area": "470.00",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "Nobroker.com",
  "expectedPrice": "4600000.00",
  "expectedRate": "9787.23",
  "builtUpExpectedRate": "8156.03",
  "image": "cases/65213247119cca234ddd568b/
indicator_1697452308991_Image.png",
  "squareMeter": "43.66",
  "id": "511820"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652a8d65758ee2361b41890f",
    "name":
"externallmg_1697287525080_WhatsApp_Image_20231014_at_60318_PM.jpeg",
    "path": "cases/65213247119cca234ddd568b/
externallmg_1697287525080_WhatsApp_Image_20231014_at_60318_PM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652a8d65758ee2361b418910",
    "name":
"externallmg_1697287525088_WhatsApp_Image_20231014_at_60320_PM.jpeg",
    "path": "cases/65213247119cca234ddd568b/
externallmg_1697287525088_WhatsApp_Image_20231014_at_60320_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652a8d65758ee2361b418911",
    "name":
"externallmg_1697287525100_WhatsApp_Image_20231014_at_60328_PM.jpeg",
    "path": "cases/65213247119cca234ddd568b/
externallmg_1697287525100_WhatsApp_Image_20231014_at_60328_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652a8d65758ee2361b418912",
    "name":
"externallmg_1697287525131_WhatsApp_Image_20231014_at_60330_PM.jpeg",
    "path": "cases/65213247119cca234ddd568b/
externallmg_1697287525131_WhatsApp_Image_20231014_at_60330_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652a8d65758ee2361b418913",
    "name":
"externallmg_1697287525155_WhatsApp_Image_20231014_at_60331_PM_1.jpeg",
    "path": "cases/65213247119cca234ddd568b/
externallmg_1697287525155_WhatsApp_Image_20231014_at_60331_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652a8d65758ee2361b418914",
```

```
    "name":
"externallmg_1697287525177_WhatsApp_Image_20231014_at_60331_PM_2.jpeg",
  "path": "cases/65213247119cca234ddd568b/
externallmg_1697287525177_WhatsApp_Image_20231014_at_60331_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652a8d65758ee2361b418915",
  "name":
"externallmg_1697287525196_WhatsApp_Image_20231014_at_60331_PM.jpeg",
  "path": "cases/65213247119cca234ddd568b/
externallmg_1697287525196_WhatsApp_Image_20231014_at_60331_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652a8d65758ee2361b418916",
  "name":
"externallmg_1697287525207_WhatsApp_Image_20231014_at_60332_PM_1.jpeg",
  "path": "cases/65213247119cca234ddd568b/
externallmg_1697287525207_WhatsApp_Image_20231014_at_60332_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652a8d65758ee2361b418917",
  "name":
"externallmg_1697287525219_WhatsApp_Image_20231014_at_60332_PM_2.jpeg",
  "path": "cases/65213247119cca234ddd568b/
externallmg_1697287525219_WhatsApp_Image_20231014_at_60332_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652a8d65758ee2361b418918",
  "name":
"externallmg_1697287525225_WhatsApp_Image_20231014_at_60332_PM.jpeg",
  "path": "cases/65213247119cca234ddd568b/
externallmg_1697287525225_WhatsApp_Image_20231014_at_60332_PM.jpeg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652a8d65758ee2361b418919",
  "name":
"externallmg_1697287525235_WhatsApp_Image_20231014_at_60333_PM_1.jpeg",
  "path": "cases/65213247119cca234ddd568b/
externallmg_1697287525235_WhatsApp_Image_20231014_at_60333_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652a8d65758ee2361b41891a",
  "name":
"externallmg_1697287525241_WhatsApp_Image_20231014_at_60333_PM_2.jpeg",
  "path": "cases/65213247119cca234ddd568b/
externallmg_1697287525241_WhatsApp_Image_20231014_at_60333_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652a8d65758ee2361b41891b",
  "name":
"externallmg_1697287525244_WhatsApp_Image_20231014_at_60333_PM.jpeg",
  "path": "cases/65213247119cca234ddd568b/
externallmg_1697287525244_WhatsApp_Image_20231014_at_60333_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652a8d65758ee2361b41891c",
  "name":
"externallmg_1697287525248_WhatsApp_Image_20231014_at_60334_PM_1.jpeg",
  "path": "cases/65213247119cca234ddd568b/
externallmg_1697287525248_WhatsApp_Image_20231014_at_60334_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652a8d65758ee2361b41891d",
  "name":
"externallmg_1697287525253_WhatsApp_Image_20231014_at_60334_PM_2.jpeg",
```

```
    "path": "cases/65213247119cca234ddd568b/
externallmg_1697287525253_WhatsApp_Image_20231014_at_60334_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652a8d65758ee2361b41891e",
    "name":
"externallmg_1697287525255_WhatsApp_Image_20231014_at_60334_PM.jpeg",
    "path": "cases/65213247119cca234ddd568b/
externallmg_1697287525255_WhatsApp_Image_20231014_at_60334_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652a8d65758ee2361b41891f",
    "name":
"externallmg_1697287525600_WhatsApp_Image_20231014_at_60335_PM_1.jpeg",
    "path": "cases/65213247119cca234ddd568b/
externallmg_1697287525600_WhatsApp_Image_20231014_at_60335_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652a8d65758ee2361b418920",
    "name":
"externallmg_1697287525605_WhatsApp_Image_20231014_at_60335_PM_2.jpeg",
    "path": "cases/65213247119cca234ddd568b/
externallmg_1697287525605_WhatsApp_Image_20231014_at_60335_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652a8d65758ee2361b418921",
    "name":
"externallmg_1697287525614_WhatsApp_Image_20231014_at_60335_PM.jpeg",
    "path": "cases/65213247119cca234ddd568b/
externallmg_1697287525614_WhatsApp_Image_20231014_at_60335_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "652a8d65758ee2361b418922",
  "name":
"externallmg_1697287525623_WhatsApp_Image_20231014_at_60336_PM_1.jpeg",
  "path": "cases/65213247119cca234ddd568b/
externallmg_1697287525623_WhatsApp_Image_20231014_at_60336_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652a8d7c758ee2361b418960",
  "name":
"externallmg_1697287548337_WhatsApp_Image_20231014_at_60336_PM_2.jpeg",
  "path": "cases/65213247119cca234ddd568b/
externallmg_1697287548337_WhatsApp_Image_20231014_at_60336_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652a8d7c758ee2361b418961",
  "name":
"externallmg_1697287548349_WhatsApp_Image_20231014_at_60336_PM_3.jpeg",
  "path": "cases/65213247119cca234ddd568b/
externallmg_1697287548349_WhatsApp_Image_20231014_at_60336_PM_3.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652a8d7c758ee2361b418962",
  "name":
"externallmg_1697287548372_WhatsApp_Image_20231014_at_60336_PM.jpeg",
  "path": "cases/65213247119cca234ddd568b/
externallmg_1697287548372_WhatsApp_Image_20231014_at_60336_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652a8d7c758ee2361b418963",
  "name":
"externallmg_1697287548376_WhatsApp_Image_20231014_at_60337_PM_1.jpeg",
  "path": "cases/65213247119cca234ddd568b/
externallmg_1697287548376_WhatsApp_Image_20231014_at_60337_PM_1.jpeg",
```



```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652a8d7c758ee2361b418964",
    "name":
"externallmg_1697287548406_WhatsApp_Image_20231014_at_60337_PM_2.jpeg",
    "path": "cases/65213247119cca234ddd568b/
externallmg_1697287548406_WhatsApp_Image_20231014_at_60337_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652a8d7c758ee2361b418965",
    "name":
"externallmg_1697287548415_WhatsApp_Image_20231014_at_60337_PM.jpeg",
    "path": "cases/65213247119cca234ddd568b/
externallmg_1697287548415_WhatsApp_Image_20231014_at_60337_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652a8d7c758ee2361b418966",
    "name":
"externallmg_1697287548423_WhatsApp_Image_20231014_at_60338_PM_1.jpeg",
    "path": "cases/65213247119cca234ddd568b/
externallmg_1697287548423_WhatsApp_Image_20231014_at_60338_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652a8d7c758ee2361b418967",
    "name":
"externallmg_1697287548429_WhatsApp_Image_20231014_at_60338_PM_2.jpeg",
    "path": "cases/65213247119cca234ddd568b/
externallmg_1697287548429_WhatsApp_Image_20231014_at_60338_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652a8d7c758ee2361b418968",
```

```
    "name":
"externallmg_1697287548438_WhatsApp_Image_20231014_at_60338_PM.jpeg",
    "path": "cases/65213247119cca234ddd568b/
externallmg_1697287548438_WhatsApp_Image_20231014_at_60338_PM.jpeg",
    "orientation": "landscape"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652a8d7c758ee2361b418969",
    "name":
"externallmg_1697287548443_WhatsApp_Image_20231014_at_60339_PM.jpeg",
    "path": "cases/65213247119cca234ddd568b/
externallmg_1697287548443_WhatsApp_Image_20231014_at_60339_PM.jpeg",
    "orientation": "portrait"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652a8d7c758ee2361b41896a",
    "name":
"externallmg_1697287548448_WhatsApp_Image_20231014_at_60349_PM_1.jpeg",
    "path": "cases/65213247119cca234ddd568b/
externallmg_1697287548448_WhatsApp_Image_20231014_at_60349_PM_1.jpeg",
    "orientation": "portrait"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652a8d7c758ee2361b41896b",
    "name":
"externallmg_1697287548454_WhatsApp_Image_20231014_at_60349_PM.jpeg",
    "path": "cases/65213247119cca234ddd568b/
externallmg_1697287548454_WhatsApp_Image_20231014_at_60349_PM.jpeg",
    "orientation": "portrait"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652a8d7c758ee2361b41896c",
    "name":
"externallmg_1697287548463_WhatsApp_Image_20231014_at_60350_PM.jpeg",
    "path": "cases/65213247119cca234ddd568b/
externallmg_1697287548463_WhatsApp_Image_20231014_at_60350_PM.jpeg",
    "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652a8d7c758ee2361b41896d",
  "name":
"externallmg_1697287548468_WhatsApp_Image_20231014_at_60351_PM_1.jpeg",
  "path": "cases/65213247119cca234ddd568b/
externallmg_1697287548468_WhatsApp_Image_20231014_at_60351_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652a8d7c758ee2361b41896e",
  "name":
"externallmg_1697287548470_WhatsApp_Image_20231014_at_60351_PM_2.jpeg",
  "path": "cases/65213247119cca234ddd568b/
externallmg_1697287548470_WhatsApp_Image_20231014_at_60351_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652a8d93758ee2361b4189bb",
  "name":
"externallmg_1697287571181_WhatsApp_Image_20231014_at_60349_PM.jpeg",
  "path": "cases/65213247119cca234ddd568b/
externallmg_1697287571181_WhatsApp_Image_20231014_at_60349_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652a8d93758ee2361b4189bc",
  "name":
"externallmg_1697287571203_WhatsApp_Image_20231014_at_60350_PM.jpeg",
  "path": "cases/65213247119cca234ddd568b/
externallmg_1697287571203_WhatsApp_Image_20231014_at_60350_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652a8d93758ee2361b4189bd",
  "name":
"externallmg_1697287571217_WhatsApp_Image_20231014_at_60351_PM_1.jpeg",
```

```
    "path": "cases/65213247119cca234ddd568b/
externallmg_1697287571217_WhatsApp_Image_20231014_at_60351_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652a8d93758ee2361b4189be",
    "name":
"externallmg_1697287571222_WhatsApp_Image_20231014_at_60351_PM_2.jpeg",
    "path": "cases/65213247119cca234ddd568b/
externallmg_1697287571222_WhatsApp_Image_20231014_at_60351_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652a8d93758ee2361b4189bf",
    "name":
"externallmg_1697287571233_WhatsApp_Image_20231014_at_60351_PM.jpeg",
    "path": "cases/65213247119cca234ddd568b/
externallmg_1697287571233_WhatsApp_Image_20231014_at_60351_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652a8d93758ee2361b4189c0",
    "name":
"externallmg_1697287571242_WhatsApp_Image_20231014_at_60352_PM_1.jpeg",
    "path": "cases/65213247119cca234ddd568b/
externallmg_1697287571242_WhatsApp_Image_20231014_at_60352_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652a8d93758ee2361b4189c1",
    "name":
"externallmg_1697287571251_WhatsApp_Image_20231014_at_60352_PM_2.jpeg",
    "path": "cases/65213247119cca234ddd568b/
externallmg_1697287571251_WhatsApp_Image_20231014_at_60352_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "652a8d93758ee2361b4189c2",
  "name":
"externallmg_1697287571257_WhatsApp_Image_20231014_at_60352_PM.jpeg",
  "path": "cases/65213247119cca234ddd568b/
externallmg_1697287571257_WhatsApp_Image_20231014_at_60352_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652a8d93758ee2361b4189c3",
  "name":
"externallmg_1697287571262_WhatsApp_Image_20231014_at_60353_PM_1.jpeg",
  "path": "cases/65213247119cca234ddd568b/
externallmg_1697287571262_WhatsApp_Image_20231014_at_60353_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652a8d93758ee2361b4189c4",
  "name":
"externallmg_1697287571267_WhatsApp_Image_20231014_at_60353_PM_2.jpeg",
  "path": "cases/65213247119cca234ddd568b/
externallmg_1697287571267_WhatsApp_Image_20231014_at_60353_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652a8d93758ee2361b4189c5",
  "name":
"externallmg_1697287571283_WhatsApp_Image_20231014_at_60353_PM_3.jpeg",
  "path": "cases/65213247119cca234ddd568b/
externallmg_1697287571283_WhatsApp_Image_20231014_at_60353_PM_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652a8d93758ee2361b4189c6",
  "name":
"externallmg_1697287571287_WhatsApp_Image_20231014_at_60353_PM.jpeg",
  "path": "cases/65213247119cca234ddd568b/
externallmg_1697287571287_WhatsApp_Image_20231014_at_60353_PM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652a8d93758ee2361b4189c7",
    "name":
"externallmg_1697287571291_WhatsApp_Image_20231014_at_60354_PM_1.jpeg",
    "path": "cases/65213247119cca234ddd568b/
externallmg_1697287571291_WhatsApp_Image_20231014_at_60354_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652a8d93758ee2361b4189c8",
    "name":
"externallmg_1697287571298_WhatsApp_Image_20231014_at_60354_PM.jpeg",
    "path": "cases/65213247119cca234ddd568b/
externallmg_1697287571298_WhatsApp_Image_20231014_at_60354_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652a8d93758ee2361b4189c9",
    "name":
"externallmg_1697287571304_WhatsApp_Image_20231014_at_60413_PM.jpeg",
    "path": "cases/65213247119cca234ddd568b/
externallmg_1697287571304_WhatsApp_Image_20231014_at_60413_PM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-10-07T10:26:15.880Z",
"updatedAt": "2023-10-17T06:02:40.067Z",
"__v": 0,
"invoiceId": "65213248119cca234ddd56a4",
"fullAddress": "Residential Flat No. 102, 1st Floor, Eskon Heights Co-Op. Hsg. Soc.
Ltd., Navghar Manikpur, Village - Diwanman, Vasai Road (West), Taluka - Vasai, District
- Palghar, PIN - 401 202, State - Maharashtra, India",
"updatedBy": "60092304a16fab0f2af9b0c2",
"addressForMap": "",
"caseReferredBy": "62727444afd7d55eddee092c",
```

```
"contactPersonName": "Mr. Ramasray R Yadav",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "7666637625",
"reason": "Cancled by bank",
"builtupPercentage": "10",
"carpetTotal": "750.27",
"extendOfSiteRemark": "",
"finalBuiltupArea": "897.90",
"finalCarpetArea": "816.27",
"finalSalableArea": "987.69",
"otherCarpetTotal": "102.35",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Draft Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalSaleablePercentage": "0",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 1043.00",
"briefDescOfProperty": "3 Bedroom + Living Room + Kitchen + Dining + 3 Toilet",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "66.00",
"otherCompositionSaleableTotal": "0.00",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
  "leaseFrom": "",
  "leaseTo": "",
  "remainingLeasePeriod": 0,
  "leaseDate": ""
}
```

```

},
"buildingServicesRate": "2700.00",
"flatRate": "8800.00",
"landOtherRate": "6100",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"reportGeneratedDate": "Tue Oct 17 2023 11:11:49 GMT+0530 (India Standard Time)",
"siteVisitDate": "2023-10-16"
}

```

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
<b>Composition :</b>			
Living Room	10'00"	21'00"	210.00
Dining	5'2"	6'7"	34.01
Bedroom	9'6"	13'4"	126.67
Bedroom	10'00"	12'5"	124.17
Bedroom	9'00"	10'5"	93.75
Kitchen	9'3"	8'0"	74.00
Toilet	7'00"	4'00"	28.00
Toilet	7'0"	5'0"	35.00
Toilet	4'0"	6'2"	24.67
<b>Other Composition :</b>			
Passage	18'00"	3'8"	66.00
Passage	5'0"	2'0"	10.00
Passage	5'9"	4'7"	26.35