

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63b26593191f7b344b008b23"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f66be948726cc141b89",
    "email": "1nilesh.pahilwan@sbi.co.in",
    "firstName": "NILESH ",
    "mobileNo": "",
    "workMobileNo": "9769636833",
    "lastName": "PAHILWAN"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "1105000",
    "discussWithPerson": "NILESH ",
    "expectedFees": 552.5,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63b26593191f7b344b008b23",
  "name": "INDUSTRIAL FINANCE BRANCH VASAI (EAST)",
  "branchCode": "",
  "mobileNo": "022-2502456981",
  "alternateMobileNo": "",
  "email": "sbi.12939@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Industrial Estate Branch, Gavrai Pada, District Palghar - 401 201."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "627219d6afd7d55eddedd283",
    "role": "PICKUPPERSON",
```

```
"firstName": "Mangesh ",
"email": "mangeshpalande17@gmail.com",
"lastName": "Palande",
"mobileNo": "9833030550",
"shortName": "MP",
"workWithDocumentMaker": "",
"profilePhoto": "users/627219d6afd7d55eddedd283/
profilePhoto_1668055836118_WhatsApp_Image_20221110_at_101725_AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "64c777a8a5c3051014f4dd1f",
"role": "SITEENGINEER",
"firstName": "Pratik",
"email": "pratikjain2277@gmail.com",
"lastName": "Jain",
"mobileNo": "9619286285",
"designation": "",
"shortName": "Pratik",
"workWithDocumentMaker": "6006d4ce5080a310ac1fd2c"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "64cde526dc9f3034f3fefa49",
"role": "FRONTDESK",
"firstName": "Rashmi",
"email": "rashmijadhav14feb@gmail.com",
"lastName": "Jadhav",
"mobileNo": "7738144625",
"designation": "Back Office Coordinatiion",
"shortName": "RJ",
"workWithDocumentMaker": "60eeaeddf3dd69653a581316",
"profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "62fe044a48a26047e6552796",
"role": "MAKER",
"firstName": "Pradnya ",
"email": "pradnya@vastukala.org",
"lastName": "Rasam",
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
```

```
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "_id": "64cde526dc9f3034f3fefa49",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg",
  "firstName": "Rashmi",
  "lastName": "Jadhav",
  "shortName": "RJ",
  "email": "rashmijadhav14feb@gmail.com",
  "designation": "Back Office Coordinatiion",
  "mobileNo": "7738144625",
  "role": "FRONTDESK",
  "type": "EMPLOYEE",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        }
      }
    ]
  }
],
```

```
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.336513395767103",
  "longitude": "72.85022664729438"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.85022664729438,
    19.336513395767103
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
```

```
"schedule": [
  {
    "dateTime": "2023-10-10T12:00:00.000Z",
    "remark": ""
  },
  {
    "dateTime": "2023-10-10T12:00:00.000Z",
    "remark": ""
  },
  {
    "dateTime": "2023-10-10T12:00:00.000Z",
    "remark": ""
  }
],
"visitedDate": [
  {
    "status": "COMPLETED",
    "dateTime": "2023-10-11",
    "remark": "MANUAL_IN_TASK"
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "3BHK",
  "label": "3 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
```

```
"value": "Country - India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Bhayander",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "7",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "5/6",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Bhayander (West)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
```

```
"status": true,
"name": "Taluka",
"key": "taluka",
"value": "Thane",
"label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Om Girnar Co-Op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": ", 251",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Padmavati Nagar, 150 Feet Road",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
```



```
"label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "262/1/2, 263/1, 251/2",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
```

```
"name": "Block No",
"key": "blockNo",
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "705",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
}
```

```
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 401 101",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
```

```
"value": "Cement_Plastering_+_POP_Finish",
"label": "Cement Plastering + POP Finish"
}
},
"general": {
"ownership": {
"value": "Joint_Ownership",
"label": "Joint Ownership"
},
"populationClassList": {
"value": "MiddleClass",
"label": "Middle Class"
},
"populationGroupList": {
"value": "Urban",
"label": "Urban"
},
"townplanApprovedByList": {
"value": "Mira_Bhayander_Municipal_Corporation",
"label": "Mira Bhayander Municipal Corporation"
},
"whetherCoveredUnderAnyState": {
"value": "No",
"label": "No"
},
"asPerActualAgreement": {
"north": "Nageshwar CHSL",
"west": "Shankheshwar Building ",
"south": "Uttan Road",
"east": "Internal Road"
},
"asPerDocumentAgreement": {
"north": "Details is not available",
"west": "Details is not available",
"south": "Details is not available",
"east": "Details is not available"
},
"unitBoundaries": {
"asPerActual": {
"north": "Details is not available",
"east": "Details is not available",
"south": "Details is not available",
"west": "Details is not available"
},
"asPerDocument": {
"north": "Details is not available",
```

```

    "east": "Details is not available",
    "south": "Details is not available",
    "west": "Details is not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "At the time of site visit, Flat Nos. 705 & 706 are internally merged with single entrance from Flat No. 705.",
"dateOfIssusApprovePlan": "As Copy of occupancy certificate is received may be assumed that the construction is as per sanctioned plan.",
"approvePlanVerified": "N.A",
"empanelledOfApprovePlan": "N.A"
},
"compositeRate": {
  "remark": "\n1)\tAt the time of site visit, flat internal painting work was in progress. \n2)\tAs per site inspection, Flat Nos. 705 & 706 are internally amalgamated to form a single flat having entrance from Flat No. 705. \n3)\tKitchen area converted into Bedroom. \n4)\tWe have taken measurements of Flat No. 705 only. Two flats are internally amalgamated to form a single flat but can be demarcated individually.\n5)\tAs per bank request, we have done the valuation of Flat No. 705 only. \n6)\tFor the purpose of valuation, we have considered area as per Agreement for Sale. ",
  "depreciationPercentage": "21",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "10975",
  "depreciatedBuildingRate": "1975"
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "69600",
  "landRate": "22400",
  "igrImage": "cases/65253fe3703d7c40db990f0d/igr_1697188169665_Image.png",
  "squareMeterGuideLineRate": "73080.00",
  "squareFeetGuideLineRate": "6789.00"
},
"igrFinalRate": {
  "depreciationPercentage": "86",
  "rate": "6130.00",
  "squareFeetGuideLineRate": "6130.00",
  "squareMeterGuideLineRate": "65985.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  }
}

```

```
},
"propertyTypeOfUseList": {
  "value": "Residential_Purpose",
  "label": "Residential Purpose"
},
"propertyOccupiedByList": {
  "value": "Owner_Occupied",
  "label": "Owner Occupied"
},
"monthlyRent": "19,000",
"assessmentNo": "Details is not available",
"taxPaidHolderName": "Details is not available",
"taxAmount": "Details is not available",
"electricityServiceConnectionNo": "Details is not available",
"meterCardHolderName": "Details is not available",
"undividedAreaOfLandAsPerSaleDeed": "Details is not available",
"floorSpaceIndex": "As per MCGM norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  }
},
"anyFavouringForExtraPotentialValue": "Located in developed area",
"negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Stilt Car Parking Space",
```

```
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2009",
  "fullDate": "1/1/2009"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
}
```

```
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "14",
"totalLifeBuilding": "60",
"estimatedAge": "46",
"noOfBasement": "",
"noOfPodium": ""
```



```
"noOfAmenityFloors": "",
"noOfFloors": "7",
"flatFloorNo": "7",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "areaType": "Built Up",
  "area": "0.00",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + NaN%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/65253fe3703d7c40db990f0d/
routeMap_1697194515954_Image.png",
    "routeLat": "19.295302",
    "routeLng": "72.847391",
    "stationName": "Bhayander",
    "routeDistance": "3.3 Km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "5fndin",
      "name": "5fndin",
      "image": "cases/65253fe3703d7c40db990f0d/
routeMap_1697194336192_Image.png"
    }
  ]
},
"valuation": {
```

```
"wardrobesRate": "0",
"totalwardrobesRate": "0",
"wardrobesQty": "0",
"showcasesQty": "0",
"showcasesRate": "0",
"totalshowcasesRate": "0",
"kitchenArrangementsQty": "0",
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "9328750.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "9328750.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Fri Oct 13 2023 18:06:19 GMT+0530 (India Standard Time)",
  "number": "2303000",
  "dayCount": "21",
  "monthCount": "197",
  "generatedBy": "64cde526dc9f3034f3fefa49"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
```

```
"rccFootingFoundation": {
  "label": "RCC Footing/Foundation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
```

```
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "5210500.00",
"selectedBuildUpValue": "850.00",
"selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
"frontPageImages": [
{
"status": false,
"_id": "652767cef29c6044081860a8",
"name":
"externallmg_1697081294791_IMG_20231011_152336_copy_900x1200.jpg",
"path": "cases/65253fe3703d7c40db990f0d/
externallmg_1697081294791_IMG_20231011_152336_copy_900x1200.jpg",
"orientation": "portrait"
}
],
"selfieWithSiteVisitImages": [],
```

```
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "652767bcf29c604408186044",
    "name": "Living Room",
    "path": "cases/65253fe3703d7c40db990f0d/
externallmg_1697081276273_IMG_20231011_150812_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "652767bcf29c604408186045",
    "name": "Living Room",
    "path": "cases/65253fe3703d7c40db990f0d/
externallmg_1697081276279_IMG_20231011_150815_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "652767bcf29c604408186042",
    "name": "Living Room",
    "path": "cases/65253fe3703d7c40db990f0d/
externallmg_1697081276243_IMG_20231011_150750_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "652767cef29c60440818609a",
    "name": "Living Room",
    "path": "cases/65253fe3703d7c40db990f0d/
externallmg_1697081294700_IMG_20231011_150722_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "652767cef29c6044081860a0",
    "name": "Living Room",
    "path": "cases/65253fe3703d7c40db990f0d/
externallmg_1697081294742_IMG_20231011_150802_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
```

```
    "_id": "652767cef29c60440818609e",
    "name": "Living Room",
    "path": "cases/65253fe3703d7c40db990f0d/
externallmg_1697081294729_IMG_20231011_150751_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "652767cef29c60440818609d",
    "name": "Living Room",
    "path": "cases/65253fe3703d7c40db990f0d/
externallmg_1697081294718_IMG_20231011_150734_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "652767cef29c6044081860a4",
    "name": "Living Room",
    "path": "cases/65253fe3703d7c40db990f0d/
externallmg_1697081294773_IMG_20231011_152300_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "652767cef29c6044081860a8",
    "name": "Living Room",
    "path": "cases/65253fe3703d7c40db990f0d/
externallmg_1697081294791_IMG_20231011_152336_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "652767bcf29c60440818604b",
    "name": "Living Room",
    "path": "cases/65253fe3703d7c40db990f0d/
externallmg_1697081276363_IMG_20231011_152334_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "652767bcf29c60440818604a",
    "name": "Living Room",
    "path": "cases/65253fe3703d7c40db990f0d/
externallmg_1697081276347_IMG_20231011_152331_copy_900x1200.jpg",
    "orientation": "portrait"
  },
}
```

```
{
  "status": false,
  "_id": "652767bcf29c604408186047",
  "name": "Living Room",
  "path": "cases/65253fe3703d7c40db990f0d/
externallmg_1697081276298_IMG_20231011_152227_copy_900x1200.jpg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "652767bcf29c604408186048",
  "name": "Living Room",
  "path": "cases/65253fe3703d7c40db990f0d/
externallmg_1697081276311_IMG_20231011_152322_copy_901x1200.jpg",
  "orientation": "portrait"
}
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "16878",
    "max": "18551"
  },
  "builtUpRateRange": {
    "min": "14065",
    "max": "15459"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
```



```
"title": "Showcases",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
```

```
"isSiteMeasurementAllowed": true,
"finalValuationArea": "850.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentId": [],
"_id": "65253fe3703d7c40db990f0d",
"ownerName": "Mr. Chetan O. Jhunjhunwala, Sumitra O. Jhunjhunwala & Omprakash S.Jhunjhunwala",
"ownerPhoneNo": "8108003330",
"appAddress": "flat b /705 bldg no 5/6 girnar apt padmavati nagar Bhayandar ",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "21/02/2006",
      "from": {
        "value": "Developers",
        "label": "Developers"
      },
      "Developers": "M/s. Sudarshan Developers ",
      "to": {
        "value": "Purchasers",
        "label": "Purchasers"
      },
      "Purchasers": "Mr. Chetan O. Jhunjhunwala, Sumitra O. Jhunjhunwala & Omprakash S.Jhunjhunwala",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "1308 / 2006"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "942994",
    "path": "cases/65253fe3703d7c40db990f0d/document_1696939922968_31075.pdf",
    "fileName": "document_1696939922968_31075.pdf"
  },

```

```
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "23/06/2005",
    "nameOfApprovingAuthority": {
      "value": "Mira_Bhayander_Municipal_Corporation",
      "label": "Mira Bhayander Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "MB / MNP / NR / 664 / 2005 - 06"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1697182482413_488845.pdf",
  "path": "cases/65253fe3703d7c40db990f0d/
document_1697182482413_488845.pdf",
  "id": "972039",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Fri Oct 13 2023 13:04:42 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "04/05/2009",
    "nameOfApprovingAuthority": {
      "value": "Mira_Bhayander_Municipal_Corporation",
      "label": "Mira Bhayander Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "MB / MNP / NR / 2956 / 09 - 10"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1697193428655_786700.pdf",
```

```
"path": "cases/65253fe3703d7c40db990f0d/
document_1697193428655_786700.pdf",
  "id": "387847",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Fri Oct 13 2023 16:07:08 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "004334",
"createdBy": "627219d6afd7d55eddedd283",
"caseHistory": [
  {
    "id": "859216",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Oct 10 2023 17:43:23 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Chetan O. Jhunjhunwala, Sumitra O. Jhunjhunwala & Omprakash
S.Jhunjhunwala",
    "phone": "8108003330",
    "ownershipShare": "",
    "email": "",
    "id": "387007"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "265444",
    "name": "Living Room",
    "length": "15.33",
    "length1": "15",
    "length2": "4",
    "width": "9.50",
    "width1": "9",
    "width2": "6",
    "totalArea": "145.67",
    "images": [],
    "extraAreas": [],
  }
]
```

```
"finalArea": "145.67"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Bedroom",
  "length": "7.00",
  "length1": "7",
  "length2": "00",
  "width": "10.00",
  "width1": "10",
  "width2": "00",
  "totalArea": "70.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "70.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Passage",
  "length": "13.58",
  "length1": "13",
  "length2": "7",
  "width": "2.83",
  "width1": "2",
  "width2": "10",
  "totalArea": "38.49",
  "images": [],
  "extraAreas": [],
  "finalArea": "38.49"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Bedroom",
  "length": "10.17",
```

```
"length1": "10",
"length2": "2",
"width": "10.17",
"width1": "10",
"width2": "2",
"totalArea": "103.36",
"images": [],
"finalArea": "103.36",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Bedroom",
  "length": "12.67",
  "length1": "12",
  "length2": "8",
  "width": "10.42",
  "width1": "10",
  "width2": "5",
  "totalArea": "131.94",
  "images": [],
  "extraAreas": [],
  "finalArea": "131.94"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Toilet",
  "length": "5.25",
  "length1": "5",
  "length2": "3",
  "width": "4.42",
  "width1": "4",
  "width2": "5",
  "totalArea": "23.19",
  "images": [],
  "extraAreas": [],
  "finalArea": "23.19"
},
}
```

```
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Toilet",
  "length": "4.17",
  "length1": "4",
  "length2": "2",
  "width": "2.92",
  "width1": "2",
  "width2": "11",
  "totalArea": "12.15",
  "images": [],
  "extraAreas": [],
  "finalArea": "12.15"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Toilet",
  "length": "7.33",
  "length1": "7",
  "length2": "4",
  "width": "4.92",
  "width1": "4",
  "width2": "11",
  "totalArea": "36.06",
  "images": [],
  "extraAreas": [],
  "finalArea": "36.06"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
```



```
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "selectAreaTypeDocument": "Saleable",
  "squareMeterArea": "78.97",
  "totalAreaDocument": "850",
  "docBuiltpPercentage": "",
  "docFinalBUILTUp": "0.00",
  "docFinalBUILTUpSquareMeter": "0.00",
  "docSaleablePercentage": "",
  "docFinalSaleable": "0.00",
  "docFinalSaleableSquareMeter": "0.00",
  "id": "769783"
}
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "65290980d040066d2c57afc1",
    "property": "Residential Flat",
    "area": "711",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "Housing.Com",
    "expectedPrice": "12000000",
    "expectedRate": "16877.64",
    "builtUpExpectedRate": "14064.70",
    "image": "cases/65253fe3703d7c40db990f0d/
indicator_1697183811064_Image.png",
    "squareMeter": "66.05",
    "id": "621052"
  },
  {
    "printlnReport": true,
    "_id": "65290980d040066d2c57afc2",
    "property": "Residential Flat",
    "area": "690",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "Housing.Com",
    "expectedPrice": "12800000",
```

```
    "expectedRate": "18550.72",
    "builtUpExpectedRate": "15458.94",
    "image": "cases/65253fe3703d7c40db990f0d/
indicator_1697183865308_Image.png",
    "squareMeter": "64.10",
    "id": "778012"
  }
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652767bcf29c604408186042",
    "name":
"externallmg_1697081276243_IMG_20231011_150750_copy_1600x1200.jpg",
    "path": "cases/65253fe3703d7c40db990f0d/
externallmg_1697081276243_IMG_20231011_150750_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652767bcf29c604408186043",
    "name":
"externallmg_1697081276253_IMG_20231011_150757_copy_1600x1200.jpg",
    "path": "cases/65253fe3703d7c40db990f0d/
externallmg_1697081276253_IMG_20231011_150757_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652767bcf29c604408186044",
    "name":
"externallmg_1697081276273_IMG_20231011_150812_copy_1600x1200.jpg",
    "path": "cases/65253fe3703d7c40db990f0d/
externallmg_1697081276273_IMG_20231011_150812_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652767bcf29c604408186045",
    "name":
"externallmg_1697081276279_IMG_20231011_150815_copy_1600x1200.jpg",
    "path": "cases/65253fe3703d7c40db990f0d/
externallmg_1697081276279_IMG_20231011_150815_copy_1600x1200.jpg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652767bcf29c604408186046",
    "name":
"externallmg_1697081276285_IMG_20231011_152109_copy_900x1200.jpg",
    "path": "cases/65253fe3703d7c40db990f0d/
externallmg_1697081276285_IMG_20231011_152109_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652767bcf29c604408186047",
    "name":
"externallmg_1697081276298_IMG_20231011_152227_copy_900x1200.jpg",
    "path": "cases/65253fe3703d7c40db990f0d/
externallmg_1697081276298_IMG_20231011_152227_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652767bcf29c604408186048",
    "name":
"externallmg_1697081276311_IMG_20231011_152322_copy_901x1200.jpg",
    "path": "cases/65253fe3703d7c40db990f0d/
externallmg_1697081276311_IMG_20231011_152322_copy_901x1200.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652767bcf29c604408186049",
    "name":
"externallmg_1697081276330_IMG_20231011_152330_copy_900x1200.jpg",
    "path": "cases/65253fe3703d7c40db990f0d/
externallmg_1697081276330_IMG_20231011_152330_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652767bcf29c60440818604a",
```

```
    "name":  
    "externallmg_1697081276347_IMG_20231011_152331_copy_900x1200.jpg",  
    "path": "cases/65253fe3703d7c40db990f0d/  
externallmg_1697081276347_IMG_20231011_152331_copy_900x1200.jpg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "652767bcf29c60440818604b",  
    "name":  
    "externallmg_1697081276363_IMG_20231011_152334_copy_900x1200.jpg",  
    "path": "cases/65253fe3703d7c40db990f0d/  
externallmg_1697081276363_IMG_20231011_152334_copy_900x1200.jpg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "652767bcf29c60440818604c",  
    "name":  
    "externallmg_1697081276375_IMG_20231011_150714_copy_1600x1200.jpg",  
    "path": "cases/65253fe3703d7c40db990f0d/  
externallmg_1697081276375_IMG_20231011_150714_copy_1600x1200.jpg",  
    "orientation": "landscape"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "652767cef29c604408186098",  
    "name":  
    "externallmg_1697081294686_IMG_20231011_150717_copy_1600x1200.jpg",  
    "path": "cases/65253fe3703d7c40db990f0d/  
externallmg_1697081294686_IMG_20231011_150717_copy_1600x1200.jpg",  
    "orientation": "landscape"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "652767cef29c604408186099",  
    "name":  
    "externallmg_1697081294694_IMG_20231011_150721_copy_1600x1200.jpg",  
    "path": "cases/65253fe3703d7c40db990f0d/  
externallmg_1697081294694_IMG_20231011_150721_copy_1600x1200.jpg",  
    "orientation": "landscape"  
  },  
  }
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652767cef29c60440818609a",
  "name":
"externallmg_1697081294700_IMG_20231011_150722_copy_1600x1200.jpg",
  "path": "cases/65253fe3703d7c40db990f0d/
externallmg_1697081294700_IMG_20231011_150722_copy_1600x1200.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652767cef29c60440818609b",
  "name":
"externallmg_1697081294708_IMG_20231011_150728_copy_1600x1200.jpg",
  "path": "cases/65253fe3703d7c40db990f0d/
externallmg_1697081294708_IMG_20231011_150728_copy_1600x1200.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652767cef29c60440818609c",
  "name":
"externallmg_1697081294714_IMG_20231011_150730_copy_1600x1200.jpg",
  "path": "cases/65253fe3703d7c40db990f0d/
externallmg_1697081294714_IMG_20231011_150730_copy_1600x1200.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652767cef29c60440818609d",
  "name":
"externallmg_1697081294718_IMG_20231011_150734_copy_900x1200.jpg",
  "path": "cases/65253fe3703d7c40db990f0d/
externallmg_1697081294718_IMG_20231011_150734_copy_900x1200.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652767cef29c60440818609e",
  "name":
"externallmg_1697081294729_IMG_20231011_150751_copy_1600x1200.jpg",
```

```
    "path": "cases/65253fe3703d7c40db990f0d/
externallmg_1697081294729_IMG_20231011_150751_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652767cef29c60440818609f",
    "name":
"externallmg_1697081294736_IMG_20231011_150759_copy_1600x1200.jpg",
    "path": "cases/65253fe3703d7c40db990f0d/
externallmg_1697081294736_IMG_20231011_150759_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652767cef29c6044081860a0",
    "name":
"externallmg_1697081294742_IMG_20231011_150802_copy_1600x1200.jpg",
    "path": "cases/65253fe3703d7c40db990f0d/
externallmg_1697081294742_IMG_20231011_150802_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652767cef29c6044081860a1",
    "name":
"externallmg_1697081294748_IMG_20231011_150806_copy_1600x1200.jpg",
    "path": "cases/65253fe3703d7c40db990f0d/
externallmg_1697081294748_IMG_20231011_150806_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652767cef29c6044081860a2",
    "name":
"externallmg_1697081294755_IMG_20231011_152124_copy_900x1200.jpg",
    "path": "cases/65253fe3703d7c40db990f0d/
externallmg_1697081294755_IMG_20231011_152124_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "652767cef29c6044081860a3",
  "name":
"externallmg_1697081294767_IMG_20231011_152128_copy_1600x1200.jpg",
  "path": "cases/65253fe3703d7c40db990f0d/
externallmg_1697081294767_IMG_20231011_152128_copy_1600x1200.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652767cef29c6044081860a4",
  "name":
"externallmg_1697081294773_IMG_20231011_152300_copy_1600x1200.jpg",
  "path": "cases/65253fe3703d7c40db990f0d/
externallmg_1697081294773_IMG_20231011_152300_copy_1600x1200.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652767cef29c6044081860a5",
  "name":
"externallmg_1697081294778_IMG_20231011_152302_copy_1600x1200.jpg",
  "path": "cases/65253fe3703d7c40db990f0d/
externallmg_1697081294778_IMG_20231011_152302_copy_1600x1200.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652767cef29c6044081860a6",
  "name":
"externallmg_1697081294782_IMG_20231011_152306_copy_1600x1200.jpg",
  "path": "cases/65253fe3703d7c40db990f0d/
externallmg_1697081294782_IMG_20231011_152306_copy_1600x1200.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652767cef29c6044081860a7",
  "name":
"externallmg_1697081294786_IMG_20231011_152308_copy_1600x1200.jpg",
  "path": "cases/65253fe3703d7c40db990f0d/
externallmg_1697081294786_IMG_20231011_152308_copy_1600x1200.jpg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652767cef29c6044081860a8",
    "name":
"externallmg_1697081294791_IMG_20231011_152336_copy_900x1200.jpg",
    "path": "cases/65253fe3703d7c40db990f0d/
externallmg_1697081294791_IMG_20231011_152336_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652767cef29c6044081860a9",
    "name":
"externallmg_1697081294807_IMG_20231011_223933_copy_900x1200.jpg",
    "path": "cases/65253fe3703d7c40db990f0d/
externallmg_1697081294807_IMG_20231011_223933_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652767cef29c6044081860aa",
    "name":
"externallmg_1697081294822_IMG_20231011_224005_copy_900x1200.jpg",
    "path": "cases/65253fe3703d7c40db990f0d/
externallmg_1697081294822_IMG_20231011_224005_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652767cef29c6044081860ab",
    "name":
"externallmg_1697081294835_IMG_20231011_224008_copy_1600x1200.jpg",
    "path": "cases/65253fe3703d7c40db990f0d/
externallmg_1697081294835_IMG_20231011_224008_copy_1600x1200.jpg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
```



```
    "originalname": "Calculation Sheet.xlsx",
    "filename": "1697188241870_Calculation_Sheet.xlsx",
    "path": "cases/65253fe3703d7c40db990f0d/
processingDocuments/1697188241870_Calculation_Sheet.xlsx",
    "size": "502372",
    "createdAt": "Fri Oct 13 2023 14:40:42 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  },
  {
    "originalname": "chetan zunzunwala (1).pdf",
    "filename": "1697188241880_chetan_zunzunwala_1.pdf",
    "path": "cases/65253fe3703d7c40db990f0d/
processingDocuments/1697188241880_chetan_zunzunwala_1.pdf",
    "size": "3866114",
    "createdAt": "Fri Oct 13 2023 14:40:42 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  },
  {
    "originalname": "chetan zunzunwala ifb vasai (1).pdf",
    "filename": "1697188241977_chetan_zunzunwala_ifb_vasai_1.pdf",
    "path": "cases/65253fe3703d7c40db990f0d/
processingDocuments/1697188241977_chetan_zunzunwala_ifb_vasai_1.pdf",
    "size": "9409328",
    "createdAt": "Fri Oct 13 2023 14:40:42 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  },
  {
    "originalname": "Summary Sheet.xlsx",
    "filename": "1697188242271_Summary_Sheet.xlsx",
    "path": "cases/65253fe3703d7c40db990f0d/
processingDocuments/1697188242271_Summary_Sheet.xlsx",
    "size": "2157713",
    "createdAt": "Fri Oct 13 2023 14:40:42 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  }
],
"remarks": [
  {
    "createdBy": {
      "_id": "64cde526dc9f3034f3fefa49",
      "role": "FRONTDESK",
      "firstName": "Rashmi",
      "lastName": "Jadhav",
      "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
    },
  },
]
```

```
"workType": "RATE_VERIFY",
"display": true,
"status": true,
"_id": "652781b3f29c60440818b036",
"note": "Pending for approved plan and OC",
"taskId": "65254141703d7c40db991b16",
"createdAt": "2023-10-12T05:18:43.080Z"
}
],
"createdAt": "2023-10-10T12:13:23.544Z",
"updatedAt": "2023-10-13T12:53:54.601Z",
"__v": 0,
"invoiceId": "65253fe4703d7c40db990f28",
"fullAddress": "Residential Flat No. 705, 7th Floor, Building No 5/6, Wing - B, Om
Girnar Co-Op. Hsg. Soc. Ltd., , 251, Padmavati Nagar, 150 Feet Road, Village -
Bhayander, Taluka - Thane, District - Thane, Bhayander (West), PIN - 401 101, State -
Maharashtra, Country - India",
"updatedBy": "64cde526dc9f3034f3fefa49",
"addressForMap": "",
"caseReferredBy": "627219d6afd7d55eddedd283",
"contactPersonName": "Mrs. Minu Chetan Jhunhunwala",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner's Wife",
"siteVisitContactNo": "8108003330",
"briefDescOfProperty": "3 Bedroom + Living Room + Passage + 3 Toilet",
"carpetTotal": "560.8599999999999",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "616.95",
"finalCarpetArea": "560.86",
"finalSalableArea": "678.64",
"salablePercentage": "10",
"toBeAdded": "",
"buildingServicesRate": "2500",
"finalAreaType": "Saleable Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalValuationAreaString": "Saleable Area in Sq. Ft. = 850.00",
"flatRate": "11500",
"landOtherRate": "9000",
```

```

"finalSaleablePercentage": "",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Fri Oct 13 2023 17:32:14 GMT+0530 (India Standard Time)",
"siteVisitDate": "2023-10-11",
"extendOfSiteRemark": "",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00",
"shopDetails": {
  "typeOfShops": {
    "label": "",
    "value": ""
  },
  "roadFacing": false,
  "mall": false
},
"siteMeasurementRemark": ""
}

```

Name	Length	Width	Total
Composition :			
Living Room	15'4"	9'6"	145.67
Bedroom	7'00"	10'00"	70.00
Passage	13'7"	2'10"	38.49
Bedroom	10'2"	10'2"	103.36

Bedroom	12'8"	10'5"	131.94
Toilet	5'3"	4'5"	23.19
Toilet	4'2"	2'11"	12.15
Toilet	7'4"	4'11"	36.06
Other Composition :			