

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856bb41"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b9423130c",
    "firstName": "Sanjaykumar ",
    "email": "1thane.navimumbaii@bankofindia.co.in",
    "mobileNo": "-",
    "workMobileNo": "9969207619",
    "lastName": "SHrivastav"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "6418456a96b58848585f8cb2",
"name": "Thane",
"email": "thane@vastukala.com",
"phone": "1234567890",
"address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
"city": "Thane",
"shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180a",
  "type": "BANK",
  "name": "Bank of India",
  "displayName": "Bank of India",
  "initial": "BOI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856bb41",
  "branchCode": "000082",
  "type": "BRANCH",
  "name": "Thane Main Branch",
  "email": "thane.navimumbai@bankofindia.co.in",
  "mobileNo": "02225332942",
  "alternateMobileNo": "",
  "address": "1st Floor, Bank of India Building, Shivajipath, Opp. M H High School,
Thane (West), Thane - 400601, State - Maharashtra, Country - India.\n",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e2f4b16576061dae469446",
  "zoneName": "Navi Mumbai Zone"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "64abdb2806d6ec174986d16b",
  "role": "PICKUPPERSON",
  "firstName": "Sahadu",
  "email": "thoratsahadu8679@gmail.com",
  "lastName": "Thorat",
  "mobileNo": "9422389642",
  "shortName": "ST",
  "workWithDocumentMaker": ""
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62ea09ea4e679b264caf07d7",
  "role": "SITEENGINEER",
  "firstName": "Suraj",
  "email": "suraj@vastukala.org",
  "lastName": "Zore",
  "mobileNo": "8652448654",
  "designation": "",
  "shortName": "SZ",
  "workWithDocumentMaker": "60092304a16fab0f2af9b0c2",
  "profilePhoto": "users/62ea09ea4e679b264caf07d7/
profilePhoto_1685629394240_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordinatiion",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "MAKER",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
  "mobileNo": "9821518537",
```

```
"designation": "",
"shortName": "PS",
"workWithDocumentMaker": "",
"profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": {
  "_id": "64cde526dc9f3034f3fefa49",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg",
  "firstName": "Rashmi",
  "lastName": "Jadhav",
  "shortName": "RJ",
  "email": "rashmijadhav14feb@gmail.com",
  "designation": "Back Office Coordinatiion",
  "mobileNo": "7738144625",
  "role": "FRONTDESK",
  "type": "EMPLOYEE",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
    {
      "title": {
```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.207202398247755",
  "longitude": "72.9833014355822"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-16",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-16",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-14",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-14",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  }
}
```

```
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Majiwade",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "3",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Thane (West)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
```

```
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Shubh Laxmi Niwas Co-Op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Koliwada Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
```



```
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Rabodi Koliwada, Second Rabodi",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
```

```
"value": "300, 301, 256",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "A-11",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
```

```
"status": false,
"name": "Police Station(P.S)",
"key": "policeStation",
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 400 601",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_door_with_safety_door",
    "label": "Teak Wood Door frame with Solid door with safety door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
```

```
"value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
  "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
},
"finishing": {
  "value": "Cement_Plastering_with_POP_false_Ceiling",
  "label": "Cement Plastering with POP false Ceiling"
}
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Grampanchayat_Majiwade",
    "label": "Grampanchayat Majiwade"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Indian Overseas Bank Officer's Quarters Building No.5",
    "west": "Koliwada Road",
    "south": "Krishna Tower",
    "east": "Wing - B"
  },
  "asPerDocumentAgreement": {
    "north": "Details not available",
    "west": "Details not available",
    "south": "Details not available",
    "east": "Details not available"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "Staircase",
      "east": "Flat No. 10",
```

```
    "south": "Walls",
    "west": "Flat No. 12"
  },
  "asPerDocument": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of Approved Building plans and occupancy
certificate were not provided and not verified.",
"approvePlanVerified": "",
"empanelledOfApprovePlan": ""
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "36",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "8100",
  "depreciatedBuildingRate": "1600"
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "144500",
  "landRate": "56200",
  "igrImage": "cases/6526826f703d7c40db9ae38e/igr_1697522478869_Image.png",
  "squareMeterGuideLineRate": "122825.00",
  "squareFeetGuideLineRate": "11411.00"
},
"igrFinalRate": {
  "depreciationPercentage": "76",
  "rate": "9925.00",
  "squareFeetGuideLineRate": "9925.00",
  "squareMeterGuideLineRate": "106835.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Middle_Class",
    "label": "Middle Class"
  },
  "propertyTypeOfUseList": {
```

```
"value": "Residential_Purpose",
"label": "Residential Purpose"
},
"propertyOccupiedByList": {
  "value": "Owner_Occupied",
  "label": "Owner Occupied"
},
"monthlyRent": "6,500.00",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Electricity Bill Consumer No. 000022040723",
"meterCardHolderName": "Mrs. Kavita Kamlakar Kamat",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per TMC norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  }
},
"anyFavouringForExtraPotentialValue": "Located in developed area",
"negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  }
},
"waterTank": {
  "value": "MunicipalWaterSupply",
  "label": "Municipal Water Supply"
},
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": "Open Parking",
"constructionWorkStatus": {
  "value": "Completed",
```

```
"label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "1999",
  "fullDate": "1/1/1999"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
```

```
"label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenancelssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_site_information",
  "label": "As per site information"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "24",
"totalLifeBuilding": "60",
"estimatedAge": "36",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "4",
```



```
"flatFloorNo": "3",
"noOfLifts": "",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "areaType": "Built Up",
  "area": "385.00",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area as per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/6526826f703d7c40db9ae38e/
routeMap_1697539414512_Image.png",
    "routeLat": "19.207038",
    "routeLng": "72.983291",
    "stationName": "Thane",
    "routeDistance": "3.1 KM"
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "25m96d",
      "name": "25m96d",
      "image": "cases/6526826f703d7c40db9ae38e/
routeMap_1697539347265_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
```

```
"wardrobesQty": "0",
"showcasesQty": "0",
"showcasesRate": "0",
"totalshowcasesRate": "0",
"kitchenArrangementsQty": "0",
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "3118500.00",
"finalValue": "3118500.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": true
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "3821125.00",
  "selectedBuildUpValue": "385.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "652cbce0316e1359cebba3b7",
      "name": "externalimg_r_1697430730303_1697430661972_image_14.jpg",
      "path": "cases/6526826f703d7c40db9ae38e/
externalimg_r_1697430730303_1697430661972_image_14.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "652cbce0316e1359cebba3ad",
      "name": "externalimg_r_1697430653727_1697430661972_image_2.jpg",
      "path": "cases/6526826f703d7c40db9ae38e/
externalimg_r_1697430653727_1697430661972_image_2.jpg",
```

```
    "orientation": "landscape"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "652cbce0316e1359cebba3b7",
    "name": "externallmg_r_1697430730303_1697430661972_image_14.jpg",
    "path": "cases/6526826f703d7c40db9ae38e/
externallmg_r_1697430730303_1697430661972_image_14.jpg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "652cbce0316e1359cebba3b6",
    "name": "externallmg_r_1697430717803_1697430661972_image_12.jpg",
    "path": "cases/6526826f703d7c40db9ae38e/
externallmg_r_1697430717803_1697430661972_image_12.jpg",
    "orientation": "portrait"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "652cbce0316e1359cebba3b5",
    "name": "Living Room",
    "path": "cases/6526826f703d7c40db9ae38e/
externallmg_r_1697430713362_1697430661972_image_11.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "652cbce0316e1359cebba3b3",
    "name": "Living Room",
    "path": "cases/6526826f703d7c40db9ae38e/
externallmg_r_1697430704471_1697430661972_image_9.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "652cbce0316e1359cebba3ae",
    "name": "Bedroom",
    "path": "cases/6526826f703d7c40db9ae38e/
externallmg_r_1697430671834_1697430661972_image_4.jpg",
```

```
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "652cbce0316e1359cebba3af",
    "name": "Kitchen",
    "path": "cases/6526826f703d7c40db9ae38e/
externallmg_r_1697430695527_1697430661972_image_6.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "652cbce0316e1359cebba3b2",
    "name": "Living Room",
    "path": "cases/6526826f703d7c40db9ae38e/
externallmg_r_1697430701695_1697430661972_image_8.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "652cbce0316e1359cebba3b9",
    "name": "Living Room",
    "path": "cases/6526826f703d7c40db9ae38e/
externallmg_r_1697430736746_1697430661972_image_15.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "652cbce0316e1359cebba3b8",
    "name": "Living Room",
    "path": "cases/6526826f703d7c40db9ae38e/
externallmg_r_1697430723672_1697430661972_image_13.jpg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "10417",
    "max": "11818"
  },
  "builtUpRateRange": {
    "min": "9849",
    "max": "10417"
  }
}
},
```

```
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
    "title": "Interior Decorations",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```



```
"status": true,
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
```

```
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "385.00",
"empanelmentNo": [
  "NMZ/CrMD/SK//2019-20-113"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentId": [],
"_id": "6526826f703d7c40db9ae38e",
"ownerName": "Mr. Sushant Ashok Shinde & Mrs. Snehal Sushant Shinde (Before
marriage Ms. Snehal Avinash Salunkhe)",
"ownerPhoneNo": "7506942535",
"fullAddress": "Residential Flat No. A-11, 3rd Floor, Wing - A, Shubh Laxmi Niwas Co-
Op. Hsg. Soc. Ltd., Rabodi Koliwada, Second Rabodi, Koliwada Road, Village -
Majiwade, Taluka - Thane, District - Thane, Thane (West), PIN Code - 400 601, State -
Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "30/10/2017",
      "from": {
        "value": "Seller",
```

```
    "label": "Seller"
  },
  "Seller": "Mrs. Kavita Kamlakar Kamat & Mr. Kamlakar Indirakant Kamat",
  "to": {
    "value": "purchaser",
    "label": "purchaser"
  },
  "purchaser": "Mr. Sushant Ashok Shinde & Mrs. Snehal Sushant Shinde (Before
marriage Ms. Snehal Avinash Salunkhe)",
  "number": {
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "7394/2017"
},
"isHardCopy": false,
"displayStatus": true,
"id": "800679",
"path": "cases/6526826f703d7c40db9ae38e/
document_1697022523564_BOM_Main_br_Shinde.pdf",
"fileName": "document_1697022523564_BOM_Main_br_Shinde.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "30/09/1982",
    "remark": "issued by Grampanchayat Majiwade",
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "1183 / 82"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1697537371582_123162.pdf",
"path": "cases/6526826f703d7c40db9ae38e/
document_1697537371582_123162.pdf",
"id": "976409",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Tue Oct 17 2023 15:39:31 GMT+0530 (India Standard Time)"
},
{
```

```
"documentType": {
  "value": "60ae1254aa6d152c1801b325",
  "label": "Society NOC Letter "
},
"inputs": {
  "documentDate": "12/11/2017",
  "remark": "issued by Shubh Laxmi Niwas Co-Op. Hsg. Soc. Ltd."
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1697537657816_209425.pdf",
"path": "cases/6526826f703d7c40db9ae38e/
document_1697537657816_209425.pdf",
"id": "531387",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Tue Oct 17 2023 15:44:17 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1248aa6d152c1801b2ee",
    "label": "Previous Valuation Report"
  },
  "inputs": {
    "documentDate": "20/11/2017",
    "remark": "issued by Deepti & Associates "
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1697537970288_69508.pdf",
  "path": "cases/6526826f703d7c40db9ae38e/
document_1697537970288_69508.pdf",
  "id": "541820",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Tue Oct 17 2023 15:49:30 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "004356",
"createdBy": "6430f74691d7c62df11f3f15",
"caseHistory": [
  {
    "id": "768861",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Oct 11 2023 16:39:35 GMT+0530 (India Standard Time)"
  }
],
```

```
"owners": [
  {
    "name": "Mr. Sushant Ashok Shinde & Mrs. Snehal Sushant Shinde (Before
marriage Ms. Snehal Avinash Salunkhe)",
    "phone": "7506942535",
    "ownershipShare": "",
    "email": "",
    "id": "330019"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "name": "Living Room",
    "length": "",
    "length1": "21",
    "length2": "0",
    "width": "",
    "width1": "5",
    "width2": "0",
    "totalArea": "105.00",
    "images": [],
    "finalArea": "105.00",
    "extraAreas": []
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "name": "Cupboard",
    "length": "3.00",
    "length1": "3",
    "length2": "00",
    "width": "6.00",
    "width1": "6",
    "width2": "00",
    "totalArea": "18.00",
    "images": [],
```

```
"extraAreas": [],
"finalArea": "18.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Kitchen",
  "length": "9.00",
  "length1": "9",
  "length2": "00",
  "width": "6.00",
  "width1": "6",
  "width2": "00",
  "totalArea": "54.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "54.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "WC",
  "length": "5.00",
  "length1": "5",
  "length2": "00",
  "width": "2.00",
  "width1": "2",
  "width2": "00",
  "totalArea": "10.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "10.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Bathroom",
```

```
"length": "2.00",
"length1": "2",
"length2": "0",
"width": "7.00",
"width1": "7",
"width2": "0",
"totalArea": "14.00",
"images": [],
"finalArea": "14.00",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Passage",
  "length": "5.00",
  "length1": "5",
  "length2": "00",
  "width": "9.00",
  "width1": "9",
  "width2": "00",
  "totalArea": "45.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "45.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Bedroom",
  "length": "13.00",
  "length1": "13",
  "length2": "00",
  "width": "6.00",
  "width1": "6",
  "width2": "00",
  "totalArea": "78.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "78.00"
```

```
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "802465",
    "selectAreaTypeDocument": "Built_Up",
    "totalAreaDocument": "385",
    "squareMeterArea": "35.77",
    "docFinalBuiltUp": "0.00",
    "docFinalBuiltUpSquareMeter": "0.00",
    "docBuiltupPercentage": "",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "652e2344316e1359cebe6f18",
    "property": "Residential Flat",
    "area": "480",
    "builtUpPercentage": "0",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Built_Up",
    "source": "Nobroker.com",
    "expectedPrice": "5000000",
    "expectedRate": "10416.67",
    "builtUpExpectedRate": "0.00",
    "image": "cases/6526826f703d7c40db9ae38e/
indicator_1697522262915_Image.png",
    "squareMeter": "44.59",
    "id": "298677"
  },

```



```
{
  "printlnReport": true,
  "_id": "652e2344316e1359cebe6f19",
  "property": "Residential Flat",
  "area": "550",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "https://www.99acres.com/",
  "expectedPrice": "6500000",
  "expectedRate": "11818.18",
  "builtUpExpectedRate": "9848.48",
  "image": "cases/6526826f703d7c40db9ae38e/
indicator_1697522317700_Image.png",
  "squareMeter": "51.10",
  "id": "748313"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652cbce0316e1359cebba3aa",
    "name": "externalImg_r_1697430656801_1697430661972_image_3.jpg",
    "path": "cases/6526826f703d7c40db9ae38e/
externalImg_r_1697430656801_1697430661972_image_3.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652cbce0316e1359cebba3ab",
    "name": "externalImg_r_1697430651963_1697430661972_image_1.jpg",
    "path": "cases/6526826f703d7c40db9ae38e/
externalImg_r_1697430651963_1697430661972_image_1.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652cbce0316e1359cebba3ac",
    "name": "externalImg_r_1697430647280_1697430661972_image_0.jpg",
    "path": "cases/6526826f703d7c40db9ae38e/
externalImg_r_1697430647280_1697430661972_image_0.jpg",
    "orientation": "portrait"
  }
]
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652cbce0316e1359cebba3ad",
  "name": "externallmg_r_1697430653727_1697430661972_image_2.jpg",
  "path": "cases/6526826f703d7c40db9ae38e/
externallmg_r_1697430653727_1697430661972_image_2.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652cbce0316e1359cebba3ae",
  "name": "externallmg_r_1697430671834_1697430661972_image_4.jpg",
  "path": "cases/6526826f703d7c40db9ae38e/
externallmg_r_1697430671834_1697430661972_image_4.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652cbce0316e1359cebba3af",
  "name": "externallmg_r_1697430695527_1697430661972_image_6.jpg",
  "path": "cases/6526826f703d7c40db9ae38e/
externallmg_r_1697430695527_1697430661972_image_6.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652cbce0316e1359cebba3b0",
  "name": "externallmg_r_1697430689896_1697430661972_image_5.jpg",
  "path": "cases/6526826f703d7c40db9ae38e/
externallmg_r_1697430689896_1697430661972_image_5.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652cbce0316e1359cebba3b1",
  "name": "externallmg_r_1697430698575_1697430661972_image_7.jpg",
  "path": "cases/6526826f703d7c40db9ae38e/
externallmg_r_1697430698575_1697430661972_image_7.jpg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652cbce0316e1359cebba3b2",
  "name": "externallmg_r_1697430701695_1697430661972_image_8.jpg",
  "path": "cases/6526826f703d7c40db9ae38e/
externallmg_r_1697430701695_1697430661972_image_8.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652cbce0316e1359cebba3b3",
  "name": "externallmg_r_1697430704471_1697430661972_image_9.jpg",
  "path": "cases/6526826f703d7c40db9ae38e/
externallmg_r_1697430704471_1697430661972_image_9.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652cbce0316e1359cebba3b4",
  "name": "externallmg_r_1697430709075_1697430661972_image_10.jpg",
  "path": "cases/6526826f703d7c40db9ae38e/
externallmg_r_1697430709075_1697430661972_image_10.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652cbce0316e1359cebba3b5",
  "name": "externallmg_r_1697430713362_1697430661972_image_11.jpg",
  "path": "cases/6526826f703d7c40db9ae38e/
externallmg_r_1697430713362_1697430661972_image_11.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652cbce0316e1359cebba3b6",
  "name": "externallmg_r_1697430717803_1697430661972_image_12.jpg",
  "path": "cases/6526826f703d7c40db9ae38e/
externallmg_r_1697430717803_1697430661972_image_12.jpg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652cbce0316e1359cebba3b7",
    "name": "externallmg_r_1697430730303_1697430661972_image_14.jpg",
    "path": "cases/6526826f703d7c40db9ae38e/
externallmg_r_1697430730303_1697430661972_image_14.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652cbce0316e1359cebba3b8",
    "name": "externallmg_r_1697430723672_1697430661972_image_13.jpg",
    "path": "cases/6526826f703d7c40db9ae38e/
externallmg_r_1697430723672_1697430661972_image_13.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652cbce0316e1359cebba3b9",
    "name": "externallmg_r_1697430736746_1697430661972_image_15.jpg",
    "path": "cases/6526826f703d7c40db9ae38e/
externallmg_r_1697430736746_1697430661972_image_15.jpg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "652cbce0316e1359cebba3ba",
    "name": "externallmg_r_1697430622996_1697430643731_image_2.png",
    "path": "cases/6526826f703d7c40db9ae38e/
externallmg_r_1697430622996_1697430643731_image_2.png",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "652cbce0316e1359cebba3bb",
    "name": "externallmg_r_1697430620286_1697430643731_image_1.jpg",
    "path": "cases/6526826f703d7c40db9ae38e/
externallmg_r_1697430620286_1697430643731_image_1.jpg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
```

```
"status": false,
  "_id": "652cbce0316e1359cebba3bc",
  "name": "externalImg_r_1697430615858_1697430643731_image_0.jpg",
  "path": "cases/6526826f703d7c40db9ae38e/
externalImg_r_1697430615858_1697430643731_image_0.jpg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Calculation Sheet.xlsx",
    "filename": "1697522583220_Calculation_Sheet.xlsx",
    "path": "cases/6526826f703d7c40db9ae38e/
processingDocuments/1697522583220_Calculation_Sheet.xlsx",
    "size": "16308",
    "createdAt": "Tue Oct 17 2023 11:33:03 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  },
  {
    "originalname": "Summary Sheet.xlsx",
    "filename": "1697522583221_Summary_Sheet.xlsx",
    "path": "cases/6526826f703d7c40db9ae38e/
processingDocuments/1697522583221_Summary_Sheet.xlsx",
    "size": "4531184",
    "createdAt": "Tue Oct 17 2023 11:33:03 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  }
],
"remarks": [],
"createdAt": "2023-10-11T11:09:35.480Z",
"updatedAt": "2023-10-17T12:19:39.146Z",
"__v": 0,
"invoiceId": "65268270703d7c40db9ae3ad",
"updatedBy": "64cde526dc9f3034f3fefa49",
"addressForMap": "",
"caseReferredBy": "64abdb2806d6ec174986d16b",
"contactPersonName": "Mrs. Snehal Sushant Shinde",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "7506942536",
"siteVisitDate": "2023-10-14",
```

```
"buildingServicesRate": "2500",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 385.00",
"flatRate": "9000",
"landOtherRate": "6500",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Cupboard + WC +
Bathroom + Passage",
"carpetTotal": "324",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "356.40",
"finalCarpetArea": "324.00",
"finalSalableArea": "392.04",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
  "leaseFrom": "",
  "leaseTo": "",
  "remainingLeasePeriod": 0,
  "leaseDate": ""
}
},
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
```

```
},  
"reportGeneratedDate": "Tue Oct 17 2023 17:25:23 GMT+0530 (India Standard Time)"  
}
```

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
Composition :			
Living Room	21'0"	5'0"	105.00
Cupboard	3'00"	6'00"	18.00
Kitchen	9'00"	6'00"	54.00
WC	5'00"	2'00"	10.00
Bathroom	2'0"	7'0"	14.00
Passage	5'00"	9'00"	45.00
Bedroom	13'00"	6'00"	78.00
Other Composition :			