

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63b26511191f7b344b008a1d"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f66be948726cc141b8b",
    "email": "coorddesk.rasmecbhy@sbi.co.in",
    "firstName": "SHASHI RANJAN",
    "mobileNo": "",
    "workMobileNo": "9867369914",
    "lastName": "RANJAN"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "3400000",
    "discussWithPerson": "SHASHI RANJAN",
    "expectedFees": 1700,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63b26511191f7b344b008a1d",
  "name": "RASMECCC BHAYANDAR",
  "branchCode": "",
  "mobileNo": "022-28149108",
  "alternateMobileNo": "",
  "email": "Coorddesk.rasmecbhy@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "RASMECCC Bhayandar Branch\nUnit No. 101, 102, 103B, 1st Floor, IT
Landmark Building, 150ft. Road, Near Hotel Shree Nidhi, \nOpp. Maxus Mall,
Bhayander (West), Thane – 401 101, \nState – Maharashtra, Country – India."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
  "_id": "627219d6afd7d55eddedd283",
  "role": "PICKUPPERSON",
  "firstName": "Mangesh ",
  "email": "mangeshpalande17@gmail.com",
  "lastName": "Palande",
  "mobileNo": "9833030550",
  "shortName": "MP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/627219d6afd7d55eddedd283/
profilePhoto_1668055836118_WhatsApp_Image_20221110_at_101725_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "6401b61f0e28255fb44e636a",
  "role": "SITEENGINEER",
  "firstName": "Sanket",
  "email": "ksanket7414@yahoo.com",
  "lastName": "Karalkar",
  "mobileNo": "8080582858",
  "designation": "",
  "shortName": "SAK",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f91b6f344e052188ffd1fc",
  "role": "MAKER",
  "firstName": "Jayaraja",
  "email": "jayaraja@vastukala.org",
  "lastName": "Acharya",
  "mobileNo": "9867664219",
  "designation": "",
```

```
    "shortName": "JA",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
  },
  "checker": {
    "type": "EMPLOYEE",
    "_id": "60f915d3f3dd69653a592199",
    "role": "MAKER + RATE VERIFIER + CHEAKER",
    "firstName": "Shobha",
    "email": "shobha@vastukala.org",
    "lastName": "Kuperkar",
    "mobileNo": "9004134140",
    "designation": "",
    "shortName": "SH",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
  },
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "IBBI/RV/07/2018/10366",
          "label": "Registered Valuer"
        }
      ],
      "type": "EMPLOYEE",
      "_id": "5ffe92d27737ca4d986b6453",
      "role": "VALUER",
      "firstName": "Manoj",
      "email": "manoj@vastukala.org",
      "lastName": "Chalikwar",
      "mobileNo": "9819597579",
      "designation": "Registered Valuer",
      "registrationNo": [
        {
          "title": {
            "label": "IBBI"
          },
          "_id": "60af80072ffdf65bcd658651",
          "number": "IBBI/RV/07/2018/10366"
        }
      ],
      {
        "title": {
          "value": "FIIV",
```

```
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.416575938877244",
  "longitude": "72.86229460975501"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.86229460975501,
    19.416575938877244
  ]
}
},
```

```
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-10-12T04:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-10-12T04:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-10-12T04:30:00.000Z",
      "remark": ""
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-12",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
```

```
"name": "Country",
"key": "country",
"value": "India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Gokhivare",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "6",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Palghar",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
}
```

```
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Vasai",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Samary Heights",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Near Gokhivare Talao",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
```



```
"key": "landmark",
"value": "",
"label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "106",
  "label": true
},
"hissaNo": {
  "status": true,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "6",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
}
```

```
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "602",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
```

```
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 401 208",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Vasai (East)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_Frame_With_Flush_Shutters",
    "label": "Teak Wood Door Frame With Flush Shutters"
  },
  "windows": {
    "value": "Proposed_Powder_coated_aluminium_sliding_windows",
    "label": "Proposed Powder coated aluminium sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
```

```
},
"finishing": {
  "value": "Cement_Plastering",
  "label": "Cement Plastering"
}
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Vasai_Virar_City_Municipal_Corporation",
    "label": "Vasai Virar City Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Krishika Sports Turf",
    "west": "Evershine Ext. Road",
    "south": "Punjab National Bank",
    "east": "Gokhivare Talao"
  },
  "asPerDocumentAgreement": {
    "north": "Details not available",
    "west": "Details not available",
    "south": "Details not available",
    "east": "Details not available"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "",
      "west": "",
      "south": "",
      "east": ""
    }
  },
}
```

```
"asPerDocument": {
  "north": "",
  "west": "",
  "south": "",
  "east": ""
},
"isDisplay": false,
"title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As Occupancy Certificate is received it may be assumed
that the construction is as per Sanctioned Plan.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "No"
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "10.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "buildingServicesDepreciatedRate": "273",
  "depreciatedCostOfConstruction": "7727.00",
  "depreciatedBuildingRate": "2327"
},
"igrRate": {
  "propertyName": "Gokhivare",
  "rate": "58000",
  "landRate": "13400",
  "igrImage": "cases/652772fbf29c60440818706b/igr_1697177101355_Image.png",
  "squareMeterGuideLineRate": "60900.00",
  "squareFeetGuideLineRate": "5658.00"
},
"igrFinalRate": {
  "rate": "5349.00",
  "squareMeterGuideLineRate": "57575.00",
  "squareFeetGuideLineRate": "5349.00",
  "depreciationPercentage": "93"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  }
}
```

```
},
"propertyOccupiedByList": {
  "value": "Owner_Occupied",
  "label": "Owner Occupied"
},
"monthlyRent": "8,000",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per VVCMC norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in Developed Area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonry"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Stilt Car Parking Space",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  }
},
```

```
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2016",
  "fullDate": "1/1/2016"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
```

```
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "0",
  "label": "No"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
  "value": "Part_Ground_and_Part_Stilt",
  "label": "Part Ground + Part Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "53",
"ageOfBuilding": "7",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "6",
"flatFloorNo": "6",
"noOfLifts": "1",
```



```
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "areaType": "Built Up",
  "area": "625.20",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/652772fbf29c60440818706b/
routeMap_1697180063191_Image.png",
    "routeLat": "19.401222",
    "routeLng": "72.842611",
    "stationName": "Vasai",
    "routeDistance": "3.7 km"
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "wdbw0i",
      "name": "wdbw0i",
      "image": "cases/652772fbf29c60440818706b/
routeMap_1697179883357_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
```

```
"showcasesRate": "0",
"totalshowcasesRate": "0",
"kitchenArrangementsQty": "0",
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "4025767.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "4025767.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "3344195.00",
  "selectedBuildUpValue": "625.20",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "6528c327d040066d2c56c2bf",
      "name":
"externalImg_1697170215089_WhatsApp_Image_20231012_at_104721_PM.jpeg",
      "path": "cases/652772fbf29c60440818706b/
externalImg_1697170215089_WhatsApp_Image_20231012_at_104721_PM.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "6528c30fd040066d2c56c18d",
      "name":
"externalImg_1697170191629_WhatsApp_Image_20231012_at_104747_PM.jpeg",
      "path": "cases/652772fbf29c60440818706b/
externalImg_1697170191629_WhatsApp_Image_20231012_at_104747_PM.jpeg",
      "orientation": "landscape"
    }
  ]
}
```

```
],
"externalPhotos": [
  {
    "status": false,
    "_id": "6528c327d040066d2c56c2c0",
    "name":
"externallmg_1697170215096_WhatsApp_Image_20231012_at_104722_PM_1.jpeg",
    "path": "cases/652772fbf29c60440818706b/
externallmg_1697170215096_WhatsApp_Image_20231012_at_104722_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6528c327d040066d2c56c2c6",
    "name":
"externallmg_1697170215116_WhatsApp_Image_20231012_at_104728_PM.jpeg",
    "path": "cases/652772fbf29c60440818706b/
externallmg_1697170215116_WhatsApp_Image_20231012_at_104728_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6528c334d040066d2c56c342",
    "name":
"externallmg_1697170228592_WhatsApp_Image_20231012_at_104745_PM.jpeg",
    "path": "cases/652772fbf29c60440818706b/
externallmg_1697170228592_WhatsApp_Image_20231012_at_104745_PM.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "6528c30fd040066d2c56c18a",
    "name": "Living Room",
    "path": "cases/652772fbf29c60440818706b/
externallmg_1697170191619_WhatsApp_Image_20231012_at_104746_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6528c30fd040066d2c56c18b",
    "name": "Living Room",
    "path": "cases/652772fbf29c60440818706b/
externallmg_1697170191623_WhatsApp_Image_20231012_at_104747_PM_1.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6528c30fd040066d2c56c18e",
    "name": "Living Room",
    "path": "cases/652772fbf29c60440818706b/
externallmg_1697170191634_WhatsApp_Image_20231012_at_104748_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6528c30fd040066d2c56c191",
    "name": "Living Room",
    "path": "cases/652772fbf29c60440818706b/
externallmg_1697170191642_WhatsApp_Image_20231012_at_104750_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6528c30fd040066d2c56c194",
    "name": "Living Room",
    "path": "cases/652772fbf29c60440818706b/
externallmg_1697170191657_WhatsApp_Image_20231012_at_104751_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6528c30fd040066d2c56c195",
    "name": "Living Room",
    "path": "cases/652772fbf29c60440818706b/
externallmg_1697170191659_WhatsApp_Image_20231012_at_104752_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6528c30fd040066d2c56c199",
    "name": "Living Room",
    "path": "cases/652772fbf29c60440818706b/
externallmg_1697170191672_WhatsApp_Image_20231012_at_104753_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6528c334d040066d2c56c340",
    "name": "Living Room",
```

```
    "path": "cases/652772fbf29c60440818706b/
externallmg_1697170228588_WhatsApp_Image_20231012_at_104745_PM_2.jpeg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "8059",
    "max": "9745"
  },
  "builtUpRateRange": {
    "min": "6717",
    "max": "8121"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```



```
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "521.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentId": [],
"_id": "652772fbf29c60440818706b",
"ownerName": "Mr. Gowda Ashok Gopal",
"ownerPhoneNo": "7304034170",
```

```
"appAddress": "flat no 602 bldg no 1 samri height gokhivare vasai East ",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "29/03/2017",
      "from": {
        "value": "Builder",
        "label": "Builder"
      },
      "Builder": "M/s. Luiza Homes",
      "to": {
        "value": "Purchaser",
        "label": "Purchaser"
      },
      "Purchaser": "Mr. Gowda Ashok Gopal",
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "2575-2017"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1697181900746_Agreement_for_Sale.pdf",
    "path": "cases/652772fbf29c60440818706b/
document_1697181900746_Agreement_for_Sale.pdf",
    "id": "803744",
    "uploadedBy": "60f91b6f344e052188ffd1fc",
    "createdAt": "Fri Oct 13 2023 12:55:00 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae1247aa6d152c1801b2ea",
      "label": "Commencement Certificate"
    },
    "inputs": {
      "documentDate": "14/07/2015",
      "nameOfApprovingAuthority": {
        "value": "Vasai_Virar_City_Municipal_Corporation",
        "label": "Vasai Virar City Municipal Corporation"
      }
    }
  }
]
```

```
"number": {
  "value": "Document_No",
  "label": "Document No"
},
"Document_No": "VVCMC / TP / RDP / VP-5275 / 102 / 2015-16"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1697181984329_Commencement_Certificate.pdf",
"path": "cases/652772fbf29c60440818706b/
document_1697181984329_Commencement_Certificate.pdf",
"id": "843212",
"uploadedBy": "60f91b6f344e052188ffd1fc",
"createdAt": "Fri Oct 13 2023 12:56:24 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "13/12/2016",
    "nameOfApprovingAuthority": {
      "value": "Vasai_Virar_City_Municipal_Corporation",
      "label": "Vasai Virar City Municipal Corporation"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "VVCMC / TP / OC / VP-5275 / 48 / 2016-17"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1697182039784_Occupancy_Certificate.pdf",
  "path": "cases/652772fbf29c60440818706b/
document_1697182039784_Occupancy_Certificate.pdf",
  "id": "259258",
  "uploadedBy": "60f91b6f344e052188ffd1fc",
  "createdAt": "Fri Oct 13 2023 12:57:19 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "004365",
"createdBy": "627219d6afd7d55eddedd283",
"caseHistory": [
  {
```

```
"id": "583125",
"title": "Create Lead",
"description": "Create Lead",
"datetime": "Thu Oct 12 2023 09:45:55 GMT+0530 (India Standard Time)"
}
],
"owners": [
{
"name": "Mr. Gowda Ashok Gopal",
"phone": "7304034170",
"ownershipShare": "",
"email": "",
"id": "288656"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "780381",
"name": "Living Room",
"length": "10.00",
"length1": "10",
"length2": "00",
"width": "13.75",
"width1": "13",
"width2": "9",
"totalArea": "137.50",
"images": [],
"extraAreas": [],
"finalArea": "137.50"
},
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "1",
"name": "Cupboard",
"length": "4.50",
"length1": "4",
"length2": "6",
```

```
"width": "2.00",
"width1": "2",
"width2": "00",
"totalArea": "9.00",
"images": [],
"extraAreas": [],
"finalArea": "9.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Kitchen",
  "length": "12.00",
  "length1": "12",
  "length2": "00",
  "width": "7.42",
  "width1": "7",
  "width2": "5",
  "totalArea": "89.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "89.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Toilet",
  "length": "4.00",
  "length1": "4",
  "length2": "00",
  "width": "6.00",
  "width1": "6",
  "width2": "00",
  "totalArea": "24.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "24.00"
},
{
  "measurementType": {
```

```
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Passage",
  "length": "",
  "length1": "3",
  "length2": "0",
  "width": "",
  "width1": "6",
  "width2": "8",
  "totalArea": "20.00",
  "images": [],
  "finalArea": "20.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bedroom",
  "length": "9.42",
  "length1": "9",
  "length2": "5",
  "width": "12.33",
  "width1": "12",
  "width2": "4",
  "totalArea": "116.14",
  "images": [],
  "extraAreas": [],
  "finalArea": "116.14"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Toilet",
  "length": "5.00",
  "length1": "5",
  "length2": "00",
  "width": "5.00",
  "width1": "5",
```

```
"width2": "00",
"totalArea": "25.00",
"images": [],
"extraAreas": [],
"finalArea": "25.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Bedroom",
  "length": "9.00",
  "length1": "9",
  "length2": "00",
  "width": "9.42",
  "width1": "9",
  "width2": "5",
  "totalArea": "84.75",
  "images": [],
  "extraAreas": [],
  "finalArea": "84.75"
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "label": "Flowerbed",
      "value": "Flowerbed"
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "4",
    "length1": "4",
    "length2": "0",
    "length": "",
    "width1": "9",
    "width2": "0",
    "width": "",
```



```
"totalArea": "36.00",
"percentageBeforeTotal": "36.00",
"images": [],
"extraAreas": [],
"percentage": "100",
"finalArea": "36"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Flowerbed",
    "value": "Flowerbed"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "length1": "12",
  "length2": "4",
  "length": "",
  "width1": "2",
  "width2": "0",
  "width": "",
  "totalArea": "24.67",
  "percentageBeforeTotal": "24.67",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "24.67"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Dry Balcony Area",
    "value": "Dry_Balcony_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  }
}
```

```
},
  "id": "2",
  "length1": "7",
  "length2": "6",
  "length": "7.50",
  "width1": "2",
  "width2": "00",
  "width": "2.00",
  "totalArea": "15.00",
  "percentageBeforeTotal": "15.00",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "15"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Flowerbed",
    "value": "Flowerbed"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "length1": "10",
  "length2": "0",
  "length": "",
  "width1": "3",
  "width2": "9",
  "width": "",
  "totalArea": "37.50",
  "percentageBeforeTotal": "37.50",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "37.5"
}
],
"externalReport": [],
"documentPerArea": [
  {
```

```
"typeOfDocument": {
  "value": "60af48bf2ffdf65bcd6585fa",
  "label": "Agreement for sale"
},
"docMeasurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "121381",
"selectAreaTypeDocument": "Carpet",
"totalAreaDocument": "521",
"squareMeterArea": "48.4",
"docFinalBuiltUp": "625.2",
"docFinalBuiltUpSquareMeter": "58.08",
"docBuiltupPercentage": "20",
"docSaleablePercentage": "0",
"docFinalSaleable": "0",
"docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "6528de40d040066d2c5722c1",
    "property": "Deep Darshan, Vasai East",
    "area": "304",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "sale_Instance",
    "areaType": "Carpet",
    "floor": "24500000.00",
    "source": "Index_no.2",
    "expectedPrice": "2450000",
    "expectedRate": "8059.21",
    "builtUpExpectedRate": "6716.01",
    "image": "cases/652772fbf29c604440818706b/
indicator_1697176927048_Image.png",
    "squareMeter": "28.24",
    "id": "849540"
  },
  {
    "printlnReport": true,
    "_id": "6528de40d040066d2c5722c2",
    "property": "Madhuban Township, Vasai East",
    "area": "431.00",
```

```
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "Middle",
"source": "Housing.Com",
"expectedPrice": "4200000",
"expectedRate": "9744.78",
"builtUpExpectedRate": "8120.65",
"image": "cases/652772fbf29c60440818706b/
indicator_1697176994121_Image.png",
"squareMeter": "40.04",
"id": "533754"
},
{
  "printInReport": true,
  "_id": "6528de40d040066d2c5722c3",
  "property": "Madhuban Township, Vasai East",
  "area": "467",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "Middle",
  "source": "Housing.Com",
  "expectedPrice": "4189000",
  "expectedRate": "8970.02",
  "builtUpExpectedRate": "7475.02",
  "image": "cases/652772fbf29c60440818706b/
indicator_1697177047134_Image.png",
  "squareMeter": "43.39",
  "id": "667205"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6528c30fd040066d2c56c18a",
    "name":
"externallmg_1697170191619_WhatsApp_Image_20231012_at_104746_PM_2.jpeg",
    "path": "cases/652772fbf29c60440818706b/
externallmg_1697170191619_WhatsApp_Image_20231012_at_104746_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6528c30fd040066d2c56c18b",
    "name":
"externallmg_1697170191623_WhatsApp_Image_20231012_at_104747_PM_1.jpeg",
    "path": "cases/652772fbf29c60440818706b/
externallmg_1697170191623_WhatsApp_Image_20231012_at_104747_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6528c30fd040066d2c56c18c",
    "name":
"externallmg_1697170191627_WhatsApp_Image_20231012_at_104747_PM_2.jpeg",
    "path": "cases/652772fbf29c60440818706b/
externallmg_1697170191627_WhatsApp_Image_20231012_at_104747_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6528c30fd040066d2c56c18d",
    "name":
"externallmg_1697170191629_WhatsApp_Image_20231012_at_104747_PM.jpeg",
    "path": "cases/652772fbf29c60440818706b/
externallmg_1697170191629_WhatsApp_Image_20231012_at_104747_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6528c30fd040066d2c56c18e",
    "name":
"externallmg_1697170191634_WhatsApp_Image_20231012_at_104748_PM_1.jpeg",
    "path": "cases/652772fbf29c60440818706b/
externallmg_1697170191634_WhatsApp_Image_20231012_at_104748_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6528c30fd040066d2c56c18f",
    "name":
"externallmg_1697170191637_WhatsApp_Image_20231012_at_104748_PM.jpeg",
    "path": "cases/652772fbf29c60440818706b/
externallmg_1697170191637_WhatsApp_Image_20231012_at_104748_PM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6528c30fd040066d2c56c190",
    "name":
"externallmg_1697170191639_WhatsApp_Image_20231012_at_104749_PM.jpeg",
    "path": "cases/652772fbf29c60440818706b/
externallmg_1697170191639_WhatsApp_Image_20231012_at_104749_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6528c30fd040066d2c56c191",
    "name":
"externallmg_1697170191642_WhatsApp_Image_20231012_at_104750_PM.jpeg",
    "path": "cases/652772fbf29c60440818706b/
externallmg_1697170191642_WhatsApp_Image_20231012_at_104750_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6528c30fd040066d2c56c192",
    "name":
"externallmg_1697170191647_WhatsApp_Image_20231012_at_104751_PM_1.jpeg",
    "path": "cases/652772fbf29c60440818706b/
externallmg_1697170191647_WhatsApp_Image_20231012_at_104751_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6528c30fd040066d2c56c193",
    "name":
"externallmg_1697170191653_WhatsApp_Image_20231012_at_104751_PM_2.jpeg",
    "path": "cases/652772fbf29c60440818706b/
externallmg_1697170191653_WhatsApp_Image_20231012_at_104751_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6528c30fd040066d2c56c194",
```

```
    "name":
"externallmg_1697170191657_WhatsApp_Image_20231012_at_104751_PM.jpeg",
  "path": "cases/652772fbf29c60440818706b/
externallmg_1697170191657_WhatsApp_Image_20231012_at_104751_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6528c30fd040066d2c56c195",
  "name":
"externallmg_1697170191659_WhatsApp_Image_20231012_at_104752_PM_1.jpeg",
  "path": "cases/652772fbf29c60440818706b/
externallmg_1697170191659_WhatsApp_Image_20231012_at_104752_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6528c30fd040066d2c56c196",
  "name":
"externallmg_1697170191661_WhatsApp_Image_20231012_at_104752_PM_2.jpeg",
  "path": "cases/652772fbf29c60440818706b/
externallmg_1697170191661_WhatsApp_Image_20231012_at_104752_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6528c30fd040066d2c56c197",
  "name":
"externallmg_1697170191664_WhatsApp_Image_20231012_at_104752_PM.jpeg",
  "path": "cases/652772fbf29c60440818706b/
externallmg_1697170191664_WhatsApp_Image_20231012_at_104752_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6528c30fd040066d2c56c198",
  "name":
"externallmg_1697170191666_WhatsApp_Image_20231012_at_104753_PM_1.jpeg",
  "path": "cases/652772fbf29c60440818706b/
externallmg_1697170191666_WhatsApp_Image_20231012_at_104753_PM_1.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6528c30fd040066d2c56c199",
  "name":
"externallmg_1697170191672_WhatsApp_Image_20231012_at_104753_PM_2.jpeg",
  "path": "cases/652772fbf29c60440818706b/
externallmg_1697170191672_WhatsApp_Image_20231012_at_104753_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6528c30fd040066d2c56c19a",
  "name":
"externallmg_1697170191675_WhatsApp_Image_20231012_at_104753_PM_3.jpeg",
  "path": "cases/652772fbf29c60440818706b/
externallmg_1697170191675_WhatsApp_Image_20231012_at_104753_PM_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6528c30fd040066d2c56c19b",
  "name":
"externallmg_1697170191678_WhatsApp_Image_20231012_at_104753_PM.jpeg",
  "path": "cases/652772fbf29c60440818706b/
externallmg_1697170191678_WhatsApp_Image_20231012_at_104753_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6528c30fd040066d2c56c19c",
  "name":
"externallmg_1697170191681_WhatsApp_Image_20231012_at_104754_PM_1.jpeg",
  "path": "cases/652772fbf29c60440818706b/
externallmg_1697170191681_WhatsApp_Image_20231012_at_104754_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6528c30fd040066d2c56c19d",
  "name":
"externallmg_1697170191683_WhatsApp_Image_20231012_at_104754_PM_2.jpeg",
```



```
    "path": "cases/652772fbf29c60440818706b/
externallmg_1697170191683_WhatsApp_Image_20231012_at_104754_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6528c327d040066d2c56c2b8",
    "name":
"externallmg_1697170211402_WhatsApp_Image_20231012_at_104754_PM_2.jpeg",
    "path": "cases/652772fbf29c60440818706b/
externallmg_1697170211402_WhatsApp_Image_20231012_at_104754_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6528c327d040066d2c56c2b9",
    "name":
"externallmg_1697170211428_WhatsApp_Image_20231012_at_104754_PM.jpeg",
    "path": "cases/652772fbf29c60440818706b/
externallmg_1697170211428_WhatsApp_Image_20231012_at_104754_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6528c327d040066d2c56c2ba",
    "name":
"externallmg_1697170211494_WhatsApp_Image_20231012_at_104755_PM_1.jpeg",
    "path": "cases/652772fbf29c60440818706b/
externallmg_1697170211494_WhatsApp_Image_20231012_at_104755_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6528c327d040066d2c56c2bb",
    "name":
"externallmg_1697170211779_WhatsApp_Image_20231012_at_104755_PM.jpeg",
    "path": "cases/652772fbf29c60440818706b/
externallmg_1697170211779_WhatsApp_Image_20231012_at_104755_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "6528c327d040066d2c56c2bc",
  "name":
"externallmg_1697170214618_WhatsApp_Image_20231012_at_104703_PM.jpeg",
  "path": "cases/652772fbf29c60440818706b/
externallmg_1697170214618_WhatsApp_Image_20231012_at_104703_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6528c327d040066d2c56c2bd",
  "name":
"externallmg_1697170214876_WhatsApp_Image_20231012_at_104709_PM.jpeg",
  "path": "cases/652772fbf29c60440818706b/
externallmg_1697170214876_WhatsApp_Image_20231012_at_104709_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6528c327d040066d2c56c2be",
  "name":
"externallmg_1697170215014_WhatsApp_Image_20231012_at_104712_PM.jpeg",
  "path": "cases/652772fbf29c60440818706b/
externallmg_1697170215014_WhatsApp_Image_20231012_at_104712_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6528c327d040066d2c56c2bf",
  "name":
"externallmg_1697170215089_WhatsApp_Image_20231012_at_104721_PM.jpeg",
  "path": "cases/652772fbf29c60440818706b/
externallmg_1697170215089_WhatsApp_Image_20231012_at_104721_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6528c327d040066d2c56c2c0",
  "name":
"externallmg_1697170215096_WhatsApp_Image_20231012_at_104722_PM_1.jpeg",
  "path": "cases/652772fbf29c60440818706b/
externallmg_1697170215096_WhatsApp_Image_20231012_at_104722_PM_1.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6528c327d040066d2c56c2c1",
    "name":
"externallmg_1697170215100_WhatsApp_Image_20231012_at_104722_PM.jpeg",
    "path": "cases/652772fbf29c60440818706b/
externallmg_1697170215100_WhatsApp_Image_20231012_at_104722_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6528c327d040066d2c56c2c2",
    "name":
"externallmg_1697170215103_WhatsApp_Image_20231012_at_104724_PM.jpeg",
    "path": "cases/652772fbf29c60440818706b/
externallmg_1697170215103_WhatsApp_Image_20231012_at_104724_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6528c327d040066d2c56c2c3",
    "name":
"externallmg_1697170215106_WhatsApp_Image_20231012_at_104725_PM.jpeg",
    "path": "cases/652772fbf29c60440818706b/
externallmg_1697170215106_WhatsApp_Image_20231012_at_104725_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6528c327d040066d2c56c2c4",
    "name":
"externallmg_1697170215110_WhatsApp_Image_20231012_at_104726_PM.jpeg",
    "path": "cases/652772fbf29c60440818706b/
externallmg_1697170215110_WhatsApp_Image_20231012_at_104726_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6528c327d040066d2c56c2c5",
```

```
    "name":
"externallmg_1697170215112_WhatsApp_Image_20231012_at_104728_PM_1.jpeg",
  "path": "cases/652772fbf29c60440818706b/
externallmg_1697170215112_WhatsApp_Image_20231012_at_104728_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6528c327d040066d2c56c2c6",
  "name":
"externallmg_1697170215116_WhatsApp_Image_20231012_at_104728_PM.jpeg",
  "path": "cases/652772fbf29c60440818706b/
externallmg_1697170215116_WhatsApp_Image_20231012_at_104728_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6528c327d040066d2c56c2c7",
  "name":
"externallmg_1697170215123_WhatsApp_Image_20231012_at_104737_PM_1.jpeg",
  "path": "cases/652772fbf29c60440818706b/
externallmg_1697170215123_WhatsApp_Image_20231012_at_104737_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6528c327d040066d2c56c2c8",
  "name":
"externallmg_1697170215126_WhatsApp_Image_20231012_at_104737_PM.jpeg",
  "path": "cases/652772fbf29c60440818706b/
externallmg_1697170215126_WhatsApp_Image_20231012_at_104737_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6528c327d040066d2c56c2c9",
  "name":
"externallmg_1697170215131_WhatsApp_Image_20231012_at_104741_PM.jpeg",
  "path": "cases/652772fbf29c60440818706b/
externallmg_1697170215131_WhatsApp_Image_20231012_at_104741_PM.jpeg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6528c327d040066d2c56c2ca",
  "name":
"externallmg_1697170215135_WhatsApp_Image_20231012_at_104742_PM_1.jpeg",
  "path": "cases/652772fbf29c60440818706b/
externallmg_1697170215135_WhatsApp_Image_20231012_at_104742_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6528c327d040066d2c56c2cb",
  "name":
"externallmg_1697170215141_WhatsApp_Image_20231012_at_104742_PM.jpeg",
  "path": "cases/652772fbf29c60440818706b/
externallmg_1697170215141_WhatsApp_Image_20231012_at_104742_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6528c334d040066d2c56c33d",
  "name":
"externallmg_1697170228573_WhatsApp_Image_20231012_at_104744_PM_1.jpeg",
  "path": "cases/652772fbf29c60440818706b/
externallmg_1697170228573_WhatsApp_Image_20231012_at_104744_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6528c334d040066d2c56c33e",
  "name":
"externallmg_1697170228577_WhatsApp_Image_20231012_at_104744_PM.jpeg",
  "path": "cases/652772fbf29c60440818706b/
externallmg_1697170228577_WhatsApp_Image_20231012_at_104744_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6528c334d040066d2c56c33f",
  "name":
"externallmg_1697170228583_WhatsApp_Image_20231012_at_104745_PM_1.jpeg",
```

```
    "path": "cases/652772fbf29c60440818706b/
externallmg_1697170228583_WhatsApp_Image_20231012_at_104745_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6528c334d040066d2c56c340",
    "name":
"externallmg_1697170228588_WhatsApp_Image_20231012_at_104745_PM_2.jpeg",
    "path": "cases/652772fbf29c60440818706b/
externallmg_1697170228588_WhatsApp_Image_20231012_at_104745_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6528c334d040066d2c56c341",
    "name":
"externallmg_1697170228590_WhatsApp_Image_20231012_at_104745_PM_3.jpeg",
    "path": "cases/652772fbf29c60440818706b/
externallmg_1697170228590_WhatsApp_Image_20231012_at_104745_PM_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6528c334d040066d2c56c342",
    "name":
"externallmg_1697170228592_WhatsApp_Image_20231012_at_104745_PM.jpeg",
    "path": "cases/652772fbf29c60440818706b/
externallmg_1697170228592_WhatsApp_Image_20231012_at_104745_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6528c334d040066d2c56c343",
    "name":
"externallmg_1697170228600_WhatsApp_Image_20231012_at_104746_PM_1.jpeg",
    "path": "cases/652772fbf29c60440818706b/
externallmg_1697170228600_WhatsApp_Image_20231012_at_104746_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "6528c334d040066d2c56c344",
  "name":
"externalImg_1697170228602_WhatsApp_Image_20231012_at_104746_PM.jpeg",
  "path": "cases/652772fbf29c60440818706b/
externalImg_1697170228602_WhatsApp_Image_20231012_at_104746_PM.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
{
  "originalname": "1696406686585_Calculation.xlsx",
  "filename": "1697177193829_1696406686585_Calculation.xlsx",
  "path": "cases/652772fbf29c60440818706b/
processingDocuments/1697177193829_1696406686585_Calculation.xlsx",
  "size": "1421101",
  "createdAt": "Fri Oct 13 2023 11:36:33 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f915d3f3dd69653a592199"
}
],
"remarks": [],
"createdAt": "2023-10-12T04:15:55.364Z",
"updatedAt": "2023-10-13T11:18:40.227Z",
"__v": 0,
"updatedBy": "60f915d3f3dd69653a592199",
"fullAddress": "Residential Flat No. 602, 6th Floor, Samary Heights, Near Gokhivare
Talao, Village - Gokhivare, Vasai (East), Taluka - Vasai, District - Palghar, PIN - 401
208, State - Maharashtra, India",
"addressForMap": "",
"caseReferredBy": "627219d6afd7d55eddedd283",
"contactPersonName": "Mr. Gowda Ashok Gopal",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "8050608994",
"buildingServicesRate": "2600.00",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Other",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 521.00",
```

"flatRate": "8000.00",  
 "landOtherRate": "5400",  
 "briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + Cupboard + 2 Toilet + Passage",  
 "carpetTotal": "505.39",  
 "otherCarpetTotal": "113.17",  
 "otherCompositionBuiltUpTotal": "0.00",  
 "otherCompositionCarpetTotal": "113.17",  
 "otherCompositionSaleableTotal": "0.00",  
 "builtupPercentage": "20",  
 "finalBuiltupArea": "742.27",  
 "finalCarpetArea": "618.56",  
 "finalSalableArea": "742.27",  
 "salablePercentage": "0",  
 "toBeAdded": "",  
 "extendOfSiteRemark": "",  
 "siteMeasurementRemark": "Carpet Area in Sq. Ft. = 505.39\nDry Balcony Area in Sq. Ft. = 15.00\nFlowerbed Area in Sq. Ft. = 98.17\nTotal Area in Sq. Ft. = 618.56\n(Area as per actual site measurement)",  
 "finalSaleablePercentage": "",  
 "reportGeneratedDate": "Fri Oct 13 2023 16:29:38 GMT+0530 (India Standard Time)",  
 "siteVisitDate": "2023-10-12"

Name	Length	Width	Total
Composition :			
Living Room	10'00"	13'9"	137.50
Cupboard	4'6"	2'00"	9.00
Kitchen	12'00"	7'5"	89.00
Toilet	4'00"	6'00"	24.00
Passage	3'0"	6'8"	20.00
Bedroom	9'5"	12'4"	116.14
Toilet	5'00"	5'00"	25.00
Bedroom	9'00"	9'5"	84.75
Other Composition :			
Flowerbed	4'0"	9'0"	36.00



Flowerbed	12'4"	2'0"	24.67
Dry Balcony Area	7'6"	2'00"	15.00
Flowerbed	10'0"	3'9"	37.50