

```
{
  "typeOfReport": {
    "value": "Residential",
    "label": "Residential"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "A.P.F.",
    "label": "Advance Processing Facility"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": "",
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "3540"
  },
  "organization": {
    "_id": "643a5bee108b68389ed736e5",
    "name": "Nashik Branch",
    "shortName": "NSK",
    "email": "nashik@vastukala.org",
    "address": "4, 1st Floor, Mashusha Elite, Vrundavan Naka Link Road, Adgaon, ",
    "city": "Nashik"
  },
  "client": {
    "_id": "6527cea782e2722e3be611cd",
    "type": "PRIVATE_CLIENT",
    "name": "Mayur Singh",
  }
}
```

```
"displayName": "Mayur Singh",
"initial": "M"
},
"branch": "",
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": "",
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "63f9ed37ce84bf289ba991ac",
    "role": "FRONTDESK",
    "firstName": "Rushikesh",
    "email": "rushingle2201@gmail.com",
    "lastName": "Pingle",
    "mobileNo": "8788210361",
    "shortName": "RUP",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "636a29b64d42487767af43ea",
    "role": "NASHIK (LEAD + VISIT + RATE)",
    "firstName": "Sachin",
    "email": "sachinraundal9021@gmail.com",
    "lastName": "Raundal",
    "mobileNo": "9021337843",
    "designation": "Site Engg",
    "shortName": "Sachin",
    "workWithDocumentMaker": "62724142afd7d55eddede405",
    "profilePhoto": "users/636a29b64d42487767af43ea/
profilePhoto_1688819202426_image.jpeg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "636a1ad14d42487767af3f91",
    "role": "MAKER + RATE VERIFIER",
    "firstName": "Chintamani",
```

```
"email": "chintamanichaudhari099@gmail.com",
"lastName": "Chaudhari",
"mobileNo": "8007230780",
"designation": "",
"shortName": "Chintamani",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "636a1ad14d42487767af3f91",
"role": "MAKER + RATE VERFIER",
"firstName": "Chintamani",
"email": "chintamanichaudhari099@gmail.com",
"lastName": "Chaudhari",
"mobileNo": "8007230780",
"designation": "",
"shortName": "Chintamani",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "60f9147bf3dd69653a591e8c",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Vinita",
"email": "vinita.surve@vastukala.org",
"lastName": "Surve",
"mobileNo": "9820652818",
"designation": "",
"shortName": "V",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
},
"valuers": []
},
"clientType": {
"value": "PRIVATE_CLIENT",
"label": "Private Clients"
},
"location": {
"latitude": "20.05189078829173",
"longitude": "73.77691486126308"
```

```
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Makhmalabad",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
```

```
"key": "floorNo",
"value": "Upper Ground",
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Nashik",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "32+33/3",
  "label": true
},
}
```

```
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Shree Satyam Row House",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": " Shree Krushna Nagar",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Opp Kirti Apartment ,Mankar Mala ",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
```

```
"value": "",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "424/1 to 5/3",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "3",
  "label": false
},
"municipalityWardNo": {
```

```
"status": false,
"name": "Municipality Ward No.",
"key": "municipalityWardNo",
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422003",
```



```
"label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
```

```
"label": "RCC Plinth",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
"label": "Full Building Rcc",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```

```
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
```

```
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentId": [],
"_id": "6527ced482e2722e3be611d8",
"ownerName": "Mayur Singh",
"ownerPhoneNo": "7741903506",
"fullAddress": " Flat No. 3, Upper Ground Floor, Shree Satyam Row House, Opp Kirti
Apartment ,Mankar Mala , Plot No. 32+33/3, Shree Krushna Nagar, Village -
Makhmalabad, Taluka - Nashik, District - Nashik, Nashik, 422003",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1697107573896_mayur_singh.pdf",
    "path": "cases/6527ced482e2722e3be611d8/
document_1697107573896_mayur_singh.pdf",
    "id": "593037",
    "uploadedBy": "63f9ed37ce84bf289ba991ac",
    "createdAt": "Thu Oct 12 2023 16:17:03 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "004382",
```

```
"createdBy": "63f9ed37ce84bf289ba991ac",
"caseHistory": [
  {
    "id": "210949",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Oct 12 2023 16:17:48 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mayur Singh",
    "phone": "7741903506",
    "ownershipShare": "",
    "email": "",
    "id": "187691"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6527cf9282e2722e3be617a9",
    "name":
"externallmg_1697107857083_WhatsApp_Image_20231012_at_31333_PM_1.jpeg",
    "path": "cases/6527ced482e2722e3be611d8/
externallmg_1697107857083_WhatsApp_Image_20231012_at_31333_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6527cf9282e2722e3be617aa",
    "name":
"externallmg_1697107857194_WhatsApp_Image_20231012_at_31333_PM.jpeg",
    "path": "cases/6527ced482e2722e3be611d8/
externallmg_1697107857194_WhatsApp_Image_20231012_at_31333_PM.jpeg",
    "orientation": "portrait"
  }
]
```



```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6527cf9282e2722e3be617ab",
  "name":
"externallmg_1697107857296_WhatsApp_Image_20231012_at_112241_AM.jpeg",
  "path": "cases/6527ced482e2722e3be611d8/
externallmg_1697107857296_WhatsApp_Image_20231012_at_112241_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6527cf9282e2722e3be617ac",
  "name":
"externallmg_1697107857397_WhatsApp_Image_20231012_at_112244_AM.jpeg",
  "path": "cases/6527ced482e2722e3be611d8/
externallmg_1697107857397_WhatsApp_Image_20231012_at_112244_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6527cf9282e2722e3be617ad",
  "name":
"externallmg_1697107857501_WhatsApp_Image_20231012_at_112248_AM.jpeg",
  "path": "cases/6527ced482e2722e3be611d8/
externallmg_1697107857501_WhatsApp_Image_20231012_at_112248_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6527cf9282e2722e3be617ae",
  "name":
"externallmg_1697107857622_WhatsApp_Image_20231012_at_112249_AM.jpeg",
  "path": "cases/6527ced482e2722e3be611d8/
externallmg_1697107857622_WhatsApp_Image_20231012_at_112249_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6527cf9282e2722e3be617af",
  "name":
"externallmg_1697107857774_WhatsApp_Image_20231012_at_112250_AM_1.jpeg",
```

```
    "path": "cases/6527ced482e2722e3be611d8/
externallmg_1697107857774_WhatsApp_Image_20231012_at_112250_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6527cf9282e2722e3be617b0",
    "name":
"externallmg_1697107857816_WhatsApp_Image_20231012_at_112250_AM_2.jpeg",
    "path": "cases/6527ced482e2722e3be611d8/
externallmg_1697107857816_WhatsApp_Image_20231012_at_112250_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6527cf9282e2722e3be617b1",
    "name":
"externallmg_1697107857857_WhatsApp_Image_20231012_at_112250_AM.jpeg",
    "path": "cases/6527ced482e2722e3be611d8/
externallmg_1697107857857_WhatsApp_Image_20231012_at_112250_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6527cf9282e2722e3be617b2",
    "name":
"externallmg_1697107857980_WhatsApp_Image_20231012_at_112251_AM_1.jpeg",
    "path": "cases/6527ced482e2722e3be611d8/
externallmg_1697107857980_WhatsApp_Image_20231012_at_112251_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6527cf9282e2722e3be617b3",
    "name":
"externallmg_1697107858041_WhatsApp_Image_20231012_at_112251_AM_2.jpeg",
    "path": "cases/6527ced482e2722e3be611d8/
externallmg_1697107858041_WhatsApp_Image_20231012_at_112251_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "6527cf9282e2722e3be617b4",
    "name":
"externallmg_1697107858128_WhatsApp_Image_20231012_at_112251_AM.jpeg",
    "path": "cases/6527ced482e2722e3be611d8/
externallmg_1697107858128_WhatsApp_Image_20231012_at_112251_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6527cf9282e2722e3be617b5",
    "name":
"externallmg_1697107858222_WhatsApp_Image_20231012_at_112252_AM_1.jpeg",
    "path": "cases/6527ced482e2722e3be611d8/
externallmg_1697107858222_WhatsApp_Image_20231012_at_112252_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6527cf9282e2722e3be617b6",
    "name":
"externallmg_1697107858276_WhatsApp_Image_20231012_at_112252_AM_2.jpeg",
    "path": "cases/6527ced482e2722e3be611d8/
externallmg_1697107858276_WhatsApp_Image_20231012_at_112252_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6527cf9282e2722e3be617b7",
    "name":
"externallmg_1697107858331_WhatsApp_Image_20231012_at_112252_AM.jpeg",
    "path": "cases/6527ced482e2722e3be611d8/
externallmg_1697107858331_WhatsApp_Image_20231012_at_112252_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6527cf9282e2722e3be617b8",
    "name":
"externallmg_1697107858450_WhatsApp_Image_20231012_at_112253_AM_1.jpeg",
    "path": "cases/6527ced482e2722e3be611d8/
externallmg_1697107858450_WhatsApp_Image_20231012_at_112253_AM_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6527cf9282e2722e3be617b9",
    "name":
"externallmg_1697107858512_WhatsApp_Image_20231012_at_112253_AM.jpeg",
    "path": "cases/6527ced482e2722e3be611d8/
externallmg_1697107858512_WhatsApp_Image_20231012_at_112253_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6527cf9282e2722e3be617ba",
    "name":
"externallmg_1697107858592_WhatsApp_Image_20231012_at_112254_AM_1.jpeg",
    "path": "cases/6527ced482e2722e3be611d8/
externallmg_1697107858592_WhatsApp_Image_20231012_at_112254_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6527cf9e82e2722e3be617e8",
    "name":
"externallmg_1697107868976_WhatsApp_Image_20231012_at_112254_AM_2.jpeg",
    "path": "cases/6527ced482e2722e3be611d8/
externallmg_1697107868976_WhatsApp_Image_20231012_at_112254_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6527cf9e82e2722e3be617e9",
    "name":
"externallmg_1697107869030_WhatsApp_Image_20231012_at_112254_AM.jpeg",
    "path": "cases/6527ced482e2722e3be611d8/
externallmg_1697107869030_WhatsApp_Image_20231012_at_112254_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6527cf9e82e2722e3be617ea",
```

```
    "name":
"externallmg_1697107869088_WhatsApp_Image_20231012_at_112255_AM_1.jpeg",
  "path": "cases/6527ced482e2722e3be611d8/
externallmg_1697107869088_WhatsApp_Image_20231012_at_112255_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6527cf9e82e2722e3be617eb",
  "name":
"externallmg_1697107869168_WhatsApp_Image_20231012_at_112255_AM_2.jpeg",
  "path": "cases/6527ced482e2722e3be611d8/
externallmg_1697107869168_WhatsApp_Image_20231012_at_112255_AM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6527cf9e82e2722e3be617ec",
  "name":
"externallmg_1697107869236_WhatsApp_Image_20231012_at_112255_AM.jpeg",
  "path": "cases/6527ced482e2722e3be611d8/
externallmg_1697107869236_WhatsApp_Image_20231012_at_112255_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6527cf9e82e2722e3be617ed",
  "name":
"externallmg_1697107869314_WhatsApp_Image_20231012_at_112256_AM_1.jpeg",
  "path": "cases/6527ced482e2722e3be611d8/
externallmg_1697107869314_WhatsApp_Image_20231012_at_112256_AM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6527cf9e82e2722e3be617ee",
  "name":
"externallmg_1697107869499_WhatsApp_Image_20231012_at_112256_AM_2.jpeg",
  "path": "cases/6527ced482e2722e3be611d8/
externallmg_1697107869499_WhatsApp_Image_20231012_at_112256_AM_2.jpeg",
  "orientation": "portrait"
},
}
```

```

{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6527cf9e82e2722e3be617ef",
  "name":
"externallmg_1697107869707_WhatsApp_Image_20231012_at_112256_AM.jpeg",
  "path": "cases/6527ced482e2722e3be611d8/
externallmg_1697107869707_WhatsApp_Image_20231012_at_112256_AM.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-10-12T10:47:48.079Z",
"updatedAt": "2023-10-12T10:51:09.998Z",
"__v": 0,
"invoiceId": "6527ced482e2722e3be611f9",
"updatedBy": "63f9ed37ce84bf289ba991ac",
"addressForMap": "",
"caseReferredBy": "636a29b64d42487767af43ea",
"contactPersonName": "Mayur Singh",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "7741903506"
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			