

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Market Value",
    "value": "Market_Value"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b8a4"
    },
    "type": "CREDITOFFICER",
    "_id": "64cb46df0faf29427aca399a",
    "firstName": "Rajesh ",
    "lastName": "Kumar",
    "mobileNo": "",
    "workMobileNo": "9975642826",
    "email": "cord2.racpcandheri@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "2067560",
    "discussWithPerson": "Rajesh ",
    "expectedFees": 1033.78,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b8a4",
  "branchCode": "000111",
  "type": "BRANCH",
  "name": "RACPC Andheri (East)",
  "email": "cord2.racpcandheri@sbi.co.in",
  "mobileNo": "02228389765/69",
  "alternateMobileNo": "",
  "address": "1st Floor, UTI Building, Plot No. 12, MIDC, Road No. 9, Behind Tunga
Paradise Hotel, Andheri (East), Mumbai - 400 093, State - Maharashtra, Country -
India.",
  "ledgerName": "STATE BANK OF INDIA - RACPC ANDHERI",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "64535eb5ee347304f2a3005f",
  "role": "DELIVERYPERSON",
  "firstName": "Hemant",
  "email": "hkadam113@gmail.com",
  "lastName": "Kadam",
  "mobileNo": "9819455052",
  "shortName": "Hemant",
  "workWithDocumentMaker": "60b7189d2ffdf65bcd65882b",
  "profilePhoto": "users/64535eb5ee347304f2a3005f/
profilePhoto_1687240220512_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62ea09ea4e679b264caf07d7",
  "role": "SITEENGINEER",
  "firstName": "Suraj",
  "email": "suraj@vastukala.org",
  "lastName": "Zore",
  "mobileNo": "8652448654",
  "designation": "",
  "shortName": "SZ",
  "workWithDocumentMaker": "60092304a16fab0f2af9b0c2",
  "profilePhoto": "users/62ea09ea4e679b264caf07d7/
profilePhoto_1685629394240_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60eebe33f3dd69653a5837ae",
  "role": "MAKER",
  "firstName": "Shamal",
  "email": "shamal@vastukala.org",
```

```
"lastName": "Bodke",
"mobileNo": "9821740317",
"designation": "",
"shortName": "SB",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eebe33f3dd69653a5837ae\
\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
  },

```

```
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.282291657230363",
  "longitude": "73.07393443558225"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.07393443558225,
```

```
19.282291657230363
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-17",
      "remark": ""
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Temghar",
```

```
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "8",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "9",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Bhiwandi",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Bhiwandi",
  "label": true
},
"plotNo": {
  "status": false,
```

```
"name": "Plot No.",
"key": "plotNo",
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Atlanta Eden World",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Pipe Line Road",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Opp. PWD Office Bhadawad",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
}
```



```
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Phase 1",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "69/1 (Part) & other",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
```

```
"key": "selectNo",
"value": "803",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
}
```

```
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 421 302",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_door_frame,_Flush_doors_shutters",
    "label": "Teak Wood door frame, Flush doors shutters"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering_+_POP_Finish",
    "label": "Cement Plastering + POP Finish"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  }
}
```

```
},
"populationClassList": {
  "value": "MiddleClass",
  "label": "Middle Class"
},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "Bhiwandi_Nizampur_Municipal_Council",
  "label": "Bhiwandi Nizampur Municipal Council"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Pipe Line Road",
  "west": "Building No. 10",
  "south": "Ground",
  "east": "Building No. 8"
},
"asPerDocumentAgreement": {
  "north": "Details not available",
  "west": "Details not available",
  "south": "Details not available",
  "east": "Details not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "asPerDocument": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
```

```
"dateOfIssusApprovePlan": "As Occupancy Certificate is received may be assumed
that the construction is as per sanctioned plan. ",
"approvePlanVerified": "N. A.",
"empanelledOfApprovePlan": "N. A."
},
"compositeRate": {
"remark": "As per Site Inspection, Actual Total Carpet area 562.00 Sq. Ft. (Including
Flowerbed & Cupboard area) is more than Carpet area 457.00 Sq. Ft. mentioned in the
documents provided to us. We have considered area mentioned in the documents.
Hence, to give proper weightage to the value of the property, higher rate i.e. 6,727/- per
Sq. Ft. is considered.",
"depreciationPercentage": "10.5",
"depreciationRatioOfBuilding": "",
"salvageValue": "10",
"depreciatedCostOfConstruction": "6727",
"depreciatedBuildingRate": "2327"
},
"igrRate": {
"propertyName": "Tembghar",
"rate": "45500",
"landRate": "10200",
"igrImage": "cases/652d1cbb316e1359cebd68cb/igr_1697619115352_Image.png",
"squareMeterGuideLineRate": "47775.00",
"squareFeetGuideLineRate": "4438.00"
},
"igrFinalRate": {
"depreciationPercentage": "93",
"rate": "4194.00",
"squareFeetGuideLineRate": "4194.00",
"squareMeterGuideLineRate": "45145.00"
},
"outgoingDetail": {
"areaStatusList": {
"value": "Middle_Class",
"label": "Middle Class"
},
"propertyTypeOfUseList": {
"value": "Residential_Purpose",
"label": "Residential Purpose"
},
"propertyOccupiedByList": {
"value": "Owner_Occupied",
"label": "Owner Occupied"
},
"monthlyRent": "6,500",
"assessmentNo": "Details not available",
```

```
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per BNCCMC norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Stilt + Open Car Parking",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
```

```
"year": "2016",
"fullDate": "1/1/2016"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
}
```

```
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "As_Per_Part_Occupancy_Certificate",
  "label": "As Per Part Occupancy Certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "7",
"totalLifeBuilding": "60",
"estimatedAge": "53",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "12",
"flatFloorNo": "8",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "areaType": "Built Up",
  "area": "548.40",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
}
```



```
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/652d1cbb316e1359cebd68cb/
routeMap_1697623547938_Image.png",
    "routeLat": "19.288639",
    "routeLng": "73.080861",
    "stationName": "Bhiwandi",
    "routeDistance": "5.3 Km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "pifdhj",
      "name": "pifdhj",
      "image": "cases/652d1cbb316e1359cebd68cb/
routeMap_1697623482584_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
```

```
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "3074239.00",
"finalValue": "3074239.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Wed Oct 18 2023 16:15:54 GMT+0530 (India Standard Time)",
  "number": "2303069",
  "dayCount": "13",
  "monthCount": "266",
  "generatedBy": "60f915d3f3dd69653a592199"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "2299990.00",
  "selectedBuildUpValue": "548.40",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "652eb2dc7e32132d4092ff98",
      "name": "externallmg_r_1697559236800_1697559202457_image_12.jpg",
      "path": "cases/652d1cbb316e1359cebd68cb/
externallmg_r_1697559236800_1697559202457_image_12.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "652eb2dc7e32132d4092ff9b",
      "name": "externallmg_r_1697559238377_1697559202457_image_13.jpg",
      "path": "cases/652d1cbb316e1359cebd68cb/
externallmg_r_1697559238377_1697559202457_image_13.jpg",
      "orientation": "portrait"
    }
  ],
  {

```

```
    "status": false,
    "_id": "652eb2dc7e32132d4092ff9a",
    "name": "externallmg_r_1697559240926_1697559202457_image_14.jpg",
    "path": "cases/652d1cbb316e1359cebd68cb/
externallmg_r_1697559240926_1697559202457_image_14.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "652eb2dc7e32132d4092ff99",
    "name": "externallmg_r_1697559242819_1697559202457_image_15.jpg",
    "path": "cases/652d1cbb316e1359cebd68cb/
externallmg_r_1697559242819_1697559202457_image_15.jpg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "652eb2dc7e32132d4092ff96",
    "name": "externallmg_r_1697559233913_1697559202457_image_11.jpg",
    "path": "cases/652d1cbb316e1359cebd68cb/
externallmg_r_1697559233913_1697559202457_image_11.jpg",
    "orientation": "landscape"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "652eb2dc7e32132d4092ff8d",
    "name": "Living Room",
    "path": "cases/652d1cbb316e1359cebd68cb/
externallmg_r_1697559216519_1697559202457_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "652eb2dc7e32132d4092ff8f",
    "name": "Living Room",
    "path": "cases/652d1cbb316e1359cebd68cb/
externallmg_r_1697559217280_1697559202457_image_1.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
```

```
    "_id": "652eb2dc7e32132d4092ff90",
    "name": "Living Room",
    "path": "cases/652d1cbb316e1359cebd68cb/
externallmg_r_1697559224265_1697559202457_image_6.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "652eb2dc7e32132d4092ff93",
    "name": "Living Room",
    "path": "cases/652d1cbb316e1359cebd68cb/
externallmg_r_1697559222990_1697559202457_image_5.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "652eb2dc7e32132d4092ff97",
    "name": "Living Room",
    "path": "cases/652d1cbb316e1359cebd68cb/
externallmg_r_1697559231858_1697559202457_image_10.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "652eb2dc7e32132d4092ff94",
    "name": "Living Room",
    "path": "cases/652d1cbb316e1359cebd68cb/
externallmg_r_1697559228074_1697559202457_image_8.jpg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "5657",
    "max": "6186"
  },
  "builtUpRateRange": {
    "min": "4715",
    "max": "5156"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
```



```
"title": "Electricity deposits / electrical fittings, etc",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
```

```
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "457.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentId": [],
"_id": "652d1cbb316e1359cebd68cb",
"ownerName": "Mr. Yogesh S. Kulkarni & Mrs. Sharandeep Y. Kulkarni",
"ownerPhoneNo": "9619691161",
"appAddress": "Flat . no. 803 8th floor ATLANTA EDEN WOLRD TOWER no. 09
Pipeline Road Bhiwandi Gaon sohle Village Temghar Bhiwandi Thane ",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "inputs": {
      "documentDate": "26/07/2013",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "Sai Balaji Developer",
      "to": {
        "value": "Purchasers",
        "label": "Purchasers"
      }
    }
  }
],
```

```
"Purchasers": "Mr. Yogesh S. Kulkarni & Mrs. Sharandeeep Y. Kulkarni",
"number": {
  "value": "No",
  "label": "No"
},
"No": "6465/2013"
},
"isHardCopy": false,
"displayStatus": true,
"id": "467812",
"path": "cases/652d1cbb316e1359cebd68cb/
document_1697455207367_RACPC_ANDHERI_sbi_Yogesh_Kula_bhiwandi.pdf",
"fileName":
"document_1697455207367_RACPC_ANDHERI_sbi_Yogesh_Kula_bhiwandi.pdf"
},
{
  "documentType": {
    "value": "60ae1250aa6d152c1801b316",
    "label": "Part Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "05/02/2016",
    "nameOfApprovingAuthority": {
      "value": "Bhiwandi_Nizampur_City_Municipal_Corporation",
      "label": "Bhiwandi Nizampur City Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "BPK / 55 / 2013-2014 / JK / NRV / 2740"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1697622450718_OC.pdf",
  "path": "cases/652d1cbb316e1359cebd68cb/document_1697622450718_OC.pdf",
  "id": "925977",
  "uploadedBy": "60eebe33f3dd69653a5837ae",
  "createdAt": "Wed Oct 18 2023 15:17:30 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "004431",
"createdBy": "64535eb5ee347304f2a3005f",
"caseHistory": [
  {
    "id": "659119",
```

```
"title": "Create Lead",
"description": "Create Lead",
"datetime": "Mon Oct 16 2023 16:51:31 GMT+0530 (India Standard Time)"
}
],
"owners": [
{
"name": "Mr. Yogesh S. Kulkarni & Mrs. Sharandeep Y. Kulkarni",
"phone": "9619691161",
"ownershipShare": "",
"email": "",
"id": "289179"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "887241",
"name": "Living Room",
"length": "9.75",
"length1": "9",
"length2": "9",
"width": "14.83",
"width1": "14",
"width2": "10",
"totalArea": "144.62",
"images": [],
"extraAreas": [
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
}_id": "652fa5ad7e32132d40942009",
"name": "Entrance",
"extraAreaType": "Add",
"length": "4.42",
"length1": "4",
"length2": "5",
"width": "3.42",
"width1": "3",
```

```
    "width2": "5",
    "totalArea": "15.09"
  }
],
"finalArea": "159.71"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Kitchen",
  "length": "9.67",
  "length1": "9",
  "length2": "8",
  "width": "7.33",
  "width1": "7",
  "width2": "4",
  "totalArea": "70.89",
  "images": [],
  "extraAreas": [],
  "finalArea": "70.89"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "WC",
  "length": "2.67",
  "length1": "2",
  "length2": "8",
  "width": "4.67",
  "width1": "4",
  "width2": "8",
  "totalArea": "12.44",
  "images": [],
  "extraAreas": [],
  "finalArea": "12.44"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  }
}
```

```
},
  "id": "3",
  "name": "Bathroom",
  "length": "3.75",
  "length1": "3",
  "length2": "9",
  "width": "5.67",
  "width1": "5",
  "width2": "8",
  "totalArea": "21.25",
  "images": [],
  "extraAreas": [],
  "finalArea": "21.25"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Bedroom",
  "length": "9.83",
  "length1": "9",
  "length2": "10",
  "width": "18.42",
  "width1": "18",
  "width2": "5",
  "totalArea": "181.10",
  "images": [],
  "extraAreas": [],
  "finalArea": "181.10"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Passage",
  "length": "8.42",
  "length1": "8",
  "length2": "5",
  "width": "2.83",
  "width1": "2",
  "width2": "10",
  "totalArea": "23.85",
```

```
"images": [],
"extraAreas": [],
"finalArea": "23.85"
}
],
"otherComposition": [
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Cupboard",
    "value": "Cupboard"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "0",
  "length1": "6",
  "length2": "9",
  "length": "6.75",
  "width1": "1",
  "width2": "7",
  "width": "1.58",
  "totalArea": "10.69",
  "percentageBeforeTotal": "17.15",
  "images": [],
  "extraAreas": [
    {
      "measurementType": {
        "value": "Square_Feet",
        "label": "Square Feet"
      },
      "_id": "652fa7027e32132d40942a5c",
      "name": "2 Cupboard",
      "extraAreaType": "Add",
      "length": "2.58",
      "length1": "2",
      "length2": "7",
      "width": "2.50",
      "width1": "2",
      "width2": "6",
      "totalArea": "6.46"
    }
  ]
}
```

```
],
"percentage": "100",
"finalArea": "17.15"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Balcony Area",
    "value": "Balcony_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "length1": "3",
  "length2": "2",
  "length": "3.17",
  "width1": "9",
  "width2": "10",
  "width": "9.83",
  "totalArea": "31.14",
  "percentageBeforeTotal": "31.14",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "31.14"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Balcony Area",
    "value": "Balcony_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "length1": "4",
```



```
"length2": "8",
"length": "4.67",
"width1": "9",
"width2": "7",
"width": "9.58",
"totalArea": "44.72",
"percentageBeforeTotal": "44.72",
"images": [],
"extraAreas": [],
"percentage": "100",
"finalArea": "44.72"
}
],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "label": "Agreement For Sale",
    "value": "60ae1254aa6d152c1801b326"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "selectAreaTypeDocument": "Carpet",
  "squareMeterArea": "42.46",
  "totalAreaDocument": "457",
  "docBultupPercentage": "20",
  "docFinalBultUp": "548.40",
  "docFinalBultUpSquareMeter": "50.95",
  "docSaleablePercentage": "",
  "docFinalSaleable": "0.00",
  "docFinalSaleableSquareMeter": "0.00",
  "id": "303768"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "652f9cbc7e32132d4093f42e",
  "property": "Sai Atlanta Eden World",
  "area": "548",
  "bultUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
```

```
"areaType": "Carpet",
"floor": "2",
"source": "https://www.99acres.com/",
"expectedPrice": "3100000",
"expectedRate": "5656.93",
"builtUpExpectedRate": "4714.11",
"image": "cases/652d1cbb316e1359cebd68cb/
indicator_1697618720799_Image.png",
"squareMeter": "50.91",
"id": "683114"
},
{
  "printlnReport": true,
  "_id": "652f9cbc7e32132d4093f42f",
  "property": "Sai Atlanta Eden World, Bhiwandi",
  "area": "797",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "5",
  "source": "magic_bricks",
  "expectedPrice": "4900000",
  "expectedRate": "6148.06",
  "builtUpExpectedRate": "5123.38",
  "image": "cases/652d1cbb316e1359cebd68cb/
indicator_1697618762203_Image.png",
  "squareMeter": "74.04",
  "id": "565550"
},
{
  "printlnReport": true,
  "_id": "652f9cbc7e32132d4093f430",
  "property": "Sai Eden World",
  "area": "548",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "Middle",
  "source": "Commonfloor.com",
  "expectedPrice": "3390000",
  "expectedRate": "6186.13",
  "builtUpExpectedRate": "5155.11",
  "image": "cases/652d1cbb316e1359cebd68cb/
indicator_1697618956823_Image.png",
```

```
    "squareMeter": "50.91",
    "id": "963216"
  }
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652eb2dc7e32132d4092ff8c",
    "name": "externalimg_r_1697559219010_1697559202457_image_2.jpg",
    "path": "cases/652d1cbb316e1359cebd68cb/
externalimg_r_1697559219010_1697559202457_image_2.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652eb2dc7e32132d4092ff8d",
    "name": "externalimg_r_1697559216519_1697559202457_image_0.jpg",
    "path": "cases/652d1cbb316e1359cebd68cb/
externalimg_r_1697559216519_1697559202457_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652eb2dc7e32132d4092ff8e",
    "name": "externalimg_r_1697559219847_1697559202457_image_3.jpg",
    "path": "cases/652d1cbb316e1359cebd68cb/
externalimg_r_1697559219847_1697559202457_image_3.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652eb2dc7e32132d4092ff8f",
    "name": "externalimg_r_1697559217280_1697559202457_image_1.jpg",
    "path": "cases/652d1cbb316e1359cebd68cb/
externalimg_r_1697559217280_1697559202457_image_1.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652eb2dc7e32132d4092ff90",
    "name": "externalimg_r_1697559224265_1697559202457_image_6.jpg",
```

```
    "path": "cases/652d1cbb316e1359cebd68cb/
externallmg_r_1697559224265_1697559202457_image_6.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652eb2dc7e32132d4092ff91",
    "name": "externallmg_r_1697559221896_1697559202457_image_4.jpg",
    "path": "cases/652d1cbb316e1359cebd68cb/
externallmg_r_1697559221896_1697559202457_image_4.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652eb2dc7e32132d4092ff92",
    "name": "externallmg_r_1697559226402_1697559202457_image_7.jpg",
    "path": "cases/652d1cbb316e1359cebd68cb/
externallmg_r_1697559226402_1697559202457_image_7.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652eb2dc7e32132d4092ff93",
    "name": "externallmg_r_1697559222990_1697559202457_image_5.jpg",
    "path": "cases/652d1cbb316e1359cebd68cb/
externallmg_r_1697559222990_1697559202457_image_5.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652eb2dc7e32132d4092ff94",
    "name": "externallmg_r_1697559228074_1697559202457_image_8.jpg",
    "path": "cases/652d1cbb316e1359cebd68cb/
externallmg_r_1697559228074_1697559202457_image_8.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652eb2dc7e32132d4092ff95",
    "name": "externallmg_r_1697559230072_1697559202457_image_9.jpg",
    "path": "cases/652d1cbb316e1359cebd68cb/
externallmg_r_1697559230072_1697559202457_image_9.jpg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652eb2dc7e32132d4092ff96",
    "name": "externallmg_r_1697559233913_1697559202457_image_11.jpg",
    "path": "cases/652d1cbb316e1359cebd68cb/
externallmg_r_1697559233913_1697559202457_image_11.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652eb2dc7e32132d4092ff97",
    "name": "externallmg_r_1697559231858_1697559202457_image_10.jpg",
    "path": "cases/652d1cbb316e1359cebd68cb/
externallmg_r_1697559231858_1697559202457_image_10.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652eb2dc7e32132d4092ff98",
    "name": "externallmg_r_1697559236800_1697559202457_image_12.jpg",
    "path": "cases/652d1cbb316e1359cebd68cb/
externallmg_r_1697559236800_1697559202457_image_12.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652eb2dc7e32132d4092ff99",
    "name": "externallmg_r_1697559242819_1697559202457_image_15.jpg",
    "path": "cases/652d1cbb316e1359cebd68cb/
externallmg_r_1697559242819_1697559202457_image_15.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652eb2dc7e32132d4092ff9a",
    "name": "externallmg_r_1697559240926_1697559202457_image_14.jpg",
    "path": "cases/652d1cbb316e1359cebd68cb/
externallmg_r_1697559240926_1697559202457_image_14.jpg",
    "orientation": "portrait"
  }
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "652eb2dc7e32132d4092ff9b",
      "name": "externallmg_r_1697559238377_1697559202457_image_13.jpg",
      "path": "cases/652d1cbb316e1359cebd68cb/
externallmg_r_1697559238377_1697559202457_image_13.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "652eb2dc7e32132d4092ff9c",
      "name": "externallmg_r_1697559244563_1697559202457_image_16.jpg",
      "path": "cases/652d1cbb316e1359cebd68cb/
externallmg_r_1697559244563_1697559202457_image_16.jpg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "652eb2dc7e32132d4092ff9d",
      "name": "externallmg_r_1697559142513_1697559170075_image_1.png",
      "path": "cases/652d1cbb316e1359cebd68cb/
externallmg_r_1697559142513_1697559170075_image_1.png",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "652eb2dc7e32132d4092ff9e",
      "name": "externallmg_r_1697559140699_1697559170075_image_0.jpg",
      "path": "cases/652d1cbb316e1359cebd68cb/
externallmg_r_1697559140699_1697559170075_image_0.jpg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "652eb2dc7e32132d4092ff9f",
      "name": "externallmg_r_1697559142867_1697559170075_image_2.jpg",
      "path": "cases/652d1cbb316e1359cebd68cb/
externallmg_r_1697559142867_1697559170075_image_2.jpg",
      "orientation": "portrait"
    }
  }
```

```
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "1696854326515_Calculation.xlsx",
    "filename": "1697619206043_1696854326515_Calculation.xlsx",
    "path": "cases/652d1cbb316e1359cebd68cb/
processingDocuments/1697619206043_1696854326515_Calculation.xlsx",
    "size": "1621337",
    "createdAt": "Wed Oct 18 2023 14:23:26 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  },
  {
    "originalname": "1 Commencement Certificates _ NA Order for plotted
development.pdf",
    "filename": "1697624019340_1_Commencement_Certificates__NA_Order_for_plot
ted_development.pdf",
    "path": "cases/652d1cbb316e1359cebd68cb/processingDocuments/1697624019340
_1_Commencement_Certificates__NA_Order_for_plotted_development.pdf",
    "size": "395153",
    "createdAt": "Wed Oct 18 2023 15:43:39 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eebe33f3dd69653a5837ae"
  },
  {
    "originalname": "1 Details of encumbrances.pdf",
    "filename": "1697624019354_1_Details_of_encumbrances.pdf",
    "path": "cases/652d1cbb316e1359cebd68cb/
processingDocuments/1697624019354_1_Details_of_encumbrances.pdf",
    "size": "357336",
    "createdAt": "Wed Oct 18 2023 15:43:39 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eebe33f3dd69653a5837ae"
  },
  {
    "originalname": "P51700003328.pdf",
    "filename": "1697624019363_P51700003328.pdf",
    "path": "cases/652d1cbb316e1359cebd68cb/
processingDocuments/1697624019363_P51700003328.pdf",
    "size": "154745",
    "createdAt": "Wed Oct 18 2023 15:43:39 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eebe33f3dd69653a5837ae"
  }
],
"remarks": [],
"createdAt": "2023-10-16T11:21:31.824Z",
"updatedAt": "2023-10-18T10:51:35.762Z",
"__v": 0,
```

"invoiceId": "652d1cbd316e1359cebd68e2",  
"fullAddress": "Residential Flat No. 803, 8th Floor, Building No 9, Atlanta Eden World,  
Phase 1, Pipe Line Road, Opp. PWD Office Bhadawad, Village - Temghar, Taluka -  
Bhiwandi, District - Thane, Bhiwandi, PIN - 421 302, State - Maharashtra, India",  
"updatedBy": "60f915d3f3dd69653a592199",  
"addressForMap": "",  
"caseReferredBy": "64535eb5ee347304f2a3005f",  
"contactPersonName": "Chetna Kulkarni",  
"email": "",  
"isExternal": "false",  
"isUrgent": "false",  
"ownershipShare": "",  
"purchaseValueAsPerDocument": "",  
"relationWithOwner": "Owner's representative",  
"siteVisitContactNo": "9619091161",  
"buildingServicesRate": "2600.00",  
"finalAreaType": "Carpet Area",  
"finalAsPerArea": "Agreement For Sale",  
"finalBuiltUpPercentage": "20",  
"finalCarpetConvertToBuiltUpPer": "20",  
"finalMeasurementType": "Sq. Ft.",  
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 457.00",  
"flatRate": "7000",  
"landOtherRate": "4400",  
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + WC + Bathroom +  
Passage",  
"carpetTotal": "469.24",  
"otherCarpetTotal": "92.86",  
"otherCompositionBuiltUpTotal": "0.00",  
"otherCompositionCarpetTotal": "93.01",  
"otherCompositionSaleableTotal": "0.00",  
"builtupPercentage": "10",  
"finalBuiltupArea": "618.48",  
"finalCarpetArea": "562.25",  
"finalSalableArea": "680.32",  
"salablePercentage": "10",  
"toBeAdded": "",  
"extendOfSiteRemark": "",  
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 469.00\nCupboard Area in Sq.  
Ft. = 17.00\nBalcony Area in sq. Ft. = 76.00\nTotal Area in sq. Ft. = 562.00\n(Area as  
per Actual site measurement)",  
"finalSaleablePercentage": "0",  
"landDetails": {  
 "holdType": {  
 "label": "Free Hold",  
 "value": "Free\_Hold"



```

    },
    "leaseDetails": {
      "lessorName": "",
      "lesseeName": "",
      "leasePremium": "",
      "leaseRent": "",
      "leasePeriod": 0,
      "leaseFrom": "",
      "leaseTo": "",
      "remainingLeasePeriod": 0,
      "leaseDate": ""
    }
  },
  "shopDetails": {
    "typeOfShops": null,
    "roadFacing": false,
    "mall": false
  },
  "siteVisitDate": "2023-10-17"
}

```

| <b>Name</b>            | <b>Length</b> | <b>Width</b> | <b>Total</b> |
|------------------------|---------------|--------------|--------------|
| Composition :          |               |              |              |
| Living Room            | 9'9"          | 14'10"       | 144.62       |
| Kitchen                | 9'8"          | 7'4"         | 70.89        |
| WC                     | 2'8"          | 4'8"         | 12.44        |
| Bathroom               | 3'9"          | 5'8"         | 21.25        |
| Bedroom                | 9'10"         | 18'5"        | 181.10       |
| Passage                | 8'5"          | 2'10"        | 23.85        |
| Other<br>Composition : |               |              |              |
| Cupboard               | 6'9"          | 1'7"         | 10.69        |
| Balcony Area           | 3'2"          | 9'10"        | 31.14        |
| Balcony Area           | 4'8"          | 9'7"         | 44.72        |