

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b80a"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f65be948726cc1419a7",
    "email": "kaushik.datta@sbi.co.in",
    "firstName": "KAUSHUIK",
    "mobileNo": "",
    "workMobileNo": "9757023640",
    "lastName": " DATTA "
  },
  "fees": {
    "type": "fixed"
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",
    "name": "Mumbai",
    "shortName": "VCIPL/Mumbai",
    "email": "vastukalamumbai@vastukala.com",
  }
}
```

```
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b80a",
  "branchCode": "000088",
  "type": "BRANCH",
  "name": "RACPC- Chinchpokli ",
  "email": "sbi.17889@sbi.co.in",
  "mobileNo": "022-23707514",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, Mumbai South Voltas
House, 'A', 1st Floor, Dr. Ambedkar Road, Chinchpokli (East), Mumbai - 400 033, State
- Maharashtra, Country - India.\r\n",
  "ledgerName": "STATE BANK OF INDIA - CHINCHPOKALI",
  "fax": "022-23707512 / 13",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "62727444afd7d55eddee092c",
    "role": "PICKUPPERSON",
    "firstName": "Shantilal",
```

```
"email": "shantilal@vastukala.org",
"lastName": "Patel",
"mobileNo": "9969039853",
"shortName": "SHP",
"workWithDocumentMaker": "",
"profilePhoto": "users/62727444afd7d55eddee092c/
profilePhoto_1668057663775_WhatsApp_Image_20221110_at_104853_AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "64c777a8a5c3051014f4dd1f",
"role": "SITEENGINEER",
"firstName": "Pratik",
"email": "pratikjain2277@gmail.com",
"lastName": "Jain",
"mobileNo": "9619286285",
"designation": "",
"shortName": "Pratik",
"workWithDocumentMaker": "6006d4ce5080a310ac1fdcf2"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "64dc7184ccaf1e7b7f637f47",
"role": "FRONTDESK",
"firstName": "Binumon",
"email": "binu@vastukala.org",
"lastName": "Moozhickal",
"mobileNo": "9930252906",
"designation": "Back Office Team Leader",
"shortName": "BS",
"workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
"profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "60f91b6f344e052188ffd1fc",
"role": "MAKER",
"firstName": "Jayaraja",
"email": "jayaraja@vastukala.org",
"lastName": "Acharya",
"mobileNo": "9867664219",
"designation": "",
"shortName": "JA",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
```

```
},
"checker": {
  "_id": "64dc7184ccaf1e7b7f637f47",
  "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg",
  "firstName": "Binumon",
  "lastName": "Moozhickal",
  "shortName": "BS",
  "email": "binu@vastukala.org",
  "designation": "Back Office Team Leader",
  "mobileNo": "9930252906",
  "role": "FRONTDESK",
  "type": "EMPLOYEE",
  "workWithDocumentMaker": "5ffe92d27737ca4d986b6453"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        },
        "_id": "60af80072ffdf65bcd658652",
        "number": "CAT-I-F-1763"
      }
    ]
  }
]
```

```
    },
    {
      "title": {
        "value": "Chartered_Engineer",
        "label": "Chartered Engineer"
      },
      "_id": "60af80072ffdf65bcd658653",
      "number": "AM161706-3"
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.236930650066267",
  "longitude": "72.86634076441774"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.86634076441774,
    19.236930650066267
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
```

```
    "dateTime": "2023-10-17T12:00:00.000Z",
    "remark": ""
  },
  {
    "dateTime": "2023-10-17T12:00:00.000Z",
    "remark": ""
  },
  {
    "dateTime": "2023-10-17T12:00:00.000Z",
    "remark": ""
  },
  {
    "dateTime": "2023-10-17T12:00:00.000Z",
    "remark": ""
  }
],
"visitedDate": [
  {
    "status": "COMPLETED",
    "dateTime": "2023-10-20",
    "remark": "MANUAL_IN_TASK"
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
```

```
"name": "Country",
"key": "country",
"value": "India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Dahisar",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "5",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
}
```

```
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Borivali",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Romell Allure",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Adjacent to Shree Krishna Nagar",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Near Nancy Colony",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
```



```
"key": "landmark",
"value": "",
"label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "C",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "2161A, 2161B, 2161C & 2161D",
  "label": true
},
}
```

```
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "506",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
```

```
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 066",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Borivali (East)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teal_wood_door_frame_with_flush_shutters",
    "label": "Teal wood door frame with flush shutters"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
```

```
},
"finishing": {
  "value": "Cement_Plastering_+_POP_Finish",
  "label": "Cement Plastering + POP Finish"
}
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MCGM",
    "label": "Municipal Corporation of Greater Mumbai (MCGM)"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Mumbai Public School",
    "west": "Vinayak CHS",
    "south": "Road No. 15",
    "east": "Nityanand Apartment "
  },
  "asPerDocumentAgreement": {
    "north": "Details not available",
    "west": "Details not available",
    "south": "Details not available",
    "east": "Details not available"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "",
      "west": "",
      "south": "",
      "east": ""
    }
  },
}
```

```
"asPerDocument": {
  "north": "",
  "west": "",
  "south": "",
  "east": ""
},
"isDisplay": false,
"title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As Occupancy Certificate is received it may be assumed
that the construction is as per Sanctioned Plan.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "No"
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "129070",
  "landRate": "56580",
  "igrImage": "cases/652e33c7316e1359cebeb805/igr_1698384983666_Image.png",
  "squareMeterGuideLineRate": "135524.00",
  "squareFeetGuideLineRate": "12591.00"
},
"igrFinalRate": {
  "depreciationPercentage": "0",
  "rate": "129070",
  "squareMeterGuideLineRate": "135524.00",
  "squareFeetGuideLineRate": "12591.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  }
},
```

```
"propertyOccupiedByList": {
  "value": "Owner_Occupied",
  "label": "Owner Occupied"
},
"monthlyRent": "28,000",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per MCGM norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Stilt Car Parking",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
```

```
"value": "Plain_Looking",
"label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2023",
  "fullDate": "1/1/2023"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
```

```
"value": "1",
"label": "Yes"
},
"appearanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenancelssues": {
"value": "0",
"label": "No"
},
"visibleDamageInBuilding": {
"value": "0",
"label": "No"
},
"systemOfAirConditioning": {
"value": "0",
"label": "No"
},
"provisionOfFirefighting": {
"value": "Information_not_available",
"label": "Information not available"
},
"groundStilt": {
"value": "stilt",
"label": "Stilt"
},
"yearOfConstructionAsPer": {
"value": "As_Per_Part_Occupancy_Certificate",
"label": "As Per Part Occupancy Certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "60",
"ageOfBuilding": "0",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "22",
"flatFloorNo": "5",
"noOfLifts": "4",
"noOfDwellingUnitsInBuilding": "7"
```



```
},
"finalPlinthArea": {
  "areaType": "Built Up",
  "area": "462.00",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Metro_Station",
      "label": "Metro Station"
    },
    "routeMapImg": "cases/652e33c7316e1359cebeb805/
routeMap_1698322349998_Image.png",
    "routeLat": "19.236667",
    "routeLng": "72.866389",
    "stationName": "Rashtriya Udyan",
    "routeDistance": "1.00 km"
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "fxbt6h",
      "name": "fxbt6h",
      "image": "cases/652e33c7316e1359cebeb805/
routeMap_1698322103378_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",

```

```
"totalshowcasesRate": "0",
"kitchenArrangementsQty": "0",
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "11340000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "11340000.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": ""
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```

    "isHideFloor": true,
    "status": false
  },
  "externalDevelopmentFinalFinishing": {
    "label": "External Development & Final Finishing",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": true,
    "status": false
  },
  "workCompleted": {
    "label": "Work Completed (%)",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": true,
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "5817042.00",
  "selectedBuildUpValue": "462.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "6533445b619c14402da8550e",
      "name":
"externallmg_1697858650868_IMG_20231020_142926_copy_900x1200.jpg",
      "path": "cases/652e33c7316e1359cebeb805/
externallmg_1697858650868_IMG_20231020_142926_copy_900x1200.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "6533445b619c14402da8550a",
      "name":
"externallmg_1697858650775_IMG_20231020_142907_copy_901x1200.jpg",
      "path": "cases/652e33c7316e1359cebeb805/
externallmg_1697858650775_IMG_20231020_142907_copy_901x1200.jpg",
      "orientation": "portrait"
    }
  ]
},
],

```

```
"externalPhotos": [
  {
    "status": false,
    "_id": "6533445b619c14402da85509",
    "name":
"externallmg_1697858650759_IMG_20231020_142815_copy_900x1200.jpg",
    "path": "cases/652e33c7316e1359cebeb805/
externallmg_1697858650759_IMG_20231020_142815_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6533445b619c14402da8550d",
    "name":
"externallmg_1697858650851_IMG_20231020_142915_copy_900x1200.jpg",
    "path": "cases/652e33c7316e1359cebeb805/
externallmg_1697858650851_IMG_20231020_142915_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6533445b619c14402da8550f",
    "name":
"externallmg_1697858650890_IMG_20231020_142928_copy_900x1200.jpg",
    "path": "cases/652e33c7316e1359cebeb805/
externallmg_1697858650890_IMG_20231020_142928_copy_900x1200.jpg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "6533445b619c14402da85503",
    "name": "Living Room",
    "path": "cases/652e33c7316e1359cebeb805/
externallmg_1697858650676_IMG_20231020_142208_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6533445b619c14402da85505",
    "name": "Living Room",
    "path": "cases/652e33c7316e1359cebeb805/
externallmg_1697858650699_IMG_20231020_142227_copy_1600x1200.jpg",
```

```
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6533445b619c14402da85507",
    "name": "Living Room",
    "path": "cases/652e33c7316e1359cebeb805/
externallmg_1697858650721_IMG_20231020_142422_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6533444c619c14402da854c9",
    "name": "Living Room",
    "path": "cases/652e33c7316e1359cebeb805/
externallmg_1697858636302_IMG_20231020_142147_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6533444c619c14402da854ca",
    "name": "Living Room",
    "path": "cases/652e33c7316e1359cebeb805/
externallmg_1697858636314_IMG_20231020_142153_copy_1600x1200.jpg",
    "orientation": "landscape"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "25573",
    "max": "27206"
  },
  "builtUpRateRange": {
    "min": "21311",
    "max": "22672"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  }
}
```

```
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```



```
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
```

```
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Approximate Rate Lead",
  "value": "APPROXIMATE_LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "420.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentId": [],
"_id": "652e33c7316e1359cebeb805",
"ownerName": "Mr. Sachin Kisan Rasal & Mrs. Varsha Sachin Rasal",
"ownerPhoneNo": "9930830871",
"appAddress": "506 Romell Allure\nc wing\nBorivali East\n",
"remark": "urgent \nAfter visit\n",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "11/07/2022",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "M/s. Romell Real Estate Pvt. Ltd.",
      "to": {
        "value": "The_Allottees",
        "label": "The Allottees"
      },
      "The_Allottees": "Mr. Sachin Kisan Rasal & Mrs. Varsha Sachin Rasal",
      "number": {
        "value": "Document_No",
        "label": "Document No"
      }
    }
  }
],
```

```
    "Document_No": "9890-2022"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1698324727528_Sale_Deed__2022.pdf",
  "path": "cases/652e33c7316e1359cebeb805/
document_1698324727528_Sale_Deed__2022.pdf",
  "id": "104360",
  "uploadedBy": "60f91b6f344e052188ffd1fc",
  "createdAt": "Thu Oct 26 2023 18:22:07 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "05/04/1999",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_Of_Greater_Mumbai",
      "label": "Municipal Corporation Of Greater Mumbai"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    }
  },
  "Document_No": "CHE / A-0734 / BP (WS) / AR / FCC / 7 / Amend"
},
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1698324813185_1_Commencement_Certificates__NA_Order_for_plotted_development.pdf",
  "path": "cases/652e33c7316e1359cebeb805/document_1698324813185_1_Commencement_Certificates__NA_Order_for_plotted_development.pdf",
  "id": "533157",
  "uploadedBy": "60f91b6f344e052188ffd1fc",
  "createdAt": "Thu Oct 26 2023 18:23:33 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "16/06/2023",
    "nameOfApprovingAuthority": {
```

```
    "value": "Municipal_Corporation_Of_Greater_Mumbai",
    "label": "Municipal Corporation Of Greater Mumbai"
  },
  "number": {
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "CHE / A-0734 / BP (WS) / AR / OCC / 1 / NEW"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1698324943486_2_Occupancy_Certificate__Completion_C
ertificate__Architects_certificate_of_completion_for_plotted_development.pdf",
"path": "cases/652e33c7316e1359cebeb805/document_1698324943486_2_Occupa
ncy_Certificate__Completion_Certificate__Architects_certificate_of_completion_for_plot
ted_development.pdf",
"id": "970767",
"uploadedBy": "60f91b6f344e052188ffd1fc",
"createdAt": "Thu Oct 26 2023 18:25:43 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "004445",
"createdBy": "62727444afd7d55eddee092c",
"caseHistory": [
  {
    "id": "201660",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Oct 17 2023 12:42:07 GMT+0530 (India Standard Time)"
  }
]
],
"owners": [
  {
    "name": "Mr. Sachin Kisan Rasal & Mrs. Varsha Sachin Rasal",
    "phone": "9930830871",
    "ownershipShare": "",
    "email": "",
    "id": "338201"
  }
]
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
```

```
    "label": "Square Feet"
  },
  "id": "266970",
  "name": "Living Room",
  "length": "15.67",
  "length1": "15",
  "length2": "8",
  "width": "9.00",
  "width1": "9",
  "width2": "00",
  "totalArea": "141.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "141.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Kitchen",
  "length": "6.92",
  "length1": "6",
  "length2": "11",
  "width": "8.92",
  "width1": "8",
  "width2": "11",
  "totalArea": "61.67",
  "images": [],
  "extraAreas": [],
  "finalArea": "61.67"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Passage",
  "length": "5.33",
  "length1": "5",
  "length2": "4",
  "width": "3.25",
  "width1": "3",
  "width2": "3",
```

```
"totalArea": "17.33",
"images": [],
"extraAreas": [],
"finalArea": "17.33"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Toilet",
  "length": "6.83",
  "length1": "6",
  "length2": "10",
  "width": "3.67",
  "width1": "3",
  "width2": "8",
  "totalArea": "25.06",
  "images": [],
  "extraAreas": [],
  "finalArea": "25.06"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Bedroom",
  "length": "12.42",
  "length1": "12",
  "length2": "5",
  "width": "8.50",
  "width1": "8",
  "width2": "6",
  "totalArea": "105.54",
  "images": [],
  "extraAreas": [],
  "finalArea": "105.54"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },

```

```
"id": "5",
"name": "Toilet",
"length": "7.42",
"length1": "7",
"length2": "5",
"width": "3.83",
"width1": "3",
"width2": "10",
"totalArea": "28.43",
"images": [],
"extraAreas": [],
"finalArea": "28.43"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "value": "60af48bf2ffdf65bcd6585fa",
    "label": "Agreement for sale"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "946181",
  "selectAreaTypeDocument": "Carpet",
  "totalAreaDocument": "420",
  "squareMeterArea": "39.02",
  "docFinalBuiltUp": "462",
  "docFinalBuiltUpSquareMeter": "42.922000000000004",
  "docBultupPercentage": "10",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "653b4c7563432b55f3da085d",
  "property": "Residential Flat ",
  "area": "408",
  "builtUpPercentage": "20",
```

```
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "8",
"source": "Index_no.2",
"expectedPrice": "11100000.00",
"expectedRate": "27205.88",
"builtUpExpectedRate": "22671.57",
"image": "cases/652e33c7316e1359cebeb805/
indicator_1698384524215_Image.png",
"squareMeter": "37.90",
"id": "330599"
},
{
  "printlnReport": true,
  "_id": "653b4c7563432b55f3da085e",
  "property": "Residential Flat",
  "area": "586.52",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "source": "Index_no.2",
  "expectedPrice": "15700000.00",
  "expectedRate": "26768.06",
  "builtUpExpectedRate": "22306.84",
  "image": "cases/652e33c7316e1359cebeb805/
indicator_1698384688751_Image.png",
  "squareMeter": "54.49",
  "id": "108463"
},
{
  "printlnReport": true,
  "_id": "653b4c7563432b55f3da085f",
  "property": "Residential Flat ",
  "area": "567",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "Housing.Com",
  "expectedPrice": "14500000.00",
  "expectedRate": "25573.19",
  "builtUpExpectedRate": "21310.99",
  "image": "cases/652e33c7316e1359cebeb805/
indicator_1698384754975_Image.png",
```



```
"squareMeter": "52.68",
"id": "637220"
},
{
  "printlnReport": true,
  "_id": "653b4c7563432b55f3da0860",
  "property": "Residential Flat ",
  "area": "408",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "square_yards",
  "expectedPrice": "11100000",
  "expectedRate": "27205.88",
  "builtUpExpectedRate": "22671.57",
  "image": "cases/652e33c7316e1359cebeb805/
indicator_1698384854829_Image.png",
  "squareMeter": "37.90",
  "id": "526979"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6533444c619c14402da854c8",
    "name":
"externalImg_1697858636290_IMG_20231020_142141_copy_1600x1200.jpg",
    "path": "cases/652e33c7316e1359cebeb805/
externalImg_1697858636290_IMG_20231020_142141_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6533444c619c14402da854c9",
    "name":
"externalImg_1697858636302_IMG_20231020_142147_copy_1600x1200.jpg",
    "path": "cases/652e33c7316e1359cebeb805/
externalImg_1697858636302_IMG_20231020_142147_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "6533444c619c14402da854ca",
    "name":
"externallmg_1697858636314_IMG_20231020_142153_copy_1600x1200.jpg",
    "path": "cases/652e33c7316e1359cebeb805/
externallmg_1697858636314_IMG_20231020_142153_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6533444c619c14402da854cb",
    "name":
"externallmg_1697858636322_IMG_20231020_142156_copy_900x1200.jpg",
    "path": "cases/652e33c7316e1359cebeb805/
externallmg_1697858636322_IMG_20231020_142156_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6533444c619c14402da854cc",
    "name":
"externallmg_1697858636335_IMG_20231020_142200_copy_1600x1200.jpg",
    "path": "cases/652e33c7316e1359cebeb805/
externallmg_1697858636335_IMG_20231020_142200_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6533445b619c14402da85501",
    "name":
"externallmg_1697858650661_IMG_20231020_142202_copy_1600x1200.jpg",
    "path": "cases/652e33c7316e1359cebeb805/
externallmg_1697858650661_IMG_20231020_142202_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6533445b619c14402da85502",
    "name":
"externallmg_1697858650669_IMG_20231020_142204_copy_1600x1200.jpg",
    "path": "cases/652e33c7316e1359cebeb805/
externallmg_1697858650669_IMG_20231020_142204_copy_1600x1200.jpg",
    "orientation": "landscape"
  }
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6533445b619c14402da85503",
      "name":
"externallmg_1697858650676_IMG_20231020_142208_copy_1600x1200.jpg",
      "path": "cases/652e33c7316e1359cebeb805/
externallmg_1697858650676_IMG_20231020_142208_copy_1600x1200.jpg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6533445b619c14402da85504",
      "name":
"externallmg_1697858650690_IMG_20231020_142224_copy_1600x1200.jpg",
      "path": "cases/652e33c7316e1359cebeb805/
externallmg_1697858650690_IMG_20231020_142224_copy_1600x1200.jpg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6533445b619c14402da85505",
      "name":
"externallmg_1697858650699_IMG_20231020_142227_copy_1600x1200.jpg",
      "path": "cases/652e33c7316e1359cebeb805/
externallmg_1697858650699_IMG_20231020_142227_copy_1600x1200.jpg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6533445b619c14402da85506",
      "name":
"externallmg_1697858650705_IMG_20231020_142420_copy_900x1200.jpg",
      "path": "cases/652e33c7316e1359cebeb805/
externallmg_1697858650705_IMG_20231020_142420_copy_900x1200.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6533445b619c14402da85507",
      "name":
"externallmg_1697858650721_IMG_20231020_142422_copy_900x1200.jpg",
```

```
    "path": "cases/652e33c7316e1359cebeb805/
externallmg_1697858650721_IMG_20231020_142422_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6533445b619c14402da85508",
    "name":
"externallmg_1697858650742_IMG_20231020_142813_copy_900x1200.jpg",
    "path": "cases/652e33c7316e1359cebeb805/
externallmg_1697858650742_IMG_20231020_142813_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6533445b619c14402da85509",
    "name":
"externallmg_1697858650759_IMG_20231020_142815_copy_900x1200.jpg",
    "path": "cases/652e33c7316e1359cebeb805/
externallmg_1697858650759_IMG_20231020_142815_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6533445b619c14402da8550a",
    "name":
"externallmg_1697858650775_IMG_20231020_142907_copy_901x1200.jpg",
    "path": "cases/652e33c7316e1359cebeb805/
externallmg_1697858650775_IMG_20231020_142907_copy_901x1200.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6533445b619c14402da8550b",
    "name":
"externallmg_1697858650797_IMG_20231020_142911_copy_900x1200.jpg",
    "path": "cases/652e33c7316e1359cebeb805/
externallmg_1697858650797_IMG_20231020_142911_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "6533445b619c14402da8550c",
  "name":
"externallmg_1697858650824_IMG_20231020_142912_copy_900x1200.jpg",
  "path": "cases/652e33c7316e1359cebeb805/
externallmg_1697858650824_IMG_20231020_142912_copy_900x1200.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6533445b619c14402da8550d",
  "name":
"externallmg_1697858650851_IMG_20231020_142915_copy_900x1200.jpg",
  "path": "cases/652e33c7316e1359cebeb805/
externallmg_1697858650851_IMG_20231020_142915_copy_900x1200.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6533445b619c14402da8550e",
  "name":
"externallmg_1697858650868_IMG_20231020_142926_copy_900x1200.jpg",
  "path": "cases/652e33c7316e1359cebeb805/
externallmg_1697858650868_IMG_20231020_142926_copy_900x1200.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6533445b619c14402da8550f",
  "name":
"externallmg_1697858650890_IMG_20231020_142928_copy_900x1200.jpg",
  "path": "cases/652e33c7316e1359cebeb805/
externallmg_1697858650890_IMG_20231020_142928_copy_900x1200.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6533445b619c14402da85510",
  "name":
"externallmg_1697858650921_IMG_20231020_200235_copy_900x1200.jpg",
  "path": "cases/652e33c7316e1359cebeb805/
externallmg_1697858650921_IMG_20231020_200235_copy_900x1200.jpg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6533445b619c14402da85511",
    "name":
    "externallmg_1697858650966_IMG_20231020_200503_copy_1600x1200.jpg",
    "path": "cases/652e33c7316e1359cebeb805/
    externallmg_1697858650966_IMG_20231020_200503_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6533445b619c14402da85512",
    "name":
    "externallmg_1697858650978_IMG_20231020_200559_copy_1600x1200.jpg",
    "path": "cases/652e33c7316e1359cebeb805/
    externallmg_1697858650978_IMG_20231020_200559_copy_1600x1200.jpg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Sachin K Rasal - Flat No. 506 - SBI.xlsx",
    "filename": "1697539349944_Sachin_K_Rasal__Flat_No_506____SBI.xlsx",
    "path": "cases/652e33c7316e1359cebeb805/
    processingDocuments/1697539349944_Sachin_K_Rasal__Flat_No_506____SBI.xlsx",
    "size": "3080322",
    "createdAt": "Tue Oct 17 2023 16:12:30 GMT+0530 (India Standard Time)",
    "uploadedBy": "64dc7184ccaf1e7b7f637f47"
  }
],
"remarks": [
  {
    "createdBy": {
      "_id": "64dc7184ccaf1e7b7f637f47",
      "role": "FRONTDESK",
      "firstName": "Binumon",
      "lastName": "Moozhickal",
      "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
      profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
    },
    "workType": "RATE_VERIFY",
```

```
"display": true,
"status": true,
"_id": "652e652f79133f5f41feb9d1",
"note": "Value given for confirmation",
"taskId": "652e33c7316e1359cebeb847",
"createdAt": "2023-10-17T10:42:55.045Z"
}
],
"createdAt": "2023-10-17T07:12:07.025Z",
"updatedAt": "2023-10-27T07:19:14.687Z",
"__v": 0,
"updatedBy": "64dc7184ccaf1e7b7f637f47",
"fullAddress": "Residential Flat No. 506, 5th Floor, Wing - C, Romell Allure, Adjacent to
Shree Krishna Nagar, Near Nancy Colony, Village - Dahisar, Borivali (East), Taluka -
Borivali, District - Mumbai Suburban, PIN - 400 066, State - Maharashtra, India",
"addressForMap": "",
"caseReferredBy": "62727444afd7d55eddee092c",
"contactPersonName": "Mrs. Varsha Sachin Rasal ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9930830871",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Passage + 2 Toilet",
"carpetTotal": "379.03",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "416.93",
"finalCarpetArea": "379.03",
"finalSalableArea": "416.93",
"salablePercentage": "0",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalSaleablePercentage": "0",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 420.00",
"buildingServicesRate": "2800",
"flatRate": "27000",
"landOtherRate": "24200",
```

```
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"reportGeneratedDate": "Fri Oct 27 2023 11:10:23 GMT+0530 (India Standard Time)",
"siteVisitDate": "2023-10-20"
}
```

Name	Length	Width	Total
Composition :			
Living Room	15'8"	9'00"	141.00
Kitchen	6'11"	8'11"	61.67
Passage	5'4"	3'3"	17.33
Toilet	6'10"	3'8"	25.06
Bedroom	12'5"	8'6"	105.54
Toilet	7'5"	3'10"	28.43
Other Composition :			