

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b951"
    },
    "type": "CREDITOFFICER",
    "_id": "635f732fe363ef22db2f1c80",
    "firstName": "Ravindra Sir",
    "lastName": "sir",
    "mobileNo": "",
    "email": "me1@me.com",
    "workMobileNo": "7738642220"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "16500000",
    "discussWithPerson": "Ravindra Sir",
    "expectedFees": 8250,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b951",
  "branchCode": "000167",
  "type": "BRANCH",
  "name": "RACPC Belapur ",
  "email": "sbi.14677@sbi.co.in",
  "mobileNo": "022-27524090",
  "alternateMobileNo": "",
  "address": "Estate Department Corporate Centre, 4th Floor, CIDCO Tower No. 4,
Railway Station Building, C.B.D. Belapur, Navi Mumbai - 400 614, State - Maharashtra,
Country - India.",
  "ledgerName": "STATE BANK OF INDIA - CBD Estate Department",
  "fax": "022 2757 7002",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7189d2ffdf65bcd65882b",
  "role": "PICKUPPERSON",
  "firstName": "Ravindra",
  "email": "ravindrakasare186@gmail.com",
  "lastName": "Kasare",
  "mobileNo": "9167204055",
  "shortName": "RBK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60b7189d2ffdf65bcd65882b\\
\\profilePhoto_1622701555488_WhatsApp Image 2021-06-03 at 11.46.40 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f9343b45132d6a6bdd96e8",
  "role": "SITEENGINEER",
  "firstName": "Rajesh",
  "email": "rajeshb.ghadi@gmail.com",
  "lastName": "Ghadi",
  "mobileNo": "8652092666",
  "designation": "",
  "shortName": "RHG",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "627221f4afd7d55eddeddcb4",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Prajakta",
  "email": "prajakta@vastukala.org",
  "lastName": "Patil",
  "mobileNo": "9769797568",
  "designation": "",
  "shortName": "P",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f91b6f344e052188ffd1fc",
  "role": "MAKER",
  "firstName": "Jayaraja",
  "email": "jayaraja@vastukala.org",
  "lastName": "Acharya",
  "mobileNo": "9867664219",
```

```
"designation": "",
"shortName": "JA",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "627221f4afd7d55eddeddcb4",
"role": "MAKER + RATE VERIFIER + CHEAKER",
"firstName": "Prajakta",
"email": "prajakta@vastukala.org",
"lastName": "Patil",
"mobileNo": "9769797568",
"designation": "",
"shortName": "P",
"workWithDocumentMaker": "",
"profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.07587576355039",
  "longitude": "72.99646353558225"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.99646353558225,
    19.07587576355039
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-10-17T11:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-10-17T11:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-10-17T11:30:00.000Z",
      "remark": ""
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-18",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
```

```
"status": true,
"name": "Country",
"key": "country",
"value": "India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Vashi",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "1",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
```

```
"label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "26",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Reshma Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "9A",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
```



```
"name": "Landmark",
"key": "landmark",
"value": "",
"label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
}
```

```
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "6",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
```

```
"key": "policeStation",
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 703",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Navi Mumbai",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "CeramicTileFlooring",
    "label": "Ceramic Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_Frame_With_Flush_Shutters",
    "label": "Teak Wood Door Frame With Flush Shutters"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_"
```

```
"label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
},
"finishing": {
  "value": "Cement_Plastering",
  "label": "Cement Plastering"
}
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "CIDCO",
    "label": "City Industrial Development Corporation of Maharashtra"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Bulphoe CHSL",
    "west": "Internal Road / Vishwa CHSL",
    "south": "Shiv Vishnu Mandir Marg",
    "east": "Shiv Vishnu Mandir Marg"
  },
  "asPerDocumentAgreement": {
    "north": "Details not available",
    "west": "Details not available",
    "south": "Details not available",
    "east": "Details not available"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "",
      "west": "",
      "south": "",
      "east": ""
    }
  }
}
```

```
    },
    "asPerDocument": {
      "north": "",
      "west": "",
      "south": "",
      "east": ""
    },
    "isDisplay": false,
    "title": "Boundaries of The Flat"
  },
  "extraDetailOfProperty": "",
  "dateOfIssusApprovePlan": "As Occupancy Certificate is received it may be assumed
that the construction is as per Sanctioned Plan.",
  "approvePlanVerified": "N.A.",
  "empanelledOfApprovePlan": "N.A."
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "55.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "17401.5",
  "depreciatedBuildingRate": "1201.5"
},
"igrRate": {
  "propertyName": "Vashi",
  "rate": "125600",
  "landRate": "44700",
  "igrImage": "cases/652e671779133f5f41fec5de/igr_1697775240044_Image.png",
  "squareMeterGuideLineRate": "119320.00",
  "squareFeetGuideLineRate": "11085.00"
},
"igrFinalRate": {
  "depreciationPercentage": "63",
  "rate": "8520.00",
  "squareFeetGuideLineRate": "8520.00",
  "squareMeterGuideLineRate": "91711.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  }
},
"propertyTypeOfUseList": {
  "value": "Residential_Purpose",
  "label": "Residential Purpose"
}
```

```
},
"propertyOccupiedByList": {
  "value": "Vacant",
  "label": "Vacant"
},
"monthlyRent": "27000",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per CIDCO norms",
"tenantName": "",
"maintenanceOfFlat": "Normal"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\\_Thk._Brick_Masonry",
    "label": "6\\ Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Open Car Parking Space",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  }
},
```

```
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "1986",
  "fullDate": "1/1/1986"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
```

```
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "0",
  "label": "No"
},
"provisionOfFirefighting": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "23",
"ageOfBuilding": "37",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "3",
"flatFloorNo": "1",
"noOfLifts": "",
```



```
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "areaType": "Built Up",
  "area": "754.00",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area as per Index- II"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/652e671779133f5f41fec5de/
routeMap_1697784626627_Image.png",
    "routeLat": "19.075639",
    "routeLng": "72.996389",
    "stationName": "Vashi",
    "routeDistance": "1.6 km"
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "kw2eut",
      "name": "kw2eut",
      "image": "cases/652e671779133f5f41fec5de/
routeMap_1697784507487_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
```

```
"showcasesRate": "0",
"totalshowcasesRate": "0",
"kitchenArrangementsQty": "0",
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "13121108.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "13121108.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Fri Oct 20 2023 14:03:37 GMT+0530 (India Standard Time)",
  "number": "2303117",
  "dayCount": "12",
  "monthCount": "314",
  "generatedBy": "627221f4afd7d55eddeddcb4"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": true
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
```

```
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "6424080.00",
  "selectedBuildUpValue": "754.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "65309f217e32132d4094e760",
      "name": "externallmg_r_1697685281575_01256___20231018_112616AM___line4___line1_____hnbm_lmjn___org.jpg",
      "path": "cases/652e671779133f5f41fec5de/externallmg_r_1697685281575_01256___20231018_112616AM___line4___line1_____hnbm_lmjn___org.jpg",
      "orientation": "landscape"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "65309f217e32132d4094e75b",
      "name": "externallmg_1697685281646_01271___20231018Wed_113720AM___lin
```

```
e4__line1_____hnbm_lmjn___org.jpg",
  "path": "cases/652e671779133f5f41fec5de/externallmg_1697685281646_01271___
_20231018Wed_113720AM__line4__line1_____hnbm_lmjn___org.jpg",
  "orientation": "landscape"
}
],
"externalPhotos": [
  {
    "status": false,
    "_id": "65309f217e32132d4094e75f",
    "name": "externallmg_r_1697685281567_01255___20231018_112614AM__line4
__line1_____hnbm_lmjn___org.jpg",
    "path": "cases/652e671779133f5f41fec5de/externallmg_r_1697685281567_01255
___20231018_112614AM__line4__line1_____hnbm_lmjn___org.jpg",
    "orientation": "landscape"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "65309f217e32132d4094e766",
    "name": "Living Room",
    "path": "cases/652e671779133f5f41fec5de/externallmg_r_1697685281611_01262
___20231018_112935AM__line4__line1_____hnbm_lmjn___org.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65309f217e32132d4094e769",
    "name": "Living Room",
    "path": "cases/652e671779133f5f41fec5de/externallmg_r_1697685281629_01266
___20231018_112951AM__line4__line1_____hnbm_lmjn___org.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65309f217e32132d4094e76c",
    "name": "Living Room",
    "path": "cases/652e671779133f5f41fec5de/externallmg_r_1697685281642_01270
___20231018_113002AM__line4__line1_____hnbm_lmjn___org.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
```

```
    "_id": "65309f217e32132d4094e76d",
    "name": "Living Room",
    "path": "cases/652e671779133f5f41fec5de/externallmg_r_1697685281636_01268
    20231018_112957AM__line4__line1_____hnbm_lmjn__org.jpg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": null,
    "max": null
  },
  "builtUpRateRange": {
    "min": null,
    "max": null
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
```



```
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "754.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentId": [],
"_id": "652e671779133f5f41fec5de",
```

```
"ownerName": "Sharad Jagannath Pawar & Pallavi Sharad Pawar",
"ownerPhoneNo": "9619916623",
"appAddress": "flat no. A. 06 first floor Reshma co. op society sector no 9 A vashi ",
"remark": "Bankar Nilesh kuthe 83t6008675",
"documents": [
  {
    "documentType": {
      "value": "60ae1251aa6d152c1801b31a",
      "label": "Seller's Agreement for Sale"
    },
    "inputs": {
      "documentDate": "07/07/2005",
      "from": {
        "value": "Transferor",
        "label": "Transferor"
      },
      "Transferor": "Shri. Virendarnath Choudhary",
      "to": {
        "value": "transferee",
        "label": "transferee"
      },
      "transferee": "Mrs. Neena Deepak Nair "
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "719354",
    "path": "cases/652e671779133f5f41fec5de/
document_1697539776282_Sharad_pawar_sbi_Racpc_belapur.pdf",
    "fileName": "document_1697539776282_Sharad_pawar_sbi_Racpc_belapur.pdf"
  },
  {
    "documentType": {
      "value": "60ae1247aa6d152c1801b2ea",
      "label": "Commencement Certificate"
    },
    "inputs": {
      "documentDate": "05/04/1982",
      "nameOfApprovingAuthority": {
        "value": "City_and_Industrial_Development_Corp_Of_Maharashtra_ltd.",
        "label": "City and Industrial Development Corp Of Maharashtra Ltd."
      },
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "BP / V / Sec-9A / 26 / 384"
    }
  }
]
```

```
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1697786162800_Commencement_Certificate.pdf",
    "path": "cases/652e671779133f5f41fec5de/
document_1697786162800_Commencement_Certificate.pdf",
    "id": "167385",
    "uploadedBy": "60f91b6f344e052188ffd1fc",
    "createdAt": "Fri Oct 20 2023 12:46:02 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124baa6d152c1801b2fd",
      "label": "Occupancy Certificate"
    },
    "inputs": {
      "documentDate": "25/03/1986",
      "nameOfApprovingAuthority": {
        "value": "City_and_Industrial_Development_Corp_Of_Maharashtra_Ltd.",
        "label": "City and Industrial Development Corp Of Maharashtra Ltd."
      },
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "BP / V / 9A / 26 / 417"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1697786256145_Occupancy_Certificate.pdf",
    "path": "cases/652e671779133f5f41fec5de/
document_1697786256145_Occupancy_Certificate.pdf",
    "id": "725186",
    "uploadedBy": "60f91b6f344e052188ffd1fc",
    "createdAt": "Fri Oct 20 2023 12:47:36 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae1246aa6d152c1801b2e4",
      "label": "Index- II"
    },
    "inputs": {
      "documentDate": "17/10/2023",
      "from": {
        "value": "Seller",
        "label": "Seller"
      }
    }
  }
}
```

```
    },
    "Seller": "Neena Deepak Nair",
    "to": {
      "value": "Purchaser",
      "label": "Purchaser"
    },
    "Purchaser": "Sharad Jagannath Pawar & Pallavi Sharad Pawar",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "20023/2023"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1697786505146_63303.pdf",
  "path": "cases/652e671779133f5f41fec5de/document_1697786505146_63303.pdf",
  "id": "536683",
  "uploadedBy": "60f91b6f344e052188ffd1fc",
  "createdAt": "Fri Oct 20 2023 12:51:45 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "004454",
"createdBy": "60b7189d2ffdf65bcd65882b",
"caseHistory": [
  {
    "id": "283892",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Oct 17 2023 16:21:03 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Sharad Jagannath Pawar & Pallavi Sharad Pawar",
    "phone": "9619916623",
    "ownershipShare": "",
    "email": "",
    "id": "615008"
  }
],
"proposePurchasers": [
  {
    "name": "Sharad Jagannath Pawar & Pallavi Sharad Pawar",
    "phone": "",
    "email": "",
```

```
    "ownershipShare": ""
  }
],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "394346",
    "name": "Living Room",
    "length": "9.92",
    "length1": "9",
    "length2": "11",
    "width": "18.58",
    "width1": "18",
    "width2": "7",
    "totalArea": "184.28",
    "images": [],
    "extraAreas": [],
    "finalArea": "184.28"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "name": "Kitchen",
    "length": "6.58",
    "length1": "6",
    "length2": "7",
    "width": "9.42",
    "width1": "9",
    "width2": "5",
    "totalArea": "61.99",
    "images": [],
    "extraAreas": [],
    "finalArea": "61.99"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
  },
}
```

```
"id": "2",
"name": "Bedroom",
"length": "9.33",
"length1": "9",
"length2": "4",
"width": "13.17",
"width1": "13",
"width2": "2",
"totalArea": "122.89",
"images": [],
"extraAreas": [],
"finalArea": "122.89"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bedroom",
  "length": "9.83",
  "length1": "9",
  "length2": "10",
  "width": "9.75",
  "width1": "9",
  "width2": "9",
  "totalArea": "95.87",
  "images": [],
  "extraAreas": [],
  "finalArea": "95.87"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "3.00",
  "length1": "3",
  "length2": "00",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "12.00",
  "images": [],
```

```
"extraAreas": [],
"finalArea": "12.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Passage",
  "length": "",
  "length1": "3",
  "length2": "0",
  "width": "",
  "width1": "4",
  "width2": "0",
  "totalArea": "12.00",
  "images": [],
  "finalArea": "12.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Bathroom",
  "length": "6.58",
  "length1": "6",
  "length2": "7",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "26.33",
  "images": [],
  "extraAreas": [],
  "finalArea": "26.33"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Balcony",
```

```
"length": "3.50",
"length1": "3",
"length2": "6",
"width": "9.83",
"width1": "9",
"width2": "10",
"totalArea": "34.42",
"images": [],
"extraAreas": [],
"finalArea": "34.42"
}
],
"otherComposition": [
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Dry Balcony",
    "value": "Dry_Balcony"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "length1": "10",
  "length2": "8",
  "length": "",
  "width1": "2",
  "width2": "10",
  "width": "",
  "totalArea": "30.22",
  "percentageBeforeTotal": "30.22",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "30.22"
}
],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "value": "60ae1246aa6d152c1801b2e4",
```



```
    "label": "Index- II"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "534666",
  "selectAreaTypeDocument": "Built_Up",
  "totalAreaDocument": "754",
  "squareMeterArea": "70.05",
  "docFinalBuiltUp": "0.00",
  "docFinalBuiltUpSquareMeter": "0.00",
  "docBultupPercentage": "",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": false,
    "_id": "6531fe91619c14402da6492b",
    "property": "Sector 9A, Vashi, Navi Mumbai",
    "area": "1500",
    "builtUpPercentage": "0",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Built_Up",
    "source": "https://www.99acres.com/",
    "expectedPrice": "25500000",
    "expectedRate": "17000.00",
    "builtUpExpectedRate": "0.00",
    "image": "cases/652e671779133f5f41fec5de/
indicator_1697774918996_Image.png",
    "squareMeter": "139.35",
    "id": "925124"
  },
  {
    "printlnReport": false,
    "_id": "6531fe91619c14402da6492c",
    "property": "Sector 9A, Vashi, Navi Mumbai",
    "area": "700",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
```

```
"areaType": "Carpet",
"source": "https://www.99acres.com/",
"expectedPrice": "16000000",
"expectedRate": "22857.14",
"builtUpExpectedRate": "19047.62",
"image": "cases/652e671779133f5f41fec5de/
indicator_1697774963240_Image.png",
"squareMeter": "65.03",
"id": "699966"
},
{
  "printlnReport": false,
  "_id": "6531fe91619c14402da6492d",
  "property": "Sector 9A, Vashi, Navi Mumbai",
  "area": "750",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "https://www.99acres.com/",
  "expectedPrice": "17000000",
  "expectedRate": "22666.67",
  "builtUpExpectedRate": "18888.89",
  "image": "cases/652e671779133f5f41fec5de/
indicator_1697774984137_Image.png",
  "squareMeter": "69.68",
  "id": "313904"
},
{
  "printlnReport": false,
  "_id": "6531fe91619c14402da6492e",
  "property": "Reshma CHSL, Sector 9A, Vashi",
  "area": "560",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Built_Up",
  "source": "Index_no.2",
  "expectedPrice": "8500000",
  "expectedRate": "15178.57",
  "builtUpExpectedRate": "0.00",
  "image": "cases/652e671779133f5f41fec5de/
indicator_1697775167810_Image.png",
  "squareMeter": "52.03",
  "id": "625272"
}
```

```
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65309f217e32132d4094e75b",
    "name": "externallmg_1697685281646_01271___20231018Wed_113720AM___line4__line1_____hnbm_lmjn___org.jpg",
    "path": "cases/652e671779133f5f41fec5de/externallmg_1697685281646_01271___20231018Wed_113720AM___line4__line1_____hnbm_lmjn___org.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65309f217e32132d4094e75c",
    "name": "externallmg_1697685281650_IMG_20231019_075654.jpg",
    "path": "cases/652e671779133f5f41fec5de/externallmg_1697685281650_IMG_20231019_075654.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65309f217e32132d4094e75d",
    "name": "externallmg_1697685281665_IMG_20231019_075702.jpg",
    "path": "cases/652e671779133f5f41fec5de/externallmg_1697685281665_IMG_20231019_075702.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65309f217e32132d4094e75e",
    "name": "externallmg_1697685281670_Screenshot_20231019_075744.jpg",
    "path": "cases/652e671779133f5f41fec5de/externallmg_1697685281670_Screenshot_20231019_075744.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65309f217e32132d4094e75f",
    "name": "externallmg_r_1697685281567_01255___20231018_112614AM___line4__line1_____hnbm_lmjn___org.jpg",
    "path": "cases/652e671779133f5f41fec5de/externallmg_r_1697685281567_01255_
```

```
__20231018_112614AM__line4__line1____hnbm_lmjn__org.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65309f217e32132d4094e760",
  "name": "externallmg_r_1697685281575_01256__20231018_112616AM__line4_
_line1____hnbm_lmjn__org.jpg",
  "path": "cases/652e671779133f5f41fec5de/externallmg_r_1697685281575_01256_
__20231018_112616AM__line4__line1____hnbm_lmjn__org.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65309f217e32132d4094e761",
  "name": "externallmg_r_1697685281592_01258__20231018_112622AM__line4_
_line1____hnbm_lmjn__org.jpg",
  "path": "cases/652e671779133f5f41fec5de/externallmg_r_1697685281592_01258_
__20231018_112622AM__line4__line1____hnbm_lmjn__org.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65309f217e32132d4094e762",
  "name": "externallmg_r_1697685281585_01257__20231018_112620AM__line4_
_line1____hnbm_lmjn__org.jpg",
  "path": "cases/652e671779133f5f41fec5de/externallmg_r_1697685281585_01257_
__20231018_112620AM__line4__line1____hnbm_lmjn__org.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65309f217e32132d4094e763",
  "name": "externallmg_r_1697685281604_01260__20231018_112922AM__line4_
_line1____hnbm_lmjn__org.jpg",
  "path": "cases/652e671779133f5f41fec5de/externallmg_r_1697685281604_01260_
__20231018_112922AM__line4__line1____hnbm_lmjn__org.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
  "_id": "65309f217e32132d4094e764",
  "name": "externalimg_r_1697685281608_01261___20231018_112925AM___line4_
_line1_____hnbm_lmjn___org.jpg",
  "path": "cases/652e671779133f5f41fec5de/externalimg_r_1697685281608_01261_
_20231018_112925AM___line4__line1_____hnbm_lmjn___org.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65309f217e32132d4094e765",
  "name": "externalimg_r_1697685281599_01259___20231018_112919AM___line4_
_line1_____hnbm_lmjn___org.jpg",
  "path": "cases/652e671779133f5f41fec5de/externalimg_r_1697685281599_01259_
_20231018_112919AM___line4__line1_____hnbm_lmjn___org.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65309f217e32132d4094e766",
  "name": "externalimg_r_1697685281611_01262___20231018_112935AM___line4_
_line1_____hnbm_lmjn___org.jpg",
  "path": "cases/652e671779133f5f41fec5de/externalimg_r_1697685281611_01262_
_20231018_112935AM___line4__line1_____hnbm_lmjn___org.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65309f217e32132d4094e767",
  "name": "externalimg_r_1697685281624_01265___20231018_112946AM___line4_
_line1_____hnbm_lmjn___org.jpg",
  "path": "cases/652e671779133f5f41fec5de/externalimg_r_1697685281624_01265_
_20231018_112946AM___line4__line1_____hnbm_lmjn___org.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65309f217e32132d4094e768",
  "name": "externalimg_r_1697685281615_01263___20231018_112939AM___line4_
_line1_____hnbm_lmjn___org.jpg",
  "path": "cases/652e671779133f5f41fec5de/externalimg_r_1697685281615_01263_
_20231018_112939AM___line4__line1_____hnbm_lmjn___org.jpg",
  "orientation": "portrait"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65309f217e32132d4094e769",
  "name": "externallmg_r_1697685281629_01266___20231018_112951AM___line4_
_line1_____hnbm_lmjn___org.jpg",
  "path": "cases/652e671779133f5f41fec5de/externallmg_r_1697685281629_01266_
___20231018_112951AM___line4_line1_____hnbm_lmjn___org.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65309f217e32132d4094e76a",
  "name": "externallmg_r_1697685281620_01264___20231018_112944AM___line4_
_line1_____hnbm_lmjn___org.jpg",
  "path": "cases/652e671779133f5f41fec5de/externallmg_r_1697685281620_01264_
___20231018_112944AM___line4_line1_____hnbm_lmjn___org.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65309f217e32132d4094e76b",
  "name": "externallmg_r_1697685281632_01267___20231018_112954AM___line4_
_line1_____hnbm_lmjn___org.jpg",
  "path": "cases/652e671779133f5f41fec5de/externallmg_r_1697685281632_01267_
___20231018_112954AM___line4_line1_____hnbm_lmjn___org.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65309f217e32132d4094e76c",
  "name": "externallmg_r_1697685281642_01270___20231018_113002AM___line4_
_line1_____hnbm_lmjn___org.jpg",
  "path": "cases/652e671779133f5f41fec5de/externallmg_r_1697685281642_01270_
___20231018_113002AM___line4_line1_____hnbm_lmjn___org.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65309f217e32132d4094e76d",
  "name": "externallmg_r_1697685281636_01268___20231018_112957AM___line4_
```

```
_line1_____hnbm_lmjn___org.jpg",
"path": "cases/652e671779133f5f41fec5de/externallmg_r_1697685281636_01268_
__20231018_112957AM__line4__line1_____hnbm_lmjn___org.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "65309f217e32132d4094e76e",
"name": "externallmg_r_1697685281639_01269__20231018_112959AM__line4_
_line1_____hnbm_lmjn___org.jpg",
"path": "cases/652e671779133f5f41fec5de/externallmg_r_1697685281639_01269_
__20231018_112959AM__line4__line1_____hnbm_lmjn___org.jpg",
"orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-10-17T10:51:03.636Z",
"updatedAt": "2023-10-20T08:46:26.390Z",
"__v": 0,
"invoiceId": "652e671879133f5f41fec608",
"fullAddress": "Residential Flat No. 6, 1st Floor, Wing - A, Reshma Co-op. Hsg. Soc.
Ltd., Plot No. 26, Sector 9A, Village - Vashi, Navi Mumbai, Taluka - Thane, District -
Thane, PIN - 400 703, State - Maharashtra, India",
"updatedBy": "627221f4afd7d55eddeddcb4",
"addressForMap": "",
"caseReferredBy": "60b7189d2ffdf65bcd65882b",
"contactPersonName": "Mr. Balu Krishnan ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Representative of Owner",
"siteVisitContactNo": "9619916623",
"buildingServicesRate": "2700",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Index- II",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 754.00",
"flatRate": "18900",
"landOtherRate": "16200",
```

```

"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + Toilet + Passage +
Bathroom + Balcony",
"carpetTotal": "549.78",
"otherCarpetTotal": "30.22",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "30.22",
"otherCompositionSaleableTotal": "0.00",
"builtupPercentage": "20",
"finalBuiltupArea": "696.00",
"finalCarpetArea": "580.00",
"finalSalableArea": "696.00",
"salablePercentage": "0",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalSaleablePercentage": "0",
"reportGeneratedDate": "Fri Oct 20 2023 13:09:08 GMT+0530 (India Standard Time)",
"siteVisitDate": "2023-10-18",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
}
}

```

Name	Length	Width	Total
Composition :			



Living Room	9'11"	18'7"	184.28
Kitchen	6'7"	9'5"	61.99
Bedroom	9'4"	13'2"	122.89
Bedroom	9'10"	9'9"	95.87
Toilet	3'00"	4'00"	12.00
Passage	3'0"	4'0"	12.00
Bathroom	6'7"	4'00"	26.33
Balcony	3'6"	9'10"	34.42
Other Composition :			
Dry Balcony	10'8"	2'10"	30.22