

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": true,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b80a"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f65be948726cc14198f",
    "email": "pritam.patel@sbi.co.in",
    "firstName": "PRITAM PATEL",
    "mobileNo": "91-9967629819",
    "workMobileNo": "9967629819",
    "lastName": "Patel"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "0",
    "discussWithPerson": "PRITAM PATEL",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b80a",
  "branchCode": "000088",
  "type": "BRANCH",
  "name": "RACPC - Chinchpokli ",
  "email": "sbi.17889@sbi.co.in",
  "mobileNo": "022-23707514",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, Mumbai South Voltas
House, 'A', 1st Floor, Dr. Ambedkar Road, Chinchpokli (East), Mumbai - 400 033, State
- Maharashtra, Country - India.\r\n",
  "ledgerName": "STATE BANK OF INDIA - CHINCHPOKALI",
  "fax": "022-23707512 / 13",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "651e5a18b98e691677d9b737",
  "role": "PICKUPPERSON",
  "firstName": "Akshay",
  "email": "akshayomsairam966@gmail.com",
  "lastName": "Dawkhar",
  "mobileNo": "9167084090",
  "shortName": "Aks",
  "workWithDocumentMaker": "62727444afd7d55eddee092c",
  "profilePhoto": "users/651e5a18b98e691677d9b737/
profilePhoto_1696487959939_WhatsApp_Image_20231005_at_120529_PM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62ea09ea4e679b264caf07d7",
  "role": "SITEENGINEER",
  "firstName": "Suraj",
  "email": "suraj@vastukala.org",
  "lastName": "Zore",
  "mobileNo": "8652448654",
  "designation": "",
  "shortName": "SZ",
  "workWithDocumentMaker": "60092304a16fab0f2af9b0c2",
  "profilePhoto": "users/62ea09ea4e679b264caf07d7/
profilePhoto_1685629394240_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
  "designation": "",
  "shortName": "NK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627221f4afd7d55eddeddcb4",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Prajakta",
  "email": "prajakta@vastukala.org",
```

```

    "lastName": "Patil",
    "mobileNo": "9769797568",
    "designation": "",
    "shortName": "P",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
  },
  "checker": {
    "type": "EMPLOYEE",
    "_id": "60092304a16fab0f2af9b0c2",
    "role": "MAKER + RATE VERFIER + CHEAKER",
    "firstName": "Nitesh",
    "email": "nitesh.khedekar@vastukala.org",
    "lastName": "Khedekar",
    "mobileNo": "8369040652",
    "designation": "",
    "shortName": "NK",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
  },
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "IBBI/RV/07/2018/10366",
          "label": "Registered Valuer"
        }
      ],
      "type": "EMPLOYEE",
      "_id": "5ffe92d27737ca4d986b6453",
      "role": "VALUER",
      "firstName": "Manoj",
      "email": "manoj@vastukala.org",
      "lastName": "Chalikwar",
      "mobileNo": "9819597579",
      "designation": "Registered Valuer",
      "registrationNo": [
        {
          "title": {
            "label": "IBBI"
          },
          "_id": "60af80072ffdf65bcd658651",
          "number": "IBBI/RV/07/2018/10366"
        }
      ],
    }
  ],

```

```
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.16384840791594",
  "longitude": "72.88917513261141"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.88917513261141,
```

```
19.16384840791594
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-18",
      "remark": ""
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Kanjur",

```

```
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "9",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban ",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kurla",
  "label": true
},
"plotNo": {
  "status": true,
```

```
"name": "Plot No.",
"key": "plotNo",
"value": "A, B, C, D, E",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Royal Aster",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "F",
  "label": true
}
```



```
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": true,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "592, 593, 594, 594/1 to 594/10, 595, 595/1 to 595/35",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "592-A, 592-B, 592-C, 592-D, 592-E, 592-F",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
```

```
"key": "selectNo",
"value": "905",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
}
```

```
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 400 078",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Kanjurmarg (West), Mumbai",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "sole_ownership",
    "label": "sole ownership"
  }
}
```

```
},
"populationClassList": {
  "value": "MiddleClass",
  "label": "Middle Class"
},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "MCGM",
  "label": "Municipal Corporation of Greater Mumbai (MCGM)"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Parking Area",
  "west": "Road & BMC Park",
  "south": "Internal Road",
  "east": "Wing - G"
},
"asPerDocumentAgreement": {
  "north": "By Open Car Park",
  "west": "By Additional Recreational Ground",
  "south": "By Underground Tank",
  "east": "By Proposed Building"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
```

```
"dateOfIssusApprovePlan": "Copy of Approved Plan were not provided and not
verified",
  "approvePlanVerified": "N.A.",
  "empanelledOfApprovePlan": "N.A."
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "24",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "30280",
  "depreciatedBuildingRate": "2280"
},
"igrRate": {
  "propertyName": "Residential ",
  "rate": "146510",
  "landRate": "68540",
  "igrImage": "cases/652e7d507e32132d4092dab6/igr_1697606105308_Image.png",
  "squareMeterGuideLineRate": "153836.00",
  "squareFeetGuideLineRate": "14292.00"
},
"igrFinalRate": {
  "depreciationPercentage": "84",
  "rate": "13024.00",
  "squareFeetGuideLineRate": "13024.00",
  "squareMeterGuideLineRate": "140188.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Vacant",
    "label": "Vacant"
  },
  "monthlyRent": "53000",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
```

```
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per MCGM norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in Developed Area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Along with One Car parking Space No. F / 905 admeasuring Area of
10.35 Sq. M.",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2007",
    "fullDate": "1/1/2007"
  },
}
```

```
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Normal",
  "label": "Normal"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Average",
  "label": "Average"
},
"structuralSafety": {
  "value": "Normal",
  "label": "Normal"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
```

```
"label": "Normal"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "Approx.",
  "label": "Approx."
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "44",
"ageOfBuilding": "16",
"noOfBasement": "1",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "10",
"flatFloorNo": "9",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "5"
},
"finalPlinthArea": {
  "areaType": "Built Up",
  "area": "1008.00",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
```



```
"routeStation": {
  "value": "Railway_Station",
  "label": "Railway Station"
},
"routeMapImg": "cases/652e7d507e32132d4092dab6/
routeMap_1697779387721_Image.png",
"routeLat": "19.134771",
"routeLng": "72.930178",
"stationName": "Kanjur Marg",
"routeDistance": "1.2 Km."
},
"finalLatLng": {
  "coordinates": [
    null,
    null
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": true,
  "finallatLng": true
},
"locationMapImg": [
  {
    "id": "zsz2n",
    "name": "zsz2n",
    "image": "cases/652e7d507e32132d4092dab6/
routeMap_1697779333443_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
```

```
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "25435200.00",
"finalValue": "25435200.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": true,
"status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "13128192.00",
  "selectedBuildUpValue": "1008.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "6530226f7e32132d4094e440",
      "name": "externallmg_r_1697653336391_1697653292807_image_18.jpg",
      "path": "cases/652e7d507e32132d4092dab6/
externallmg_r_1697653336391_1697653292807_image_18.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "6530226f7e32132d4094e42e",
      "name": "externallmg_r_1697653278100_1697653292807_image_3.jpg",
      "path": "cases/652e7d507e32132d4092dab6/
externallmg_r_1697653278100_1697653292807_image_3.jpg",
      "orientation": "landscape"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "6530226f7e32132d4094e430",
      "name": "externallmg_r_1697653267463_1697653292807_image_0.jpg",
      "path": "cases/652e7d507e32132d4092dab6/
externallmg_r_1697653267463_1697653292807_image_0.jpg",
      "orientation": "portrait"
    }
  ],
}
```

```
{
  "status": false,
  "_id": "6530226f7e32132d4094e43c",
  "name": "externallmg_r_1697653324347_1697653292807_image_15.jpg",
  "path": "cases/652e7d507e32132d4092dab6/
externallmg_r_1697653324347_1697653292807_image_15.jpg",
  "orientation": "portrait"
}
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "6530226f7e32132d4094e42f",
    "name": "externallmg_r_1697653273250_1697653292807_image_2.jpg",
    "path": "cases/652e7d507e32132d4092dab6/
externallmg_r_1697653273250_1697653292807_image_2.jpg",
    "orientation": "landscape"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "6530226f7e32132d4094e432",
    "name": "Living Room",
    "path": "cases/652e7d507e32132d4092dab6/
externallmg_r_1697653283622_1697653292807_image_4.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6530226f7e32132d4094e433",
    "name": "Living Room",
    "path": "cases/652e7d507e32132d4092dab6/
externallmg_r_1697653287414_1697653292807_image_5.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6530226f7e32132d4094e436",
    "name": "Living Room",
    "path": "cases/652e7d507e32132d4092dab6/
externallmg_r_1697653297477_1697653292807_image_8.jpg",
    "orientation": "portrait"
  },
  {

```

```
    "status": false,
    "_id": "6530226f7e32132d4094e43a",
    "name": "Living Room",
    "path": "cases/652e7d507e32132d4092dab6/
externallmg_r_1697653312407_1697653292807_image_12.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6530226f7e32132d4094e43b",
    "name": "Living Room",
    "path": "cases/652e7d507e32132d4092dab6/
externallmg_r_1697653316065_1697653292807_image_13.jpg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "29204",
    "max": "31455"
  },
  "builtUpRateRange": {
    "min": "24337",
    "max": "26213"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```



```
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
```

```
"finalValuationArea": "840.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentId": [],
"_id": "652e7d507e32132d4092dab6",
"ownerName": "Rashmi Dey & Mr. Subrata Kumar Dey",
"ownerPhoneNo": "9833750763",
"appAddress": "flat no.905, B Royal Aster\nKaniur w mumbai 400078",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae1251aa6d152c1801b31a",
      "label": "Seller\\\\\\\\'s Agreement for Sale"
    },
    "inputs": {
      "documentDate": "11/05/2005",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "The Great Eastern Shipping Company",
      "to": {
        "value": "purchaser",
        "label": "purchaser"
      },
      "purchaser": "Rashmi Dey & Mr. Subrata Kumar Dey"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "394419",
    "path": "cases/652e7d507e32132d4092dab6/
document_1697545473021_214064.pdf",
    "fileName": "document_1697545473021_214064.pdf"
  }
],
"caseNumber": "004460",
"createdBy": "651e5a18b98e691677d9b737",
"caseHistory": [
  {
    "id": "673043",
    "title": "Create Lead",
```

```
"description": "Create Lead",
"datetime": "Tue Oct 17 2023 17:55:52 GMT+0530 (India Standard Time)"
}
],
"owners": [
{
"name": "Rashmi Dey & Mr. Subrata Kumar Dey",
"phone": "9833750763",
"ownershipShare": "",
"email": "",
"id": "378337"
}
],
"proposePurchasers": [
{
"name": "Mahesh Matekar",
"phone": "",
"ownershipShare": "",
"email": ""
}
],
"siteInspection": [],
"composition": [
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "194974",
"name": "Passage",
"length": "3.58",
"length1": "3",
"length2": "7",
"width": "8.50",
"width1": "8",
"width2": "6",
"totalArea": "30.46",
"images": [],
"extraAreas": [],
"finalArea": "30.46"
},
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
}
},
]
```

```
"id": "1",
"name": "Kitchen",
"length": "15.08",
"length1": "15",
"length2": "1",
"width": "8.08",
"width1": "8",
"width2": "1",
"totalArea": "121.92",
"images": [],
"extraAreas": [],
"finalArea": "121.92"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Living Room",
  "length": "21.00",
  "length1": "21",
  "length2": "00",
  "width": "11.00",
  "width1": "11",
  "width2": "00",
  "totalArea": "231.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "231.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Passage",
  "length": "4.25",
  "length1": "4",
  "length2": "3",
  "width": "5.00",
  "width1": "5",
  "width2": "00",
  "totalArea": "21.25",
  "images": [],
```

```
"extraAreas": [],
"finalArea": "21.25"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "4.67",
  "length1": "4",
  "length2": "8",
  "width": "8.17",
  "width1": "8",
  "width2": "2",
  "totalArea": "38.11",
  "images": [],
  "extraAreas": [],
  "finalArea": "38.11"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Toilet",
  "length": "4.67",
  "length1": "4",
  "length2": "8",
  "width": "7.42",
  "width1": "7",
  "width2": "5",
  "totalArea": "34.61",
  "images": [],
  "extraAreas": [],
  "finalArea": "34.61"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Bedroom",
```

```
"length": "13.58",
"length1": "13",
"length2": "7",
"width": "10.50",
"width1": "10",
"width2": "6",
"totalArea": "142.62",
"images": [],
"extraAreas": [],
"finalArea": "142.62"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Bedroom",
  "length": "13.42",
  "length1": "13",
  "length2": "5",
  "width": "10.42",
  "width1": "10",
  "width2": "5",
  "totalArea": "139.76",
  "images": [],
  "extraAreas": [],
  "finalArea": "139.76"
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "label": "Cupboard",
      "value": "Cupboard"
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "0",
    "length1": "4",
```

```
"length2": "6",
"length": "4.50",
"width1": "2",
"width2": "4",
"width": "2.33",
"totalArea": "10.50",
"percentageBeforeTotal": "10.50",
"images": [],
"extraAreas": [],
"percentage": "100",
"finalArea": "10.5"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Balcony Area",
    "value": "Balcony_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "length1": "4",
  "length2": "5",
  "length": "4.42",
  "width1": "10",
  "width2": "8",
  "width": "10.67",
  "totalArea": "47.11",
  "percentageBeforeTotal": "47.11",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "47.11"
}
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60ae1251aa6d152c1801b31a",
      "label": "Seller\\\\\\\\'s Agreement for Sale"
    }
  }
]
```

```

    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "749496",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "840",
    "squareMeterArea": "78.04",
    "docFinalBuiltUp": "1008",
    "docFinalBuiltUpSquareMeter": "93.64800000000001",
    "docBuiltupPercentage": "20",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "652f69e57e32132d4093523f",
    "property": "2BHK Flat for Sale in Mahindra Great Eastern Gardens, Ambedkar
Nagar",
    "area": "763.00",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "https://www.99acres.com/",
    "expectedPrice": "24000000.00",
    "expectedRate": "31454.78",
    "builtUpExpectedRate": "26212.32",
    "image": "cases/652e7d507e32132d4092dab6/
indicator_1697605608971_Image.png",
    "squareMeter": "70.89",
    "id": "257628"
  },
  {
    "printlnReport": true,
    "_id": "652f69e57e32132d40935240",
    "property": "3BHK Flat for Sale in Mahindra Great Eastern Gardens, Ambedkar
Nagar",
    "area": "1130.00",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",

```



```
"rateType": "price_Indicator",
"areaType": "Carpet",
"source": "https://www.99acres.com/",
"expectedPrice": "33000000.00",
"expectedRate": "29203.54",
"builtUpExpectedRate": "24336.28",
"image": "cases/652e7d507e32132d4092dab6/
indicator_1697605667408_Image.png",
"squareMeter": "104.98",
"id": "395881"
},
{
  "printlnReport": true,
  "_id": "652f69e57e32132d40935241",
  "property": "2BHK 2Baths Flat/Apartment for Sale in Mahindra Great Eastern
Gardens, Ambedkar Nagar,",
  "area": "735.00",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "https://www.99acres.com/",
  "expectedPrice": "22000000.00",
  "expectedRate": "29931.97",
  "builtUpExpectedRate": "24943.31",
  "image": "cases/652e7d507e32132d4092dab6/
indicator_1697605710026_Image.png",
  "squareMeter": "68.28",
  "id": "174594"
},
{
  "printlnReport": true,
  "_id": "652f69e57e32132d40935242",
  "property": "The Great Eastern Gardens, Kanjurmarg West, Mumbai",
  "area": "763.00",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "Housing.Com",
  "expectedPrice": "24000000.00",
  "expectedRate": "31454.78",
  "builtUpExpectedRate": "26212.32",
  "image": "cases/652e7d507e32132d4092dab6/
indicator_1697605806219_Image.png",
  "squareMeter": "70.89",
```

```
    "id": "939413"
  }
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6530226f7e32132d4094e42e",
    "name": "externalimg_r_1697653278100_1697653292807_image_3.jpg",
    "path": "cases/652e7d507e32132d4092dab6/
externalimg_r_1697653278100_1697653292807_image_3.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6530226f7e32132d4094e42f",
    "name": "externalimg_r_1697653273250_1697653292807_image_2.jpg",
    "path": "cases/652e7d507e32132d4092dab6/
externalimg_r_1697653273250_1697653292807_image_2.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6530226f7e32132d4094e430",
    "name": "externalimg_r_1697653267463_1697653292807_image_0.jpg",
    "path": "cases/652e7d507e32132d4092dab6/
externalimg_r_1697653267463_1697653292807_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6530226f7e32132d4094e431",
    "name": "externalimg_r_1697653269842_1697653292807_image_1.jpg",
    "path": "cases/652e7d507e32132d4092dab6/
externalimg_r_1697653269842_1697653292807_image_1.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6530226f7e32132d4094e432",
    "name": "externalimg_r_1697653283622_1697653292807_image_4.jpg",
    "path": "cases/652e7d507e32132d4092dab6/
externalimg_r_1697653283622_1697653292807_image_4.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6530226f7e32132d4094e433",
  "name": "externallmg_r_1697653287414_1697653292807_image_5.jpg",
  "path": "cases/652e7d507e32132d4092dab6/
externallmg_r_1697653287414_1697653292807_image_5.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6530226f7e32132d4094e434",
  "name": "externallmg_r_1697653291467_1697653292807_image_6.jpg",
  "path": "cases/652e7d507e32132d4092dab6/
externallmg_r_1697653291467_1697653292807_image_6.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6530226f7e32132d4094e435",
  "name": "externallmg_r_1697653294385_1697653292807_image_7.jpg",
  "path": "cases/652e7d507e32132d4092dab6/
externallmg_r_1697653294385_1697653292807_image_7.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6530226f7e32132d4094e436",
  "name": "externallmg_r_1697653297477_1697653292807_image_8.jpg",
  "path": "cases/652e7d507e32132d4092dab6/
externallmg_r_1697653297477_1697653292807_image_8.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6530226f7e32132d4094e437",
  "name": "externallmg_r_1697653300685_1697653292807_image_9.jpg",
  "path": "cases/652e7d507e32132d4092dab6/
externallmg_r_1697653300685_1697653292807_image_9.jpg",
  "orientation": "portrait"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6530226f7e32132d4094e438",
  "name": "externallmg_r_1697653309305_1697653292807_image_11.jpg",
  "path": "cases/652e7d507e32132d4092dab6/
externallmg_r_1697653309305_1697653292807_image_11.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6530226f7e32132d4094e439",
  "name": "externallmg_r_1697653304290_1697653292807_image_10.jpg",
  "path": "cases/652e7d507e32132d4092dab6/
externallmg_r_1697653304290_1697653292807_image_10.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6530226f7e32132d4094e43a",
  "name": "externallmg_r_1697653312407_1697653292807_image_12.jpg",
  "path": "cases/652e7d507e32132d4092dab6/
externallmg_r_1697653312407_1697653292807_image_12.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6530226f7e32132d4094e43b",
  "name": "externallmg_r_1697653316065_1697653292807_image_13.jpg",
  "path": "cases/652e7d507e32132d4092dab6/
externallmg_r_1697653316065_1697653292807_image_13.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6530226f7e32132d4094e43c",
  "name": "externallmg_r_1697653324347_1697653292807_image_15.jpg",
  "path": "cases/652e7d507e32132d4092dab6/
externallmg_r_1697653324347_1697653292807_image_15.jpg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6530226f7e32132d4094e43d",
  "name": "externallmg_r_1697653319317_1697653292807_image_14.jpg",
  "path": "cases/652e7d507e32132d4092dab6/
externallmg_r_1697653319317_1697653292807_image_14.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6530226f7e32132d4094e43e",
  "name": "externallmg_r_1697653332581_1697653292807_image_17.jpg",
  "path": "cases/652e7d507e32132d4092dab6/
externallmg_r_1697653332581_1697653292807_image_17.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6530226f7e32132d4094e43f",
  "name": "externallmg_r_1697653328338_1697653292807_image_16.jpg",
  "path": "cases/652e7d507e32132d4092dab6/
externallmg_r_1697653328338_1697653292807_image_16.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6530226f7e32132d4094e440",
  "name": "externallmg_r_1697653336391_1697653292807_image_18.jpg",
  "path": "cases/652e7d507e32132d4092dab6/
externallmg_r_1697653336391_1697653292807_image_18.jpg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6530226f7e32132d4094e441",
  "name": "externallmg_r_1697653246584_1697653274545_image_2.png",
  "path": "cases/652e7d507e32132d4092dab6/
externallmg_r_1697653246584_1697653274545_image_2.png",
  "orientation": "portrait"
},
{
```

```
"type": "MEASUREMENT_IMAGE",
"status": false,
"_id": "6530226f7e32132d4094e442",
"name": "externalimg_r_1697653245520_1697653274545_image_1.jpg",
"path": "cases/652e7d507e32132d4092dab6/
externalimg_r_1697653245520_1697653274545_image_1.jpg",
"orientation": "portrait"
},
{
"type": "MEASUREMENT_IMAGE",
"status": false,
"_id": "6530226f7e32132d4094e443",
"name": "externalimg_r_1697653244190_1697653274545_image_0.jpg",
"path": "cases/652e7d507e32132d4092dab6/
externalimg_r_1697653244190_1697653274545_image_0.jpg",
"orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [
{
"createdBy": {
"_id": "627221f4afd7d55eddeddcb4",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Prajakta",
"lastName": "Patil",
"profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"workType": "MAKER",
"display": true,
"status": true,
"_id": "6531070e619c14402da59b00",
"note": "Cancelled by bank",
"taskId": "652f6a1a7e32132d40935312",
"createdAt": "2023-10-19T10:38:06.807Z"
}
],
"createdAt": "2023-10-17T12:25:52.319Z",
"updatedAt": "2023-10-20T06:04:02.143Z",
"__v": 0,
"invoiceId": "652e7d507e32132d4092dad6",
"fullAddress": "Residential Flat No. 905, 9th Floor, Wing - F, Royal Aster, Plot No. A, B,
C, D, E, Village - Kanjur, Kanjurmarg (West), Mumbai, Taluka - Kurla, District - Mumbai
Suburban , PIN Code - 400 078, State - Maharashtra, India",
```

"updatedBy": "60092304a16fab0f2af9b0c2",
"addressForMap": "",
"caseReferredBy": "651e5a18b98e691677d9b737",
"contactPersonName": "Mr. Mahesh Matekar (Proposed Buyer)",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9833750763",
"buildingServicesRate": "3000.00",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Seller\\\\\\\\'s Agreement for Sale",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 840.00",
"flatRate": "31000.00",
"landOtherRate": "28000",
"siteVisitDate": "2023-10-18",
"builtupPercentage": "10",
"carpetTotal": "687.01",
"extendOfSiteRemark": "",
"finalBuiltupArea": "899.07",
"finalCarpetArea": "817.34",
"finalSalableArea": "988.98",
"otherCarpetTotal": "57.61",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"finalSaleablePercentage": "0",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + 2 Passage + 2 Toilet",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "57.61",
"otherCompositionSaleableTotal": "0.00",
"landDetails": {
 "holdType": {
 "label": "Free Hold",
 "value": "Free_Hold"
 },
},
"leaseDetails": {
 "lessorName": "",
 "lesseeName": "",
 "leasePremium": "",
 "leaseRent": "",

```

    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
}
}

```

Name	Length	Width	Total
Composition :			
Passage	3'7"	8'6"	30.46
Kitchen	15'1"	8'1"	121.92
Living Room	21'00"	11'00"	231.00
Passage	4'3"	5'00"	21.25
Toilet	4'8"	8'2"	38.11
Toilet	4'8"	7'5"	34.61
Bedroom	13'7"	10'6"	142.62
Bedroom	13'5"	10'5"	139.76
Other Composition :			
Cupboard	4'6"	2'4"	10.50
Balcony Area	4'5"	10'8"	47.11