

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b80a"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f65be948726cc1419a7",
    "email": "kaushik.datta@sbi.co.in",
    "firstName": "KAUSHUIK",
    "mobileNo": "",
    "workMobileNo": "9757023640",
    "lastName": " DATTA "
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "0",
    "discussWithPerson": "KAUSHUIK",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b80a",
  "branchCode": "000088",
  "type": "BRANCH",
  "name": "RACPC - Chinchpokli ",
  "email": "sbi.17889@sbi.co.in",
  "mobileNo": "022-23707514",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, Mumbai South Voltas
House, 'A', 1st Floor, Dr. Ambedkar Road, Chinchpokli (East), Mumbai - 400 033, State
- Maharashtra, Country - India.\r\n",
  "ledgerName": "STATE BANK OF INDIA - CHINCHPOKALI",
  "fax": "022-23707512 / 13",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "651e5a18b98e691677d9b737",
  "role": "PICKUPPERSON",
  "firstName": "Akshay",
  "email": "akshayomsairam966@gmail.com",
  "lastName": "Dawkhar",
  "mobileNo": "9167084090",
  "shortName": "Aks",
  "workWithDocumentMaker": "62727444afd7d55eddee092c",
  "profilePhoto": "users/651e5a18b98e691677d9b737/
profilePhoto_1696487959939_WhatsApp_Image_20231005_at_120529_PM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f9462345132d6a6bddb9d5",
  "role": "SITEENGINEER",
  "firstName": "Dashrath ",
  "email": "dasrat.jaiswar1234@gmail.com",
  "lastName": "Jaiswar",
  "mobileNo": "9987305468",
  "designation": "",
  "shortName": "DFJ",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60eebe33f3dd69653a5837ae",
  "role": "MAKER",
  "firstName": "Shamal",
  "email": "shamal@vastukala.org",
  "lastName": "Bodke",
  "mobileNo": "9821740317",
```

```
"designation": "",
"shortName": "SB",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eebe33f3dd69653a5837ae\
\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
},
"checker": "",
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
"value": "FIIV",
"label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
"title": {
"value": "Chartered_Engineer",
"label": "Chartered Engineer"
},
"_id": "60af80072ffdf65bcd658653",
"number": "AM161706-3"
}
```

```
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.064572324469054",
  "longitude": "72.88481043179186"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.88481043179186,
    19.064572324469054
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-18",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-18",
      "remark": ""
    }
  ]
}
```

```
    }
  ],
  "schedule": [],
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "3BHK",
  "label": "3 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Kurla 3",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "14",
    "label": false
  },
  "buildingNo": {
```

```
"status": true,
"name": "Building No",
"key": "buildingNo",
"value": "45",
"label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Kurla (East)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kurla",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Gagan 45",
```

```
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Nehru Nagar",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Nehru Nagar Kedar Darshan Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
```



```
"name": "Old Survey No.",
"key": "oldSurveyNumber",
"value": "",
"label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "229 & 267",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "12(P)",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1401",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
}
```

```
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 024",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
```

```

    "key": "suburb",
    "value": "",
    "label": false
  }
},
"flatSpecifications": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "flooring": {
    "value": "Proposed_Vitrified_tiles_flooring",
    "label": "Proposed Vitrified tiles flooring"
  },
  "doors": {
    "value": "Proposed_Teak_wood_door_frame_with_flush_doors",
    "label": "Proposed Teak wood door frame with flush doors"
  },
  "windows": {
    "value": "Proposed_Powder_coated_aluminium_sliding_windows",
    "label": "Proposed Powder coated aluminium sliding windows"
  },
  "fittings": {
    "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Proposed_Electrical_wiring_with_Concealed.",
    "label": "Proposed Concealed plumbing with C.P. fittings. Proposed Electrical wiring with Concealed."
  },
  "finishing": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  }
},

```

```
"townplanApprovedByList": {
  "value": "MHADA",
  "label": "MHADA"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Building No. 47",
  "west": "Building No. 46",
  "south": "Kedarnath Marg",
  "east": "Narayan D Mistri Marg"
},
"asPerDocumentAgreement": {
  "north": "Details not available",
  "west": "Details not available",
  "south": "Details not available",
  "east": "Details not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "asPerDocument": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "As per approved plan, the composition of Flat is 3
Bedrooms + Living Room + Dining + Kitchen + 3 Toilets + Passage.",
"dateOfIssusApprovePlan": "Copy of Approved Building Plan No. MH / EE / (BP) /
GM / MHADA-22 / 1020 / 2023 Dated 21.02.2023 issued by MHADA.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A."
},
"compositeRate": {
  "remark": "The details about the work progress status has been provided by Sales
Manager Inderjit Singh (Contact No. 9819784307)",
```

```
"depreciationPercentage": "",
"depreciationRatioOfBuilding": "",
"salvageValue": "",
"depreciatedCostOfConstruction": "",
"depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "125170",
  "landRate": "49960",
  "igrImage": "cases/652e7f067e32132d4092e4ff/igr_1697777365675_Image.png",
  "squareMeterGuideLineRate": "137687.00",
  "squareFeetGuideLineRate": "12792.00"
},
"igrFinalRate": {
  "depreciationPercentage": "0",
  "rate": "125170",
  "squareMeterGuideLineRate": "137687.00",
  "squareFeetGuideLineRate": "12792.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  },
  "monthlyRent": "41,000",
  "assessmentNo": "Building Under Construction",
  "taxPaidHolderName": "Building Under Construction",
  "taxAmount": "Building Under Construction",
  "electricityServiceConnectionNo": "Building Under Construction",
  "meterCardHolderName": "Building Under Construction",
  "undividedAreaOfLandAsPerSaleDeed": "Building Under Construction",
  "floorSpaceIndex": "As per MHADA norms",
  "tenantName": "",
  "maintenanceOfFlat": "Building Under Construction"
},
"marketability": {
  "marketabilityList": {
```

```
"value": "Good",
"label": "Good"
},
"anyFavouringForExtraPotentialValue": "Located in developed area",
"negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
"roof": {
"value": "Proposed_R.C.C._Slab",
"label": "Proposed R.C.C. Slab"
},
"partitions": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"waterTank": {
"value": "Proposed_Municipal_Water_Supply",
"label": "Proposed Municipal Water Supply"
},
"pavementLaid": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"carParking": "Stilt + Open Car Parking",
"constructionWorkStatus": {
"value": "InProgress",
"label": "Under Construction"
},
"asthetikLook": {
"value": "Plain_Looking",
"label": "Plain Looking"
},
"dateOfConstruction": {
"date": "",
"month": "1",
"year": "2025",
"fullDate": "1/1/2025"
},
"planningArea": {
"value": "Residential",
"label": "Residential"
},
"typeOfStructure": {
"value": "Proposed_R.C.C._Framed_Structure",
"label": "Proposed R.C.C Framed Structure"
},
}
```

```
"typeOfFoundation": {
  "value": "Proposed_R.C.C._Foundation",
  "label": "Proposed R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"materialUsedList": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"buildingSpecification": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"structuralSafety": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "Proposed_Connected_to_Municipal_Sewerage_System_",
  "label": "Proposed Connected to Municipal Sewerage System "
},
"walls": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"appearanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenancelssues": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"visibleDamageInBuilding": {
  "value": "Building_Under_Construction",
```

```
"label": "Building Under Construction"
},
"systemOfAirConditioning": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"provisionOfFirefighting": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"groundStilt": {
  "value": "Part_Ground_and_Part_Stilt",
  "label": "Part Ground + Part Stilt"
},
"yearOfConstructionAsPer": {
  "value": "As_per_RERA_Certificate",
  "label": "As per RERA Certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "0",
"ageOfBuilding": "0",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "20",
"flatFloorNo": "14",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "areaType": "Built Up",
  "area": "929.50",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/652e7f067e32132d4092e4ff/
routeMap_1697781351524_Image.png",
    "routeLat": "19.060139",
    "routeLng": "72.881222",
```



```
"stationName": "Kurla",
"routeDistance": "1 Km."
},
"finalLatLng": {
  "coordinates": [
    null,
    null
  ],
  "type": "Point"
},
"showLocation": {
  "latlng": true,
  "finallatlng": true
},
"locationMapImg": [
  {
    "id": "6vxsc5",
    "name": "6vxsc5",
    "image": "cases/652e7f067e32132d4092e4ff/
routeMap_1697781102415_Image.png"
  }
],
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
```

```
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "16477500.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "16477500.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "22",
    "percentage": "40",
    "isHideFloor": false,
    "status": true
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "22",
    "percentage": "7.00",
    "isHideFloor": false,
    "status": true
  }
}
```

```
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "22",
  "percentage": "7.00",
  "isHideFloor": false,
  "status": true
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "22",
  "percentage": "3.50",
  "isHideFloor": false,
  "status": true
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "22",
  "percentage": "3.50",
  "isHideFloor": false,
  "status": true
},
"door": {
  "label": "Door",
  "floorsCompleted": "22",
  "percentage": "2.50",
  "isHideFloor": false,
  "status": true
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "12",
  "percentage": "5.45",
  "isHideFloor": false,
  "status": true
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "78.95",
  "isHideFloor": true,
  "status": true
}
}
```

```
},
"guidelineDetails": {
  "finalGuidelineValue": "11890164.00",
  "selectedBuildUpValue": "929.50",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "652fc0557e32132d409496bc",
      "name": "externallmg_1697628160752_1697628151811_image_3.jpeg",
      "path": "cases/652e7f067e32132d4092e4ff/
externallmg_1697628160752_1697628151811_image_3.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "652fc0557e32132d409496b9",
      "name": "externallmg_1697628124188_1697628151811_image_0.jpeg",
      "path": "cases/652e7f067e32132d4092e4ff/
externallmg_1697628124188_1697628151811_image_0.jpeg",
      "orientation": "portrait"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "652fc0557e32132d409496ba",
      "name": "externallmg_1697628144688_1697628151811_image_1.jpeg",
      "path": "cases/652e7f067e32132d4092e4ff/
externallmg_1697628144688_1697628151811_image_1.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "652fc0557e32132d409496bc",
      "name": "externallmg_1697628160752_1697628151811_image_3.jpeg",
      "path": "cases/652e7f067e32132d4092e4ff/
externallmg_1697628160752_1697628151811_image_3.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
```

```
    "_id": "652fc0557e32132d409496bb",
    "name": "externallmg_1697628156478_1697628151811_image_2.jpeg",
    "path": "cases/652e7f067e32132d4092e4ff/
externallmg_1697628156478_1697628151811_image_2.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "18496",
    "max": "20986"
  },
  "builtUpRateRange": {
    "min": "16815",
    "max": "19079"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
}
```

```
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```

```
"isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": false,
"finalValuationArea": "845.00",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentId": [],
```



```
"_id": "652e7f067e32132d4092e4ff",
"ownerName": "Mr. Sunil Harishchandra Ghadge, Mr. Swapnil Sunil Ghadge, Mr.
Nilesh Sunil Ghadge & Ms. Tejasvi Sunil Ghadge",
"ownerPhoneNo": "9870690605",
"appAddress": "Falt no.1401, B wing nehru nagar ,Darshan che ltd,Kurla east, Mumbai
400024.",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "11/10/2023",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "M/s. Gagangiri Developers",
      "to": {
        "value": "Allottee",
        "label": "Allottee"
      },
      "Allottee": "Mr. Sunil Harishchandra Ghadge, Mr. Swapnil Sunil Ghadge, Mr. Nilesh
Sunil Ghadge & Ms. Tejasvi Sunil Ghadge",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "21796/2023"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "351301",
    "path": "cases/652e7f067e32132d4092e4ff/
document_1697545921898_124716.pdf",
    "fileName": "document_1697545921898_124716.pdf"
  },
  {
    "documentType": {
      "value": "60ae1247aa6d152c1801b2ea",
      "label": "Commencement Certificate"
    },
    "inputs": {
      "documentDate": "01/03/2023",
```

```
"nameOfApprovingAuthority": {
  "value": "Mumbai_Housing_and_Area_Development_Board",
  "label": "Mumbai Housing and Area Development Board"
},
"number": {
  "value": "No",
  "label": "No"
},
"No": "MH / EE / (BP) / GM / MHADA-22 / 1020 / 2023 / FCC / 1 / Amend"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1697779603160_2_Commencement_Certificates___NA_Order_for_plotted_development.pdf",
"path": "cases/652e7f067e32132d4092e4ff/document_1697779603160_2_Commencement_Certificates___NA_Order_for_plotted_development.pdf",
"id": "759279",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Fri Oct 20 2023 10:56:43 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "21/02/2023",
    "nameOfApprovingAuthority": {
      "value": "Mumbai_Housing_and_Area_Development_Board",
      "label": "Mumbai Housing and Area Development Board"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "MH / EE / (BP) / GM / MHADA-22 / 1020 / 2023"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1697779764948_9_Building_Plan_Approval___NA_Order_for_plotted_development.pdf",
"path": "cases/652e7f067e32132d4092e4ff/document_1697779764948_9_Building_Plan_Approval___NA_Order_for_plotted_development.pdf",
"id": "355186",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Fri Oct 20 2023 10:59:25 GMT+0530 (India Standard Time)"
```

```
    },
    {
      "documentType": {
        "value": "60ae129faa6d152c1801b47d",
        "label": "RERA Certificate"
      },
      "inputs": {
        "documentDate": "08/03/2022",
        "nameOfApprovingAuthority": {
          "value": "Maharashtra_Real_Estate_Regulatory_Authority",
          "label": "Maharashtra Real Estate Regulatory Authority"
        },
        "number": {
          "value": "Registration_No",
          "label": "Registration No"
        },
        "Registration_No": "P51800033764"
      },
      "isHardCopy": false,
      "displayStatus": false,
      "fileName": "document_1697779946277_P51800033764.pdf",
      "path": "cases/652e7f067e32132d4092e4ff/
document_1697779946277_P51800033764.pdf",
      "id": "403951",
      "uploadedBy": "60eebe33f3dd69653a5837ae",
      "createdAt": "Fri Oct 20 2023 11:02:26 GMT+0530 (India Standard Time)"
    }
  ],
  "caseNumber": "004462",
  "createdBy": "651e5a18b98e691677d9b737",
  "caseHistory": [
    {
      "id": "705039",
      "title": "Create Lead",
      "description": "Create Lead",
      "datetime": "Tue Oct 17 2023 18:03:10 GMT+0530 (India Standard Time)"
    }
  ],
  "owners": [
    {
      "name": "Mr. Sunil Harishchandra Ghadge, Mr. Swapnil Sunil Ghadge, Mr. Nilesh Sunil Ghadge & Ms. Tejasvi Sunil Ghadge",
      "phone": "9870690605",
      "ownershipShare": "",
      "email": "",
      "id": "658369"
    }
  ]
}
```

```
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "602346",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "845",
    "squareMeterArea": "78.5",
    "docFinalBuiltUp": "929.5",
    "docFinalBuiltUpSquareMeter": "86.35",
    "docBuiltupPercentage": "10",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "653206dc619c14402da66eaf",
    "property": "FIAT",
    "area": "845",
    "builtUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "15",
    "source": "magic_bricks",
    "expectedPrice": "17500000",
    "expectedRate": "20710.06",
    "builtUpExpectedRate": "18827.33",
    "image": "cases/652e7f067e32132d4092e4ff/
indicator_1697776990282_Image.png",
```

```
"squareMeter": "78.50",
"id": "667008"
},
{
  "printlnReport": true,
  "_id": "653206dc619c14402da66eb0",
  "property": "Flat",
  "area": "791",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "square_yards",
  "expectedPrice": "16600000",
  "expectedRate": "20986.09",
  "builtUpExpectedRate": "19078.27",
  "image": "cases/652e7f067e32132d4092e4ff/
indicator_1697777065172_Image.png",
  "squareMeter": "73.49",
  "id": "794735"
},
{
  "printlnReport": true,
  "_id": "653206dc619c14402da66eb1",
  "property": "Flat",
  "area": "811",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "square_yards",
  "expectedPrice": "15000000",
  "expectedRate": "18495.68",
  "builtUpExpectedRate": "16814.26",
  "image": "cases/652e7f067e32132d4092e4ff/
indicator_1697777122546_Image.png",
  "squareMeter": "75.34",
  "id": "106751"
}
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652fc0557e32132d409496b9",
    "name": "externallmg_1697628124188_1697628151811_image_0.jpeg",
```

```
    "path": "cases/652e7f067e32132d4092e4ff/
externallmg_1697628124188_1697628151811_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652fc0557e32132d409496ba",
    "name": "externallmg_1697628144688_1697628151811_image_1.jpeg",
    "path": "cases/652e7f067e32132d4092e4ff/
externallmg_1697628144688_1697628151811_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652fc0557e32132d409496bb",
    "name": "externallmg_1697628156478_1697628151811_image_2.jpeg",
    "path": "cases/652e7f067e32132d4092e4ff/
externallmg_1697628156478_1697628151811_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652fc0557e32132d409496bc",
    "name": "externallmg_1697628160752_1697628151811_image_3.jpeg",
    "path": "cases/652e7f067e32132d4092e4ff/
externallmg_1697628160752_1697628151811_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652fc0557e32132d409496bd",
    "name": "externallmg_1697628165659_1697628151811_image_4.jpeg",
    "path": "cases/652e7f067e32132d4092e4ff/
externallmg_1697628165659_1697628151811_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652fc0557e32132d409496be",
    "name": "externallmg_1697628177258_1697628151811_image_5.jpeg",
    "path": "cases/652e7f067e32132d4092e4ff/
externallmg_1697628177258_1697628151811_image_5.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652fc0557e32132d409496bf",
  "name": "externallmg_1697628186293_1697628151811_image_6.jpeg",
  "path": "cases/652e7f067e32132d4092e4ff/
externallmg_1697628186293_1697628151811_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652fc0557e32132d409496c0",
  "name": "externallmg_1697628187537_1697628151811_image_7.jpeg",
  "path": "cases/652e7f067e32132d4092e4ff/
externallmg_1697628187537_1697628151811_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "652fc0557e32132d409496c1",
  "name": "externallmg_1697628085699_1697628112489_image_0.jpeg",
  "path": "cases/652e7f067e32132d4092e4ff/
externallmg_1697628085699_1697628112489_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "652fc0557e32132d409496c2",
  "name": "externallmg_1697628104824_1697628112494_image_1.jpeg",
  "path": "cases/652e7f067e32132d4092e4ff/
externallmg_1697628104824_1697628112494_image_1.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-10-17T12:33:10.600Z",
"updatedAt": "2023-10-20T05:58:57.236Z",
"__v": 0,
"invoiceId": "652e7f077e32132d4092e522",
```

"fullAddress": "Residential Flat No. 1401, 14th Floor, Building No 45, Wing - B, Gagan 45, Nehru Nagar Kedar Darshan Co-op. Hsg. Soc. Ltd., Nehru Nagar, Village - Kurla 3, Taluka - Kurla, District - Mumbai, Kurla (East), PIN - 400 024, State - Maharashtra, India",

"updatedBy": "60eebe33f3dd69653a5837ae",
"addressForMap": "",
"caseReferredBy": "651e5a18b98e691677d9b737",
"contactPersonName": "Mr. Inderjit Singh (Sales Manager)",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9819784307",
"buildingServicesRate": "2900",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 845.00",
"flatRate": "19500",
"landOtherRate": "16600",
"builtupPercentage": "10",
"carpetTotal": "0",
"extendOfSiteRemark": "",
"finalBuiltupArea": "0.00",
"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"otherCarpetTotal": "0",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"finalSaleablePercentage": "0",
"landDetails": {
 "holdType": {
 "label": "Free Hold",
 "value": "Free_Hold"
 },
 "leaseDetails": {
 "lessorName": "",
 "lesseeName": "",
 "leasePremium": "",
 "leaseRent": "",
 "leasePeriod": 0,


```
"leaseFrom": "",  
"leaseTo": "",  
"remainingLeasePeriod": 0,  
"leaseDate": ""  
}  
}  
}
```

| Name | Length | Width | Total |
|---------------|---------------|--------------|--------------|
| <hr/> | | | |
| Composition : | | | |
| <hr/> | | | |
| Other | | | |
| Composition : | | | |
| <hr/> | | | |