

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63b26511191f7b344b008a1d"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f66be948726cc141b8b",
    "email": "coorddesk.rasmecbhy@sbi.co.in",
    "firstName": "SHASHI RANJAN",
    "mobileNo": "",
    "workMobileNo": "9867369914",
    "lastName": "RANJAN"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5553000",
    "discussWithPerson": "SHASHI RANJAN",
    "expectedFees": 2776.5,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63b26511191f7b344b008a1d",
  "name": "RASMECCC BHAYANDAR",
  "branchCode": "",
  "mobileNo": "022-28149108",
  "alternateMobileNo": "",
  "email": "Coorddesk.rasmecbhy@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "RASMECCC Bhayandar Branch\nUnit No. 101, 102, 103B, 1st Floor, IT
Landmark Building, 150ft. Road, Near Hotel Shree Nidhi, \nOpp. Maxus Mall,
Bhayander (West), Thane – 401 101, \nState – Maharashtra, Country – India."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "627219d6afd7d55eddedd283",
"role": "PICKUPPERSON",
"firstName": "Mangesh ",
"email": "mangeshpalande17@gmail.com",
"lastName": "Palande",
"mobileNo": "9833030550",
"shortName": "MP",
"workWithDocumentMaker": "",
"profilePhoto": "users/627219d6afd7d55eddedd283/
profilePhoto_1668055836118_WhatsApp_Image_20221110_at_101725_AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "62ea09ea4e679b264caf07d7",
"role": "SITEENGINEER",
"firstName": "Suraj",
"email": "suraj@vastukala.org",
"lastName": "Zore",
"mobileNo": "8652448654",
"designation": "",
"shortName": "SZ",
"workWithDocumentMaker": "60092304a16fab0f2af9b0c2",
"profilePhoto": "users/62ea09ea4e679b264caf07d7/
profilePhoto_1685629394240_image.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "64cde526dc9f3034f3fefa49",
"role": "FRONTDESK",
"firstName": "Rashmi",
"email": "rashmijadhav14feb@gmail.com",
"lastName": "Jadhav",
"mobileNo": "7738144625",
"designation": "Back Office Coordinatiion",
"shortName": "RJ",
"workWithDocumentMaker": "60eeaeddf3dd69653a581316",
"profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "62fe044a48a26047e6552796",
"role": "MAKER",
"firstName": "Pradnya ",
"email": "pradnya@vastukala.org",
"lastName": "Rasam",
```

```
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "_id": "64cde526dc9f3034f3fefa49",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg",
  "firstName": "Rashmi",
  "lastName": "Jadhav",
  "shortName": "RJ",
  "email": "rashmijadhav14feb@gmail.com",
  "designation": "Back Office Coordinatiion",
  "mobileNo": "7738144625",
  "role": "FRONTDESK",
  "type": "EMPLOYEE",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
  }
]
```

```
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.268641292701783",
  "longitude": " 72.96990072153383"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.96990072153383,
    19.268641292701783
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-19",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-18",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-18",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
```

```
"key": "country",
"value": "India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Vadavali",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "4",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Thane (West)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
```

```
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Sukur Sapphire - Phase 2",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
```



```
"value": "",
"label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "10/3A, 3B, 7/17",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
```

```
"status": false,
"name": "Block No",
"key": "blockNo",
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "404",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
```

```
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 615",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
}
```

```
"finishing": {
  "value": "Cement_Plastering_+_POP_Finish",
  "label": "Cement Plastering + POP Finish"
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Thane_Municipal_Corporation",
    "label": "Thane Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Wing - C",
    "west": "Wing - A",
    "south": "Kavita CHSL",
    "east": "Open Plot"
  },
  "asPerDocumentAgreement": {
    "north": "Details not available",
    "west": "Details not available",
    "south": "Details not available",
    "east": "Details not available"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "Details not available",
      "east": "Details not available",
      "south": "Details not available",
      "west": "Details not available"
    },
    "asPerDocument": {
```

```
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As Copy of Part Occupancy Certificate is received may
be assumed that the construction is as per sanctioned plan.",
"approvePlanVerified": "N.A",
"empanelledOfApprovePlan": "N.A"
},
"compositeRate": {
  "remark": " At the time of site visit, final finishing work of flat was in progress. ",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "97700",
  "landRate": "19900",
  "igrImage": "cases/652f734f7e32132d40937675/igr_1697628573358_Image.png",
  "squareMeterGuideLineRate": "97700.00",
  "squareFeetGuideLineRate": "9077.00"
},
"igrFinalRate": {
  "rate": "97700.00",
  "squareMeterGuideLineRate": "97700.00",
  "squareFeetGuideLineRate": "9077.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Vacant",
```

```
"label": "Vacant"
},
"monthlyRent": "11,500",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per TMC norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area ",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Allotted One Car Parking Space",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  }
}
```

```
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2023",
  "fullDate": "1/1/2023"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
}
```

```
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "As_Per_Part_Occupancy_Certificate",
  "label": "As Per Part Occupancy Certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "0",
"totalLifeBuilding": "60",
"estimatedAge": "60",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "20",
"flatFloorNo": "4",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "6"
},
"finalPlinthArea": {
```



```
"areaType": "Built Up",
"area": "460.90",
"measurementType": "Sq. Ft.",
"areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/652f734f7e32132d40937675/
routeMap_1697694781411_Image.png",
    "routeLat": "19.268748",
    "routeLng": "72.969949",
    "stationName": "Thane",
    "routeDistance": "11.2 Km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finalLatLng": true
  },
  "locationMapImg": [
    {
      "id": "kaslnq",
      "name": "kaslnq",
      "image": "cases/652f734f7e32132d40937675/
routeMap_1697694636370_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
```

```
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "5656500.00",
"finalValue": "5656500.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": ""
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "4183589.00",
  "selectedBuildUpValue": "460.90",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "6530921e7e32132d4094e495",
      "name": "externalImg_r_1697681915561_1697681944048_image_0.jpg",
      "path": "cases/652f734f7e32132d40937675/
externalImg_r_1697681915561_1697681944048_image_0.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "6530921e7e32132d4094e49a",
      "name": "externalImg_r_1697681920056_1697681944048_image_4.jpg",
      "path": "cases/652f734f7e32132d40937675/
externalImg_r_1697681920056_1697681944048_image_4.jpg",
      "orientation": "landscape"
    }
  ],
  "externalPhotos": [
    {
```

```
    "status": false,
    "_id": "6530921e7e32132d4094e496",
    "name": "externallmg_r_1697681916675_1697681944048_image_1.jpg",
    "path": "cases/652f734f7e32132d40937675/
externallmg_r_1697681916675_1697681944048_image_1.jpg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "6530921e7e32132d4094e497",
    "name": "externallmg_r_1697681918822_1697681944048_image_3.jpg",
    "path": "cases/652f734f7e32132d40937675/
externallmg_r_1697681918822_1697681944048_image_3.jpg",
    "orientation": "portrait"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "6530921e7e32132d4094e4a1",
    "name": "Living Room",
    "path": "cases/652f734f7e32132d40937675/
externallmg_r_1697681937570_1697681944048_image_12.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6530921e7e32132d4094e49f",
    "name": "Living Room",
    "path": "cases/652f734f7e32132d40937675/
externallmg_r_1697681930460_1697681944048_image_9.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6530921e7e32132d4094e499",
    "name": "Living Room",
    "path": "cases/652f734f7e32132d40937675/
externallmg_r_1697681924599_1697681944048_image_6.jpg",
    "orientation": "portrait"
  }
]
},
```

```
"indicatorRange": {
  "carpetRateRange": {
    "min": "14014",
    "max": "14218"
  },
  "builtUpRateRange": {
    "min": "11679",
    "max": "11849"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
```



```
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "419.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentId": [],
"_id": "652f734f7e32132d40937675",
"ownerName": "Wilson Pepaul Fernandes",
"ownerPhoneNo": "8692912265",
"appAddress": "flat no b/404 mukur safire fase 2 wadwali thane w",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
```

```
"value": "60ae1254aa6d152c1801b326"
},
"inputs": {
  "documentDate": "06/10/2023",
  "from": {
    "value": "Promoter",
    "label": "Promoter"
  },
  "Promoter": "M/s. Rajaram Construction",
  "to": {
    "value": "Purchasers",
    "label": "Purchasers"
  },
  "Purchasers": "Mr. Wilson Perpaul Fernandes & Mrs. Graciana Wilson Fernandes",
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "7232 / 2023"
},
"isHardCopy": false,
"displayStatus": true,
"id": "208011",
"path": "cases/652f734f7e32132d40937675/document_1697608431319_169760844
9165_WAILSON_FARNANDES__AGREEMENT.pdf",
"fileName": "document_1697608431319_1697608449165_WAILSON_FARNANDES
__AGREEMENT.pdf"
},
{
  "documentType": {
    "value": "60ae1250aa6d152c1801b316",
    "label": "Part Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "17/05/2023",
    "nameOfApprovingAuthority": {
      "value": "Thane_Municipal_Corporation",
      "label": "Thane Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "TMCB / PO / 2023 / APL / 00038"
  },
  "isHardCopy": false,
```

```
    "displayStatus": false,
    "fileName": "document_1697692192325_246068.pdf",
    "path": "cases/652f734f7e32132d40937675/
document_1697692192325_246068.pdf",
    "id": "579194",
    "uploadedBy": "62fe044a48a26047e6552796",
    "createdAt": "Thu Oct 19 2023 10:39:52 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae1247aa6d152c1801b2ea",
      "label": "Commencement Certificate"
    },
    "inputs": {
      "documentDate": "06/05/2022",
      "nameOfApprovingAuthority": {
        "value": "Thane_Municipal_Corporation",
        "label": "Thane Municipal Corporation"
      },
      "number": {
        "value": "No",
        "label": "No"
      }
    },
    "No": "S06 / 0180 / 13 / TMC / TDD / 4047 / 22"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1697692247172_339132.pdf",
  "path": "cases/652f734f7e32132d40937675/
document_1697692247172_339132.pdf",
  "id": "154765",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Thu Oct 19 2023 10:40:47 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "09/06/2022",
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "P51700045743"
```

```
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1697692297114_248757.pdf",
    "path": "cases/652f734f7e32132d40937675/
document_1697692297114_248757.pdf",
    "id": "911092",
    "uploadedBy": "62fe044a48a26047e6552796",
    "createdAt": "Thu Oct 19 2023 10:41:37 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae12b1aa6d152c1801b4d6",
      "label": "Title Report"
    },
    "inputs": {
      "documentDate": "19/05/2022",
      "remark": " issued by Damodar A. Patil (Advocate)",
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "DAP / 2022 / 24"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1697692383246_342972.pdf",
    "path": "cases/652f734f7e32132d40937675/
document_1697692383246_342972.pdf",
    "id": "451544",
    "uploadedBy": "62fe044a48a26047e6552796",
    "createdAt": "Thu Oct 19 2023 10:43:03 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "004469",
"createdBy": "627219d6afd7d55eddedd283",
"caseHistory": [
  {
    "id": "130342",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Oct 18 2023 11:25:27 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
```

```
"name": "Mr. Wilson Perpaul Fernandes & Mrs. Graciana Wilson Fernandes",
"phone": "8692912265",
"ownershipShare": "",
"email": "",
"id": "950621"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "361885",
  "name": "Living Room",
  "length": "9.75",
  "length1": "9",
  "length2": "9",
  "width": "14.67",
  "width1": "14",
  "width2": "8",
  "totalArea": "143.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "143.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Kitchen",
  "length": "9.42",
  "length1": "9",
  "length2": "5",
  "width": "7.25",
  "width1": "7",
  "width2": "3",
  "totalArea": "68.27",
  "images": [],
  "extraAreas": [],
  "finalArea": "68.27"
},
}
```

```
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Passage",
  "length": "2.75",
  "length1": "2",
  "length2": "9",
  "width": "4.33",
  "width1": "4",
  "width2": "4",
  "totalArea": "11.92",
  "images": [],
  "extraAreas": [],
  "finalArea": "11.92"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "WC",
  "length": "3.83",
  "length1": "3",
  "length2": "10",
  "width": "6.92",
  "width1": "6",
  "width2": "11",
  "totalArea": "26.51",
  "images": [],
  "extraAreas": [],
  "finalArea": "26.51"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Bathroom",
  "length": "3.83",
  "length1": "3",
  "length2": "10",
```

```
"width": "6.92",
"width1": "6",
"width2": "11",
"totalArea": "26.51",
"images": [],
"extraAreas": [],
"finalArea": "26.51"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Bedroom",
  "length": "10.50",
  "length1": "10",
  "length2": "6",
  "width": "10.67",
  "width1": "10",
  "width2": "8",
  "totalArea": "112.00",
  "images": [],
  "finalArea": "112.00",
  "extraAreas": []
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "label": "Dry Balcony Area",
      "value": "Dry_Balcony_Area"
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "0",
    "length1": "2",
    "length2": "9",
    "length": "2.75",
    "width1": "5",
```

```
"width2": "10",
"width": "5.83",
"totalArea": "16.04",
"percentageBeforeTotal": "16.04",
"images": [],
"extraAreas": [],
"percentage": "100",
"finalArea": "16.04"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Balcony Area",
    "value": "Balcony_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "length1": "9",
  "length2": "9",
  "length": "9.75",
  "width1": "2",
  "width2": "3",
  "width": "2.25",
  "totalArea": "21.94",
  "percentageBeforeTotal": "21.94",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "21.94"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Balcony Area",
    "value": "Balcony_Area"
  },
  "measurementType": {
```



```
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "length1": "2",
  "length2": "1",
  "length": "2.08",
  "width1": "10",
  "width2": "9",
  "width": "10.75",
  "totalArea": "22.40",
  "percentageBeforeTotal": "22.40",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "22.4"
}
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "38.93",
    "totalAreaDocument": "419",
    "docBultupPercentage": "10",
    "docFinalBultUp": "460.90",
    "docFinalBultUpSquareMeter": "42.82",
    "docSaleablePercentage": "",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "572282"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "652fc1d07e32132d40949bcc",
```

```
"property": "Residential Flat",
"area": "421",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"source": "https://www.99acres.com/",
"expectedPrice": "5900000",
"expectedRate": "14014.25",
"builtUpExpectedRate": "11678.54",
"image": "cases/652f734f7e32132d40937675/
indicator_1697628359396_Image.png",
"squareMeter": "39.11",
"id": "312727"
},
{
  "printlnReport": true,
  "_id": "652fc1d07e32132d40949bcd",
  "property": "Residential Flat",
  "area": "422",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "https://www.99acres.com/",
  "expectedPrice": "6000000",
  "expectedRate": "14218.01",
  "builtUpExpectedRate": "11848.34",
  "image": "cases/652f734f7e32132d40937675/
indicator_1697628392631_Image.png",
  "squareMeter": "39.21",
  "id": "376996"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6530921e7e32132d4094e495",
    "name": "externalImg_r_1697681915561_1697681944048_image_0.jpg",
    "path": "cases/652f734f7e32132d40937675/
externalImg_r_1697681915561_1697681944048_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "6530921e7e32132d4094e496",
  "name": "externallmg_r_1697681916675_1697681944048_image_1.jpg",
  "path": "cases/652f734f7e32132d40937675/
externallmg_r_1697681916675_1697681944048_image_1.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6530921e7e32132d4094e497",
  "name": "externallmg_r_1697681918822_1697681944048_image_3.jpg",
  "path": "cases/652f734f7e32132d40937675/
externallmg_r_1697681918822_1697681944048_image_3.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6530921e7e32132d4094e498",
  "name": "externallmg_r_1697681917815_1697681944048_image_2.jpg",
  "path": "cases/652f734f7e32132d40937675/
externallmg_r_1697681917815_1697681944048_image_2.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6530921e7e32132d4094e499",
  "name": "externallmg_r_1697681924599_1697681944048_image_6.jpg",
  "path": "cases/652f734f7e32132d40937675/
externallmg_r_1697681924599_1697681944048_image_6.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6530921e7e32132d4094e49a",
  "name": "externallmg_r_1697681920056_1697681944048_image_4.jpg",
  "path": "cases/652f734f7e32132d40937675/
externallmg_r_1697681920056_1697681944048_image_4.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "6530921e7e32132d4094e49b",
    "name": "externallmg_r_1697681922806_1697681944048_image_5.jpg",
    "path": "cases/652f734f7e32132d40937675/
externallmg_r_1697681922806_1697681944048_image_5.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6530921e7e32132d4094e49c",
    "name": "externallmg_r_1697681926435_1697681944048_image_7.jpg",
    "path": "cases/652f734f7e32132d40937675/
externallmg_r_1697681926435_1697681944048_image_7.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6530921e7e32132d4094e49d",
    "name": "externallmg_r_1697681932404_1697681944048_image_10.jpg",
    "path": "cases/652f734f7e32132d40937675/
externallmg_r_1697681932404_1697681944048_image_10.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6530921e7e32132d4094e49e",
    "name": "externallmg_r_1697681928638_1697681944048_image_8.jpg",
    "path": "cases/652f734f7e32132d40937675/
externallmg_r_1697681928638_1697681944048_image_8.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6530921e7e32132d4094e49f",
    "name": "externallmg_r_1697681930460_1697681944048_image_9.jpg",
    "path": "cases/652f734f7e32132d40937675/
externallmg_r_1697681930460_1697681944048_image_9.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6530921e7e32132d4094e4a0",
```

```
    "name": "externallmg_r_1697681933841_1697681944048_image_11.jpg",
    "path": "cases/652f734f7e32132d40937675/
externallmg_r_1697681933841_1697681944048_image_11.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6530921e7e32132d4094e4a1",
    "name": "externallmg_r_1697681937570_1697681944048_image_12.jpg",
    "path": "cases/652f734f7e32132d40937675/
externallmg_r_1697681937570_1697681944048_image_12.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6530921e7e32132d4094e4a2",
    "name": "externallmg_r_1697681938451_1697681944048_image_13.jpg",
    "path": "cases/652f734f7e32132d40937675/
externallmg_r_1697681938451_1697681944048_image_13.jpg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6530921e7e32132d4094e4a3",
    "name": "externallmg_r_1697681887388_1697681915724_image_2.png",
    "path": "cases/652f734f7e32132d40937675/
externallmg_r_1697681887388_1697681915724_image_2.png",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6530921e7e32132d4094e4a4",
    "name": "externallmg_r_1697681886168_1697681915724_image_1.jpg",
    "path": "cases/652f734f7e32132d40937675/
externallmg_r_1697681886168_1697681915724_image_1.jpg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6530921e7e32132d4094e4a5",
    "name": "externallmg_r_1697681884883_1697681915724_image_0.jpg",
```

```
    "path": "cases/652f734f7e32132d40937675/
externallmg_r_1697681884883_1697681915724_image_0.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Calculation Sheet.xlsx",
    "filename": "1697691014362_Calculation_Sheet.xlsx",
    "path": "cases/652f734f7e32132d40937675/
processingDocuments/1697691014362_Calculation_Sheet.xlsx",
    "size": "16247",
    "createdAt": "Thu Oct 19 2023 10:20:14 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  },
  {
    "originalname": "Summary Sheet.xlsx",
    "filename": "1697691014364_Summary_Sheet.xlsx",
    "path": "cases/652f734f7e32132d40937675/
processingDocuments/1697691014364_Summary_Sheet.xlsx",
    "size": "2939854",
    "createdAt": "Thu Oct 19 2023 10:20:14 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  }
],
"remarks": [],
"createdAt": "2023-10-18T05:55:27.926Z",
"updatedAt": "2023-10-19T07:20:45.443Z",
"__v": 0,
"invoiceId": "652f73517e32132d409376a9",
"fullAddress": "Residential Flat No. 404, 4th Floor, Wing - B, Sukur Sapphire - Phase
2, Village - Vadavali, Taluka - Thane, District - Thane, Thane (West), PIN - 400 615,
State - Maharashtra, India",
"updatedBy": "64cde526dc9f3034f3fefa49",
"addressForMap": "",
"caseReferredBy": "627219d6afd7d55eddedd283",
"contactPersonName": "Mr. Dinesh",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Supervisor",
"siteVisitContactNo": "8692912265",
"buildingServicesRate": "3000",
```

```
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 419.00",
"flatRate": "13500",
"landOtherRate": "10500",
"builtupPercentage": "10",
"carpetTotal": "388.21",
"extendOfSiteRemark": "",
"finalBuiltupArea": "493.45",
"finalCarpetArea": "448.59",
"finalSalableArea": "542.79",
"otherCarpetTotal": "60.38",
"salablePercentage": "10",
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 388.00\nDry Balcony Area in Sq.
Ft. = 16.00\nBalcony Area in Sq. Ft. = 44.00\n\n",
"toBeAdded": "",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Passage + WC +
Bathroom",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "60.38",
"otherCompositionSaleableTotal": "0.00",
"finalSaleablePercentage": "0",
"siteVisitDate": "2023-10-18",
"reportGeneratedDate": "Thu Oct 19 2023 10:23:47 GMT+0530 (India Standard
Time)",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
  "leaseFrom": "",
  "leaseTo": "",
  "remainingLeasePeriod": 0,
  "leaseDate": ""
}
},
"shopDetails": {
```

```
"typeOfShops": null,  
"roadFacing": false,  
"mall": false
```

```
}  
}
```

Name	Length	Width	Total
Composition :			
Living Room	9'9"	14'8"	143.00
Kitchen	9'5"	7'3"	68.27
Passage	2'9"	4'4"	11.92
WC	3'10"	6'11"	26.51
Bathroom	3'10"	6'11"	26.51
Bedroom	10'6"	10'8"	112.00
Other Composition :			
Dry Balcony Area	2'9"	5'10"	16.04
Balcony Area	9'9"	2'3"	21.94
Balcony Area	2'1"	10'9"	22.40