

```
{
  "typeOfReport": {
    "value": "Cost_Vetting",
    "label": "Cost Vetting"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002",
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002"
  },
  "masterTypeOfPurpose": {
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002",
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "646dc536b05e530fb6c47b3b"
    },
    "type": "CREDITOFFICER",
    "_id": "64cb7e0add0a6d4cc439286c",
    "firstName": "Pushpa",
    "lastName": "Potinde",
    "mobileNo": "",
    "workMobileNo": "9403511861",
    "email": "cs.ho@bankofbaroda.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": ""
  }
}
```

```
"expectedFees": null,
"quotedAmount": "1180"
},
"organization": {
  "_id": "643a5bee108b68389ed736e5",
  "name": "Nashik Branch",
  "shortName": "NSK",
  "email": "nashik@vastukala.org",
  "address": "4, 1st Floor, Mashusha Elite, Vrundavan Naka Link Road, Adgaon, ",
  "city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180c",
  "type": "BANK",
  "name": "Bank Of Baroda",
  "displayName": "Bank Of Baroda",
  "initial": "BOB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "646dc536b05e530fb6c47b3b",
  "name": "RO Nashik\t",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "rlf.nasik@bankofbaroda.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "BSN Building, Data Mandir Road, Nashik Road, Nashik 422101\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "63fda060ce84bf289baace4c",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "63f9ed37ce84bf289ba991ac",
  "role": "FRONTDESK",
  "firstName": "Rushikesh",
  "email": "rushingle2201@gmail.com",
  "lastName": "Pingle",
  "mobileNo": "8788210361",
  "shortName": "RUP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "63f9f4adce84bf289ba9956e",
  "role": "FRONTDESK + ENGINEER",
  "firstName": "Swapnil",
  "email": "waghswapnil309@gmail.com",
  "lastName": "Wagh",
  "mobileNo": "8237116625",
  "designation": "",
  "shortName": "SW",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/63f9f4adce84bf289ba9956e/
profilePhoto_1688707461551_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "636a1ad14d42487767af3f91",
  "role": "MAKER + RATE VERFIER",
  "firstName": "Chintamani",
  "email": "chintamanichaudhari099@gmail.com",
  "lastName": "Chaudhari",
  "mobileNo": "8007230780",
  "designation": "",
  "shortName": "Chintamani",
  "workWithDocumentMaker": "62724142afd7d55eddede405",
  "profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "63f9ed37ce84bf289ba991ac",
  "role": "FRONTDESK",
  "firstName": "Rushikesh",
  "email": "rushingle2201@gmail.com",
```

```
"lastName": "Pingle",
"mobileNo": "8788210361",
"designation": "",
"shortName": "RUP",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "64dc7184ccaf1e7b7f637f47",
  "role": "FRONTDESK",
  "firstName": "Binumon",
  "email": "binu@vastukala.org",
  "lastName": "Moozhickal",
  "mobileNo": "9930252906",
  "designation": "Back Office Team Leader",
  "shortName": "BS",
  "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
  "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"valuers": [],
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.984867000641618",
  "longitude": "73.79524909060714"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
}
```

```
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Nashik",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "2",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
```

```
"value": "Nashik",
"label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "1",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Marhaba Residency",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
```

```
"status": false,
"name": "Street 1 ",
"key": "street1",
"value": "",
"label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Pakhhal Road",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Beside Nashik Vapi Transport ",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "812/2/1/1",
```

```
"label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "201",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
```



```
"name": "Mouza",
"key": "mouza",
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422011",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
}
```

```
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "areaType": "Built Up",
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
```

```
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
},
```

```
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```

```
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
}
```

```
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentId": [],
"_id": "652f7d3e7e32132d40939494",
"ownerName": "Farhanaz Shaikh ",
"ownerPhoneNo": "7722039280",
"fullAddress": " Cost Vetting No. 201, 2nd Floor, Marhaba Residency, Beside Nashik
Vapi Transport , Plot No. 1, New/Current Survey No. 812/2/1/1, Pakhal Road, Village -
Nashik, Taluka - Nashik, District - Nashik, Nashik, 422011",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae128aaa6d152c1801b41f",
      "label": "Vetting Documents"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1697611017178_Sarfaraaj_Shaikh_Extra_Amunity.pdf",
    "path": "cases/652f7d3e7e32132d40939494/
document_1697611017178_Sarfaraaj_Shaikh_Extra_Amunity.pdf",
    "id": "362474",
    "uploadedBy": "63f9ed37ce84bf289ba991ac",
    "createdAt": "Wed Oct 18 2023 12:07:04 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "004471",
"createdBy": "63f9ed37ce84bf289ba991ac",
"caseHistory": [
  {
    "id": "498110",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Oct 18 2023 12:07:50 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Farhanaz Shaikh ",
    "phone": "7722039280",
    "ownershipShare": ""
  }
]
```



```
    "email": "",
    "id": "230647"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652f7db67e32132d40939952",
    "name":
"externalImg_1697611188461_WhatsApp_Image_20231010_at_11644_PM.jpeg",
    "path": "cases/652f7d3e7e32132d40939494/
externalImg_1697611188461_WhatsApp_Image_20231010_at_11644_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652f7db67e32132d40939953",
    "name":
"externalImg_1697611188536_WhatsApp_Image_20231010_at_11645_PM_1.jpeg",
    "path": "cases/652f7d3e7e32132d40939494/
externalImg_1697611188536_WhatsApp_Image_20231010_at_11645_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652f7db67e32132d40939954",
    "name":
"externalImg_1697611188615_WhatsApp_Image_20231010_at_11645_PM.jpeg",
    "path": "cases/652f7d3e7e32132d40939494/
externalImg_1697611188615_WhatsApp_Image_20231010_at_11645_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "652f7db67e32132d40939955",
    "name":
"externallmg_1697611188714_WhatsApp_Image_20231010_at_11651_PM.jpeg",
    "path": "cases/652f7d3e7e32132d40939494/
externallmg_1697611188714_WhatsApp_Image_20231010_at_11651_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652f7db67e32132d40939956",
    "name":
"externallmg_1697611188847_WhatsApp_Image_20231010_at_11653_PM.jpeg",
    "path": "cases/652f7d3e7e32132d40939494/
externallmg_1697611188847_WhatsApp_Image_20231010_at_11653_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652f7db67e32132d40939957",
    "name":
"externallmg_1697611188941_WhatsApp_Image_20231010_at_11658_PM.jpeg",
    "path": "cases/652f7d3e7e32132d40939494/
externallmg_1697611188941_WhatsApp_Image_20231010_at_11658_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652f7db67e32132d40939958",
    "name":
"externallmg_1697611189024_WhatsApp_Image_20231010_at_11701_PM.jpeg",
    "path": "cases/652f7d3e7e32132d40939494/
externallmg_1697611189024_WhatsApp_Image_20231010_at_11701_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652f7db67e32132d40939959",
    "name":
"externallmg_1697611189131_WhatsApp_Image_20231010_at_11706_PM.jpeg",
    "path": "cases/652f7d3e7e32132d40939494/
externallmg_1697611189131_WhatsApp_Image_20231010_at_11706_PM.jpeg",
    "orientation": "portrait"
  }
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652f7db67e32132d4093995a",
  "name":
  "externallmg_1697611189259_WhatsApp_Image_20231010_at_11710_PM.jpeg",
  "path": "cases/652f7d3e7e32132d40939494/
externallmg_1697611189259_WhatsApp_Image_20231010_at_11710_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652f7db67e32132d4093995b",
  "name":
  "externallmg_1697611189372_WhatsApp_Image_20231010_at_11712_PM.jpeg",
  "path": "cases/652f7d3e7e32132d40939494/
externallmg_1697611189372_WhatsApp_Image_20231010_at_11712_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652f7db67e32132d4093995c",
  "name":
  "externallmg_1697611189488_WhatsApp_Image_20231010_at_11716_PM.jpeg",
  "path": "cases/652f7d3e7e32132d40939494/
externallmg_1697611189488_WhatsApp_Image_20231010_at_11716_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652f7db67e32132d4093995d",
  "name":
  "externallmg_1697611189627_WhatsApp_Image_20231010_at_11721_PM.jpeg",
  "path": "cases/652f7d3e7e32132d40939494/
externallmg_1697611189627_WhatsApp_Image_20231010_at_11721_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652f7db67e32132d4093995e",
  "name":
  "externallmg_1697611189743_WhatsApp_Image_20231010_at_11723_PM.jpeg",
```

```
    "path": "cases/652f7d3e7e32132d40939494/
externallmg_1697611189743_WhatsApp_Image_20231010_at_11723_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652f7db67e32132d4093995f",
    "name":
"externallmg_1697611189826_WhatsApp_Image_20231010_at_11724_PM.jpeg",
    "path": "cases/652f7d3e7e32132d40939494/
externallmg_1697611189826_WhatsApp_Image_20231010_at_11724_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652f7db67e32132d40939960",
    "name":
"externallmg_1697611189893_WhatsApp_Image_20231010_at_11729_PM.jpeg",
    "path": "cases/652f7d3e7e32132d40939494/
externallmg_1697611189893_WhatsApp_Image_20231010_at_11729_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652f7db67e32132d40939961",
    "name":
"externallmg_1697611190016_WhatsApp_Image_20231010_at_11731_PM.jpeg",
    "path": "cases/652f7d3e7e32132d40939494/
externallmg_1697611190016_WhatsApp_Image_20231010_at_11731_PM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-10-18T06:37:50.705Z",
"updatedAt": "2023-10-18T06:39:50.279Z",
"__v": 0,
"invoiceId": "652f7d407e32132d409394d2",
"updatedBy": "63f9ed37ce84bf289ba991ac",
"addressForMap": "",
"caseReferredBy": "643a91f233d16f6b1237a4ee",
"contactPersonName": "Farhanaz Shaikh ",
```

"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "7722039280"

}

| Name | Length | Width | Total |
|-------------|---------------|--------------|--------------|
|-------------|---------------|--------------|--------------|

Composition :

Other

Composition :
