

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7f7"
    },
    "type": "CREDITOFFICER",
    "_id": "64d4829d87258203eab0d8d8",
    "firstName": "Shivani ",
    "lastName": "Yadav",
    "mobileNo": "",
    "workMobileNo": "8240289378",
    "email": "racpcghatkopar.sanctions@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "10000000",
    "discussWithPerson": "Shivani ",
    "expectedFees": 5000,
    "quotedAmount": "2500"
  },
  "organization": {
```

```
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7f7",
  "branchCode": "000064",
  "type": "BRANCH",
  "name": "RACPC Ghatkopar (West)",
  "email": "racpcghatkopar.sanctions@sbi.co.in",
  "mobileNo": "022-25009143",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, 1st Floor, Ashok Silk Mills
Compound, LBS Marg, Ghatkopar (West), Mumbai - 400 086, State - Maharashtra,
Country - India.\r\n\r\n\r\n",
  "ledgerName": "STATE BANK OF INDIA - RACPC GHATKOPAR",
  "fax": "022-25009010",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f9462345132d6a6bddb9d5",
  "role": "SITEENGINEER",
  "firstName": "Dashrath ",
  "email": "dasrat.jaiswar1234@gmail.com",
  "lastName": "Jaiswar",
  "mobileNo": "9987305468",
  "designation": "",
  "shortName": "DFJ",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
  "designation": "",
  "shortName": "NK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
```

```
"designation": "",
"shortName": "NK",
"workWithDocumentMaker": "",
"profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "627221f4afd7d55eddeddcb4",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Prajakta",
"email": "prajakta@vastukala.org",
"lastName": "Patil",
"mobileNo": "9769797568",
"designation": "",
"shortName": "P",
"workWithDocumentMaker": "",
"profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
}
],
{
"title": {
```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.058963943107393",
  "longitude": "72.8826607490844"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.8826607490844,
    19.058963943107393
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-21",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-21",
      "remark": ""
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
```

```
"name": "Village",
"key": "village",
"value": "Chembur",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "2",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kurla",
  "label": true
}
```

```
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "46/47",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "The Highway Co-Op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
```



```
"key": "wing",
"value": "",
"label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Shiv Shruti ",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "14 (pt)",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "114/25",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
}
```

```
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "C-6",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
```

```
"value": "",
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 024",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Kurla (East), Mumbai",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "Partly_Kota_Stone_/ _Partly_Vitrified_tiles_",
    "label": "Partly Kota Stone / Partly Vitrified tiles "
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Aluminium_Sliding_Windows_with_window_grills",
    "label": "Aluminium Sliding Windows with window grills"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Casting_Capping_Electrical_wiring",
    "label": "Concealed plumbing with C.P. fittings. Casting Capping Electrical wiring"
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
}
},
"general": {
```

```
"ownership": {
  "value": "Joint_Ownership",
  "label": "Joint Ownership"
},
"populationClassList": {
  "value": "MiddleClass",
  "label": "Middle Class"
},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "MCGM",
  "label": "Municipal Corporation of Greater Mumbai (MCGM)"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Road",
  "west": "Konkan Prantiya CHSL",
  "south": "Sarvodaya Vidya Niketan",
  "east": "Ajanta Building"
},
"asPerDocumentAgreement": {
  "north": "Details not available",
  "west": "Details not available",
  "south": "Details not available",
  "east": "Details not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  }
},
"isDisplay": false,
```

```
    "title": "Boundaries of The Flat"
  },
  "extraDetailOfProperty": "",
  "dateOfIssusApprovePlan": "As Occupancy Certificate is available it may be
assumed that the construction is as per Sanctioned Plan.",
  "approvePlanVerified": "N.A.",
  "empanelledOfApprovePlan": "N.A."
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "67.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "22610",
  "depreciatedBuildingRate": "910"
},
"igrRate": {
  "propertyName": "Residential ",
  "rate": "93710",
  "landRate": "39150",
  "igrImage": "cases/652f93627e32132d4093e810/igr_1698056185199_Image.png",
  "squareMeterGuideLineRate": "84339.00",
  "squareFeetGuideLineRate": "7835.00"
},
"igrFinalRate": {
  "depreciationPercentage": "57",
  "rate": "6030.00",
  "squareFeetGuideLineRate": "6030.00",
  "squareMeterGuideLineRate": "64908.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "28500",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
```

```
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per MCGM norms",
"tenantName": "",
"maintenanceOfFlat": "Normal"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Open parking space",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "1978",
```

```
"fullDate": "1/1/1978"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Normal",
  "label": "Normal"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Average",
  "label": "Average"
},
"structuralSafety": {
  "value": "Normal",
  "label": "Normal"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
}
```

```
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "45",
"totalLifeBuilding": "60",
"estimatedAge": "15",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "3",
"flatFloorNo": "2",
"noOfLifts": "-",
"noOfDwellingUnitsInBuilding": "3"
},
"finalPlinthArea": {
  "areaType": "Built Up",
  "area": "734.40",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
```



```
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/652f93627e32132d4093e810/
routeMap_1698059225565_Image.png",
    "routeLat": "19.057278",
    "routeLng": "72.882000",
    "stationName": "Kurla",
    "routeDistance": "1.5 Km"
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "s1i7mi",
      "name": "s1i7mi",
      "image": "cases/652f93627e32132d4093e810/
routeMap_1698060278321_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
```

```
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "13837320.00",
"finalValue": "13837320.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Mon Oct 23 2023 16:54:58 GMT+0530 (India Standard Time)",
  "number": "2303162",
  "dayCount": "15",
  "monthCount": "359",
  "generatedBy": "627221f4afd7d55eddeddcb4"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": ""
  }
}
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "4428432.00",
  "selectedBuildUpValue": "734.40",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "6533c745619c14402da9e58c",
      "name": "externalImg_1697892111464_1697892069062_image_19.jpeg",
      "path": "cases/652f93627e32132d4093e810/externalImg_1697892111464_1697892069062_image_19.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "6533c745619c14402da9e581",
      "name": "externalImg_1697892062675_1697892069062_image_8.jpeg",
      "path": "cases/652f93627e32132d4093e810/externalImg_1697892062675_1697892069062_image_8.jpeg",
      "orientation": "portrait"
    }
  ],
  "externalPhotos": [
    {
```

```
    "status": false,
    "_id": "6533c745619c14402da9e58a",
    "name": "externallmg_1697892095564_1697892069062_image_17.jpeg",
    "path": "cases/652f93627e32132d4093e810/
externallmg_1697892095564_1697892069062_image_17.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "6533c745619c14402da9e588",
    "name": "externallmg_1697892085130_1697892069062_image_15.jpeg",
    "path": "cases/652f93627e32132d4093e810/
externallmg_1697892085130_1697892069062_image_15.jpeg",
    "orientation": "portrait"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "6533c745619c14402da9e57c",
    "name": "Living Room",
    "path": "cases/652f93627e32132d4093e810/
externallmg_1697892052535_1697892069062_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6533c745619c14402da9e57a",
    "name": "Living Room",
    "path": "cases/652f93627e32132d4093e810/
externallmg_1697892045601_1697892069062_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6533c745619c14402da9e57d",
    "name": "Living Room",
    "path": "cases/652f93627e32132d4093e810/
externallmg_1697892055575_1697892069062_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
```

```
    "_id": "6533c745619c14402da9e579",
    "name": "Living Room",
    "path": "cases/652f93627e32132d4093e810/
externallmg_1697892041991_1697892069062_image_0.jpeg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "22581",
    "max": "25093"
  },
  "builtUpRateRange": {
    "min": "18818",
    "max": "20911"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
```



```
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "612.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentId": [],
"_id": "652f93627e32132d4093e810",
```

```
"ownerName": "Mr. Doveson Jose Cheruvathur",
"ownerPhoneNo": "9168599666",
"appAddress": "Flat no. C-6, 2nd Floor, The Highway CHS, Shiv Shrushti, Kurla East ",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "inputs": {
      "documentDate": "30/03/2019",
      "from": {
        "value": "Seller",
        "label": "Seller"
      },
      "Seller": "Mr. Prakash Balram Ajwani & Mrs. Neha Prakash Ajwani",
      "to": {
        "value": "purchaser",
        "label": "purchaser"
      },
      "purchaser": "Mr. Doveson Jose Cheruvathur & Mrs. Poonam Doveson
Cheruvathur",
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "4024/2019"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "108922",
    "path": "cases/652f93627e32132d4093e810/document_1697616672302_16976167
02088_Racpc_Ghatkopar_Doveson_Cheruvathur.pdf",
    "fileName": "document_1697616672302_1697616702088_Racpc_Ghatkopar_Dove
son_Cheruvathur.pdf"
  },
  {
    "documentType": {
      "value": "60ae124baa6d152c1801b2fd",
      "label": "Occupancy Certificate"
    },
    "inputs": {
      "documentDate": "30/03/1978",
      "nameOfApprovingAuthority": {
        "value": "Municipal_Corporation_Of_Greater_Mumbai",
```

```
    "label": "Municipal Corporation Of Greater Mumbai"
  },
  "number": {
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "-",
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1698057984959_124491.pdf",
"path": "cases/652f93627e32132d4093e810/
document_1698057984959_124491.pdf",
"id": "436816",
"uploadedBy": "60092304a16fab0f2af9b0c2",
"createdAt": "Mon Oct 23 2023 16:16:25 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "004474",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "219012",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Oct 18 2023 13:42:18 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Doveson Jose Cheruvathur",
    "phone": "9168599666",
    "ownershipShare": "",
    "email": "",
    "id": "270765"
  },
  {
    "name": "Mrs. Poonam Doveson Cheruvathur",
    "phone": "",
    "email": "",
    "ownershipShare": "",
    "id": "554960"
  }
],
"proposePurchasers": [],
"siteInspection": [],
```

```
"composition": [  
  {  
    "measurementType": {  
      "value": "Square_Feet",  
      "label": "Square Feet"  
    },  
    "id": "7",  
    "name": "Living Room",  
    "length": "",  
    "length1": "10",  
    "length2": "9",  
    "width": "",  
    "width1": "14",  
    "width2": "10",  
    "totalArea": "159.46",  
    "images": [],  
    "finalArea": "159.46",  
    "extraAreas": []  
  },  
  {  
    "measurementType": {  
      "value": "Square_Feet",  
      "label": "Square Feet"  
    },  
    "id": "7",  
    "name": "Kitchen",  
    "length": "13.33",  
    "length1": "13",  
    "length2": "4",  
    "width": "7.50",  
    "width1": "7",  
    "width2": "6",  
    "totalArea": "100.00",  
    "images": [],  
    "finalArea": "100.00",  
    "extraAreas": []  
  },  
  {  
    "measurementType": {  
      "value": "Square_Feet",  
      "label": "Square Feet"  
    },  
    "id": "7",  
    "name": "Passage",  
    "length": "3.00",  
    "length1": "3",
```

```
"length2": "0",
"width": "8.00",
"width1": "8",
"width2": "0",
"totalArea": "24.00",
"images": [],
"finalArea": "24.00",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Passage",
  "length": "3.25",
  "length1": "3",
  "length2": "3",
  "width": "2.83",
  "width1": "2",
  "width2": "10",
  "totalArea": "9.21",
  "images": [],
  "finalArea": "9.21",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "WC",
  "length": "3.75",
  "length1": "3",
  "length2": "9",
  "width": "7.42",
  "width1": "7",
  "width2": "5",
  "totalArea": "27.81",
  "images": [],
  "extraAreas": [],
  "finalArea": "27.81"
},
{
```

```
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "5",
"name": "Bathroom",
"length": "3.00",
"length1": "3",
"length2": "0",
"width": "4.00",
"width1": "4",
"width2": "0",
"totalArea": "12.00",
"images": [],
"extraAreas": [],
"finalArea": "12.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Bedroom",
  "length": "10.25",
  "length1": "10",
  "length2": "3",
  "width": "9.83",
  "width1": "9",
  "width2": "10",
  "totalArea": "100.79",
  "images": [],
  "finalArea": "100.79",
  "extraAreas": []
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
```

```
    "label": "Square Feet"
  },
  "selectAreaTypeDocument": "Carpet",
  "squareMeterArea": "56.86",
  "totalAreaDocument": "612.00",
  "docBUILTUPPercentage": "20",
  "docFinalBUILTUP": "734.40",
  "docFinalBUILTUPSquareMeter": "68.23",
  "docSaleablePercentage": "",
  "docFinalSaleable": "0.00",
  "docFinalSaleableSquareMeter": "0.00",
  "id": "598810"
}
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "653648b5619c14402dab3d0a",
    "property": "2 BHK Flat In Highway Society, Kurla ",
    "area": "620.00",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "Nobroker.com",
    "expectedPrice": "14000000.00",
    "expectedRate": "22580.65",
    "builtUpExpectedRate": "18817.20",
    "image": "cases/652f93627e32132d4093e810/
indicator_1698055535136_Image.png",
    "squareMeter": "57.60",
    "id": "865421"
  },
  {
    "printlnReport": true,
    "_id": "653648b5619c14402dab3d0b",
    "property": "1 BHK Flat In Amar Chs For Sale In Kurla East",
    "area": "480.00",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "Nobroker.com",
    "expectedPrice": "11000000.00",
    "expectedRate": "22916.67",
```

```
"builtUpExpectedRate": "19097.22",
"image": "cases/652f93627e32132d4093e810/
indicator_1698055595780_Image.png",
"squareMeter": "44.59",
"id": "344705"
},
{
  "printlnReport": true,
  "_id": "653648b5619c14402dab3d0c",
  "property": "2 BHK Flat In Parijat For Sale In Kurla",
  "area": "830.00",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "source": "Nobroker.com",
  "expectedPrice": "16500000.00",
  "expectedRate": "19879.52",
  "builtUpExpectedRate": "0.00",
  "image": "cases/652f93627e32132d4093e810/
indicator_1698055665512_Image.png",
  "squareMeter": "77.11",
  "id": "147660"
},
{
  "printlnReport": false,
  "_id": "653648b5619c14402dab3d0d",
  "property": "Shri Shri Kalimata CHS, Shiv Shakti Nagar, Kurla East, Mumbai",
  "area": "540.00",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "Housing.Com",
  "expectedPrice": "12500000",
  "expectedRate": "23148.15",
  "builtUpExpectedRate": "19290.12",
  "image": "cases/652f93627e32132d4093e810/
indicator_1698055869963_Image.png",
  "squareMeter": "50.17",
  "id": "546493"
},
{
  "printlnReport": true,
  "_id": "653648b5619c14402dab3d0e",
  "property": "805 Sq-ft 2 BHK Flat For Sale in Shiv Srushti Kurla, Mumbai",
```



```
"area": "805.00",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"source": "magic_bricks",
"expectedPrice": "20200000",
"expectedRate": "25093.17",
"builtUpExpectedRate": "20910.97",
"image": "cases/652f93627e32132d4093e810/
indicator_1698056345630_Image.png",
"squareMeter": "74.79",
"id": "674059"
}
],
"externalImages": [
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "6533c745619c14402da9e579",
"name": "externallmg_1697892041991_1697892069062_image_0.jpeg",
"path": "cases/652f93627e32132d4093e810/
externallmg_1697892041991_1697892069062_image_0.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "6533c745619c14402da9e57a",
"name": "externallmg_1697892045601_1697892069062_image_1.jpeg",
"path": "cases/652f93627e32132d4093e810/
externallmg_1697892045601_1697892069062_image_1.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "6533c745619c14402da9e57b",
"name": "externallmg_1697892049190_1697892069062_image_2.jpeg",
"path": "cases/652f93627e32132d4093e810/
externallmg_1697892049190_1697892069062_image_2.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
```

```
    "_id": "6533c745619c14402da9e57c",
    "name": "externallmg_1697892052535_1697892069062_image_3.jpeg",
    "path": "cases/652f93627e32132d4093e810/
externallmg_1697892052535_1697892069062_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6533c745619c14402da9e57d",
    "name": "externallmg_1697892055575_1697892069062_image_4.jpeg",
    "path": "cases/652f93627e32132d4093e810/
externallmg_1697892055575_1697892069062_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6533c745619c14402da9e57e",
    "name": "externallmg_1697892057385_1697892069062_image_5.jpeg",
    "path": "cases/652f93627e32132d4093e810/
externallmg_1697892057385_1697892069062_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6533c745619c14402da9e57f",
    "name": "externallmg_1697892059025_1697892069062_image_6.jpeg",
    "path": "cases/652f93627e32132d4093e810/
externallmg_1697892059025_1697892069062_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6533c745619c14402da9e580",
    "name": "externallmg_1697892060945_1697892069062_image_7.jpeg",
    "path": "cases/652f93627e32132d4093e810/
externallmg_1697892060945_1697892069062_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6533c745619c14402da9e581",
```

```
    "name": "externallmg_1697892062675_1697892069062_image_8.jpeg",
    "path": "cases/652f93627e32132d4093e810/
externallmg_1697892062675_1697892069062_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6533c745619c14402da9e582",
    "name": "externallmg_1697892064550_1697892069062_image_9.jpeg",
    "path": "cases/652f93627e32132d4093e810/
externallmg_1697892064550_1697892069062_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6533c745619c14402da9e583",
    "name": "externallmg_1697892065965_1697892069062_image_10.jpeg",
    "path": "cases/652f93627e32132d4093e810/
externallmg_1697892065965_1697892069062_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6533c745619c14402da9e584",
    "name": "externallmg_1697892069570_1697892069062_image_11.jpeg",
    "path": "cases/652f93627e32132d4093e810/
externallmg_1697892069570_1697892069062_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6533c745619c14402da9e585",
    "name": "externallmg_1697892075285_1697892069062_image_12.jpeg",
    "path": "cases/652f93627e32132d4093e810/
externallmg_1697892075285_1697892069062_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6533c745619c14402da9e586",
    "name": "externallmg_1697892076599_1697892069062_image_13.jpeg",
```

```
    "path": "cases/652f93627e32132d4093e810/
externallmg_1697892076599_1697892069062_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6533c745619c14402da9e587",
    "name": "externallmg_1697892078060_1697892069062_image_14.jpeg",
    "path": "cases/652f93627e32132d4093e810/
externallmg_1697892078060_1697892069062_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6533c745619c14402da9e588",
    "name": "externallmg_1697892085130_1697892069062_image_15.jpeg",
    "path": "cases/652f93627e32132d4093e810/
externallmg_1697892085130_1697892069062_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6533c745619c14402da9e589",
    "name": "externallmg_1697892090365_1697892069062_image_16.jpeg",
    "path": "cases/652f93627e32132d4093e810/
externallmg_1697892090365_1697892069062_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6533c745619c14402da9e58a",
    "name": "externallmg_1697892095564_1697892069062_image_17.jpeg",
    "path": "cases/652f93627e32132d4093e810/
externallmg_1697892095564_1697892069062_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6533c745619c14402da9e58b",
    "name": "externallmg_1697892104669_1697892069062_image_18.jpeg",
    "path": "cases/652f93627e32132d4093e810/
externallmg_1697892104669_1697892069062_image_18.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6533c745619c14402da9e58c",
  "name": "externallmg_1697892111464_1697892069062_image_19.jpeg",
  "path": "cases/652f93627e32132d4093e810/
externallmg_1697892111464_1697892069062_image_19.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6533c745619c14402da9e58d",
  "name": "externallmg_1697891980125_1697892009919_image_0.jpeg",
  "path": "cases/652f93627e32132d4093e810/
externallmg_1697891980125_1697892009919_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6533c745619c14402da9e58e",
  "name": "externallmg_1697891986593_1697892009926_image_1.jpeg",
  "path": "cases/652f93627e32132d4093e810/
externallmg_1697891986593_1697892009926_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6533c745619c14402da9e58f",
  "name": "externallmg_1697891987757_1697892009926_image_2.jpeg",
  "path": "cases/652f93627e32132d4093e810/
externallmg_1697891987757_1697892009926_image_2.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-10-18T08:12:18.274Z",
"updatedAt": "2023-10-23T12:07:41.705Z",
"__v": 0,
"invoiceId": "652f93647e32132d4093e848",
```

"fullAddress": "Residential Flat No. C-6, 2nd Floor, The Highway Co-Op. Hsg. Soc. Ltd., Shiv Shruti , Plot No. 46/47, Village - Chembur, Kurla (East), Mumbai, Taluka - Kurla, District - Mumbai Suburban, PIN - 400 024, State - Maharashtra, India",  
"updatedBy": "627221f4afd7d55eddeddcb4",  
"addressForMap": "",  
"caseReferredBy": "60b7177d2ffdf65bcd65882a",  
"contactPersonName": "Mrs. Poonam Cheruvathur",  
"email": "",  
"isExternal": "false",  
"isUrgent": "false",  
"ownershipShare": "",  
"purchaseValueAsPerDocument": "",  
"relationWithOwner": "self",  
"siteVisitContactNo": "9168599666",  
"buildingServicesRate": "2800.00",  
"finalAreaType": "Carpet Area",  
"finalAsPerArea": "Agreement For Sale",  
"finalBuiltUpPercentage": "20",  
"finalCarpetConvertToBuiltUpPer": "20",  
"finalMeasurementType": "Sq. Ft.",  
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 612.00",  
"flatRate": "24500.00",  
"landOtherRate": "21700",  
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + 2 Passage + WC + Bathroom",  
"carpetTotal": "433.27",  
"otherCarpetTotal": "0.00",  
"otherCompositionBuiltUpTotal": "0.00",  
"otherCompositionCarpetTotal": "134.45",  
"otherCompositionSaleableTotal": "0.00",  
"builtupPercentage": "20",  
"finalBuiltupArea": "681.26",  
"finalCarpetArea": "567.72",  
"finalSalableArea": "749.39",  
"salablePercentage": "10",  
"toBeAdded": "",  
"extendOfSiteRemark": "Carpet Area in Sq. Ft. = 433.00\nBalcony Area in Sq. Ft. = 135.00\nTotal Carpet Area in Sq. Ft. = 568.00\n(Area as per Actual Site Measurement)",  
"siteMeasurementRemark": "",  
"finalSaleablePercentage": "0",  
"landDetails": {  
 "holdType": {  
 "label": "Free Hold",  
 "value": "Free\_Hold"  
 },  
 "leaseDetails": {

```

"lessorName": "",
"lesseeName": "",
"leasePremium": "",
"leaseRent": "",
"leasePeriod": 0,
"leaseFrom": "",
"leaseTo": "",
"remainingLeasePeriod": 0,
"leaseDate": ""
}
},
"assignmentType": {
"value": "Commercial",
"label": "Commercial"
},
"siteVisitDate": "2023-10-21",
"shopDetails": {
"typeOfShops": null,
"roadFacing": false,
"mall": false
}
}

```

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
Composition :			
Living Room	10'9"	14'10"	159.46
Kitchen	13'4"	7'6"	100.00
Passage	3'0"	8'0"	24.00
Passage	3'3"	2'10"	9.21
WC	3'9"	7'5"	27.81
Bathroom	3'0"	4'0"	12.00
Bedroom	10'3"	9'10"	100.79
Other Composition :			