

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b951"
    },
    "type": "CREDITOFFICER",
    "_id": "635f732fe363ef22db2f1c80",
    "firstName": "Ravindra Sir",
    "lastName": "sir",
    "mobileNo": "",
    "email": "me1@me.com",
    "workMobileNo": "7738642220"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "2425000",
    "discussWithPerson": "Ravindra Sir",
    "expectedFees": 1212.5,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b951",
  "branchCode": "000167",
  "type": "BRANCH",
  "name": "RACPC Belapur ",
  "email": "sbi.14677@sbi.co.in",
  "mobileNo": "022-27524090",
  "alternateMobileNo": "",
  "address": "Estate Department Corporate Centre, 4th Floor, CIDCO Tower No. 4,
Railway Station Building, C.B.D. Belapur, Navi Mumbai - 400 614, State - Maharashtra,
Country - India.",
  "ledgerName": "STATE BANK OF INDIA - CBD Estate Department",
  "fax": "022 2757 7002",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7189d2ffdf65bcd65882b",
  "role": "PICKUPPERSON",
  "firstName": "Ravindra",
  "email": "ravindrakasare186@gmail.com",
  "lastName": "Kasare",
  "mobileNo": "9167204055",
  "shortName": "RBK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60b7189d2ffdf65bcd65882b\\
\\profilePhoto_1622701555488_WhatsApp Image 2021-06-03 at 11.46.40 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "64e5a649daae6a1c98101989",
  "role": "SITEENGINEER",
  "firstName": "Sameer",
  "email": "sameeryp2010@gmail.com",
  "lastName": "Parab",
  "mobileNo": "8291009567",
  "designation": "Site Engineer",
  "shortName": "Sameer",
  "workWithDocumentMaker": "62ea09ea4e679b264caf07d7"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60eebe33f3dd69653a5837ae",
  "role": "MAKER",
  "firstName": "Shamal",
  "email": "shamal@vastukala.org",
  "lastName": "Bodke",
  "mobileNo": "9821740317",
```

```
"designation": "",
"shortName": "SB",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eebe33f3dd69653a5837ae\
\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
},
"checker": "",
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
"value": "FIIV",
"label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
"title": {
"value": "Chartered_Engineer",
"label": "Chartered Engineer"
},
"_id": "60af80072ffdf65bcd658653",
"number": "AM161706-3"
}
```

```
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.035425909412997",
  "longitude": "73.06465824907582"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.06465824907582,
    19.035425909412997
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-19",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-19",
      "remark": ""
    }
  ]
}
```

```
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-19",
      "remark": ""
    }
  ],
  "schedule": [],
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Kohoj Khuntavli",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
```

```
"key": "floorNo",
"value": "Ground",
"label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "Type B",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Ambernath (West)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Ambernath",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "3",
  "label": true
},
```

```
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Patel's Prestige",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
```



```
"value": "",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "17",
  "label": true
},
"hisNo": {
  "status": true,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "2A, C, D",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "005",
  "label": false
},
"municipalityWardNo": {
```

```
"status": false,
"name": "Municipality Ward No.",
"key": "municipalityWardNo",
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 421 501",
```

```

    "label": false
  },
  "suburb": {
    "status": false,
    "name": "Suburb",
    "key": "suburb",
    "value": "",
    "label": false
  }
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Wooden_frame_openable_widow_with_M._S._Grill",
    "label": "Wooden frame openable widow with M. S. Grill"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering_+_POP_Finish",
    "label": "Cement Plastering + POP Finish"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  }
},

```

```
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "Ambernath_Municipal_Council",
  "label": "Ambernath Municipal Council"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Club House",
  "west": "Type C",
  "south": "Internal Road",
  "east": "Open Plot"
},
"asPerDocumentAgreement": {
  "north": "Details not available",
  "west": "Details not available",
  "south": "Details not available",
  "east": "Details not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "asPerDocument": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As Occupancy Certificate is received may be assumed
that the construction is as per sanctioned plan. ",
"approvePlanVerified": "N. A.",
"empanelledOfApprovePlan": "N. A."
},
```

```
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Kohoj Khuntvali",
  "rate": "54000",
  "landRate": "10580",
  "igrImage": "cases/652fac9d7e32132d40944be7/igr_1697698062449_Image.png",
  "squareMeterGuideLineRate": "54000.00",
  "squareFeetGuideLineRate": "5017.00"
},
"igrFinalRate": {
  "depreciationPercentage": "0",
  "rate": "54000",
  "squareMeterGuideLineRate": "54000.00",
  "squareFeetGuideLineRate": "5017.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "5,500",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per ANC norms",
  "tenantName": "",
  "maintenanceOfFlat": "Good"
},
```

```
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Stilt + Open Car Parking",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2023",
    "fullDate": "1/1/2023"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  },
  "typeOfStructure": {
    "value": "R.C.C._Framed_Structure",
```

```
"label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenancelssues": {
  "value": "Information_not_available",
  "label": "Information not available"
},
}
```

```
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "60",
"ageOfBuilding": "0",
"noOfBasement": "1",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "8",
"flatFloorNo": "Ground",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "10"
},
"finalPlinthArea": {
  "areaType": "Built Up",
  "area": "381.70",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  },
  "routeMapImg": "cases/652fac9d7e32132d40944be7/
routeMap_1697709512808_Image.png",
```



```
"routeLat": "19.219917",
"routeLng": "73.201444",
"stationName": "Ambarnath",
"routeDistance": "3.5 Km."
},
"finalLatLng": {
  "coordinates": [
    null,
    null
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": true,
  "finallatLng": true
},
"locationMapImg": [
  {
    "id": "hs4qmsc",
    "name": "hs4qmsc",
    "image": "cases/652fac9d7e32132d40944be7/
routeMap_1697709427392_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
```

```
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "2637200.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "2637200.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
```

```
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
```

```
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "1914989.00",
  "selectedBuildUpValue": "381.70",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "6530ba3c7e32132d409536e0",
      "name": "externallmg_1697692177785_1697692184555_image_0.jpeg",
      "path": "cases/652fac9d7e32132d40944be7/externallmg_1697692177785_1697692184555_image_0.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "6530ba3c7e32132d409536e7",
      "name": "externallmg_1697692209579_1697692184555_image_7.jpeg",
      "path": "cases/652fac9d7e32132d40944be7/externallmg_1697692209579_1697692184555_image_7.jpeg",
      "orientation": "landscape"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "6530ba3c7e32132d409536ea",
      "name": "externallmg_1697692210294_1697692184555_image_10.jpeg",
      "path": "cases/652fac9d7e32132d40944be7/externallmg_1697692210294_1697692184555_image_10.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "6530ba3c7e32132d409536e3",
      "name": "externallmg_1697692206154_1697692184555_image_3.jpeg",
      "path": "cases/652fac9d7e32132d40944be7/externallmg_1697692206154_1697692184555_image_3.jpeg",
      "orientation": "portrait"
    }
  ],
}
```

```
{
  "status": false,
  "_id": "6530ba3c7e32132d409536e1",
  "name": "externallmg_1697692201358_1697692184555_image_1.jpeg",
  "path": "cases/652fac9d7e32132d40944be7/
externallmg_1697692201358_1697692184555_image_1.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "6530ba3c7e32132d409536e2",
  "name": "externallmg_1697692205149_1697692184555_image_2.jpeg",
  "path": "cases/652fac9d7e32132d40944be7/
externallmg_1697692205149_1697692184555_image_2.jpeg",
  "orientation": "portrait"
}
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "6530ba3c7e32132d409536eb",
    "name": "externallmg_1697692210413_1697692184555_image_11.jpeg",
    "path": "cases/652fac9d7e32132d40944be7/
externallmg_1697692210413_1697692184555_image_11.jpeg",
    "orientation": "portrait"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "6530ba3c7e32132d409536e5",
    "name": "Living Room",
    "path": "cases/652fac9d7e32132d40944be7/
externallmg_1697692208893_1697692184555_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6530ba3c7e32132d409536e6",
    "name": "Living Room",
    "path": "cases/652fac9d7e32132d40944be7/
externallmg_1697692209258_1697692184555_image_6.jpeg",
    "orientation": "portrait"
  }
]
```

```
    "status": false,
    "_id": "6530ba3c7e32132d409536e9",
    "name": "Living Room",
    "path": "cases/652fac9d7e32132d40944be7/
externallmg_1697692210009_1697692184555_image_9.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6530ba3c7e32132d409536e8",
    "name": "Living Room",
    "path": "cases/652fac9d7e32132d40944be7/
externallmg_1697692209814_1697692184555_image_8.jpeg",
    "orientation": "landscape"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "7408",
    "max": "7719"
  },
  "builtUpRateRange": {
    "min": "6735",
    "max": "7017"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```



```
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
```

```
"finalValuationArea": "347.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentId": [],
"_id": "652fac9d7e32132d40944be7",
"ownerName": "Mrs. Maremma Hanamappa Madiwal & Mr. Hanamappa Ramappa
Madiwal",
"ownerPhoneNo": "8087384252",
"appAddress": "flat no B 005 plot no 3 patel prctigr kohojkhtavali Ambernath ",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "inputs": {
      "documentDate": "10/02/2023",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "M/s. Vrudee Associates",
      "to": {
        "value": "Allottee",
        "label": "Allottee"
      },
      "Allottee": "Mrs. Maremma Hanamappa Madiwal & Mr. Hanamappa Ramappa
Madiwal",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "1747/2023"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "680864",
    "path": "cases/652fac9d7e32132d40944be7/
document_1697623093346_Maremma_madiwal_Racpc_belapur.pdf",
    "fileName": "document_1697623093346_Maremma_madiwal_Racpc_belapur.pdf"
  },

```

```
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "01/03/2023",
    "nameOfApprovingAuthority": {
      "value": "Ambernath_Municipal_Council",
      "label": "Ambernath Municipal Council"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "ANP / NRV / 22-23 / 1465"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1697708584049_1_Occupancy_Certificate__Completion_Certificate__Architects_certificate_of_completion_for_plotted_development.pdf",
  "path": "cases/652fac9d7e32132d40944be7/document_1697708584049_1_Occupancy_Certificate__Completion_Certificate__Architects_certificate_of_completion_for_plotted_development.pdf",
  "id": "214878",
  "uploadedBy": "60eebe33f3dd69653a5837ae",
  "createdAt": "Thu Oct 19 2023 15:13:04 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "15/03/2021",
    "nameOfApprovingAuthority": {
      "value": "Ambernath_Municipal_Council",
      "label": "Ambernath Municipal Council"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "ANP / NRV / BP / 20-21 / 1312 / 9110/ 58"
  },
  "isHardCopy": false,

```

```
"displayStatus": false,
"fileName": "document_1697708876752_CC.pdf",
"path": "cases/652fac9d7e32132d40944be7/document_1697708876752_CC.pdf",
"id": "539764",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Thu Oct 19 2023 15:17:56 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "09/09/2021",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
      "label": "Maharashtra Real Estate Regulatory Authority"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "P51700017035"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1697708920064_P51700017035.pdf",
  "path": "cases/652fac9d7e32132d40944be7/
document_1697708920064_P51700017035.pdf",
  "id": "272879",
  "uploadedBy": "60eebe33f3dd69653a5837ae",
  "createdAt": "Thu Oct 19 2023 15:18:40 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "004478",
"createdBy": "60b7189d2ffdf65bcd65882b",
"caseHistory": [
  {
    "id": "681243",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Oct 18 2023 15:29:57 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
```

```
"name": "Mrs. Maremma Hanamappa Madiwal & Mr. Hanamappa Ramappa
Madiwal",
"phone": "8087384252",
"ownershipShare": "",
"email": "",
"id": "785891"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "772247",
"name": "Living Room",
"length": "13.83",
"length1": "13",
"length2": "10",
"width": "8.92",
"width1": "8",
"width2": "11",
"totalArea": "123.35",
"images": [],
"extraAreas": [
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"_id": "6530f854619c14402da556cc",
"name": "Extra",
"extraAreaType": "Add",
"length": "4.17",
"length1": "4",
"length2": "2",
"width": "7.17",
"width1": "7",
"width2": "2",
"totalArea": "29.86"
}
],
"finalArea": "153.20999999999998"
},
```

```
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Toilet",
  "length": "6.17",
  "length1": "6",
  "length2": "2",
  "width": "3.17",
  "width1": "3",
  "width2": "2",
  "totalArea": "19.53",
  "images": [],
  "extraAreas": [],
  "finalArea": "19.53"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Toilet",
  "length": "6.25",
  "length1": "6",
  "length2": "3",
  "width": "3.75",
  "width1": "3",
  "width2": "9",
  "totalArea": "23.44",
  "images": [],
  "extraAreas": [],
  "finalArea": "23.44"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Passage",
  "length": "4.58",
  "length1": "4",
  "length2": "7",
```

```
"width": "2.75",
"width1": "2",
"width2": "9",
"totalArea": "12.60",
"images": [],
"extraAreas": [],
"finalArea": "12.60"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Bedroom",
  "length": "11.67",
  "length1": "11",
  "length2": "8",
  "width": "9.75",
  "width1": "9",
  "width2": "9",
  "totalArea": "113.75",
  "images": [],
  "extraAreas": [],
  "finalArea": "113.75"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Kitchen",
  "length": "8.17",
  "length1": "8",
  "length2": "2",
  "width": "7.25",
  "width1": "7",
  "width2": "3",
  "totalArea": "59.21",
  "images": [],
  "extraAreas": [],
  "finalArea": "59.21"
},
{
  "measurementType": {
```

```
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Balcony",
  "length": "5.58",
  "length1": "5",
  "length2": "7",
  "width": "1.83",
  "width1": "1",
  "width2": "10",
  "totalArea": "10.24",
  "images": [],
  "extraAreas": [],
  "finalArea": "10.24"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "32.24",
    "totalAreaDocument": "347",
    "docBultupPercentage": "10",
    "docFinalBultUp": "381.70",
    "docFinalBultUpSquareMeter": "35.46",
    "docSaleablePercentage": "",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "806643"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "6530d118619c14402da4c97d",
```



```
"property": "Patel Prestige, Ambernath",
"area": "338",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "Middle",
"source": "square_yards",
"expectedPrice": "2504000",
"expectedRate": "7408.28",
"builtUpExpectedRate": "6734.80",
"image": "cases/652fac9d7e32132d40944be7/
indicator_1697697622182_Image.png",
"squareMeter": "31.40",
"id": "538039"
},
{
  "printlnReport": true,
  "_id": "6530d118619c14402da4c97e",
  "property": "Patel Prestige, Ambernath",
  "area": "391",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "Middle",
  "source": "square_yards",
  "expectedPrice": "3018000",
  "expectedRate": "7718.67",
  "builtUpExpectedRate": "7016.97",
  "image": "cases/652fac9d7e32132d40944be7/
indicator_1697697663286_Image.png",
  "squareMeter": "36.33",
  "id": "604158"
},
{
  "printlnReport": true,
  "_id": "6530d118619c14402da4c97f",
  "property": "Patel Prestige, Ambernath",
  "area": "347",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "7",
  "source": "Index_no.2",
```

```
    "expectedPrice": "2580000",
    "expectedRate": "7435.16",
    "builtUpExpectedRate": "6759.24",
    "image": "cases/652fac9d7e32132d40944be7/
indicator_1697697714891_Image.png",
    "squareMeter": "32.24",
    "id": "872018"
  },
  {
    "printlnReport": true,
    "_id": "6530d118619c14402da4c980",
    "property": "Patel Prestige, Ambernath",
    "area": "338",
    "builtUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "sale_Instance",
    "areaType": "Carpet",
    "floor": "3",
    "source": "Index_no.2",
    "expectedPrice": "2550000",
    "expectedRate": "7544.38",
    "builtUpExpectedRate": "6858.53",
    "image": "cases/652fac9d7e32132d40944be7/
indicator_1697697962212_Image.png",
    "squareMeter": "31.40",
    "id": "638227"
  }
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6530ba3c7e32132d409536e0",
    "name": "externalImg_1697692177785_1697692184555_image_0.jpeg",
    "path": "cases/652fac9d7e32132d40944be7/
externalImg_1697692177785_1697692184555_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6530ba3c7e32132d409536e1",
    "name": "externalImg_1697692201358_1697692184555_image_1.jpeg",
    "path": "cases/652fac9d7e32132d40944be7/
externalImg_1697692201358_1697692184555_image_1.jpeg",
    "orientation": "portrait"
  }
]
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6530ba3c7e32132d409536e2",
    "name": "externallmg_1697692205149_1697692184555_image_2.jpeg",
    "path": "cases/652fac9d7e32132d40944be7/
externallmg_1697692205149_1697692184555_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6530ba3c7e32132d409536e3",
    "name": "externallmg_1697692206154_1697692184555_image_3.jpeg",
    "path": "cases/652fac9d7e32132d40944be7/
externallmg_1697692206154_1697692184555_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6530ba3c7e32132d409536e4",
    "name": "externallmg_1697692207373_1697692184555_image_4.jpeg",
    "path": "cases/652fac9d7e32132d40944be7/
externallmg_1697692207373_1697692184555_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6530ba3c7e32132d409536e5",
    "name": "externallmg_1697692208893_1697692184555_image_5.jpeg",
    "path": "cases/652fac9d7e32132d40944be7/
externallmg_1697692208893_1697692184555_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6530ba3c7e32132d409536e6",
    "name": "externallmg_1697692209258_1697692184555_image_6.jpeg",
    "path": "cases/652fac9d7e32132d40944be7/
externallmg_1697692209258_1697692184555_image_6.jpeg",
    "orientation": "portrait"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6530ba3c7e32132d409536e7",
  "name": "externallmg_1697692209579_1697692184555_image_7.jpeg",
  "path": "cases/652fac9d7e32132d40944be7/
externallmg_1697692209579_1697692184555_image_7.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6530ba3c7e32132d409536e8",
  "name": "externallmg_1697692209814_1697692184555_image_8.jpeg",
  "path": "cases/652fac9d7e32132d40944be7/
externallmg_1697692209814_1697692184555_image_8.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6530ba3c7e32132d409536e9",
  "name": "externallmg_1697692210009_1697692184555_image_9.jpeg",
  "path": "cases/652fac9d7e32132d40944be7/
externallmg_1697692210009_1697692184555_image_9.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6530ba3c7e32132d409536ea",
  "name": "externallmg_1697692210294_1697692184555_image_10.jpeg",
  "path": "cases/652fac9d7e32132d40944be7/
externallmg_1697692210294_1697692184555_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6530ba3c7e32132d409536eb",
  "name": "externallmg_1697692210413_1697692184555_image_11.jpeg",
  "path": "cases/652fac9d7e32132d40944be7/
externallmg_1697692210413_1697692184555_image_11.jpeg",
  "orientation": "portrait"
},
{
```

```
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "6530ba3c7e32132d409536ec",
"name": "externallmg_1697692210874_1697692197088_image_0.jpeg",
"path": "cases/652fac9d7e32132d40944be7/
externallmg_1697692210874_1697692197088_image_0.jpeg",
"orientation": "portrait"
},
{
"type": "MEASUREMENT_IMAGE",
"status": false,
"_id": "6530ba3c7e32132d409536ee",
"name": "externallmg_1697692140003_1697692166466_image_0.jpeg",
"path": "cases/652fac9d7e32132d40944be7/
externallmg_1697692140003_1697692166466_image_0.jpeg",
"orientation": "portrait"
},
{
"type": "MEASUREMENT_IMAGE",
"status": false,
"_id": "6530ba3c7e32132d409536ef",
"name": "externallmg_1697692148713_1697692166466_image_1.jpeg",
"path": "cases/652fac9d7e32132d40944be7/
externallmg_1697692148713_1697692166466_image_1.jpeg",
"orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
{
"originalname": "1696854326515_Calculation.xlsx",
"filename": "1697698194385_1696854326515_Calculation.xlsx",
"path": "cases/652fac9d7e32132d40944be7/
processingDocuments/1697698194385_1696854326515_Calculation.xlsx",
"size": "2880720",
"createdAt": "Thu Oct 19 2023 12:19:55 GMT+0530 (India Standard Time)",
"uploadedBy": "60f915d3f3dd69653a592199"
}
],
"remarks": [],
"createdAt": "2023-10-18T09:59:57.758Z",
"updatedAt": "2023-10-19T10:04:49.265Z",
"__v": 0,
"invoiceId": "652faca07e32132d40944c3f",
"fullAddress": "Residential Flat No. 005, Ground Floor, Building No Type B, Patel's
Prestige, Plot No. 3, Village - Kohoj Khuntavli, Taluka - Ambernath, District - Thane,
```

Ambernath (West), PIN - 421 501, State - Maharashtra, India",
"updatedBy": "60eebe33f3dd69653a5837ae",
"addressForMap": "",
"caseReferredBy": "60b7189d2ffdf65bcd65882b",
"contactPersonName": "Mrs. Maremma Madiwal",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9730146893",
"buildingServicesRate": "2600.00",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 347.00",
"flatRate": "7600",
"landOtherRate": "5000",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + 2 Toilet + Passage +
Balcony",
"carpetTotal": "391.98",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "431.18",
"finalCarpetArea": "391.98",
"finalSalableArea": "474.30",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalSaleablePercentage": "0",
"landDetails": {
 "holdType": {
 "label": "Free Hold",
 "value": "Free_Hold"
 },
},
"leaseDetails": {
 "lessorName": "",
 "lesseeName": "",
 "leasePremium": "",
 "leaseRent": "",
 "leasePeriod": 0,
 "leaseFrom": "",

```
"leaseTo": "",  
"remainingLeasePeriod": 0,  
"leaseDate": ""
```

```
}  
}  
}
```

Name	Length	Width	Total
Composition :			
Living Room	13'10"	8'11"	123.35
Toilet	6'2"	3'2"	19.53
Toilet	6'3"	3'9"	23.44
Passage	4'7"	2'9"	12.60
Bedroom	11'8"	9'9"	113.75
Kitchen	8'2"	7'3"	59.21
Balcony	5'7"	1'10"	10.24
Other Composition :			