

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856bb41"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f65be948726cc141a5d",
    "email": "",
    "firstName": "Mr. Sanjaykumar SHrivastav",
    "mobileNo": "91-9969207619",
    "workMobileNo": "",
    "lastName": ""
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "6418456a96b58848585f8cb2",
"name": "Thane",
"email": "thane@vastukala.com",
"phone": "1234567890",
"address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
"city": "Thane",
"shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180a",
  "type": "BANK",
  "name": "Bank of India",
  "displayName": "Bank of India",
  "initial": "BOI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856bb41",
  "branchCode": "000082",
  "type": "BRANCH",
  "name": "Thane Main Branch",
  "email": "thane.navimumbai@bankofindia.co.in",
  "mobileNo": "02225332942",
  "alternateMobileNo": "",
  "address": "1st Floor, Bank of India Building, Shivajipath, Opp. M H High School,
Thane (West), Thane - 400601, State - Maharashtra, Country - India.\n",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e2f4b16576061dae469446",
  "zoneName": "Navi Mumbai Zone"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "64abdb2806d6ec174986d16b",
  "role": "PICKUPPERSON",
  "firstName": "Sahadu",
  "email": "thoratsahadu8679@gmail.com",
  "lastName": "Thorat",
  "mobileNo": "9422389642",
  "shortName": "ST",
  "workWithDocumentMaker": ""
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f9462345132d6a6bddb9d5",
  "role": "SITEENGINEER",
  "firstName": "Dashrath ",
  "email": "dasrat.jaiswar1234@gmail.com",
  "lastName": "Jaiswar",
  "mobileNo": "9987305468",
  "designation": "",
  "shortName": "DFJ",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "MAKER",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
  "mobileNo": "9821518537",
  "designation": "",
  "shortName": "PS",
```

```
"workWithDocumentMaker": "",
"profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        }
      }
    ]
  }
]
```

```
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.062050549487473",
  "longitude": "72.88343260499077"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
```

```
"siteVisitStatus": false,
"schedule": [
  {
    "dateTime": "2023-10-19T04:30:00.000Z",
    "remark": ""
  }
],
"visitedDate": [],
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Chembur",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "3",
    "label": false
  },
},
```

```
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Kurla (East)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kurla",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "63",
  "label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
```

```
"value": "",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "S. G. Barve Marg",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "C.S.T. Road",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Shivrushti",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "The Premier Co-Operative Housing Society Ltd.",
  "label": false
},
"oldSurveyNumber": {
```



```
"status": false,
"name": "Old Survey No.",
"key": "oldSurveyNumber",
"value": "",
"label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "114/17",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "B-13",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
```

```
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 400 024",
  "label": false
},
"suburb": {
  "status": false,
```

```
    "name": "Suburb",
    "key": "suburb",
    "value": "",
    "label": false
  }
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "areaType": "Built Up",
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
```

```
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,

```

```
"status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
```



```
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "true",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentId": [],
"_id": "652fb7ae7e32132d4094823c",
"ownerName": "Mrs. Perpetual Comport James Godad",
"ownerPhoneNo": "9892013527",
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "9892013527",
"contactPersonName": "Mrs. Perpetual Comport James Godad",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "Mrs. Perpetual Comport James Godad",
    "phone": "9892013527",
    "ownershipShare": "",
    "email": "",
    "id": "283535"
  }
],
"caseReferredBy": "64abdb2806d6ec174986d16b",
"relationWithOwner": "self",
"fullAddress": "Residential Flat No. B-13, 3rd Floor, Wing - B, The Premier Co-Operative Housing Society Ltd., Shivrushti, Plot No. 63, S. G. Barve Marg, C.S.T. Road, Village - Chembur, Taluka - Kurla, District - Mumbai Suburban, Kurla (East), PIN Code - 400 024, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
```

```
    "value": "60af48bf2ffdf65bcd6585fa",
    "label": "Agreement for sale"
  },
  "inputs": {
    "documentDate": "29/04/2016",
    "from": {
      "value": "Vendor",
      "label": "Vendor"
    },
    "Vendor": "Mrs. Maithili Sanjay Shinde",
    "to": {
      "value": "purchaser",
      "label": "purchaser"
    },
    "purchaser": "Mrs. Perpetual Comport James Godad",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "4138/2016"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1697625933445_Boi_main_br_James_Godad.pdf",
  "path": "cases/652fb7ae7e32132d4094823c/
document_1697625933445_Boi_main_br_James_Godad.pdf",
  "id": "607621",
  "uploadedBy": "6430f74691d7c62df11f3f15",
  "createdAt": "Wed Oct 18 2023 16:16:27 GMT+0530 (India Standard Time)"
}
],
"isUrgent": "false",
"isExternal": "false",
"scheduleSiteVisitDate": "Invalid date",
"caseNumber": "004481",
"createdBy": "6430f74691d7c62df11f3f15",
"caseHistory": [
  {
    "id": "584522",
    "title": "Create Case",
    "description": "Create Case",
    "datetime": "Wed Oct 18 2023 16:17:10 GMT+0530 (India Standard Time)"
  }
],
"proposePurchasers": [],
"siteInspection": [],
```

```
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-10-18T10:47:10.432Z",
"updatedAt": "2023-10-21T06:25:59.337Z",
"__v": 0,
"invoiceId": "652fb7ae7e32132d40948243",
"addressForMap": "",
"updatedBy": "627222afafd7d55eddedd82"
```

}

Name	Length	Width	Total
Composition :			
Other Composition :			