

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002",
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002"
  },
  "masterTypeOfPurpose": {
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002",
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63fc957bce84bf289baa55ec"
    },
    "type": "CREDITOFFICER",
    "_id": "65269eb2703d7c40db9b5919",
    "firstName": "Walmik",
    "lastName": "Wagh",
    "mobileNo": "",
    "workMobileNo": "8424998009",
    "email": "1sbi.05168@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "3250000",
    "discussWithPerson": "Walmik",
  }
}
```

```
"expectedFees": 1625,
"quotedAmount": ""
},
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63fc957bce84bf289baa55ec",
  "name": "SARB Churchgate",
  "branchCode": "",
  "mobileNo": "02222053163",
  "alternateMobileNo": "",
  "email": "sarc.mumbai@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "6th Floor, International 16, Maharshi Karve Road, Churchgate, Mumbai -
400020, State - Maharashtra, Country - India"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
```

```
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af6ae22ffdf65bcd65861d",
    "role": "PICKUPPERSON",
    "firstName": "Sunil",
    "email": "misalsunil87@gmail.com",
    "lastName": "Misal",
    "mobileNo": "8422982721",
    "shortName": "SM",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60af6ae22ffdf65bcd65861d\\
\\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "64c777a8a5c3051014f4dd1f",
    "role": "SITEENGINEER",
    "firstName": "Pratik",
    "email": "pratikjain2277@gmail.com",
    "lastName": "Jain",
    "mobileNo": "9619286285",
    "designation": "",
    "shortName": "Pratik",
    "workWithDocumentMaker": "6006d4ce5080a310ac1fdcf2"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "64cde526dc9f3034f3fefa49",
    "role": "FRONTDESK",
    "firstName": "Rashmi",
    "email": "rashmijadhav14feb@gmail.com",
    "lastName": "Jadhav",
    "mobileNo": "7738144625",
    "designation": "Back Office Coordinatiion",
    "shortName": "RJ",
    "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
    "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
  },
  "maker": {
    "type": "EMPLOYEE",
    "_id": "62fe044a48a26047e6552796",
    "role": "MAKER",
    "firstName": "Pradnya ",
    "email": "pradnya@vastukala.org",
```

```
"lastName": "Rasam",
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "_id": "64cde526dc9f3034f3fefa49",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg",
  "firstName": "Rashmi",
  "lastName": "Jadhav",
  "shortName": "RJ",
  "email": "rashmijadhav14feb@gmail.com",
  "designation": "Back Office Coordinatiion",
  "mobileNo": "7738144625",
  "role": "FRONTDESK",
  "type": "EMPLOYEE",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "[N]C.C.I.T/I -14/52/2008-09",
        "label": "Wealth Tax"
      }
    ]
  },
  "type": "EMPLOYEE",
  "_id": "6084131a13f01f158c6ea1f3",
  "PANNo": "AEAPC7114Q",
  "role": "VALUER",
  "firstName": "Sharadkumar",
  "fatherName": "Baburao",
  "email": "cmd@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9422171100",
  "designation": "CMD",
  "registrationNo": [
    {
      "title": {
        "value": "Wealth_Tax",
        "label": "Wealth Tax"
      }
    }
  ],
}
```

```
    "_id": "6084131a13f01f158c6ea1f4",
    "number": "[N]C.C.I.T/I -14/52/2008-09"
  }
],
  "shortName": "SBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.29501421573242",
  "longitude": "72.87495800915002"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.87495800915002,
    19.29501421573242
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-10-18T12:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-10-18T12:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-10-18T12:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-10-18T12:30:00.000Z",
      "remark": ""
    }
  ]
}
```

```
    "dateTime": "2023-10-18T12:30:00.000Z",
    "remark": ""
  }
],
"visitedDate": [
  {
    "status": "COMPLETED",
    "dateTime": "2023-10-19",
    "remark": "MANUAL_IN_TASK"
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Navghar",
    "label": true
  },
}
```

```
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "6",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mira Road (East)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
```

```
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Lilac Co-Op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
```



```
"status": true,
"name": "Project Name",
"key": "projectName",
"value": "Jangid Enclave",
"label": false
},
"oldSurveyNumber": {
  "status": true,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "292, 293 & New Survey No. 60, 61",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "606",
```

```
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
```

```
"name": "Postal Code",
"key": "postalCode",
"value": "PIN - 401 107",
"label": false
},
"suburb": {
"status": false,
"name": "Suburb",
"key": "suburb",
"value": "",
"label": false
}
},
"flatSpecifications": {
"roof": {
"value": "rcc_Slab",
"label": "R. C. C. Slab"
},
"flooring": {
"value": "VerifiedTileFlooring",
"label": "Vitrified Tile Flooring"
},
"doors": {
"value": "Teak_Wood_Door_frame_with_Solid_flush_door",
"label": "Teak Wood Door frame with Solid flush door"
},
"windows": {
"value": "Powder_coated_Aluminum_sliding_windows_with_M._S._Grills",
"label": "Powder coated Aluminum sliding windows with M. S. Grills"
},
"fittings": {
"value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
"label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
},
"finishing": {
"value": "Cement_Plastering_+_POP_Finish",
"label": "Cement Plastering + POP Finish"
}
},
"general": {
"ownership": {
"value": "Joint_Ownership",
"label": "Joint Ownership"
},
"populationClassList": {
```

```
"value": "MiddleClass",
"label": "Middle Class"
},
"populationGroupList": {
"value": "Urban",
"label": "Urban"
},
"townplanApprovedByList": {
"value": "Mira_Bhayander_Municipal_Corporation",
"label": "Mira Bhayander Municipal Corporation"
},
"whetherCoveredUnderAnyState": {
"value": "No",
"label": "No"
},
"asPerActualAgreement": {
"north": "BMC Office",
"west": "Jangid Enclave Road",
"south": "Paradise Road",
"east": "Internal Road"
},
"asPerDocumentAgreement": {
"north": "Details not available",
"west": "Details not available",
"south": "Details not available",
"east": "Details not available"
},
"unitBoundaries": {
"asPerActual": {
"north": "Details not available",
"east": "Details not available",
"south": "Details not available",
"west": "Details not available"
},
"asPerDocument": {
"north": "Details not available",
"east": "Details not available",
"south": "Details not available",
"west": "Details not available"
},
"setDisplay": false,
"title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "As per site inspection, 1BHK Flat converted into 2BHK by
converting Part portion of Bedroom into Kitchen & Kitchen into Bedroom.",
"dateOfIssusApprovePlan": "As Copy of Occupancy Certificate is received may be
```

```
assumed that the construction is as per sanctioned plan",
  "approvePlanVerified": "N.A",
  "empanelledOfApprovePlan": "N.A"
},
"compositeRate": {
  "remark": "As per site inspection, 1BHK Flat converted into 2BHK by converting Part
portion of Bedroom into Kitchen & Kitchen into Bedroom.",
  "depreciationPercentage": "18",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "12550",
  "depreciatedBuildingRate": "2050"
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "84200",
  "landRate": "26920",
  "igrImage": "cases/652fc2327e32132d40949c99/igr_1697784210620_Image.png",
  "squareMeterGuideLineRate": "88410.00",
  "squareFeetGuideLineRate": "8214.00"
},
"igrFinalRate": {
  "depreciationPercentage": "88",
  "rate": "7528.00",
  "squareFeetGuideLineRate": "7528.00",
  "squareMeterGuideLineRate": "81031.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "11,500",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
```

```
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per MBMC norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed Area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Stilt Car Parking Space",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2011",
    "fullDate": "1/1/2011"
  },
  "planningArea": {
```

```
"value": "Residential",
"label": "Residential"
},
"typeOfStructure": {
"value": "R.C.C.",
"label": "R.C.C. Framed"
},
"typeOfFoundation": {
"value": "rcc",
"label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
"value": "Good",
"label": "Good"
},
"materialUsedList": {
"value": "Good",
"label": "Good"
},
"buildingSpecification": {
"value": "Standard",
"label": "Standard"
},
"structuralSafety": {
"value": "Good",
"label": "Good"
},
"protAgainstNatDis": {
"value": "Good",
"label": "Good"
},
"sewerageSystem": {
"value": "MunicipalSewerageSystem",
"label": "Connected to Municipal Sewerage System"
},
"walls": {
"value": "1",
"label": "Yes"
},
"appearanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenanceOfTheBuilding": {
"value": "Normal",
"label": "Normal"
}
```

```
},
"maintenanceIssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "Part_Ground_and_Part_Stilt",
  "label": "Part Ground + Part Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "12",
"totalLifeBuilding": "60",
"estimatedAge": "48",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "7",
"flatFloorNo": "6",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "areaType": "Built Up",
  "area": "568.80",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
```



```
    "value": "Railway_Station",
    "label": "Railway Station"
  },
  "routeMapImg": "cases/652fc2327e32132d40949c99/
routeMap_1697787268712_Image.png",
  "routeLat": "19.294602",
  "routeLng": "72.876797",
  "stationName": "Mira Road",
  "routeDistance": "3.3 Km."
},
"finalLatLng": {
  "coordinates": [
    null,
    null
  ],
  "type": "Point"
},
"showLocation": {
  "latlng": true,
  "finallatlng": true
},
"locationMapImg": [
  {
    "id": "8ki6jl",
    "name": "8ki6jl",
    "image": "cases/652fc2327e32132d40949c99/
routeMap_1697787300739_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
```

```
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "5948700.00",
"distressValuePercentage": "70",
"realizableValuePercentage": "85",
"bookValue": "0",
"finalValue": "5948700.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
}
```

```
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"guidelineDetails": {
  "finalGuidelineValue": "4281926.00",
  "selectedBuildUpValue": "568.80",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "6531fa82619c14402da63dc9",
      "name":
"externalImg_1697774210514_IMG_20231019_165832_copy_900x1200.jpg",
      "path": "cases/652fc2327e32132d40949c99/
externalImg_1697774210514_IMG_20231019_165832_copy_900x1200.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": [
    {
      "status": false,
      "_id": "6531fa71619c14402da63d76",
      "name": "Living Room",
      "path": "cases/652fc2327e32132d40949c99/
externalImg_1697774192798_IMG_20231019_165247_copy_900x1200.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "6531fa71619c14402da63d7d",
      "name": "Living Room",
      "path": "cases/652fc2327e32132d40949c99/
externalImg_1697774192907_IMG_20231019_165236_copy_1600x1200.jpg",
      "orientation": "landscape"
    }
  ],
}
```

```
{
  "status": false,
  "_id": "6531fa82619c14402da63dbd",
  "name": "Living Room",
  "path": "cases/652fc2327e32132d40949c99/
externallmg_1697774210436_IMG_20231019_165326_copy_1600x1200.jpg",
  "orientation": "landscape"
},
{
  "status": false,
  "_id": "6531fa82619c14402da63dbe",
  "name": "Living Room",
  "path": "cases/652fc2327e32132d40949c99/
externallmg_1697774210440_IMG_20231019_165343_copy_1600x1200.jpg",
  "orientation": "landscape"
},
{
  "status": false,
  "_id": "6531fa82619c14402da63dc2",
  "name": "Living Room",
  "path": "cases/652fc2327e32132d40949c99/
externallmg_1697774210459_IMG_20231019_165356_copy_1600x1200.jpg",
  "orientation": "landscape"
},
{
  "status": false,
  "_id": "6531fa82619c14402da63dc5",
  "name": "Living Room",
  "path": "cases/652fc2327e32132d40949c99/
externallmg_1697774210479_IMG_20231019_165706_copy_900x1200.jpg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "6531fa82619c14402da63dc6",
  "name": "Living Room",
  "path": "cases/652fc2327e32132d40949c99/
externallmg_1697774210486_IMG_20231019_165744_copy_1600x1200.jpg",
  "orientation": "landscape"
},
{
  "status": false,
  "_id": "6531fa82619c14402da63dca",
  "name": "Living Room",
  "path": "cases/652fc2327e32132d40949c99/
externallmg_1697774210529_IMG_20231019_165843_copy_900x1200.jpg",
```

```
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6531fa82619c14402da63dc9",
    "name": "Living Room",
    "path": "cases/652fc2327e32132d40949c99/
externallmg_1697774210514_IMG_20231019_165832_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6531fa71619c14402da63d7a",
    "name": "Living Room",
    "path": "cases/652fc2327e32132d40949c99/
externallmg_1697774192864_IMG_20231019_165820_copy_901x1200.jpg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "10703",
    "max": "13478"
  },
  "builtUpRateRange": {
    "min": "8919",
    "max": "11232"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
}
```

```
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```



```
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
```

```
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "474.00",
"empanelmentNo": [
  "SME/TCC/2021-22/85/13"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentId": [],
"_id": "652fc2327e32132d40949c99",
"ownerName": "Vidhyavati R Dubey",
"ownerPhoneNo": "8419993999",
"appAddress": "Flat no.606, floor - 6th, Jangid Encave Village Navghar Tal & Dist-
Thane ",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "inputs": {
      "documentDate": "16/01/2006",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "M/s. Jangid Properties ",
      "to": {
        "value": "Purchasers",
        "label": "Purchasers"
      },
      "Purchasers": "Mrs. Vidyawati R. Dubey & Mr. Ramnarayan R. Dubey ",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "361 / 2006"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "775803",
    "path": "cases/652fc2327e32132d40949c99/
document_1697628304948_SALE_DEED_VIDHYAVATI_DUBEY_1.pdf",
```

```
"fileName":
"document_1697628304948_SALE_DEED_VIDHYAVATI_DUBEY_1.pdf"
},
{
  "documentType": {
    "label": "Occupancy Certificate",
    "value": "60ae124baa6d152c1801b2fd"
  },
  "inputs": {
    "documentDate": "19/05/2011",
    "nameOfApprovingAuthority": {
      "value": "Mira_Bhayander_Municipal_Corporation",
      "label": "Mira Bhayander Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "MNP / NR / 493 / 2011 - 12"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "292650",
  "path": "cases/652fc2327e32132d40949c99/
document_1697628429973_Dubey_Bldg_OC_copy.pdf",
  "fileName": "document_1697628429973_Dubey_Bldg_OC_copy.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "28/06/2005",
    "nameOfApprovingAuthority": {
      "value": "Mira_Bhayander_Municipal_Corporation",
      "label": "Mira Bhayander Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "MB / MNP / NR / 702 / 2005 - 06"
  },
  "isHardCopy": false,
  "displayStatus": false,
```

```
    "fileName": "document_1697786505689_document_1697628304948_SALE_DEED
_VIDHYAVATI_DUBEY_1.pdf",
    "path": "cases/652fc2327e32132d40949c99/document_1697786505689_document_
1697628304948_SALE_DEED_VIDHYAVATI_DUBEY_1.pdf",
    "id": "875925",
    "uploadedBy": "62fe044a48a26047e6552796",
    "createdAt": "Fri Oct 20 2023 12:51:46 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "004484",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "288170",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Oct 18 2023 17:02:02 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mrs. Vidyawati R. Dubey & Mr. Ramnarayan R. Dubey ",
    "phone": "8419993999",
    "ownershipShare": "",
    "email": "",
    "id": "709743"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "254342",
    "name": "Living Room",
    "length": "14.67",
    "length1": "14",
    "length2": "8",
    "width": "10.00",
    "width1": "10",
    "width2": "00",
    "totalArea": "146.67",
    "images": [],
```

```
"extraAreas": [],
"finalArea": "146.67"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Passage",
  "length": "10.17",
  "length1": "10",
  "length2": "2",
  "width": "3.17",
  "width1": "3",
  "width2": "2",
  "totalArea": "32.19",
  "images": [],
  "extraAreas": [],
  "finalArea": "32.19"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Bedroom",
  "length": "7.17",
  "length1": "7",
  "length2": "2",
  "width": "10.08",
  "width1": "10",
  "width2": "1",
  "totalArea": "72.26",
  "images": [],
  "finalArea": "72.26",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Toilet",
```

```
"length": "6.50",
"length1": "6",
"length2": "6",
"width": "4.33",
"width1": "4",
"width2": "4",
"totalArea": "28.17",
"images": [],
"extraAreas": [],
"finalArea": "28.17"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "4.08",
  "length1": "4",
  "length2": "1",
  "width": "5.17",
  "width1": "5",
  "width2": "2",
  "totalArea": "21.10",
  "images": [],
  "extraAreas": [],
  "finalArea": "21.10"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Kitchen",
  "length": "11.67",
  "length1": "11",
  "length2": "8",
  "width": "4.75",
  "width1": "4",
  "width2": "9",
  "totalArea": "55.42",
  "images": [],
  "extraAreas": [],
  "finalArea": "55.42"
```

```
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Bedroom",
  "length": "12.00",
  "length1": "12",
  "length2": "00",
  "width": "9.92",
  "width1": "9",
  "width2": "11",
  "totalArea": "119.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "119.00"
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "label": "Cupboard",
      "value": "Cupboard"
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "0",
    "length1": "6",
    "length2": "7",
    "length": "6.58",
    "width1": "2",
    "width2": "2",
    "width": "2.17",
    "totalArea": "14.26",
    "percentageBeforeTotal": "14.26",
    "images": [],
    "extraAreas": [],
    "percentage": "100",
```

```
"finalArea": "14.26"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Balcony Area",
    "value": "Balcony_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "length1": "3",
  "length2": "6",
  "length": "3.50",
  "width1": "9",
  "width2": "11",
  "width": "9.92",
  "totalArea": "34.71",
  "percentageBeforeTotal": "34.71",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "34.71"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Balcony Area",
    "value": "Balcony_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "length1": "2",
  "length2": "00",
  "length": "2.00",
```



```
"width1": "4",
"width2": "6",
"width": "4.50",
"totalArea": "9.00",
"percentageBeforeTotal": "9.00",
"images": [],
"extraAreas": [],
"percentage": "100",
"finalArea": "9"
}
],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "label": "Agreement For Sale",
    "value": "60ae1254aa6d152c1801b326"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "selectAreaTypeDocument": "Carpet",
  "squareMeterArea": "44.04",
  "totalAreaDocument": "474",
  "docBultupPercentage": "20",
  "docFinalBultUp": "568.80",
  "docFinalBultUpSquareMeter": "52.84",
  "docSaleablePercentage": "",
  "docFinalSaleable": "0.00",
  "docFinalSaleableSquareMeter": "0.00",
  "id": "122362"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "653221a1619c14402da713c9",
  "property": "Residential Flat",
  "area": "560",
  "bultUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Bult_Up",
  "source": "square_yards",
```

```
    "expectedPrice": "5800000",
    "expectedRate": "10357.14",
    "builtUpExpectedRate": "0.00",
    "image": "cases/652fc2327e32132d40949c99/
indicator_1697783789883_Image.png",
    "squareMeter": "52.03",
    "id": "581819"
  },
  {
    "printlnReport": true,
    "_id": "653221a1619c14402da713ca",
    "property": "Residential Flat",
    "area": "552",
    "builtUpPercentage": "0",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Built_Up",
    "source": "Nobroker.com",
    "expectedPrice": "6200000",
    "expectedRate": "11231.88",
    "builtUpExpectedRate": "0.00",
    "image": "cases/652fc2327e32132d40949c99/
indicator_1697783929866_Image.png",
    "squareMeter": "51.28",
    "id": "399158"
  },
  {
    "printlnReport": true,
    "_id": "653221a1619c14402da713cb",
    "property": "Residential Flat",
    "area": "555",
    "builtUpPercentage": "0",
    "saleablePercentage": "0",
    "rateType": "sale_Instance",
    "areaType": "Built_Up",
    "source": "Index_no.2",
    "expectedPrice": "4950000",
    "expectedRate": "8918.92",
    "builtUpExpectedRate": "7432.43",
    "image": "cases/652fc2327e32132d40949c99/
indicator_1697783988845_Image.png",
    "squareMeter": "51.56",
    "id": "180204"
  }
],
"externallImages": [
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6531fa71619c14402da63d75",
  "name":
"externallmg_1697774192791_IMG_20231019_165238_copy_1600x1200.jpg",
  "path": "cases/652fc2327e32132d40949c99/
externallmg_1697774192791_IMG_20231019_165238_copy_1600x1200.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6531fa71619c14402da63d76",
  "name":
"externallmg_1697774192798_IMG_20231019_165247_copy_900x1200.jpg",
  "path": "cases/652fc2327e32132d40949c99/
externallmg_1697774192798_IMG_20231019_165247_copy_900x1200.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6531fa71619c14402da63d77",
  "name":
"externallmg_1697774192818_IMG_20231019_165248_copy_900x1200.jpg",
  "path": "cases/652fc2327e32132d40949c99/
externallmg_1697774192818_IMG_20231019_165248_copy_900x1200.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6531fa71619c14402da63d78",
  "name":
"externallmg_1697774192837_IMG_20231019_165257_copy_900x1200.jpg",
  "path": "cases/652fc2327e32132d40949c99/
externallmg_1697774192837_IMG_20231019_165257_copy_900x1200.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6531fa71619c14402da63d79",
  "name":
"externallmg_1697774192853_IMG_20231019_165743_copy_1600x1200.jpg",
```

```
    "path": "cases/652fc2327e32132d40949c99/
externallmg_1697774192853_IMG_20231019_165743_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6531fa71619c14402da63d7a",
    "name":
"externallmg_1697774192864_IMG_20231019_165820_copy_901x1200.jpg",
    "path": "cases/652fc2327e32132d40949c99/
externallmg_1697774192864_IMG_20231019_165820_copy_901x1200.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6531fa71619c14402da63d7b",
    "name":
"externallmg_1697774192879_IMG_20231019_165831_copy_900x1200.jpg",
    "path": "cases/652fc2327e32132d40949c99/
externallmg_1697774192879_IMG_20231019_165831_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6531fa71619c14402da63d7c",
    "name":
"externallmg_1697774192900_IMG_20231019_191340_copy_1600x1200.jpg",
    "path": "cases/652fc2327e32132d40949c99/
externallmg_1697774192900_IMG_20231019_191340_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6531fa71619c14402da63d7d",
    "name":
"externallmg_1697774192907_IMG_20231019_165236_copy_1600x1200.jpg",
    "path": "cases/652fc2327e32132d40949c99/
externallmg_1697774192907_IMG_20231019_165236_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "6531fa71619c14402da63d7e",
    "name":
"externallmg_1697774192915_IMG_20231019_165241_copy_1600x1200.jpg",
    "path": "cases/652fc2327e32132d40949c99/
externallmg_1697774192915_IMG_20231019_165241_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6531fa82619c14402da63dba",
    "name":
"externallmg_1697774210407_IMG_20231019_165250_copy_900x1200.jpg",
    "path": "cases/652fc2327e32132d40949c99/
externallmg_1697774210407_IMG_20231019_165250_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6531fa82619c14402da63dbb",
    "name":
"externallmg_1697774210424_IMG_20231019_165301_copy_900x1200.jpg",
    "path": "cases/652fc2327e32132d40949c99/
externallmg_1697774210424_IMG_20231019_165301_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6531fa82619c14402da63dbc",
    "name":
"externallmg_1697774210432_IMG_20231019_165324_copy_1600x1200.jpg",
    "path": "cases/652fc2327e32132d40949c99/
externallmg_1697774210432_IMG_20231019_165324_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6531fa82619c14402da63dbd",
    "name":
"externallmg_1697774210436_IMG_20231019_165326_copy_1600x1200.jpg",
    "path": "cases/652fc2327e32132d40949c99/
externallmg_1697774210436_IMG_20231019_165326_copy_1600x1200.jpg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6531fa82619c14402da63dbe",
    "name":
"externallmg_1697774210440_IMG_20231019_165343_copy_1600x1200.jpg",
    "path": "cases/652fc2327e32132d40949c99/
externallmg_1697774210440_IMG_20231019_165343_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6531fa82619c14402da63dbf",
    "name":
"externallmg_1697774210445_IMG_20231019_165344_copy_1600x1200.jpg",
    "path": "cases/652fc2327e32132d40949c99/
externallmg_1697774210445_IMG_20231019_165344_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6531fa82619c14402da63dc0",
    "name":
"externallmg_1697774210449_IMG_20231019_165346_copy_1600x1200.jpg",
    "path": "cases/652fc2327e32132d40949c99/
externallmg_1697774210449_IMG_20231019_165346_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6531fa82619c14402da63dc1",
    "name":
"externallmg_1697774210453_IMG_20231019_165352_copy_1600x1200.jpg",
    "path": "cases/652fc2327e32132d40949c99/
externallmg_1697774210453_IMG_20231019_165352_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6531fa82619c14402da63dc2",
```

```
    "name":
"externallmg_1697774210459_IMG_20231019_165356_copy_1600x1200.jpg",
  "path": "cases/652fc2327e32132d40949c99/
externallmg_1697774210459_IMG_20231019_165356_copy_1600x1200.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6531fa82619c14402da63dc3",
  "name":
"externallmg_1697774210463_IMG_20231019_165612_copy_900x1200.jpg",
  "path": "cases/652fc2327e32132d40949c99/
externallmg_1697774210463_IMG_20231019_165612_copy_900x1200.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6531fa82619c14402da63dc4",
  "name":
"externallmg_1697774210471_IMG_20231019_165614_copy_900x1200.jpg",
  "path": "cases/652fc2327e32132d40949c99/
externallmg_1697774210471_IMG_20231019_165614_copy_900x1200.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6531fa82619c14402da63dc5",
  "name":
"externallmg_1697774210479_IMG_20231019_165706_copy_900x1200.jpg",
  "path": "cases/652fc2327e32132d40949c99/
externallmg_1697774210479_IMG_20231019_165706_copy_900x1200.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6531fa82619c14402da63dc6",
  "name":
"externallmg_1697774210486_IMG_20231019_165744_copy_1600x1200.jpg",
  "path": "cases/652fc2327e32132d40949c99/
externallmg_1697774210486_IMG_20231019_165744_copy_1600x1200.jpg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6531fa82619c14402da63dc7",
  "name":
"externallmg_1697774210492_IMG_20231019_165750_copy_1600x1200.jpg",
  "path": "cases/652fc2327e32132d40949c99/
externallmg_1697774210492_IMG_20231019_165750_copy_1600x1200.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6531fa82619c14402da63dc8",
  "name":
"externallmg_1697774210500_IMG_20231019_165830_copy_900x1200.jpg",
  "path": "cases/652fc2327e32132d40949c99/
externallmg_1697774210500_IMG_20231019_165830_copy_900x1200.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6531fa82619c14402da63dc9",
  "name":
"externallmg_1697774210514_IMG_20231019_165832_copy_900x1200.jpg",
  "path": "cases/652fc2327e32132d40949c99/
externallmg_1697774210514_IMG_20231019_165832_copy_900x1200.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6531fa82619c14402da63dca",
  "name":
"externallmg_1697774210529_IMG_20231019_165843_copy_900x1200.jpg",
  "path": "cases/652fc2327e32132d40949c99/
externallmg_1697774210529_IMG_20231019_165843_copy_900x1200.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6531fa82619c14402da63dcb",
  "name":
"externallmg_1697774210544_IMG_20231019_191226_copy_900x1200.jpg",
```



```
    "path": "cases/652fc2327e32132d40949c99/
externallmg_1697774210544_IMG_20231019_191226_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6531fa82619c14402da63dcc",
    "name":
"externallmg_1697774210558_IMG_20231019_191329_copy_1600x1200.jpg",
    "path": "cases/652fc2327e32132d40949c99/
externallmg_1697774210558_IMG_20231019_191329_copy_1600x1200.jpg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Calculation Sheet.xlsx",
    "filename": "1697784240689_Calculation_Sheet.xlsx",
    "path": "cases/652fc2327e32132d40949c99/
processingDocuments/1697784240689_Calculation_Sheet.xlsx",
    "size": "16232",
    "createdAt": "Fri Oct 20 2023 12:14:00 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  },
  {
    "originalname": "Summary Sheet.xlsx",
    "filename": "1697784240690_Summary_Sheet.xlsx",
    "path": "cases/652fc2327e32132d40949c99/
processingDocuments/1697784240690_Summary_Sheet.xlsx",
    "size": "2756345",
    "createdAt": "Fri Oct 20 2023 12:14:00 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  }
],
"remarks": [],
"createdAt": "2023-10-18T11:32:02.467Z",
"updatedAt": "2023-10-20T09:35:19.832Z",
"__v": 0,
"invoiceId": "652fc2327e32132d40949ca9",
"fullAddress": "Residential Flat No. 606, 6th Floor, Lilac Co-Op. Hsg. Soc. Ltd., Jangid
Enclave, Village - Navghar, Taluka - Thane, District - Thane, Mira Road (East), PIN -
401 107, State - Maharashtra, Country - India",
"updatedAt": "64cde526dc9f3034f3fefa49",
"addressForMap": ""
```

```
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Miss. Ruli Anil Dubey",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner's Representative",
"siteVisitContactNo": "8419993999",
"buildingServicesRate": "2500",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 474.00",
"flatRate": "13000",
"landOtherRate": "10500",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + Passage + 2 Toilet",
"carpetTotal": "474.81000000000006",
"otherCarpetTotal": "57.97",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "57.97",
"otherCompositionSaleableTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "586.06",
"finalCarpetArea": "532.78",
"finalSalableArea": "644.66",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 474.00\nCup Board Area in Sq.
Ft. = 14.00\nBalcony Area in Sq. Ft. = 44.00\n\n\n",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  }
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
  "leaseFrom": "",
```

```

    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Fri Oct 20 2023 12:17:39 GMT+0530 (India Standard Time)",
"siteVisitDate": "2023-10-19",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
}
}

```

Name	Length	Width	Total
Composition :			
Living Room	14'8"	10'00"	146.67
Passage	10'2"	3'2"	32.19
Bedroom	7'2"	10'1"	72.26
Toilet	6'6"	4'4"	28.17
Toilet	4'1"	5'2"	21.10
Kitchen	11'8"	4'9"	55.42
Bedroom	12'00"	9'11"	119.00
Other Composition :			
Cupboard	6'7"	2'2"	14.26
Balcony Area	3'6"	9'11"	34.71
Balcony Area	2'00"	4'6"	9.00