

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7f7"
    },
    "type": "CREDITOFFICER",
    "_id": "63fd9434ce84bf289baab0e9",
    "firstName": "Sharmila",
    "lastName": "Mahto",
    "mobileNo": "",
    "workMobileNo": "9521405151",
    "email": "sharmila.mahto@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5000000",
    "discussWithPerson": "Sharmila",
    "expectedFees": 2500,
    "quotedAmount": "2500"
  },
  "organization": {
```

```
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7f7",
  "branchCode": "000064",
  "type": "BRANCH",
  "name": "RACPC Ghatkopar (West)",
  "email": "racpcghatkopar.sanctions@sbi.co.in",
  "mobileNo": "022-25009143",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, 1st Floor, Ashok Silk Mills
Compound, LBS Marg, Ghatkopar (West), Mumbai - 400 086, State - Maharashtra,
Country - India.\r\n\r\n\r\n",
  "ledgerName": "STATE BANK OF INDIA - RACPC GHATKOPAR",
  "fax": "022-25009010",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "648fcad91b499c2d52dc86f3",
  "role": "SITEENGINEER",
  "firstName": "Barkat",
  "email": "barkathodekar68@gmail.com",
  "lastName": "Hodekar",
  "mobileNo": "8879011615",
  "designation": "Site Engg",
  "shortName": "Barkat",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/648fcad91b499c2d52dc86f3/
profilePhoto_1687758876977_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordinatiion",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
  "email": "pradnya@vastukala.org",
```

```
"lastName": "Rasam",
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordinatiion",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "[N]C.C.I.T/I -14/52/2008-09",
        "label": "Wealth Tax"
      }
    ]
  },
  "type": "EMPLOYEE",
  "_id": "6084131a13f01f158c6ea1f3",
  "PANNo": "AEAPC7114Q",
  "role": "VALUER",
  "firstName": "Sharadkumar",
  "fatherName": "Baburao",
  "email": "cmd@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9422171100",
  "designation": "CMD",
  "registrationNo": [
    {
      "title": {
        "value": "Wealth_Tax",
        "label": "Wealth Tax"
      }
    }
  ],
}
```

```
    "_id": "6084131a13f01f158c6ea1f4",
    "number": "[N]C.C.I.T/I -14/52/2008-09"
  }
],
  "shortName": "SBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.089766645469908",
  "longitude": "72.90815600440361"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.90815600440361,
    19.089766645469908
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-23",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-23",
      "remark": ""
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
```

```
"value": "1BHK",
"label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Kirol",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "3",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
```

```
"name": "District",
"key": "district",
"value": "Mumbai Suburban",
"label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Ghatkopar (West)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kurla",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "K. K. Residency",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
}
```

```
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Nari Seva Sadan Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Dr. Ambedkar Nagar SRA CHS (PROP)",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "G",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
```



```
"key": "newSurveyNumber",
"value": "",
"label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "174A(Part)",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "303",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
}
```

```
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 086",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
```

```
"label": "R. C. C. Slab"
},
"flooring": {
  "value": "VerifiedTileFlooring",
  "label": "Vitrified Tile Flooring"
},
"doors": {
  "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
  "label": "Teak Wood Door frame with Solid flush door"
},
"windows": {
  "value": "Powder_coated_Aluminum_sliding_windows_with_M._S._Grills",
  "label": "Powder coated Aluminum sliding windows with M. S. Grills"
},
"fittings": {
  "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
  "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
},
"finishing": {
  "value": "Cement_Plastering_+_POP_Finish",
  "label": "Cement Plastering + POP Finish"
}
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Slum_Rehabilitation_Authority",
    "label": "Slum Rehabilitation Authority"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
```

```
"north": "Internal Road",
"west": "SRA Building ",
"south": "SRA Building ",
"east": "Wing - H"
},
"asPerDocumentAgreement": {
  "north": "Buddh Vihar ",
  "west": "B.M.C Road",
  "south": "Industrial Area ",
  "east": "Mahindra Park"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "asPerDocument": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As Copy of Part Occupancy Certificate is received may
be assumed that the construction is as per sanctioned plan",
"approvePlanVerified": "N.A",
"empanelledOfApprovePlan": "N.A"
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "0",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "buildingServicesDepreciatedRate": "0",
  "depreciatedCostOfConstruction": "13500.00",
  "depreciatedBuildingRate": "2500"
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "82350",
  "landRate": "31510",
```

```
"igrImage": "cases/6532411d619c14402da7958c/igr_1697886448053_Image.png",
"squareMeterGuideLineRate": "82350.00",
"squareFeetGuideLineRate": "7651.00"
},
"igrFinalRate": {
  "rate": "82350.00",
  "squareMeterGuideLineRate": "82350.00",
  "squareFeetGuideLineRate": "7651.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Tenant_Occupied",
    "label": "Tenant Occupied"
  },
  "monthlyRent": "16,500",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per SRA norms",
  "tenantName": "Mr. Mujib Khan / Occupied Since - Last 4 Months",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
}
```

```
"partitions": {
  "value": "6\"_Thk._Brick_Masonry",
  "label": "6\" Thk. Brick Masonery"
},
"waterTank": {
  "value": "MunicipalWaterSupply",
  "label": "Municipal Water Supply"
},
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": "Covered Car Parking Space",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2021",
  "fullDate": "1/1/2021"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
}
```

```
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
```

```
    "value": "ground",
    "label": "Ground"
  },
  "yearOfConstructionAsPer": {
    "value": "As_Per_Part_Occupancy_Certificate",
    "label": "As Per Part Occupancy Certificate"
  },
  "isSiteVisitAllowed": true,
  "ageOfBuilding": "2",
  "totalLifeBuilding": "60",
  "estimatedAge": "58",
  "noOfBasement": "2",
  "noOfPodium": "",
  "noOfAmenityFloors": "",
  "noOfFloors": "5",
  "flatFloorNo": "3",
  "noOfLifts": "1",
  "noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "areaType": "Built Up",
  "area": "513.60",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Metro_Station",
      "label": "Metro Station"
    },
    "routeMapImg": "cases/6532411d619c14402da7958c/
routeMap_1698221307847_Image.png",
    "routeLat": "19.090250",
    "routeLng": "72.896310",
    "stationName": "Ghatkopar ",
    "routeDistance": "2.4 Km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
```



```
"latlng": true,
"finallatlng": true
},
"locationMapImg": [
  {
    "id": "y7tdh",
    "name": "y7tdh",
    "image": "cases/6532411d619c14402da7958c/
routeMap_1698221214894_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "5778000.00",
  "finalValue": "5778000.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValueDocument": null,
  "purchaseValueDocument": null,
```

```
"bookValue": "0"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
```

```
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "3929554.00",
  "selectedBuildUpValue": "513.60",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
```

```
    "status": false,
    "_id": "6535ec4c619c14402daa082c",
    "name": "externallmg_1698032706721_1698032736963_image_5.jpeg",
    "path": "cases/6532411d619c14402da7958c/
externallmg_1698032706721_1698032736963_image_5.jpeg",
    "orientation": "portrait"
  }
],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "6535ec4c619c14402daa081c",
    "name": "Living Room",
    "path": "cases/6532411d619c14402da7958c/
externallmg_1698032627230_1698032626379_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6535ec4c619c14402daa081f",
    "name": "Living Room",
    "path": "cases/6532411d619c14402da7958c/
externallmg_1698032629037_1698032626379_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6535ec4c619c14402daa0823",
    "name": "Living Room",
    "path": "cases/6532411d619c14402da7958c/
externallmg_1698032630591_1698032626379_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6535ec4c619c14402daa0824",
    "name": "Living Room",
    "path": "cases/6532411d619c14402da7958c/
externallmg_1698032630875_1698032626379_image_11.jpeg",
    "orientation": "portrait"
  },
  {
```

```
    "status": false,
    "_id": "6535ec4c619c14402daa081b",
    "name": "Living Room",
    "path": "cases/6532411d619c14402da7958c/
externallmg_1698032627097_1698032626379_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6535ec4c619c14402daa082b",
    "name": "Living Room",
    "path": "cases/6532411d619c14402da7958c/
externallmg_1698032706377_1698032736963_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6535ec4c619c14402daa0828",
    "name": "Living Room",
    "path": "cases/6532411d619c14402da7958c/
externallmg_1698032704238_1698032736963_image_1.jpeg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "10814",
    "max": "15399"
  },
  "builtUpRateRange": {
    "min": "9012",
    "max": "12833"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```

```
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
```



```
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "428.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentId": [],
"_id": "6532411d619c14402da7958c",
"ownerName": "Mrs. Mumtaz Akbar Khalifa ",
"ownerPhoneNo": "8286214545",
"appAddress": "Flat no. 303, 3rd Floor, Wing - G, K K Residency, Dr. Ambedkar Nagar
SRA CHS, GHatkopar West ",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "inputs": {
      "documentDate": "12/10/2023",
      "from": {
        "value": "Developers",
        "label": "Developers"
      },
      "Developers": "M/s. K.K. Constructions ",
      "to": {
        "value": "Purchasers",
        "label": "Purchasers"
      },
      "Purchasers": "Mrs. Mumtaz Akbar Khalifa ",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "20292 / 2023"
    }
  },
]
```

```
    "isHardCopy": false,
    "displayStatus": true,
    "id": "360966",
    "path": "cases/6532411d619c14402da7958c/
document_1697792206206_1697792236129_Racpc_GhatkoparMumtaz_Khalifa.pdf",
    "fileName":
"document_1697792206206_1697792236129_Racpc_GhatkoparMumtaz_Khalifa.pdf"
  },
  {
    "documentType": {
      "value": "60ae1247aa6d152c1801b2ea",
      "label": "Commencement Certificate"
    },
    "inputs": {
      "documentDate": "10/09/2020",
      "nameOfApprovingAuthority": {
        "value": "Slum_Rehabilitation_Authority_(SRA)",
        "label": "Slum Rehabilitation Authority (SRA)"
      },
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "SRA / ENG / 2452 / N / STGL / AP"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1698218437771_document_1697792206206_16977922361
29_Racpc_GhatkoparMumtaz_Khalifa.pdf",
    "path": "cases/6532411d619c14402da7958c/document_1698218437771_document
_1697792206206_1697792236129_Racpc_GhatkoparMumtaz_Khalifa.pdf",
    "id": "844305",
    "uploadedBy": "62fe044a48a26047e6552796",
    "createdAt": "Wed Oct 25 2023 12:50:38 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae1250aa6d152c1801b316",
      "label": "Part Occupancy Certificate"
    },
    "inputs": {
      "documentDate": "02/06/2021",
      "nameOfApprovingAuthority": {
        "value": "Slum_Rehabilitation_Authority_(SRA)",
        "label": "Slum Rehabilitation Authority (SRA)"
      }
    }
  },
```

```
"number": {
  "value": "No",
  "label": "No"
},
"No": "SRA / ENG / 2452 / N / STGL / AP"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1698218502050_document_1697792206206_16977922361
29_Racpc_GhatkoparMumtaz_Khalifa.pdf",
"path": "cases/6532411d619c14402da7958c/document_1698218502050_document
_1697792206206_1697792236129_Racpc_GhatkoparMumtaz_Khalifa.pdf",
"id": "709772",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Wed Oct 25 2023 12:51:42 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "18/05/2020",
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "P51800005115"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1698218555174_document_1697792206206_16977922361
29_Racpc_GhatkoparMumtaz_Khalifa.pdf",
"path": "cases/6532411d619c14402da7958c/document_1698218555174_document
_1697792206206_1697792236129_Racpc_GhatkoparMumtaz_Khalifa.pdf",
"id": "506017",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Wed Oct 25 2023 12:52:35 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "004538",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "238488",
    "title": "Create Lead",
```

```
"description": "Create Lead",
"datetime": "Fri Oct 20 2023 14:28:05 GMT+0530 (India Standard Time)"
}
],
"owners": [
{
"name": "Mrs. Mumtaz Akbar Khalifa ",
"phone": "8286214545",
"ownershipShare": "",
"email": "",
"id": "249511"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "952581",
"name": "Living Room",
"length": "18.00",
"length1": "18",
"length2": "00",
"width": "10.42",
"width1": "10",
"width2": "5",
"totalArea": "187.50",
"images": [],
"extraAreas": [],
"finalArea": "187.50"
},
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "1",
"name": "Kitchen",
"length": "6.00",
"length1": "6",
"length2": "00",
"width": "11.67",
"width1": "11",
```

```
"width2": "8",
"totalArea": "70.00",
"images": [],
"extraAreas": [],
"finalArea": "70.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "WC",
  "length": "",
  "length1": "6",
  "length2": "0",
  "width": "",
  "width1": "4",
  "width2": "0",
  "totalArea": "24.00",
  "images": [],
  "finalArea": "24.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bathroom",
  "length": "5.58",
  "length1": "5",
  "length2": "7",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "22.33",
  "images": [],
  "extraAreas": [],
  "finalArea": "22.33"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  }
}
```

```
    },
    "id": "5",
    "name": "Bedroom",
    "length": "9.00",
    "length1": "9",
    "length2": "0",
    "width": "11.92",
    "width1": "11",
    "width2": "11",
    "totalArea": "107.25",
    "images": [],
    "finalArea": "107.25",
    "extraAreas": []
  }
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "39.76",
    "totalAreaDocument": "428",
    "docBuiltpPercentage": "20",
    "docFinalBuiltp": "513.60",
    "docFinalBuiltpSquareMeter": "47.72",
    "docSaleablePercentage": "",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "633474"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "6533b0fd619c14402da9a874",
    "property": "Residential Flat",
    "area": "421",
```

```
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"source": "Housing.Com",
"expectedPrice": "6483000",
"expectedRate": "15399.05",
"builtUpExpectedRate": "12832.54",
"image": "cases/6532411d619c14402da7958c/
indicator_1697885881275_Image.png",
"squareMeter": "39.11",
"id": "358204"
},
{
  "printlnReport": true,
  "_id": "6533b0fd619c14402da9a875",
  "property": "Residential Flat",
  "area": "504",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Built_Up",
  "source": "Index_no.2",
  "expectedPrice": "6000000",
  "expectedRate": "11904.76",
  "builtUpExpectedRate": "0.00",
  "image": "cases/6532411d619c14402da7958c/
indicator_1697885963084_Image.png",
  "squareMeter": "46.82",
  "id": "248695"
},
{
  "printlnReport": true,
  "_id": "6533b0fd619c14402da9a876",
  "property": "Residential Flat",
  "area": "430",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "source": "Nobroker.com",
  "expectedPrice": "4650000",
  "expectedRate": "10813.95",
  "builtUpExpectedRate": "9011.63",
  "image": "cases/6532411d619c14402da7958c/
indicator_1697886065180_Image.png",
```

```
    "squareMeter": "39.95",
    "id": "532106"
  }
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6535ec4c619c14402daa081a",
    "name": "externallmg_1698032625947_1698032626379_image_0.jpeg",
    "path": "cases/6532411d619c14402da7958c/
externallmg_1698032625947_1698032626379_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6535ec4c619c14402daa081b",
    "name": "externallmg_1698032627097_1698032626379_image_1.jpeg",
    "path": "cases/6532411d619c14402da7958c/
externallmg_1698032627097_1698032626379_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6535ec4c619c14402daa081c",
    "name": "externallmg_1698032627230_1698032626379_image_2.jpeg",
    "path": "cases/6532411d619c14402da7958c/
externallmg_1698032627230_1698032626379_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6535ec4c619c14402daa081d",
    "name": "externallmg_1698032627804_1698032626379_image_3.jpeg",
    "path": "cases/6532411d619c14402da7958c/
externallmg_1698032627804_1698032626379_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6535ec4c619c14402daa081e",
    "name": "externallmg_1698032628603_1698032626379_image_4.jpeg",
```



```
    "path": "cases/6532411d619c14402da7958c/
externallmg_1698032628603_1698032626379_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6535ec4c619c14402daa081f",
    "name": "externallmg_1698032629037_1698032626379_image_5.jpeg",
    "path": "cases/6532411d619c14402da7958c/
externallmg_1698032629037_1698032626379_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6535ec4c619c14402daa0820",
    "name": "externallmg_1698032629267_1698032626379_image_6.jpeg",
    "path": "cases/6532411d619c14402da7958c/
externallmg_1698032629267_1698032626379_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6535ec4c619c14402daa0821",
    "name": "externallmg_1698032629701_1698032626379_image_7.jpeg",
    "path": "cases/6532411d619c14402da7958c/
externallmg_1698032629701_1698032626379_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6535ec4c619c14402daa0822",
    "name": "externallmg_1698032629967_1698032626379_image_8.jpeg",
    "path": "cases/6532411d619c14402da7958c/
externallmg_1698032629967_1698032626379_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6535ec4c619c14402daa0823",
    "name": "externallmg_1698032630591_1698032626379_image_10.jpeg",
    "path": "cases/6532411d619c14402da7958c/
externallmg_1698032630591_1698032626379_image_10.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6535ec4c619c14402daa0824",
  "name": "externallmg_1698032630875_1698032626379_image_11.jpeg",
  "path": "cases/6532411d619c14402da7958c/
externallmg_1698032630875_1698032626379_image_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6535ec4c619c14402daa0825",
  "name": "externallmg_1698032631925_1698032626379_image_13.jpeg",
  "path": "cases/6532411d619c14402da7958c/
externallmg_1698032631925_1698032626379_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6535ec4c619c14402daa0826",
  "name": "externallmg_1698032633490_1698032626379_image_16.jpeg",
  "path": "cases/6532411d619c14402da7958c/
externallmg_1698032633490_1698032626379_image_16.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6535ec4c619c14402daa0827",
  "name": "externallmg_1698032703893_1698032736963_image_0.jpeg",
  "path": "cases/6532411d619c14402da7958c/
externallmg_1698032703893_1698032736963_image_0.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6535ec4c619c14402daa0828",
  "name": "externallmg_1698032704238_1698032736963_image_1.jpeg",
  "path": "cases/6532411d619c14402da7958c/
externallmg_1698032704238_1698032736963_image_1.jpeg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6535ec4c619c14402daa0829",
      "name": "externallmg_1698032705016_1698032736963_image_2.jpeg",
      "path": "cases/6532411d619c14402da7958c/
externallmg_1698032705016_1698032736963_image_2.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6535ec4c619c14402daa082a",
      "name": "externallmg_1698032705487_1698032736963_image_3.jpeg",
      "path": "cases/6532411d619c14402da7958c/
externallmg_1698032705487_1698032736963_image_3.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6535ec4c619c14402daa082b",
      "name": "externallmg_1698032706377_1698032736963_image_4.jpeg",
      "path": "cases/6532411d619c14402da7958c/
externallmg_1698032706377_1698032736963_image_4.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6535ec4c619c14402daa082c",
      "name": "externallmg_1698032706721_1698032736963_image_5.jpeg",
      "path": "cases/6532411d619c14402da7958c/
externallmg_1698032706721_1698032736963_image_5.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "6535ec4c619c14402daa082d",
      "name": "externallmg_1698032556276_1698032589251_image_0.jpeg",
      "path": "cases/6532411d619c14402da7958c/
externallmg_1698032556276_1698032589251_image_0.jpeg",
      "orientation": "landscape"
    },
  ],
```

```
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6535ec4c619c14402daa082e",
  "name": "externalImg_1698032556487_1698032589251_image_1.jpeg",
  "path": "cases/6532411d619c14402da7958c/
externalImg_1698032556487_1698032589251_image_1.jpeg",
  "orientation": "landscape"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Calculation Sheet.xlsx",
    "filename": "1697886479372_Calculation_Sheet.xlsx",
    "path": "cases/6532411d619c14402da7958c/
processingDocuments/1697886479372_Calculation_Sheet.xlsx",
    "size": "16169",
    "createdAt": "Sat Oct 21 2023 16:37:59 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  },
  {
    "originalname": "Summary Sheet.xlsx",
    "filename": "1697886479373_Summary_Sheet.xlsx",
    "path": "cases/6532411d619c14402da7958c/
processingDocuments/1697886479373_Summary_Sheet.xlsx",
    "size": "1440867",
    "createdAt": "Sat Oct 21 2023 16:37:59 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  }
],
"remarks": [],
"createdAt": "2023-10-20T08:58:05.425Z",
"updatedAt": "2023-10-25T09:13:17.216Z",
"__v": 0,
"invoiceId": "6532411f619c14402da795b1",
"fullAddress": "Residential Flat No. 303, 3rd Floor, Wing - G, K. K. Residency, Dr.
Ambedkar Nagar SRA CHS (PROP), Nari Seva Sadan Road, Village - Kirol, Taluka -
Kurla, District - Mumbai Suburban, Ghatkopar (West), PIN - 400 086, State -
Maharashtra, India",
"updatedAt": "64cde526dc9f3034f3fefa49",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Mr. Mujib Khan",
"email": "",
"isExternal": "false",
```

```
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Tenant",
"siteVisitContactNo": "8286214545",
"buildingServicesRate": "2500",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 428.00",
"flatRate": "13500",
"landOtherRate": "11000",
"siteVisitDate": "2023-10-23",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + WC + Bathroom",
"carpetTotal": "411.08",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "452.19",
"finalCarpetArea": "411.08",
"finalSalableArea": "497.41",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "\n",
"finalSaleablePercentage": "0",
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
}
```

```

    }
  },
  "otherCompositionBuiltUpTotal": "0.00",
  "otherCompositionCarpetTotal": "0.00",
  "otherCompositionSaleableTotal": "0.00",
  "shopDetails": {
    "typeOfShops": null,
    "roadFacing": false,
    "mall": false
  }
}

```

Name	Length	Width	Total
Composition :			
Living Room	18'00"	10'5"	187.50
Kitchen	6'00"	11'8"	70.00
WC	6'0"	4'0"	24.00
Bathroom	5'7"	4'00"	22.33
Bedroom	9'0"	11'11"	107.25
Other Composition :			