

```
{
  "typeOfReport": {
    "value": "Residential",
    "label": "Residential"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63fdb72bce84bf289baaece8"
    },
    "type": "CREDITOFFICER",
    "_id": "63fdb72bce84bf289baaecea",
    "firstName": "Chaitanya",
    "lastName": "Singh",
    "mobileNo": "",
    "workMobileNo": "7011129647",
    "email": "chaitanya@bankofbaroda.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "2950"
  },
  "organization": {
```

```
"_id": "643a5bee108b68389ed736e5",
"name": "Nashik Branch",
"shortName": "NSK",
"email": "nashik@vastukala.org",
"address": "4, 1st Floor, Mashusha Elite, Vrundavan Naka Link Road, Adgaon, ",
"city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180c",
  "type": "BANK",
  "name": "Bank Of Baroda",
  "displayName": "Bank Of Baroda",
  "initial": "BOB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63fdb72bce84bf289baaece8",
  "name": "Narsingh Nagar Branch",
  "branchCode": "",
  "mobileNo": "7011129647",
  "alternateMobileNo": "",
  "email": "abganga@bankofbaroda.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Sukhashanti heights Narsingh Nagar, Gangapur Road, Nashik- 422013"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "63fda060ce84bf289baace4c",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "63f9f4adce84bf289ba9956e",
    "role": "FRONTDESK + ENGINEER",
    "firstName": "Swapnil",
```

```
"email": "waghswapnil309@gmail.com",
"lastName": "Wagh",
"mobileNo": "8237116625",
"shortName": "SW",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9f4adce84bf289ba9956e/
profilePhoto_1688707461551_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "63f9f4adce84bf289ba9956e",
"role": "FRONTDESK + ENGINEER",
"firstName": "Swapnil",
"email": "waghswapnil309@gmail.com",
"lastName": "Wagh",
"mobileNo": "8237116625",
"designation": "",
"shortName": "SW",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9f4adce84bf289ba9956e/
profilePhoto_1688707461551_image.jpeg"
},
"valuers": []
},
"clientType": {
"value": "BANK",
"label": "BANK"
},
"location": {
"latitude": "20.027141573503215",
"longitude": "73.75296198644966"
},
"geo": {
"type": "Point",
"coordinates": [
0,
0
]
},
"siteVisit": {
"siteVisitStatus": false,
"schedule": [],
"visitedDate": []
},
"marketAnalysisAndRemark": {
"audioNotes": []
}
```

```
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Chandshi",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Basement",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
```

```
"value": "Nashik",
"label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik ",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Chandshi",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "76",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": " Samarth Shrushti Apartment",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
```

```
"status": true,
"name": "Street 1",
"key": "street1",
"value": "Off Mungsare Chandshi Road",
"label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Bapu Pool",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Near Hotel Red Rose",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
```

```
"label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "104",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
```

```
"name": "Mouza",
"key": "mouza",
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": true,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "48/3, 48/4 + 50/1+3/2",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422003",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
}
},
```



```
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "areaType": "Built Up",
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
```

```
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "0",
"selectedBuildUpValue": "0",
"selectedBuildUpMeasurementType": ""
},
"reportImages": {
"frontPageImages": [],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
"carpetRateRange": {
"min": "0.00",
"max": "0.00"
},
"builtUpRateRange": {
"min": "0.00",
"max": "0.00"
}
},
"detailsOfValuation": {
"presentValueOfFlat": {
"title": "Present value of the flat (incl. car parking, if provided)",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
"title": "Wardrobes",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
},
```

```
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```

```
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "true",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
}
```

```
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentId": [],
"_id": "65337ddc619c14402da919b4",
"ownerName": "Prashant Vikram Pawar",
"ownerPhoneNo": "9970774591",
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "9970774591",
"contactPersonName": "Prashant Vikram Pawar",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "Prashant Vikram Pawar",
    "phone": "9970774591",
    "ownershipShare": "",
    "email": "",
    "id": "714161"
  }
],
"caseReferredBy": "63f9f4adce84bf289ba9956e",
"relationWithOwner": "self",
"fullAddress": "Residential Flat No. 104, Basement Floor, Samarth Shrushti
Apartment, Near Hotel Red Rose, Plot No. 76, Off Mungsare Chandshi Road, Babu
Pool, Village - Chandshi, Gut No. 48/3, 48/4 + 50/1+3/2, Taluka - Chandshi, District -
Nashik, Nashik , 422003, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1697873276362_prashant_pawar_1.pdf",
    "path": "cases/65337ddc619c14402da919b4/
document_1697873276362_prashant_pawar_1.pdf",
    "id": "312950",
    "uploadedBy": "63f9ed37ce84bf289ba991ac",
    "createdAt": "Sat Oct 21 2023 12:58:48 GMT+0530 (India Standard Time)"
  }
]
```

```
    },
    {
      "documentType": {
        "value": "60ae1248aa6d152c1801b2ee",
        "label": "Previous Valuation Report"
      },
      "isHardCopy": false,
      "displayStatus": false,
      "fileName": "document_1697873308944_Prashant_pawar.pdf",
      "path": "cases/65337ddc619c14402da919b4/
document_1697873308944_Prashant_pawar.pdf",
      "id": "486832",
      "uploadedBy": "63f9ed37ce84bf289ba991ac",
      "createdAt": "Sat Oct 21 2023 12:58:48 GMT+0530 (India Standard Time)"
    }
  ],
  "isUrgent": "false",
  "isExternal": "false",
  "scheduleSiteVisitDate": "Invalid date",
  "caseNumber": "004561",
  "createdBy": "63f9ed37ce84bf289ba991ac",
  "caseHistory": [
    {
      "id": "161219",
      "title": "Create Case",
      "description": "Create Case",
      "datetime": "Sat Oct 21 2023 12:59:32 GMT+0530 (India Standard Time)"
    }
  ],
  "proposePurchasers": [],
  "siteInspection": [],
  "composition": [],
  "otherComposition": [],
  "externalReport": [],
  "documentPerArea": [],
  "images": [],
  "indicatorArr": [],
  "externalImages": [
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65337f19619c14402da91e51",
      "name":
"externallmg_1697873689026_WhatsApp_Image_20231019_at_22553_PM.jpeg",
      "path": "cases/65337ddc619c14402da919b4/
externallmg_1697873689026_WhatsApp_Image_20231019_at_22553_PM.jpeg",
```



```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65337f19619c14402da91e52",
    "name":
"externallmg_1697873689051_WhatsApp_Image_20231019_at_22555_PM.jpeg",
    "path": "cases/65337ddc619c14402da919b4/
externallmg_1697873689051_WhatsApp_Image_20231019_at_22555_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65337f19619c14402da91e53",
    "name":
"externallmg_1697873689108_WhatsApp_Image_20231019_at_22558_PM.jpeg",
    "path": "cases/65337ddc619c14402da919b4/
externallmg_1697873689108_WhatsApp_Image_20231019_at_22558_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65337f19619c14402da91e54",
    "name":
"externallmg_1697873689221_WhatsApp_Image_20231019_at_22559_PM.jpeg",
    "path": "cases/65337ddc619c14402da919b4/
externallmg_1697873689221_WhatsApp_Image_20231019_at_22559_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65337f19619c14402da91e55",
    "name":
"externallmg_1697873689263_WhatsApp_Image_20231019_at_22602_PM.jpeg",
    "path": "cases/65337ddc619c14402da919b4/
externallmg_1697873689263_WhatsApp_Image_20231019_at_22602_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65337f19619c14402da91e56",
```

```
    "name":  
    "externallmg_1697873689374_WhatsApp_Image_20231019_at_22604_PM_1.jpeg",  
    "path": "cases/65337ddc619c14402da919b4/  
externallmg_1697873689374_WhatsApp_Image_20231019_at_22604_PM_1.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "65337f19619c14402da91e57",  
    "name":  
    "externallmg_1697873689463_WhatsApp_Image_20231019_at_22604_PM.jpeg",  
    "path": "cases/65337ddc619c14402da919b4/  
externallmg_1697873689463_WhatsApp_Image_20231019_at_22604_PM.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "65337f19619c14402da91e58",  
    "name":  
    "externallmg_1697873689507_WhatsApp_Image_20231019_at_22606_PM.jpeg",  
    "path": "cases/65337ddc619c14402da919b4/  
externallmg_1697873689507_WhatsApp_Image_20231019_at_22606_PM.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "65337f19619c14402da91e59",  
    "name":  
    "externallmg_1697873689576_WhatsApp_Image_20231019_at_22608_PM.jpeg",  
    "path": "cases/65337ddc619c14402da919b4/  
externallmg_1697873689576_WhatsApp_Image_20231019_at_22608_PM.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "65337f19619c14402da91e5a",  
    "name":  
    "externallmg_1697873689632_WhatsApp_Image_20231019_at_22609_PM.jpeg",  
    "path": "cases/65337ddc619c14402da919b4/  
externallmg_1697873689632_WhatsApp_Image_20231019_at_22609_PM.jpeg",  
    "orientation": "portrait"  
  },  
  }
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65337f19619c14402da91e5b",
  "name":
"externallmg_1697873689698_WhatsApp_Image_20231019_at_22610_PM.jpeg",
  "path": "cases/65337ddc619c14402da919b4/
externallmg_1697873689698_WhatsApp_Image_20231019_at_22610_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65337f26619c14402da91e89",
  "name":
"externallmg_1697873701867_WhatsApp_Image_20231019_at_22530_PM.jpeg",
  "path": "cases/65337ddc619c14402da919b4/
externallmg_1697873701867_WhatsApp_Image_20231019_at_22530_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65337f26619c14402da91e8a",
  "name":
"externallmg_1697873702008_WhatsApp_Image_20231019_at_22534_PM.jpeg",
  "path": "cases/65337ddc619c14402da919b4/
externallmg_1697873702008_WhatsApp_Image_20231019_at_22534_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65337f26619c14402da91e8b",
  "name":
"externallmg_1697873702189_WhatsApp_Image_20231019_at_22536_PM_1.jpeg",
  "path": "cases/65337ddc619c14402da919b4/
externallmg_1697873702189_WhatsApp_Image_20231019_at_22536_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65337f26619c14402da91e8c",
  "name":
"externallmg_1697873702230_WhatsApp_Image_20231019_at_22536_PM.jpeg",
```

```
    "path": "cases/65337ddc619c14402da919b4/
externallmg_1697873702230_WhatsApp_Image_20231019_at_22536_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65337f26619c14402da91e8d",
    "name":
"externallmg_1697873702356_WhatsApp_Image_20231019_at_22540_PM.jpeg",
    "path": "cases/65337ddc619c14402da919b4/
externallmg_1697873702356_WhatsApp_Image_20231019_at_22540_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65337f26619c14402da91e8e",
    "name":
"externallmg_1697873702398_WhatsApp_Image_20231019_at_22543_PM.jpeg",
    "path": "cases/65337ddc619c14402da919b4/
externallmg_1697873702398_WhatsApp_Image_20231019_at_22543_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65337f26619c14402da91e8f",
    "name":
"externallmg_1697873702449_WhatsApp_Image_20231019_at_22546_PM.jpeg",
    "path": "cases/65337ddc619c14402da919b4/
externallmg_1697873702449_WhatsApp_Image_20231019_at_22546_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65337f26619c14402da91e90",
    "name":
"externallmg_1697873702564_WhatsApp_Image_20231019_at_22547_PM.jpeg",
    "path": "cases/65337ddc619c14402da919b4/
externallmg_1697873702564_WhatsApp_Image_20231019_at_22547_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```

    "status": false,
    "_id": "65337f26619c14402da91e91",
    "name":
"externallmg_1697873702603_WhatsApp_Image_20231019_at_22550_PM.jpeg",
    "path": "cases/65337ddc619c14402da919b4/
externallmg_1697873702603_WhatsApp_Image_20231019_at_22550_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65337f26619c14402da91e92",
    "name":
"externallmg_1697873702678_WhatsApp_Image_20231019_at_22551_PM.jpeg",
    "path": "cases/65337ddc619c14402da919b4/
externallmg_1697873702678_WhatsApp_Image_20231019_at_22551_PM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-10-21T07:29:32.608Z",
"updatedAt": "2023-10-21T07:35:02.792Z",
"__v": 0,
"invoiceId": "65337ddc619c14402da919b6",
"updatedBy": "63f9f4adce84bf289ba9956e"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			