

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9f4"
    },
    "type": "CREDITOFFICER",
    "_id": "650581d3a8e9b70221e855e5",
    "firstName": "Bhakti",
    "lastName": "Podkar",
    "mobileNo": "",
    "workMobileNo": "8425827511",
    "email": "Bhakti.racpc.sion@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5000000",
    "discussWithPerson": "Bhakti",
    "expectedFees": 2500,
    "quotedAmount": "2500"
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9f4",
  "branchCode": "000215",
  "type": "BRANCH",
  "name": "RACPC Sion ",
  "email": "racpc.sion@sbi.co.in",
  "mobileNo": "02225046265",
  "alternateMobileNo": "",
  "address": "B-603 & 604, Kohinoor City, Commercial-1, 6th Floor, Kiro Road, Off
L.B.S. Marg, Kurla (West), Mumbai, Pin Code - 400 070, State - Maharashtra, Country -
India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "64e5a649daae6a1c98101989",
  "role": "SITEENGINEER",
  "firstName": "Sameer",
  "email": "sameeryp2010@gmail.com",
  "lastName": "Parab",
  "mobileNo": "8291009567",
  "designation": "Site Engineer",
  "shortName": "Sameer",
  "workWithDocumentMaker": "62ea09ea4e679b264caf07d7"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60eebe33f3dd69653a5837ae",
  "role": "MAKER",
  "firstName": "Shamal",
  "email": "shamal@vastukala.org",
  "lastName": "Bodke",
  "mobileNo": "9821740317",
```

```
"designation": "",
"shortName": "SB",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eebe33f3dd69653a5837ae\
\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
},
"checker": "",
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
"value": "FIIV",
"label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
"title": {
"value": "Chartered_Engineer",
"label": "Chartered Engineer"
},
"_id": "60af80072ffdf65bcd658653",
"number": "AM161706-3"
}
```

```
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.207061395298606",
  "longitude": "73.10251558261902"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.10251558261902,
    19.207061395298606
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-22",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-22",
      "remark": ""
    }
  ]
}
```

```
    }
  ],
  "schedule": [],
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Nandivali",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "4",
    "label": false
  },
  "buildingNo": {
```

```
"status": false,
"name": "Building No",
"key": "buildingNo",
"value": "",
"label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Dombivali (East)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kalyan",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Siddharth Shrushti",
```

```
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Near Ravikiran Socitey, Desale Pada",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "C",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
```



```
"name": "Old Survey No.",
"key": "oldSurveyNumber",
"value": "",
"label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "17",
  "label": true
},
"hisNo": {
  "status": true,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "9(P)",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "403",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
}
```

```
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 421 201",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
```

```

    "key": "suburb",
    "value": "",
    "label": false
  }
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {

```

```
"value": "(Grampanchayat)_Zilla_Parishad,_Thane",
"label": "(Grampanchayat) Zilla Parishad, Thane"
},
"whetherCoveredUnderAnyState": {
"value": "No",
"label": "No"
},
"asPerActualAgreement": {
"north": "Open Plot & Bhavani Paradise Building",
"west": "Reliable Arcade",
"south": "Ashtadhatu Shiv Mandir Road",
"east": "Bungalow & Vedant Shree Apartment"
},
"asPerDocumentAgreement": {
"north": "Details not available",
"west": "Details not available",
"south": "Details not available",
"east": "Details not available"
},
"unitBoundaries": {
"asPerActual": {
"north": "Details not available",
"east": "Details not available",
"south": "Details not available",
"west": "Details not available"
},
"asPerDocument": {
"north": "Details not available",
"east": "Details not available",
"south": "Details not available",
"west": "Details not available"
},
"isActive": false,
"title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of Approved Building plans were not provided and
not verified.",
"approvePlanVerified": "N. A.",
"empanelledOfApprovePlan": "N. A."
},
"compositeRate": {
"remark": "",
"depreciationPercentage": "",
"depreciationRatioOfBuilding": "",
"salvageValue": "",
```

```
"depreciatedCostOfConstruction": "",
"depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Nandivli Panchanand",
  "rate": "56400",
  "landRate": "21400",
  "igrImage": "cases/6533a18a619c14402da97516/igr_1698065307930_Image.png",
  "squareMeterGuideLineRate": "56400.00",
  "squareFeetGuideLineRate": "5240.00"
},
"igrFinalRate": {
  "depreciationPercentage": "0",
  "rate": "56400",
  "squareMeterGuideLineRate": "56400.00",
  "squareFeetGuideLineRate": "5240.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Tenant_Occupied",
    "label": "Tenant Occupied"
  },
  "monthlyRent": "4,500",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per Local norms",
  "tenantName": "Pramila Thapa",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  }
},
```

```
"anyFavouringForExtraPotentialValue": "Located in developed area",
"negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Stilt + Open Car Parking",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2021",
    "fullDate": "1/1/2021"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  },
  "typeOfStructure": {
    "value": "R.C.C._Framed_Structure",
    "label": "R.C.C. Framed Structure"
  },
  "typeOfFoundation": {
    "value": "rcc",
    "label": "R.C.C. Foundation"
  }
}
```

```
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
```

```
    "value": "Information_not_available",
    "label": "Information not available"
  },
  "provisionOfFirefighting": {
    "value": "Information_not_available",
    "label": "Information not available"
  },
  "groundStilt": {
    "value": "stilt",
    "label": "Stilt"
  },
  "yearOfConstructionAsPer": {
    "value": "as_per_site_information",
    "label": "As per site information"
  },
  "isSiteVisitAllowed": true,
  "totalLifeBuilding": "60",
  "estimatedAge": "58",
  "ageOfBuilding": "2",
  "noOfBasement": "",
  "noOfPodium": "",
  "noOfAmenityFloors": "",
  "noOfFloors": "7",
  "flatFloorNo": "4",
  "noOfLifts": "1",
  "noOfDwellingUnitsInBuilding": "8"
},
"finalPlinthArea": {
  "areaType": "Built Up",
  "area": "595.00",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area as per Agreement For Sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/6533a18a619c14402da97516/
routeMap_1698211621949_Image.png",
    "routeLat": "19.197806",
    "routeLng": "73.090000",
    "stationName": "Dombivali",
    "routeDistance": "4 Km"
  },
}
```



```
"finalLatLng": {
  "coordinates": [
    null,
    null
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": true,
  "finallatLng": true
},
"locationMapImg": [
  {
    "id": "ayfrk",
    "name": "ayfrk",
    "image": "cases/6533a18a619c14402da97516/
routeMap_1698211529583_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
```

```
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "3272500.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "3272500.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "3117800.00",
```

```
"selectedBuildUpValue": "595.00",
"selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "65355d08619c14402da9f5e4",
      "name": "externallmg_1697995973882_1697995996071_image_13.jpeg",
      "path": "cases/6533a18a619c14402da97516/
externallmg_1697995973882_1697995996071_image_13.jpeg",
      "orientation": "landscape"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "65355d08619c14402da9f5e0",
      "name": "externallmg_1697995971613_1697995996071_image_9.jpeg",
      "path": "cases/6533a18a619c14402da97516/
externallmg_1697995971613_1697995996071_image_9.jpeg",
      "orientation": "landscape"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "65355d08619c14402da9f5d9",
      "name": "externallmg_1697995966229_1697995996071_image_0.jpeg",
      "path": "cases/6533a18a619c14402da97516/
externallmg_1697995966229_1697995996071_image_0.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "65355d08619c14402da9f5da",
      "name": "externallmg_1697995966587_1697995996071_image_1.jpeg",
      "path": "cases/6533a18a619c14402da97516/
externallmg_1697995966587_1697995996071_image_1.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "65355d08619c14402da9f5e4",
      "name": "externallmg_1697995973882_1697995996071_image_13.jpeg",
      "path": "cases/6533a18a619c14402da97516/
externallmg_1697995973882_1697995996071_image_13.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "65355d08619c14402da9f5e5",
    "name": "externallmg_1697996019363_1697996053768_image_0.jpeg",
    "path": "cases/6533a18a619c14402da97516/
externallmg_1697996019363_1697996053768_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65355d08619c14402da9f5e2",
    "name": "externallmg_1697995972137_1697995996071_image_11.jpeg",
    "path": "cases/6533a18a619c14402da97516/
externallmg_1697995972137_1697995996071_image_11.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "65355d08619c14402da9f5db",
    "name": "Living Room",
    "path": "cases/6533a18a619c14402da97516/
externallmg_1697995967373_1697995996071_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "65355d08619c14402da9f5dc",
    "name": "Living Room",
    "path": "cases/6533a18a619c14402da97516/
externallmg_1697995967842_1697995996071_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65355d08619c14402da9f5dd",
    "name": "Living Room",
    "path": "cases/6533a18a619c14402da97516/
externallmg_1697995970037_1697995996071_image_6.jpeg",
    "orientation": "portrait"
  },
],
```

```
{
  "status": false,
  "_id": "65355d08619c14402da9f5e1",
  "name": "Living Room",
  "path": "cases/6533a18a619c14402da97516/
externallmg_1697995971862_1697995996071_image_10.jpeg",
  "orientation": "landscape"
}
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": null,
    "max": null
  },
  "builtUpRateRange": {
    "min": "5826",
    "max": "6316"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
```

```
"title": "Kitchen arrangements",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```



```
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "595.00",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentId": [],
"_id": "6533a18a619c14402da97516",
```

```
"ownerName": "Mr. Amarpal Jitai Chaurasiya, Mrs. Durgavati Amarapal Chaurasiya & Mr. Digvijay Amarapal Chaurasiya",
"ownerPhoneNo": "8108329540",
"appAddress": "Flat no. 403, 4th Floor, Wing - C, Siddharth Shrushti, Deslepada, Dombivali East ",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "inputs": {
      "documentDate": "07/04/2021",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "M/s. Om Construction",
      "to": {
        "value": "Purchasers",
        "label": "Purchasers"
      },
      "Purchasers": "Mr. Amarpal Jitai Chaurasiya, Mrs. Durgavati Amarapal Chaurasiya & Mr. Digvijay Amarapal Chaurasiya",
      "number": {
        "value": "Registration_No",
        "label": "Registration No"
      },
      "Registration_No": "7969/2021"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "993481",
    "path": "cases/6533a18a619c14402da97516/document_1697882449563_1697882482135_Racpc_Sion_Amarpal_Chaurasiya.pdf",
    "fileName": "document_1697882449563_1697882482135_Racpc_Sion_Amarpal_Chaurasiya.pdf"
  },
  {
    "documentType": {
      "value": "60ae1247aa6d152c1801b2ea",
      "label": "Commencement Certificate"
    },
    "inputs": {
      "documentDate": "12/11/2008",
```

```
"number": {
  "value": "No",
  "label": "No"
},
"No": "SPV / Gram / Pradhikaran / VS / 87 / 2008"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1698211916023_CC.pdf",
"path": "cases/6533a18a619c14402da97516/document_1698211916023_CC.pdf",
"id": "941496",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Wed Oct 25 2023 11:01:56 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "004572",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "281388",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Oct 21 2023 15:31:46 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Amarpal Jitai Chaurasiya, Mrs. Durgavati Amarapal Chaurasiya & Mr. Digvijay Amarapal Chaurasiya",
    "phone": "8108329540",
    "ownershipShare": "",
    "email": "",
    "id": "678238"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "580569",
    "name": "Living Room",
    "length": "9.50",
```

```
"length1": "9",
"length2": "6",
"width": "16.92",
"width1": "16",
"width2": "11",
"totalArea": "160.71",
"images": [],
"extraAreas": [],
"finalArea": "160.71"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Kitchen",
  "length": "7.75",
  "length1": "7",
  "length2": "9",
  "width": "10.33",
  "width1": "10",
  "width2": "4",
  "totalArea": "80.08",
  "images": [],
  "extraAreas": [],
  "finalArea": "80.08"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Bathroom",
  "length": "4.67",
  "length1": "4",
  "length2": "8",
  "width": "4.17",
  "width1": "4",
  "width2": "2",
  "totalArea": "19.44",
  "images": [],
  "extraAreas": [],
  "finalArea": "19.44"
},
}
```

```
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "WC",
  "length": "2.50",
  "length1": "2",
  "length2": "6",
  "width": "4.58",
  "width1": "4",
  "width2": "7",
  "totalArea": "11.46",
  "images": [],
  "extraAreas": [],
  "finalArea": "11.46"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Passage",
  "length": "3.83",
  "length1": "3",
  "length2": "10",
  "width": "3.08",
  "width1": "3",
  "width2": "1",
  "totalArea": "11.82",
  "images": [],
  "extraAreas": [],
  "finalArea": "11.82"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bedroom",
  "length": "9.83",
  "length1": "9",
  "length2": "10",
```

```
"width": "10.42",
"width1": "10",
"width2": "5",
"totalArea": "102.43",
"images": [],
"extraAreas": [],
"finalArea": "102.43"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Balcony",
  "length": "2.67",
  "length1": "2",
  "length2": "8",
  "width": "9.58",
  "width1": "9",
  "width2": "7",
  "totalArea": "25.56",
  "images": [],
  "extraAreas": [],
  "finalArea": "25.56"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Built_Up",
    "squareMeterArea": "55.28",
    "totalAreaDocument": "595",
    "docBuiltpPercentage": "",
    "docFinalBuiltUp": "0.00",
    "docFinalBuiltUpSquareMeter": "0.00",
    "docSaleablePercentage": ""
  }
]
```

```
"docFinalSaleable": "0.00",
"docFinalSaleableSquareMeter": "0.00",
"id": "879133"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "65366be72a1baf5f34c194c9",
  "property": "Swanand Heights, Dombivli East",
  "area": "570",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "floor": "middle",
  "source": "square_yards",
  "expectedPrice": "3500000",
  "expectedRate": "6140.35",
  "builtUpExpectedRate": "0.00",
  "image": "cases/6533a18a619c14402da97516/
indicator_1698064934073_Image.png",
  "squareMeter": "52.95",
  "id": "134155"
},
{
  "printlnReport": true,
  "_id": "65366be72a1baf5f34c194ca",
  "property": "Reliable Arcade, Dombivali East",
  "area": "475",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "floor": "Middle",
  "source": "Nobroker.com",
  "expectedPrice": "3000000",
  "expectedRate": "6315.79",
  "builtUpExpectedRate": "0.00",
  "image": "cases/6533a18a619c14402da97516/
indicator_1698065022104_Image.png",
  "squareMeter": "44.13",
  "id": "210833"
},
{
```

```
"printlnReport": true,
  "_id": "65366be72a1baf5f34c194cb",
  "property": "Reliable Arcade, Dombivali East",
  "area": "515",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "floor": "middle",
  "source": "Nobroker.com",
  "expectedPrice": "3000000",
  "expectedRate": "5825.24",
  "builtUpExpectedRate": "0.00",
  "image": "cases/6533a18a619c14402da97516/
indicator_1698065087160_Image.png",
  "squareMeter": "47.85",
  "id": "232879"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65355d08619c14402da9f5d8",
    "name": "externalImg_1697995931290_1697995962421_image_0.jpeg",
    "path": "cases/6533a18a619c14402da97516/
externalImg_1697995931290_1697995962421_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65355d08619c14402da9f5d9",
    "name": "externalImg_1697995966229_1697995996071_image_0.jpeg",
    "path": "cases/6533a18a619c14402da97516/
externalImg_1697995966229_1697995996071_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65355d08619c14402da9f5da",
    "name": "externalImg_1697995966587_1697995996071_image_1.jpeg",
    "path": "cases/6533a18a619c14402da97516/
externalImg_1697995966587_1697995996071_image_1.jpeg",
    "orientation": "portrait"
  }
]
```



```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65355d08619c14402da9f5db",
  "name": "externallmg_1697995967373_1697995996071_image_2.jpeg",
  "path": "cases/6533a18a619c14402da97516/
externallmg_1697995967373_1697995996071_image_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65355d08619c14402da9f5dc",
  "name": "externallmg_1697995967842_1697995996071_image_3.jpeg",
  "path": "cases/6533a18a619c14402da97516/
externallmg_1697995967842_1697995996071_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65355d08619c14402da9f5dd",
  "name": "externallmg_1697995970037_1697995996071_image_6.jpeg",
  "path": "cases/6533a18a619c14402da97516/
externallmg_1697995970037_1697995996071_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65355d08619c14402da9f5de",
  "name": "externallmg_1697995970428_1697995996071_image_7.jpeg",
  "path": "cases/6533a18a619c14402da97516/
externallmg_1697995970428_1697995996071_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65355d08619c14402da9f5df",
  "name": "externallmg_1697995970792_1697995996071_image_8.jpeg",
  "path": "cases/6533a18a619c14402da97516/
externallmg_1697995970792_1697995996071_image_8.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65355d08619c14402da9f5e0",
  "name": "externallmg_1697995971613_1697995996071_image_9.jpeg",
  "path": "cases/6533a18a619c14402da97516/
externallmg_1697995971613_1697995996071_image_9.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65355d08619c14402da9f5e1",
  "name": "externallmg_1697995971862_1697995996071_image_10.jpeg",
  "path": "cases/6533a18a619c14402da97516/
externallmg_1697995971862_1697995996071_image_10.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65355d08619c14402da9f5e2",
  "name": "externallmg_1697995972137_1697995996071_image_11.jpeg",
  "path": "cases/6533a18a619c14402da97516/
externallmg_1697995972137_1697995996071_image_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65355d08619c14402da9f5e3",
  "name": "externallmg_1697995972953_1697995996071_image_12.jpeg",
  "path": "cases/6533a18a619c14402da97516/
externallmg_1697995972953_1697995996071_image_12.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65355d08619c14402da9f5e4",
  "name": "externallmg_1697995973882_1697995996071_image_13.jpeg",
  "path": "cases/6533a18a619c14402da97516/
externallmg_1697995973882_1697995996071_image_13.jpeg",
  "orientation": "landscape"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65355d08619c14402da9f5e5",
    "name": "externallmg_1697996019363_1697996053768_image_0.jpeg",
    "path": "cases/6533a18a619c14402da97516/
externallmg_1697996019363_1697996053768_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65355d08619c14402da9f5e6",
    "name": "externallmg_1697996023654_1697995975095_image_0.jpeg",
    "path": "cases/6533a18a619c14402da97516/
externallmg_1697996023654_1697995975095_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65355d08619c14402da9f5e7",
    "name": "externallmg_1697996023962_1697995975095_image_1.jpeg",
    "path": "cases/6533a18a619c14402da97516/
externallmg_1697996023962_1697995975095_image_1.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname":
"1697696061713_1696590611268_1696506280505_Calculation.xlsx",
    "filename": "1698208915731_1697696061713_1696590611268_1696506280505_C
alculation.xlsx",
    "path": "cases/6533a18a619c14402da97516/processingDocuments/169820891573
1_1697696061713_1696590611268_1696506280505_Calculation.xlsx",
    "size": "95027",
    "createdAt": "Wed Oct 25 2023 10:11:55 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  }
],
"remarks": [],
"createdAt": "2023-10-21T10:01:46.739Z",
"updatedAt": "2023-10-25T05:32:03.278Z",
"__v": 0,
"invoiceId": "6533a18a619c14402da97527",
```

"fullAddress": "Residential Flat No. 403, 4th Floor, Wing - C, Siddharth Shrushti, Near Ravikiran Socitey, Desale Pada, Village - Nandivali, Taluka - Kalyan, District - Thane, Dombivali (East), PIN - 421 201, State - Maharashtra, India",  
"updatedBy": "60eebe33f3dd69653a5837ae",  
"addressForMap": "",  
"caseReferredBy": "60b7177d2ffdf65bcd65882a",  
"contactPersonName": "Pramila Thapa (Tenant)",  
"email": "",  
"isExternal": "false",  
"isUrgent": "false",  
"ownershipShare": "",  
"purchaseValueAsPerDocument": "",  
"relationWithOwner": "self",  
"siteVisitContactNo": "9076451856",  
"buildingServicesRate": "2600",  
"finalAreaType": "Built Up Area",  
"finalAsPerArea": "Agreement For Sale",  
"finalBuiltUpPercentage": "0",  
"finalCarpetConvertToBuiltUpPer": "0",  
"finalMeasurementType": "Sq. Ft.",  
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 595.00",  
"flatRate": "5500.00",  
"landOtherRate": "2900",  
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Bathroom + WC + Passage + Balcony",  
"carpetTotal": "411.50",  
"otherCarpetTotal": "0.00",  
"builtupPercentage": "10",  
"finalBuiltupArea": "452.65",  
"finalCarpetArea": "411.50",  
"finalSalableArea": "497.91",  
"salablePercentage": "10",  
"toBeAdded": "",  
"extendOfSiteRemark": "",  
"siteMeasurementRemark": "",  
"finalSaleablePercentage": "0",  
"landDetails": {  
 "holdType": {  
 "label": "Free Hold",  
 "value": "Free\_Hold"  
 },  
},  
"leaseDetails": {  
 "lessorName": "",  
 "lesseeName": "",  
 "leasePremium": "",  
 "leaseRent": "",

```
"leasePeriod": 0,  
"leaseFrom": "",  
"leaseTo": "",  
"remainingLeasePeriod": 0,  
"leaseDate": ""  
}  
}  
}
```

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
Composition :			
Living Room	9'6"	16'11"	160.71
Kitchen	7'9"	10'4"	80.08
Bathroom	4'8"	4'2"	19.44
WC	2'6"	4'7"	11.46
Passage	3'10"	3'1"	11.82
Bedroom	9'10"	10'5"	102.43
Balcony	2'8"	9'7"	25.56
Other Composition :			