

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9f4"
    },
    "type": "CREDITOFFICER",
    "_id": "64d483a687258203eab0dd0f",
    "firstName": "Rohan ",
    "lastName": "Raut ",
    "mobileNo": "",
    "workMobileNo": "8097138369",
    "email": "Rohan.racpc.sion@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "2500000",
    "discussWithPerson": "Rohan ",
    "expectedFees": 1250,
    "quotedAmount": "2500"
  },
  "organization": {
```

```
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9f4",
  "branchCode": "000215",
  "type": "BRANCH",
  "name": "RACPC Sion ",
  "email": "racpc.sion@sbi.co.in",
  "mobileNo": "02225046265",
  "alternateMobileNo": "",
  "address": "B-603 & 604, Kohinoor City, Commercial-1, 6th Floor, Kirol Road, Off
L.B.S. Marg, Kurla (West), Mumbai, Pin Code - 400 070, State - Maharashtra, Country -
India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "63fc4680ce84bf289ba9c7fc",
  "role": "SITEENGINEER",
  "firstName": "Nikhil ",
  "email": "valtechnical2022@gmail.com",
  "lastName": "Sonawane",
  "mobileNo": "9819470709",
  "designation": "",
  "shortName": "NS",
  "workWithDocumentMaker": "6006d4ce5080a310ac1fdcf2",
  "profilePhoto": "users/63fc4680ce84bf289ba9c7fc/
profilePhoto_1681380664371_WhatsApp_Image_20230413_at_33801_PM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62691c48afd7d55eddecfda3",
  "role": "SITEENGINEER+MAKAR",
  "firstName": "Bhavika",
  "email": "bhavikachavan0102@gmail.com",
```

```
"lastName": "chavan",
"mobileNo": "8390804382",
"designation": "Site Engineer",
"shortName": "BH",
"workWithDocumentMaker": "",
"profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
  },

```

```
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.169456049590586",
  "longitude": "73.0463999490758"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.0463999490758,
```

```
19.169456049590586
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-10-21T10:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-10-21T10:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-10-21T10:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-10-21T10:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-10-21T10:30:00.000Z",
      "remark": ""
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-22",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,

```

```
"name": "State",
"key": "state",
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Dawale",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "10",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "C-1",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Diva (East)",
  "label": false
}
```

```
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Divine Heights",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Diva Shill Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
```



```
"key": "street2",
"value": "",
"label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Sudama Greens",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "167",
  "label": true
},
"hissaNo": {
  "status": true,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "2A, 3",
  "label": true
},
}
```

```
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1013",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
```

```
"value": "",
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "Thane – 400 612",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "Proposed_RCC_SLab",
    "label": "Proposed RCC SLab"
  },
  "flooring": {
    "value": "Proposed_Vitrified_tiles_flooring",
    "label": "Proposed Vitrified tiles flooring"
  },
  "doors": {
    "value": "Proposed_Powder_Coated_Aluminum_Sliding_Windows",
    "label": "Proposed Powder Coated Aluminum Sliding Windows"
  },
  "windows": {
```

```
"value": "Proposed_Powder_coated_aluminium_sliding_windows",
"label": "Proposed Powder coated aluminium sliding windows"
},
"fittings": {
  "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Concealed_wiring",
"label": "Proposed Concealed plumbing with C.P. fittings. Concealed wiring"
},
"finishing": {
  "value": "Proposed_Cement_Plastering",
"label": "Proposed Cement Plastering"
}
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Semi_Urban",
    "label": "Semi Urban"
  },
  "townplanApprovedByList": {
    "value": "Thane_Municipal_Corporation",
    "label": "Thane Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Greens Road & Open Plot",
    "west": "Diva Shill Road",
    "south": "Open Plot",
    "east": "Open Plot"
  },
  "asPerDocumentAgreement": {
    "north": "Details not available",
    "west": "Details not available",
    "south": "Details not available",
    "east": "Details not available"
  },
  "unitBoundaries": {
```

```
"asPerActual": {
  "north": "",
  "west": "",
  "south": "",
  "east": ""
},
"asPerDocument": {
  "north": "",
  "west": "",
  "south": "",
  "east": ""
},
"setDisplay": false,
"title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "It is in under construction building. As per site information,
the composition of flat is 1 Bedroom + Living Room + Kitchen + 2 Toilets + Passage
(i.e., 1 BHK + 2 Toilets)",
"dateOfIssusApprovePlan": "Copy of approved building plans were not provided and
not verified.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A."
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "52300",
  "landRate": "10400",
  "igrImage": "cases/6533a57e619c14402da9860c/igr_1698045560130_Image.png",
  "squareMeterGuideLineRate": "54915.00",
  "squareFeetGuideLineRate": "5102.00"
},
"igrFinalRate": {
  "depreciationPercentage": "0",
  "rate": "52300",
  "squareMeterGuideLineRate": "54915.00",
  "squareFeetGuideLineRate": "5102.00"
},
"outgoingDetail": {
```

```
"areaStatusList": {
  "value": "Middle_Class",
  "label": "Middle Class"
},
"propertyTypeOfUseList": {
  "value": "Residential_Purpose",
  "label": "Residential Purpose"
},
"propertyOccupiedByList": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"monthlyRent": "6,800",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Building is under construction",
"floorSpaceIndex": "As per TMC norms",
"tenantName": "",
"maintenanceOfFlat": "Details not available"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "Proposed_RCC_SLab",
    "label": "Proposed RCC SLab"
  },
  "partitions": {
    "value": "Proposed_6\"_Thk._Brick_Masonry",
    "label": "Proposed 6\" Thk. Brick Masonry"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Building_Under_Construction",
```

```
"label": "Building Under Construction"
},
"carParking": "Stilt Parking",
"constructionWorkStatus": {
  "value": "InProgress",
  "label": "Under Construction"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "",
  "month": "1",
  "year": "2025",
  "fullDate": "1/1/2025"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
```

```
"value": "Designed_as_per_I.S._codes",
"label": "Designed as per I.S. codes"
},
"sewerageSystem": {
"value": "MunicipalSewerageSystem",
"label": "Connected to Municipal Sewerage System"
},
"walls": {
"value": "1",
"label": "Yes"
},
"appearanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenancelssues": {
"value": "1",
"label": "Yes"
},
"visibleDamageInBuilding": {
"value": "1",
"label": "Yes"
},
"systemOfAirConditioning": {
"value": "1",
"label": "Yes"
},
"provisionOfFirefighting": {
"value": "1",
"label": "Yes"
},
"groundStilt": {
"value": "Part_Ground_and_Part_Stilt",
"label": "Part Ground + Part Stilt"
},
"yearOfConstructionAsPer": {
"value": "as_per_site_information",
"label": "As per site information"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "0",
```



```
"ageOfBuilding": "0",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "24",
"flatFloorNo": "10",
"noOfLifts": "3",
"noOfDwellingUnitsInBuilding": "15"
},
"finalPlinthArea": {
  "areaType": "Built Up",
  "area": "331.10",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/6533a57e619c14402da9860c/
routeMap_1698048337156_Image.png",
    "routeLat": "19.169083",
    "routeLng": "73.047139",
    "stationName": "Diva Junction",
    "routeDistance": "2.7 Km"
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "1m0vpv",
      "name": "1m0vpv",
      "image": "cases/6533a57e619c14402da9860c/
routeMap_1698048168898_Image.png"
    }
  ]
}
```

```
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "2709000.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValue": "0",
  "finalValue": "2709000.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Mon Oct 23 2023 17:00:15 GMT+0530 (India Standard Time)",
  "number": "2303163",
  "dayCount": "16",
  "monthCount": "360",
  "generatedBy": "5fc78e26625ecd20ec1f88e9"
},
"rateVerify": {
```

```
"status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "25",
    "percentage": "38.46153846153847",
    "isHideFloor": false,
    "status": true
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "21",
    "percentage": "5.65",
    "isHideFloor": false,
    "status": true
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "21",
    "percentage": "5.65",
    "isHideFloor": false,
    "status": true
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "19",
    "percentage": "2.56",
    "isHideFloor": false,
    "status": true
  },
  "externalPlastering": {
```

```
"label": "External Plastering",
"floorsCompleted": "19",
"percentage": "2.56",
"isHideFloor": false,
"status": true
},
"door": {
"label": "Door",
"floorsCompleted": "19",
"percentage": "1.83",
"isHideFloor": false,
"status": true
},
"window": {
"label": "Window",
"floorsCompleted": "19",
"percentage": "1.83",
"isHideFloor": false,
"status": true
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "19",
"percentage": "7.31",
"isHideFloor": false,
"status": true
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": true
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "75.85",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "1689272.00",
  "selectedBuildUpValue": "331.10",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "6535eb8c619c14402daa04c0",
      "name":
"externalImg_1698032523988_WhatsApp_Image_20231023_at_84217_AM_1.jpeg",
      "path": "cases/6533a57e619c14402da9860c/
externalImg_1698032523988_WhatsApp_Image_20231023_at_84217_AM_1.jpeg",
      "orientation": "portrait"
    }
  ]
}
```

```
}
],
"selfieWithSiteVisitImages": [
  {
    "status": false,
    "_id": "6535eb8c619c14402daa04c4",
    "name":
"externallmg_1698032524012_WhatsApp_Image_20231023_at_84217_AM_5.jpeg",
    "path": "cases/6533a57e619c14402da9860c/
externallmg_1698032524012_WhatsApp_Image_20231023_at_84217_AM_5.jpeg",
    "orientation": "portrait"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "6535eb8c619c14402daa04c1",
    "name":
"externallmg_1698032523994_WhatsApp_Image_20231023_at_84217_AM_2.jpeg",
    "path": "cases/6533a57e619c14402da9860c/
externallmg_1698032523994_WhatsApp_Image_20231023_at_84217_AM_2.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "6535eb8c619c14402daa04c1",
    "name":
"externallmg_1698032523994_WhatsApp_Image_20231023_at_84217_AM_2.jpeg",
    "path": "cases/6533a57e619c14402da9860c/
externallmg_1698032523994_WhatsApp_Image_20231023_at_84217_AM_2.jpeg",
    "orientation": "portrait"
  }
],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "8291",
    "max": "10494"
  },
  "builtUpRateRange": {
    "min": "7538",
    "max": "9540"
  }
}
```

```
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
    "title": "Interior Decorations",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
```



```
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": false,
"finalValuationArea": "301.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentId": [],
"_id": "6533a57e619c14402da9860c",
"ownerName": "Mrs. Shradha Sandesh Ambekar, Mr . Ambekar Sandesh Suresh & Mr.
Sameer Suresh Ambekar",
"ownerPhoneNo": "8291249595",
"appAddress": "Flat no. 1013, 10th Floor, Divine Heights, Sudama Greens, Building -
C1, Diva Shill Road, Village - Dawale, ",
"remark": "Dheerendra Singh SSL - 9140957299",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "inputs": {
      "documentDate": "10/10/2023",
      "from": {
        "value": "Developers",
```

```
    "label": "Developers"
  },
  "Developers": "M/s, Patil Developers ",
  "to": {
    "value": "The_Allottees",
    "label": "The Allottees"
  },
  "The_Allottees": "Mrs. Shradha Sandesh Amberkar, Mr . Ambekar Sandesh
Suresh & Mr. Sameer Suresh Ambekar",
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "16517 /02023"
},
"isHardCopy": false,
"displayStatus": true,
"id": "524857",
"path": "cases/6533a57e619c14402da9860c/
document_1697883384348_1697883416664_Racpc_Sion_Shraddha_Ambekar.pdf",
"fileName":
"document_1697883384348_1697883416664_Racpc_Sion_Shraddha_Ambekar.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "12/04/2023",
    "nameOfApprovingAuthority": {
      "value": "Thane_Municipal_Corporation",
      "label": "Thane Municipal Corporation"
    },
    "number": {
      "value": "V.P._No._",
      "label": "V.P. No. "
    },
    "V.P._No._": "S11 / 0051 / 12 TMC / TDD /4368 / 23"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1698039401530_4_Commencement_Certificates___NA_Or
der_for_plotted_development_2.pdf",
  "path": "cases/6533a57e619c14402da9860c/document_1698039401530_4_Comme
ncement_Certificates___NA_Order_for_plotted_development_2.pdf",
```

```
"id": "911928",
"uploadedBy": "62691c48afd7d55eddecfda3",
"createdAt": "Mon Oct 23 2023 11:11:48 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2e8",
    "label": "Layout Plan"
  },
  "inputs": {
    "documentDate": "12/04/2023",
    "nameOfApprovingAuthority": {
      "value": "Thane_Municipal_Corporation",
      "label": "Thane Municipal Corporation"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "TMC/TDD/4368/23"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName":
"document_1698039606976_2_Copy_of_Layout_Approval_in_case_of_layout_1.pdf",
  "path": "cases/6533a57e619c14402da9860c/
document_1698039606976_2_Copy_of_Layout_Approval_in_case_of_layout_1.pdf",
  "id": "535209",
  "uploadedBy": "62691c48afd7d55eddecfda3",
  "createdAt": "Mon Oct 23 2023 11:11:48 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "09/09/2023",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
      "label": "Maharashtra Real Estate Regulatory Authority"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
}
```

```
"No": "P51700019573"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1698039687672_document_1697883384348_16978834166
64_Racpc_Sion_Shraddha_Ambekar.pdf",
"path": "cases/6533a57e619c14402da9860c/document_1698039687672_document
_1697883384348_1697883416664_Racpc_Sion_Shraddha_Ambekar.pdf",
"id": "566679",
"uploadedBy": "62691c48afd7d55eddecfda3",
"createdAt": "Mon Oct 23 2023 11:11:48 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "004576",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
{
"id": "458689",
"title": "Create Lead",
"description": "Create Lead",
"datetime": "Sat Oct 21 2023 15:48:38 GMT+0530 (India Standard Time)"
}
],
"owners": [
{
"name": "Mrs. Shradha Sandesh Ambekar, Mr . Ambekar Sandesh Suresh & Mr.
Sameer Suresh Ambekar",
"phone": "8291249595",
"ownershipShare": "",
"email": "",
"id": "182672"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
{
"typeOfDocument": {
"label": "Agreement For Sale",
"value": "60ae1254aa6d152c1801b326"
},
"docMeasurementType": {
"value": "Square_Feet",
```

```
    "label": "Square Feet"
  },
  "selectAreaTypeDocument": "Carpet",
  "squareMeterArea": "27.96",
  "totalAreaDocument": "301",
  "docBultupPercentage": "10",
  "docFinalBultUp": "331.10",
  "docFinalBultUpSquareMeter": "30.76",
  "docSaleablePercentage": "",
  "docFinalSaleable": "0.00",
  "docFinalSaleableSquareMeter": "0.00",
  "id": "330127"
}
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "65361eda619c14402daacc0a",
    "property": "Flat",
    "area": "295",
    "bultUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "sale_Instance",
    "areaType": "Carpet",
    "floor": "1",
    "source": "Index_no.2",
    "expectedPrice": "2700000",
    "expectedRate": "9152.54",
    "bultUpExpectedRate": "8320.49",
    "image": "cases/6533a57e619c14402da9860c/
indicator_1698045298138_Image.png",
    "squareMeter": "27.41",
    "id": "237968"
  },
  {
    "printlnReport": true,
    "_id": "65361eda619c14402daacc0b",
    "property": "Flat",
    "area": "398",
    "bultUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "square_yards",
    "expectedPrice": "3300000",
```

```
    "expectedRate": "8291.46",
    "builtUpExpectedRate": "7537.69",
    "image": "cases/6533a57e619c14402da9860c/
indicator_1698045360089_Image.png",
    "squareMeter": "36.98",
    "id": "654190"
  },
  {
    "printlnReport": true,
    "_id": "65361eda619c14402daacc0c",
    "property": "Flat",
    "area": "324",
    "builtUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "square_yards",
    "expectedPrice": "3400000",
    "expectedRate": "10493.83",
    "builtUpExpectedRate": "9539.84",
    "image": "cases/6533a57e619c14402da9860c/
indicator_1698045426115_Image.png",
    "squareMeter": "30.10",
    "id": "869707"
  },
  {
    "printlnReport": true,
    "_id": "65361eda619c14402daacc0d",
    "property": "Flat",
    "area": "470",
    "builtUpPercentage": "0",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Built_Up",
    "source": "square_yards",
    "expectedPrice": "3711000",
    "expectedRate": "7895.74",
    "builtUpExpectedRate": "0.00",
    "image": "cases/6533a57e619c14402da9860c/
indicator_1698045498672_Image.png",
    "squareMeter": "43.66",
    "id": "162069"
  }
],
"externallImages": [
  {
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6535eb8c619c14402daa04c0",
    "name":
"externallmg_1698032523988_WhatsApp_Image_20231023_at_84217_AM_1.jpeg",
    "path": "cases/6533a57e619c14402da9860c/
externallmg_1698032523988_WhatsApp_Image_20231023_at_84217_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6535eb8c619c14402daa04c1",
    "name":
"externallmg_1698032523994_WhatsApp_Image_20231023_at_84217_AM_2.jpeg",
    "path": "cases/6533a57e619c14402da9860c/
externallmg_1698032523994_WhatsApp_Image_20231023_at_84217_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6535eb8c619c14402daa04c2",
    "name":
"externallmg_1698032524002_WhatsApp_Image_20231023_at_84217_AM_3.jpeg",
    "path": "cases/6533a57e619c14402da9860c/
externallmg_1698032524002_WhatsApp_Image_20231023_at_84217_AM_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6535eb8c619c14402daa04c3",
    "name":
"externallmg_1698032524005_WhatsApp_Image_20231023_at_84217_AM_4.jpeg",
    "path": "cases/6533a57e619c14402da9860c/
externallmg_1698032524005_WhatsApp_Image_20231023_at_84217_AM_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6535eb8c619c14402daa04c4",
    "name":
"externallmg_1698032524012_WhatsApp_Image_20231023_at_84217_AM_5.jpeg",
    "path": "cases/6533a57e619c14402da9860c/
externallmg_1698032524012_WhatsApp_Image_20231023_at_84217_AM_5.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6535eb8c619c14402daa04c5",
    "name":
"externallmg_1698032524015_WhatsApp_Image_20231023_at_84217_AM_6.jpeg",
    "path": "cases/6533a57e619c14402da9860c/
externallmg_1698032524015_WhatsApp_Image_20231023_at_84217_AM_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6535eb8c619c14402daa04c6",
    "name":
"externallmg_1698032524019_WhatsApp_Image_20231023_at_84217_AM_7.jpeg",
    "path": "cases/6533a57e619c14402da9860c/
externallmg_1698032524019_WhatsApp_Image_20231023_at_84217_AM_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6535eb8c619c14402daa04c7",
    "name":
"externallmg_1698032524020_WhatsApp_Image_20231023_at_84217_AM.jpeg",
    "path": "cases/6533a57e619c14402da9860c/
externallmg_1698032524020_WhatsApp_Image_20231023_at_84217_AM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-10-21T10:18:38.602Z",
"updatedAt": "2023-10-23T11:37:24.850Z",
"__v": 0,
"invoiceId": "6533a583619c14402da98644",
"fullAddress": "Residential Flat No. 1013, 10th Floor, Building No C-1, Divine Heights,
Sudama Greens, Diva Shill Road, Village - Dawale, Diva (East), Thane – 400 612,
State - Maharashtra, India",
"updatedBy": "5fc78e26625ecd20ec1f88e9",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
```



```
"contactPersonName": "Mr. Joseph ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Sales Person",
"siteVisitContactNo": "8591086460",
"buildingServicesRate": "2800",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 301.00",
"flatRate": "9000",
"landOtherRate": "6200",
"builtupPercentage": "10",
"carpetTotal": "0",
"extendOfSiteRemark": "",
"finalBuiltupArea": "0.00",
"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"otherCarpetTotal": "0",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
  "leaseFrom": "",
  "leaseTo": "",
  "remainingLeasePeriod": 0,
  "leaseDate": ""
}
},
"reportGeneratedDate": "Mon Oct 23 2023 17:00:43 GMT+0530 (India Standard Time)",
```

"siteVisitDate": "2023-10-22"

}

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
-------------	---------------	--------------	--------------

---

Composition :

---

Other

Composition :

---