

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": true,
    "RVDSValues": true
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6436535ee4256a03ecde45c8"
    },
    "type": "CREDITOFFICER",
    "_id": "6436535ee4256a03ecde45ca",
    "firstName": "Deepika ",
    "lastName": "Kumari",
    "mobileNo": "",
    "workMobileNo": "1981955591",
    "email": ""
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "10000000",
    "discussWithPerson": "Deepika ",
    "expectedFees": 5000,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6436535ee4256a03ecde45c8",
  "name": "Nepean Sea Road Branch (01862) ",
  "branchCode": "",
  "mobileNo": "02223676710",
  "alternateMobileNo": "",
  "email": "sbi.01862@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "8-A, Garden View Appt. \n\nKheshwala Premises Co-Op Society \n\nLJ
Marg, Mumbai-400006 "
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "62727444afd7d55eddee092c",
```

```
"role": "PICKUPPERSON",
"firstName": "Shantilal",
"email": "shantilal@vastukala.org",
"lastName": "Patel",
"mobileNo": "9969039853",
"shortName": "SHP",
"workWithDocumentMaker": "",
"profilePhoto": "users/62727444afd7d55eddee092c/
profilePhoto_1668057663775_WhatsApp_Image_20221110_at_104853_AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "63fc575ece84bf289ba9e82d",
"role": "SITEENGINEER",
"firstName": "Deepak ",
"email": "daksh7831@gmail.com",
"lastName": "Jain ",
"mobileNo": "9022815908",
"designation": "",
"shortName": "DJ",
"workWithDocumentMaker": ""
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60f915d3f3dd69653a592199",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Shobha",
"email": "shobha@vastukala.org",
"lastName": "Kuperkar",
"mobileNo": "9004134140",
"designation": "",
"shortName": "SH",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "60eebe33f3dd69653a5837ae",
"role": "MAKER",
"firstName": "Shamal",
"email": "shamal@vastukala.org",
"lastName": "Bodke",
"mobileNo": "9821740317",
"designation": "",
"shortName": "SB",
```

```
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eebe33f3dd69653a5837ae\
\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "[N]C.C.I.T/I -14/52/2008-09",
        "label": "Wealth Tax"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "6084131a13f01f158c6ea1f3",
    "PANNo": "AEAPC7114Q",
    "role": "VALUER",
    "firstName": "Sharadkumar",
    "fatherName": "Baburao",
    "email": "cmd@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9422171100",
    "designation": "CMD",
    "registrationNo": [
      {
        "title": {
          "value": "Wealth_Tax",
          "label": "Wealth Tax"
        },
        "_id": "6084131a13f01f158c6ea1f4",
        "number": "[N]C.C.I.T/I -14/52/2008-09"
      }
    ],
  },
],
```

```
    "shortName": "SBC",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\6084131a13f01f158c6ea1f3\
\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
  }
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.15553938938111",
  "longitude": "72.83789802024032"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.83789802024032,
    19.15553938938111
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-25",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-25",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-23",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
```

```
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Pahadi Goregaon",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "1",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
```

```
"status": true,
"name": "District",
"key": "district",
"value": "Mumbai",
"label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Goregaon (West)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Borivali",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "A-2",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Haware Gandhi Indraprastha Regency",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
```

```
"label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Road No. 4",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Motilal Nagar No. 1, New Link Road, Trikoni Maidan",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
```



```
"name": "New/Current Survey No.",
"key": "newSurveyNumber",
"value": "",
"label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "249(P) & 3",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "101",
  "label": false
},
"municipalityWardNo": {
  "status": true,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "P/South",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
}
```

```
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 104",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
```

```
"value": "rcc_Slab",
"label": "R. C. C. Slab"
},
"flooring": {
"value": "VerifiedTileFlooring",
"label": "Vitrified Tile Flooring"
},
"doors": {
"value": "Teak_Wood_Door_frame_with_Solid_flush_door",
"label": "Teak Wood Door frame with Solid flush door"
},
"windows": {
"value": "Wooden_frame_openable_widow_with_M._S._Grill",
"label": "Wooden frame openable widow with M. S. Grill"
},
"fittings": {
"value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
"label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
},
"finishing": {
"value": "Cement_Plastering",
"label": "Cement Plastering"
}
},
"general": {
"ownership": {
"value": "Proposed_Purchaser_-_Joint_Ownership",
"label": "Proposed Purchaser - Joint Ownership"
},
"populationClassList": {
"value": "MiddleClass",
"label": "Middle Class"
},
"populationGroupList": {
"value": "Urban",
"label": "Urban"
},
"townplanApprovedByList": {
"value": "MCGM",
"label": "Municipal Corporation of Greater Mumbai (MCGM)"
},
"whetherCoveredUnderAnyState": {
"value": "No",
"label": "No"
}
},
```

```
"asPerActualAgreement": {
  "north": "Road No. 2",
  "west": "Open Plot",
  "south": "Internal Road",
  "east": "Road No. 4"
},
"asPerDocumentAgreement": {
  "north": "Details not available",
  "west": "Details not available",
  "south": "Details not available",
  "east": "Details not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "asPerDocument": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As Occupancy Certificate is received may be assumed
that the construction is as per sanctioned plan. ",
"approvePlanVerified": "N. A.",
"empanelledOfApprovePlan": "N. A."
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "21",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "22370",
  "depreciatedBuildingRate": "2370"
},
"igrRate": {
  "propertyName": "Pahadi Goregaon West",
  "rate": "160470.00",
  "landRate": "76820",
```

```
"igrImage": "cases/65362464619c14402daae23e/igr_1698227646965_Image.png",
"squareMeterGuideLineRate": "160470.00",
"squareFeetGuideLineRate": "14908.00"
},
"igrFinalRate": {
  "depreciationPercentage": "86",
  "rate": "13820.00",
  "squareFeetGuideLineRate": "13820.00",
  "squareMeterGuideLineRate": "148759.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Middle_Class",
    "label": "Middle Class"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Tenant_Occupied",
    "label": "Tenant Occupied"
  },
  "monthlyRent": "Details not available",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per MCGM norms",
  "tenantName": "Mr. Soham Chhajer",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  }
}
```

```
},
"partitions": {
  "value": "6\"_Thk._Brick_Masonry",
  "label": "6\" Thk. Brick Masonery"
},
"waterTank": {
  "value": "MunicipalWaterSupply",
  "label": "Municipal Water Supply"
},
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": "Open Car Parking",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2009",
  "fullDate": "1/1/2009"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
```

```
"label": "Good"
},
"buildingSpecification": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenancelssues": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
}
```

```
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "46",
"ageOfBuilding": "14",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "6",
"flatFloorNo": "1",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "3"
},
"finalPlinthArea": {
  "areaType": "Built Up",
  "area": "820.80",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/65362464619c14402daae23e/
routeMap_1698232057515_Image.png",
    "routeLat": "19.155521",
    "routeLng": "72.837775",
    "stationName": "Ram Mandir",
    "routeDistance": "1.6"
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
}
```



```
"showLocation": {
  "latlng": true,
  "finallatlng": true
},
"locationMapImg": [
  {
    "id": "xv1xw",
    "name": "xv1xw",
    "image": "cases/65362464619c14402daae23e/
routeMap_1698232001346_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "15301080.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValue": "0",
  "finalValue": "15301080.00"
```

```
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "11343456.00",
  "selectedBuildUpValue": "820.80",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,

```

```
    "_id": "6538a9302a1baf5f34c21b85",
    "name": "externallmg_1698211614283_1698211642688_image_1.jpeg",
    "path": "cases/65362464619c14402daae23e/
externallmg_1698211614283_1698211642688_image_1.jpeg",
    "orientation": "portrait"
  }
],
"selfieWithSiteVisitImages": [
  {
    "status": false,
    "_id": "6538a9302a1baf5f34c21b70",
    "name": "externallmg_1698211712740_1698211735040_image_0.jpeg",
    "path": "cases/65362464619c14402daae23e/
externallmg_1698211712740_1698211735040_image_0.jpeg",
    "orientation": "portrait"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "6538a9302a1baf5f34c21b7b",
    "name": "externallmg_1698211782518_1698211807535_image_1.jpeg",
    "path": "cases/65362464619c14402daae23e/
externallmg_1698211782518_1698211807535_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6538a9302a1baf5f34c21b7d",
    "name": "externallmg_1698211785988_1698211807535_image_3.jpeg",
    "path": "cases/65362464619c14402daae23e/
externallmg_1698211785988_1698211807535_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6538a9302a1baf5f34c21b83",
    "name": "externallmg_1698211803268_1698211807535_image_9.jpeg",
    "path": "cases/65362464619c14402daae23e/
externallmg_1698211803268_1698211807535_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6538a9302a1baf5f34c21b81",
    "name": "externallmg_1698211793498_1698211807535_image_7.jpeg",
```

```
    "path": "cases/65362464619c14402daae23e/
externallmg_1698211793498_1698211807535_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6538a9302a1baf5f34c21b84",
    "name": "externallmg_1698211609330_1698211642688_image_0.jpeg",
    "path": "cases/65362464619c14402daae23e/
externallmg_1698211609330_1698211642688_image_0.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "6538a9302a1baf5f34c21b78",
    "name": "externallmg_1698211726649_1698211735040_image_8.jpeg",
    "path": "cases/65362464619c14402daae23e/
externallmg_1698211726649_1698211735040_image_8.jpeg",
    "orientation": "portrait"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "6538a9302a1baf5f34c21b73",
    "name": "Living Room",
    "path": "cases/65362464619c14402daae23e/
externallmg_1698211719054_1698211735040_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6538a9302a1baf5f34c21b72",
    "name": "Living Room",
    "path": "cases/65362464619c14402daae23e/
externallmg_1698211717559_1698211735040_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6538a9302a1baf5f34c21b74",
    "name": "Living Room",
    "path": "cases/65362464619c14402daae23e/
externallmg_1698211720470_1698211735040_image_4.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6538a9302a1baf5f34c21b75",
    "name": "Living Room",
    "path": "cases/65362464619c14402daae23e/
externallmg_1698211721928_1698211735040_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6538a9302a1baf5f34c21b77",
    "name": "Living Room",
    "path": "cases/65362464619c14402daae23e/
externallmg_1698211725901_1698211735040_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6538a9302a1baf5f34c21b79",
    "name": "Living Room",
    "path": "cases/65362464619c14402daae23e/
externallmg_1698211728329_1698211735040_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6538a9302a1baf5f34c21b7c",
    "name": "Living Room",
    "path": "cases/65362464619c14402daae23e/
externallmg_1698211783788_1698211807535_image_2.jpeg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "23022",
    "max": "23810"
  },
  "builtUpRateRange": {
    "min": "19185",
    "max": "19842"
  }
}
},
```

```
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
    "title": "Interior Decorations",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```



```
"status": true,
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
```

```
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "684.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86A/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentId": [],
"_id": "65362464619c14402daae23e",
"ownerName": "Mrs. Trupti Prakashchandra Vora",
"ownerPhoneNo": "8655544550",
"appAddress": "Contact Abhijeet\n8655544550",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae1256aa6d152c1801b330",
      "label": "Draft Agreement for sale"
    },
    "inputs": {
      "from": {
        "value": "Vendor",
        "label": "Vendor"
      },
      "Vendor": "Mrs. Trupti Prakashchandra Vora",
      "to": {
        "value": "Purchasers",
```

```
    "label": "Purchasers"
  },
  "Purchasers": "Mr. Vipin Kumar Indramani Upadhyay & Mrs. Vandana Vipin
Upadhyay"
},
"isHardCopy": false,
"displayStatus": true,
"id": "172327",
"path": "cases/65362464619c14402daae23e/document_1698046951123_16980469
82687_Flat_No_A_101_Indraprastha_Regency.pdf",
"fileName": "document_1698046951123_1698046982687_Flat_No_A_101_Indrapra
stha_Regency.pdf"
},
{
  "documentType": {
    "value": "60af48bf2ffdf65bcd6585fa",
    "label": "Agreement for sale"
  },
  "inputs": {
    "documentDate": "14/05/2013",
    "from": {
      "value": "Vendor",
      "label": "Vendor"
    },
    "Vendor": "Mrs. Sangita Ravi Thakur & Mr. Ravi Kishan Thakur",
    "to": {
      "value": "Purchaser",
      "label": "Purchaser"
    },
    "Purchaser": "Mrs. Trupti Prakashchandra Vora",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "4560/2013"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1698231194913_2nd_Agreement.pdf",
  "path": "cases/65362464619c14402daae23e/
document_1698231194913_2nd_Agreement.pdf",
  "id": "454203",
  "uploadedBy": "60eebe33f3dd69653a5837ae",
  "createdAt": "Wed Oct 25 2023 16:23:15 GMT+0530 (India Standard Time)"
},
{
```

```
"documentType": {
  "value": "60ae124baa6d152c1801b2fd",
  "label": "Occupancy Certificate"
},
"inputs": {
  "documentDate": "30/07/2009",
  "nameOfApprovingAuthority": {
    "value": "Municipal_Corporation_of_Greater_Mumbai",
    "label": "Municipal Corporation of Greater Mumbai"
  },
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "CHE / 8293 / BP (WS) / AP"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1698231265719_OC.pdf",
"path": "cases/65362464619c14402daae23e/document_1698231265719_OC.pdf",
"id": "273424",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Wed Oct 25 2023 16:24:26 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "004591",
"createdBy": "62727444afd7d55eddee092c",
"caseHistory": [
  {
    "id": "486094",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Oct 23 2023 13:14:36 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mrs. Trupti Prakashchandra Vora",
    "phone": "8655544550",
    "ownershipShare": "",
    "email": "",
    "id": "367404"
  }
],
"proposePurchasers": [
  {
```

```
"name": "Mr. Vipin Kumar Indramani Upadhyay & Mrs. Vandana Vipin Upadhyay",
"phone": "",
"ownershipShare": "",
"email": ""
}
],
"siteInspection": [],
"composition": [
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "139962",
  "name": "Living Room",
  "length": "22.33",
  "length1": "22",
  "length2": "4",
  "width": "9.08",
  "width1": "9",
  "width2": "1",
  "totalArea": "202.86",
  "images": [],
  "extraAreas": [],
  "finalArea": "202.86"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Dining",
  "length": "8.17",
  "length1": "8",
  "length2": "2",
  "width": "10.50",
  "width1": "10",
  "width2": "6",
  "totalArea": "85.75",
  "images": [],
  "extraAreas": [],
  "finalArea": "85.75"
},
{
  "measurementType": {
```

```
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Kitchen",
  "length": "14.50",
  "length1": "14",
  "length2": "6",
  "width": "6.58",
  "width1": "6",
  "width2": "7",
  "totalArea": "95.46",
  "images": [],
  "extraAreas": [],
  "finalArea": "95.46"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Passage",
  "length": "5.67",
  "length1": "5",
  "length2": "8",
  "width": "3.08",
  "width1": "3",
  "width2": "1",
  "totalArea": "17.47",
  "images": [],
  "extraAreas": [],
  "finalArea": "17.47"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "5.33",
  "length1": "5",
  "length2": "4",
  "width": "3.67",
  "width1": "3",
```

```
"width2": "8",
"totalArea": "19.56",
"images": [],
"extraAreas": [],
"finalArea": "19.56"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bedroom",
  "length": "15.75",
  "length1": "15",
  "length2": "9",
  "width": "8.75",
  "width1": "8",
  "width2": "9",
  "totalArea": "137.81",
  "images": [],
  "extraAreas": [],
  "finalArea": "137.81"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Bedroom",
  "length": "14.67",
  "length1": "14",
  "length2": "8",
  "width": "8.42",
  "width1": "8",
  "width2": "5",
  "totalArea": "123.44",
  "images": [],
  "extraAreas": [
    {
      "measurementType": {
        "value": "Square_Feet",
        "label": "Square Feet"
      },
      "_id": "6538f2912a1baf5f34c32bf7",
```

```
    "name": "Extra passage",
    "extraAreaType": "Add",
    "length": "3.25",
    "length1": "3",
    "length2": "3",
    "width": "3.08",
    "width1": "3",
    "width2": "1",
    "totalArea": "10.02"
  }
],
"finalArea": "133.46"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Toilet",
  "length": "3.75",
  "length1": "3",
  "length2": "9",
  "width": "8.75",
  "width1": "8",
  "width2": "9",
  "totalArea": "32.81",
  "images": [],
  "extraAreas": [],
  "finalArea": "32.81"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60ae1256aa6d152c1801b330",
      "label": "Draft Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "977665",
    "selectAreaTypeDocument": "Carpet",
```



```
"totalAreaDocument": "684",
"squareMeterArea": "63.55",
"docFinalBuiltUp": "820.8",
"docFinalBuiltUpSquareMeter": "76.25999999999999",
"docBuiltupPercentage": "20",
"docSaleablePercentage": "0",
"docFinalSaleable": "0",
"docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "6538e5d92a1baf5f34c30a03",
  "property": "Indraprastha Regency, Goregaon West",
  "area": "630",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "Middle",
  "source": "Nobroker.com",
  "expectedPrice": "15000000",
  "expectedRate": "23809.52",
  "builtUpExpectedRate": "19841.27",
  "image": "cases/65362464619c14402daae23e/
indicator_1698227318433_Image.png",
  "squareMeter": "58.53",
  "id": "248720"
},
{
  "printlnReport": true,
  "_id": "6538e5d92a1baf5f34c30a04",
  "property": "Indraprastha Regency, Goregaon West",
  "area": "470",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "Middle",
  "source": "Nobroker.com",
  "expectedPrice": "11000000",
  "expectedRate": "23404.26",
  "builtUpExpectedRate": "19503.55",
  "image": "cases/65362464619c14402daae23e/
indicator_1698227402848_Image.png",
```

```
"squareMeter": "43.66",
"id": "894628"
},
{
  "printlnReport": true,
  "_id": "6538e5d92a1baf5f34c30a05",
  "property": "Indraprastha Regency, Goregaon West",
  "area": "695",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "4",
  "source": "magic_bricks",
  "expectedPrice": "16000000",
  "expectedRate": "23021.58",
  "builtUpExpectedRate": "19184.65",
  "image": "cases/65362464619c14402daae23e/
indicator_1698227469254_Image.png",
  "squareMeter": "64.57",
  "id": "234126"
},
{
  "printlnReport": true,
  "_id": "6538e5d92a1baf5f34c30a06",
  "property": "Indraprastha Regency, Goregaon West",
  "area": "700",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "3",
  "source": "https://www.99acres.com/",
  "expectedPrice": "16500000",
  "expectedRate": "23571.43",
  "builtUpExpectedRate": "19642.86",
  "image": "cases/65362464619c14402daae23e/
indicator_1698227529024_Image.png",
  "squareMeter": "65.03",
  "id": "199718"
}
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,

```

```
    "_id": "6538a9302a1baf5f34c21b70",
    "name": "externallmg_1698211712740_1698211735040_image_0.jpeg",
    "path": "cases/65362464619c14402daae23e/
externallmg_1698211712740_1698211735040_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6538a9302a1baf5f34c21b71",
    "name": "externallmg_1698211716529_1698211735040_image_1.jpeg",
    "path": "cases/65362464619c14402daae23e/
externallmg_1698211716529_1698211735040_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6538a9302a1baf5f34c21b72",
    "name": "externallmg_1698211717559_1698211735040_image_2.jpeg",
    "path": "cases/65362464619c14402daae23e/
externallmg_1698211717559_1698211735040_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6538a9302a1baf5f34c21b73",
    "name": "externallmg_1698211719054_1698211735040_image_3.jpeg",
    "path": "cases/65362464619c14402daae23e/
externallmg_1698211719054_1698211735040_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6538a9302a1baf5f34c21b74",
    "name": "externallmg_1698211720470_1698211735040_image_4.jpeg",
    "path": "cases/65362464619c14402daae23e/
externallmg_1698211720470_1698211735040_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6538a9302a1baf5f34c21b75",
```

```
    "name": "externallmg_1698211721928_1698211735040_image_5.jpeg",
    "path": "cases/65362464619c14402daae23e/
externallmg_1698211721928_1698211735040_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6538a9302a1baf5f34c21b76",
    "name": "externallmg_1698211725882_1698211735040_image_6.jpeg",
    "path": "cases/65362464619c14402daae23e/
externallmg_1698211725882_1698211735040_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6538a9302a1baf5f34c21b77",
    "name": "externallmg_1698211725901_1698211735040_image_7.jpeg",
    "path": "cases/65362464619c14402daae23e/
externallmg_1698211725901_1698211735040_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6538a9302a1baf5f34c21b78",
    "name": "externallmg_1698211726649_1698211735040_image_8.jpeg",
    "path": "cases/65362464619c14402daae23e/
externallmg_1698211726649_1698211735040_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6538a9302a1baf5f34c21b79",
    "name": "externallmg_1698211728329_1698211735040_image_9.jpeg",
    "path": "cases/65362464619c14402daae23e/
externallmg_1698211728329_1698211735040_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6538a9302a1baf5f34c21b7a",
    "name": "externallmg_1698211780604_1698211807535_image_0.jpeg",
```

```
    "path": "cases/65362464619c14402daae23e/
externallmg_1698211780604_1698211807535_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6538a9302a1baf5f34c21b7b",
    "name": "externallmg_1698211782518_1698211807535_image_1.jpeg",
    "path": "cases/65362464619c14402daae23e/
externallmg_1698211782518_1698211807535_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6538a9302a1baf5f34c21b7c",
    "name": "externallmg_1698211783788_1698211807535_image_2.jpeg",
    "path": "cases/65362464619c14402daae23e/
externallmg_1698211783788_1698211807535_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6538a9302a1baf5f34c21b7d",
    "name": "externallmg_1698211785988_1698211807535_image_3.jpeg",
    "path": "cases/65362464619c14402daae23e/
externallmg_1698211785988_1698211807535_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6538a9302a1baf5f34c21b7e",
    "name": "externallmg_1698211787448_1698211807535_image_4.jpeg",
    "path": "cases/65362464619c14402daae23e/
externallmg_1698211787448_1698211807535_image_4.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6538a9302a1baf5f34c21b7f",
    "name": "externallmg_1698211788838_1698211807535_image_5.jpeg",
    "path": "cases/65362464619c14402daae23e/
externallmg_1698211788838_1698211807535_image_5.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6538a9302a1baf5f34c21b80",
  "name": "externallmg_1698211790201_1698211807535_image_6.jpeg",
  "path": "cases/65362464619c14402daae23e/
externallmg_1698211790201_1698211807535_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6538a9302a1baf5f34c21b81",
  "name": "externallmg_1698211793498_1698211807535_image_7.jpeg",
  "path": "cases/65362464619c14402daae23e/
externallmg_1698211793498_1698211807535_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6538a9302a1baf5f34c21b82",
  "name": "externallmg_1698211798133_1698211807535_image_8.jpeg",
  "path": "cases/65362464619c14402daae23e/
externallmg_1698211798133_1698211807535_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6538a9302a1baf5f34c21b83",
  "name": "externallmg_1698211803268_1698211807535_image_9.jpeg",
  "path": "cases/65362464619c14402daae23e/
externallmg_1698211803268_1698211807535_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6538a9302a1baf5f34c21b84",
  "name": "externallmg_1698211609330_1698211642688_image_0.jpeg",
  "path": "cases/65362464619c14402daae23e/
externallmg_1698211609330_1698211642688_image_0.jpeg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "6538a9302a1baf5f34c21b85",
      "name": "externallmg_1698211614283_1698211642688_image_1.jpeg",
      "path": "cases/65362464619c14402daae23e/
externallmg_1698211614283_1698211642688_image_1.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "6538a9302a1baf5f34c21b86",
      "name": "externallmg_1698211617370_1698211642688_image_2.jpeg",
      "path": "cases/65362464619c14402daae23e/
externallmg_1698211617370_1698211642688_image_2.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "6538a9302a1baf5f34c21b87",
      "name": "externallmg_1698211620680_1698211642688_image_3.jpeg",
      "path": "cases/65362464619c14402daae23e/
externallmg_1698211620680_1698211642688_image_3.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "6538a9302a1baf5f34c21b88",
      "name": "externallmg_1698211623880_1698211642688_image_4.jpeg",
      "path": "cases/65362464619c14402daae23e/
externallmg_1698211623880_1698211642688_image_4.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "6538a9302a1baf5f34c21b89",
      "name": "externallmg_1698211626026_1698211642688_image_5.jpeg",
      "path": "cases/65362464619c14402daae23e/
externallmg_1698211626026_1698211642688_image_5.jpeg",
      "orientation": "landscape"
    },
  },
}
```

```
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6538a9302a1baf5f34c21b8a",
  "name": "externallmg_1698211627435_1698211642688_image_6.jpeg",
  "path": "cases/65362464619c14402daae23e/
externallmg_1698211627435_1698211642688_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6538a9302a1baf5f34c21b8b",
  "name": "externallmg_1698211628635_1698211642688_image_7.jpeg",
  "path": "cases/65362464619c14402daae23e/
externallmg_1698211628635_1698211642688_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6538a9302a1baf5f34c21b8c",
  "name": "externallmg_1698211632349_1698211642688_image_8.jpeg",
  "path": "cases/65362464619c14402daae23e/
externallmg_1698211632349_1698211642688_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6538a9302a1baf5f34c21b8d",
  "name": "externallmg_1698212064505_1698212099584_image_0.jpeg",
  "path": "cases/65362464619c14402daae23e/
externallmg_1698212064505_1698212099584_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6538a9302a1baf5f34c21b8e",
  "name": "externallmg_1698212066180_1698212099584_image_1.jpeg",
  "path": "cases/65362464619c14402daae23e/
externallmg_1698212066180_1698212099584_image_1.jpeg",
  "orientation": "portrait"
},
{
```



```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6538a9302a1baf5f34c21b8f",
    "name": "externallmg_1698212120544_1698212155562_image_0.jpeg",
    "path": "cases/65362464619c14402daae23e/
externallmg_1698212120544_1698212155562_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6538a9302a1baf5f34c21b90",
    "name": "externallmg_1698212121794_1698212155562_image_1.jpeg",
    "path": "cases/65362464619c14402daae23e/
externallmg_1698212121794_1698212155562_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6538b4282a1baf5f34c253ae",
    "name":
"externallmg_1698214951740_WhatsApp_Image_20231025_at_114931_AM.jpeg",
    "path": "cases/65362464619c14402daae23e/
externallmg_1698214951740_WhatsApp_Image_20231025_at_114931_AM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname":
"1697696061713_1696590611268_1696506280505_Calculation.xlsx",
    "filename": "1698223707867_1697696061713_1696590611268_1696506280505_C
alculation.xlsx",
    "path": "cases/65362464619c14402daae23e/processingDocuments/169822370786
7_1697696061713_1696590611268_1696506280505_Calculation.xlsx",
    "size": "3310859",
    "createdAt": "Wed Oct 25 2023 14:18:27 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  }
],
"remarks": [],
"createdAt": "2023-10-23T07:44:36.971Z",
"updatedAt": "2023-10-25T12:15:04.657Z",
"__v": 0,
```

```
"invoiceId": "65362467619c14402daae263",
"fullAddress": "Residential Flat No. 101, 1st Floor, Wing - A, Haware Gandhi
Indraprastha Regency, Plot No. A-2, Road No. 4, Motilal Nagar No. 1, New Link Road,
Trikoni Maidan, Village - Pahadi Goregaon, Municipality Ward No. P/South, Taluka -
Borivali, District - Mumbai, Goregaon (West), PIN - 400 104, State - Maharashtra, India",
"updatedBy": "60f915d3f3dd69653a592199",
"addressForMap": "",
"caseReferredBy": "62727444afd7d55eddee092c",
"contactPersonName": "Mr. Abhijeet Tripathi ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner's Representative",
"siteVisitContactNo": "8655544550",
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"buildingServicesRate": "3000",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Draft Agreement for sale",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 684.00",
"flatRate": "23000",
"landOtherRate": "20000",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + Dining + Passage + 2
Toilet",
"carpetTotal": "725.18",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "797.70",
"finalCarpetArea": "725.18",
"finalSalableArea": "877.47",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
```

```

    },
    "leaseDetails": {
      "lessorName": "",
      "lesseeName": "",
      "leasePremium": "",
      "leaseRent": "",
      "leasePeriod": 0,
      "leaseFrom": "",
      "leaseTo": "",
      "remainingLeasePeriod": 0,
      "leaseDate": ""
    }
  },
  "reportGeneratedDate": "Wed Oct 25 2023 16:01:30 GMT+0530 (India Standard Time)",
  "siteVisitDate": "2023-10-23"
}

```

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
Composition :			
Living Room	22'4"	9'1"	202.86
Dining	8'2"	10'6"	85.75
Kitchen	14'6"	6'7"	95.46
Passage	5'8"	3'1"	17.47
Toilet	5'4"	3'8"	19.56
Bedroom	15'9"	8'9"	137.81
Bedroom	14'8"	8'5"	123.44
Toilet	3'9"	8'9"	32.81
Other Composition :			