

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7f7"
    },
    "type": "CREDITOFFICER",
    "_id": "63fd9434ce84bf289baab0e9",
    "firstName": "Sharmila",
    "lastName": "Mahto",
    "mobileNo": "",
    "workMobileNo": "9521405151",
    "email": "sharmila.mahto@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "6418456a96b58848585f8cb2",
"name": "Thane",
"email": "thane@vastukala.com",
"phone": "1234567890",
"address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
"city": "Thane",
"shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7f7",
  "branchCode": "000064",
  "type": "BRANCH",
  "name": "RACPC Ghatkopar (West)",
  "email": "racpcghatkopar.sanctions@sbi.co.in",
  "mobileNo": "022-25009143",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, 1st Floor, Ashok Silk Mills
Compound, LBS Marg, Ghatkopar (West), Mumbai - 400 086, State - Maharashtra,
Country - India.\r\n\r\n\r\n\r\n",
  "ledgerName": "STATE BANK OF INDIA - RACPC GHATKOPAR",
  "fax": "022-25009010",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "64abdb2806d6ec174986d16b",
  "role": "PICKUPPERSON",
  "firstName": "Sahadu",
  "email": "thoratsahadu8679@gmail.com",
  "lastName": "Thorat",
  "mobileNo": "9422389642",
  "shortName": "ST",
  "workWithDocumentMaker": ""
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "64e5a649daae6a1c98101989",
  "role": "SITEENGINEER",
  "firstName": "Sameer",
  "email": "sameeryp2010@gmail.com",
  "lastName": "Parab",
  "mobileNo": "8291009567",
  "designation": "Site Engineer",
  "shortName": "Sameer",
  "workWithDocumentMaker": "62ea09ea4e679b264caf07d7"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "MAKER",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
  "mobileNo": "9821518537",
  "designation": ""
}
```

```
"shortName": "PS",
"workWithDocumentMaker": "",
"profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": "",
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
"value": "FIIV",
"label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
"title": {
"value": "Chartered_Engineer",
"label": "Chartered Engineer"
},
"_id": "60af80072ffdf65bcd658653",
"number": "AM161706-3"
},
},
```

```
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
},
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.25735873758172",
  "longitude": "73.13483137889641"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-25",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-25",
      "remark": ""
    }
  ]
}
```

```
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Chikanghar",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "3",
    "label": false
  },
  "buildingNo": {
    "status": true,
```

```
"name": "Building No",
"key": "buildingNo",
"value": "3",
"label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Kalyan (West)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kalyan",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Rohini",
  "label": false
}
```

```
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Birla college Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Shankeshwar Krupa Building No. 3 Co-OP. Hsg. Soc. Ltd.",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
```



```
"key": "oldSurveyNumber",
"value": "",
"label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "5, Hissa No. 4Part",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "A/303",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
}
```

```
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 421 301",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
```

```
"value": "",
"label": false
}
},
"flatSpecifications": {
"roof": {
"value": "rcc_Slab",
"label": "R. C. C. Slab"
},
"flooring": {
"value": "VerifiedTileFlooring",
"label": "Vitrified Tile Flooring"
},
"doors": {
"value": "Teak_Wood_Door_frame_with_Solid_flush_door_with_M.S_Safety_door",
"label": "Teak Wood Door frame with Solid flush door with M.S Safety door"
},
"windows": {
"value": "Aluminium_Sliding_Windows_with_window_grills",
"label": "Aluminium Sliding Windows with window grills"
},
"fittings": {
"value": "Open-Conduit_plumbing_with_Casing_Capping_Electrical_wiring_",
"label": "Open-Conduit plumbing with Casing Capping Electrical wiring "
},
"finishing": {
"value": "Cement_Plastering_+_POP_Finish",
"label": "Cement Plastering + POP Finish"
}
},
"general": {
"ownership": {
"value": "Joint_Ownership",
"label": "Joint Ownership"
},
"populationClassList": {
"value": "MiddleClass",
"label": "Middle Class"
},
"populationGroupList": {
"value": "Urban",
"label": "Urban"
},
"townplanApprovedByList": {
"value": "Kalyan_Dombivali_Municipal_Corporation",
"label": "Kalyan Dombivali Municipal Corporation"
}
```

```
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Bhiwandi Road",
  "west": "Parking Area",
  "south": "Open Plot",
  "east": "Anuradha Apartment"
},
"asPerDocumentAgreement": {
  "north": "Details not available",
  "west": "Details not available",
  "south": "Details not available",
  "east": "Details not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "asPerDocument": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As Part Occupancy Certificate is received may be assumed that the construction is as per sanctioned plan.",
"approvePlanVerified": "",
"empanelledOfApprovePlan": ""
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "27",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "6525",
  "depreciatedBuildingRate": "1825"
```

```
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "69000",
  "landRate": "24100",
  "igrImage": "cases/653667232a1baf5f34c1871e/igr_1698298527985_Image.png",
  "squareMeterGuideLineRate": "58650.00",
  "squareFeetGuideLineRate": "5449.00"
},
"igrFinalRate": {
  "depreciationPercentage": "82",
  "rate": "4871.00",
  "squareFeetGuideLineRate": "4871.00",
  "squareMeterGuideLineRate": "52431.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Tenant_Occupied",
    "label": "Tenant Occupied"
  },
  "monthlyRent": "9000.00",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per KDMC norms",
  "tenantName": "Mr. Krushna Shukla",
  "maintenanceOfFlat": "Details not available"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
}
```

```
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Open Car Parking",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2005",
    "fullDate": "1/1/2005"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  },
  "typeOfStructure": {
    "value": "R.C.C._Framed_Structure",
    "label": "R.C.C. Framed Structure"
  },
  "typeOfFoundation": {
    "value": "rcc",
    "label": "R.C.C. Foundation"
  },
  "qualityOfConstruction": {
```

```
"value": "Normal",
"label": "Normal"
},
"materialUsedList": {
"value": "Information_Not_Available",
"label": "Information Not Available"
},
"buildingSpecification": {
"value": "Standard",
"label": "Standard"
},
"structuralSafety": {
"value": "Normal",
"label": "Normal"
},
"protAgainstNatDis": {
"value": "Information_not_available",
"label": "Information not available"
},
"sewerageSystem": {
"value": "MunicipalSewerageSystem",
"label": "Connected to Municipal Sewerage System"
},
"walls": {
"value": "1",
"label": "Yes"
},
"appearanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenanceOfTheBuilding": {
"value": "Normal",
"label": "Normal"
},
"maintenanceIssues": {
"value": "Information_not_available",
"label": "Information not available"
},
"visibleDamageInBuilding": {
"value": "1",
"label": "Yes"
},
"systemOfAirConditioning": {
"value": "Information_not_available",
"label": "Information not available"
}
```

```
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "As_Per_Part_Occupancy_Certificate",
  "label": "As Per Part Occupancy Certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "18",
"totalLifeBuilding": "60",
"estimatedAge": "42",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "4",
"flatFloorNo": "3",
"noOfLifts": "",
"noOfDwellingUnitsInBuilding": "3"
},
"finalPlinthArea": {
  "areaType": "Built Up",
  "area": "540.00",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area as per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/653667232a1baf5f34c1871e/
routeMap_1698306807919_Image.png",
    "routeLat": "19.250655",
    "routeLng": "73.139751",
    "stationName": "Kalyan",
    "routeDistance": "3.2 Km"
  },
  "finalLatLng": {
    "coordinates": [
```



```
    null,
    null
  ],
  "type": "Point"
},
"showLocation": {
  "latlng": true,
  "finallatlng": true
},
"locationMapImg": [
  {
    "id": "e3s0qd",
    "name": "e3s0qd",
    "image": "cases/653667232a1baf5f34c1871e/
routeMap_1698306505801_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
```

```
"finaltotal": "3523500.00",
"finalValue": "3523500.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "2630340.00",
```

```
"selectedBuildUpValue": "540.00",
"selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "6538c4312a1baf5f34c28be8",
      "name": "externallmg_1698218955905_1698218970808_image_1.jpeg",
      "path": "cases/653667232a1baf5f34c1871e/
externallmg_1698218955905_1698218970808_image_1.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "6538c4312a1baf5f34c28bf2",
      "name": "externallmg_1698218965937_1698218970808_image_13.jpeg",
      "path": "cases/653667232a1baf5f34c1871e/
externallmg_1698218965937_1698218970808_image_13.jpeg",
      "orientation": "landscape"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "6538c4312a1baf5f34c28bee",
      "name": "externallmg_1698218963634_1698218970808_image_7.jpeg",
      "path": "cases/653667232a1baf5f34c1871e/
externallmg_1698218963634_1698218970808_image_7.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "6538c4312a1baf5f34c28bed",
      "name": "externallmg_1698218963603_1698218970808_image_6.jpeg",
      "path": "cases/653667232a1baf5f34c1871e/
externallmg_1698218963603_1698218970808_image_6.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "6538c4312a1baf5f34c28be8",
      "name": "externallmg_1698218955905_1698218970808_image_1.jpeg",
      "path": "cases/653667232a1baf5f34c1871e/
externallmg_1698218955905_1698218970808_image_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6538c4312a1baf5f34c28be7",
    "name": "externallmg_1698218955495_1698218970808_image_0.jpeg",
    "path": "cases/653667232a1baf5f34c1871e/
externallmg_1698218955495_1698218970808_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6538c4312a1baf5f34c28bec",
    "name": "externallmg_1698218959483_1698218970808_image_5.jpeg",
    "path": "cases/653667232a1baf5f34c1871e/
externallmg_1698218959483_1698218970808_image_5.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "6538c4312a1baf5f34c28bf3",
    "name": "Living Room",
    "path": "cases/653667232a1baf5f34c1871e/
externallmg_1698218967799_1698218970808_image_14.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6538c4312a1baf5f34c28bf5",
    "name": "Living Room",
    "path": "cases/653667232a1baf5f34c1871e/
externallmg_1698219048274_1698219082641_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6538c4312a1baf5f34c28bef",
    "name": "Bedroom",
    "path": "cases/653667232a1baf5f34c1871e/
externallmg_1698218963651_1698218970808_image_8.jpeg",
    "orientation": "portrait"
  },
]
```

```
{
  "status": false,
  "_id": "6538c4312a1baf5f34c28bf1",
  "name": "Kitchen",
  "path": "cases/653667232a1baf5f34c1871e/
externallmg_1698218964227_1698218970808_image_11.jpeg",
  "orientation": "portrait"
}
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "6111",
    "max": "11395"
  },
  "builtUpRateRange": {
    "min": "6112",
    "max": "9497"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
```

```
"title": "Kitchen arrangements",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```



```
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "true",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "540.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
```

```
"paymentId": [],
"_id": "653667232a1baf5f34c1871e",
"ownerName": "Mr. Sameer Ravikant Sawant & Mrs. Jayashree Ravikant Sawant",
"ownerPhoneNo": "9967812391",
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "9970473032",
"contactPersonName": "Mrs. Sadhana Shukla",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "Mr. Sameer Ravikant Sawant & Mrs. Jayashree Ravikant Sawant",
    "phone": "9967812391",
    "ownershipShare": "",
    "email": "",
    "id": "956704"
  }
],
"caseReferredBy": "64abdb2806d6ec174986d16b",
"relationWithOwner": "Tenant's wife",
"fullAddress": "Residential Flat No. A/303, 3rd Floor, Building No 3, Rohini,
Shankeshwar Krupa Building No. 3 Co-OP. Hsg. Soc. Ltd., Birla college Road, Village -
Chikanghar, Taluka - Kalyan, District - Thane, Kalyan (West), PIN Code - 421 301,
State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "02/05/2018",
      "from": {
        "value": "Transferor",
        "label": "Transferor"
      },
      "Transferor": "Mr. Niteen Shivaji Sapkal",
      "to": {
        "value": "transferee",
        "label": "transferee"
      },
      "transferee": "Mr. Sameer Ravikant Sawant & Mrs. Jayashree Ravikant Sawant",
      "number": {
        "value": "No",
        "label": "No"
      }
    }
  }
]
```

```
    },
    "No": "5156 / 2018"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "588369",
  "path": "cases/653667232a1baf5f34c1871e/
document_1698214606134_Final__Sameer_SawantSbiMulundE_2.pdf",
  "fileName":
"document_1698214606134_Final__Sameer_SawantSbiMulundE_2.pdf"
},
{
  "documentType": {
    "value": "60ae1279aa6d152c1801b3d4",
    "label": "Amended Commencement Certificate"
  },
  "inputs": {
    "documentDate": "02/01/2004",
    "nameOfApprovingAuthority": {
      "value": "Kalyan_Dombivli_Municipal_Corporation",
      "label": "Kalyan Dombivli Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "KDMC / NRV / BP / KV / 490 - 203"
},
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1698308624298_179169.pdf",
  "path": "cases/653667232a1baf5f34c1871e/
document_1698308624298_179169.pdf",
  "id": "233052",
  "uploadedBy": "627222afafd7d55eddedd82",
  "createdAt": "Thu Oct 26 2023 13:53:44 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1250aa6d152c1801b316",
    "label": "Part Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "03/04/2005",
    "nameOfApprovingAuthority": {
      "value": "Kalyan_Dombivli_Municipal_Corporation",
```

```
    "label": "Kalyan Dombivli Municipal Corporation"
  },
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "KDMC / NRV / CC / KV / 588"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1698308787579_92027.pdf",
"path": "cases/653667232a1baf5f34c1871e/document_1698308787579_92027.pdf",
"id": "300785",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Thu Oct 26 2023 13:56:27 GMT+0530 (India Standard Time)"
}
],
"isUrgent": "false",
"isExternal": "false",
"scheduleSiteVisitDate": "Invalid date",
"caseNumber": "004613",
"createdBy": "6430f74691d7c62df11f3f15",
"caseHistory": [
  {
    "id": "674532",
    "title": "Create Case",
    "description": "Create Case",
    "datetime": "Mon Oct 23 2023 17:59:23 GMT+0530 (India Standard Time)"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "936160",
    "name": "Living Room",
    "length": "15.00",
    "length1": "15",
    "length2": "00",
    "width": "9.00",
    "width1": "9",
    "width2": "00",
```

```
"totalArea": "135.00",
"images": [],
"extraAreas": [],
"finalArea": "135.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Kitchen",
  "length": "17.00",
  "length1": "17",
  "length2": "00",
  "width": "5.00",
  "width1": "5",
  "width2": "00",
  "totalArea": "85.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "85.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Bathroom",
  "length": "3.00",
  "length1": "3",
  "length2": "0",
  "width": "7.00",
  "width1": "7",
  "width2": "0",
  "totalArea": "21.00",
  "images": [],
  "finalArea": "21.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
}
```

```
"id": "3",
"name": "WC",
"length": "2.00",
"length1": "2",
"length2": "00",
"width": "6.00",
"width1": "6",
"width2": "00",
"totalArea": "12.00",
"images": [],
"extraAreas": [],
"finalArea": "12.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Bedroom",
  "length": "10.00",
  "length1": "10",
  "length2": "00",
  "width": "10.00",
  "width1": "10",
  "width2": "00",
  "totalArea": "100.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "100.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Passage",
  "length": "2.00",
  "length1": "2",
  "length2": "00",
  "width": "11.00",
  "width1": "11",
  "width2": "00",
  "totalArea": "22.00",
  "images": [],
```

```
"extraAreas": [],
"finalArea": "22.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Passage",
  "length": "2.00",
  "length1": "2",
  "length2": "00",
  "width": "6.00",
  "width1": "6",
  "width2": "00",
  "totalArea": "12.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "12.00"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Built_Up",
    "squareMeterArea": "50.17",
    "totalAreaDocument": "540",
    "docBultupPercentage": "",
    "docFinalBuiltUp": "0.00",
    "docFinalBuiltUpSquareMeter": "0.00",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "240793"
  }
],
```

```
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "6539fac23fa06c290666e9bb",
    "property": "Flat",
    "area": "810",
    "builtUpPercentage": "0",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Built_Up",
    "floor": "3",
    "source": "Index_no.2",
    "expectedPrice": "4950000",
    "expectedRate": "6111.11",
    "builtUpExpectedRate": "0.00",
    "image": "cases/653667232a1baf5f34c1871e/
indicator_1698298146133_Image.png",
    "squareMeter": "75.25",
    "id": "747917"
  },
  {
    "printlnReport": true,
    "_id": "6539fac23fa06c290666e9bc",
    "property": "Flat",
    "area": "400",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "0",
    "source": "magic_bricks",
    "expectedPrice": "4000000",
    "expectedRate": "10000.00",
    "builtUpExpectedRate": "8333.33",
    "image": "cases/653667232a1baf5f34c1871e/
indicator_1698298205229_Image.png",
    "squareMeter": "37.16",
    "id": "557044"
  },
  {
    "printlnReport": true,
    "_id": "6539fac23fa06c290666e9bd",
    "property": "Flat",
    "area": "430",
    "builtUpPercentage": "20",
```



```
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "3",
"source": "https://www.99acres.com/",
"expectedPrice": "4900000",
"expectedRate": "11395.35",
"builtUpExpectedRate": "9496.12",
"image": "cases/653667232a1baf5f34c1871e/
indicator_1698298250502_Image.png",
"squareMeter": "39.95",
"id": "804413"
},
{
  "printlnReport": true,
  "_id": "6539fac23fa06c290666e9be",
  "property": "Flat",
  "area": "395",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "3",
  "source": "https://www.99acres.com/",
  "expectedPrice": "3900000",
  "expectedRate": "9873.42",
  "builtUpExpectedRate": "8227.85",
  "image": "cases/653667232a1baf5f34c1871e/
indicator_1698298395365_Image.png",
  "squareMeter": "36.70",
  "id": "428562"
}
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6538c4312a1baf5f34c28be7",
    "name": "externallmg_1698218955495_1698218970808_image_0.jpeg",
    "path": "cases/653667232a1baf5f34c1871e/
externallmg_1698218955495_1698218970808_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "6538c4312a1baf5f34c28be8",
    "name": "externallmg_1698218955905_1698218970808_image_1.jpeg",
    "path": "cases/653667232a1baf5f34c1871e/
externallmg_1698218955905_1698218970808_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6538c4312a1baf5f34c28be9",
    "name": "externallmg_1698218956603_1698218970808_image_2.jpeg",
    "path": "cases/653667232a1baf5f34c1871e/
externallmg_1698218956603_1698218970808_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6538c4312a1baf5f34c28bea",
    "name": "externallmg_1698218957520_1698218970808_image_3.jpeg",
    "path": "cases/653667232a1baf5f34c1871e/
externallmg_1698218957520_1698218970808_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6538c4312a1baf5f34c28beb",
    "name": "externallmg_1698218958240_1698218970808_image_4.jpeg",
    "path": "cases/653667232a1baf5f34c1871e/
externallmg_1698218958240_1698218970808_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6538c4312a1baf5f34c28bec",
    "name": "externallmg_1698218959483_1698218970808_image_5.jpeg",
    "path": "cases/653667232a1baf5f34c1871e/
externallmg_1698218959483_1698218970808_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6538c4312a1baf5f34c28bed",
```

```
    "name": "externallmg_1698218963603_1698218970808_image_6.jpeg",
    "path": "cases/653667232a1baf5f34c1871e/
externallmg_1698218963603_1698218970808_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6538c4312a1baf5f34c28bee",
    "name": "externallmg_1698218963634_1698218970808_image_7.jpeg",
    "path": "cases/653667232a1baf5f34c1871e/
externallmg_1698218963634_1698218970808_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6538c4312a1baf5f34c28bef",
    "name": "externallmg_1698218963651_1698218970808_image_8.jpeg",
    "path": "cases/653667232a1baf5f34c1871e/
externallmg_1698218963651_1698218970808_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6538c4312a1baf5f34c28bf0",
    "name": "externallmg_1698218963774_1698218970808_image_10.jpeg",
    "path": "cases/653667232a1baf5f34c1871e/
externallmg_1698218963774_1698218970808_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6538c4312a1baf5f34c28bf1",
    "name": "externallmg_1698218964227_1698218970808_image_11.jpeg",
    "path": "cases/653667232a1baf5f34c1871e/
externallmg_1698218964227_1698218970808_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6538c4312a1baf5f34c28bf2",
    "name": "externallmg_1698218965937_1698218970808_image_13.jpeg",
```

```
    "path": "cases/653667232a1baf5f34c1871e/
externallmg_1698218965937_1698218970808_image_13.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6538c4312a1baf5f34c28bf3",
    "name": "externallmg_1698218967799_1698218970808_image_14.jpeg",
    "path": "cases/653667232a1baf5f34c1871e/
externallmg_1698218967799_1698218970808_image_14.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6538c4312a1baf5f34c28bf4",
    "name": "externallmg_1698218969466_1698218970808_image_17.jpeg",
    "path": "cases/653667232a1baf5f34c1871e/
externallmg_1698218969466_1698218970808_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6538c4312a1baf5f34c28bf5",
    "name": "externallmg_1698219048274_1698219082641_image_1.jpeg",
    "path": "cases/653667232a1baf5f34c1871e/
externallmg_1698219048274_1698219082641_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6538c4312a1baf5f34c28bf6",
    "name": "externallmg_1698218907281_1698218934627_image_0.jpeg",
    "path": "cases/653667232a1baf5f34c1871e/
externallmg_1698218907281_1698218934627_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6538c4312a1baf5f34c28bf7",
    "name": "externallmg_1698218907597_1698218934627_image_1.jpeg",
    "path": "cases/653667232a1baf5f34c1871e/
externallmg_1698218907597_1698218934627_image_1.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6538c4312a1baf5f34c28bf8",
  "name": "externallmg_1698218907977_1698218941978_image_0.jpeg",
  "path": "cases/653667232a1baf5f34c1871e/
externallmg_1698218907977_1698218941978_image_0.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Calculation (2)- sawant.xlsx",
    "filename": "1698298606628_Calculation_2_sawant.xlsx",
    "path": "cases/653667232a1baf5f34c1871e/
processingDocuments/1698298606628_Calculation_2_sawant.xlsx",
    "size": "16101",
    "createdAt": "Thu Oct 26 2023 11:06:46 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "igr1.pdf",
    "filename": "1698298606629_igr1.pdf",
    "path": "cases/653667232a1baf5f34c1871e/
processingDocuments/1698298606629_igr1.pdf",
    "size": "495745",
    "createdAt": "Thu Oct 26 2023 11:06:46 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "Summary - saswant.xlsx",
    "filename": "1698298606638_Summary__saswant.xlsx",
    "path": "cases/653667232a1baf5f34c1871e/
processingDocuments/1698298606638_Summary__saswant.xlsx",
    "size": "3347449",
    "createdAt": "Thu Oct 26 2023 11:06:46 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  }
],
"remarks": [],
"createdAt": "2023-10-23T12:29:23.195Z",
"updatedAt": "2023-10-26T09:23:39.945Z",
"__v": 0,
```

```
"invoiceId": "653667232a1baf5f34c18730",
"addressForMap": "",
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"updatedBy": "627222afafd7d55eddedd82",
"buildingServicesRate": "2500",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 540.00",
"flatRate": "7200",
"landOtherRate": "4700",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Bathroom + WC + 2
Passage",
"carpetTotal": "387",
"otherCarpetTotal": "0.00",
"finalSaleablePercentage": "0",
"builtupPercentage": "10",
"extendOfSiteRemark": "",
"finalBuiltupArea": "425.70",
"finalCarpetArea": "387.00",
"finalSalableArea": "468.27",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
  "leaseFrom": "",
  "leaseTo": "",
  "remainingLeasePeriod": 0,
  "leaseDate": ""
}
},
```

```

"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"siteVisitDate": "2023-10-25"
}

```

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
Composition :			
Living Room	15'00"	9'00"	135.00
Kitchen	17'00"	5'00"	85.00
Bathroom	3'0"	7'0"	21.00
WC	2'00"	6'00"	12.00
Bedroom	10'00"	10'00"	100.00
Passage	2'00"	11'00"	22.00
Passage	2'00"	6'00"	12.00
Other Composition :			