

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": true,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6273b00bafd7d55eddee5f69"
    },
    "type": "CREDITOFFICER",
    "_id": "6363aa704d42487767aeaf99",
    "firstName": "SUNIL BHOSALE",
    "lastName": "BHOSALE",
    "mobileNo": "9004074579",
    "email": "sunil.bhosale@sbi.co.in",
    "workMobileNo": "9004074579"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "00",
    "discussWithPerson": "SUNIL BHOSALE",
    "expectedFees": null,
    "quotedAmount": "2500"
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6273b00bafd7d55eddee5f69",
  "name": "SPL PBB Fort",
  "branchCode": "4205 ",
  "mobileNo": "02223662641",
  "alternateMobileNo": "",
  "email": "sbi.04205@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Mumbai Main Branch Building, Gate no 1 Horniman Circle Mumbai
samachar marg Fort."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af3d172ffdf65bcd6585cd",
```

```
"role": "PICKUPPERSON",
"firstName": "Sachin",
"email": "sachin.joshi@vastukala.org",
"lastName": "Joshi",
"mobileNo": "9167204063",
"shortName": "SJ",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60af3d172ffdf65bcd6585cd\
\profilePhoto_1622372567671_Sachin Joshi Photo 3 (2).jpg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "648fcad91b499c2d52dc86f3",
"role": "SITEENGINEER",
"firstName": "Barkat",
"email": "barkathodekar68@gmail.com",
"lastName": "Hodekar",
"mobileNo": "8879011615",
"designation": "Site Engg",
"shortName": "Barkat",
"workWithDocumentMaker": "",
"profilePhoto": "users/648fcad91b499c2d52dc86f3/
profilePhoto_1687758876977_image.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60eeaeddf3dd69653a581316",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Shyam",
"email": "shyam@vastukala.org",
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shyam_Photo.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "60eebe33f3dd69653a5837ae",
"role": "MAKER",
"firstName": "Shamal",
"email": "shamal@vastukala.org",
"lastName": "Bodke",
"mobileNo": "9821740317",
```

```
"designation": "",
"shortName": "SB",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eebe33f3dd69653a5837ae\
\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "60eeaeddf3dd69653a581316",
"role": "MAKER + RATE VERIFIER + CHEAKER",
"firstName": "Shyam",
"email": "shyam@vastukala.org",
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "[N]C.C.I.T/I -14/52/2008-09",
"label": "Wealth Tax"
}
],
"type": "EMPLOYEE",
"_id": "6084131a13f01f158c6ea1f3",
"PANNo": "AEAPC7114Q",
"role": "VALUER",
"firstName": "Sharadkumar",
"fatherName": "Baburao",
"email": "cmd@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9422171100",
"designation": "CMD",
"registrationNo": [
{
"title": {
"value": "Wealth_Tax",
"label": "Wealth Tax"
}
},
"_id": "6084131a13f01f158c6ea1f4",
"number": "[N]C.C.I.T/I -14/52/2008-09"
```

```
    }
  ],
  "shortName": "SBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.061057584976005",
  "longitude": "72.88294850189432"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.88294850189432,
    19.061057584976005
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-26",
      "remark": ""
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
}
```

```
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Kurla - 3",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "3",
    "label": false
  },
  "buildingNo": {
    "status": true,
    "name": "Building No",
    "key": "buildingNo",
    "value": "67",
    "label": true
  },
  "district": {
    "status": false,
    "name": "District",
    "key": "district",
    "value": "",
    "label": true
  },
  "city": {
    "status": true,
```

```
"name": "City",
"key": "city",
"value": "Kurla (East)",
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Nehru Nagar Sagar Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
}
```

```
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Nehru Nagar, MHADA Colony",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "229 & 267",
  "label": true
},
"hisssaNo": {
  "status": false,
  "name": "Hissa No.",
```



```
"key": "hissaNo",
"value": "",
"label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "12(P)",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "301",
  "label": false
},
"municipalityWardNo": {
  "status": true,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "L",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
}
```

```
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 24",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
```

```
"value": "Teak_Wood_Door_frame_with_Solid_flush_door",
"label": "Teak Wood Door frame with Solid flush door"
},
"windows": {
"value": "Powder_coated_Aluminum_sliding_windows",
"label": "Powder coated Aluminum sliding windows"
},
"fixtures": {
"value":
"Concealed_plumbing_with_C.P._fixtures._Electrical_wiring_with_concealed_",
"label": "Concealed plumbing with C.P. fixtures. Electrical wiring with concealed "
},
"finishing": {
"value": "Cement_Plastering",
"label": "Cement Plastering"
}
},
"general": {
"ownership": {
"value": "Proposed_Purchaser_-_Joint_Ownership",
"label": "Proposed Purchaser - Joint Ownership"
},
"populationClassList": {
"value": "MiddleClass",
"label": "Middle Class"
},
"populationGroupList": {
"value": "Urban",
"label": "Urban"
},
"townplanApprovedByList": {
"value": "MCGM",
"label": "Municipal Corporation of Greater Mumbai (MCGM)"
},
"whetherCoveredUnderAnyState": {
"value": "No",
"label": "No"
},
"asPerActualAgreement": {
"north": "Internal Road",
"west": "Building No. 69",
"south": "Internal Road",
"east": "Building No. 65"
},
"asPerDocumentAgreement": {
"north": "12.20 Trs Road",
```

```
"west": "Building No. 69",
"south": "12.20 Ttrs Road",
"east": "Building No. 65"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "asPerDocument": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of Approved Building Plan No. CHE / ES / 1126 /
L / 337 Dated 02.03.2018 issued by Municipal Corporation of Greater Mumbai.",
"approvePlanVerified": "Yes",
"empanelledOfApprovePlan": "N. A."
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "125170",
  "landRate": "49960",
  "igrImage": "cases/653a09b2164a9341fb0258b0/igr_1698392805038_Image.png",
  "squareMeterGuideLineRate": "125170.00",
  "squareFeetGuideLineRate": "11629.00"
},
"igrFinalRate": {
  "depreciationPercentage": "0",
  "rate": "125170",
  "squareMeterGuideLineRate": "125170.00",
```

```
"squareFeetGuideLineRate": "11629.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Middle_Class",
    "label": "Middle Class"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Vacant",
    "label": "Vacant"
  },
  "monthlyRent": "25,000",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per MHADA norms",
  "tenantName": "",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\\_Thk._Brick_Masonry",
    "label": "6\\ Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  }
}
```

```
},
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": "Stilt + Open Car Parking",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2022",
  "fullDate": "1/1/2022"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
```

```
"label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_site_information",
  "label": "As per site information"
},
}
```

```
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "59",
"ageOfBuilding": "1",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "19",
"flatFloorNo": "3",
"noOfLifts": "3",
"noOfDwellingUnitsInBuilding": "6"
},
"finalPlinthArea": {
  "areaType": "Built Up",
  "area": "624.00",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/653a09b2164a9341fb0258b0/
routeMap_1698403771392_Image.png",
    "routeLat": "19.060935",
    "routeLng": "72.882976",
    "stationName": "Kurla",
    "routeDistance": "900 Mtr."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "sydabq",
      "name": "sydabq",

```



```
    "image": "cases/653a09b2164a9341fb0258b0/  
routeMap_1698403693502_Image.png"
```

```
  }
```

```
]
```

```
},
```

```
"valuation": {
```

```
  "wardrobesRate": "0",
```

```
  "totalwardrobesRate": "0",
```

```
  "wardrobesQty": "0",
```

```
  "showcasesQty": "0",
```

```
  "showcasesRate": "0",
```

```
  "totalshowcasesRate": "0",
```

```
  "kitchenArrangementsQty": "0",
```

```
  "kitchenArrangementsRate": "0",
```

```
  "totalkitchenArrangementsRate": "0",
```

```
  "superfineFinishQty": "0",
```

```
  "superfineFinishRate": "0",
```

```
  "totalsuperfineFinishRate": "0",
```

```
  "interiorDecorationsQty": "0",
```

```
  "interiorDecorationsRate": "0",
```

```
  "totalinteriorDecorationsRate": "0",
```

```
  "electricityDepositsQty": "0",
```

```
  "electricityDepositsRate": "0",
```

```
  "totalelectricityDepositsRate": "0",
```

```
  "extraCollapsibleGatesQty": "0",
```

```
  "extraCollapsibleGatesRate": "0",
```

```
  "totalextraCollapsibleGatesRate": "0",
```

```
  "potentialValueQty": "0",
```

```
  "potentialValueRate": "0",
```

```
  "totalpotentialValueRate": "0",
```

```
  "othersQty": "0",
```

```
  "othersRate": "0",
```

```
  "totalothersRate": "0",
```

```
  "finaltotal": "12012000.00",
```

```
  "distressValuePercentage": "80",
```

```
  "realizableValuePercentage": "90",
```

```
  "bookValue": "0",
```

```
  "finalValue": "12012000.00"
```

```
},
```

```
"outward": {
```

```
  "status": false,
```

```
  "remark": "SYSTEM_GENERATED"
```

```
},
```

```
"rateVerify": {
```

```
  "status": false
```

```
},
```

```
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
    "label": "External Plastering",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "7256496.00",
  "selectedBuildUpValue": "624.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "653aa8a0164a9341fb03d124",
      "name": "externalImg_1698343005133_1698343038453_image_2.jpeg",
      "path": "cases/653a09b2164a9341fb0258b0/
externalImg_1698343005133_1698343038453_image_2.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
```

```
{
  "status": false,
  "_id": "653aa8a0164a9341fb03d122",
  "name": "externallmg_1698343003670_1698343038453_image_0.jpeg",
  "path": "cases/653a09b2164a9341fb0258b0/
externallmg_1698343003670_1698343038453_image_0.jpeg",
  "orientation": "portrait"
}
],
"externalPhotos": [
  {
    "status": false,
    "_id": "653aa8a0164a9341fb03d123",
    "name": "externallmg_1698343004143_1698343038453_image_1.jpeg",
    "path": "cases/653a09b2164a9341fb0258b0/
externallmg_1698343004143_1698343038453_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "653aa8a0164a9341fb03d125",
    "name": "externallmg_1698343006305_1698343038453_image_3.jpeg",
    "path": "cases/653a09b2164a9341fb0258b0/
externallmg_1698343006305_1698343038453_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "653aa8a0164a9341fb03d129",
    "name": "externallmg_1698343008400_1698343038453_image_7.jpeg",
    "path": "cases/653a09b2164a9341fb0258b0/
externallmg_1698343008400_1698343038453_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "653aa8a0164a9341fb03d131",
    "name": "externallmg_1698343048168_1698343073234_image_7.jpeg",
    "path": "cases/653a09b2164a9341fb0258b0/
externallmg_1698343048168_1698343073234_image_7.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
```

```
{
  "status": false,
  "_id": "653aa8a0164a9341fb03d12a",
  "name": "Living Room",
  "path": "cases/653a09b2164a9341fb0258b0/
externallmg_1698343045792_1698343073234_image_0.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "653aa8a0164a9341fb03d12b",
  "name": "Living Room",
  "path": "cases/653a09b2164a9341fb0258b0/
externallmg_1698343046107_1698343073234_image_1.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "653aa8a0164a9341fb03d12c",
  "name": "Living Room",
  "path": "cases/653a09b2164a9341fb0258b0/
externallmg_1698343046345_1698343073234_image_2.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "653aa8a0164a9341fb03d12f",
  "name": "Living Room",
  "path": "cases/653a09b2164a9341fb0258b0/
externallmg_1698343047380_1698343073234_image_5.jpeg",
  "orientation": "portrait"
}
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "19059",
    "max": "24167"
  },
  "builtUpRateRange": {
    "min": "15883",
    "max": "20139"
  }
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
```

```
"title": "Present value of the flat (incl. car parking, if provided)",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
```



```
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "520.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86A/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentId": [],
"_id": "653a09b2164a9341fb0258b0",
"ownerName": "Mr. Ashutosh Anandkumar Samarth",
"ownerPhoneNo": "9029369160",
"appAddress": "Flat no 301,3floor,Building No 67,Nehru Nagar Sagar CHS,Nehru
Nagar Kurla East ",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f9",
      "label": "Memorandum of Understanding"
    },
    "inputs": {
      "from": {
        "value": "Vendor",
        "label": "Vendor"
      },
      "Vendor": "Mr. Ashutosh Anandkumar Samarth",
      "to": {
        "value": "Purchasers",
        "label": "Purchasers"
      }
    }
  }
]
```

```
    },
    "Purchasers": "Mr. Vimal Chandra Prakash Jain & Mrs. Riya Vimal Jain"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1698402183056_document_1698303404032_VIMAL_JAIN_
DRAFT_AGREEMENT.pdf",
  "path": "cases/653a09b2164a9341fb0258b0/document_1698402183056_document
_1698303404032_VIMAL_JAIN_DRAFT_AGREEMENT.pdf",
  "id": "254783",
  "uploadedBy": "60eebe33f3dd69653a5837ae",
  "createdAt": "Fri Oct 27 2023 15:53:04 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1260aa6d152c1801b35e",
    "label": "Agreement of Permanent Alternate Accommodation"
  },
  "inputs": {
    "documentDate": "20/08/2023",
    "from": {
      "value": "Developers",
      "label": "Developers"
    },
    "Developers": "Mr. Vimal Chandra Prakash Jain & Mrs. Riya Vimal Jain",
    "to": {
      "value": "Member",
      "label": "Member"
    },
    "Member": "Mr. Ashutosh Anandkumar Samarth"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1698402255213_document_1698303415204_VIMAL_JAIN_
AGREEMENT.pdf",
  "path": "cases/653a09b2164a9341fb0258b0/document_1698402255213_document
_1698303415204_VIMAL_JAIN_AGREEMENT.pdf",
  "id": "201266",
  "uploadedBy": "60eebe33f3dd69653a5837ae",
  "createdAt": "Fri Oct 27 2023 15:54:15 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
}
```

```
"inputs": {
  "documentDate": "21/09/2018",
  "nameOfApprovingAuthority": {
    "value": "Maharashtra_Housing_And_Area_Development_Authority",
    "label": "Maharashtra Housing And Area Development Authority"
  },
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "MH / EE / (B.P.) / GM / MHADA - 22 / 043 / 2018"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1698402510055_CC.pdf",
"path": "cases/653a09b2164a9341fb0258b0/document_1698402510055_CC.pdf",
"id": "618332",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Fri Oct 27 2023 15:58:30 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1248aa6d152c1801b2ef",
    "label": "Society Share Certificate"
  },
  "inputs": {
    "documentDate": "12/01/2017",
    "to": {
      "value": "Member",
      "label": "Member"
    },
    "Member": "Mr. Ashutosh Anandkumar Samarth",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "11"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1698402752441_Share_certi.pdf",
  "path": "cases/653a09b2164a9341fb0258b0/
document_1698402752441_Share_certi.pdf",
  "id": "872656",
  "uploadedBy": "60eebe33f3dd69653a5837ae",
  "createdAt": "Fri Oct 27 2023 16:02:32 GMT+0530 (India Standard Time)"
}
```

```
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "02/03/2018",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_of_Greater_Mumbai",
      "label": "Municipal Corporation of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "CHE / ES / 1126 / L / 337"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1698402894139_Drawing.pdf",
  "path": "cases/653a09b2164a9341fb0258b0/
document_1698402894139_Drawing.pdf",
  "id": "539335",
  "uploadedBy": "60eebe33f3dd69653a5837ae",
  "createdAt": "Fri Oct 27 2023 16:04:54 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "004661",
"createdBy": "60af3d172ffdf65bcd6585cd",
"caseHistory": [
  {
    "id": "598848",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Oct 26 2023 12:09:46 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Ashutosh Anandkumar Samarth",
    "phone": "9029369160",
    "ownershipShare": "",
    "email": "",
    "id": "797582"
  }
]
```

```
],
"proposePurchasers": [
  {
    "name": "Mr. Vimal Chandra Prakash Jain & Mrs. Riya Vimal Jain",
    "phone": "",
    "ownershipShare": "",
    "email": ""
  }
],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "432097",
    "name": "Living Room",
    "length": "17.17",
    "length1": "17",
    "length2": "2",
    "width": "10.17",
    "width1": "10",
    "width2": "2",
    "totalArea": "174.53",
    "images": [],
    "extraAreas": [],
    "finalArea": "174.53"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "name": "Kitchen",
    "length": "7.00",
    "length1": "7",
    "length2": "00",
    "width": "7.00",
    "width1": "7",
    "width2": "00",
    "totalArea": "49.00",
    "images": [],
    "extraAreas": [],
    "finalArea": "49.00"
  }
]
```

```
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Passage",
  "length": "12.42",
  "length1": "12",
  "length2": "5",
  "width": "3.17",
  "width1": "3",
  "width2": "2",
  "totalArea": "39.32",
  "images": [],
  "extraAreas": [],
  "finalArea": "39.32"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bedroom",
  "length": "10.00",
  "length1": "10",
  "length2": "00",
  "width": "11.00",
  "width1": "11",
  "width2": "00",
  "totalArea": "110.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "110.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "7.00",
  "length1": "7",
```

```
"length2": "00",
"width": "4.00",
"width1": "4",
"width2": "00",
"totalArea": "28.00",
"images": [],
"extraAreas": [],
"finalArea": "28.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bedroom",
  "length": "9.17",
  "length1": "9",
  "length2": "2",
  "width": "10.42",
  "width1": "10",
  "width2": "5",
  "totalArea": "95.49",
  "images": [],
  "extraAreas": [],
  "finalArea": "95.49"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Toilet",
  "length": "7.33",
  "length1": "7",
  "length2": "4",
  "width": "3.33",
  "width1": "3",
  "width2": "4",
  "totalArea": "24.44",
  "images": [],
  "extraAreas": [],
  "finalArea": "24.44"
}
],
```

```
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60ae1260aa6d152c1801b35e",
      "label": "Agreement of Permanent Alternate Accommodation"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "595032",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "520",
    "squareMeterArea": "48.31",
    "docFinalBuiltUp": "624",
    "docFinalBuiltUpSquareMeter": "57.972",
    "docBuiltupPercentage": "20",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": false,
    "_id": "653b6afac70a316a760f9cf3",
    "property": "Residential Flat",
    "area": "800",
    "builtUpPercentage": "0",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Built_Up",
    "source": "Housing.Com",
    "expectedPrice": "16000000",
    "expectedRate": "20000.00",
    "builtUpExpectedRate": "0.00",
    "image": "cases/653a09b2164a9341fb0258b0/indicator_1698392598499_Image.png",
    "squareMeter": "74.32",
    "id": "147990"
  },
  {
    "printlnReport": true,

```



```
    "_id": "653b6afac70a316a760f9cf4",
    "property": "Residential Flat",
    "area": "600",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "Nobroker.com",
    "expectedPrice": "14500000",
    "expectedRate": "24166.67",
    "builtUpExpectedRate": "20138.89",
    "image": "cases/653a09b2164a9341fb0258b0/
indicator_1698392618345_Image.png",
    "squareMeter": "55.74",
    "id": "314742"
  },
  {
    "printlnReport": true,
    "_id": "653b6afac70a316a760f9cf5",
    "property": "Residential Flat",
    "area": "850",
    "builtUpPercentage": "0",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Built_Up",
    "source": "Nobroker.com",
    "expectedPrice": "13500000",
    "expectedRate": "15882.35",
    "builtUpExpectedRate": "0.00",
    "image": "cases/653a09b2164a9341fb0258b0/
indicator_1698392764525_Image.png",
    "squareMeter": "78.97",
    "id": "700345"
  }
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653aa8a0164a9341fb03d122",
    "name": "externalImg_1698343003670_1698343038453_image_0.jpeg",
    "path": "cases/653a09b2164a9341fb0258b0/
externalImg_1698343003670_1698343038453_image_0.jpeg",
    "orientation": "portrait"
  },
  {
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653aa8a0164a9341fb03d123",
    "name": "externallmg_1698343004143_1698343038453_image_1.jpeg",
    "path": "cases/653a09b2164a9341fb0258b0/
externallmg_1698343004143_1698343038453_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653aa8a0164a9341fb03d124",
    "name": "externallmg_1698343005133_1698343038453_image_2.jpeg",
    "path": "cases/653a09b2164a9341fb0258b0/
externallmg_1698343005133_1698343038453_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653aa8a0164a9341fb03d125",
    "name": "externallmg_1698343006305_1698343038453_image_3.jpeg",
    "path": "cases/653a09b2164a9341fb0258b0/
externallmg_1698343006305_1698343038453_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653aa8a0164a9341fb03d126",
    "name": "externallmg_1698343007474_1698343038453_image_4.jpeg",
    "path": "cases/653a09b2164a9341fb0258b0/
externallmg_1698343007474_1698343038453_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653aa8a0164a9341fb03d127",
    "name": "externallmg_1698343007691_1698343038453_image_5.jpeg",
    "path": "cases/653a09b2164a9341fb0258b0/
externallmg_1698343007691_1698343038453_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "653aa8a0164a9341fb03d128",
    "name": "externallmg_1698343008060_1698343038453_image_6.jpeg",
    "path": "cases/653a09b2164a9341fb0258b0/
externallmg_1698343008060_1698343038453_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653aa8a0164a9341fb03d129",
    "name": "externallmg_1698343008400_1698343038453_image_7.jpeg",
    "path": "cases/653a09b2164a9341fb0258b0/
externallmg_1698343008400_1698343038453_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653aa8a0164a9341fb03d12a",
    "name": "externallmg_1698343045792_1698343073234_image_0.jpeg",
    "path": "cases/653a09b2164a9341fb0258b0/
externallmg_1698343045792_1698343073234_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653aa8a0164a9341fb03d12b",
    "name": "externallmg_1698343046107_1698343073234_image_1.jpeg",
    "path": "cases/653a09b2164a9341fb0258b0/
externallmg_1698343046107_1698343073234_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653aa8a0164a9341fb03d12c",
    "name": "externallmg_1698343046345_1698343073234_image_2.jpeg",
    "path": "cases/653a09b2164a9341fb0258b0/
externallmg_1698343046345_1698343073234_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "653aa8a0164a9341fb03d12d",
    "name": "externallmg_1698343046578_1698343073234_image_3.jpeg",
    "path": "cases/653a09b2164a9341fb0258b0/
externallmg_1698343046578_1698343073234_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653aa8a0164a9341fb03d12e",
    "name": "externallmg_1698343046836_1698343073234_image_4.jpeg",
    "path": "cases/653a09b2164a9341fb0258b0/
externallmg_1698343046836_1698343073234_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653aa8a0164a9341fb03d12f",
    "name": "externallmg_1698343047380_1698343073234_image_5.jpeg",
    "path": "cases/653a09b2164a9341fb0258b0/
externallmg_1698343047380_1698343073234_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653aa8a0164a9341fb03d130",
    "name": "externallmg_1698343047706_1698343073234_image_6.jpeg",
    "path": "cases/653a09b2164a9341fb0258b0/
externallmg_1698343047706_1698343073234_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653aa8a0164a9341fb03d131",
    "name": "externallmg_1698343048168_1698343073234_image_7.jpeg",
    "path": "cases/653a09b2164a9341fb0258b0/
externallmg_1698343048168_1698343073234_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653aa8a0164a9341fb03d132",
```

```
    "name": "externalImg_1698343048419_1698343073234_image_8.jpeg",
    "path": "cases/653a09b2164a9341fb0258b0/
externalImg_1698343048419_1698343073234_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653aa8a0164a9341fb03d133",
    "name": "externalImg_1698343048936_1698343073234_image_9.jpeg",
    "path": "cases/653a09b2164a9341fb0258b0/
externalImg_1698343048936_1698343073234_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "653aa8a0164a9341fb03d134",
    "name": "externalImg_1698342957922_1698342988521_image_0.jpeg",
    "path": "cases/653a09b2164a9341fb0258b0/
externalImg_1698342957922_1698342988521_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "653aa8a0164a9341fb03d135",
    "name": "externalImg_1698342957952_1698342988521_image_1.jpeg",
    "path": "cases/653a09b2164a9341fb0258b0/
externalImg_1698342957952_1698342988521_image_1.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "2126408_FurtherCC_signed.pdf",
    "filename": "1698404055233_2126408_FurtherCC_signed.pdf",
    "path": "cases/653a09b2164a9341fb0258b0/
processingDocuments/1698404055233_2126408_FurtherCC_signed.pdf",
    "size": "144850",
    "createdAt": "Fri Oct 27 2023 16:24:15 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eebe33f3dd69653a5837ae"
  },
  {
    "originalname": "document_1698302327918_112130.pdf",
```

```
"filename": "1698404055238_document_1698302327918_112130.pdf",
"path": "cases/653a09b2164a9341fb0258b0/
processingDocuments/1698404055238_document_1698302327918_112130.pdf",
"size": "113394",
"createdAt": "Fri Oct 27 2023 16:24:15 GMT+0530 (India Standard Time)",
"uploadedBy": "60eebe33f3dd69653a5837ae"
}
],
"remarks": [],
"createdAt": "2023-10-26T06:39:46.762Z",
"updatedAt": "2023-10-27T11:11:16.961Z",
"__v": 0,
"invoiceId": "653a09b4164a9341fb0258ff",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 301, 3rd Floor, Building No 67, Nehru Nagar Sagar
Co-op. Hsg. Soc. Ltd., Nehru Nagar, MHADA Colony, Village - Kurla - 3, Municipality
Ward No. 'L', Kurla (East), PIN - 400 24, State - Maharashtra, India",
"updatedBy": "60eeaeddf3dd69653a581316",
"addressForMap": "",
"caseReferredBy": "60af3d172ffdf65bcd6585cd",
"contactPersonName": "Mr. Vimal Chandra Prakash Jain",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Client",
"siteVisitContactNo": "9029369160",
"buildingServicesRate": "2700",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement of Permanent Alternate Accommodation",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 520.00",
"flatRate": "23100",
"landOtherRate": "20400",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + Passage + 2 Toilet",
"carpetTotal": "492.78",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "572.86",
"finalCarpetArea": "520.78",
```

```

"finalSalableArea": "630.14",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"siteVisitDate": "2023-10-26"
}

```

Name	Length	Width	Total
Composition :			
Living Room	17'2"	10'2"	174.53
Kitchen	7'00"	7'00"	49.00
Passage	12'5"	3'2"	39.32
Bedroom	10'00"	11'00"	110.00
Toilet	7'00"	4'00"	28.00
Bedroom	9'2"	10'5"	95.49
Toilet	7'4"	3'4"	24.44
Other Composition :			