

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "652e3ee4316e1359cebed68e"
    },
    "type": "CREDITOFFICER",
    "_id": "652e3ee4316e1359cebed690",
    "firstName": "Siddharth",
    "lastName": "Jha",
    "mobileNo": "",
    "workMobileNo": "8657798653",
    "email": "brmgr1756@mahabank.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "3520000",
    "discussWithPerson": "Siddharth",
    "expectedFees": 1760,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180e",
  "type": "BANK",
  "name": "Bank Of Maharashtra",
  "displayName": "Bank Of Maharashtra",
  "initial": "BOM",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "652e3ee4316e1359cebed68e",
  "name": "Andheri East Seepz Branch",
  "branchCode": "1756",
  "mobileNo": "0000000000",
  "alternateMobileNo": "",
  "email": "brmgr1756@mahabank.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Shop No 4 & 5, Options PrimoBuilding , Plot no 21, MIDC Andheri East
Mumbai 400093"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "63abe77f4e30460e90087d32",
  "zoneName": "Mumbai City Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af6ae22ffdf65bcd65861d",
```

```
"role": "PICKUPPERSON",
"firstName": "Sunil",
"email": "misalsunil87@gmail.com",
"lastName": "Misal",
"mobileNo": "8422982721",
"shortName": "SM",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60af6ae22ffdf65bcd65861d\
\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "648fcad91b499c2d52dc86f3",
"role": "SITEENGINEER",
"firstName": "Barkat",
"email": "barkathodekar68@gmail.com",
"lastName": "Hodekar",
"mobileNo": "8879011615",
"designation": "Site Engg",
"shortName": "Barkat",
"workWithDocumentMaker": "",
"profilePhoto": "users/648fcad91b499c2d52dc86f3/
profilePhoto_1687758876977_image.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60eeaeddf3dd69653a581316",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Shyam",
"email": "shyam@vastukala.org",
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shymam_Photo.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "60eebe33f3dd69653a5837ae",
"role": "MAKER",
"firstName": "Shamal",
"email": "shamal@vastukala.org",
"lastName": "Bodke",
"mobileNo": "9821740317",
```

```
"designation": "",
"shortName": "SB",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eebe33f3dd69653a5837ae\
\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "60eeaeddf3dd69653a581316",
"role": "MAKER + RATE VERIFIER + CHEAKER",
"firstName": "Shyam",
"email": "shyam@vastukala.org",
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "[N]C.C.I.T/I -14/52/2008-09",
"label": "Wealth Tax"
}
],
"type": "EMPLOYEE",
"_id": "6084131a13f01f158c6ea1f3",
"PANNo": "AEAPC7114Q",
"role": "VALUER",
"firstName": "Sharadkumar",
"fatherName": "Baburao",
"email": "cmd@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9422171100",
"designation": "CMD",
"registrationNo": [
{
"title": {
"value": "Wealth_Tax",
"label": "Wealth Tax"
}
},
"_id": "6084131a13f01f158c6ea1f4",
"number": "[N]C.C.I.T/I -14/52/2008-09"
```

```
    }
  ],
  "shortName": "SBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.115061276033412",
  "longitude": "72.8732716850274"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.8732716850274,
    19.115061276033412
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-28",
      "remark": ""
    }
  ]
},
"schedule": [],
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
}
```

```
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Kondivita",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "2",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
    "value": "Mumbai",
    "label": true
  },
  "city": {
    "status": true,
```

```
"name": "City",
"key": "city",
"value": "Mumbai",
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Andheri",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Akshay Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Kondivita Road, J. B. Nagar",
  "label": false
}
```

```
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Y. A. C. Nagar",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "18/3(P), 21/6, 21/11, 22/3, 26/1 & 26/3",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
```



```
"key": "hissaNo",
"value": "",
"label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "138/8, 145, 146, 129, 154 & 132",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "203",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
}
```

```
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 059",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Andheri (East)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
```

```

    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Aluminium_Sliding_Windows_with_window_grills",
    "label": "Aluminium Sliding Windows with window grills"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Casting_Capping_Electrical_wiring",
    "label": "Concealed plumbing with C.P. fittings. Casting Capping Electrical wiring"
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MCGM",
    "label": "Municipal Corporation of Greater Mumbai (MCGM)"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Internal Road & Ganesh-Kunj CHSL",
    "west": "Kondivita Road",
    "south": "The Palladium",
    "east": "B & C Wing"
  },
  "asPerDocumentAgreement": {
    "north": "Details not available",

```

```
"west": "Details not available",
"south": "Details not available",
"east": "Details not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "asPerDocument": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As Occupancy Certificate is received may be assumed
that the construction is as per sanctioned plan. ",
"approvePlanVerified": "N. A.",
"empanelledOfApprovePlan": "N. A."
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "34.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "21937.5",
  "depreciatedBuildingRate": "1637.5"
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "142640",
  "landRate": "68580",
  "igrImage": "cases/653a2d04164a9341fb02c8d8/igr_1698641706717_Image.png",
  "squareMeterGuideLineRate": "128376.00",
  "squareFeetGuideLineRate": "11927.00"
},
"igrFinalRate": {
  "depreciationPercentage": "77",
  "rate": "10649.00",
  "squareFeetGuideLineRate": "10649.00",
```

```
"squareMeterGuideLineRate": "114623.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Tenant_Occupied",
    "label": "Tenant Occupied"
  },
  "monthlyRent": "20,000",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per MCGM norms",
  "tenantName": "Mr. Sanjay Dhaktu Kadam",
  "maintenanceOfFlat": "Normal"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\\_Thk._Brick_Masonry",
    "label": "6\\ Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  }
}
```

```
},
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": "Open Car Parking",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2000",
  "fullDate": "1/1/2000"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Normal",
  "label": "Normal"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"structuralSafety": {
  "value": "Normal",
```

```
"label": "Normal"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceIssues": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
}
```

```
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "37",
"ageOfBuilding": "23",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "3",
"flatFloorNo": "2",
"noOfLifts": "",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "areaType": "Built Up",
  "area": "436.00",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area as per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Metro_Station",
      "label": "Metro Station"
    },
    "routeMapImg": "cases/653a2d04164a9341fb02c8d8/
routeMap_1698644863669_Image.png",
    "routeLat": "19.115056",
    "routeLng": "72.873139",
    "stationName": "Chakala Metro Station ",
    "routeDistance": "1.1"
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "n4ijyve",
      "name": "n4ijyve",

```



```
    "image": "cases/653a2d04164a9341fb02c8d8/  
routeMap_1698644740352_Image.png"
```

```
  }  
]
```

```
},
```

```
"valuation": {
```

```
  "wardrobesRate": "0",
```

```
  "totalwardrobesRate": "0",
```

```
  "wardrobesQty": "0",
```

```
  "showcasesQty": "0",
```

```
  "showcasesRate": "0",
```

```
  "totalshowcasesRate": "0",
```

```
  "kitchenArrangementsQty": "0",
```

```
  "kitchenArrangementsRate": "0",
```

```
  "totalkitchenArrangementsRate": "0",
```

```
  "superfineFinishQty": "0",
```

```
  "superfineFinishRate": "0",
```

```
  "totalsuperfineFinishRate": "0",
```

```
  "interiorDecorationsQty": "0",
```

```
  "interiorDecorationsRate": "0",
```

```
  "totalinteriorDecorationsRate": "0",
```

```
  "electricityDepositsQty": "0",
```

```
  "electricityDepositsRate": "0",
```

```
  "totalelectricityDepositsRate": "0",
```

```
  "extraCollapsibleGatesQty": "0",
```

```
  "extraCollapsibleGatesRate": "0",
```

```
  "totalextraCollapsibleGatesRate": "0",
```

```
  "potentialValueQty": "0",
```

```
  "potentialValueRate": "0",
```

```
  "totalpotentialValueRate": "0",
```

```
  "othersQty": "0",
```

```
  "othersRate": "0",
```

```
  "totalothersRate": "0",
```

```
  "finaltotal": "9564968.00",
```

```
  "distressValuePercentage": "80",
```

```
  "realizableValuePercentage": "90",
```

```
  "bookValue": "0",
```

```
  "finalValue": "9564968.00"
```

```
},
```

```
"outward": {
```

```
  "status": false,
```

```
  "remark": "SYSTEM_GENERATED"
```

```
},
```

```
"rateVerify": {
```

```
  "status": false
```

```
},
```

```
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
    "label": "External Plastering",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "4642964.00",
  "selectedBuildUpValue": "436.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "653cf555d6fbd83553d3b37f",
      "name": "externalImg_1698493757154_1698493746162_image_4.jpeg",
      "path": "cases/653a2d04164a9341fb02c8d8/
externalImg_1698493757154_1698493746162_image_4.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
```

```
{
  "status": false,
  "_id": "653cf555d6fbd83553d3b37d",
  "name": "externallmg_1698493746243_1698493746162_image_2.jpeg",
  "path": "cases/653a2d04164a9341fb02c8d8/
externallmg_1698493746243_1698493746162_image_2.jpeg",
  "orientation": "portrait"
}
],
"externalPhotos": [
  {
    "status": false,
    "_id": "653cf555d6fbd83553d3b380",
    "name": "externallmg_1698493769474_1698493746162_image_5.jpeg",
    "path": "cases/653a2d04164a9341fb02c8d8/
externallmg_1698493769474_1698493746162_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "653cf555d6fbd83553d3b37f",
    "name": "externallmg_1698493757154_1698493746162_image_4.jpeg",
    "path": "cases/653a2d04164a9341fb02c8d8/
externallmg_1698493757154_1698493746162_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "653cf555d6fbd83553d3b37b",
    "name": "externallmg_1698493709761_1698493746162_image_0.jpeg",
    "path": "cases/653a2d04164a9341fb02c8d8/
externallmg_1698493709761_1698493746162_image_0.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "653cf555d6fbd83553d3b36f",
    "name": "Living Room",
    "path": "cases/653a2d04164a9341fb02c8d8/
externallmg_1698493611834_1698493648761_image_0.jpeg",
    "orientation": "portrait"
  },
  ],
```

```
{
  "status": false,
  "_id": "653cf555d6fbd83553d3b370",
  "name": "Living Room",
  "path": "cases/653a2d04164a9341fb02c8d8/
externallmg_1698493618171_1698493648761_image_1.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "653cf555d6fbd83553d3b372",
  "name": "Living Room",
  "path": "cases/653a2d04164a9341fb02c8d8/
externallmg_1698493624131_1698493648761_image_3.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "653cf555d6fbd83553d3b376",
  "name": "Living Room",
  "path": "cases/653a2d04164a9341fb02c8d8/
externallmg_1698493668155_1698493700876_image_1.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "653cf555d6fbd83553d3b378",
  "name": "Living Room",
  "path": "cases/653a2d04164a9341fb02c8d8/
externallmg_1698493672655_1698493700876_image_3.jpeg",
  "orientation": "portrait"
}
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "24563",
    "max": "28750"
  },
  "builtUpRateRange": {
    "min": "22223",
    "max": "23959"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
```

```
"title": "Present value of the flat (incl. car parking, if provided)",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
```



```
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "436.00",
"empanelmentNo": [
  "AX33/CREMON/Valuer/Empanelment/ Sr No.55/ 2019-20"
],
"isAdvancelInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentId": [],
"_id": "653a2d04164a9341fb02c8d8",
"ownerName": "Mr. Pravin Kanji Singhal",
"ownerPhoneNo": "8211965006",
"appAddress": "Flat no.203,2 nd floor A-wing Bldg -A ,Y.A.C.Nagar,Kondivita Road J.B
Nagar Andheri East - 400059",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "09/02/1984",
      "from": {
        "value": "Seller",
        "label": "Seller"
      },
      "Seller": "M/s. Y. A. Chunawala & Co.",
      "to": {
        "value": "Purchaser",
```

```
    "label": "Purchaser"
  },
  "Purchaser": "Mr. Pravin Kanji Singhal",
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "-",
},
"isHardCopy": false,
"displayStatus": true,
"path": "cases/653a2d04164a9341fb02c8d8/document_1698641503777_AGR.pdf",
"fileName": "document_1698641503777_AGR.pdf",
"id": "501947",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Mon Oct 30 2023 10:58:43 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "30/05/2000",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_of_Greater_Mumbai",
      "label": "Municipal Corporation of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "CE / 8308 / BSII / AK"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1698643874463_OC.pdf",
  "path": "cases/653a2d04164a9341fb02c8d8/document_1698643874463_OC.pdf",
  "id": "339233",
  "uploadedBy": "60eebe33f3dd69653a5837ae",
  "createdAt": "Mon Oct 30 2023 11:01:14 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "004671",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
```

```
{
  "id": "222831",
  "title": "Create Lead",
  "description": "Create Lead",
  "datetime": "Thu Oct 26 2023 14:40:28 GMT+0530 (India Standard Time)"
},
"owners": [
  {
    "name": "Mr. Pravin Kanji Singhal",
    "phone": "8211965006",
    "ownershipShare": "",
    "email": "",
    "id": "255679"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "104840",
    "name": "Living Room",
    "length": "14.50",
    "length1": "14",
    "length2": "6",
    "width": "9.08",
    "width1": "9",
    "width2": "1",
    "totalArea": "131.71",
    "images": [],
    "extraAreas": [],
    "finalArea": "131.71"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "name": "Passage",
    "length": "7.00",
    "length1": "7",
```

```
"length2": "00",
"width": "3.00",
"width1": "3",
"width2": "00",
"totalArea": "21.00",
"images": [],
"extraAreas": [],
"finalArea": "21.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Kitchen",
  "length": "9.50",
  "length1": "9",
  "length2": "6",
  "width": "6.08",
  "width1": "6",
  "width2": "1",
  "totalArea": "57.79",
  "images": [],
  "extraAreas": [],
  "finalArea": "57.79"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Toilet",
  "length": "4.42",
  "length1": "4",
  "length2": "5",
  "width": "7.17",
  "width1": "7",
  "width2": "2",
  "totalArea": "31.65",
  "images": [],
  "extraAreas": [],
  "finalArea": "31.65"
},
{
```

```
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "4",
"name": "Bedroom",
"length": "11.00",
"length1": "11",
"length2": "00",
"width": "9.00",
"width1": "9",
"width2": "00",
"totalArea": "99.00",
"images": [],
"extraAreas": [],
"finalArea": "99.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Balcony",
  "length": "4.33",
  "length1": "4",
  "length2": "4",
  "width": "4.25",
  "width1": "4",
  "width2": "3",
  "totalArea": "18.42",
  "images": [],
  "extraAreas": [],
  "finalArea": "18.42"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
```

```
    "label": "Square Feet"
  },
  "selectAreaTypeDocument": "Built_Up",
  "squareMeterArea": "40.51",
  "totalAreaDocument": "436",
  "docBultupPercentage": "",
  "docFinalBuiltUp": "0.00",
  "docFinalBuiltUpSquareMeter": "0.00",
  "docSaleablePercentage": "",
  "docFinalSaleable": "0.00",
  "docFinalSaleableSquareMeter": "0.00",
  "id": "789495"
}
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "653f3733d6fbd83553d53c88",
    "property": "Residential Flat",
    "area": "488",
    "builtUpPercentage": "0",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Built_Up",
    "source": "https://www.99acres.com/",
    "expectedPrice": "11000000",
    "expectedRate": "22540.98",
    "builtUpExpectedRate": "0.00",
    "image": "cases/653a2d04164a9341fb02c8d8/
indicator_1698641570629_Image.png",
    "squareMeter": "45.34",
    "id": "560736"
  },
  {
    "printlnReport": true,
    "_id": "653f3733d6fbd83553d53c89",
    "property": "Residential Flat",
    "area": "300",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "https://www.99acres.com/",
    "expectedPrice": "8000000",
    "expectedRate": "26666.67",
```

```
    "builtUpExpectedRate": "22222.22",
    "image": "cases/653a2d04164a9341fb02c8d8/
indicator_1698641585722_Image.png",
    "squareMeter": "27.87",
    "id": "528146"
  },
  {
    "printlnReport": true,
    "_id": "653f3733d6fbd83553d53c8a",
    "property": "Residential Flat",
    "area": "515",
    "builtUpPercentage": "0",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Built_Up",
    "source": "Nobroker.com",
    "expectedPrice": "11500000",
    "expectedRate": "22330.10",
    "builtUpExpectedRate": "0.00",
    "image": "cases/653a2d04164a9341fb02c8d8/
indicator_1698641612068_Image.png",
    "squareMeter": "47.85",
    "id": "551892"
  },
  {
    "printlnReport": true,
    "_id": "653f3733d6fbd83553d53c8b",
    "property": "Residential Flat",
    "area": "400",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "Housing.Com",
    "expectedPrice": "11500000",
    "expectedRate": "28750.00",
    "builtUpExpectedRate": "23958.33",
    "image": "cases/653a2d04164a9341fb02c8d8/
indicator_1698641634751_Image.png",
    "squareMeter": "37.16",
    "id": "392486"
  }
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "653cf555d6fbd83553d3b36f",
    "name": "externallmg_1698493611834_1698493648761_image_0.jpeg",
    "path": "cases/653a2d04164a9341fb02c8d8/
externallmg_1698493611834_1698493648761_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653cf555d6fbd83553d3b370",
    "name": "externallmg_1698493618171_1698493648761_image_1.jpeg",
    "path": "cases/653a2d04164a9341fb02c8d8/
externallmg_1698493618171_1698493648761_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653cf555d6fbd83553d3b371",
    "name": "externallmg_1698493621745_1698493648761_image_2.jpeg",
    "path": "cases/653a2d04164a9341fb02c8d8/
externallmg_1698493621745_1698493648761_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653cf555d6fbd83553d3b372",
    "name": "externallmg_1698493624131_1698493648761_image_3.jpeg",
    "path": "cases/653a2d04164a9341fb02c8d8/
externallmg_1698493624131_1698493648761_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653cf555d6fbd83553d3b373",
    "name": "externallmg_1698493626719_1698493648761_image_4.jpeg",
    "path": "cases/653a2d04164a9341fb02c8d8/
externallmg_1698493626719_1698493648761_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```



```
    "_id": "653cf555d6fbd83553d3b374",
    "name": "externallmg_1698493628981_1698493648761_image_5.jpeg",
    "path": "cases/653a2d04164a9341fb02c8d8/
externallmg_1698493628981_1698493648761_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653cf555d6fbd83553d3b375",
    "name": "externallmg_1698493663110_1698493700876_image_0.jpeg",
    "path": "cases/653a2d04164a9341fb02c8d8/
externallmg_1698493663110_1698493700876_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653cf555d6fbd83553d3b376",
    "name": "externallmg_1698493668155_1698493700876_image_1.jpeg",
    "path": "cases/653a2d04164a9341fb02c8d8/
externallmg_1698493668155_1698493700876_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653cf555d6fbd83553d3b377",
    "name": "externallmg_1698493670778_1698493700876_image_2.jpeg",
    "path": "cases/653a2d04164a9341fb02c8d8/
externallmg_1698493670778_1698493700876_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653cf555d6fbd83553d3b378",
    "name": "externallmg_1698493672655_1698493700876_image_3.jpeg",
    "path": "cases/653a2d04164a9341fb02c8d8/
externallmg_1698493672655_1698493700876_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653cf555d6fbd83553d3b379",
```

```
    "name": "externallmg_1698493673738_1698493700876_image_4.jpeg",
    "path": "cases/653a2d04164a9341fb02c8d8/
externallmg_1698493673738_1698493700876_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653cf555d6fbd83553d3b37a",
    "name": "externallmg_1698493675149_1698493700876_image_5.jpeg",
    "path": "cases/653a2d04164a9341fb02c8d8/
externallmg_1698493675149_1698493700876_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653cf555d6fbd83553d3b37b",
    "name": "externallmg_1698493709761_1698493746162_image_0.jpeg",
    "path": "cases/653a2d04164a9341fb02c8d8/
externallmg_1698493709761_1698493746162_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653cf555d6fbd83553d3b37c",
    "name": "externallmg_1698493739797_1698493746162_image_1.jpeg",
    "path": "cases/653a2d04164a9341fb02c8d8/
externallmg_1698493739797_1698493746162_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653cf555d6fbd83553d3b37d",
    "name": "externallmg_1698493746243_1698493746162_image_2.jpeg",
    "path": "cases/653a2d04164a9341fb02c8d8/
externallmg_1698493746243_1698493746162_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653cf555d6fbd83553d3b37e",
    "name": "externallmg_1698493749528_1698493746162_image_3.jpeg",
```

```
    "path": "cases/653a2d04164a9341fb02c8d8/
externallmg_1698493749528_1698493746162_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653cf555d6fbd83553d3b37f",
    "name": "externallmg_1698493757154_1698493746162_image_4.jpeg",
    "path": "cases/653a2d04164a9341fb02c8d8/
externallmg_1698493757154_1698493746162_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653cf555d6fbd83553d3b380",
    "name": "externallmg_1698493769474_1698493746162_image_5.jpeg",
    "path": "cases/653a2d04164a9341fb02c8d8/
externallmg_1698493769474_1698493746162_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "653cf555d6fbd83553d3b381",
    "name": "externallmg_1698493582001_1698493618822_image_0.jpeg",
    "path": "cases/653a2d04164a9341fb02c8d8/
externallmg_1698493582001_1698493618822_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "653cf555d6fbd83553d3b382",
    "name": "externallmg_1698493586657_1698493618822_image_1.jpeg",
    "path": "cases/653a2d04164a9341fb02c8d8/
externallmg_1698493586657_1698493618822_image_1.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Summary New=Pravin.xlsx",
    "filename": "1698641732232_Summary_NewPravin.xlsx",
```

```
    "path": "cases/653a2d04164a9341fb02c8d8/
processingDocuments/1698641732232_Summary_NewPravin.xlsx",
    "size": "1647269",
    "createdAt": "Mon Oct 30 2023 10:25:32 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "AGR.pdf",
    "filename": "1698641732271_AGR.pdf",
    "path": "cases/653a2d04164a9341fb02c8d8/
processingDocuments/1698641732271_AGR.pdf",
    "size": "11150882",
    "createdAt": "Mon Oct 30 2023 10:25:32 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "externallmg_1698493582001_1698493618822_image_0.jpeg",
    "filename":
"1698641732449_externallmg_1698493582001_1698493618822_image_0.jpeg",
    "path": "cases/653a2d04164a9341fb02c8d8/processingDocuments/1698641732449
_externallmg_1698493582001_1698493618822_image_0.jpeg",
    "size": "1195354",
    "createdAt": "Mon Oct 30 2023 10:25:32 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "externallmg_1698493586657_1698493618822_image_1.jpeg",
    "filename":
"1698641732468_externallmg_1698493586657_1698493618822_image_1.jpeg",
    "path": "cases/653a2d04164a9341fb02c8d8/processingDocuments/1698641732468
_externallmg_1698493586657_1698493618822_image_1.jpeg",
    "size": "768747",
    "createdAt": "Mon Oct 30 2023 10:25:32 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  }
],
"remarks": [
  {
    "createdBy": {
      "_id": "60eeaeddf3dd69653a581316",
      "role": "MAKER + RATE VERFIER + CHEAKER",
      "firstName": "Shyam",
      "lastName": "Kajvilkar",
      "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
profilePhoto_1626255068979_Shym_Photo.jpg"
    }
  },
  {
    "createdBy": {
      "_id": "60eeaeddf3dd69653a581316",
      "role": "MAKER + RATE VERFIER + CHEAKER",
      "firstName": "Shyam",
      "lastName": "Kajvilkar",
      "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
profilePhoto_1626255068979_Shym_Photo.jpg"
    }
  }
]
```

```
"workType": "RATE_VERIFY",
"display": true,
"status": true,
"_id": "653e09c8d6fbd83553d46a0e",
"note": "Pending For Value Confirmation",
"taskId": "653a361f164a9341fb02eb68",
"createdAt": "2023-10-29T07:29:12.178Z"
},
{
  "createdBy": {
    "_id": "60eeaeddf3dd69653a581316",
    "role": "MAKER + RATE VERFIER + CHEAKER",
    "firstName": "Shyam",
    "lastName": "Kajvilkar",
    "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
  },
  "workType": "RATE_VERIFY",
  "display": true,
  "status": true,
  "_id": "653e0f8ed6fbd83553d471b7",
  "note": "Pending For Value Confirmation",
  "taskId": "653a361f164a9341fb02eb68",
  "createdAt": "2023-10-29T07:53:50.017Z"
}
],
"createdAt": "2023-10-26T09:10:28.868Z",
"updatedAt": "2023-10-30T06:00:31.665Z",
"__v": 0,
"invoiceId": "653a2d06164a9341fb02c92e",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 203, 2nd Floor, Wing - A, Akshay Co-op. Hsg. Soc.
Ltd., Y. A. C. Nagar, Kondivita Road, J. B. Nagar, Village - Kondivita, Andheri (East),
Taluka - Andheri, District - Mumbai, Mumbai, PIN - 400 059, State - Maharashtra, India",
"updatedBy": "60eeaeddf3dd69653a581316",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Mr. Sanjay Dhaktu Kadam",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
```

```

"relationWithOwner": "Tenant",
"siteVisitContactNo": "9819346905",
"buildingServicesRate": "2500",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 436.00",
"flatRate": "22800",
"landOtherRate": "20300",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Passage + Toilet +
Balcony",
"carpetTotal": "239.57",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "395.53",
"finalCarpetArea": "359.57",
"finalSalableArea": "435.08",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
}
}
}

```

Name	Length	Width	Total
Composition :			

Living Room	14'6"	9'1"	131.71
Passage	7'00"	3'00"	21.00
Kitchen	9'6"	6'1"	57.79
Toilet	4'5"	7'2"	31.65
Bedroom	11'00"	9'00"	99.00
Balcony	4'4"	4'3"	18.42
Other Composition :			