

```
{
  "typeOfReport": {
    "value": "Commercial",
    "label": "Commercial"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9ab"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94230fbb",
    "firstName": "Rohit",
    "email": "0_default_",
    "mobileNo": "0_DEFAULT_-",
    "workMobileNo": "0_DEFAULT_91-8830627275"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",

```

```
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9ab",
  "branchCode": "000189",
  "type": "BRANCH",
  "name": "Panvel Branch",
  "email": "sbi.00448@sbi.co.in",
  "mobileNo": "02227460773",
  "alternateMobileNo": "",
  "address": "Priyadarshani Society, Shop No. 3, Opp. State Bank, Near Panchratna
Hotel, Uran Road,Panvel, Pin Code - 410 206, State - Maharashtra, Country - India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Commercial",
  "label": "Commercial"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "62691c48afd7d55eddecfda3",
```

```
"role": "ADMIN",
"firstName": "Bhavika",
"email": "bhavikachavan0102@gmail.com",
"lastName": "chavan",
"mobileNo": "8390804382",
"shortName": "BH",
"workWithDocumentMaker": "",
"profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "62691c48afd7d55eddecfda3",
"role": "ADMIN",
"firstName": "Bhavika",
"email": "bhavikachavan0102@gmail.com",
"lastName": "chavan",
"mobileNo": "8390804382",
"designation": "Site Engineer",
"shortName": "BH",
"workWithDocumentMaker": "",
"profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
},
"rateVerifier": "",
"maker": "",
"checker": "",
"valuers": []
},
"clientType": {
"value": "BANK",
"label": "BANK"
},
"location": {
"latitude": "19.068381",
"longitude": " 73.019638"
},
"geo": {
"type": "Point",
"coordinates": [
0,
0
]
},
"siteVisit": {
"siteVisitStatus": false,
```

```
"schedule": [],
"visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
    "key": "village",
    "value": "",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "1",
    "label": false
  },
  "buildingNo": {
    "status": true,
    "name": "Building No",
    "key": "buildingNo",
    "value": "Sagar Ratana",
    "label": true
  }
}
```

```
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Turbhe",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
```

```
"key": "selectArea",
"value": "",
"label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Thane Belapur Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
```

```
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "Unit 119 & 120",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
```

```
"value": "",
"label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
```



```
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "areaType": "Built Up",
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": true,
"status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
```

```
"title": "Extra collapsible gates / grill works etc",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
```

```
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentId": [],
"_id": "653b8786c70a316a76100eca",
"ownerName": "Terra Electrosoft",
"ownerPhoneNo": "9029040777",
"fullAddress": " Flat No. Unit 119 & 120, 1st Floor, Building No Sagar Ratana, Thane
Belapur Road, Turbhe",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1698400040760_119_Sagar_Ratan.pdf",
    "path": "cases/653b8786c70a316a76100eca/
document_1698400040760_119_Sagar_Ratan.pdf",
    "id": "641000",
    "uploadedBy": "62691c48afd7d55eddecfda3",
    "createdAt": "Fri Oct 27 2023 15:18:07 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1698400068401_120_Sagar_Ratan.pdf",
    "path": "cases/653b8786c70a316a76100eca/
document_1698400068401_120_Sagar_Ratan.pdf",
    "id": "366369",
    "uploadedBy": "62691c48afd7d55eddecfda3",
```

```
    "createdAt": "Fri Oct 27 2023 15:18:07 GMT+0530 (India Standard Time)"
  }
],
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"caseNumber": "004714",
"createdBy": "62691c48afd7d55eddecfda3",
"caseHistory": [
  {
    "id": "194636",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Oct 27 2023 15:18:54 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Terra Electrosoft",
    "phone": "9029040777",
    "ownershipShare": "",
    "email": "",
    "id": "559972"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653e2531d6fbd83553d4ad10",
    "name":
"externalmg_1698571569173_WhatsApp_Image_20231029_at_12247_PM_1.jpeg",
    "path": "cases/653b8786c70a316a76100eca/
externalmg_1698571569173_WhatsApp_Image_20231029_at_12247_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
```



```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653e2531d6fbd83553d4ad11",
    "name":
"externallmg_1698571569178_WhatsApp_Image_20231029_at_12247_PM_2.jpeg",
    "path": "cases/653b8786c70a316a76100eca/
externallmg_1698571569178_WhatsApp_Image_20231029_at_12247_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653e2531d6fbd83553d4ad12",
    "name":
"externallmg_1698571569185_WhatsApp_Image_20231029_at_12247_PM_3.jpeg",
    "path": "cases/653b8786c70a316a76100eca/
externallmg_1698571569185_WhatsApp_Image_20231029_at_12247_PM_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653e2531d6fbd83553d4ad13",
    "name":
"externallmg_1698571569188_WhatsApp_Image_20231029_at_12247_PM_4.jpeg",
    "path": "cases/653b8786c70a316a76100eca/
externallmg_1698571569188_WhatsApp_Image_20231029_at_12247_PM_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653e2531d6fbd83553d4ad14",
    "name":
"externallmg_1698571569195_WhatsApp_Image_20231029_at_12247_PM_5.jpeg",
    "path": "cases/653b8786c70a316a76100eca/
externallmg_1698571569195_WhatsApp_Image_20231029_at_12247_PM_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653e2531d6fbd83553d4ad15",
    "name":
"externallmg_1698571569197_WhatsApp_Image_20231029_at_12247_PM_6.jpeg",
    "path": "cases/653b8786c70a316a76100eca/
externallmg_1698571569197_WhatsApp_Image_20231029_at_12247_PM_6.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653e2531d6fbd83553d4ad16",
    "name":
"externallmg_1698571569202_WhatsApp_Image_20231029_at_12247_PM.jpeg",
    "path": "cases/653b8786c70a316a76100eca/
externallmg_1698571569202_WhatsApp_Image_20231029_at_12247_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653e2531d6fbd83553d4ad17",
    "name":
"externallmg_1698571569204_WhatsApp_Image_20231029_at_12245_PM_1.jpeg",
    "path": "cases/653b8786c70a316a76100eca/
externallmg_1698571569204_WhatsApp_Image_20231029_at_12245_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653e2531d6fbd83553d4ad18",
    "name":
"externallmg_1698571569208_WhatsApp_Image_20231029_at_12245_PM_2.jpeg",
    "path": "cases/653b8786c70a316a76100eca/
externallmg_1698571569208_WhatsApp_Image_20231029_at_12245_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653e2531d6fbd83553d4ad19",
    "name":
"externallmg_1698571569210_WhatsApp_Image_20231029_at_12245_PM_3.jpeg",
    "path": "cases/653b8786c70a316a76100eca/
externallmg_1698571569210_WhatsApp_Image_20231029_at_12245_PM_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653e2531d6fbd83553d4ad1a",
```

```
    "name":
"externallmg_1698571569213_WhatsApp_Image_20231029_at_12245_PM_4.jpeg",
  "path": "cases/653b8786c70a316a76100eca/
externallmg_1698571569213_WhatsApp_Image_20231029_at_12245_PM_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653e2531d6fbd83553d4ad1b",
  "name":
"externallmg_1698571569215_WhatsApp_Image_20231029_at_12245_PM_5.jpeg",
  "path": "cases/653b8786c70a316a76100eca/
externallmg_1698571569215_WhatsApp_Image_20231029_at_12245_PM_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653e2531d6fbd83553d4ad1c",
  "name":
"externallmg_1698571569218_WhatsApp_Image_20231029_at_12245_PM_6.jpeg",
  "path": "cases/653b8786c70a316a76100eca/
externallmg_1698571569218_WhatsApp_Image_20231029_at_12245_PM_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653e2531d6fbd83553d4ad1d",
  "name":
"externallmg_1698571569220_WhatsApp_Image_20231029_at_12245_PM_7.jpeg",
  "path": "cases/653b8786c70a316a76100eca/
externallmg_1698571569220_WhatsApp_Image_20231029_at_12245_PM_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653e253ed6fbd83553d4ad4b",
  "name":
"externallmg_1698571582618_WhatsApp_Image_20231029_at_12245_PM_6.jpeg",
  "path": "cases/653b8786c70a316a76100eca/
externallmg_1698571582618_WhatsApp_Image_20231029_at_12245_PM_6.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653e253ed6fbd83553d4ad4c",
  "name":
"externallmg_1698571582621_WhatsApp_Image_20231029_at_12245_PM_7.jpeg",
  "path": "cases/653b8786c70a316a76100eca/
externallmg_1698571582621_WhatsApp_Image_20231029_at_12245_PM_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653e253ed6fbd83553d4ad4d",
  "name":
"externallmg_1698571582627_WhatsApp_Image_20231029_at_12245_PM.jpeg",
  "path": "cases/653b8786c70a316a76100eca/
externallmg_1698571582627_WhatsApp_Image_20231029_at_12245_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653e253ed6fbd83553d4ad4e",
  "name":
"externallmg_1698571582633_WhatsApp_Image_20231029_at_12246_PM_1.jpeg",
  "path": "cases/653b8786c70a316a76100eca/
externallmg_1698571582633_WhatsApp_Image_20231029_at_12246_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653e253ed6fbd83553d4ad4f",
  "name":
"externallmg_1698571582635_WhatsApp_Image_20231029_at_12246_PM_2.jpeg",
  "path": "cases/653b8786c70a316a76100eca/
externallmg_1698571582635_WhatsApp_Image_20231029_at_12246_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653e253ed6fbd83553d4ad50",
  "name":
"externallmg_1698571582638_WhatsApp_Image_20231029_at_12246_PM_3.jpeg",
```

```
    "path": "cases/653b8786c70a316a76100eca/
externallmg_1698571582638_WhatsApp_Image_20231029_at_12246_PM_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653e253ed6fbd83553d4ad51",
    "name":
"externallmg_1698571582641_WhatsApp_Image_20231029_at_12246_PM_4.jpeg",
    "path": "cases/653b8786c70a316a76100eca/
externallmg_1698571582641_WhatsApp_Image_20231029_at_12246_PM_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653e253ed6fbd83553d4ad52",
    "name":
"externallmg_1698571582644_WhatsApp_Image_20231029_at_12246_PM_5.jpeg",
    "path": "cases/653b8786c70a316a76100eca/
externallmg_1698571582644_WhatsApp_Image_20231029_at_12246_PM_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653e253ed6fbd83553d4ad53",
    "name":
"externallmg_1698571582646_WhatsApp_Image_20231029_at_12246_PM_6.jpeg",
    "path": "cases/653b8786c70a316a76100eca/
externallmg_1698571582646_WhatsApp_Image_20231029_at_12246_PM_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653e253ed6fbd83553d4ad54",
    "name":
"externallmg_1698571582648_WhatsApp_Image_20231029_at_12246_PM.jpeg",
    "path": "cases/653b8786c70a316a76100eca/
externallmg_1698571582648_WhatsApp_Image_20231029_at_12246_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "653e26b4d6fbd83553d4b56e",
  "name":
"externalImg_1698571954908_WhatsApp_Image_20231029_at_30112_PM.jpeg",
  "path": "cases/653b8786c70a316a76100eca/
externalImg_1698571954908_WhatsApp_Image_20231029_at_30112_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653e26b4d6fbd83553d4b56f",
  "name":
"externalImg_1698571955482_WhatsApp_Image_20231029_at_30111_PM.jpeg",
  "path": "cases/653b8786c70a316a76100eca/
externalImg_1698571955482_WhatsApp_Image_20231029_at_30111_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653e26b4d6fbd83553d4b570",
  "name":
"externalImg_1698571956821_WhatsApp_Image_20231029_at_30110_PM.jpeg",
  "path": "cases/653b8786c70a316a76100eca/
externalImg_1698571956821_WhatsApp_Image_20231029_at_30110_PM.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-10-27T09:48:54.848Z",
"updatedAt": "2023-10-29T09:32:36.941Z",
"__v": 0,
"invoiceId": "653b878ac70a316a76100f20",
"updatedBy": "62691c48afd7d55eddecfda3",
"addressForMap": "",
"caseReferredBy": "",
"contactPersonName": "Terra Electrosoft",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
```

"siteVisitContactNo": "9029040777"

}

Name	Length	Width	Total
-------------	---------------	--------------	--------------

Composition :

Other
Composition :
