

```
{
  "typeOfReport": {
    "value": "Residential",
    "label": "Residential"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "64e58e18daae6a1c980f9e1e"
    },
    "type": "CREDITOFFICER",
    "_id": "64e58e18daae6a1c980f9e20",
    "firstName": "S.K",
    "lastName": "Sushil",
    "mobileNo": "912532463482",
    "workMobileNo": "9168590072",
    "email": "nasikr@bankofbaroda.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "2950"
  },
  "organization": {
```

```
"_id": "643a5bee108b68389ed736e5",
"name": "Nashik Branch",
"shortName": "NSK",
"email": "nashik@vastukala.org",
"address": "4, 1st Floor, Mashusha Elite, Vrundavan Naka Link Road, Adgaon, ",
"city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180c",
  "type": "BANK",
  "name": "Bank Of Baroda",
  "displayName": "Bank Of Baroda",
  "initial": "BOB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "64e58e18daae6a1c980f9e1e",
  "name": "Nashik Road 2",
  "branchCode": "BARB0NASIKR",
  "mobileNo": "91 2535463482",
  "alternateMobileNo": "9168590072",
  "email": "nasikr@bankofbaroda.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "03 & 04 Icon Plaza, Near Punjab Colony Nashik Pune Road, Datta
Mandir Rd, near Titan Showroom At, Nashik, Maharashtra 422101"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "63fda060ce84bf289baace4c",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "63f9f4adce84bf289ba9956e",
    "role": "FRONTDESK + ENGINEER",
```

```
"firstName": "Swapnil",
"email": "waghswapnil309@gmail.com",
"lastName": "Wagh",
"mobileNo": "8237116625",
"shortName": "SW",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9f4adce84bf289ba9956e/
profilePhoto_1688707461551_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "63f9f4adce84bf289ba9956e",
  "role": "FRONTDESK + ENGINEER",
  "firstName": "Swapnil",
  "email": "waghswapnil309@gmail.com",
  "lastName": "Wagh",
  "mobileNo": "8237116625",
  "designation": "",
  "shortName": "SW",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/63f9f4adce84bf289ba9956e/
profilePhoto_1688707461551_image.jpeg"
},
"valuers": []
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "20.029343865899218",
  "longitude": "73.82588333213674"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
```

```
"audioNotes": [],
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
    "key": "village",
    "value": "",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "6",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
```

```
"key": "district",
"value": "Nashik ",
"label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "15",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Hari Darshan Heights Apartment",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
}
```

```
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Hari Om Kalpesh Nagar ",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Asha Nagar, Meri - Rasbihari Road",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": " Near Cutie - Pie Preschool",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": true,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "234/ 1/ 1+2A/ 2/ 2",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
```

```
"value": "",
"label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "602",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
```

```
"status": false,
"name": "Mouza",
"key": "mouza",
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": " 422101",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
}
```



```
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "areaType": "Built Up",
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
}
```

```
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
```

```
    "label": "Work Completed (%)",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": true,
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
}
```

```
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "true",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
```

```
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentId": [],
"_id": "653cc91f3349b15c57cedc01",
"ownerName": " Samadhan Sharad Bagul",
"ownerPhoneNo": "9209507108",
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "9209507108",
"contactPersonName": "Sandip Patil (Site Supervisor)",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": " Samadhan Sharad Bagul",
    "phone": "9209507108",
    "ownershipShare": "",
    "email": "",
    "id": "725666"
  }
],
"caseReferredBy": "63f9f4adce84bf289ba9956e",
"relationWithOwner": "Builder",
"fullAddress": "Residential Flat No. 602, 6th Floor, Wing - A, Hari Darshan Heights
Apartment, Near Cutie - Pie Preschool, Plot No. 15, Hari Om Kalpesh Nagar , Asha
Nagar, Meri - Rasbihari Road, Taluka - Nashik, District - Nashik , Nashik, 422101,
State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1698482390545_CamScanner_10262023_165901.pdf",
    "path": "cases/653cc91f3349b15c57cedc01/
document_1698482390545_CamScanner_10262023_165901.pdf",
    "id": "820288",
    "uploadedBy": "63f9f4adce84bf289ba9956e",
```

```
    "createdAt": "Sat Oct 28 2023 14:10:12 GMT+0530 (India Standard Time)"
  }
],
"isUrgent": "false",
"isExternal": "false",
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"scheduleSiteVisitDate": "Invalid date",
"caseNumber": "004727",
"createdBy": "63f9f4adce84bf289ba9956e",
"caseHistory": [
  {
    "id": "152731",
    "title": "Create Case",
    "description": "Create Case",
    "datetime": "Sat Oct 28 2023 14:11:03 GMT+0530 (India Standard Time)"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653cc9513349b15c57cedcdf",
    "name":
"externallmg_1698482512623_WhatsApp_Image_20231026_at_122201_PM.jpeg",
    "path": "cases/653cc91f3349b15c57cedc01/
externallmg_1698482512623_WhatsApp_Image_20231026_at_122201_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653cc9513349b15c57cedce0",
    "name":
"externallmg_1698482512638_WhatsApp_Image_20231026_at_122202_PM_1.jpeg",
    "path": "cases/653cc91f3349b15c57cedc01/
externallmg_1698482512638_WhatsApp_Image_20231026_at_122202_PM_1.jpeg",
```



```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653cc9513349b15c57cedce1",
    "name":
"externallmg_1698482512712_WhatsApp_Image_20231026_at_122202_PM_2.jpeg",
    "path": "cases/653cc91f3349b15c57cedc01/
externallmg_1698482512712_WhatsApp_Image_20231026_at_122202_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653cc9513349b15c57cedce2",
    "name":
"externallmg_1698482512776_WhatsApp_Image_20231026_at_122202_PM.jpeg",
    "path": "cases/653cc91f3349b15c57cedc01/
externallmg_1698482512776_WhatsApp_Image_20231026_at_122202_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653cc9513349b15c57cedce3",
    "name":
"externallmg_1698482512834_WhatsApp_Image_20231026_at_122203_PM_1.jpeg",
    "path": "cases/653cc91f3349b15c57cedc01/
externallmg_1698482512834_WhatsApp_Image_20231026_at_122203_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653cc9513349b15c57cedce4",
    "name":
"externallmg_1698482512862_WhatsApp_Image_20231026_at_122203_PM_2.jpeg",
    "path": "cases/653cc91f3349b15c57cedc01/
externallmg_1698482512862_WhatsApp_Image_20231026_at_122203_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653cc9513349b15c57cedce5",
```

```
    "name":
"externallmg_1698482512929_WhatsApp_Image_20231026_at_122203_PM.jpeg",
  "path": "cases/653cc91f3349b15c57cedc01/
externallmg_1698482512929_WhatsApp_Image_20231026_at_122203_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653cc9513349b15c57cedce6",
  "name":
"externallmg_1698482512954_WhatsApp_Image_20231026_at_122204_PM.jpeg",
  "path": "cases/653cc91f3349b15c57cedc01/
externallmg_1698482512954_WhatsApp_Image_20231026_at_122204_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653cc95b3349b15c57cedd0e",
  "name":
"externallmg_1698482523254_WhatsApp_Image_20231026_at_122157_PM.jpeg",
  "path": "cases/653cc91f3349b15c57cedc01/
externallmg_1698482523254_WhatsApp_Image_20231026_at_122157_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653cc95b3349b15c57cedd0f",
  "name":
"externallmg_1698482523315_WhatsApp_Image_20231026_at_122158_PM_1.jpeg",
  "path": "cases/653cc91f3349b15c57cedc01/
externallmg_1698482523315_WhatsApp_Image_20231026_at_122158_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653cc95b3349b15c57cedd10",
  "name":
"externallmg_1698482523370_WhatsApp_Image_20231026_at_122158_PM.jpeg",
  "path": "cases/653cc91f3349b15c57cedc01/
externallmg_1698482523370_WhatsApp_Image_20231026_at_122158_PM.jpeg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653cc95b3349b15c57cedd11",
  "name":
"externallmg_1698482523431_WhatsApp_Image_20231026_at_122159_PM_1.jpeg",
  "path": "cases/653cc91f3349b15c57cedc01/
externallmg_1698482523431_WhatsApp_Image_20231026_at_122159_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653cc95b3349b15c57cedd12",
  "name":
"externallmg_1698482523509_WhatsApp_Image_20231026_at_122159_PM.jpeg",
  "path": "cases/653cc91f3349b15c57cedc01/
externallmg_1698482523509_WhatsApp_Image_20231026_at_122159_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653cc95b3349b15c57cedd13",
  "name":
"externallmg_1698482523550_WhatsApp_Image_20231026_at_122200_PM_1.jpeg",
  "path": "cases/653cc91f3349b15c57cedc01/
externallmg_1698482523550_WhatsApp_Image_20231026_at_122200_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653cc95b3349b15c57cedd14",
  "name":
"externallmg_1698482523606_WhatsApp_Image_20231026_at_122200_PM_2.jpeg",
  "path": "cases/653cc91f3349b15c57cedc01/
externallmg_1698482523606_WhatsApp_Image_20231026_at_122200_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653cc95b3349b15c57cedd15",
  "name":
"externallmg_1698482523632_WhatsApp_Image_20231026_at_122200_PM.jpeg",
```

```

    "path": "cases/653cc91f3349b15c57cedc01/
externallmg_1698482523632_WhatsApp_Image_20231026_at_122200_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653cc95b3349b15c57cedd16",
    "name":
"externallmg_1698482523689_WhatsApp_Image_20231026_at_122201_PM_1.jpeg",
    "path": "cases/653cc91f3349b15c57cedc01/
externallmg_1698482523689_WhatsApp_Image_20231026_at_122201_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653cc95b3349b15c57cedd17",
    "name":
"externallmg_1698482523759_WhatsApp_Image_20231026_at_122201_PM_2.jpeg",
    "path": "cases/653cc91f3349b15c57cedc01/
externallmg_1698482523759_WhatsApp_Image_20231026_at_122201_PM_2.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-10-28T08:41:03.641Z",
"updatedAt": "2023-10-28T08:42:03.919Z",
"__v": 0,
"invoiceId": "653cc91f3349b15c57cedc03",
"updatedBy": "63f9f4adce84bf289ba9956e"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			