

```
{
  "typeOfReport": {
    "value": "Residential",
    "label": "Residential"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856baea"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b9423121d",
    "firstName": "Ram Thakur",
    "email": "0_default_",
    "mobileNo": "0_DEFAULT_-",
    "workMobileNo": "0_DEFAULT_91-9423584228"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "6418456a96b58848585f8cb2",

```

```
"name": "Thane",
"email": "thane@vastukala.com",
"phone": "1234567890",
"address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
"city": "Thane",
"shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1812",
  "type": "BANK",
  "name": "Punjab National Bank",
  "displayName": "Punjab National Bank",
  "initial": "PNB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856baea",
  "branchCode": "000077",
  "type": "BRANCH",
  "name": "Thane East Branch",
  "email": "bo3303@pnb.co.in",
  "mobileNo": ".",
  "alternateMobileNo": "",
  "address": "Chatrapati Shivaji CHS,Plot No 1F10,S.V.Nagar,Thane East ",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60f7fcadf3dd69653a58d9d7",
  "zoneName": "Mumbai Zone (Maharashtra)"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "62720e52afd7d55eddedc887",
```

```
"role": "PICKUPPERSON",
"firstName": "Harshad",
"email": "harshad@vastukala.org",
"lastName": "Panchal",
"mobileNo": "9029575553",
"shortName": "HP",
"workWithDocumentMaker": ""
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "62ea09ea4e679b264caf07d7",
"role": "SITEENGINEER",
"firstName": "Suraj",
"email": "suraj@vastukala.org",
"lastName": "Zore",
"mobileNo": "8652448654",
"designation": "",
"shortName": "SZ",
"workWithDocumentMaker": "60092304a16fab0f2af9b0c2",
"profilePhoto": "users/62ea09ea4e679b264caf07d7/
profilePhoto_1685629394240_image.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"email": "v.sarmalkar@vastukala.org",
"lastName": "Sarmalkar",
"mobileNo": "9004437379",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"maker": {
"type": "EMPLOYEE",
"_id": "627222afafd7d55eddeddd82",
"role": "MAKER",
"firstName": "Pratibha",
"email": "shilvanta_pratibha@yahoo.co.in",
"lastName": "Shilvantha",
"mobileNo": "9821518537",
"designation": "",
"shortName": "PS",
```

```
    "workWithDocumentMaker": "",
    "profilePhoto": "users/627222afafd7d55eddedd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
  },
  "checker": "",
  "valuers": []
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.218306787925396",
  "longitude": "72.96063285687124"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-29",
      "remark": ""
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
```

```
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Majiwade",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "15",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "Viraj Tower",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Thane (West)",
  "label": false
},
"tahasilNo": {
```

```
"status": false,
"name": "Tahasil",
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Pokharan Road No. 2",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
```

```
"label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "192 / 1P",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
```

```
"name": "CTS No.",
"key": "CTSNo",
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1501A",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
}
```



```
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 400 606",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "areaType": "Built Up",
  "area": "0.00"
},
"routeMap": {
```

```
"finalLatLng": {
  "coordinates": []
},
"locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
```

```
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
```

```
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "true",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"paymentId": [],
"_id": "653cd2fd3349b15c57ceecee",
"ownerName": "Manohar Radhakrishna Hukmani, Reshma Manohar Hukmani &
Mayur Manohar Hukmani ",
```

```
"ownerPhoneNo": "9769118227",
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "9769118227",
"contactPersonName": "Manohar Radhakrishna Hukmani, Reshma Manohar Hukmani
& Mayur Manohar Hukmani ",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "Manohar Radhakrishna Hukmani, Reshma Manohar Hukmani & Mayur
Manohar Hukmani ",
    "phone": "9769118227",
    "ownershipShare": "",
    "email": "",
    "id": "234617"
  }
],
"caseReferredBy": "62720e52afd7d55eddedc887",
"relationWithOwner": "self",
"fullAddress": "Residential Flat No. 1501A, 15th Floor, Building No Viraj Tower,
Pokharan Road No. 2, Village - Majiwade, Taluka - Thane, District - Thane, Thane
(West), PIN Code - 400 606, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "27/09/2023",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "M/s. Shree Viraj Enterprises",
      "to": {
        "value": "Allottee",
        "label": "Allottee"
      },
      "Allottee": "Manohar Radhakrishna Hukmani, Reshma Manohar Hukmani & Mayur
Manohar Hukmani ",
      "number": {
        "value": "No",
        "label": "No"
      }
    }
  }
],
```



```
"No": "23681/2023"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1698484930245_279905.pdf",
"path": "cases/653cd2fd3349b15c57ceecee/
document_1698484930245_279905.pdf",
"id": "754354",
"uploadedBy": "6430f74691d7c62df11f3f15",
"createdAt": "Sat Oct 28 2023 14:52:18 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1279aa6d152c1801b3d4",
    "label": "Amended Commencement Certificate"
  },
  "inputs": {
    "documentDate": "20/05/2016",
    "nameOfApprovingAuthority": {
      "value": "Thane_Municipal_Corporation",
      "label": "Thane Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "2003 / 27 / TMC / TDD / 1814 / 16"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1698576162027_1_Commencement_Certificates___NA_Order_for_plotted_development__20231029T131909566.pdf",
"path": "cases/653cd2fd3349b15c57ceecee/document_1698576162027_1_Commencement_Certificates___NA_Order_for_plotted_development__20231029T131909566.pdf",
"id": "414098",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Sun Oct 29 2023 16:13:22 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "30/09/2019",
```

```
"nameOfApprovingAuthority": {
  "value": "Thane_Municipal_Corporation",
  "label": "Thane Municipal Corporation"
},
"number": {
  "value": "No",
  "label": "No"
},
"No": "2003 / 27 / TMC / TDD / OCC / 0745 / 19"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1698576202761_1_Occupancy_Certificate__Completion_C
ertificate__Architects_certificate_of_completion_for_plotted_development_24.pdf",
"path": "cases/653cd2fd3349b15c57ceecee/document_1698576202761_1_Occupa
ncy_Certificate__Completion_Certificate__Architects_certificate_of_completion_for_plot
ted_development_24.pdf",
"id": "465564",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Sun Oct 29 2023 16:13:22 GMT+0530 (India Standard Time)"
}
],
"isUrgent": "false",
"isExternal": "false",
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
},
"scheduleSiteVisitDate": "Invalid date",
"caseNumber": "004730",
"createdBy": "6430f74691d7c62df11f3f15",
"caseHistory": [
  {
    "id": "678079",
    "title": "Create Case",
    "description": "Create Case",
    "datetime": "Sat Oct 28 2023 14:53:09 GMT+0530 (India Standard Time)"
  }
]
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
```

```
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653db68cd6fbd83553d3d8ed",
    "name": "externalimg_r_1698543145875_1698543174693_image_2.jpg",
    "path": "cases/653cd2fd3349b15c57ceecee/
externalimg_r_1698543145875_1698543174693_image_2.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653db68cd6fbd83553d3d8ee",
    "name": "externalimg_r_1698543141248_1698543174693_image_0.jpg",
    "path": "cases/653cd2fd3349b15c57ceecee/
externalimg_r_1698543141248_1698543174693_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653db68cd6fbd83553d3d8ef",
    "name": "externalimg_r_1698543144009_1698543174693_image_1.jpg",
    "path": "cases/653cd2fd3349b15c57ceecee/
externalimg_r_1698543144009_1698543174693_image_1.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653db68cd6fbd83553d3d8f0",
    "name": "externalimg_r_1698543146881_1698543174693_image_3.jpg",
    "path": "cases/653cd2fd3349b15c57ceecee/
externalimg_r_1698543146881_1698543174693_image_3.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653db68cd6fbd83553d3d8f1",
    "name": "externalimg_r_1698543148524_1698543174693_image_5.jpg",
    "path": "cases/653cd2fd3349b15c57ceecee/
externalimg_r_1698543148524_1698543174693_image_5.jpg",
    "orientation": "portrait"
  }
]
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653db68cd6fbd83553d3d8f2",
  "name": "externallmg_r_1698543147743_1698543174693_image_4.jpg",
  "path": "cases/653cd2fd3349b15c57ceecee/
externallmg_r_1698543147743_1698543174693_image_4.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653db68cd6fbd83553d3d8f3",
  "name": "externallmg_r_1698543150038_1698543174693_image_6.jpg",
  "path": "cases/653cd2fd3349b15c57ceecee/
externallmg_r_1698543150038_1698543174693_image_6.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653db68cd6fbd83553d3d8f4",
  "name": "externallmg_r_1698543152352_1698543174693_image_7.jpg",
  "path": "cases/653cd2fd3349b15c57ceecee/
externallmg_r_1698543152352_1698543174693_image_7.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653db68cd6fbd83553d3d8f5",
  "name": "externallmg_r_1698543158299_1698543174693_image_10.jpg",
  "path": "cases/653cd2fd3349b15c57ceecee/
externallmg_r_1698543158299_1698543174693_image_10.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653db68cd6fbd83553d3d8f6",
  "name": "externallmg_r_1698543154042_1698543174693_image_8.jpg",
  "path": "cases/653cd2fd3349b15c57ceecee/
externallmg_r_1698543154042_1698543174693_image_8.jpg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653db68cd6fbd83553d3d8f7",
  "name": "externallmg_r_1698543156135_1698543174693_image_9.jpg",
  "path": "cases/653cd2fd3349b15c57ceecee/
externallmg_r_1698543156135_1698543174693_image_9.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653db68cd6fbd83553d3d8f8",
  "name": "externallmg_r_1698543159723_1698543174693_image_11.jpg",
  "path": "cases/653cd2fd3349b15c57ceecee/
externallmg_r_1698543159723_1698543174693_image_11.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653db68cd6fbd83553d3d8f9",
  "name": "externallmg_r_1698543162373_1698543174693_image_12.jpg",
  "path": "cases/653cd2fd3349b15c57ceecee/
externallmg_r_1698543162373_1698543174693_image_12.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653db68cd6fbd83553d3d8fa",
  "name": "externallmg_r_1698543164364_1698543174693_image_13.jpg",
  "path": "cases/653cd2fd3349b15c57ceecee/
externallmg_r_1698543164364_1698543174693_image_13.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653db68cd6fbd83553d3d8fb",
  "name": "externallmg_r_1698543166288_1698543174693_image_14.jpg",
  "path": "cases/653cd2fd3349b15c57ceecee/
externallmg_r_1698543166288_1698543174693_image_14.jpg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653db68cd6fbd83553d3d8fc",
    "name": "externallmg_r_1698543168340_1698543174693_image_15.jpg",
    "path": "cases/653cd2fd3349b15c57ceecee/
externallmg_r_1698543168340_1698543174693_image_15.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653db68cd6fbd83553d3d8fd",
    "name": "externallmg_r_1698543172569_1698543174693_image_17.jpg",
    "path": "cases/653cd2fd3349b15c57ceecee/
externallmg_r_1698543172569_1698543174693_image_17.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653db68cd6fbd83553d3d8fe",
    "name": "externallmg_r_1698543175871_1698543174693_image_18.jpg",
    "path": "cases/653cd2fd3349b15c57ceecee/
externallmg_r_1698543175871_1698543174693_image_18.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653db68cd6fbd83553d3d8ff",
    "name": "externallmg_r_1698543170748_1698543174693_image_16.jpg",
    "path": "cases/653cd2fd3349b15c57ceecee/
externallmg_r_1698543170748_1698543174693_image_16.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653db68cd6fbd83553d3d900",
    "name": "externallmg_r_1698543176800_1698543174693_image_19.jpg",
    "path": "cases/653cd2fd3349b15c57ceecee/
externallmg_r_1698543176800_1698543174693_image_19.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "653db68cd6fbd83553d3d901",
  "name": "externalimg_r_1698543225969_1698543261215_image_1.jpg",
  "path": "cases/653cd2fd3349b15c57ceecee/
externalimg_r_1698543225969_1698543261215_image_1.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653db68cd6fbd83553d3d902",
  "name": "externalimg_r_1698543225008_1698543261215_image_0.jpg",
  "path": "cases/653cd2fd3349b15c57ceecee/
externalimg_r_1698543225008_1698543261215_image_0.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653db68cd6fbd83553d3d903",
  "name": "externalimg_r_1698543228336_1698543261215_image_3.jpg",
  "path": "cases/653cd2fd3349b15c57ceecee/
externalimg_r_1698543228336_1698543261215_image_3.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653db68cd6fbd83553d3d904",
  "name": "externalimg_r_1698543227504_1698543261215_image_2.jpg",
  "path": "cases/653cd2fd3349b15c57ceecee/
externalimg_r_1698543227504_1698543261215_image_2.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653db68cd6fbd83553d3d905",
  "name": "externalimg_r_1698543229763_1698543261215_image_4.jpg",
  "path": "cases/653cd2fd3349b15c57ceecee/
externalimg_r_1698543229763_1698543261215_image_4.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "653db68cd6fbd83553d3d906",
    "name": "externalimg_r_1698543231386_1698543261215_image_5.jpg",
    "path": "cases/653cd2fd3349b15c57ceecee/
externalimg_r_1698543231386_1698543261215_image_5.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653db68cd6fbd83553d3d907",
    "name": "externalimg_r_1698543236136_1698543261215_image_7.jpg",
    "path": "cases/653cd2fd3349b15c57ceecee/
externalimg_r_1698543236136_1698543261215_image_7.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653db68cd6fbd83553d3d908",
    "name": "externalimg_r_1698543233477_1698543261215_image_6.jpg",
    "path": "cases/653cd2fd3349b15c57ceecee/
externalimg_r_1698543233477_1698543261215_image_6.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653db68cd6fbd83553d3d909",
    "name": "externalimg_r_1698543237660_1698543261215_image_8.jpg",
    "path": "cases/653cd2fd3349b15c57ceecee/
externalimg_r_1698543237660_1698543261215_image_8.jpg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "653db68cd6fbd83553d3d90a",
    "name": "externalimg_r_1698543109053_1698543146408_image_2.png",
    "path": "cases/653cd2fd3349b15c57ceecee/
externalimg_r_1698543109053_1698543146408_image_2.png",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "653db68cd6fbd83553d3d90b",
```



```

    "name": "externalImg_r_1698543108198_1698543146408_image_1.jpg",
    "path": "cases/653cd2fd3349b15c57ceecee/
externalImg_r_1698543108198_1698543146408_image_1.jpg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "653db68cd6fbd83553d3d90c",
    "name": "externalImg_r_1698543106908_1698543146408_image_0.jpg",
    "path": "cases/653cd2fd3349b15c57ceecee/
externalImg_r_1698543106908_1698543146408_image_0.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-10-28T09:23:09.145Z",
"updatedAt": "2023-10-29T10:43:22.984Z",
"__v": 0,
"invoiceId": "653cd2fd3349b15c57ceecf2",
"updatedBy": "627222afafd7d55eddeddd82",
"addressForMap": "",
"siteVisitDate": "2023-10-29"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			