

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "64645e68ee6a9735bf790e6f"
    },
    "type": "CREDITOFFICER",
    "_id": "64645e68ee6a9735bf790e71",
    "firstName": "Rajnessh ",
    "lastName": "Kumar",
    "mobileNo": "",
    "workMobileNo": "9167940785",
    "email": "bmmsro0618@centralbank.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5298900",
    "discussWithPerson": "Rajnessh ",
    "expectedFees": 2649.4500000000003,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17fa",
  "type": "BANK",
  "name": "Central Bank of India",
  "displayName": "Central Bank of India",
  "initial": "CBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "64645e68ee6a9735bf790e6f",
  "name": "Malad West Branch\t",
  "branchCode": "",
  "mobileNo": "0222891551\t02228821375",
  "alternateMobileNo": "",
  "email": "bmmsro0618@centralbank.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Vishnu Bhawan,Anand Road, Opp, Malad Railway Station, Malad west
Mumbai-400064\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60f917e0f3dd69653a592221",
  "zoneName": "South Mumbai Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "627219d6afd7d55eddedd283",
```

```
"role": "PICKUPPERSON",
"firstName": "Mangesh ",
"email": "mangeshpalande17@gmail.com",
"lastName": "Palande",
"mobileNo": "9833030550",
"shortName": "MP",
"workWithDocumentMaker": "",
"profilePhoto": "users/627219d6afd7d55eddedd283/
profilePhoto_1668055836118_WhatsApp_Image_20221110_at_101725_AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "62691c48afd7d55eddecfda3",
"role": "ADMIN",
"firstName": "Bhavika",
"email": "bhavikachavan0102@gmail.com",
"lastName": "chavan",
"mobileNo": "8390804382",
"designation": "Site Engineer",
"shortName": "BH",
"workWithDocumentMaker": "",
"profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "64dc7184ccaf1e7b7f637f47",
"role": "FRONTDESK",
"firstName": "Binumon",
"email": "binu@vastukala.org",
"lastName": "Moozhickal",
"mobileNo": "9930252906",
"designation": "Back Office Team Leader",
"shortName": "BS",
"workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
"profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abf0c819dbff58c0f.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "60eebe33f3dd69653a5837ae",
"role": "MAKER",
"firstName": "Shamal",
"email": "shamal@vastukala.org",
"lastName": "Bodke",
"mobileNo": "9821740317",
```

```
    "designation": "",
    "shortName": "SB",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60eebe33f3dd69653a5837ae\
\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
  },
  "checker": {
    "type": "EMPLOYEE",
    "_id": "64dc7184ccaf1e7b7f637f47",
    "role": "FRONTDESK",
    "firstName": "Binumon",
    "email": "binu@vastukala.org",
    "lastName": "Moozhickal",
    "mobileNo": "9930252906",
    "designation": "Back Office Team Leader",
    "shortName": "BS",
    "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
    "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
  },
  "valuers": [],
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.185084348881343",
  "longitude": "72.86111795517411"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.86111795517411,
    19.185084348881343
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-10-30T10:00:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-10-30T10:00:00.000Z",
```

```
    "remark": ""
  },
  {
    "dateTime": "2023-10-30T10:00:00.000Z",
    "remark": ""
  },
  {
    "dateTime": "2023-10-30T10:00:00.000Z",
    "remark": ""
  },
  {
    "dateTime": "2023-10-30T10:00:00.000Z",
    "remark": ""
  },
  {
    "dateTime": "30/10/2023 03:30 pm"
  },
  {
    "dateTime": "30/10/2023 12:00 am"
  }
],
"visitedDate": [
  {
    "status": "COMPLETED",
    "dateTime": "2023-11-26",
    "remark": "MANUAL_IN_TASK"
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
```

```
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Malad (East)",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "27",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Malad (East), Mumbai",
  "label": false
},
"tahasilNo": {
```

```
"status": false,
"name": "Tahasil",
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Borivali",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Altamonte Tower A Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Pathanwadi, Kokanipada",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Off. Western Express Highway",
```

```
"label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Near Shantaram Talao",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
```



```
"name": "CTS No.",
"key": "CTSNo",
"value": "812, 813, 821(P), 811 A/7(P), 814, 824 & 844",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "2705",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
}
```

```
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 097",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  }
}
```

```

    },
    "fittings": {
      "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
      "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
    },
    "finishing": {
      "value": "Cement_Plastering_with_POP_false_Ceiling",
      "label": "Cement Plastering with POP false Ceiling"
    }
  },
  "general": {
    "ownership": {
      "value": "Joint_Ownership",
      "label": "Joint Ownership"
    },
    "populationClassList": {
      "value": "MiddleClass",
      "label": "Middle Class"
    },
    "populationGroupList": {
      "value": "Urban",
      "label": "Urban"
    },
    "townplanApprovedByList": {
      "value": "Slum_Rehabilitation_Authority",
      "label": "Slum Rehabilitation Authority"
    },
    "whetherCoveredUnderAnyState": {
      "value": "No",
      "label": "No"
    },
    "asPerActualAgreement": {
      "north": "Internal Road & Green Point Building ",
      "west": "Omkar Signet",
      "south": "Internal Road & Janki Niwas Building ",
      "east": "Slum Area"
    },
    "asPerDocumentAgreement": {
      "north": "Details not available",
      "west": "Details not available",
      "south": "Details not available",
      "east": "Details not available"
    },
    "unitBoundaries": {
      "asPerActual": {

```

```
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "asPerDocument": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As Occupancy Certificate is received may be assumed
that the construction is as per sanctioned plan. ",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A."
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "10.666666666666666",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "20",
  "depreciatedCostOfConstruction": "20969.333333333332",
  "depreciatedBuildingRate": "2769.3333333333335"
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "168670",
  "landRate": "72420",
  "igrImage": "cases/653f62e1d6fbd83553d5bab2/igr_1701426683089_Image.png",
  "squareMeterGuideLineRate": "193971.00",
  "squareFeetGuideLineRate": "18020.00"
},
"igrFinalRate": {
  "floorRatePercentage": "15",
  "depreciationPercentage": "135.5",
  "rate": "22029.00",
  "squareFeetGuideLineRate": "22029.00",
  "squareMeterGuideLineRate": "237122.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
```

```
"label": "Medium"
},
"propertyTypeOfUseList": {
  "value": "Residential_Purpose",
  "label": "Residential Purpose"
},
"propertyOccupiedByList": {
  "value": "Owner_Occupied",
  "label": "Owner Occupied"
},
"monthlyRent": "60,000",
"assessmentNo": "Property Tax No.PN0602022700000",
"taxPaidHolderName": "Omkar Realtors & Developers Pvt. Ltd.",
"taxAmount": "28,26,031.00",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per SRA norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  }
},
```

```
"carParking": "Along with One Car Parking Space No. 24",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2015",
  "fullDate": "1/1/2015"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
}
```

```
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenancelssues": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "52",
"ageOfBuilding": "8",
"noOfBasement": "",
```

```
"noOfPodium": "",
"noOfAmenityFloors": "3",
"noOfFloors": "45",
"flatFloorNo": "27",
"noOfLifts": "7",
"noOfDwellingUnitsInBuilding": "6"
},
"finalPlinthArea": {
  "area": "1137.00",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area as per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/653f62e1d6fbd83553d5bab2/
routeMap_1701518203991_Image.png",
    "routeLat": "19.183556",
    "routeLng": "72.860417",
    "stationName": "Malad",
    "routeDistance": "1.8 Km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "7gmuam",
      "name": "7gmuam",
      "image": "cases/653f62e1d6fbd83553d5bab2/
routeMap_1701518130758_Image.png"
    }
  ]
},
"valuation": {
```



```
"wardrobesRate": "0",
"totalwardrobesRate": "0",
"wardrobesQty": "0",
"showcasesQty": "0",
"showcasesRate": "0",
"totalshowcasesRate": "0",
"kitchenArrangementsQty": "0",
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "1",
"othersRate": "1000000",
"totalothersRate": "1000000",
"finaltotal": "24841753.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "23841753.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": true
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "25046973.00",
  "selectedBuildUpValue": "1137.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "656b1c2ecebbe17144129388",
      "name":
"externallmg_1701518381237_WhatsApp_Image_20231202_at_43219_PM.jpeg",
      "path": "cases/653f62e1d6fbd83553d5bab2/
externallmg_1701518381237_WhatsApp_Image_20231202_at_43219_PM.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "65409e25eb542d69409939c7",
      "name":
"externallmg_1698733605542_WhatsApp_Image_20231031_at_114454_AM.jpeg",
```

```
    "path": "cases/653f62e1d6fbd83553d5bab2/
externallmg_1698733605542_WhatsApp_Image_20231031_at_114454_AM.jpeg",
    "orientation": "portrait"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "656b1c2ecebbe1714412938a",
    "name":
"externallmg_1701518381260_WhatsApp_Image_20231202_at_43220_PM.jpeg",
    "path": "cases/653f62e1d6fbd83553d5bab2/
externallmg_1701518381260_WhatsApp_Image_20231202_at_43220_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "656b1c2ecebbe17144129387",
    "name":
"externallmg_1701518381213_WhatsApp_Image_20231202_at_43219_PM_1.jpeg",
    "path": "cases/653f62e1d6fbd83553d5bab2/
externallmg_1701518381213_WhatsApp_Image_20231202_at_43219_PM_1.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "65409e25eb542d69409939c2",
    "name": "Living Room",
    "path": "cases/653f62e1d6fbd83553d5bab2/
externallmg_1698733605513_WhatsApp_Image_20231031_at_114451_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65409e25eb542d69409939c5",
    "name": "Living Room",
    "path": "cases/653f62e1d6fbd83553d5bab2/
externallmg_1698733605532_WhatsApp_Image_20231031_at_114453_AM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
```

```
    "_id": "65409e25eb542d69409939ca",
    "name": "Living Room",
    "path": "cases/653f62e1d6fbd83553d5bab2/
externallmg_169873360552_WhatsApp_Image_20231031_at_114456_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "65409e37eb542d6940993a22",
    "name": "Living Room",
    "path": "cases/653f62e1d6fbd83553d5bab2/
externallmg_1698733623693_WhatsApp_Image_20231031_at_114321_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65409e37eb542d6940993a2a",
    "name": "Living Room",
    "path": "cases/653f62e1d6fbd83553d5bab2/
externallmg_1698733623722_WhatsApp_Image_20231031_at_114351_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65409e37eb542d6940993a31",
    "name": "Living Room",
    "path": "cases/653f62e1d6fbd83553d5bab2/
externallmg_1698733623742_WhatsApp_Image_20231031_at_114444_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65409e37eb542d6940993a32",
    "name": "Living Room",
    "path": "cases/653f62e1d6fbd83553d5bab2/
externallmg_1698733623747_WhatsApp_Image_20231031_at_114446_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65409e37eb542d6940993a35",
    "name": "Living Room",
    "path": "cases/653f62e1d6fbd83553d5bab2/
externallmg_1698733623760_WhatsApp_Image_20231031_at_114449_AM.jpeg",
    "orientation": "landscape"
  },
}
```

```
{
  "status": false,
  "_id": "65409e37eb542d6940993a34",
  "name": "Living Room",
  "path": "cases/653f62e1d6fbd83553d5bab2/
externallmg_1698733623751_WhatsApp_Image_20231031_at_114447_AM.jpeg",
  "orientation": "landscape"
},
{
  "status": false,
  "_id": "65409e37eb542d6940993a33",
  "name": "Living Room",
  "path": "cases/653f62e1d6fbd83553d5bab2/
externallmg_1698733623750_WhatsApp_Image_20231031_at_114446_AM.jpeg",
  "orientation": "portrait"
}
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "17110",
    "max": "28049"
  },
  "builtUpRateRange": {
    "min": "15555",
    "max": "23374"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
```

```
"title": "Showcases",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```



```
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
```

```
"isSiteMeasurementAllowed": true,
"finalValuationArea": "1137.00",
"empanelmentNo": [],
"isAdvancelInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentId": [],
"_id": "653f62e1d6fbd83553d5bab2",
"ownerName": "Mrs. Rachana Vikas Ganeriwala & Mr. Vikas R. Ganeriwala",
"ownerPhoneNo": "9322255556",
"appAddress": "flat no A/2705 omkar alata monte tower kurar rd malad east",
"remark": "Prposed Buyer Vikas Ganeriwala",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "29/11/2023",
      "from": {
        "value": "Seller",
        "label": "Seller"
      },
      "Seller": "Kejriwal Plywoods Private Limited",
      "to": {
        "value": "Purchasers",
        "label": "Purchasers"
      },
      "Purchasers": "Mrs. Rachana Vikas Ganeriwala & Mr. Vikas R. Ganeriwala",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "18332/2023"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1701517001890_document_1701425298289_rachana_ganeriwala_central_malad_omkar_case.pdf",
    "path": "cases/653f62e1d6fbd83553d5bab2/document_1701517001890_document_1701425298289_rachana_ganeriwala_central_malad_omkar_case.pdf",
    "id": "731207",
    "uploadedBy": "60eebe33f3dd69653a5837ae",
    "createdAt": "Sat Dec 02 2023 17:06:42 GMT+0530 (India Standard Time)"
  },

```

```
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "23/12/2015",
    "nameOfApprovingAuthority": {
      "value": "Slum_Rehabilitation_Authority_(SRA)",
      "label": "Slum Rehabilitation Authority (SRA)"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "SRA / ENG / 2143 / PN / PL & STGL / AP"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1701517220567_OC.pdf",
  "path": "cases/653f62e1d6fbd83553d5bab2/document_1701517220567_OC.pdf",
  "id": "630103",
  "uploadedBy": "60eebe33f3dd69653a5837ae",
  "createdAt": "Sat Dec 02 2023 17:10:20 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1258aa6d152c1801b339",
    "label": "Possession Letter"
  },
  "inputs": {
    "documentDate": "17/11/2016",
    "remark": " issued by Omkar",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "-"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1701517310992_Possess.pdf",
  "path": "cases/653f62e1d6fbd83553d5bab2/
document_1701517310992_Possess.pdf",
  "id": "901982",
  "uploadedBy": "60eebe33f3dd69653a5837ae",
```

```
"createdAt": "Sat Dec 02 2023 17:11:51 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "10/08/2011",
    "nameOfApprovingAuthority": {
      "value": "Slum_Rehabilitation_Authority_(SRA)",
      "label": "Slum Rehabilitation Authority (SRA)"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "SRA / ENG / 2143 / PN / PL / AP"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1701517364171_CC.pdf",
"path": "cases/653f62e1d6fbd83553d5bab2/document_1701517364171_CC.pdf",
"id": "175211",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Sat Dec 02 2023 17:12:44 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124daa6d152c1801b306",
    "label": "Property Tax"
  },
  "inputs": {
    "documentDate": "01/12/2022",
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "PN0602022700000"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1701517472757_Property.pdf",
"path": "cases/653f62e1d6fbd83553d5bab2/
document_1701517472757_Property.pdf",
"id": "229384",
```

```
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Sat Dec 02 2023 17:14:32 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "004752",
"createdBy": "627219d6afd7d55eddedd283",
"caseHistory": [
  {
    "id": "589376",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Oct 30 2023 13:31:37 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mrs. Rachana Vikas Ganeriwala & Mr. Vikas R. Ganeriwala",
    "phone": "9322255556",
    "ownershipShare": "",
    "email": "",
    "id": "762514"
  }
],
"proposePurchasers": [
  {
    "name": "Vikas Ganeriwala",
    "phone": "",
    "ownershipShare": "",
    "email": ""
  }
],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "814165",
    "name": "Living Room",
    "length": "16.33",
    "length1": "16",
    "length2": "4",
    "width": "11.33",
    "width1": "11",
    "width2": "4",
```

```

"totalArea": "185.11",
"images": [],
"extraAreas": [],
"finalArea": "185.11"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Kitchen",
  "length": "16.67",
  "length1": "16",
  "length2": "8",
  "width": "8.83",
  "width1": "8",
  "width2": "10",
  "totalArea": "147.22",
  "images": [],
  "extraAreas": [],
  "finalArea": "147.22"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Passage",
  "length": "9.25",
  "length1": "9",
  "length2": "3",
  "width": "10.83",
  "width1": "10",
  "width2": "10",
  "totalArea": "100.21",
  "images": [],
  "extraAreas": [],
  "finalArea": "100.21"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },

```

```
"id": "3",
"name": "Bedroom",
"length": "10.92",
"length1": "10",
"length2": "11",
"width": "10.17",
"width1": "10",
"width2": "2",
"totalArea": "110.99",
"images": [],
"extraAreas": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "_id": "656b103ecebbe17144126e89",
    "name": "Extra ",
    "extraAreaType": "Add",
    "length": "2.92",
    "length1": "2",
    "length2": "11",
    "width": "6.92",
    "width1": "6",
    "width2": "11",
    "totalArea": "20.17"
  }
],
"finalArea": "131.16"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "5.58",
  "length1": "5",
  "length2": "7",
  "width": "6.17",
  "width1": "6",
  "width2": "2",
  "totalArea": "34.43",
  "images": [],
  "extraAreas": [],
```

```
"finalArea": "34.43"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bedroom",
  "length": "12.50",
  "length1": "12",
  "length2": "6",
  "width": "11.75",
  "width1": "11",
  "width2": "9",
  "totalArea": "146.87",
  "images": [],
  "extraAreas": [
    {
      "measurementType": {
        "value": "Square_Feet",
        "label": "Square Feet"
      },
      "_id": "656b10a3cebbe17144126eba",
      "name": "Extra",
      "extraAreaType": "Add",
      "length": "7.75",
      "length1": "7",
      "length2": "9",
      "width": "9.25",
      "width1": "9",
      "width2": "3",
      "totalArea": "71.69"
    }
  ],
  "finalArea": "218.56"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Toilet",
  "length": "7.50",
  "length1": "7",
```



```
"length2": "6",
"width": "4.58",
"width1": "4",
"width2": "7",
"totalArea": "34.37",
"images": [],
"extraAreas": [],
"finalArea": "34.37"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Balcony",
  "length": "20.92",
  "length1": "20",
  "length2": "11",
  "width": "3.75",
  "width1": "3",
  "width2": "9",
  "totalArea": "78.44",
  "images": [],
  "extraAreas": [
    {
      "measurementType": {
        "value": "Square_Feet",
        "label": "Square Feet"
      },
      "_id": "656b1182cebbe17144127187",
      "name": "Balcony 1",
      "extraAreaType": "Add",
      "length": "9.00",
      "length1": "9",
      "length2": "0",
      "width": "3.25",
      "width1": "3",
      "width2": "3",
      "totalArea": "29.25"
    },
    {
      "measurementType": {
        "value": "Square_Feet",
        "label": "Square Feet"
      },
    }
  ]
}
```

```
    "_id": "656b1195cebbe1714412719a",
    "name": "Balcony 2",
    "extraAreaType": "Add",
    "length": "5.17",
    "length1": "5",
    "length2": "2",
    "width": "11.42",
    "width1": "11",
    "width2": "5",
    "totalArea": "58.99"
  }
],
"finalArea": "166.68"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "484409",
    "selectAreaTypeDocument": "Built_Up",
    "totalAreaDocument": "1137",
    "squareMeterArea": "105.63",
    "docFinalBuiltUp": "0.00",
    "docFinalBuiltUpSquareMeter": "0.00",
    "docBUILTUPPercentage": "",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "6569b701bd53ea1a14360558",
    "property": "Residential Flat ",
    "area": "1833",
```

```
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"source": "magic_bricks",
"expectedPrice": "47500000",
"expectedRate": "25913.80",
"builtUpExpectedRate": "21594.84",
"image": "cases/653f62e1d6fbd83553d5bab2/
indicator_1701426363533_Image.png",
"squareMeter": "170.29",
"id": "684330"
},
{
  "printlnReport": true,
  "_id": "6569b701bd53ea1a14360559",
  "property": "Residential Flat ",
  "area": "1427",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "https://www.99acres.com/",
  "expectedPrice": "33500000",
  "expectedRate": "23475.82",
  "builtUpExpectedRate": "19563.19",
  "image": "cases/653f62e1d6fbd83553d5bab2/
indicator_1701426448828_Image.png",
  "squareMeter": "132.57",
  "id": "319506"
},
{
  "printlnReport": true,
  "_id": "6569b701bd53ea1a1436055a",
  "property": "Residential Flat ",
  "area": "1230",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "https://www.99acres.com/",
  "expectedPrice": "34500000",
  "expectedRate": "28048.78",
  "builtUpExpectedRate": "23373.98",
  "image": "cases/653f62e1d6fbd83553d5bab2/
indicator_1701426493133_Image.png",
```

```
"squareMeter": "114.27",
"id": "583965"
},
{
  "printlnReport": true,
  "_id": "6569b701bd53ea1a1436055b",
  "property": "Residential Flat ",
  "area": "1716.52",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Built_Up",
  "source": "Index_no.2",
  "expectedPrice": "26700000",
  "expectedRate": "15554.73",
  "builtUpExpectedRate": "0.00",
  "image": "cases/653f62e1d6fbd83553d5bab2/
indicator_1701426632932_Image.png",
  "squareMeter": "159.47",
  "id": "642586"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65409e25eb542d69409939c2",
    "name":
"externalImg_1698733605513_WhatsApp_Image_20231031_at_114451_AM.jpeg",
    "path": "cases/653f62e1d6fbd83553d5bab2/
externalImg_1698733605513_WhatsApp_Image_20231031_at_114451_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65409e25eb542d69409939c3",
    "name":
"externalImg_1698733605519_WhatsApp_Image_20231031_at_114452_AM_1.jpeg",
    "path": "cases/653f62e1d6fbd83553d5bab2/
externalImg_1698733605519_WhatsApp_Image_20231031_at_114452_AM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "65409e25eb542d69409939c4",
    "name":
"externallmg_1698733605524_WhatsApp_Image_20231031_at_114452_AM.jpeg",
    "path": "cases/653f62e1d6fbd83553d5bab2/
externallmg_1698733605524_WhatsApp_Image_20231031_at_114452_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65409e25eb542d69409939c5",
    "name":
"externallmg_1698733605532_WhatsApp_Image_20231031_at_114453_AM_1.jpeg",
    "path": "cases/653f62e1d6fbd83553d5bab2/
externallmg_1698733605532_WhatsApp_Image_20231031_at_114453_AM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65409e25eb542d69409939c6",
    "name":
"externallmg_1698733605537_WhatsApp_Image_20231031_at_114453_AM.jpeg",
    "path": "cases/653f62e1d6fbd83553d5bab2/
externallmg_1698733605537_WhatsApp_Image_20231031_at_114453_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65409e25eb542d69409939c7",
    "name":
"externallmg_1698733605542_WhatsApp_Image_20231031_at_114454_AM.jpeg",
    "path": "cases/653f62e1d6fbd83553d5bab2/
externallmg_1698733605542_WhatsApp_Image_20231031_at_114454_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65409e25eb542d69409939c8",
    "name":
"externallmg_1698733605544_WhatsApp_Image_20231031_at_114455_AM.jpeg",
    "path": "cases/653f62e1d6fbd83553d5bab2/
externallmg_1698733605544_WhatsApp_Image_20231031_at_114455_AM.jpeg",
    "orientation": "landscape"
  }
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65409e25eb542d69409939c9",
      "name":
        "externallmg_1698733605547_WhatsApp_Image_20231031_at_114456_AM_1.jpeg",
      "path": "cases/653f62e1d6fbd83553d5bab2/
externallmg_1698733605547_WhatsApp_Image_20231031_at_114456_AM_1.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65409e25eb542d69409939ca",
      "name":
        "externallmg_1698733605552_WhatsApp_Image_20231031_at_114456_AM.jpeg",
      "path": "cases/653f62e1d6fbd83553d5bab2/
externallmg_1698733605552_WhatsApp_Image_20231031_at_114456_AM.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65409e25eb542d69409939cb",
      "name":
        "externallmg_1698733605555_WhatsApp_Image_20231031_at_114130_AM.jpeg",
      "path": "cases/653f62e1d6fbd83553d5bab2/
externallmg_1698733605555_WhatsApp_Image_20231031_at_114130_AM.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65409e25eb542d69409939cc",
      "name":
        "externallmg_1698733605558_WhatsApp_Image_20231031_at_114256_AM.jpeg",
      "path": "cases/653f62e1d6fbd83553d5bab2/
externallmg_1698733605558_WhatsApp_Image_20231031_at_114256_AM.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65409e25eb542d69409939cd",
      "name":
        "externallmg_1698733605561_WhatsApp_Image_20231031_at_114258_AM.jpeg",
```

```
    "path": "cases/653f62e1d6fbd83553d5bab2/
externallmg_1698733605561_WhatsApp_Image_20231031_at_114258_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65409e25eb542d69409939ce",
    "name":
"externallmg_1698733605563_WhatsApp_Image_20231031_at_114300_AM.jpeg",
    "path": "cases/653f62e1d6fbd83553d5bab2/
externallmg_1698733605563_WhatsApp_Image_20231031_at_114300_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65409e25eb542d69409939cf",
    "name":
"externallmg_1698733605566_WhatsApp_Image_20231031_at_114316_AM.jpeg",
    "path": "cases/653f62e1d6fbd83553d5bab2/
externallmg_1698733605566_WhatsApp_Image_20231031_at_114316_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65409e25eb542d69409939d0",
    "name":
"externallmg_1698733605569_WhatsApp_Image_20231031_at_114318_AM.jpeg",
    "path": "cases/653f62e1d6fbd83553d5bab2/
externallmg_1698733605569_WhatsApp_Image_20231031_at_114318_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65409e37eb542d6940993a22",
    "name":
"externallmg_1698733623693_WhatsApp_Image_20231031_at_114321_AM.jpeg",
    "path": "cases/653f62e1d6fbd83553d5bab2/
externallmg_1698733623693_WhatsApp_Image_20231031_at_114321_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "65409e37eb542d6940993a23",
  "name":
"externallmg_1698733623696_WhatsApp_Image_20231031_at_114324_AM.jpeg",
  "path": "cases/653f62e1d6fbd83553d5bab2/
externallmg_1698733623696_WhatsApp_Image_20231031_at_114324_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65409e37eb542d6940993a24",
  "name":
"externallmg_1698733623700_WhatsApp_Image_20231031_at_114326_AM.jpeg",
  "path": "cases/653f62e1d6fbd83553d5bab2/
externallmg_1698733623700_WhatsApp_Image_20231031_at_114326_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65409e37eb542d6940993a25",
  "name":
"externallmg_1698733623707_WhatsApp_Image_20231031_at_114328_AM.jpeg",
  "path": "cases/653f62e1d6fbd83553d5bab2/
externallmg_1698733623707_WhatsApp_Image_20231031_at_114328_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65409e37eb542d6940993a26",
  "name":
"externallmg_1698733623710_WhatsApp_Image_20231031_at_114342_AM.jpeg",
  "path": "cases/653f62e1d6fbd83553d5bab2/
externallmg_1698733623710_WhatsApp_Image_20231031_at_114342_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65409e37eb542d6940993a27",
  "name":
"externallmg_1698733623715_WhatsApp_Image_20231031_at_114344_AM.jpeg",
  "path": "cases/653f62e1d6fbd83553d5bab2/
externallmg_1698733623715_WhatsApp_Image_20231031_at_114344_AM.jpeg",
```



```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65409e37eb542d6940993a28",
    "name":
"externallmg_1698733623717_WhatsApp_Image_20231031_at_114347_AM.jpeg",
    "path": "cases/653f62e1d6fbd83553d5bab2/
externallmg_1698733623717_WhatsApp_Image_20231031_at_114347_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65409e37eb542d6940993a29",
    "name":
"externallmg_1698733623720_WhatsApp_Image_20231031_at_114349_AM.jpeg",
    "path": "cases/653f62e1d6fbd83553d5bab2/
externallmg_1698733623720_WhatsApp_Image_20231031_at_114349_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65409e37eb542d6940993a2a",
    "name":
"externallmg_1698733623722_WhatsApp_Image_20231031_at_114351_AM.jpeg",
    "path": "cases/653f62e1d6fbd83553d5bab2/
externallmg_1698733623722_WhatsApp_Image_20231031_at_114351_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65409e37eb542d6940993a2b",
    "name":
"externallmg_1698733623725_WhatsApp_Image_20231031_at_114428_AM.jpeg",
    "path": "cases/653f62e1d6fbd83553d5bab2/
externallmg_1698733623725_WhatsApp_Image_20231031_at_114428_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65409e37eb542d6940993a2c",
```

```
    "name":
"externallmg_1698733623728_WhatsApp_Image_20231031_at_114429_AM.jpeg",
  "path": "cases/653f62e1d6fbd83553d5bab2/
externallmg_1698733623728_WhatsApp_Image_20231031_at_114429_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65409e37eb542d6940993a2d",
  "name":
"externallmg_1698733623731_WhatsApp_Image_20231031_at_114431_AM.jpeg",
  "path": "cases/653f62e1d6fbd83553d5bab2/
externallmg_1698733623731_WhatsApp_Image_20231031_at_114431_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65409e37eb542d6940993a2e",
  "name":
"externallmg_1698733623733_WhatsApp_Image_20231031_at_114433_AM.jpeg",
  "path": "cases/653f62e1d6fbd83553d5bab2/
externallmg_1698733623733_WhatsApp_Image_20231031_at_114433_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65409e37eb542d6940993a2f",
  "name":
"externallmg_1698733623736_WhatsApp_Image_20231031_at_114434_AM.jpeg",
  "path": "cases/653f62e1d6fbd83553d5bab2/
externallmg_1698733623736_WhatsApp_Image_20231031_at_114434_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65409e37eb542d6940993a30",
  "name":
"externallmg_1698733623738_WhatsApp_Image_20231031_at_114443_AM.jpeg",
  "path": "cases/653f62e1d6fbd83553d5bab2/
externallmg_1698733623738_WhatsApp_Image_20231031_at_114443_AM.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65409e37eb542d6940993a31",
  "name":
"externallmg_1698733623742_WhatsApp_Image_20231031_at_114444_AM.jpeg",
  "path": "cases/653f62e1d6fbd83553d5bab2/
externallmg_1698733623742_WhatsApp_Image_20231031_at_114444_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65409e37eb542d6940993a32",
  "name":
"externallmg_1698733623747_WhatsApp_Image_20231031_at_114446_AM_1.jpeg",
  "path": "cases/653f62e1d6fbd83553d5bab2/
externallmg_1698733623747_WhatsApp_Image_20231031_at_114446_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65409e37eb542d6940993a33",
  "name":
"externallmg_1698733623750_WhatsApp_Image_20231031_at_114446_AM.jpeg",
  "path": "cases/653f62e1d6fbd83553d5bab2/
externallmg_1698733623750_WhatsApp_Image_20231031_at_114446_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65409e37eb542d6940993a34",
  "name":
"externallmg_1698733623751_WhatsApp_Image_20231031_at_114447_AM.jpeg",
  "path": "cases/653f62e1d6fbd83553d5bab2/
externallmg_1698733623751_WhatsApp_Image_20231031_at_114447_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65409e37eb542d6940993a35",
  "name":
"externallmg_1698733623760_WhatsApp_Image_20231031_at_114449_AM.jpeg",
```

```
    "path": "cases/653f62e1d6fbd83553d5bab2/
externallmg_1698733623760_WhatsApp_Image_20231031_at_114449_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656b1c2ecebbe17144129387",
    "name":
"externallmg_1701518381213_WhatsApp_Image_20231202_at_43219_PM_1.jpeg",
    "path": "cases/653f62e1d6fbd83553d5bab2/
externallmg_1701518381213_WhatsApp_Image_20231202_at_43219_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656b1c2ecebbe17144129388",
    "name":
"externallmg_1701518381237_WhatsApp_Image_20231202_at_43219_PM.jpeg",
    "path": "cases/653f62e1d6fbd83553d5bab2/
externallmg_1701518381237_WhatsApp_Image_20231202_at_43219_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656b1c2ecebbe17144129389",
    "name":
"externallmg_1701518381251_WhatsApp_Image_20231202_at_43220_PM_1.jpeg",
    "path": "cases/653f62e1d6fbd83553d5bab2/
externallmg_1701518381251_WhatsApp_Image_20231202_at_43220_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656b1c2ecebbe1714412938a",
    "name":
"externallmg_1701518381260_WhatsApp_Image_20231202_at_43220_PM.jpeg",
    "path": "cases/653f62e1d6fbd83553d5bab2/
externallmg_1701518381260_WhatsApp_Image_20231202_at_43220_PM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
```

```
"processingDocuments": [
  {
    "originalname": "1701426964430_Vikas_Gupta__Flat_No_2705____CBI.xlsx",
    "filename":
"1701518640763_1701426964430_Vikas_Gupta__Flat_No_2705____CBI.xlsx",
    "path": "cases/653f62e1d6fbd83553d5bab2/processingDocuments/1701518640763
_1701426964430_Vikas_Gupta__Flat_No_2705____CBI.xlsx",
    "size": "3096564",
    "createdAt": "Sat Dec 02 2023 17:34:00 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eebe33f3dd69653a5837ae"
  },
  {
    "originalname":
"document_1698652799279_1698652835820_p_buyer_case_vikas_ganeriwal.pdf",
    "filename": "1701518654397_document_1698652799279_1698652835820_p_buyer
_case_vikas_ganeriwal.pdf",
    "path": "cases/653f62e1d6fbd83553d5bab2/processingDocuments/1701518654397
_document_1698652799279_1698652835820_p_buyer_case_vikas_ganeriwal.pdf",
    "size": "15244148",
    "createdAt": "Sat Dec 02 2023 17:34:14 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eebe33f3dd69653a5837ae"
  },
  {
    "originalname":
"document_1701425298289_rachana_ganeriwala_central_malad_omkar_case.pdf",
    "filename": "1701518654698_document_1701425298289_rachana_ganeriwala_cent
ral_malad_omkar_case.pdf",
    "path": "cases/653f62e1d6fbd83553d5bab2/processingDocuments/1701518654698
_document_1701425298289_rachana_ganeriwala_central_malad_omkar_case.pdf",
    "size": "9456958",
    "createdAt": "Sat Dec 02 2023 17:34:14 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eebe33f3dd69653a5837ae"
  }
],
"remarks": [
  {
    "createdBy": {
      "_id": "64dc7184ccaf1e7b7f637f47",
      "role": "FRONTDESK",
      "firstName": "Binumon",
      "lastName": "Moozhickal",
      "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
  }
]
```

```
"status": true,
  "_id": "6541f7cdcad8865a54daf560",
  "note": "Pending for Draft agreement ( draft agreement expecting after Diwali)",
  "taskId": "653f784ad6fbd83553d5df60",
  "createdAt": "2023-11-01T07:01:33.495Z"
}
],
"createdAt": "2023-10-30T08:01:37.398Z",
"updatedAt": "2023-12-02T12:21:32.888Z",
"__v": 0,
"invoiceId": "653f62e3d6fbd83553d5badd",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 2705, 27th Floor, Wing - A, Altamonte Tower A Co-
op. Hsg. Soc. Ltd., Near Shantaram Talao, Pathanwadi, Kokanipada, Off. Western
Express Highway, Village - Malad (East), Taluka - Borivali, District - Mumbai Suburban,
Malad (East), Mumbai, PIN - 400 097, State - Maharashtra, India",
"updatedBy": "64dc7184ccaf1e7b7f637f47",
"addressForMap": "",
"caseReferredBy": "627219d6afd7d55eddedd283",
"contactPersonName": "Mr. Vikas Ganeriwala",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9322255556",
"buildingServicesRate": "3100",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 1137.00",
"flatRate": "21300",
"landOtherRate": "18200",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + Passage + 2 Toilet +
Balcony",
```

```

"carpetTotal": "1017.74",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "1119.51",
"finalCarpetArea": "1017.74",
"finalSalableArea": "1231.47",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Sat Dec 02 2023 16:09:37 GMT+0530 (India Standard Time)",
"siteVisitDate": "2023-11-26",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00",
"leadRemarks": [],
"audioRemarks": []
}

```

Name	Length	Width	Total
Composition :			
Living Room	16'4"	11'4"	185.11
Kitchen	16'8"	8'10"	147.22
Passage	9'3"	10'10"	100.21

Bedroom	10'11"	10'2"	110.99
Toilet	5'7"	6'2"	34.43
Bedroom	12'6"	11'9"	146.87
Toilet	7'6"	4'7"	34.37
Balcony	20'11"	3'9"	78.44
Other Composition :			