

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "645cdef97f94762ec78921f9"
    },
    "type": "CREDITOFFICER",
    "_id": "645cdef97f94762ec78921fb",
    "firstName": "Racpc ",
    "lastName": "Pen",
    "mobileNo": "",
    "workMobileNo": "9784010678",
    "email": "sbi.64071@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "3535100",
    "discussWithPerson": "Racpc ",
    "expectedFees": 1767.55,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "645cdef97f94762ec78921f9",
  "name": "Racpc Pen\t",
  "branchCode": "",
  "mobileNo": "02222742431",
  "alternateMobileNo": "",
  "email": "sbi.64071@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Astha Building , Pen Dharmatar Road, Near BSNL Office, Pen 402107\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60b7189d2ffdf65bcd65882b",
    "role": "PICKUPPERSON",
```

```
"firstName": "Ravindra",
"email": "ravindrakasare186@gmail.com",
"lastName": "Kasare",
"mobileNo": "9167204055",
"shortName": "RBK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60b7189d2ffdf65bcd65882b\
\profilePhoto_1622701555488_WhatsApp Image 2021-06-03 at 11.46.40 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f9343b45132d6a6bdd96e8",
  "role": "SITEENGINEER",
  "firstName": "Rajesh",
  "email": "rajeshb.ghadi@gmail.com",
  "lastName": "Ghadi",
  "mobileNo": "8652092666",
  "designation": "",
  "shortName": "RHG",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64dc7184ccaf1e7b7f637f47",
  "role": "FRONTDESK",
  "firstName": "Binumon",
  "email": "binu@vastukala.org",
  "lastName": "Moozhickal",
  "mobileNo": "9930252906",
  "designation": "Back Office Team Leader",
  "shortName": "BS",
  "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
  "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60eebe33f3dd69653a5837ae",
  "role": "MAKER",
  "firstName": "Shamal",
  "email": "shamal@vastukala.org",
  "lastName": "Bodke",
  "mobileNo": "9821740317",
  "designation": "",
  "shortName": "SB",
  "workWithDocumentMaker": ""
```

```
"profilePhoto": "users\\60eebe33f3dd69653a5837ae\\
\\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
},
"checker": "",
"valuers": [
{
  "valuersRegistrationNumber": [
    {
      "value": "[N]C.C.I.T/I -14/52/2008-09",
      "label": "Wealth Tax"
    }
  ],
  "type": "EMPLOYEE",
  "_id": "6084131a13f01f158c6ea1f3",
  "PANNo": "AEAPC7114Q",
  "role": "VALUER",
  "firstName": "Sharadkumar",
  "fatherName": "Baburao",
  "email": "cmd@vastukala.org",
  "lastName": " Chalikwar",
  "mobileNo": "9422171100",
  "designation": "CMD",
  "registrationNo": [
    {
      "title": {
        "value": "Wealth_Tax",
        "label": "Wealth Tax"
      },
      "_id": "6084131a13f01f158c6ea1f4",
      "number": "[N]C.C.I.T/I -14/52/2008-09"
    }
  ],
  "shortName": "SBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "18.96277417780576",
  "longitude": "73.03455737975968"
```

```
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.03455737975968,
    18.96277417780576
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "2023-11-03T06:00:00.000Z",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Vahal",
  }
}
```

```
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "2",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Raigad",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Navi Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Panvel",
  "label": true
},
"plotNo": {
  "status": true,
```

```
"name": "Plot No.",
"key": "plotNo",
"value": "211",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Sai Priya Corner",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "25",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Pushpak Node",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
}
```

```
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
```



```
"key": "selectNo",
"value": "203",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
}
```

```
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 410 206",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "0",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "buildingServicesDepreciatedRate": "0",
  "depreciatedCostOfConstruction": "8800.00",
  "depreciatedBuildingRate": "2800"
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "82500",
  "landRate": "17500",
  "igrImage": "cases/6543b37b99e3743444bcfaa6/igr_1699073722177_Image.png",
  "squareMeterGuideLineRate": "82500.00",
  "squareFeetGuideLineRate": "7665.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0.00",
  "rate": "82500.00",
  "squareMeterGuideLineRate": "82500.00",
  "squareFeetGuideLineRate": "7665.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
}
```

```
"siteMeasurement": {
  "constructionWorkStatus": {
    "value": "InProgress",
    "label": "Under Construction"
  },
  "dateOfConstruction": {
    "fullDate": "1/1/2024",
    "date": "1",
    "month": "1",
    "year": "2024"
  },
  "typeOfStructure": {
    "value": "R.C.C.",
    "label": "R.C.C. Framed"
  },
  "yearOfConstructionAsPer": {
    "value": "As_per_RERA_Certificate",
    "label": "As per RERA Certificate"
  },
  "isSiteVisitAllowed": true,
  "ageOfBuilding": "",
  "totalLifeBuilding": "60",
  "estimatedAge": "",
  "noOfLifts": "1"
},
"finalPlinthArea": {
  "areaType": "Built Up",
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": ""
  }
}
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "3265443.00",
  "selectedBuildUpValue": "426.02",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "8072",
    "max": "9211"
  },
  "builtUpRateRange": {
    "min": "7983",
    "max": null
  }
}
```

```
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
    "title": "Interior Decorations",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
```



```
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "387.29",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentId": [],
"_id": "6543b37b99e3743444bcfaa6",
"ownerName": "Shrawani Krishna Koli",
"ownerPhoneNo": "9223596088",
"appAddress": "flat no 203 3nt floor Bldg sai priya plot no 211 . sector no 25pushpak
Node vahal",
"remark": "Ajay Ambilpure 9820889476",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "path": "cases/6543b37b99e3743444bcfaa6/
document_1698987737730_Koli_sbi_Racpc_pen.pdf",
    "fileName": "document_1698987737730_Koli_sbi_Racpc_pen.pdf",
    "displayStatus": false,
    "id": "728097",
    "uploadedBy": "60b7189d2ffdf65bcd65882b",
```

```
"createdAt": "Fri Nov 03 2023 10:32:55 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "004843",
"createdBy": "60b7189d2ffdf65bcd65882b",
"caseHistory": [
{
  "id": "697008",
  "title": "Create Lead",
  "description": "Create Lead",
  "datetime": "Thu Nov 02 2023 20:04:35 GMT+0530 (India Standard Time)"
}
],
"owners": [
{
  "name": "Shrawani Krishna Koli",
  "phone": "9223596088",
  "ownershipShare": "",
  "email": "",
  "id": "750281"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "label": "Agreement For Sale",
    "value": "60ae1254aa6d152c1801b326"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "selectAreaTypeDocument": "Carpet",
  "squareMeterArea": "35.98",
  "totalAreaDocument": "387.29",
  "docBultupPercentage": "10",
  "docFinalBultUp": "426.02",
  "docFinalBultUpSquareMeter": "39.58",
  "docSaleablePercentage": "",
  "docFinalSaleable": "0.00",
  "docFinalSaleableSquareMeter": "0.00",
```

```
    "id": "732496"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "6545cee899ec7e6193deddcc",
    "property": "Residential Flat",
    "area": "380",
    "builtUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "https://www.99acres.com/",
    "expectedPrice": "3500000",
    "expectedRate": "9210.53",
    "builtUpExpectedRate": "8373.21",
    "image": "cases/6543b37b99e3743444bcfaa6/
indicator_1699072189227_Image.png",
    "squareMeter": "35.30",
    "id": "736524"
  },
  {
    "printlnReport": true,
    "_id": "6545cee899ec7e6193deddcd",
    "property": "Residential Flat",
    "area": "410",
    "builtUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "https://www.99acres.com/",
    "expectedPrice": "3600000",
    "expectedRate": "8780.49",
    "builtUpExpectedRate": "7982.26",
    "image": "cases/6543b37b99e3743444bcfaa6/
indicator_1699072298020_Image.png",
    "squareMeter": "38.09",
    "id": "294999"
  },
  {
    "printlnReport": true,
    "_id": "6545cee899ec7e6193deddce",
    "property": "Residential Flat",
    "area": "463.32",
```

```
"builtUpPercentage": "0",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Built_Up",
"floor": "4",
"source": "Index_no.2",
"expectedPrice": "3400000",
"expectedRate": "Infinity",
"builtUpExpectedRate": "0.00",
"image": "cases/6543b37b99e3743444bcfaa6/
indicator_1699072945838_Image.png",
"squareMeter": "43.04",
"id": "580419"
}
],
"externalImages": [],
"externalDocuments": [],
"processingDocuments": [
{
  "originalname": "SHRAWANI KRISHNA KOLI - Flat No. 203 - SBI.xlsx",
  "filename":
"1699073791814_SHRAWANI_KRISHNA_KOLI__Flat_No_203__SBI.xlsx",
  "path": "cases/6543b37b99e3743444bcfaa6/processingDocuments/1699073791814
_SHRAWANI_KRISHNA_KOLI__Flat_No_203__SBI.xlsx",
  "size": "2091363",
  "createdAt": "Sat Nov 04 2023 10:26:31 GMT+0530 (India Standard Time)",
  "uploadedBy": "64dc7184ccaf1e7b7f637f47"
}
],
"remarks": [
{
  "createdBy": {
    "_id": "64dc7184ccaf1e7b7f637f47",
    "role": "FRONTDESK",
    "firstName": "Binumon",
    "lastName": "Moozhickal",
    "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
  },
  "workType": "RATE_VERIFY",
  "display": true,
  "status": true,
  "_id": "65449e7a99e3743444bde595",
  "note": "Value Given For Confirmation",
  "taskId": "65448fd099e3743444bda318",
  "createdAt": "2023-11-03T07:17:14.384Z"
```

```

    }
  ],
  "createdAt": "2023-11-02T14:34:36.014Z",
  "updatedAt": "2023-11-07T05:32:41.657Z",
  "__v": 0,
  "updatedBy": "60eebe33f3dd69653a5837ae",
  "assignmentType": {
    "value": "Retail",
    "label": "Retail"
  },
  "fullAddress": "Residential Flat No. 203, 2nd Floor, Sai Priya Corner, Plot No. 211, Sector 25, Pushpak Node, Village - Vahal, Taluka - Panvel, District - Raigad, Navi Mumbai, PIN - 410 206, State - Maharashtra, India",
  "addressForMap": "",
  "caseReferredBy": "60b7189d2ffdf65bcd65882b",
  "contactPersonName": "Shrawani Krishna Koli",
  "email": "",
  "isExternal": "false",
  "isUrgent": "false",
  "ownershipShare": "",
  "purchaseValueAsPerDocument": "",
  "relationWithOwner": "self",
  "siteVisitContactNo": "9223596088",
  "buildingServicesRate": "2800",
  "finalAreaType": "Carpet Area",
  "finalAsPerArea": "Agreement For Sale",
  "finalBuiltUpPercentage": "10",
  "finalCarpetConvertToBuiltUpPer": "10",
  "finalMeasurementType": "Sq. Ft.",
  "finalValuationAreaString": "Carpet Area in Sq. Ft. = 387.29",
  "flatRate": "8800",
  "landOtherRate": "6000"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			