

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b81e"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94230d0f",
    "firstName": "Swapana Kumar",
    "email": "bmmums0617@centralbank.co.in",
    "mobileNo": "-",
    "workMobileNo": "9920758578",
    "lastName": "Das"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5000000",
    "discussWithPerson": "Swapana Kumar",
    "expectedFees": 2500,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17fa",
  "type": "BANK",
  "name": "Central Bank of India",
  "displayName": "Central Bank of India",
  "initial": "CBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b81e",
  "branchCode": "280617 ",
  "type": "BRANCH",
  "name": "Mahim Branch",
  "email": "bmmumn0617@centralbank.co.in",
  "mobileNo": "022-2445 3999",
  "alternateMobileNo": "",
  "address": "Mohammedin House, Behind Shafi Mansion, 57, Lady Jamshedji Marg,
Mahim, Mumbai - 400 016, State - Maharashtra, Country - India.",
  "ledgerName": "CENTRAL BANK OF INDIA - MAHIM",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60f917e0f3dd69653a592221",
  "zoneName": "South Mumbai Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
  "_id": "62723addafd7d55eddeddfe4",
  "role": "PICKUPPERSON",
  "firstName": "Ramkrishna ",
  "email": "rampatakar1991@gmail.com",
  "lastName": "Patkar",
  "mobileNo": "7045746060",
  "shortName": "RP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62723addafd7d55eddeddfe4/
profilePhoto_1668056044525_WhatsApp_Image_20221110_at_102139_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "64c8cdd2a5c3051014f62c65",
  "role": "SITEENGINEER",
  "firstName": "Bhavesh",
  "email": "freelancevaluer@gmail.com",
  "lastName": "Shelar",
  "mobileNo": "9272696074",
  "designation": "",
  "shortName": "BSS",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/64c8cdd2a5c3051014f62c65/profilePhoto_1690881490040_3
25961526_225125063269350_5532229620043102208_n.jpg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shym_Photo.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60eebe33f3dd69653a5837ae",
  "role": "MAKER",
  "firstName": "Shamal",
  "email": "shamal@vastukala.org",
  "lastName": "Bodke",
```

```
"mobileNo": "9821740317",
"designation": "",
"shortName": "SB",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eebe33f3dd69653a5837ae\
\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  "type": "EMPLOYEE",
  "_id": "5ffe92d27737ca4d986b6453",
  "role": "VALUER",
  "firstName": "Manoj",
  "email": "manoj@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9819597579",
  "designation": "Registered Valuer",
  "registrationNo": [
    {
      "title": {
        "label": "IBBI"
      },
      "_id": "60af80072ffdf65bcd658651",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  {
```

```
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.819719634823063",
  "longitude": "72.75635132444368"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.75635132444368,
    19.819719634823063
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-11-06T11:00:00.000Z",
      "remark": ""
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-11-07",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-11-07",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "3BHK",
  "label": "3 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
```

```
"key": "country",
"value": "India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Saravali",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "7",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "4",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Palghar",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Boisar (West), Palghar",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
```

```
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Palghar",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "RH-81",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Castor",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Tarapur Industrial Area",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
```



```
"value": "Near Rahul International School",
"label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Thakur Galaxy",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
```

```
"status": false,
"name": "Block No",
"key": "blockNo",
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "704",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
```

```
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 401 501",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_door_frame,_Flush_doors_shutters",
    "label": "Teak Wood door frame, Flush doors shutters"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
}
```

```
"finishing": {
  "value": "Cement_Plastering_with_POP_false_Celling",
  "label": "Cement Plastering with POP false Ceiling"
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Maharashtra_Industrial_Development_Corporation",
    "label": "Maharashtra Industrial Development Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Building No. 5",
    "west": "Internal Road & Building",
    "south": "Building No. 3",
    "east": "Internal Road"
  },
  "asPerDocumentAgreement": {
    "north": "Details not available",
    "west": "Details not available",
    "south": "Details not available",
    "east": "Details not available"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "Details not available",
      "east": "Details not available",
      "south": "Details not available",
      "west": "Details not available"
    },
    "asPerDocument": {
```

```
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of Building Completion Certificate No. IFMS / DE /
TD / TRP / CO4175 / 2017 Dated 06.06.2017 issued by Maharashtra Industrial
Development Corporation. ",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A."
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "9",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "6275",
  "depreciatedBuildingRate": "2275"
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "33600",
  "landRate": "3440",
  "igrImage": "cases/6548c428594ccb46f00241e1/igr_1699358190045_Image.png",
  "squareMeterGuideLineRate": "35280.00",
  "squareFeetGuideLineRate": "3278.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0.00",
  "depreciationPercentage": "94",
  "rate": "3100.00",
  "squareFeetGuideLineRate": "3100.00",
  "squareMeterGuideLineRate": "33370.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Middle_Class",
    "label": "Middle Class"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  }
}
```

```
},
"propertyOccupiedByList": {
  "value": "Tenant_Occupied",
  "label": "Tenant Occupied"
},
"monthlyRent": "Details not available",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "103251023038",
"meterCardHolderName": "Mrs. Nilima Prakash Shivde",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per MIDC norms",
"tenantName": "Ram Vilas",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Stilt + Open Car Parking",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  }
},
```

```
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2017",
  "fullDate": "1/1/2017"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
```

```
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
  "value": "Part_Ground_and_Part_Stilt",
  "label": "Part Ground + Part Stilt"
},
"yearOfConstructionAsPer": {
  "value": "Building_Completion_Certificate",
  "label": "Building Completion Certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "54",
"ageOfBuilding": "6",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "7",
"flatFloorNo": "7",
"noOfLifts": "1",
```



```
"noOfDwellingUnitsInBuilding": "6"
},
"finalPlinthArea": {
  "areaType": "Built Up",
  "area": "878.40",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/6548c428594ccb46f00241e1/
routeMap_1699360283357_Image.png",
    "routeLat": "19.792306",
    "routeLng": "72.756972",
    "stationName": "Boisar",
    "routeDistance": "1.1 Km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "if1kt8",
      "name": "if1kt8",
      "image": "cases/6548c428594ccb46f00241e1/
routeMap_1699360224652_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
```

```
"showcasesRate": "0",
"totalshowcasesRate": "0",
"kitchenArrangementsQty": "0",
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "4593300.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "4593300.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Wed Nov 08 2023 10:36:23 GMT+0530 (India Standard Time)",
  "number": "2303425",
  "dayCount": "1",
  "monthCount": "121",
  "generatedBy": "60eeaeddf3dd69653a581316"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": true
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
```

```
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "2723040.00",
  "selectedBuildUpValue": "878.40",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "654a0ad4637db60f88b48f7d",
      "name":
"externalImg_1699351251911_WhatsApp_Image_20231107_at_32116_PM_1.jpeg",
      "path": "cases/6548c428594ccb46f00241e1/
externalImg_1699351251911_WhatsApp_Image_20231107_at_32116_PM_1.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "654a0ae4637db60f88b48fcb",
      "name":
"externalImg_1699351268493_WhatsApp_Image_20231107_at_32120_PM_3.jpeg",
```

```
    "path": "cases/6548c428594ccb46f00241e1/
externallmg_1699351268493_WhatsApp_Image_20231107_at_32120_PM_3.jpeg",
    "orientation": "portrait"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "654a0ad4637db60f88b48f74",
    "name":
"externallmg_1699351251886_WhatsApp_Image_20231107_at_32113_PM_2.jpeg",
    "path": "cases/6548c428594ccb46f00241e1/
externallmg_1699351251886_WhatsApp_Image_20231107_at_32113_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "654a0ad4637db60f88b48f7a",
    "name":
"externallmg_1699351251903_WhatsApp_Image_20231107_at_32115_PM_1.jpeg",
    "path": "cases/6548c428594ccb46f00241e1/
externallmg_1699351251903_WhatsApp_Image_20231107_at_32115_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "654a0ae4637db60f88b48fce",
    "name":
"externallmg_1699351268502_WhatsApp_Image_20231107_at_32121_PM_2.jpeg",
    "path": "cases/6548c428594ccb46f00241e1/
externallmg_1699351268502_WhatsApp_Image_20231107_at_32121_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "654a0ad4637db60f88b48f7d",
    "name":
"externallmg_1699351251911_WhatsApp_Image_20231107_at_32116_PM_1.jpeg",
    "path": "cases/6548c428594ccb46f00241e1/
externallmg_1699351251911_WhatsApp_Image_20231107_at_32116_PM_1.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
```

```
    "status": false,
    "_id": "654a0ad4637db60f88b48f6d",
    "name":
"externallmg_1699351251856_WhatsApp_Image_20231107_at_32111_PM_1.jpeg",
    "path": "cases/6548c428594ccb46f00241e1/
externallmg_1699351251856_WhatsApp_Image_20231107_at_32111_PM_1.jpeg",
    "orientation": "portrait"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "654a0ad4637db60f88b48f70",
    "name": "Living Room",
    "path": "cases/6548c428594ccb46f00241e1/
externallmg_1699351251872_WhatsApp_Image_20231107_at_32112_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "654a0ad4637db60f88b48f73",
    "name": "Living Room",
    "path": "cases/6548c428594ccb46f00241e1/
externallmg_1699351251883_WhatsApp_Image_20231107_at_32113_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "654a0ad4637db60f88b48f78",
    "name": "Living Room",
    "path": "cases/6548c428594ccb46f00241e1/
externallmg_1699351251899_WhatsApp_Image_20231107_at_32114_PM_3.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "654a0ad4637db60f88b48f7b",
    "name": "Living Room",
    "path": "cases/6548c428594ccb46f00241e1/
externallmg_1699351251905_WhatsApp_Image_20231107_at_32115_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "654a0ad4637db60f88b48f7e",
    "name": "Living Room",
```

```
    "path": "cases/6548c428594ccb46f00241e1/
externallmg_1699351251916_WhatsApp_Image_20231107_at_32116_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "654a0ae4637db60f88b48fc1",
    "name": "Living Room",
    "path": "cases/6548c428594ccb46f00241e1/
externallmg_1699351268465_WhatsApp_Image_20231107_at_32117_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "654a0ae4637db60f88b48fc7",
    "name": "Living Room",
    "path": "cases/6548c428594ccb46f00241e1/
externallmg_1699351268482_WhatsApp_Image_20231107_at_32119_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "654a0ae4637db60f88b48fcf",
    "name": "Living Room",
    "path": "cases/6548c428594ccb46f00241e1/
externallmg_1699351268505_WhatsApp_Image_20231107_at_32121_PM.jpeg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "5921",
    "max": "7855"
  },
  "builtUpRateRange": {
    "min": "0",
    "max": "6546"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```



```
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
```

```
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "732.00",
"empanelmentNo": [
  "SMRO /CREDIT/2017-18/1311"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REPORTGENERATED",
"paymentId": [],
"_id": "6548c428594ccb46f00241e1",
"ownerName": "Mrs. Nilima Prakash Shivde",
"ownerPhoneNo": "7972158171",
"appAddress": "flat no 704, 7th floor , A wing , sarawli, plot no RH 81, Thakur galaxy,
caster, Palghar ",
"remark": "tomorrow visit, urgent report required ",
"documents": [
  {
    "documentType": {
      "value": "60ae126eaa6d152c1801b39f",
      "label": "Agreement"
    },
    "inputs": {
      "documentDate": "14/02/2022",
      "from": {
        "value": "Developers",
        "label": "Developers"
      },
      "Developers": "M/s. Instacroissance Limited",
      "to": {
        "value": "Purchasers",
        "label": "Purchasers"
      },
      "Purchasers": "Mrs. Nilima Prakash Shivde"
    }
  },

```

```
"isHardCopy": false,
"displayStatus": true,
"id": "972514",
"path": "cases/6548c428594ccb46f00241e1/
document_1699267501394_1699267548923_CBI_mahim.pdf",
"fileName": "document_1699267501394_1699267548923_CBI_mahim.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "19/01/2015",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Industrial_Development_Corporation",
      "label": "Maharashtra Industrial Development Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "IFMS / DE / SPA / TRP / A21395 / 2015"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1699359499187_CC.pdf",
  "path": "cases/6548c428594ccb46f00241e1/document_1699359499187_CC.pdf",
  "id": "456752",
  "uploadedBy": "60eebe33f3dd69653a5837ae",
  "createdAt": "Tue Nov 07 2023 17:48:19 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1267aa6d152c1801b380",
    "label": "Building Completion Certificate"
  },
  "inputs": {
    "documentDate": "06/06/2017",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Industrial_Development_Corporation",
      "label": "Maharashtra Industrial Development Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  }
}
```

```
    },
    "No": "IFMS / DE / TD / TRP / CO4175 / 2017"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1699359647952_Completion.pdf",
  "path": "cases/6548c428594ccb46f00241e1/
document_1699359647952_Completion.pdf",
  "id": "317257",
  "uploadedBy": "60eebe33f3dd69653a5837ae",
  "createdAt": "Tue Nov 07 2023 17:50:48 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "6077c791395bc80714864a30",
    "label": "Electricity Bill"
  },
  "inputs": {
    "documentDate": "12/07/2023",
    "number": {
      "value": "Consumer_No",
      "label": "Consumer No"
    },
    "Consumer_No": "103251023038"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1699360055127_243529.pdf",
  "path": "cases/6548c428594ccb46f00241e1/
document_1699360055127_243529.pdf",
  "id": "283435",
  "uploadedBy": "60eebe33f3dd69653a5837ae",
  "createdAt": "Tue Nov 07 2023 17:57:35 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "004924",
"createdBy": "62723addafd7d55eddeddfe4",
"caseHistory": [
  {
    "id": "278637",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Nov 06 2023 16:17:04 GMT+0530 (India Standard Time)"
  }
],
"owners": [
```

```
{
  "name": "Mrs. Nilima Prakash Shivde",
  "phone": "7972158171",
  "ownershipShare": "",
  "email": "",
  "id": "371650"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "11",
    "name": "Living Room",
    "length": "8.33",
    "length1": "8",
    "length2": "4",
    "width": "15.92",
    "width1": "15",
    "width2": "11",
    "totalArea": "132.64",
    "images": [],
    "finalArea": "132.64",
    "extraAreas": []
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "11",
    "name": "Kitchen",
    "length": "6.92",
    "length1": "6",
    "length2": "11",
    "width": "9.08",
    "width1": "9",
    "width2": "1",
    "totalArea": "62.83",
    "images": [],
    "finalArea": "62.83",
    "extraAreas": []
  }
]
```

```
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "11",
  "name": "Bedroom",
  "length": "6.67",
  "length1": "6",
  "length2": "8",
  "width": "11.92",
  "width1": "11",
  "width2": "11",
  "totalArea": "79.44",
  "images": [],
  "finalArea": "79.44",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "11",
  "name": "Bedroom",
  "length": "11.92",
  "length1": "11",
  "length2": "11",
  "width": "8.92",
  "width1": "8",
  "width2": "11",
  "totalArea": "106.26",
  "images": [],
  "finalArea": "106.26",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "11",
  "name": "Bedroom",
  "length": "8.92",
  "length1": "8",
```

```
"length2": "11",
"width": "10.17",
"width1": "10",
"width2": "2",
"totalArea": "90.65",
"images": [],
"finalArea": "90.65",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "11",
  "name": "Toilet",
  "length": "4.08",
  "length1": "4",
  "length2": "1",
  "width": "5.92",
  "width1": "5",
  "width2": "11",
  "totalArea": "24.16",
  "images": [],
  "finalArea": "24.16",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "11",
  "name": "Toilet",
  "length": "6.08",
  "length1": "6",
  "length2": "1",
  "width": "3.92",
  "width1": "3",
  "width2": "11",
  "totalArea": "23.83",
  "images": [],
  "finalArea": "23.83",
  "extraAreas": []
},
{
```



```
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "11",
"name": "Toilet",
"length": "5.83",
"length1": "5",
"length2": "10",
"width": "3.75",
"width1": "3",
"width2": "9",
"totalArea": "21.87",
"images": [],
"finalArea": "21.87",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "11",
  "name": "Passage",
  "length": "2.58",
  "length1": "2",
  "length2": "7",
  "width": "4.50",
  "width1": "4",
  "width2": "6",
  "totalArea": "11.62",
  "images": [],
  "finalArea": "39.57",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "11",
  "name": "Dining",
  "length": "10.58",
  "length1": "10",
  "length2": "7",
  "width": "7.08",
```

```
"width1": "7",
"width2": "1",
"totalArea": "74.97",
"images": [],
"finalArea": "74.97",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "10",
  "name": "Balcony",
  "length": "1.83",
  "length1": "1",
  "length2": "10",
  "width": "16.17",
  "width1": "16",
  "width2": "2",
  "totalArea": "29.64",
  "images": [],
  "extraAreas": [],
  "finalArea": "29.64"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "11",
  "name": "Balcony",
  "length": "2.17",
  "length1": "2",
  "length2": "2",
  "width": "8.33",
  "width1": "8",
  "width2": "4",
  "totalArea": "18.06",
  "images": [],
  "extraAreas": [],
  "finalArea": "18.06"
},
{
  "measurementType": {
    "value": "Square_Feet",
```

```
    "label": "Square Feet"
  },
  "id": "12",
  "name": "Passage",
  "length": "2.83",
  "length1": "2",
  "length2": "10",
  "width": "2.08",
  "width1": "2",
  "width2": "1",
  "totalArea": "5.90",
  "images": [],
  "extraAreas": [],
  "finalArea": "5.90"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "13",
  "name": "Passage",
  "length": "2.08",
  "length1": "2",
  "length2": "1",
  "width": "11.17",
  "width1": "11",
  "width2": "2",
  "totalArea": "23.26",
  "images": [],
  "extraAreas": [],
  "finalArea": "23.26"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60ae126eaa6d152c1801b39f",
      "label": "Agreement"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    }
  },

```

```
"id": "155100",
"selectAreaTypeDocument": "Carpet",
"totalAreaDocument": "732",
"squareMeterArea": "68.01",
"docFinalBuiltUp": "878.4",
"docFinalBuiltUpSquareMeter": "81.61200000000001",
"docBuiltupPercentage": "20",
"docSaleablePercentage": "0",
"docFinalSaleable": "0",
"docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "654a25f5637db60f88b4de93",
  "property": "Residential Flat",
  "area": "662",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "Housing.Com",
  "expectedPrice": "4718000",
  "expectedRate": "7126.89",
  "builtUpExpectedRate": "5939.07",
  "image": "cases/6548c428594ccb46f00241e1/
indicator_1699357513323_Image.png",
  "squareMeter": "61.50",
  "id": "905616"
},
{
  "printlnReport": true,
  "_id": "654a25f5637db60f88b4de94",
  "property": "Residential Flat",
  "area": "662",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "Housing.Com",
  "expectedPrice": "5200000",
  "expectedRate": "7854.98",
  "builtUpExpectedRate": "6545.82",
  "image": "cases/6548c428594ccb46f00241e1/
indicator_1699357554371_Image.png",
```

```
"squareMeter": "61.50",
"id": "568442"
},
{
  "printlnReport": true,
  "_id": "654a25f5637db60f88b4de96",
  "property": "Residential Flat",
  "area": "993",
  "builtUpPercentage": "0",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "source": "square_yards",
  "expectedPrice": "4900000",
  "expectedRate": "4934.54",
  "builtUpExpectedRate": "0.00",
  "image": "cases/6548c428594ccb46f00241e1/
indicator_1699358069415_Image.png",
  "squareMeter": "92.25",
  "id": "253166"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "654a0ad4637db60f88b48f6d",
    "name":
"externalImg_1699351251856_WhatsApp_Image_20231107_at_32111_PM_1.jpeg",
    "path": "cases/6548c428594ccb46f00241e1/
externalImg_1699351251856_WhatsApp_Image_20231107_at_32111_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "654a0ad4637db60f88b48f6e",
    "name":
"externalImg_1699351251861_WhatsApp_Image_20231107_at_32111_PM.jpeg",
    "path": "cases/6548c428594ccb46f00241e1/
externalImg_1699351251861_WhatsApp_Image_20231107_at_32111_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "654a0ad4637db60f88b48f6f",
    "name":
"externallmg_1699351251867_WhatsApp_Image_20231107_at_32112_PM_1.jpeg",
    "path": "cases/6548c428594ccb46f00241e1/
externallmg_1699351251867_WhatsApp_Image_20231107_at_32112_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "654a0ad4637db60f88b48f70",
    "name":
"externallmg_1699351251872_WhatsApp_Image_20231107_at_32112_PM_2.jpeg",
    "path": "cases/6548c428594ccb46f00241e1/
externallmg_1699351251872_WhatsApp_Image_20231107_at_32112_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "654a0ad4637db60f88b48f71",
    "name":
"externallmg_1699351251874_WhatsApp_Image_20231107_at_32112_PM_3.jpeg",
    "path": "cases/6548c428594ccb46f00241e1/
externallmg_1699351251874_WhatsApp_Image_20231107_at_32112_PM_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "654a0ad4637db60f88b48f72",
    "name":
"externallmg_1699351251879_WhatsApp_Image_20231107_at_32112_PM.jpeg",
    "path": "cases/6548c428594ccb46f00241e1/
externallmg_1699351251879_WhatsApp_Image_20231107_at_32112_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "654a0ad4637db60f88b48f73",
    "name":
"externallmg_1699351251883_WhatsApp_Image_20231107_at_32113_PM_1.jpeg",
    "path": "cases/6548c428594ccb46f00241e1/
externallmg_1699351251883_WhatsApp_Image_20231107_at_32113_PM_1.jpeg",
    "orientation": "portrait"
  }
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "654a0ad4637db60f88b48f74",
  "name":
"externallmg_1699351251886_WhatsApp_Image_20231107_at_32113_PM_2.jpeg",
  "path": "cases/6548c428594ccb46f00241e1/
externallmg_1699351251886_WhatsApp_Image_20231107_at_32113_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "654a0ad4637db60f88b48f75",
  "name":
"externallmg_1699351251891_WhatsApp_Image_20231107_at_32113_PM.jpeg",
  "path": "cases/6548c428594ccb46f00241e1/
externallmg_1699351251891_WhatsApp_Image_20231107_at_32113_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "654a0ad4637db60f88b48f76",
  "name":
"externallmg_1699351251893_WhatsApp_Image_20231107_at_32114_PM_1.jpeg",
  "path": "cases/6548c428594ccb46f00241e1/
externallmg_1699351251893_WhatsApp_Image_20231107_at_32114_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "654a0ad4637db60f88b48f77",
  "name":
"externallmg_1699351251896_WhatsApp_Image_20231107_at_32114_PM_2.jpeg",
  "path": "cases/6548c428594ccb46f00241e1/
externallmg_1699351251896_WhatsApp_Image_20231107_at_32114_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "654a0ad4637db60f88b48f78",
  "name":
"externallmg_1699351251899_WhatsApp_Image_20231107_at_32114_PM_3.jpeg",
```

```
    "path": "cases/6548c428594ccb46f00241e1/
externallmg_1699351251899_WhatsApp_Image_20231107_at_32114_PM_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "654a0ad4637db60f88b48f79",
    "name":
"externallmg_1699351251901_WhatsApp_Image_20231107_at_32114_PM.jpeg",
    "path": "cases/6548c428594ccb46f00241e1/
externallmg_1699351251901_WhatsApp_Image_20231107_at_32114_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "654a0ad4637db60f88b48f7a",
    "name":
"externallmg_1699351251903_WhatsApp_Image_20231107_at_32115_PM_1.jpeg",
    "path": "cases/6548c428594ccb46f00241e1/
externallmg_1699351251903_WhatsApp_Image_20231107_at_32115_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "654a0ad4637db60f88b48f7b",
    "name":
"externallmg_1699351251905_WhatsApp_Image_20231107_at_32115_PM_2.jpeg",
    "path": "cases/6548c428594ccb46f00241e1/
externallmg_1699351251905_WhatsApp_Image_20231107_at_32115_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "654a0ad4637db60f88b48f7c",
    "name":
"externallmg_1699351251908_WhatsApp_Image_20231107_at_32115_PM.jpeg",
    "path": "cases/6548c428594ccb46f00241e1/
externallmg_1699351251908_WhatsApp_Image_20231107_at_32115_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```



```
"status": false,
  "_id": "654a0ad4637db60f88b48f7d",
  "name":
"externallmg_1699351251911_WhatsApp_Image_20231107_at_32116_PM_1.jpeg",
  "path": "cases/6548c428594ccb46f00241e1/
externallmg_1699351251911_WhatsApp_Image_20231107_at_32116_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "654a0ad4637db60f88b48f7e",
  "name":
"externallmg_1699351251916_WhatsApp_Image_20231107_at_32116_PM_2.jpeg",
  "path": "cases/6548c428594ccb46f00241e1/
externallmg_1699351251916_WhatsApp_Image_20231107_at_32116_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "654a0ad4637db60f88b48f7f",
  "name":
"externallmg_1699351251919_WhatsApp_Image_20231107_at_32116_PM_3.jpeg",
  "path": "cases/6548c428594ccb46f00241e1/
externallmg_1699351251919_WhatsApp_Image_20231107_at_32116_PM_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "654a0ad4637db60f88b48f80",
  "name":
"externallmg_1699351251922_WhatsApp_Image_20231107_at_32116_PM.jpeg",
  "path": "cases/6548c428594ccb46f00241e1/
externallmg_1699351251922_WhatsApp_Image_20231107_at_32116_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "654a0ae4637db60f88b48fc0",
  "name":
"externallmg_1699351268462_WhatsApp_Image_20231107_at_32117_PM_1.jpeg",
  "path": "cases/6548c428594ccb46f00241e1/
externallmg_1699351268462_WhatsApp_Image_20231107_at_32117_PM_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "654a0ae4637db60f88b48fc1",
    "name":
"externallmg_1699351268465_WhatsApp_Image_20231107_at_32117_PM_2.jpeg",
    "path": "cases/6548c428594ccb46f00241e1/
externallmg_1699351268465_WhatsApp_Image_20231107_at_32117_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "654a0ae4637db60f88b48fc2",
    "name":
"externallmg_1699351268467_WhatsApp_Image_20231107_at_32117_PM.jpeg",
    "path": "cases/6548c428594ccb46f00241e1/
externallmg_1699351268467_WhatsApp_Image_20231107_at_32117_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "654a0ae4637db60f88b48fc3",
    "name":
"externallmg_1699351268470_WhatsApp_Image_20231107_at_32118_PM_1.jpeg",
    "path": "cases/6548c428594ccb46f00241e1/
externallmg_1699351268470_WhatsApp_Image_20231107_at_32118_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "654a0ae4637db60f88b48fc4",
    "name":
"externallmg_1699351268472_WhatsApp_Image_20231107_at_32118_PM_2.jpeg",
    "path": "cases/6548c428594ccb46f00241e1/
externallmg_1699351268472_WhatsApp_Image_20231107_at_32118_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "654a0ae4637db60f88b48fc5",
```

```
    "name":  
    "externallmg_1699351268474_WhatsApp_Image_20231107_at_32118_PM.jpeg",  
    "path": "cases/6548c428594ccb46f00241e1/  
externallmg_1699351268474_WhatsApp_Image_20231107_at_32118_PM.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "654a0ae4637db60f88b48fc6",  
    "name":  
    "externallmg_1699351268476_WhatsApp_Image_20231107_at_32119_PM_1.jpeg",  
    "path": "cases/6548c428594ccb46f00241e1/  
externallmg_1699351268476_WhatsApp_Image_20231107_at_32119_PM_1.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "654a0ae4637db60f88b48fc7",  
    "name":  
    "externallmg_1699351268482_WhatsApp_Image_20231107_at_32119_PM_2.jpeg",  
    "path": "cases/6548c428594ccb46f00241e1/  
externallmg_1699351268482_WhatsApp_Image_20231107_at_32119_PM_2.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "654a0ae4637db60f88b48fc8",  
    "name":  
    "externallmg_1699351268484_WhatsApp_Image_20231107_at_32119_PM.jpeg",  
    "path": "cases/6548c428594ccb46f00241e1/  
externallmg_1699351268484_WhatsApp_Image_20231107_at_32119_PM.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "654a0ae4637db60f88b48fc9",  
    "name":  
    "externallmg_1699351268486_WhatsApp_Image_20231107_at_32120_PM_1.jpeg",  
    "path": "cases/6548c428594ccb46f00241e1/  
externallmg_1699351268486_WhatsApp_Image_20231107_at_32120_PM_1.jpeg",  
    "orientation": "portrait"  
  },  
  }
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "654a0ae4637db60f88b48fca",
  "name":
"externallmg_1699351268491_WhatsApp_Image_20231107_at_32120_PM_2.jpeg",
  "path": "cases/6548c428594ccb46f00241e1/
externallmg_1699351268491_WhatsApp_Image_20231107_at_32120_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "654a0ae4637db60f88b48fcb",
  "name":
"externallmg_1699351268493_WhatsApp_Image_20231107_at_32120_PM_3.jpeg",
  "path": "cases/6548c428594ccb46f00241e1/
externallmg_1699351268493_WhatsApp_Image_20231107_at_32120_PM_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "654a0ae4637db60f88b48fcc",
  "name":
"externallmg_1699351268495_WhatsApp_Image_20231107_at_32120_PM.jpeg",
  "path": "cases/6548c428594ccb46f00241e1/
externallmg_1699351268495_WhatsApp_Image_20231107_at_32120_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "654a0ae4637db60f88b48fcd",
  "name":
"externallmg_1699351268497_WhatsApp_Image_20231107_at_32121_PM_1.jpeg",
  "path": "cases/6548c428594ccb46f00241e1/
externallmg_1699351268497_WhatsApp_Image_20231107_at_32121_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "654a0ae4637db60f88b48fce",
  "name":
"externallmg_1699351268502_WhatsApp_Image_20231107_at_32121_PM_2.jpeg",
```

```
    "path": "cases/6548c428594ccb46f00241e1/
externallmg_1699351268502_WhatsApp_Image_20231107_at_32121_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "654a0ae4637db60f88b48fcf",
    "name":
"externallmg_1699351268505_WhatsApp_Image_20231107_at_32121_PM.jpeg",
    "path": "cases/6548c428594ccb46f00241e1/
externallmg_1699351268505_WhatsApp_Image_20231107_at_32121_PM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "AGR.pdf",
    "filename": "1699358225373_AGR.pdf",
    "path": "cases/6548c428594ccb46f00241e1/
processingDocuments/1699358225373_AGR.pdf",
    "size": "55589096",
    "createdAt": "Tue Nov 07 2023 17:27:07 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "Summary New=NILIMA.xlsx",
    "filename": "1699358226943_Summary_NewNILIMA.xlsx",
    "path": "cases/6548c428594ccb46f00241e1/
processingDocuments/1699358226943_Summary_NewNILIMA.xlsx",
    "size": "2605371",
    "createdAt": "Tue Nov 07 2023 17:27:07 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  }
],
"remarks": [],
"createdAt": "2023-11-06T10:47:04.611Z",
"updatedAt": "2023-11-08T06:32:20.990Z",
"__v": 0,
"invoiceId": "6548c42d594ccb46f002424e",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 704, 7th Floor, Building No 4, Wing - A, Castor,
```

Thakur Galaxy, Near Rahul International School, Plot No. RH-81, Tarapur Industrial Area, Village - Saravali, Taluka - Palghar, District - Palghar, Boisar (West), Palghar, PIN - 401 501, State - Maharashtra, India",

```
"updatedBy": "60eeaeddf3dd69653a581316",
"addressForMap": "",
"caseReferredBy": "62723addafd7d55eddeddfe4",
"contactPersonName": "Mrs. Nilima Shivde",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "7972158171",
"briefDescOfProperty": "3 Bedroom + Living Room + Kitchen + 3 Toilet + 3 Passage + Dining + 2 Balcony",
"carpetTotal": "733.08",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0.00",
"buildingServicesRate": "2500",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 732.00",
"flatRate": "6500",
"landOtherRate": "4000",
"builtupPercentage": "10",
"finalBuiltupArea": "806.39",
"finalCarpetArea": "733.08",
"finalSalableArea": "887.03",
"salablePercentage": "10",
"toBeAdded": "",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  }
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
  "leaseFrom": "",
  "leaseTo": ""
}
```

```

    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalSaleablePercentage": "0",
"reportGeneratedDate": "Wed Nov 08 2023 18:02:32 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2023-11-07"
}

```

Name	Length	Width	Total
Composition :			
Living Room	8'4"	15'11"	132.64
Kitchen	6'11"	9'1"	62.83
Bedroom	6'8"	11'11"	79.44
Bedroom	11'11"	8'11"	106.26
Bedroom	8'11"	10'2"	90.65
Toilet	4'1"	5'11"	24.16
Toilet	6'1"	3'11"	23.83
Toilet	5'10"	3'9"	21.87
Passage	2'7"	4'6"	11.62
Dining	10'7"	7'1"	74.97
Balcony	1'10"	16'2"	29.64
Balcony	2'2"	8'4"	18.06
Passage	2'10"	2'1"	5.90
Passage	2'1"	11'2"	23.26
Other Composition :			