

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b899"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b9423100d",
    "firstName": "Yogini Anand Gokhale",
    "email": "0_default_sbi.04498@sbi.co.in",
    "mobileNo": "0_DEFAULT_022-25382751",
    "workMobileNo": "0_DEFAULT_91-9930451861"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "6418456a96b58848585f8cb2",

```

```
"name": "Thane",
"email": "thane@vastukala.com",
"phone": "1234567890",
"address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
"city": "Thane",
"shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b899",
  "branchCode": "000127",
  "type": "BRANCH",
  "name": "RACPC Thane ",
  "email": "rasecc.thane@sbi.co.in",
  "mobileNo": "02220812026",
  "alternateMobileNo": "02220812027",
  "address": "Retail Assets Centralized, Processing Centre,Dosti Pinnacle , Plot no
E7,Near New Passport Office,Gate No-3,Road No 22,Panchpakhadi Village Wagle Indl
Estate,Thane- 400604\r\n",
  "ledgerName": "STATE BANK OF INDIA - THANE RACPC",
  "fax": "2538 2750 ",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "64abdb2806d6ec174986d16b",
  "role": "PICKUPPERSON",
  "firstName": "Sahadu",
  "email": "thoratsahadu8679@gmail.com",
  "lastName": "Thorat",
  "mobileNo": "9422389642",
  "shortName": "ST",
  "workWithDocumentMaker": ""
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62ea09ea4e679b264caf07d7",
  "role": "SITEENGINEER",
  "firstName": "Suraj",
  "email": "suraj@vastukala.org",
  "lastName": "Zore",
  "mobileNo": "8652448654",
  "designation": "",
  "shortName": "SZ",
  "workWithDocumentMaker": "60092304a16fab0f2af9b0c2",
  "profilePhoto": "users/62ea09ea4e679b264caf07d7/
profilePhoto_1685629394240_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "MAKER",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
  "mobileNo": "9821518537",
```

```
"designation": "",
"shortName": "PS",
"workWithDocumentMaker": "60f915d3f3dd69653a592199",
"profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"email": "v.sarmalkar@vastukala.org",
"lastName": "Sarmalkar",
"mobileNo": "9004437379",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "[N]C.C.I.T/I -14/52/2008-09",
"label": "Wealth Tax"
}
],
"type": "EMPLOYEE",
"_id": "6084131a13f01f158c6ea1f3",
"PANNo": "AEAPC7114Q",
"role": "VALUER",
"firstName": "Sharadkumar",
"fatherName": "Baburao",
"email": "cmd@vastukala.org",
"lastName": " Chalikwar",
"mobileNo": "9422171100",
"designation": "CMD",
"registrationNo": [
{
"title": {
"value": "Wealth_Tax",
"label": "Wealth Tax"
}
},
"_id": "6084131a13f01f158c6ea1f4",
"number": "[N]C.C.I.T/I -14/52/2008-09"
```

```
    }
  ],
  "shortName": "SBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.219964024802675",
  "longitude": "72.96452397000702"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-11-08",
      "remark": ""
    }
  ]
},
"schedule": [],
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
}
```

```
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Majiwade",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "9",
    "label": false
  },
  "buildingNo": {
    "status": true,
    "name": "Building No",
    "key": "buildingNo",
    "value": "2",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
    "value": "Thane",
    "label": true
  },
  "city": {
    "status": true,
```

```
"name": "City",
"key": "city",
"value": "Thane (West)",
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Courtyard - Asteria B",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Pokharan Road No. 2",
  "label": false
}
```

```
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Off Galaxyo Company",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "281/2A/1B, 281/2A/2, 281/2A/3, 283/1, 283/2, 288/2D/1D, 288/2D/2",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
```



```
"key": "hissaNo",
"value": "",
"label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "Village - Majiwade",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "905",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
}
```

```
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 400 610",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "flooring": {
    "value": "Proposed_Vitrified_tiles_flooring",
    "label": "Proposed Vitrified tiles flooring"
  },
  "doors": {
```

```
"value": "Proposed_Teak_wood_door_frame_with_flush_doors",
"label": "Proposed Teak wood door frame with flush doors"
},
"windows": {
"value": "Proposed_Powder_coated_aluminium_sliding_windows",
"label": "Proposed Powder coated aluminium sliding windows"
},
"fittings": {
"value": "Proposed_Concealed_plumbing_with_C.P._fittings._Concealed_wiring",
"label": "Proposed Concealed plumbing with C.P. fittings. Concealed wiring"
},
"finishing": {
"value": "Proposed_Cement_Plastering",
"label": "Proposed Cement Plastering"
}
},
"general": {
"ownership": {
"value": "Joint_Ownership",
"label": "Joint Ownership"
},
"populationClassList": {
"value": "MiddleClass",
"label": "Middle Class"
},
"populationGroupList": {
"value": "Urban",
"label": "Urban"
},
"townplanApprovedByList": {
"value": "Thane_Municipal_Corporation",
"label": "Thane Municipal Corporation"
},
"whetherCoveredUnderAnyState": {
"value": "No",
"label": "No"
},
"asPerActualAgreement": {
"north": "Rozanne Building",
"west": "Siddhachal Housing Society",
"south": "Pokharan Road Number 2",
"east": "Arjun Building"
},
"asPerDocumentAgreement": {
"north": "Details not available",
"west": "Details not available",
```

```
"south": "Details not available",
"east": "Details not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "asPerDocument": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of Approved Building Plan V.P. No. .S04 / 0099 /
16 / TMC / TD-DP / TPS / 4009 / 21 Dated 28.03.202 issued by Thane Municipal
Corporation. \n",
"approvePlanVerified": "",
"empanelledOfApprovePlan": ""
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "137600",
  "landRate": "41400",
  "igrImage": "cases/654a193d637db60f88b4b56e/igr_1699529390174_Image.png",
  "squareMeterGuideLineRate": "144480.00",
  "squareFeetGuideLineRate": "13423.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0.00",
  "depreciationPercentage": "0",
  "rate": "137600",
```

```
"squareMeterGuideLineRate": "144480.00",
"squareFeetGuideLineRate": "13423.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Middle_Class",
    "label": "Middle Class"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  },
  "monthlyRent": "47,000.00",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per TMC norms",
  "tenantName": "",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "partitions": {
    "value": "Proposed_6\"_Thk._Brick_Masonry",
    "label": "Proposed 6\" Thk. Brick Masonry"
  },
  "waterTank": {
    "value": "Proposed_Municipal_Water_Supply",
```

```
"label": "Proposed Municipal Water Supply"
},
"pavementLaid": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"carParking": "Along with one covered parking space",
"constructionWorkStatus": {
  "value": "InProgress",
  "label": "Under Construction"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "",
  "month": "1",
  "year": "2027",
  "fullDate": "1/1/2027"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "Proposed_R.C.C_Framed_Structure",
  "label": "Proposed R.C.C Framed Structure"
},
"typeOfFoundation": {
  "value": "Proposed_R.C.C_Foundation",
  "label": "Proposed R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Building_is_under_construction_",
  "label": "Building is under construction "
},
"materialUsedList": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"buildingSpecification": {
  "value": "Proposed_Standard",
  "label": "Proposed Standard"
},
"structuralSafety": {
```

```
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"protAgainstNatDis": {
"value": "Information_not_available",
"label": "Information not available"
},
"sewerageSystem": {
"value": "Proposed_Connected_to_Municipal_Sewerage_System_",
"label": "Proposed Connected to Municipal Sewerage System "
},
"walls": {
"value": "Proposed,_Yes",
"label": "Proposed, Yes"
},
"appearanceOfTheBuilding": {
"value": "UnderConstruction",
"label": "Building Under Construction"
},
"maintenanceOfTheBuilding": {
"value": "UnderConstruction",
"label": "Building Under Construction"
},
"maintenancelssues": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"visibleDamageInBuilding": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"systemOfAirConditioning": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"provisionOfFirefighting": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"groundStilt": {
"value": "ground",
"label": "Ground"
},
"yearOfConstructionAsPer": {
"value": "as_per_site_information",
"label": "As per site information"
}
```

```
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "0",
"ageOfBuilding": "0",
"noOfBasement": "3",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "31",
"flatFloorNo": "9",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "6"
},
"finalPlinthArea": {
  "areaType": "Built Up",
  "area": "913.00",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/654a193d637db60f88b4b56e/
routeMap_1699524652408_Image.png",
    "routeLat": "19.220157",
    "routeLng": "72.964376",
    "stationName": "Thane",
    "routeDistance": "5.3 KM"
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "ncmzm",
```



```
    "name": "ncmzm",
    "image": "cases/654a193d637db60f88b4b56e/
routeMap_1699524584222_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "18841000.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValue": "0",
  "finalValue": "18841000.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Thu Nov 09 2023 16:45:57 GMT+0530 (India Standard Time)",
  "number": "2303461",
  "dayCount": "20",
```

```
"monthCount": "157",
"generatedBy": "5fc78e26625ecd20ec1f88e9"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "1",
    "percentage": "1.1111111111111112",
    "isHideFloor": false,
    "status": true
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
```

```
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "10.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "12255199.00",
"selectedBuildUpValue": "913.00",
"selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
"frontPageImages": [
{
"status": false,
"_id": "654b93b6637db60f88b729e2",
"name": "externalimg_r_1699451808505_1699451845579_image_7.jpg",
```

```
    "path": "cases/654a193d637db60f88b4b56e/
externallmg_r_1699451808505_1699451845579_image_7.jpg",
    "orientation": "portrait"
  }
],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "654b93b6637db60f88b729de",
    "name": "Bedroom",
    "path": "cases/654a193d637db60f88b4b56e/
externallmg_r_1699451799325_1699451845579_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "654b93b6637db60f88b729e0",
    "name": "Bedroom",
    "path": "cases/654a193d637db60f88b4b56e/
externallmg_r_1699451805586_1699451845579_image_5.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "654b93b6637db60f88b729e2",
    "name": "Bedroom",
    "path": "cases/654a193d637db60f88b4b56e/
externallmg_r_1699451808505_1699451845579_image_7.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "654b93b6637db60f88b729e3",
    "name": "Bedroom",
    "path": "cases/654a193d637db60f88b4b56e/
externallmg_r_1699451804413_1699451845579_image_4.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "654b93b6637db60f88b729e4",
    "name": "Bedroom",
```

```
    "path": "cases/654a193d637db60f88b4b56e/
externallmg_r_1699451812372_1699451845579_image_8.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "654b93b6637db60f88b729df",
    "name": "Bedroom",
    "path": "cases/654a193d637db60f88b4b56e/
externallmg_r_1699451800272_1699451845579_image_1.jpg",
    "orientation": "landscape"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "21665",
    "max": "23253"
  },
  "builtUpRateRange": {
    "min": "19696",
    "max": "21140"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
{others": {
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
totalValues": {
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
taskStatus": {
"SITE_INSPECTION": true,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
createCase": "false",
type": "CASE",
leadType": {
"label": "Lead",
"value": "LEAD"
},
siteVisitType": "PARTIAL",
isSiteMeasurementAllowed": true,
finalValuationArea": "830.00",
empanelmentNo": [
"SME/TCC/2021-22/86A/3"
```



```
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentId": [],
"_id": "654a193d637db60f88b4b56e",
"ownerName": "Mr. Harish Choudhary & Mrs. kamla Harish Choudhary",
"ownerPhoneNo": "9892909035",
"fullAddress": "Residential Flat No. 905, 9th Floor, Building No 2, Courtyard - Asteria
B, Off Galaxyo Company, Pokharan Road No. 2, Village - Majiwade, Taluka - Thane,
District - Thane, Thane (West), PIN Code - 400 610, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "10/08/2023",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "Courtyard Real Estate Private Limited ",
      "to": {
        "value": "purchaser",
        "label": "purchaser"
      },
      "purchaser": "Mr. Harish Choudhary & Mrs. kamla Harish Choudhary",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "19890/2023"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1699354909264_Harish_Choudhary_Valuation_.pdf",
    "path": "cases/654a193d637db60f88b4b56e/
document_1699354909264_Harish_Choudhary_Valuation_.pdf",
    "id": "735123",
    "uploadedBy": "6430f74691d7c62df11f3f15",
    "createdAt": "Tue Nov 07 2023 16:32:21 GMT+0530 (India Standard Time)"
  },
  {
```

```
"documentType": {
  "value": "60ae129faa6d152c1801b47d",
  "label": "RERA Certificate"
},
"inputs": {
  "documentDate": "17/11/2022",
  "nameOfApprovingAuthority": {
    "value": "Maharashtra_Real_Estate_Regulatory_Authority",
    "label": "Maharashtra Real Estate Regulatory Authority"
  },
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "P51700047655"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1699522620264_P51700047655.pdf",
"path": "cases/654a193d637db60f88b4b56e/
document_1699522620264_P51700047655.pdf",
"id": "200899",
"uploadedBy": "627222afafd7d55eddedd82",
"createdAt": "Thu Nov 09 2023 15:07:00 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "30/12/2022",
    "nameOfApprovingAuthority": {
      "value": "Thane_Municipal_Corporation",
      "label": "Thane Municipal Corporation"
    },
    "number": {
      "value": "V.P._No._",
      "label": "V.P. No. "
    },
    "V.P._No._": "97 / 096 / New V. P. No. S04 / 0099 / 16 / TMC / TDD / 4270 / 22"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1699522793790_147737.pdf",
  "path": "cases/654a193d637db60f88b4b56e/
document_1699522793790_147737.pdf",
```

```
"id": "458136",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Thu Nov 09 2023 15:09:53 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "28/03/2022",
    "nameOfApprovingAuthority": {
      "value": "Thane_Municipal_Corporation",
      "label": "Thane Municipal Corporation"
    },
    "number": {
      "value": "V.P._No._",
      "label": "V.P. No. "
    },
    "V.P._No._": "S04 / 0099 / 16 / TMC / TD-DP / TPS / 4009 / 21"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1699523300676_Take__4_Building_Plan_Approval___NA_Order_for_plotted_development_14.pdf",
  "path": "cases/654a193d637db60f88b4b56e/document_1699523300676_Take__4_Building_Plan_Approval___NA_Order_for_plotted_development_14.pdf",
  "id": "722633",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Thu Nov 09 2023 15:18:21 GMT+0530 (India Standard Time)"
}
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "004945",
"createdBy": "6430f74691d7c62df11f3f15",
"caseHistory": [
  {
    "id": "744983",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Nov 07 2023 16:32:21 GMT+0530 (India Standard Time)"
  }
],
```

```
"owners": [
  {
    "name": "Mr. Harish Choudhary & Mrs. kamla Harish Choudhary",
    "phone": "9892909035",
    "ownershipShare": "",
    "email": "",
    "id": "656196"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "464136",
    "name": "Living Room",
    "length": "0.00",
    "length1": "0",
    "length2": "00",
    "width": "0.00",
    "width1": "0",
    "width2": "00",
    "totalArea": "0.00",
    "images": [],
    "extraAreas": [],
    "finalArea": "0.00"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "name": "Bedroom",
    "length": "0.00",
    "length1": "0",
    "length2": "00",
    "width": "0.00",
    "width1": "0",
    "width2": "00",
    "totalArea": "0.00",
    "images": [],
    "extraAreas": [],
  }
]
```

```
"finalArea": "0.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Bedroom",
  "length": "0.00",
  "length1": "0",
  "length2": "00",
  "width": "0.00",
  "width1": "0",
  "width2": "00",
  "totalArea": "0.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "0.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Kitchen",
  "length": "",
  "length1": "0",
  "length2": "0",
  "width": "",
  "width1": "0",
  "width2": "0",
  "totalArea": "0.00",
  "images": [],
  "finalArea": "0.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "0.00",
```

```
"length1": "0",
"length2": "00",
"width": "0.00",
"width1": "0",
"width2": "00",
"totalArea": "0.00",
"images": [],
"extraAreas": [],
"finalArea": "0.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Toilet",
  "length": "0.00",
  "length1": "0",
  "length2": "00",
  "width": "0.00",
  "width1": "0",
  "width2": "00",
  "totalArea": "0.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "0.00"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "77.11",
    "totalAreaDocument": "830",
    "docBuiltupPercentage": "10",
    "docFinalBuiltUp": "913.00",
```

```
    "docFinalBuiltUpSquareMeter": "84.82",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "630796"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "654c7695637db60f88b798a6",
    "property": "Flat",
    "area": "830",
    "builtUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "magic_bricks",
    "expectedPrice": "18900000",
    "expectedRate": "22771.08",
    "builtUpExpectedRate": "20700.99",
    "image": "cases/654a193d637db60f88b4b56e/
indicator_1699509526259_Image.png",
    "squareMeter": "77.11",
    "id": "265345"
  },
  {
    "printlnReport": true,
    "_id": "654c7695637db60f88b798a7",
    "property": "Flat",
    "area": "830",
    "builtUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "10",
    "source": "magic_bricks",
    "expectedPrice": "19300000",
    "expectedRate": "23253.01",
    "builtUpExpectedRate": "21139.10",
    "image": "cases/654a193d637db60f88b4b56e/
indicator_1699509577088_Image.png",
    "squareMeter": "77.11",
    "id": "159100"
  },
]
```

```
{
  "printlnReport": true,
  "_id": "654c7695637db60f88b798a8",
  "property": "Flat",
  "area": "830",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "10",
  "source": "magic_bricks",
  "expectedPrice": "19100000",
  "expectedRate": "23012.05",
  "builtUpExpectedRate": "20920.04",
  "image": "cases/654a193d637db60f88b4b56e/
indicator_1699509601671_Image.png",
  "squareMeter": "77.11",
  "id": "484178"
},
{
  "printlnReport": true,
  "_id": "654c7695637db60f88b798a9",
  "property": "Flat",
  "area": "830",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "4",
  "source": "Index_no.2",
  "expectedPrice": "17981864",
  "expectedRate": "21664.90",
  "builtUpExpectedRate": "19695.36",
  "image": "cases/654a193d637db60f88b4b56e/
indicator_1699509670531_Image.png",
  "squareMeter": "77.11",
  "id": "638707"
},
{
  "printlnReport": true,
  "_id": "654c7695637db60f88b798aa",
  "property": "Flat",
  "area": "830",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
```



```
"areaType": "Carpet",
"floor": "5",
"source": "Index_no.2",
"expectedPrice": "18052938",
"expectedRate": "21750.53",
"builtUpExpectedRate": "19773.21",
"image": "cases/654a193d637db60f88b4b56e/
indicator_1699509711201_Image.png",
"squareMeter": "77.11",
"id": "892259"
}
],
"externalImages": [
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "654b93b6637db60f88b729dc",
"name": "externalimg_r_1699451801870_1699451845579_image_2.jpg",
"path": "cases/654a193d637db60f88b4b56e/
externalimg_r_1699451801870_1699451845579_image_2.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "654b93b6637db60f88b729dd",
"name": "externalimg_r_1699451802987_1699451845579_image_3.jpg",
"path": "cases/654a193d637db60f88b4b56e/
externalimg_r_1699451802987_1699451845579_image_3.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "654b93b6637db60f88b729de",
"name": "externalimg_r_1699451799325_1699451845579_image_0.jpg",
"path": "cases/654a193d637db60f88b4b56e/
externalimg_r_1699451799325_1699451845579_image_0.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "654b93b6637db60f88b729df",
"name": "externalimg_r_1699451800272_1699451845579_image_1.jpg",
"path": "cases/654a193d637db60f88b4b56e/
externalimg_r_1699451800272_1699451845579_image_1.jpg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "654b93b6637db60f88b729e0",
  "name": "externallmg_r_1699451805586_1699451845579_image_5.jpg",
  "path": "cases/654a193d637db60f88b4b56e/
externallmg_r_1699451805586_1699451845579_image_5.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "654b93b6637db60f88b729e1",
  "name": "externallmg_r_1699451806873_1699451845579_image_6.jpg",
  "path": "cases/654a193d637db60f88b4b56e/
externallmg_r_1699451806873_1699451845579_image_6.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "654b93b6637db60f88b729e2",
  "name": "externallmg_r_1699451808505_1699451845579_image_7.jpg",
  "path": "cases/654a193d637db60f88b4b56e/
externallmg_r_1699451808505_1699451845579_image_7.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "654b93b6637db60f88b729e3",
  "name": "externallmg_r_1699451804413_1699451845579_image_4.jpg",
  "path": "cases/654a193d637db60f88b4b56e/
externallmg_r_1699451804413_1699451845579_image_4.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "654b93b6637db60f88b729e4",
  "name": "externallmg_r_1699451812372_1699451845579_image_8.jpg",
  "path": "cases/654a193d637db60f88b4b56e/
externallmg_r_1699451812372_1699451845579_image_8.jpg",
  "orientation": "portrait"
}
```

```
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "654b93b6637db60f88b729e5",
  "name": "externalImg_r_1699451772758_1699451821473_image_1.png",
  "path": "cases/654a193d637db60f88b4b56e/
externalImg_r_1699451772758_1699451821473_image_1.png",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "654b93b6637db60f88b729e6",
  "name": "externalImg_r_1699451770959_1699451821473_image_0.jpg",
  "path": "cases/654a193d637db60f88b4b56e/
externalImg_r_1699451770959_1699451821473_image_0.jpg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Calculation (2)- harish.xlsx",
    "filename": "1699509932433_Calculation_2_harish.xlsx",
    "path": "cases/654a193d637db60f88b4b56e/
processingDocuments/1699509932433_Calculation_2_harish.xlsx",
    "size": "16071",
    "createdAt": "Thu Nov 09 2023 11:35:37 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "Courtyard - Asteria B.pdf",
    "filename": "1699509932435_Courtyard__Asteria_B.pdf",
    "path": "cases/654a193d637db60f88b4b56e/
processingDocuments/1699509932435_Courtyard__Asteria_B.pdf",
    "size": "1713142",
    "createdAt": "Thu Nov 09 2023 11:35:37 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "igr1.pdf",
    "filename": "1699509932825_igr1.pdf",
    "path": "cases/654a193d637db60f88b4b56e/
processingDocuments/1699509932825_igr1.pdf",
    "size": "578787",
```

```
"createdAt": "Thu Nov 09 2023 11:35:37 GMT+0530 (India Standard Time)",
"uploadedBy": "5fc78e26625ecd20ec1f88e9"
},
{
  "originalname": "igr2.pdf",
  "filename": "1699509933085_igr2.pdf",
  "path": "cases/654a193d637db60f88b4b56e/
processingDocuments/1699509933085_igr2.pdf",
  "size": "549650",
  "createdAt": "Thu Nov 09 2023 11:35:37 GMT+0530 (India Standard Time)",
  "uploadedBy": "5fc78e26625ecd20ec1f88e9"
},
{
  "originalname": "igr3.pdf",
  "filename": "1699509933094_igr3.pdf",
  "path": "cases/654a193d637db60f88b4b56e/
processingDocuments/1699509933094_igr3.pdf",
  "size": "516960",
  "createdAt": "Thu Nov 09 2023 11:35:37 GMT+0530 (India Standard Time)",
  "uploadedBy": "5fc78e26625ecd20ec1f88e9"
},
{
  "originalname": "igr4.pdf",
  "filename": "1699509933102_igr4.pdf",
  "path": "cases/654a193d637db60f88b4b56e/
processingDocuments/1699509933102_igr4.pdf",
  "size": "551125",
  "createdAt": "Thu Nov 09 2023 11:35:37 GMT+0530 (India Standard Time)",
  "uploadedBy": "5fc78e26625ecd20ec1f88e9"
},
{
  "originalname": "plan.pdf",
  "filename": "1699509933111_plan.pdf",
  "path": "cases/654a193d637db60f88b4b56e/
processingDocuments/1699509933111_plan.pdf",
  "size": "1794111",
  "createdAt": "Thu Nov 09 2023 11:35:37 GMT+0530 (India Standard Time)",
  "uploadedBy": "5fc78e26625ecd20ec1f88e9"
},
{
  "originalname": "Summary - harish.xlsx",
  "filename": "1699509936958_Summary__harish.xlsx",
  "path": "cases/654a193d637db60f88b4b56e/
processingDocuments/1699509936958_Summary__harish.xlsx",
  "size": "3015218",
  "createdAt": "Thu Nov 09 2023 11:35:37 GMT+0530 (India Standard Time)",
```

```
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  }
],
"remarks": [],
"createdAt": "2023-11-07T11:02:21.459Z",
"updatedAt": "2023-11-09T11:30:40.939Z",
"__v": 0,
"invoiceId": "654a193e637db60f88b4b57a",
"updatedBy": "5fc78e26625ecd20ec1f88e9",
"addressForMap": "",
"caseReferredBy": "64abdb2806d6ec174986d16b",
"contactPersonName": "Mr. Sachin",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Sales Person",
"siteVisitContactNo": "8657530756",
"buildingServicesRate": "2600",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 830.00",
"flatRate": "22700",
"landOtherRate": "20100",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + 2 Toilet",
"carpetTotal": "0.00",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"extendOfSiteRemark": "RERA Carpet area in Sq. Ft. = 765.00\nService Area in Sq. Ft. = 65.00",
"finalBuiltupArea": "0.00",
"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  }
},
```

```

"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
  "leaseFrom": "",
  "leaseTo": "",
  "remainingLeasePeriod": 0,
  "leaseDate": ""
}
},
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
}
}

```

Name	Length	Width	Total
Composition :			
Living Room	0'00"	0'00"	0.00
Bedroom	0'00"	0'00"	0.00
Bedroom	0'00"	0'00"	0.00
Kitchen	0'0"	0'0"	0.00
Toilet	0'00"	0'00"	0.00
Toilet	0'00"	0'00"	0.00
Other Composition :			