

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7f7"
    },
    "type": "CREDITOFFICER",
    "_id": "63fd9434ce84bf289baab0e9",
    "firstName": "Sharmila",
    "lastName": "Mahto",
    "mobileNo": "",
    "workMobileNo": "9521405151",
    "email": "sharmila.mahto@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5000000",
    "discussWithPerson": "Sharmila",
    "expectedFees": 2500,
    "quotedAmount": "2500"
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7f7",
  "branchCode": "000064",
  "type": "BRANCH",
  "name": "RACPC Ghatkopar (West)",
  "email": "racpcghatkopar.sanctions@sbi.co.in",
  "mobileNo": "022-25009143",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, 1st Floor, Ashok Silk Mills
Compound, LBS Marg, Ghatkopar (West), Mumbai - 400 086, State - Maharashtra,
Country - India.\r\n\r\n\r\n",
  "ledgerName": "STATE BANK OF INDIA - RACPC GHATKOPAR",
  "fax": "022-25009010",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62ea09ea4e679b264caf07d7",
  "role": "SITEENGINEER",
  "firstName": "Suraj",
  "email": "suraj@vastukala.org",
  "lastName": "Zore",
  "mobileNo": "8652448654",
  "designation": "",
  "shortName": "SZ",
  "workWithDocumentMaker": "60092304a16fab0f2af9b0c2",
  "profilePhoto": "users/62ea09ea4e679b264caf07d7/
profilePhoto_1685629394240_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60eebe33f3dd69653a5837ae",
  "role": "MAKER",
  "firstName": "Shamal",
  "email": "shamal@vastukala.org",
```

```
"lastName": "Bodke",
"mobileNo": "9821740317",
"designation": "",
"shortName": "SB",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eebe33f3dd69653a5837ae\
\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
  },

```

```
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.135662785719397",
  "longitude": "72.93137332402556"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.93137332402556,
```

```
19.135662785719397
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-11-13",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-11-10",
      "remark": "MANUAL_IN_TASK"
    }
  ],
  "schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
}
```

```
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Kanjur",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "26",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Kanjurmarg (East), Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
```

```
"value": "Kurla",
"label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Daffodils – Runwal Bliss",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Crompton Greaves Compound",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
```



```
"status": true,
"name": "Wing",
"key": "wing",
"value": "B",
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "-",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "1004, 1005(P), 1005/1, 1006, 1007/3(P), 1007(P), 1007/4, 1009(P),
1009/5, 1009/6, 1010(P), 1013(P), 1014(P), 1014/1 to 1014/6, 1017, 1017/ 1 to 1017/6,
1018, 1018/1 to 1018/9",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
```

```
"key": "blockNo",
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "2606",
  "label": false
},
"municipalityWardNo": {
  "status": true,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "S",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
}
```

```
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 042",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering",
```

```
    "label": "Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MCGM",
    "label": "Municipal Corporation of Greater Mumbai (MCGM)"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Veer Savarkar Road",
    "west": "Crompton Greaves Compound",
    "south": "Shraddha Autumn Park Building",
    "east": "Kanjur Village Road"
  },
  "asPerDocumentAgreement": {
    "north": "Details not available",
    "west": "Details not available",
    "south": "Details not available",
    "east": "Details not available"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "Details not available",
      "east": "Details not available",
      "south": "Details not available",
      "west": "Details not available"
    },
    "asPerDocument": {
      "north": "Details not available",
      "east": "Details not available",
```

```
    "south": "Details not available",
    "west": "Details not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of Approved Building Plan No. CHE / ES / 1699 / S / 337 (New) / 16 / Amend Dated 27.03.2023 issued by Municipal Corporation of Greater Mumbai.",
"approvePlanVerified": "Yes",
"empanelledOfApprovePlan": "N. A."
},
"compositeRate": {
  "remark": "Internal Renovation of flat is work in progress.",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Kanjurmarg",
  "rate": "158440",
  "landRate": "72910",
  "igrImage": "cases/654c966a637db60f88b80b1b/igr_1700113888453_Image.png",
  "squareMeterGuideLineRate": "182206.00",
  "squareFeetGuideLineRate": "16928.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0.00",
  "rate": "158440.00",
  "squareMeterGuideLineRate": "182206.00",
  "squareFeetGuideLineRate": "16928.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Vacant",
```

```
"label": "Vacant"
},
"monthlyRent": "46,000",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per MCGM norms",
"tenantName": "",
"maintenanceOfFlat": "Internal Renovation of flat is work in progress."
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Along with One Car Parking Space",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  }
}
```

```
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2023",
  "fullDate": "1/1/2023"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
}
```

```
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "60",
"ageOfBuilding": "0",
"noOfBasement": "1",
"noOfPodium": "4",
"noOfAmenityFloors": "",
"noOfFloors": "50",
"flatFloorNo": "26",
"noOfLifts": "6",
"noOfDwellingUnitsInBuilding": "6"
},
"finalPlinthArea": {
```



```
"area": "756.80",
"measurementType": "Sq. Ft.",
"areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/654c966a637db60f88b80b1b/
routeMap_1700122283809_Image.png",
    "routeLat": "19.133910",
    "routeLng": "72.935977",
    "stationName": "Kanjur Marg",
    "routeDistance": "1.1 Km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "g405hk",
      "name": "g405hk",
      "image": "cases/654c966a637db60f88b80b1b/
routeMap_1700122199527_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
```

```
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "18576000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "18576000.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
}
```

```
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "12811110.00",
  "selectedBuildUpValue": "756.80",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "655219eb637db60f88b993aa",
      "name": "externalimg_r_1699879362631_1699879413432_image_0.jpg",
      "path": "cases/654c966a637db60f88b80b1b/
externalimg_r_1699879362631_1699879413432_image_0.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "655219eb637db60f88b993b0",
      "name": "externalimg_r_1699879376357_1699879413432_image_10.jpg",
      "path": "cases/654c966a637db60f88b80b1b/
externalimg_r_1699879376357_1699879413432_image_10.jpg",
      "orientation": "landscape"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "655219eb637db60f88b993a8",
      "name": "externalimg_r_1699879365470_1699879413432_image_2.jpg",
```

```
    "path": "cases/654c966a637db60f88b80b1b/
externallmg_r_1699879365470_1699879413432_image_2.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "655219eb637db60f88b993ab",
    "name": "externallmg_r_1699879364191_1699879413432_image_1.jpg",
    "path": "cases/654c966a637db60f88b80b1b/
externallmg_r_1699879364191_1699879413432_image_1.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "655219eb637db60f88b993a9",
    "name": "externallmg_r_1699879366709_1699879413432_image_3.jpg",
    "path": "cases/654c966a637db60f88b80b1b/
externallmg_r_1699879366709_1699879413432_image_3.jpg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "655219eb637db60f88b993ac",
    "name": "Living Room",
    "path": "cases/654c966a637db60f88b80b1b/
externallmg_r_1699879369846_1699879413432_image_5.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "655219eb637db60f88b993ad",
    "name": "Living Room",
    "path": "cases/654c966a637db60f88b80b1b/
externallmg_r_1699879368166_1699879413432_image_4.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "655219eb637db60f88b993af",
    "name": "Living Room",
    "path": "cases/654c966a637db60f88b80b1b/
externallmg_r_1699879372234_1699879413432_image_7.jpg",
```

```
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "655219eb637db60f88b993b2",
    "name": "Living Room",
    "path": "cases/654c966a637db60f88b80b1b/
externallmg_r_1699879375052_1699879413432_image_9.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "655219eb637db60f88b993b1",
    "name": "Living Room",
    "path": "cases/654c966a637db60f88b80b1b/
externallmg_r_1699879373399_1699879413432_image_8.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "655219eb637db60f88b993b6",
    "name": "Living Room",
    "path": "cases/654c966a637db60f88b80b1b/
externallmg_r_1699879380124_1699879413432_image_12.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "655219eb637db60f88b993b7",
    "name": "Living Room",
    "path": "cases/654c966a637db60f88b80b1b/
externallmg_r_1699879386092_1699879413432_image_15.jpg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "27536",
    "max": "28265"
  },
  "builtUpRateRange": {
    "min": "25033",
    "max": "25696"
  }
}
},
```

```
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
    "title": "Interior Decorations",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```



```
"status": true,
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
```

```
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "688.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentId": [],
"audioRemarks": [],
"_id": "654c966a637db60f88b80b1b",
"ownerName": "Shaila Shankar Shelke & Shankar Haribhau Shelke",
"ownerPhoneNo": "9987420515",
"appAddress": "Flat no. 2606, 26th Floor, Tower - B, Daffodils, Runwal Bliss,
Kanjurmarg East ",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
  },
  "inputs": {
    "documentDate": "28/06/2018",
    "from": {
      "value": "Promoter",
      "label": "Promoter"
    }
  },
},
```

```
"Promoter": "Evie Real Estate Private Limited",
"to": {
  "value": "Allottee",
  "label": "Allottee"
},
"Allottee": "Shaila Shankar Shelke & Shankar Haribhau Shelke",
"number": {
  "value": "No",
  "label": "No"
},
"No": "7891/2018"
},
"isHardCopy": false,
"displayStatus": true,
"id": "395318",
"path": "cases/654c966a637db60f88b80b1b/
document_1700113640207_New_Doc_20190907_135615.pdf",
"fileName": "document_1700113640207_New_Doc_20190907_135615.pdf"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "11/09/2023",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_of_Greater_Mumbai",
      "label": "Municipal Corporation of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "CHE / ES / 1699 / S / 337 (New) / OCC / 3 / New"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1700120670252_document_1699518013099_16995180637
14_Shaila_Shelke_Oc.pdf",
  "path": "cases/654c966a637db60f88b80b1b/document_1700120670252_document
_1699518013099_1699518063714_Shaila_Shelke_Oc.pdf",
  "id": "757398",
  "uploadedBy": "60eebe33f3dd69653a5837ae",
  "createdAt": "Thu Nov 16 2023 13:14:30 GMT+0530 (India Standard Time)"
},
```

```
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "15/07/2021",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_of_Greater_Mumbai",
      "label": "Municipal Corporation of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "CHE / ES / 1699 / S / 337 (New) / FCC / 7 / Amend "
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1700120778066_2381783_FurtherCC_signed.pdf",
  "path": "cases/654c966a637db60f88b80b1b/
document_1700120778066_2381783_FurtherCC_signed.pdf",
  "id": "857732",
  "uploadedBy": "60eebe33f3dd69653a5837ae",
  "createdAt": "Thu Nov 16 2023 13:16:18 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "27/03/2023",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_of_Greater_Mumbai",
      "label": "Municipal Corporation of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "CHE / ES / 1699 / S / 337 (New) / 16 / Amend"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1700120884440_Drawing.pdf",
```

```
    "path": "cases/654c966a637db60f88b80b1b/
document_1700120884440_Drawing.pdf",
    "id": "620883",
    "uploadedBy": "60eebe33f3dd69653a5837ae",
    "createdAt": "Thu Nov 16 2023 13:18:05 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae129faa6d152c1801b47d",
      "label": "RERA Certificate"
    },
    "inputs": {
      "documentDate": "09/09/2021",
      "nameOfApprovingAuthority": {
        "value": "Maharashtra_Real_Estate_Regulatory_Authority",
        "label": "Maharashtra Real Estate Regulatory Authority"
      },
      "number": {
        "value": "No",
        "label": "No"
      }
    },
    "No": "P51800005684"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1700120928500_P51800005684.pdf",
  "path": "cases/654c966a637db60f88b80b1b/
document_1700120928500_P51800005684.pdf",
  "id": "730367",
  "uploadedBy": "60eebe33f3dd69653a5837ae",
  "createdAt": "Thu Nov 16 2023 13:18:48 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "004982",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "317804",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Nov 09 2023 13:50:58 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Shaila Shankar Shelke & Shankar Haribhau Shelke",
```

```
"phone": "9987420515",
"ownershipShare": "",
"email": "",
"id": "107791"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "420127",
"name": "Living Room",
"length": "21.17",
"length1": "21",
"length2": "2",
"width": "10.08",
"width1": "10",
"width2": "1",
"totalArea": "213.43",
"images": [],
"extraAreas": [],
"finalArea": "213.43"
},
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "1",
"name": "Kitchen",
"length": "7.25",
"length1": "7",
"length2": "3",
"width": "9.58",
"width1": "9",
"width2": "7",
"totalArea": "69.48",
"images": [],
"extraAreas": [],
"finalArea": "69.48"
},
{

```

```
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "2",
"name": "Toilet",
"length": "7.17",
"length1": "7",
"length2": "2",
"width": "4.33",
"width1": "4",
"width2": "4",
"totalArea": "31.06",
"images": [],
"extraAreas": [],
"finalArea": "31.06"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Toilet",
  "length": "4.33",
  "length1": "4",
  "length2": "4",
  "width": "7.25",
  "width1": "7",
  "width2": "3",
  "totalArea": "31.42",
  "images": [],
  "extraAreas": [],
  "finalArea": "31.42"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Bedroom",
  "length": "9.67",
  "length1": "9",
  "length2": "8",
  "width": "10.25",
```

```
"width1": "10",
"width2": "3",
"totalArea": "99.08",
"images": [],
"extraAreas": [],
"finalArea": "99.08"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bedroom",
  "length": "13.83",
  "length1": "13",
  "length2": "10",
  "width": "9.83",
  "width1": "9",
  "width2": "10",
  "totalArea": "136.03",
  "images": [],
  "extraAreas": [],
  "finalArea": "136.03"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Passage",
  "length": "3.42",
  "length1": "3",
  "length2": "5",
  "width": "15.75",
  "width1": "15",
  "width2": "9",
  "totalArea": "53.81",
  "images": [],
  "extraAreas": [],
  "finalArea": "53.81"
}
],
"otherComposition": [
  {
```



```
"toBeAdded": {
  "label": "Carpet",
  "value": "Carpet"
},
"name": {
  "label": "Dry Balcony",
  "value": "Dry_Balcony"
},
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "0",
"length1": "7",
"length2": "5",
"length": "7.42",
"width1": "3",
"width2": "4",
"width": "3.33",
"totalArea": "24.72",
"percentageBeforeTotal": "24.72",
"images": [],
"extraAreas": [],
"percentage": "100",
"finalArea": "24.72"
}
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "897923",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "688",
    "squareMeterArea": "63.92",
    "docFinalBuiltUp": "756.8",
    "docFinalBuiltUpSquareMeter": "70.312",
    "docBuiltupPercentage": "10",
    "docSaleablePercentage": "0",
```

```
"docFinalSaleable": "0",
"docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "6555afb3637db60f88ba15e7",
  "property": "Runwal Bliss, Kanjurmarg",
  "area": "690",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "5",
  "source": "https://www.99acres.com/",
  "expectedPrice": "19000000",
  "expectedRate": "27536.23",
  "builtUpExpectedRate": "25032.94",
  "image": "cases/654c966a637db60f88b80b1b/
indicator_1700113728408_Image.png",
  "squareMeter": "64.10",
  "id": "855404"
},
{
  "printlnReport": true,
  "_id": "6555afb3637db60f88ba15e8",
  "property": "Runwal Bliss, Kanjurmarg",
  "area": "513",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "8",
  "source": "https://www.99acres.com/",
  "expectedPrice": "14500000",
  "expectedRate": "28265.11",
  "builtUpExpectedRate": "25695.55",
  "image": "cases/654c966a637db60f88b80b1b/
indicator_1700113779770_Image.png",
  "squareMeter": "47.66",
  "id": "450436"
},
{
  "printlnReport": true,
```

```
    "_id": "6555afb3637db60f88ba15e9",
    "property": "Runwal Bliss, Kanjurmarg",
    "area": "660",
    "builtUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "2",
    "source": "https://www.99acres.com/",
    "expectedPrice": "18300000",
    "expectedRate": "27727.27",
    "builtUpExpectedRate": "25206.61",
    "image": "cases/654c966a637db60f88b80b1b/
indicator_1700113814264_Image.png",
    "squareMeter": "61.32",
    "id": "658867"
  }
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655219eb637db60f88b993a8",
    "name": "externalimg_r_1699879365470_1699879413432_image_2.jpg",
    "path": "cases/654c966a637db60f88b80b1b/
externalimg_r_1699879365470_1699879413432_image_2.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655219eb637db60f88b993a9",
    "name": "externalimg_r_1699879366709_1699879413432_image_3.jpg",
    "path": "cases/654c966a637db60f88b80b1b/
externalimg_r_1699879366709_1699879413432_image_3.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655219eb637db60f88b993aa",
    "name": "externalimg_r_1699879362631_1699879413432_image_0.jpg",
    "path": "cases/654c966a637db60f88b80b1b/
externalimg_r_1699879362631_1699879413432_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655219eb637db60f88b993ab",
    "name": "externalimg_r_1699879362631_1699879413432_image_1.jpg",
    "path": "cases/654c966a637db60f88b80b1b/
externalimg_r_1699879362631_1699879413432_image_1.jpg",
    "orientation": "portrait"
  }
]
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655219eb637db60f88b993ab",
  "name": "externallmg_r_1699879364191_1699879413432_image_1.jpg",
  "path": "cases/654c966a637db60f88b80b1b/
externallmg_r_1699879364191_1699879413432_image_1.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655219eb637db60f88b993ac",
  "name": "externallmg_r_1699879369846_1699879413432_image_5.jpg",
  "path": "cases/654c966a637db60f88b80b1b/
externallmg_r_1699879369846_1699879413432_image_5.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655219eb637db60f88b993ad",
  "name": "externallmg_r_1699879368166_1699879413432_image_4.jpg",
  "path": "cases/654c966a637db60f88b80b1b/
externallmg_r_1699879368166_1699879413432_image_4.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655219eb637db60f88b993ae",
  "name": "externallmg_r_1699879371015_1699879413432_image_6.jpg",
  "path": "cases/654c966a637db60f88b80b1b/
externallmg_r_1699879371015_1699879413432_image_6.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655219eb637db60f88b993af",
  "name": "externallmg_r_1699879372234_1699879413432_image_7.jpg",
  "path": "cases/654c966a637db60f88b80b1b/
externallmg_r_1699879372234_1699879413432_image_7.jpg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655219eb637db60f88b993b0",
    "name": "externallmg_r_1699879376357_1699879413432_image_10.jpg",
    "path": "cases/654c966a637db60f88b80b1b/
externallmg_r_1699879376357_1699879413432_image_10.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655219eb637db60f88b993b1",
    "name": "externallmg_r_1699879373399_1699879413432_image_8.jpg",
    "path": "cases/654c966a637db60f88b80b1b/
externallmg_r_1699879373399_1699879413432_image_8.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655219eb637db60f88b993b2",
    "name": "externallmg_r_1699879375052_1699879413432_image_9.jpg",
    "path": "cases/654c966a637db60f88b80b1b/
externallmg_r_1699879375052_1699879413432_image_9.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655219eb637db60f88b993b3",
    "name": "externallmg_r_1699879378339_1699879413432_image_11.jpg",
    "path": "cases/654c966a637db60f88b80b1b/
externallmg_r_1699879378339_1699879413432_image_11.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655219eb637db60f88b993b4",
    "name": "externallmg_r_1699879382188_1699879413432_image_13.jpg",
    "path": "cases/654c966a637db60f88b80b1b/
externallmg_r_1699879382188_1699879413432_image_13.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "655219eb637db60f88b993b5",
  "name": "externallmg_r_1699879384352_1699879413432_image_14.jpg",
  "path": "cases/654c966a637db60f88b80b1b/
externallmg_r_1699879384352_1699879413432_image_14.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655219eb637db60f88b993b6",
  "name": "externallmg_r_1699879380124_1699879413432_image_12.jpg",
  "path": "cases/654c966a637db60f88b80b1b/
externallmg_r_1699879380124_1699879413432_image_12.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655219eb637db60f88b993b7",
  "name": "externallmg_r_1699879386092_1699879413432_image_15.jpg",
  "path": "cases/654c966a637db60f88b80b1b/
externallmg_r_1699879386092_1699879413432_image_15.jpg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "655219eb637db60f88b993b8",
  "name": "externallmg_r_1699879329921_1699879382342_image_2.png",
  "path": "cases/654c966a637db60f88b80b1b/
externallmg_r_1699879329921_1699879382342_image_2.png",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "655219eb637db60f88b993b9",
  "name": "externallmg_r_1699879326942_1699879382342_image_0.jpg",
  "path": "cases/654c966a637db60f88b80b1b/
externallmg_r_1699879326942_1699879382342_image_0.jpg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
```

```
    "_id": "655219eb637db60f88b993ba",
    "name": "externalimg_r_1699879328433_1699879382342_image_1.jpg",
    "path": "cases/654c966a637db60f88b80b1b/
externalimg_r_1699879328433_1699879382342_image_1.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "1699252194037_Calculation.xlsx",
    "filename": "1700113952267_1699252194037_Calculation.xlsx",
    "path": "cases/654c966a637db60f88b80b1b/
processingDocuments/1700113952267_1699252194037_Calculation.xlsx",
    "size": "1740524",
    "createdAt": "Thu Nov 16 2023 11:22:33 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  }
],
"remarks": [],
"createdAt": "2023-11-09T08:20:58.031Z",
"updatedAt": "2023-11-16T09:27:31.201Z",
"__v": 0,
"invoiceId": "654c966a637db60f88b80b21",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 2606, 26th Floor, Wing - B, Daffodils – Runwal
Bliss, Crompton Greaves Compound, Village - Kanjur, Municipality Ward No. S, Taluka -
Kurla, District - Mumbai Suburban, Kanjurmarg (East), Mumbai, PIN - 400 042, State -
Maharashtra, India",
"updatedBy": "60f915d3f3dd69653a592199",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Shaila Shankar Shelke",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9987420515",
"buildingServicesRate": "3000.00",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
```

```
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 688.00",
"flatRate": "27000.00",
"landOtherRate": "24000",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + 2 Toilet + Passage",
"carpetTotal": "634.31",
"otherCarpetTotal": "24.72",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "24.72",
"otherCompositionSaleableTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "724.93",
"finalCarpetArea": "659.03",
"finalSalableArea": "797.43",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "\nCarpet Area in Sq. Ft. = 665.00\nUtility Area in Sq. Ft. =
23.00\n(Area as per Agreement for sale)",
"siteMeasurementRemark": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
  "leaseFrom": "",
  "leaseTo": "",
  "remainingLeasePeriod": 0,
  "leaseDate": ""
}
},
"reportGeneratedDate": "Thu Nov 16 2023 13:43:30 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2023-11-10",
"leadRemarks": []
}
```



<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
Composition :			
Living Room	21'2"	10'1"	213.43
Kitchen	7'3"	9'7"	69.48
Toilet	7'2"	4'4"	31.06
Toilet	4'4"	7'3"	31.42
Bedroom	9'8"	10'3"	99.08
Bedroom	13'10"	9'10"	136.03
Passage	3'5"	15'9"	53.81
Other Composition :			
Dry Balcony	7'5"	3'4"	24.72