

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9d4"
    },
    "type": "CREDITOFFICER",
    "_id": "6531f9ad619c14402da63a80",
    "firstName": "Abhishek",
    "lastName": "Sir",
    "mobileNo": "",
    "workMobileNo": "9769858467",
    "email": "1cbsprabhadevi@unionbankofindia.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "8500000",
    "discussWithPerson": "Abhishek",
    "expectedFees": 4250,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1828",
  "type": "BANK",
  "name": "Union Bank of India",
  "displayName": "Union Bank of India",
  "initial": "UBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9d4",
  "branchCode": "000009",
  "type": "BRANCH",
  "name": "Prabhadevi Branch",
  "email": "cbsprabhadevi@unionbankofindia.com",
  "mobileNo": "02224220497",
  "alternateMobileNo": "",
  "address": "263, Madhu Hans, Near Century Bazar, Dr, Annie Besant
Road, Prabhadevi, Mumbai-400025",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60f93be845132d6a6bdda676",
  "zoneName": "MUMBAI SOUTH"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "62727444afd7d55eddee092c",
"role": "PICKUPPERSON",
"firstName": "Shantilal",
"email": "shantilal@vastukala.org",
"lastName": "Patel",
"mobileNo": "9969039853",
"shortName": "SHP",
"workWithDocumentMaker": "",
"profilePhoto": "users/62727444afd7d55eddee092c/
profilePhoto_1668057663775_WhatsApp_Image_20221110_at_104853_AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "60f949ce45132d6a6bddbcc3",
"role": "SITEENGINEER",
"firstName": "Tushar ",
"email": "tusharbhuwad90@gmail.com",
"lastName": "Bhuwad",
"mobileNo": "9082053889",
"designation": "",
"shortName": "TSB",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f949ce45132d6a6bddbcc3/
profilePhoto_1668058314746_WhatsApp_Image_20221110_at_105931_AM.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60eeaeddf3dd69653a581316",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Shyam",
"email": "shyam@vastukala.org",
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shym_Photo.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "62691c48afd7d55eddecfda3",
"role": "SITEENGINEER+MAKAR",
"firstName": "Bhavika",
"email": "bhavikachavan0102@gmail.com",
"lastName": "chavan",
```

```
"mobileNo": "8390804382",
"designation": "Site Engineer",
"shortName": "BH",
"workWithDocumentMaker": "",
"profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\
profilePhoto_1626255068979_Shyam_Photo.jpg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "[N]C.C.I.T/I -14/52/2008-09",
        "label": "Wealth Tax"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "6084131a13f01f158c6ea1f3",
    "PANNo": "AEAPC7114Q",
    "role": "VALUER",
    "firstName": "Sharadkumar",
    "fatherName": "Baburao",
    "email": "cmd@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9422171100",
    "designation": "CMD",
    "registrationNo": [
      {
        "title": {
          "value": "Wealth_Tax",
          "label": "Wealth Tax"
        }
      }
    ],
    "_id": "6084131a13f01f158c6ea1f4",
```

```
    "number": "[N]C.C.I.T/I -14/52/2008-09"
  }
],
  "shortName": "SBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.101531814514562",
  "longitude": "72.85068132349534"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.85068132349534,
    19.101531814514562
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-11-16T05:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-11-16T05:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-11-16T05:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-11-16T05:30:00.000Z",
      "remark": ""
    }
  ]
}
```

```
    "remark": ""
  }
],
"visitedDate": [
  {
    "status": "COMPLETED",
    "dateTime": "2023-11-19",
    "remark": "MANUAL_IN_TASK"
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Vile Parle",
    "label": true
  },
  "floorNo": {
```

```
"status": true,
"name": "Floor No",
"key": "floorNo",
"value": "3",
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai ",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai Suburban",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Andheri",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "518",
```

```
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "SBI Employees Nilambari Co-op. Hsg. Soc. Ltd. ",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Veer Makrand Ghanekar Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
```



```
"name": "Project Name",
"key": "projectName",
"value": "",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "1958",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "302",
  "label": false
}
```

```
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
```

```
"key": "postalCode",
"value": "PIN - 400 057",
"label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Vile Parle (East)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "White_Marble_Flooring",
    "label": "White Marble Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows_with_M._S._Grills",
    "label": "Powder coated Aluminum sliding windows with M. S. Grills"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
```

```
"label": "Middle Class"
},
"populationGroupList": {
  "value": "Semi_Urban",
  "label": "Semi Urban"
},
"townplanApprovedByList": {
  "value": "MCGM",
  "label": "Municipal Corporation of Greater Mumbai (MCGM)"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Airport Road CHSL",
  "west": "Railway Track",
  "south": "Millan Bridge",
  "east": "Motivilla CHSL"
},
"asPerDocumentAgreement": {
  "north": "Details not available ",
  "west": "Details not available",
  "south": "Details not available",
  "east": "Details not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of Occupancy Certificate No .CHE / WS / 0695 /
K / 337(NEW) Dated 06.06.2016 issued by Municipal\nCorporation Of Greater Mumbai",
"approvePlanVerified": "N.A",
```

```
"empanelledOfApprovePlan": "N.A"
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "10.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "buildingServicesDepreciatedRate": "283.5",
  "depreciatedCostOfConstruction": "28716.50",
  "depreciatedBuildingRate": "2416.5"
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "215850",
  "landRate": "108770",
  "igrImage": "cases/65549396637db60f88b99862/igr_1700548355770_Image.png",
  "squareMeterGuideLineRate": "215850.00",
  "squareFeetGuideLineRate": "20053.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0.00",
  "rate": "19357.00",
  "squareMeterGuideLineRate": "208354.00",
  "squareFeetGuideLineRate": "19357.00",
  "depreciationPercentage": "93"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Middle_Class",
    "label": "Middle Class"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Vacant",
    "label": "Vacant"
  },
  "monthlyRent": "46,500",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
```

```
"floorSpaceIndex": "As per MCGM norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located at developing area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Open Parking",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2016",
    "fullDate": "1/1/2016"
  },
  "planningArea": {
    "value": "Residential",
```

```
"label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Designed_as_per_I.S._codes",
  "label": "Designed as per I.S. codes"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
}
```

```
"maintenancelssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "53",
"ageOfBuilding": "7",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "6",
"flatFloorNo": "3",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "930.00",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  }
}
```



```
    },
    "routeMapImg": "cases/65549396637db60f88b99862/
routeMap_1700552174104_Image.png",
    "routeLat": "19.091525222266878",
    "routeLng": "72.84327224885105",
    "stationName": "Vile Parle",
    "routeDistance": "900 Mt."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "h2aklb",
      "name": "h2aklb",
      "image": "cases/65549396637db60f88b99862/
routeMap_1700552025736_Image.png"
    }
  ],
  "valuation": {
    "wardrobesRate": "0",
    "totalwardrobesRate": "0",
    "wardrobesQty": "0",
    "showcasesQty": "0",
    "showcasesRate": "0",
    "totalshowcasesRate": "0",
    "kitchenArrangementsQty": "0",
    "kitchenArrangementsRate": "0",
    "totalkitchenArrangementsRate": "0",
    "superfineFinishQty": "0",
    "superfineFinishRate": "0",
    "totalsuperfineFinishRate": "0",
    "interiorDecorationsQty": "0",
    "interiorDecorationsRate": "0",
    "totalinteriorDecorationsRate": "0",
    "electricityDepositsQty": "0",
    "electricityDepositsRate": "0",
```

```
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "22255675.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "22255675.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
```

```
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
```

```
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": true,
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "18002010.00",
  "selectedBuildUpValue": "930.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "655ae6f35586e008158c9a17",
      "name": "externallmg_r_1700456179190_IMG20231119161318.jpg",
      "path": "cases/65549396637db60f88b99862/externallmg_r_1700456179190_IMG20231119161318.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "655ae7075586e008158c9a77",
      "name": "externallmg_r_1700456199049_IMG20231119160824.jpg",
      "path": "cases/65549396637db60f88b99862/externallmg_r_1700456199049_IMG20231119160824.jpg",
      "orientation": "portrait"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "655ae7075586e008158c9a7c",
      "name": "externallmg_r_1700456199066_IMG20231119161313.jpg",
      "path": "cases/65549396637db60f88b99862/externallmg_r_1700456199066_IMG20231119161313.jpg",
      "orientation": "portrait"
    }
  ],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": [
    {
```

```
    "status": false,
    "_id": "655ae6f35586e008158c9a10",
    "name": "Living Room",
    "path": "cases/65549396637db60f88b99862/
externallmg_r_1700456179171_IMG20231119160331.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "655ae6f35586e008158c9a0f",
    "name": "Living Room",
    "path": "cases/65549396637db60f88b99862/
externallmg_r_1700456179173_IMG20231119160339.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "655ae7075586e008158c9a73",
    "name": "Living Room",
    "path": "cases/65549396637db60f88b99862/
externallmg_r_1700456199042_IMG20231119160323.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "655ae7075586e008158c9a75",
    "name": "Living Room",
    "path": "cases/65549396637db60f88b99862/
externallmg_r_1700456199047_IMG20231119160358.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "655ae7075586e008158c9a7a",
    "name": "Living Room",
    "path": "cases/65549396637db60f88b99862/
externallmg_r_1700456199057_IMG20231119161120.jpg",
    "orientation": "landscape"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "26412",
    "max": "30882"
  }
},
```

```
"builtUpRateRange": {
  "min": "22010",
  "max": "25736"
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
}
```

```
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
```



```
    "isEditable": false
  }
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "775.00",
"empanelmentNo": [
  "RO(S):ADV:VAL:012: 2018-19"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentId": [],
"audioRemarks": [],
"_id": "65549396637db60f88b99862",
"ownerName": "Mrs. Jyoti Shailesh Mohite & Dr. Shailesh Chintaman Mohite",
"ownerPhoneNo": "9819036050",
"appAddress": "302\nSBI Employees Neelam co operative society\nvileprale E\nMumbai 57",
"remark": "Urgent\n all Documents in Mumbai id ",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    }
  },
  "inputs": {
```

```
"documentDate": "16/11/2023",
"from": {
  "value": "The_Transferor",
  "label": "The Transferor"
},
"The_Transferor": "Mr. Nikhil Suresh Kapadia",
"to": {
  "value": "The_Transferee",
  "label": "The Transferee"
},
"The_Transferee": "Mrs. Jyoti Shailesh Mohite & Dr. Shailesh Chintaman Mohite",
"number": {
  "value": "No",
  "label": "No"
},
"No": "15588/6/44"
},
"isHardCopy": false,
"displayStatus": true,
"id": "355630",
"path": "cases/65549396637db60f88b99862/
document_1700453308033_Document_478.pdf",
"fileName": "document_1700453308033_Document_478.pdf"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "06/06/2016",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_Of_Greater_Mumbai",
      "label": "Municipal Corporation Of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "CHE / WS / 0695 / K / 337(NEW)"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1700550722138_OC_CER.pdf",
  "path": "cases/65549396637db60f88b99862/
document_1700550722138_OC_CER.pdf",
```

```
"id": "796636",
"uploadedBy": "62691c48afd7d55eddecfda3",
"createdAt": "Tue Nov 21 2023 12:42:02 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "005010",
"createdBy": "62727444afd7d55eddee092c",
"caseHistory": [
{
" id": "197205",
" title": "Create Lead",
" description": "Create Lead",
" datetime": "Wed Nov 15 2023 15:17:02 GMT+0530 (India Standard Time)"
}
],
"owners": [
{
" name": "Mrs. Jyoti Shailesh Mohite & Dr. Shailesh Chintaman Mohite",
" phone": "9819036050",
" ownershipShare": "",
" email": "",
" id": "583583"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
{
" measurementType": {
" value": "Square_Feet",
" label": "Square Feet"
}
},
" id": "450802",
" name": "Living Room",
" length": "10.08",
" length1": "10",
" length2": "1",
" width": "22.17",
" width1": "22",
" width2": "2",
" totalArea": "223.51",
" images": [],
" extraAreas": [],
" finalArea": "223.51"
}
],
{
```

```
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "1",
"name": "Bedroom",
"length": "10.25",
"length1": "10",
"length2": "3",
"width": "16.75",
"width1": "16",
"width2": "9",
"totalArea": "171.69",
"images": [],
"extraAreas": [],
"finalArea": "171.69"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Bedroom",
  "length": "11.08",
  "length1": "11",
  "length2": "1",
  "width": "11.50",
  "width1": "11",
  "width2": "6",
  "totalArea": "127.46",
  "images": [],
  "extraAreas": [],
  "finalArea": "127.46"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Kitchen",
  "length": "",
  "length1": "7",
  "length2": "1",
  "width": "",
```

```
"width1": "13",
"width2": "6",
"totalArea": "95.62",
"images": [],
"finalArea": "95.62",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Dining",
  "length": "",
  "length1": "3",
  "length2": "11",
  "width": "",
  "width1": "12",
  "width2": "7",
  "totalArea": "49.28",
  "images": [],
  "finalArea": "49.28",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Toilet",
  "length": "7.08",
  "length1": "7",
  "length2": "1",
  "width": "4.08",
  "width1": "4",
  "width2": "1",
  "totalArea": "28.92",
  "images": [],
  "extraAreas": [],
  "finalArea": "28.92"
},
{
  "measurementType": {
    "value": "Square_Feet",
```

```
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Toilet",
  "length": "3.83",
  "length1": "3",
  "length2": "10",
  "width": "7.17",
  "width1": "7",
  "width2": "2",
  "totalArea": "27.47",
  "images": [],
  "finalArea": "27.47",
  "extraAreas": []
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "label": "Passage",
      "value": "Passage"
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "0",
    "length1": "8",
    "length2": "3",
    "length": "8.25",
    "width1": "3",
    "width2": "8",
    "width": "3.67",
    "totalArea": "30.25",
    "percentageBeforeTotal": "30.25",
    "images": [],
    "extraAreas": [],
    "percentage": "100",
    "finalArea": "30.25"
  },
  {
    "toBeAdded": {
```

```
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Passage",
    "value": "Passage"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "length1": "3",
  "length2": "5",
  "length": "3.42",
  "width1": "5",
  "width2": "4",
  "width": "5.33",
  "totalArea": "18.22",
  "percentageBeforeTotal": "18.22",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "18.22"
}
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "350850",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "775",
    "squareMeterArea": "72",
    "docFinalBuiltUp": "930",
    "docFinalBuiltUpSquareMeter": "86.4",
    "docBultupPercentage": "20",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
```

```
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "655c4f0e5586e008158eb25f",
    "property": "Residential Flat",
    "area": "795",
    "builtUpPercentage": "0",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Built_Up",
    "source": "Nobroker.com",
    "expectedPrice": "19500000",
    "expectedRate": "24528.30",
    "builtUpExpectedRate": "0.00",
    "image": "cases/65549396637db60f88b99862/
indicator_1700548237493_Image.png",
    "squareMeter": "73.86",
    "id": "355455"
  },
  {
    "printlnReport": true,
    "_id": "655c4f0e5586e008158eb260",
    "property": "Residential Flat",
    "area": "600",
    "builtUpPercentage": "0",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Built_Up",
    "source": "Nobroker.com",
    "expectedPrice": "15000000",
    "expectedRate": "25000.00",
    "builtUpExpectedRate": "0.00",
    "image": "cases/65549396637db60f88b99862/
indicator_1700548257003_Image.png",
    "squareMeter": "55.74",
    "id": "737460"
  },
  {
    "printlnReport": true,
    "_id": "655c4f0e5586e008158eb261",
    "property": "Residential Flat",
    "area": "602",
```



```
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"source": "https://www.99acres.com/",
"expectedPrice": "15900000",
"expectedRate": "26411.96",
"builtUpExpectedRate": "22009.97",
"image": "cases/65549396637db60f88b99862/
indicator_1700548275395_Image.png",
"squareMeter": "55.93",
"id": "215064"
},
{
  "printlnReport": true,
  "_id": "655c4f0e5586e008158eb262",
  "property": "Residential Flat",
  "area": "680",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "https://www.99acres.com/",
  "expectedPrice": "21000000",
  "expectedRate": "30882.35",
  "builtUpExpectedRate": "25735.29",
  "image": "cases/65549396637db60f88b99862/
indicator_1700548293545_Image.png",
  "squareMeter": "63.17",
  "id": "753122"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655ae6d85586e008158c99dc",
    "name": "externalImg_r_1700456152006_IMG20231120100023.jpg",
    "path": "cases/65549396637db60f88b99862/
externalImg_r_1700456152006_IMG20231120100023.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655ae6d85586e008158c99dd",
```

```
    "name": "externallmg_r_1700456151945_IMG20231120100013.jpg",
    "path": "cases/65549396637db60f88b99862/
externallmg_r_1700456151945_IMG20231120100013.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655ae6f35586e008158c9a08",
    "name": "externallmg_1700456179159_Screenshot_2023111916122462_3d9111e2
d3171bf4882369f490c087b4.jpg",
    "path": "cases/65549396637db60f88b99862/externallmg_1700456179159_Screens
hot_2023111916122462_3d9111e2d3171bf4882369f490c087b4.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655ae6f35586e008158c9a09",
    "name": "externallmg_r_1700456179149_IMG20231119161405.jpg",
    "path": "cases/65549396637db60f88b99862/
externallmg_r_1700456179149_IMG20231119161405.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655ae6f35586e008158c9a0a",
    "name": "externallmg_r_1700456179154_IMG20231119161415.jpg",
    "path": "cases/65549396637db60f88b99862/
externallmg_r_1700456179154_IMG20231119161415.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655ae6f35586e008158c9a0b",
    "name": "externallmg_r_1700456179164_IMG20231119155636.jpg",
    "path": "cases/65549396637db60f88b99862/
externallmg_r_1700456179164_IMG20231119155636.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655ae6f35586e008158c9a0c",
```

```
    "name": "externallmg_r_1700456179167_IMG20231119155638.jpg",
    "path": "cases/65549396637db60f88b99862/
externallmg_r_1700456179167_IMG20231119155638.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655ae6f35586e008158c9a0d",
    "name": "externallmg_r_1700456179169_IMG20231119160325.jpg",
    "path": "cases/65549396637db60f88b99862/
externallmg_r_1700456179169_IMG20231119160325.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655ae6f35586e008158c9a0e",
    "name": "externallmg_r_1700456179175_IMG20231119160912.jpg",
    "path": "cases/65549396637db60f88b99862/
externallmg_r_1700456179175_IMG20231119160912.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655ae6f35586e008158c9a0f",
    "name": "externallmg_r_1700456179173_IMG20231119160339.jpg",
    "path": "cases/65549396637db60f88b99862/
externallmg_r_1700456179173_IMG20231119160339.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655ae6f35586e008158c9a10",
    "name": "externallmg_r_1700456179171_IMG20231119160331.jpg",
    "path": "cases/65549396637db60f88b99862/
externallmg_r_1700456179171_IMG20231119160331.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655ae6f35586e008158c9a11",
    "name": "externallmg_r_1700456179176_IMG20231119160914.jpg",
```

```
    "path": "cases/65549396637db60f88b99862/
externallmg_r_1700456179176_IMG20231119160914.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655ae6f35586e008158c9a12",
    "name": "externallmg_r_1700456179178_IMG20231119160942.jpg",
    "path": "cases/65549396637db60f88b99862/
externallmg_r_1700456179178_IMG20231119160942.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655ae6f35586e008158c9a13",
    "name": "externallmg_r_1700456179181_IMG20231119161046.jpg",
    "path": "cases/65549396637db60f88b99862/
externallmg_r_1700456179181_IMG20231119161046.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655ae6f35586e008158c9a14",
    "name": "externallmg_r_1700456179183_IMG20231119161123.jpg",
    "path": "cases/65549396637db60f88b99862/
externallmg_r_1700456179183_IMG20231119161123.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655ae6f35586e008158c9a15",
    "name": "externallmg_r_1700456179186_IMG20231119161129.jpg",
    "path": "cases/65549396637db60f88b99862/
externallmg_r_1700456179186_IMG20231119161129.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655ae6f35586e008158c9a16",
    "name": "externallmg_r_1700456179188_IMG20231119161130.jpg",
    "path": "cases/65549396637db60f88b99862/
externallmg_r_1700456179188_IMG20231119161130.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655ae6f35586e008158c9a17",
  "name": "externallmg_r_1700456179190_IMG20231119161318.jpg",
  "path": "cases/65549396637db60f88b99862/
externallmg_r_1700456179190_IMG20231119161318.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655ae6f35586e008158c9a18",
  "name": "externallmg_r_1700456179192_IMG20231119161323.jpg",
  "path": "cases/65549396637db60f88b99862/
externallmg_r_1700456179192_IMG20231119161323.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655ae6f35586e008158c9a19",
  "name": "externallmg_r_1700456179195_IMG20231119161336.jpg",
  "path": "cases/65549396637db60f88b99862/
externallmg_r_1700456179195_IMG20231119161336.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655ae6f35586e008158c9a1a",
  "name": "externallmg_r_1700456179197_IMG20231119161401.jpg",
  "path": "cases/65549396637db60f88b99862/
externallmg_r_1700456179197_IMG20231119161401.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655ae6f35586e008158c9a1b",
  "name": "externallmg_r_1700456179199_IMG20231119161403.jpg",
  "path": "cases/65549396637db60f88b99862/
externallmg_r_1700456179199_IMG20231119161403.jpg",
  "orientation": "portrait"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655ae7075586e008158c9a6e",
  "name": "externallmg_r_1700456199031_IMG20231119160242.jpg",
  "path": "cases/65549396637db60f88b99862/
externallmg_r_1700456199031_IMG20231119160242.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655ae7075586e008158c9a6f",
  "name": "externallmg_r_1700456199024_IMG20231119155649.jpg",
  "path": "cases/65549396637db60f88b99862/
externallmg_r_1700456199024_IMG20231119155649.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655ae7075586e008158c9a70",
  "name": "externallmg_r_1700456199034_IMG20231119160255.jpg",
  "path": "cases/65549396637db60f88b99862/
externallmg_r_1700456199034_IMG20231119160255.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655ae7075586e008158c9a71",
  "name": "externallmg_r_1700456199028_IMG20231119155738.jpg",
  "path": "cases/65549396637db60f88b99862/
externallmg_r_1700456199028_IMG20231119155738.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655ae7075586e008158c9a72",
  "name": "externallmg_r_1700456199039_IMG20231119160309.jpg",
  "path": "cases/65549396637db60f88b99862/
externallmg_r_1700456199039_IMG20231119160309.jpg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655ae7075586e008158c9a73",
  "name": "externallmg_r_1700456199042_IMG20231119160323.jpg",
  "path": "cases/65549396637db60f88b99862/
externallmg_r_1700456199042_IMG20231119160323.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655ae7075586e008158c9a74",
  "name": "externallmg_r_1700456199043_IMG20231119160353.jpg",
  "path": "cases/65549396637db60f88b99862/
externallmg_r_1700456199043_IMG20231119160353.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655ae7075586e008158c9a75",
  "name": "externallmg_r_1700456199047_IMG20231119160358.jpg",
  "path": "cases/65549396637db60f88b99862/
externallmg_r_1700456199047_IMG20231119160358.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655ae7075586e008158c9a76",
  "name": "externallmg_r_1700456199050_IMG20231119160857.jpg",
  "path": "cases/65549396637db60f88b99862/
externallmg_r_1700456199050_IMG20231119160857.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655ae7075586e008158c9a77",
  "name": "externallmg_r_1700456199049_IMG20231119160824.jpg",
  "path": "cases/65549396637db60f88b99862/
externallmg_r_1700456199049_IMG20231119160824.jpg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655ae7075586e008158c9a78",
    "name": "externallmg_r_1700456199055_IMG20231119161040.jpg",
    "path": "cases/65549396637db60f88b99862/
externallmg_r_1700456199055_IMG20231119161040.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655ae7075586e008158c9a79",
    "name": "externallmg_r_1700456199053_IMG20231119161027.jpg",
    "path": "cases/65549396637db60f88b99862/
externallmg_r_1700456199053_IMG20231119161027.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655ae7075586e008158c9a7a",
    "name": "externallmg_r_1700456199057_IMG20231119161120.jpg",
    "path": "cases/65549396637db60f88b99862/
externallmg_r_1700456199057_IMG20231119161120.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655ae7075586e008158c9a7b",
    "name": "externallmg_r_1700456199060_IMG20231119161250.jpg",
    "path": "cases/65549396637db60f88b99862/
externallmg_r_1700456199060_IMG20231119161250.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655ae7075586e008158c9a7c",
    "name": "externallmg_r_1700456199066_IMG20231119161313.jpg",
    "path": "cases/65549396637db60f88b99862/
externallmg_r_1700456199066_IMG20231119161313.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
```



```
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-11-15T09:47:02.109Z",
"updatedAt": "2023-11-21T12:48:38.604Z",
"__v": 0,
"invoiceId": "65549396637db60f88b99868",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 302, 3rd Floor, SBI Employees Nilambari Co-op.
Hsg. Soc. Ltd. , Plot No. 518, Veer Makrand Ghanekar Road, Village - Vile Parle, Vile
Parle (East), Taluka - Andheri, District - Mumbai , Mumbai Suburban, PIN - 400 057,
State - Maharashtra, India",
"updatedBy": "60eeaeddf3dd69653a581316",
"addressForMap": "",
"caseReferredBy": "62727444afd7d55eddee092c",
"contactPersonName": "Dr. Shailesh Chintaman Mohite",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9819036050",
"buildingServicesRate": "2700",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 775.00",
"flatRate": "29000",
"landOtherRate": "26300",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + Dining + 2 Toilet",
"carpetTotal": "723.9499999999999",
"otherCarpetTotal": "48.47",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "48.47",
"otherCompositionSaleableTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "849.66",
"finalCarpetArea": "772.42",
"finalSalableArea": "934.63",
"salablePercentage": "10",
"toBeAdded": "",
```

```

"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"reportGeneratedDate": "Tue Nov 21 2023 16:10:56 GMT+0530 (India Standard Time)",
"siteVisitDate": "2023-11-19",
"leadRemarks": []
}

```

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
<b>Composition :</b>			
Living Room	10'1"	22'2"	223.51
Bedroom	10'3"	16'9"	171.69
Bedroom	11'1"	11'6"	127.46
Kitchen	7'1"	13'6"	95.62
Dining	3'11"	12'7"	49.28
Toilet	7'1"	4'1"	28.92
Toilet	3'10"	7'2"	27.47

Other  
Composition :

Passage	8'3"	3'8"	30.25
Passage	3'5"	5'4"	18.22