

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856bb63"
    },
    "type": "CREDITOFFICER",
    "_id": "64bb68afa87c525d5c04ab8b",
    "firstName": "Sayali",
    "lastName": "Bangar",
    "mobileNo": "",
    "workMobileNo": "8097275708",
    "email": "cord.racpckalyan@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "6418456a96b58848585f8cb2",
"name": "Thane",
"email": "thane@vastukala.com",
"phone": "1234567890",
"address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
"city": "Thane",
"shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856bb63",
  "branchCode": "000355",
  "type": "BRANCH",
  "name": "RACPC Kalyan",
  "email": "cord.racpckalyan@sbi.co.in",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "address": "Ground Floor, 1 st Floor, Millenium Heights, Opp. Patedar Bhawan
Marriage Hall, Shahad Mohone Road, Shahad, Kalyan (West) - 421 103 \n\n",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "6410199a140f140ffc59b58c",
  "role": "PICKUPPERSON",
  "firstName": "Prakash ",
  "email": "prakashnvetkoli@gmail.com",
  "lastName": "Vetkoli",
  "mobileNo": "9076237689",
  "shortName": "PV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/6410199a140f140ffc59b58c/
profilePhoto_1689054480133_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "64e5a649daae6a1c98101989",
  "role": "SITEENGINEER",
  "firstName": "Sameer",
  "email": "sameeryp2010@gmail.com",
  "lastName": "Parab",
  "mobileNo": "8291009567",
  "designation": "Site Engineer",
  "shortName": "Sameer",
  "workWithDocumentMaker": "62ea09ea4e679b264caf07d7"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordinatiion",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "MAKER",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
  "mobileNo": "9821518537",
```

```
"designation": "",
"shortName": "PS",
"workWithDocumentMaker": "60f915d3f3dd69653a592199",
"profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": {
  "_id": "64cde526dc9f3034f3fefa49",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg",
  "firstName": "Rashmi",
  "lastName": "Jadhav",
  "shortName": "RJ",
  "email": "rashmijadhav14feb@gmail.com",
  "designation": "Back Office Coordinatiion",
  "mobileNo": "7738144625",
  "role": "FRONTDESK",
  "type": "EMPLOYEE",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
    {
      "title": {
```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.242170105811574",
  "longitude": "73.12493062208802"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-11-16",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-11-16",
      "remark": ""
    }
  ],
  "schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
```

```
"name": "Village",
"key": "village",
"value": "Kalyan",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "3",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Kalyan (West)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kalyan",
  "label": true
}
```

```
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Silver Heights ",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
```



```
"key": "wing",
"value": "",
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "1892, 1893, 1894, 1895, 1897 & 1891 ",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
}
```

```
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "302",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
```

```
"value": "",
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 421 301",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering_+_POP_Finish",
    "label": "Cement Plastering + POP Finish"
  }
},
"general": {
```

```
"ownership": {
  "value": "Joint_Ownership",
  "label": "Joint Ownership"
},
"populationClassList": {
  "value": "MiddleClass",
  "label": "Middle Class"
},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "Kalyan_Dombivali_Municipal_Corporation",
  "label": "Kalyan Dombivali Municipal Corporation"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Bazar Peth Road",
  "west": "Nilmal Niwas CHSL",
  "south": "Shivade Chana Mart",
  "east": "Anna Saheb Vartak Road"
},
"asPerDocumentAgreement": {
  "north": "Mr. Shivade Property",
  "west": "D. P. Raoad",
  "south": "Mr. Pathare Property",
  "east": "Mr. Pathare Old Property Ground + 2 Floor & Gali"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "asPerDocument": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "isDisplay": false,
```

```
"title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of Approved Building Plan No. KDMC / TPD / BP /
KD / 2020 - 2021 / 04 / 13 Dated 03.04.2021 issued by Kalyan Dombivli Municipal
Corporation.",
"approvePlanVerified": "",
"empanelledOfApprovePlan": ""
},
"compositeRate": {
"remark": "",
"depreciationPercentage": "",
"depreciationRatioOfBuilding": "",
"salvageValue": "",
"depreciatedCostOfConstruction": "",
"depreciatedBuildingRate": ""
},
"igrRate": {
"propertyName": "Residential Flat",
"rate": "57300",
"landRate": "22500",
"igrImage": "cases/65559c25637db60f88b9bf2d/igr_1700216047559_Image.png",
"squareMeterGuideLineRate": "57300.00",
"squareFeetGuideLineRate": "5323.00"
},
"igrFinalRate": {
"floorRatePercentage": "0.00",
"depreciationPercentage": "0",
"rate": "57300",
"squareMeterGuideLineRate": "57300.00",
"squareFeetGuideLineRate": "5323.00"
},
"outgoingDetail": {
"areaStatusList": {
"value": "Medium",
"label": "Medium"
},
"propertyTypeOfUseList": {
"value": "Residential_Purpose",
"label": "Residential Purpose"
},
"propertyOccupiedByList": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"monthlyRent": "8000.00",
```

```
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per KDMC norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "Proposed_Municipal_Water_Supply",
    "label": "Proposed Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Proposed,_Yes",
    "label": "Proposed, Yes"
  },
  "carParking": "Open Parking",
  "constructionWorkStatus": {
    "value": "InProgress",
    "label": "Under Construction"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "",
```

```
"month": "1",
"year": "2025",
"fullDate": "1/1/2025"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "Proposed_Connected_to_Municipal_Sewerage_System_",
  "label": "Proposed Connected to Municipal Sewerage System "
},
"walls": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"appearanceOfTheBuilding": {
  "value": "Good",
```

```
"label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenancelssues": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "As_per_RERA_Certificate",
  "label": "As per RERA Certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "0",
"ageOfBuilding": "0",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "7",
"flatFloorNo": "3",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "2"
},
"finalPlinthArea": {
  "area": "518.10",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
}
```



```
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/65559c25637db60f88b9bf2d/
routeMap_1700221813680_Image.png",
    "routeLat": "19.242306",
    "routeLng": "73.124861",
    "stationName": "Kalyan",
    "routeDistance": "1.2 KM"
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "kkclu89",
      "name": "kkclu89",
      "image": "cases/65559c25637db60f88b9bf2d/
routeMap_1700221547482_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",

```

```
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "3909300.00",
"finalValue": "3909300.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Fri Nov 17 2023 18:16:19 GMT+0530 (India Standard Time)",
  "number": "2303510",
  "dayCount": "18",
  "monthCount": "206",
  "generatedBy": "64cde526dc9f3034f3fefa49"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
```

```
"floorsCompleted": "Complete",
"percentage": "5",
"isHideFloor": false,
"status": true
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "9",
  "percentage": "40",
  "isHideFloor": false,
  "status": true
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "9",
  "percentage": "7.00",
  "isHideFloor": false,
  "status": true
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "9",
  "percentage": "7.00",
  "isHideFloor": false,
  "status": true
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "9",
  "percentage": "3.50",
  "isHideFloor": false,
  "status": true
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "9",
  "percentage": "3.50",
  "isHideFloor": false,
  "status": true
},
"door": {
  "label": "Door",
  "floorsCompleted": "9",
  "percentage": "2.50",
  "isHideFloor": false,
  "status": true
}
```

```
},
"window": {
  "label": "Window",
  "floorsCompleted": "2",
  "percentage": "0.56",
  "isHideFloor": false,
  "status": true
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "9",
  "percentage": "10.00",
  "isHideFloor": false,
  "status": true
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "9",
  "percentage": "1.50",
  "isHideFloor": false,
  "status": true
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "9",
  "percentage": "1.50",
  "isHideFloor": false,
  "status": true
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "9",
  "percentage": "5.00",
  "isHideFloor": false,
  "status": true
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": true,
"status": true
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "92.06",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "2757846.00",
  "selectedBuildUpValue": "518.10",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "6555be7d363cef6b4f5ee678",
      "name": "externallmg_1700118133837_1700118189567_image_1.jpeg",
      "path": "cases/65559c25637db60f88b9bf2d/
externallmg_1700118133837_1700118189567_image_1.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "6555be7d363cef6b4f5ee67f",
      "name": "externallmg_1700118135532_1700118189567_image_8.jpeg",
      "path": "cases/65559c25637db60f88b9bf2d/
externallmg_1700118135532_1700118189567_image_8.jpeg",
      "orientation": "landscape"
    }
  ],
  "externalPhotos": [
```

```
{
  "status": false,
  "_id": "6555be7d363cef6b4f5ee67d",
  "name": "externallmg_1700118134812_1700118189567_image_6.jpeg",
  "path": "cases/65559c25637db60f88b9bf2d/
externallmg_1700118134812_1700118189567_image_6.jpeg",
  "orientation": "portrait"
}
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "6555be7d363cef6b4f5ee67e",
    "name": "Living Room",
    "path": "cases/65559c25637db60f88b9bf2d/
externallmg_1700118135232_1700118189567_image_7.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6555be7d363cef6b4f5ee680",
    "name": "Living Room",
    "path": "cases/65559c25637db60f88b9bf2d/
externallmg_1700118135677_1700118189567_image_9.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6555be7d363cef6b4f5ee684",
    "name": "Bedroom",
    "path": "cases/65559c25637db60f88b9bf2d/
externallmg_1700118136262_1700118189567_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6555be7d363cef6b4f5ee683",
    "name": "Kitchen",
    "path": "cases/65559c25637db60f88b9bf2d/
externallmg_1700118136057_1700118189567_image_12.jpeg",
    "orientation": "portrait"
  }
]
},
```

```
"indicatorRange": {
  "carpetRateRange": {
    "min": "6369",
    "max": "8500"
  },
  "builtUpRateRange": {
    "min": "5308",
    "max": "7084"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
```



```
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "471.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentId": [],
"audioRemarks": [],
"_id": "65559c25637db60f88b9bf2d",
"ownerName": "Mr. Rizwan Yakub Maniyar & Mrs. Maherunnisa Rizwan Maniyar",
"ownerPhoneNo": "7977488010",
"fullAddress": "Residential Flat No. 302, 3rd Floor, Silver Heights , Village - Kalyan,
Taluka - Kalyan, Kalyan (West), PIN Code - 421 301, State - Maharashtra, India",
"remark": "",
"documents": [
  {
```

```
"documentType": {
  "value": "60af48bf2ffdf65bcd6585fa",
  "label": "Agreement for sale"
},
"inputs": {
  "documentDate": "10/10/2023",
  "from": {
    "value": "Promoter",
    "label": "Promoter"
  },
  "Promoter": "M/s. Sulbha Enterprises",
  "to": {
    "value": "purchaser",
    "label": "purchaser"
  },
  "purchaser": "Mr. Rizwan Yakub Maniyar & Mrs. Maherunnisa Rizwan Maniyar",
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "21723/2023"
},
"isHardCopy": false,
"displayStatus": true,
"id": "166456",
"path": "cases/65559c25637db60f88b9bf2d/
document_1700109336036_agreement_0001_2.pdf",
"fileName": "document_1700109336036_agreement_0001_2.pdf"
},
{
  "documentType": {
    "value": "60ae1279aa6d152c1801b3d4",
    "label": "Amended Commencement Certificate"
  },
  "inputs": {
    "documentDate": "09/04/2021",
    "nameOfApprovingAuthority": {
      "value": "Kalyan_Dombivli_Municipal_Corporation",
      "label": "Kalyan Dombivli Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "KDMC / TPD / BP / KD / 2020-2021 / 04 / 13"
  },
}
```

```
"isHardCopy": false,
"displayStatus": true,
"id": "978196",
"path": "cases/65559c25637db60f88b9bf2d/
document_1700219792587_239367.pdf",
"fileName": "document_1700219792587_239367.pdf"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "30/08/2021",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
      "label": "Maharashtra Real Estate Regulatory Authority"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "P51700030528"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1700219932407_188724.pdf",
  "path": "cases/65559c25637db60f88b9bf2d/
document_1700219932407_188724.pdf",
  "id": "184380",
  "uploadedBy": "627222afafd7d55eddedd82",
  "createdAt": "Fri Nov 17 2023 16:48:52 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "09/04/2021",
    "nameOfApprovingAuthority": {
      "value": "Kalyan_Dombivli_Municipal_Corporation",
      "label": "Kalyan Dombivli Municipal Corporation"
    },
    "number": {
      "value": "No",
```

```
    "label": "No"
  },
  "No": "KDMC / TPD / BP / KD / 2020 - 2021 / 04 / 13"
},
"isHardCopy": false,
"displayStatus": false,
"id": "532891",
"path": "cases/65559c25637db60f88b9bf2d/
document_1700220157078_1700216072929_Plan.pdf",
"fileName": "document_1700220157078_1700216072929_Plan.pdf"
},
{
  "documentType": {
    "value": "60ae12b6aa6d152c1801b4ea",
    "label": "DEMAND LETTER"
  },
  "inputs": {
    "documentDate": "30/10/2023",
    "remark": "issued by Sulbha Enterprises Builders & Developers"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1700220313568_92931.pdf",
  "path": "cases/65559c25637db60f88b9bf2d/document_1700220313568_92931.pdf",
  "id": "953811",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Fri Nov 17 2023 16:55:13 GMT+0530 (India Standard Time)"
}
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "005018",
"createdBy": "6430f74691d7c62df11f3f15",
"caseHistory": [
  {
    "id": "225423",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Nov 16 2023 10:05:49 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Rizwan Yakub Maniyar & Mrs. Maherunnisa Rizwan Maniyar",
```

```
"phone": "7977488010",
"ownershipShare": "",
"email": "",
"id": "467271"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "273807",
"name": "Living Room",
"length": "13.00",
"length1": "13",
"length2": "00",
"width": "9.00",
"width1": "9",
"width2": "00",
"totalArea": "117.00",
"images": [],
"extraAreas": [],
"finalArea": "117.00"
},
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "2",
"name": "Kitchen",
"length": "",
"length1": "7",
"length2": "0",
"width": "",
"width1": "12",
"width2": "0",
"totalArea": "84.00",
"images": [],
"finalArea": "84.00",
"extraAreas": []
},
{
```

```
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "2",
"name": "Toilet",
"length": "4.00",
"length1": "4",
"length2": "00",
"width": "7.00",
"width1": "7",
"width2": "00",
"totalArea": "28.00",
"images": [],
"extraAreas": [],
"finalArea": "28.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bedroom",
  "length": "17.00",
  "length1": "17",
  "length2": "00",
  "width": "6.00",
  "width1": "6",
  "width2": "00",
  "totalArea": "102.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "102.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "7.00",
  "length1": "7",
  "length2": "00",
  "width": "5.00",
```

```
"width1": "5",
"width2": "00",
"totalArea": "35.00",
"images": [],
"extraAreas": [],
"finalArea": "35.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Balcony",
  "length": "23.00",
  "length1": "23",
  "length2": "00",
  "width": "2.00",
  "width1": "2",
  "width2": "00",
  "totalArea": "46.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "46.00"
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "label": "Dry Balcony",
      "value": "Dry_Balcony"
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "0",
    "length1": "3",
    "length2": "00",
    "length": "3.00",
    "width1": "8",
    "width2": "00",
```

```
"width": "8.00",
"totalArea": "24.00",
"percentageBeforeTotal": "24.00",
"images": [],
"extraAreas": [],
"percentage": "100",
"finalArea": "24"
}
],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "value": "60af48bf2ffdf65bcd6585fa",
    "label": "Agreement for sale"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "selectAreaTypeDocument": "Carpet",
  "squareMeterArea": "43.76",
  "totalAreaDocument": "471",
  "docBUILTUPPercentage": "10",
  "docFinalBUILTUP": "518.10",
  "docFinalBUILTUPSquareMeter": "48.13",
  "docSaleablePercentage": "",
  "docFinalSaleable": "0.00",
  "docFinalSaleableSquareMeter": "0.00",
  "id": "740892"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "65573d205586e0081589d1a9",
  "property": "Residential Flat",
  "area": "378",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "Commonfloor.com",
  "expectedPrice": "3213000",
  "expectedRate": "8500.00",
```



```
    "builtUpExpectedRate": "7083.33",
    "image": "cases/65559c25637db60f88b9bf2d/
indicator_1700215860281_Image.png",
    "squareMeter": "35.12",
    "id": "190405"
  },
  {
    "printlnReport": true,
    "_id": "65573d205586e0081589d1aa",
    "property": "Residential Flat",
    "area": "471",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "sale_Instance",
    "areaType": "Carpet",
    "source": "Index_no.2",
    "expectedPrice": "3000000",
    "expectedRate": "6369.43",
    "builtUpExpectedRate": "5307.86",
    "image": "cases/65559c25637db60f88b9bf2d/
indicator_1700215905313_Image.png",
    "squareMeter": "43.76",
    "id": "267281"
  }
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6555be7d363cef6b4f5ee677",
    "name": "externalImg_1700118133679_1700118189567_image_0.jpeg",
    "path": "cases/65559c25637db60f88b9bf2d/
externalImg_1700118133679_1700118189567_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6555be7d363cef6b4f5ee678",
    "name": "externalImg_1700118133837_1700118189567_image_1.jpeg",
    "path": "cases/65559c25637db60f88b9bf2d/
externalImg_1700118133837_1700118189567_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "6555be7d363cef6b4f5ee679",
    "name": "externallmg_1700118134057_1700118189567_image_2.jpeg",
    "path": "cases/65559c25637db60f88b9bf2d/
externallmg_1700118134057_1700118189567_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6555be7d363cef6b4f5ee67a",
    "name": "externallmg_1700118134207_1700118189567_image_3.jpeg",
    "path": "cases/65559c25637db60f88b9bf2d/
externallmg_1700118134207_1700118189567_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6555be7d363cef6b4f5ee67b",
    "name": "externallmg_1700118134360_1700118189567_image_4.jpeg",
    "path": "cases/65559c25637db60f88b9bf2d/
externallmg_1700118134360_1700118189567_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6555be7d363cef6b4f5ee67c",
    "name": "externallmg_1700118134582_1700118189567_image_5.jpeg",
    "path": "cases/65559c25637db60f88b9bf2d/
externallmg_1700118134582_1700118189567_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6555be7d363cef6b4f5ee67d",
    "name": "externallmg_1700118134812_1700118189567_image_6.jpeg",
    "path": "cases/65559c25637db60f88b9bf2d/
externallmg_1700118134812_1700118189567_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "6555be7d363cef6b4f5ee67e",
    "name": "externallmg_1700118135232_1700118189567_image_7.jpeg",
    "path": "cases/65559c25637db60f88b9bf2d/
externallmg_1700118135232_1700118189567_image_7.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6555be7d363cef6b4f5ee67f",
    "name": "externallmg_1700118135532_1700118189567_image_8.jpeg",
    "path": "cases/65559c25637db60f88b9bf2d/
externallmg_1700118135532_1700118189567_image_8.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6555be7d363cef6b4f5ee680",
    "name": "externallmg_1700118135677_1700118189567_image_9.jpeg",
    "path": "cases/65559c25637db60f88b9bf2d/
externallmg_1700118135677_1700118189567_image_9.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6555be7d363cef6b4f5ee681",
    "name": "externallmg_1700118135762_1700118189567_image_10.jpeg",
    "path": "cases/65559c25637db60f88b9bf2d/
externallmg_1700118135762_1700118189567_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6555be7d363cef6b4f5ee682",
    "name": "externallmg_1700118135817_1700118189567_image_11.jpeg",
    "path": "cases/65559c25637db60f88b9bf2d/
externallmg_1700118135817_1700118189567_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6555be7d363cef6b4f5ee683",
```

```
    "name": "externallmg_1700118136057_1700118189567_image_12.jpeg",
    "path": "cases/65559c25637db60f88b9bf2d/
externallmg_1700118136057_1700118189567_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6555be7d363cef6b4f5ee684",
    "name": "externallmg_1700118136262_1700118189567_image_13.jpeg",
    "path": "cases/65559c25637db60f88b9bf2d/
externallmg_1700118136262_1700118189567_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6555be7d363cef6b4f5ee685",
    "name": "externallmg_1700118136387_1700118189567_image_14.jpeg",
    "path": "cases/65559c25637db60f88b9bf2d/
externallmg_1700118136387_1700118189567_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6555be7d363cef6b4f5ee686",
    "name": "externallmg_1700118109560_1700118156614_image_0.jpeg",
    "path": "cases/65559c25637db60f88b9bf2d/
externallmg_1700118109560_1700118156614_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6555be7d363cef6b4f5ee687",
    "name": "externallmg_1700118109675_1700118156614_image_1.jpeg",
    "path": "cases/65559c25637db60f88b9bf2d/
externallmg_1700118109675_1700118156614_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6555be7d363cef6b4f5ee688",
    "name": "externallmg_1700118109808_1700118166834_image_0.jpeg",
```

```
    "path": "cases/65559c25637db60f88b9bf2d/
externalImg_1700118109808_1700118166834_image_0.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Calculation Sheet NEW.xlsx",
    "filename": "1700216066534_Calculation_Sheet_NEW.xlsx",
    "path": "cases/65559c25637db60f88b9bf2d/
processingDocuments/1700216066534_Calculation_Sheet_NEW.xlsx",
    "size": "1022399",
    "createdAt": "Fri Nov 17 2023 15:44:26 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  },
  {
    "originalname": "Plan.pdf",
    "filename": "1700216072929_Plan.pdf",
    "path": "cases/65559c25637db60f88b9bf2d/
processingDocuments/1700216072929_Plan.pdf",
    "size": "882618",
    "createdAt": "Fri Nov 17 2023 15:44:33 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  }
],
"remarks": [],
"createdAt": "2023-11-16T04:35:50.009Z",
"updatedAt": "2023-11-17T12:50:08.929Z",
"__v": 0,
"invoiceId": "65559c26637db60f88b9bf3b",
"updatedBy": "64cde526dc9f3034f3fefa49",
"addressForMap": "",
"caseReferredBy": "6410199a140f140ffc59b58c",
"contactPersonName": "Mr. Zafar",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Site Supervisor",
"siteVisitContactNo": "8655504879",
"buildingServicesRate": "2500",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
```

```
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 471.00",
"flatRate": "8300",
"landOtherRate": "5800",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + 2 Toilet + Balcony",
"carpetTotal": "384.00",
"otherCarpetTotal": "24.00",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "24.00",
"otherCompositionSaleableTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "479.60",
"finalCarpetArea": "436.00",
"finalSalableArea": "527.56",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "\nAll the above areas are within 8% of the Agreement for Sale
Area. The above calculations and detail measurements taken by us prove that the
Agreement for Sale are is not exorbitantly inflated. Hence, valuation is based on the
Agreement for Sale area",
"siteMeasurementRemark": "\n",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
  "leaseFrom": "",
  "leaseTo": "",
  "remainingLeasePeriod": 0,
  "leaseDate": ""
}
},
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"leadRemarks": []
```

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
Composition :			
Living Room	13'00"	9'00"	117.00
Kitchen	7'0"	12'0"	84.00
Toilet	4'00"	7'00"	28.00
Bedroom	17'00"	6'00"	102.00
Toilet	7'00"	5'00"	35.00
Balcony	23'00"	2'00"	46.00
Other Composition :			
Dry Balcony	3'00"	8'00"	24.00