

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b80a"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f65be948726cc1419a7",
    "email": "kaushik.datta@sbi.co.in",
    "firstName": "KAUSHUIK",
    "mobileNo": "",
    "workMobileNo": "9757023640",
    "lastName": " DATTA "
  },
  "fees": {
    "type": "fixed"
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",
    "name": "Mumbai",
    "shortName": "VCIPL/Mumbai",
    "email": "vastukalamumbai@vastukala.com",
  }
}
```

```
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b80a",
  "branchCode": "000088",
  "type": "BRANCH",
  "name": "RACPC- Chinchpokli ",
  "email": "sbi.17889@sbi.co.in",
  "mobileNo": "022-23707514",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, Mumbai South Voltas
House, 'A', 1st Floor, Dr. Ambedkar Road, Chinchpokli (East), Mumbai - 400 033, State
- Maharashtra, Country - India.\r\n",
  "ledgerName": "STATE BANK OF INDIA - CHINCHPOKALI",
  "fax": "022-23707512 / 13",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "62727444afd7d55eddee092c",
    "role": "PICKUPPERSON",
    "firstName": "Shantilal",
```

```
"email": "shantilal@vastukala.org",
"lastName": "Patel",
"mobileNo": "9969039853",
"shortName": "SHP",
"workWithDocumentMaker": "",
"profilePhoto": "users/62727444afd7d55eddee092c/
profilePhoto_1668057663775_WhatsApp_Image_20221110_at_104853_AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "60f9343b45132d6a6bdd96e8",
"role": "SITEENGINEER",
"firstName": "Rajesh",
"email": "rajeshb.ghadi@gmail.com",
"lastName": "Ghadi",
"mobileNo": "8652092666",
"designation": "",
"shortName": "RHG",
"workWithDocumentMaker": ""
},
"rateVerifier": "",
"maker": {
"type": "EMPLOYEE",
"_id": "60eeaeddf3dd69653a581316",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Shyam",
"email": "shyam@vastukala.org",
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shyma_Photo.jpg"
},
"checker": "",
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
]
},
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
```

```
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
```

```
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.08963088767782",
  "longitude": "73.07685046626213"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.07685046626213,
    19.08963088767782
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "2023-11-16T10:00:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-11-16T10:00:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-11-16T10:00:00.000Z",
      "remark": ""
    }
  ]
},
"visitedDate": [],
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
}
```

```
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Rohinjan",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "12",
    "label": false
  },
  "buildingNo": {
    "status": true,
    "name": "Building No",
    "key": "buildingNo",
    "value": "3",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
    "value": "Raigad",
    "label": true
  },
  "city": {
    "status": true,
```

```
"name": "City",
"key": "city",
"value": "Navi Mumbai",
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Panvel",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Anandam - II",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
}
```

```
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A ",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "112/1, 113/2, 114/1A, 114/9A, 114/10/11/B, 115/6",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
```



```
"key": "hissaNo",
"value": "",
"label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1207",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
}
```

```
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "410210",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "Proposed_Vitrified_tiles_flooring",
    "label": "Proposed Vitrified tiles flooring"
  },
  "doors": {
```

```
"value": "Proposed_Teak_wood_door_frame_with_flush_doors",
"label": "Proposed Teak wood door frame with flush doors"
},
"windows": {
"value": "Proposed_Powder_coated_aluminium_sliding_windows",
"label": "Proposed Powder coated aluminium sliding windows"
},
"fittings": {
"value": "Proposed_Concealed_plumbing_with_C.P._fittings._Proposed_Electrical_wiring_with_Concealed.",
"label": "Proposed Concealed plumbing with C.P. fittings. Proposed Electrical wiring with Concealed."
},
"finishing": {
"value": "Proposed_Cement_Plastering",
"label": "Proposed Cement Plastering"
}
},
"general": {
"ownership": {
"value": "Joint_Ownership",
"label": "Joint Ownership"
},
"populationClassList": {
"value": "MiddleClass",
"label": "Middle Class"
},
"populationGroupList": {
"value": "Urban",
"label": "Urban"
},
"townplanApprovedByList": {
"value": "Panvel_Municipal_Corporation",
"label": "Panvel Municipal Corporation"
},
"whetherCoveredUnderAnyState": {
"value": "No",
"label": "No"
},
"asPerActualAgreement": {
"north": "Open Plot",
"west": "Internal Road",
"south": "Internal Road",
"east": "Internal Road"
},
"asPerDocumentAgreement": {
```

```
"north": "Details not available",
"west": "Details not available",
"south": "Details not available",
"east": "Details not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "asPerDocument": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of approved building plan were not provided and not verified.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A."
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "0",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "buildingServicesDepreciatedRate": "0",
  "depreciatedCostOfConstruction": "13200.00",
  "depreciatedBuildingRate": "2500"
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "56400",
  "landRate": "7380",
  "igrImage": "cases/65559d8f637db60f88b9c807/igr_1700130000605_Image.png",
  "squareMeterGuideLineRate": "62040.00",
  "squareFeetGuideLineRate": "5764.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0.00",
```

```
"rate": "56400.00",
"squareMeterGuideLineRate": "62040.00",
"squareFeetGuideLineRate": "5764.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  },
  "monthlyRent": "21000.00",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per PMC norms",
  "tenantName": "",
  "maintenanceOfFlat": "Building is under construction"
},
"marketability": {
  "marketabilityList": {
    "value": "Average",
    "label": "Average"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "N.A."
},
"siteMeasurement": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "partitions": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  },
  "waterTank": {
```

```
"value": "Proposed_Municipal_Water_Supply",
"label": "Proposed Municipal Water Supply"
},
"pavementLaid": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"carParking": "Open",
"constructionWorkStatus": {
"value": "InProgress",
"label": "Under Construction"
},
"asthetikLook": {
"value": "Plain_Looking",
"label": "Plain Looking"
},
"dateOfConstruction": {
"date": "",
"month": "1",
"year": "2027",
"fullDate": "1/1/2027"
},
"planningArea": {
"value": "Residential",
"label": "Residential"
},
"typeOfStructure": {
"value": "R.C.C.",
"label": "R.C.C. Framed"
},
"typeOfFoundation": {
"value": "rcc",
"label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
"value": "UnderConstruction",
"label": "Building Under Construction"
},
"materialUsedList": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"buildingSpecification": {
"value": "Standard",
"label": "Standard"
},
}
```

```
"structuralSafety": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "Proposed_Connected_to_Municipal_Sewerage_System_",
  "label": "Proposed Connected to Municipal Sewerage System "
},
"walls": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"appearanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenancelssues": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"visibleDamageInBuilding": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"systemOfAirConditioning": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"provisionOfFirefighting": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "As_per_RERA_Certificate",
```

```
"label": "As per RERA Certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "0",
"ageOfBuilding": "0",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "14",
"flatFloorNo": "12",
"noOfLifts": "3",
"noOfDwellingUnitsInBuilding": "8"
},
"finalPlinthArea": {
  "area": "701.80",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/65559d8f637db60f88b9c807/
routeMap_1700299489311_Image.png",
    "routeLat": "19.087907",
    "routeLng": "73.074871",
    "stationName": "Taloja",
    "routeDistance": "2 Km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "oo8z19",
```



```
    "name": "oo8z19",
    "image": "cases/65559d8f637db60f88b9c807/
routeMap_1700299438086_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "8421600.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValue": "0",
  "finalValue": "8421600.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
}
```

```
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
    "label": "External Plastering",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```

},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "10.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "4045175.00",
  "selectedBuildUpValue": "701.80",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "65573cc15586e0081589d0b5",
      "name":
"externalImg_1700216001836_WhatsApp_Image_20231117_at_34045_PM_1.jpeg",
      "path": "cases/65559d8f637db60f88b9c807/
externalImg_1700216001836_WhatsApp_Image_20231117_at_34045_PM_1.jpeg",
      "orientation": "landscape"
    }
  ]
}

```

```
],
"selfieWithSiteVisitImages": [],
"externalPhotos": [
  {
    "status": false,
    "_id": "65573cc15586e0081589d0b2",
    "name":
"externallmg_1700216001826_WhatsApp_Image_20231117_at_34044_PM_1.jpeg",
    "path": "cases/65559d8f637db60f88b9c807/
externallmg_1700216001826_WhatsApp_Image_20231117_at_34044_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "65573cc15586e0081589d0b3",
    "name":
"externallmg_1700216001828_WhatsApp_Image_20231117_at_34044_PM_2.jpeg",
    "path": "cases/65559d8f637db60f88b9c807/
externallmg_1700216001828_WhatsApp_Image_20231117_at_34044_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "65573cc15586e0081589d0b4",
    "name":
"externallmg_1700216001832_WhatsApp_Image_20231117_at_34044_PM.jpeg",
    "path": "cases/65559d8f637db60f88b9c807/
externallmg_1700216001832_WhatsApp_Image_20231117_at_34044_PM.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "12587",
    "max": "15231"
  },
  "builtUpRateRange": {
    "min": "11444",
    "max": "13847"
  }
},
"detailsOfValuation": {
```

```
"presentValueOfFlat": {
  "title": "Present value of the flat (incl. car parking, if provided)",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```

```
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
```

```
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Approximate Rate Lead",
  "value": "APPROXIMATE_LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": false,
"finalValuationArea": "638.00",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"paymentId": [],
"audioRemarks": [],
"_id": "65559d8f637db60f88b9c807",
"ownerName": "Mrs. Pallavi Pandey & Mr. Amrita Nand",
"ownerPhoneNo": "9004475993",
"appAddress": "1207\nbuilding no 3A\nANAND DHAM li\nPANVEL ",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "23/10/2023",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "Today Global Homes",
      "to": {
        "value": "Purchaser",
        "label": "Purchaser"
      }
    }
  }
]
```



```
    },
    "Purchaser": "Mrs. Pallavi Pandey & Mr. Amrita Nand",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "14802/2023"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "992987",
  "path": "cases/65559d8f637db60f88b9c807/
document_1700112119091_1700112162263_Pallavi_Pandye_serach_file.pdf",
  "fileName":
"document_1700112119091_1700112162263_Pallavi_Pandye_serach_file.pdf"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "07/12/2022",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
      "label": "Maharashtra Real Estate Regulatory Authority"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "P52000048037"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1700293247900_1636486.pdf",
  "path": "cases/65559d8f637db60f88b9c807/
document_1700293247900_1636486.pdf",
  "id": "965255",
  "uploadedBy": "60eeaeddf3dd69653a581316",
  "createdAt": "Sat Nov 18 2023 13:10:47 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "005019",
"createdBy": "62727444afd7d55eddee092c",
"caseHistory": [
```

```
{
  "id": "205315",
  "title": "Create Lead",
  "description": "Create Lead",
  "datetime": "Thu Nov 16 2023 10:11:51 GMT+0530 (India Standard Time)"
}
],
"owners": [
  {
    "name": "Mrs. Pallavi Pandey & Mr. Amrita Nand",
    "phone": "9004475993",
    "ownershipShare": "",
    "email": "",
    "id": "831497"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "59.27",
    "totalAreaDocument": "638",
    "docBultupPercentage": "10",
    "docFinalBultUp": "701.80",
    "docFinalBultUpSquareMeter": "65.20",
    "docSaleablePercentage": "",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "697344"
  }
],
"images": [],
"indicatorArr": [
  {
```

```
"printlnReport": true,
  "_id": "6555ecf45586e00815881296",
  "property": "Residential Flat",
  "area": "650",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "magic_bricks",
  "expectedPrice": "9900000",
  "expectedRate": "15230.77",
  "builtUpExpectedRate": "13846.15",
  "image": "cases/65559d8f637db60f88b9c807/
indicator_1700129494202_Image.png",
  "squareMeter": "60.39",
  "id": "224894"
},
{
  "printlnReport": true,
  "_id": "6555ecf45586e00815881297",
  "property": "Residential Flat",
  "area": "600",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "magic_bricks",
  "expectedPrice": "8400000",
  "expectedRate": "14000.00",
  "builtUpExpectedRate": "12727.27",
  "image": "cases/65559d8f637db60f88b9c807/
indicator_1700129510838_Image.png",
  "squareMeter": "55.74",
  "id": "784680"
},
{
  "printlnReport": true,
  "_id": "6555ecf45586e00815881298",
  "property": "Residential Flat",
  "area": "650",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "Nobroker.com",
  "expectedPrice": "9900000",
```

```
    "expectedRate": "15230.77",
    "builtUpExpectedRate": "13846.15",
    "image": "cases/65559d8f637db60f88b9c807/
indicator_1700129538078_Image.png",
    "squareMeter": "60.39",
    "id": "412723"
  },
  {
    "printlnReport": true,
    "_id": "6555ecf45586e00815881299",
    "property": "Residential Flat",
    "area": "429",
    "builtUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "Housing.Com",
    "expectedPrice": "5400000",
    "expectedRate": "12587.41",
    "builtUpExpectedRate": "11443.10",
    "image": "cases/65559d8f637db60f88b9c807/
indicator_1700129599417_Image.png",
    "squareMeter": "39.86",
    "id": "159814"
  }
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65573cc15586e0081589d0af",
    "name":
"externallmg_1700216001813_WhatsApp_Image_20231117_at_34042_PM.jpeg",
    "path": "cases/65559d8f637db60f88b9c807/
externallmg_1700216001813_WhatsApp_Image_20231117_at_34042_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65573cc15586e0081589d0b0",
    "name":
"externallmg_1700216001817_WhatsApp_Image_20231117_at_34043_PM_1.jpeg",
    "path": "cases/65559d8f637db60f88b9c807/
externallmg_1700216001817_WhatsApp_Image_20231117_at_34043_PM_1.jpeg",
    "orientation": "portrait"
  }
]
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65573cc15586e0081589d0b1",
  "name":
  "externallmg_1700216001822_WhatsApp_Image_20231117_at_34043_PM.jpeg",
  "path": "cases/65559d8f637db60f88b9c807/
externallmg_1700216001822_WhatsApp_Image_20231117_at_34043_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65573cc15586e0081589d0b2",
  "name":
  "externallmg_1700216001826_WhatsApp_Image_20231117_at_34044_PM_1.jpeg",
  "path": "cases/65559d8f637db60f88b9c807/
externallmg_1700216001826_WhatsApp_Image_20231117_at_34044_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65573cc15586e0081589d0b3",
  "name":
  "externallmg_1700216001828_WhatsApp_Image_20231117_at_34044_PM_2.jpeg",
  "path": "cases/65559d8f637db60f88b9c807/
externallmg_1700216001828_WhatsApp_Image_20231117_at_34044_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65573cc15586e0081589d0b4",
  "name":
  "externallmg_1700216001832_WhatsApp_Image_20231117_at_34044_PM.jpeg",
  "path": "cases/65559d8f637db60f88b9c807/
externallmg_1700216001832_WhatsApp_Image_20231117_at_34044_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65573cc15586e0081589d0b5",
  "name":
  "externallmg_1700216001836_WhatsApp_Image_20231117_at_34045_PM_1.jpeg",
```

```
    "path": "cases/65559d8f637db60f88b9c807/
externallmg_1700216001836_WhatsApp_Image_20231117_at_34045_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65573cc15586e0081589d0b6",
    "name":
"externallmg_1700216001837_WhatsApp_Image_20231117_at_34045_PM_2.jpeg",
    "path": "cases/65559d8f637db60f88b9c807/
externallmg_1700216001837_WhatsApp_Image_20231117_at_34045_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65573cc15586e0081589d0b7",
    "name":
"externallmg_1700216001839_WhatsApp_Image_20231117_at_34045_PM.jpeg",
    "path": "cases/65559d8f637db60f88b9c807/
externallmg_1700216001839_WhatsApp_Image_20231117_at_34045_PM.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Summary New=PALLAVI.xlsx",
    "filename": "1700130049822_Summary_NewPALLAVI.xlsx",
    "path": "cases/65559d8f637db60f88b9c807/
processingDocuments/1700130049822_Summary_NewPALLAVI.xlsx",
    "size": "3370701",
    "createdAt": "Thu Nov 16 2023 15:50:49 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  }
],
"remarks": [
  {
    "createdBy": {
      "_id": "60eeaeddf3dd69653a581316",
      "role": "MAKER + RATE VERFIER + CHEAKER",
      "firstName": "Shyam",
      "lastName": "Kajvilkar",
      "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
profilePhoto_1626255068979_Shymam_Photo.jpg"
```

```
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "6555e4145586e0081587e9c8",
    "note": "Approx. Value Given Rs. 84 Lakh",
    "taskId": "65559d92637db60f88b9c834",
    "createdAt": "2023-11-16T09:42:44.070Z"
  }
],
"createdAt": "2023-11-16T04:41:51.817Z",
"updatedAt": "2023-11-18T09:25:28.444Z",
"__v": 0,
"updatedBy": "60eeaeddf3dd69653a581316",
"fullAddress": "Residential Flat No. 1207, 12th Floor, Building No 3, Wing - A ,
Anandam - II, Village - Rohinjan, Taluka - Panvel, District - Raigad, Navi Mumbai,
410210, State - Maharashtra, India",
"addressForMap": "",
"caseReferredBy": "62727444afd7d55eddee092c",
"contactPersonName": "Kishor Shinde",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Sales Person",
"siteVisitContactNo": "9324509832",
"buildingServicesRate": "2500",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 638.00",
"flatRate": "13200",
"landOtherRate": "10700",
"builtupPercentage": "10",
"carpetTotal": "0",
"extendOfSiteRemark": "",
"finalBuiltupArea": "0.00",
"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"otherCarpetTotal": "0",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
```

```

"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"leadRemarks": []
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			