

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b895"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f66be948726cc141b2f",
    "email": "asmita.doshi@cosmosbank.in",
    "firstName": "ASMITA ",
    "mobileNo": "",
    "workMobileNo": "9922662811",
    "lastName": " DOSHI"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "2200000",
    "discussWithPerson": "ASMITA ",
    "expectedFees": 1100,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b895",
  "branchCode": "000001",
  "type": "BRANCH",
  "name": "Bhayander (West) Branch",
  "email": "bhayander@cosmosbank.in",
  "mobileNo": "022-28041167",
  "alternateMobileNo": "022-28041168",
  "address": "Shop No. 3, 4, 5, Rishab Apartment, S. No. - 5A, Hissa No. 1Part, Patel
Nagar No.1, Station Road, Bhayander (West), Thane - 401 101, State -Maharashtra,
Country - India",
  "ledgerName": "COSMOS BANK - Bhayander",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "627219d6afd7d55eddedd283",
  "role": "PICKUPPERSON",
  "firstName": "Mangesh ",
  "email": "mangeshpalande17@gmail.com",
  "lastName": "Palande",
  "mobileNo": "9833030550",
  "shortName": "MP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/627219d6afd7d55eddedd283/
profilePhoto_1668055836118_WhatsApp_Image_20221110_at_101725_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "64c777a8a5c3051014f4dd1f",
  "role": "SITEENGINEER",
  "firstName": "Pratik",
  "email": "pratikjain2277@gmail.com",
  "lastName": "Jain",
  "mobileNo": "9619286285",
  "designation": "",
  "shortName": "Pratik",
  "workWithDocumentMaker": "6006d4ce5080a310ac1fdcf2"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": "",
"checker": "",
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  }
]
```

```
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
```

```
\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
],
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.307175423317318",
  "longitude": " 72.84982176631041"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.84982176631041,
    19.307175423317318
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "2023-11-16T09:00:00.000Z",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  }
}
```

```
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Bhaynder",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "1",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
```

```
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Bombay Market D Wing CHSL",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Near Shivsena Office",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Station Road ",
  "label": false
},
}
```

```
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "D",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
```



```
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "17",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
```

```
"status": false,
"name": "Police Station(P.S)",
"key": "policeStation",
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Bhaynder West\t",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
```

```
"finalLatLng": {
  "coordinates": []
},
"locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
```

```
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
```

```
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentId": [],
"audioRemarks": [],
"_id": "6555ddfd5586e0081587d746",
"ownerName": "Amin Mahendra Shah",
```



```
"ownerPhoneNo": "9137351912",
"appAddress": "flat D/17 Bombay market chs near shivsena office stn rd bhayander w",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": " Agreement",
      "value": "652d16a0316e1359cebd3c15"
    },
    "isHardCopy": false,
    "path": "cases/6555ddfd5586e0081587d746/
document_1700126177566_77042.pdf",
    "fileName": "document_1700126177566_77042.pdf",
    "displayStatus": false,
    "id": "573168",
    "uploadedBy": "627219d6afd7d55eddedd283",
    "createdAt": "Thu Nov 16 2023 14:46:45 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "005035",
"createdBy": "627219d6afd7d55eddedd283",
"caseHistory": [
  {
    "id": "903181",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Nov 16 2023 14:46:45 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Amin Mahendra Shah",
    "phone": "9137351912",
    "ownershipShare": "",
    "email": "",
    "id": "936369"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
```

```
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655844545586e008158a9d48",
    "name":
"externalImg_1700283475575_IMG_20231117_114343_copy_1600x1200.jpg",
    "path": "cases/6555ddfd5586e0081587d746/
externalImg_1700283475575_IMG_20231117_114343_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655844545586e008158a9d49",
    "name":
"externalImg_1700283475604_IMG_20231117_120835_copy_901x1200.jpg",
    "path": "cases/6555ddfd5586e0081587d746/
externalImg_1700283475604_IMG_20231117_120835_copy_901x1200.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655844545586e008158a9d4a",
    "name":
"externalImg_1700283475621_IMG_20231117_120843_copy_900x1200.jpg",
    "path": "cases/6555ddfd5586e0081587d746/
externalImg_1700283475621_IMG_20231117_120843_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655844545586e008158a9d4b",
    "name":
"externalImg_1700283475637_IMG_20231117_120844_copy_900x1200.jpg",
    "path": "cases/6555ddfd5586e0081587d746/
externalImg_1700283475637_IMG_20231117_120844_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655844545586e008158a9d4c",
    "name":
"externalImg_1700283475657_IMG_20231117_120845_copy_900x1200.jpg",
```

```
    "path": "cases/6555ddfd5586e0081587d746/
externallmg_1700283475657_IMG_20231117_120845_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655844545586e008158a9d4d",
    "name":
"externallmg_1700283475689_IMG_20231117_120847_copy_900x1200.jpg",
    "path": "cases/6555ddfd5586e0081587d746/
externallmg_1700283475689_IMG_20231117_120847_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655844545586e008158a9d4e",
    "name":
"externallmg_1700283475710_IMG_20231117_120849_copy_900x1200.jpg",
    "path": "cases/6555ddfd5586e0081587d746/
externallmg_1700283475710_IMG_20231117_120849_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655844545586e008158a9d4f",
    "name":
"externallmg_1700283475730_IMG_20231117_120903_copy_900x1200.jpg",
    "path": "cases/6555ddfd5586e0081587d746/
externallmg_1700283475730_IMG_20231117_120903_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655844545586e008158a9d50",
    "name":
"externallmg_1700283475767_IMG_20231117_120905_copy_900x1200.jpg",
    "path": "cases/6555ddfd5586e0081587d746/
externallmg_1700283475767_IMG_20231117_120905_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "655844545586e008158a9d51",
  "name":
"externallmg_1700283475804_IMG_20231117_120907_copy_900x1200.jpg",
  "path": "cases/6555ddfd5586e0081587d746/
externallmg_1700283475804_IMG_20231117_120907_copy_900x1200.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655844545586e008158a9d52",
  "name":
"externallmg_1700283475818_IMG_20231117_212829_copy_900x1200.jpg",
  "path": "cases/6555ddfd5586e0081587d746/
externallmg_1700283475818_IMG_20231117_212829_copy_900x1200.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655844545586e008158a9d53",
  "name":
"externallmg_1700283475830_IMG_20231117_114341_copy_1600x1200.jpg",
  "path": "cases/6555ddfd5586e0081587d746/
externallmg_1700283475830_IMG_20231117_114341_copy_1600x1200.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655844545586e008158a9d54",
  "name":
"externallmg_1700283475841_IMG_20231117_114345_copy_1600x1200.jpg",
  "path": "cases/6555ddfd5586e0081587d746/
externallmg_1700283475841_IMG_20231117_114345_copy_1600x1200.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655844545586e008158a9d55",
  "name":
"externallmg_1700283475853_IMG_20231117_115851_copy_1600x1200.jpg",
  "path": "cases/6555ddfd5586e0081587d746/
externallmg_1700283475853_IMG_20231117_115851_copy_1600x1200.jpg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655844545586e008158a9d56",
    "name":
"externallmg_1700283475858_IMG_20231117_115854_copy_1600x1200.jpg",
    "path": "cases/6555ddfd5586e0081587d746/
externallmg_1700283475858_IMG_20231117_115854_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655844935586e008158a9f4e",
    "name":
"externallmg_1700283539485_IMG_20231117_115901_copy_1600x1200.jpg",
    "path": "cases/6555ddfd5586e0081587d746/
externallmg_1700283539485_IMG_20231117_115901_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655844935586e008158a9f4f",
    "name":
"externallmg_1700283539492_IMG_20231117_115903_copy_1600x1200.jpg",
    "path": "cases/6555ddfd5586e0081587d746/
externallmg_1700283539492_IMG_20231117_115903_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655844935586e008158a9f50",
    "name":
"externallmg_1700283539510_IMG_20231117_115913_copy_1600x1200.jpg",
    "path": "cases/6555ddfd5586e0081587d746/
externallmg_1700283539510_IMG_20231117_115913_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655844935586e008158a9f51",
```

```
    "name":
"externallmg_1700283539517_IMG_20231117_115927_copy_1600x1200.jpg",
  "path": "cases/6555ddfd5586e0081587d746/
externallmg_1700283539517_IMG_20231117_115927_copy_1600x1200.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655844935586e008158a9f52",
  "name":
"externallmg_1700283539522_IMG_20231117_115929_copy_1600x1200.jpg",
  "path": "cases/6555ddfd5586e0081587d746/
externallmg_1700283539522_IMG_20231117_115929_copy_1600x1200.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655844935586e008158a9f53",
  "name":
"externallmg_1700283539527_IMG_20231117_115935_copy_1600x1200.jpg",
  "path": "cases/6555ddfd5586e0081587d746/
externallmg_1700283539527_IMG_20231117_115935_copy_1600x1200.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655844935586e008158a9f54",
  "name":
"externallmg_1700283539541_IMG_20231117_115941_copy_1600x1200.jpg",
  "path": "cases/6555ddfd5586e0081587d746/
externallmg_1700283539541_IMG_20231117_115941_copy_1600x1200.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655844935586e008158a9f55",
  "name":
"externallmg_1700283539548_IMG_20231117_115943_copy_1600x1200.jpg",
  "path": "cases/6555ddfd5586e0081587d746/
externallmg_1700283539548_IMG_20231117_115943_copy_1600x1200.jpg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655844935586e008158a9f56",
  "name":
"externallmg_1700283539570_IMG_20231117_115950_copy_900x1200.jpg",
  "path": "cases/6555ddfd5586e0081587d746/
externallmg_1700283539570_IMG_20231117_115950_copy_900x1200.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655844935586e008158a9f57",
  "name":
"externallmg_1700283539660_IMG_20231117_115951_copy_900x1200.jpg",
  "path": "cases/6555ddfd5586e0081587d746/
externallmg_1700283539660_IMG_20231117_115951_copy_900x1200.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655844935586e008158a9f58",
  "name":
"externallmg_1700283539674_IMG_20231117_115954_copy_900x1200.jpg",
  "path": "cases/6555ddfd5586e0081587d746/
externallmg_1700283539674_IMG_20231117_115954_copy_900x1200.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655844935586e008158a9f59",
  "name":
"externallmg_1700283539685_IMG_20231117_120006_copy_900x1200.jpg",
  "path": "cases/6555ddfd5586e0081587d746/
externallmg_1700283539685_IMG_20231117_120006_copy_900x1200.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655844935586e008158a9f5a",
  "name":
"externallmg_1700283539717_IMG_20231117_120018_copy_900x1200.jpg",
```

```
    "path": "cases/6555ddfd5586e0081587d746/
externallmg_1700283539717_IMG_20231117_120018_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655844935586e008158a9f5b",
    "name":
"externallmg_1700283539728_IMG_20231117_120026_copy_900x1200.jpg",
    "path": "cases/6555ddfd5586e0081587d746/
externallmg_1700283539728_IMG_20231117_120026_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655844935586e008158a9f5c",
    "name":
"externallmg_1700283539739_IMG_20231117_120033_copy_900x1200.jpg",
    "path": "cases/6555ddfd5586e0081587d746/
externallmg_1700283539739_IMG_20231117_120033_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655844b95586e008158aa06f",
    "name":
"externallmg_1700283573647_IMG_20231117_115941_copy_1600x1200.jpg",
    "path": "cases/6555ddfd5586e0081587d746/
externallmg_1700283573647_IMG_20231117_115941_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655844b95586e008158aa070",
    "name":
"externallmg_1700283573655_IMG_20231117_115943_copy_1600x1200.jpg",
    "path": "cases/6555ddfd5586e0081587d746/
externallmg_1700283573655_IMG_20231117_115943_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```



```
"status": false,
  "_id": "655844b95586e008158aa071",
  "name":
"externallmg_1700283576344_IMG_20231117_115950_copy_900x1200.jpg",
  "path": "cases/6555ddfd5586e0081587d746/
externallmg_1700283576344_IMG_20231117_115950_copy_900x1200.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655844b95586e008158aa072",
  "name":
"externallmg_1700283576831_IMG_20231117_115951_copy_900x1200.jpg",
  "path": "cases/6555ddfd5586e0081587d746/
externallmg_1700283576831_IMG_20231117_115951_copy_900x1200.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655844b95586e008158aa073",
  "name":
"externallmg_1700283576843_IMG_20231117_115954_copy_900x1200.jpg",
  "path": "cases/6555ddfd5586e0081587d746/
externallmg_1700283576843_IMG_20231117_115954_copy_900x1200.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655844b95586e008158aa074",
  "name":
"externallmg_1700283576853_IMG_20231117_120006_copy_900x1200.jpg",
  "path": "cases/6555ddfd5586e0081587d746/
externallmg_1700283576853_IMG_20231117_120006_copy_900x1200.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655844b95586e008158aa075",
  "name":
"externallmg_1700283576861_IMG_20231117_120018_copy_900x1200.jpg",
  "path": "cases/6555ddfd5586e0081587d746/
externallmg_1700283576861_IMG_20231117_120018_copy_900x1200.jpg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655844b95586e008158aa076",
    "name":
"externallmg_1700283576870_IMG_20231117_120026_copy_900x1200.jpg",
    "path": "cases/6555ddfd5586e0081587d746/
externallmg_1700283576870_IMG_20231117_120026_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655844b95586e008158aa077",
    "name":
"externallmg_1700283576878_IMG_20231117_120033_copy_900x1200.jpg",
    "path": "cases/6555ddfd5586e0081587d746/
externallmg_1700283576878_IMG_20231117_120033_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655844b95586e008158aa078",
    "name":
"externallmg_1700283576887_IMG_20231117_120051_copy_1600x1200.jpg",
    "path": "cases/6555ddfd5586e0081587d746/
externallmg_1700283576887_IMG_20231117_120051_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655844b95586e008158aa079",
    "name":
"externallmg_1700283576892_IMG_20231117_120052_copy_1600x1200.jpg",
    "path": "cases/6555ddfd5586e0081587d746/
externallmg_1700283576892_IMG_20231117_120052_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655844b95586e008158aa07a",
```

```
    "name":
"externallmg_1700283576898_IMG_20231117_120054_copy_1600x1200.jpg",
  "path": "cases/6555ddfd5586e0081587d746/
externallmg_1700283576898_IMG_20231117_120054_copy_1600x1200.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655844b95586e008158aa07b",
  "name":
"externallmg_1700283576906_IMG_20231117_120651_copy_900x1200.jpg",
  "path": "cases/6555ddfd5586e0081587d746/
externallmg_1700283576906_IMG_20231117_120651_copy_900x1200.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655844b95586e008158aa07c",
  "name":
"externallmg_1700283576918_IMG_20231117_120654_copy_900x1200.jpg",
  "path": "cases/6555ddfd5586e0081587d746/
externallmg_1700283576918_IMG_20231117_120654_copy_900x1200.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655844b95586e008158aa07d",
  "name":
"externallmg_1700283576928_IMG_20231117_120757_copy_1600x1200.jpg",
  "path": "cases/6555ddfd5586e0081587d746/
externallmg_1700283576928_IMG_20231117_120757_copy_1600x1200.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655844b95586e008158aa07e",
  "name":
"externallmg_1700283576934_IMG_20231117_120800_copy_1600x1200.jpg",
  "path": "cases/6555ddfd5586e0081587d746/
externallmg_1700283576934_IMG_20231117_120800_copy_1600x1200.jpg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655844b95586e008158aa07f",
  "name":
"externallmg_1700283576940_IMG_20231117_120802_copy_1600x1200.jpg",
  "path": "cases/6555ddfd5586e0081587d746/
externallmg_1700283576940_IMG_20231117_120802_copy_1600x1200.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655844b95586e008158aa080",
  "name":
"externallmg_1700283576948_IMG_20231117_120815_copy_1600x1200.jpg",
  "path": "cases/6555ddfd5586e0081587d746/
externallmg_1700283576948_IMG_20231117_120815_copy_1600x1200.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655844b95586e008158aa081",
  "name":
"externallmg_1700283576954_IMG_20231117_212844_copy_1600x1200.jpg",
  "path": "cases/6555ddfd5586e0081587d746/
externallmg_1700283576954_IMG_20231117_212844_copy_1600x1200.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655844b95586e008158aa082",
  "name":
"externallmg_1700283576960_IMG_20231117_212852_copy_1600x1200.jpg",
  "path": "cases/6555ddfd5586e0081587d746/
externallmg_1700283576960_IMG_20231117_212852_copy_1600x1200.jpg",
  "orientation": "landscape"
}
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"remarks": [],
"createdAt": "2023-11-16T09:16:45.124Z",
```

"updatedAt": "2023-11-18T04:59:37.060Z",  
"\_\_v": 0,  
"invoiceId": "6555ddfd5586e0081587d74f",  
"fullAddress": " Flat No. 17, 1st Floor, Wing - D, Bombay Market D Wing CHSL, Near  
Shivsena Office, Station Road , Village - Bhaynder, Bhaynder West\t",  
"updatedBy": "6006d4ce5080a310ac1fdfc2",  
"addressForMap": "",  
"caseReferredBy": "627219d6afd7d55eddedd283",  
"contactPersonName": "Amin Mahendra Shah",  
"email": "",  
"isExternal": "false",  
"isUrgent": "false",  
"ownershipShare": "",  
"purchaseValueAsPerDocument": "",  
"relationWithOwner": "self",  
"siteVisitContactNo": "9137351912"

}

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
Composition :			
Other Composition :			